



Wildcat

DIESEL SERVICE

KEEPIN' RIGS ROARIN' SINCE 1986

TAX INVOICE

ABN 34 008 180 470

No. 00029897

cash sale

TERMS	DATE	PAGE NO.
C.O.D.	20/03/2026	Page 1 of 1

Customer ABN:

QTY	DESCRIPTION	PRICE	EXTENDED
	Mack Fleetliner - XS-58HE - 409387 km's		
1	Carry-out visual inspection for change of ownership.		
2	Check & adjust brakes.		
3	Adjust clutch.		
4	Tension & replace body bolts where required.		
	Overhaul RHF brakes		
	- Steam clean area.		
	- Machine drum.		
	- Replace wheel bearing.		
	- Replace seal.		
	Perform brake test.		
	... Supply printed report - Pass		
1.3	1ST YEAR APPRENTICE LABOUR	\$65.00	\$84.50
1.2	LABOUR APPRENTICE 2nd YEAR	\$80.00	\$96.00
3.2	LABOUR NORMAL HOURS	\$140.00	\$448.00
	PARTS		
1	Hub seal	\$44.50	\$44.50
1	Hub cover gasket	\$4.90	\$4.90
0.3	Litre 85W140 diff oil	\$9.95	\$2.99
1	Steer brake shoe set	\$146.60	\$146.60
1	Steer brake drum	\$286.44	\$286.44
0.5	Litres degreaser	\$8.00	\$4.00
1	Waste Disposal	\$60.00	\$60.00
1	Brake test	\$90.00	\$90.00
1	Consumables	\$10.00	\$10.00

EFT PAYMENTS		SALE AMOUNT	\$1,277.93
BSB [REDACTED]		FREIGHT	\$0.00
ACCOUNT [REDACTED]		GST	\$127.79
ORDER NUMBER	XS58HE / Shane	TOTAL INCLUDING GST	\$1,405.72

Your prompt payment is greatly appreciated. Please note all overdue invoices will incur a fee of 5%
We thank you for your business.

Service Brake

Axle	Force left [N]	Diff [%]	Force right [N]	Pedal Force [N]	Decel. peak [%]	Decel. Average [%]
1	12160	28	8710	--	32	28
2	11750	17	14120	--	79	56
3	8290	14	7130	--	45	38
Vehicle	32200	7	29960	--	47	38

Hand Brake

Axle	Force left [N]	Diff [%]	Force right [N]	Decel. peak [%]	Decel. Average [%]
2	8900	16	10540	60	47
3	8720	18	7130	47	39
Vehicle	17620	0	17670	27	21

Brake Test Report

PASS

■ = PASS
 ■ = FAIL
 ■ = INSPECTION RECOMMENDED

Vehicle No: **XS58HE**
 Examiner No: **ROBBIE**
 Inspection Station No:
 Calibration Due: **NOV 2027**
 Serial No: **TSI0506523**

Wildcat Diesel
70-76 Magazine Rd
Dry Creek SA 5094

Signature



20.03.2026 10.52.05



Wildcat

DIESEL SERVICE

KEEPIN' RIGS ROARIN' SINCE 1986

TAX INVOICE

ABN 34 008 180 470

No. 00029624

cash sale

Customer ABN:

TERMS	DATE	PAGE NO.
C.O.D.	24/10/2025	Page 1 of 2

QTY	DESCRIPTION	PRICE	EXTENDED
	Mack Fleetliner - XS-58HE - 401186 km's		
1	Carry-out full service and inspection. - Change fuel filters.		
2	Check & adjust brakes.		
3	Check & correct tyre pressures.		
4	Adjust clutch.		
5	Tension LHF lower shock bolt.		
0.5	LABOUR APPRENTICE 2nd YEAR	\$75.00	\$37.50
2.5	LABOUR NORMAL HOURS	\$150.00	\$375.00
	PARTS		
29	Litre All Fleet Plus 15W40	\$6.95	\$201.55
1	Service kit - Genuine	\$184.75	\$184.75
5	Amber reflector	\$2.90	\$14.50
1	Tyre valve core	\$1.00	\$1.00
1	Environmental recovery levy	\$16.00	\$16.00
1	Consumables	\$10.00	\$10.00

EFT PAYMENTS

BSB [REDACTED]
ACCOUNT [REDACTED]

SALE AMOUNT

FREIGHT

GST

ORDER NUMBER

XS58HE - Shane

TOTAL INCLUDING GST

**Your prompt payment is greatly appreciated. Please note all overdue invoices will incur a fee of 5%
We thank you for your business.**



Wildcat

DIESEL SERVICE

KEEPIN' RIGS ROARIN' SINCE 1986

TAX INVOICE

ABN 34 008 180 470

No. 00029624

cash sale

Customer ABN:

TERMS	DATE	PAGE NO.
C.O.D.	24/10/2025	Page 2 of 2

QTY	DESCRIPTION	PRICE	EXTENDED
	<p>COMMENTS:</p> <ol style="list-style-type: none">1. Auto-electrician to rectify air conditioning split hose at TX valve 6/11/25. Will need vehicle afternoon before to remove air cleaner box.2. RHFD hub seal booked for 6/11/25.3. Slight movement in kingpins.4. Power steer pressure hose weeping.5. Slight front cab mount movement.6. RH seat belt slight fray.7. SR1 relay valve slight leak at RHFD.		

EFT PAYMENTS	SALE AMOUNT	\$840.30
BSB [REDACTED]	FREIGHT	\$0.00
ACCOUNT [REDACTED]	GST	\$84.03

ORDER NUMBER	XS58HE - Shane	TOTAL INCLUDING GST	\$924.33
---------------------	----------------	----------------------------	----------

**Your prompt payment is greatly appreciated. Please note all overdue invoices will incur a fee of 5%
We thank you for your business.**



Wildcat

DIESEL SERVICE

KEEPIN' RIGS ROARIN' SINCE 1986

TAX INVOICE

ABN 34 008 180 470

No. 00029650

cash sale

Customer ABN:

TERMS	DATE	PAGE NO.
C.O.D.	7/11/2025	Page 1 of 1

QTY	DESCRIPTION	PRICE	EXTENDED
	Mack Fleetliner - XS-58HE - 402136 km's 10039 hours.		
1	Arrange for auto electrician to replace split air con hose & service system. - Remove air intake, hoses & bracket to gain access to area.		
2	Replace leaking RHFD hub seal. - Steam clean area until clean. - Utilise heat to remove oil from brake linings.		
3	Check washer operation - Motor found faulty - On order and in stock, allow half an hour to fit.		
3	1ST YEAR APPRENTICE LABOUR	\$65.00	\$195.00
3.6	LABOUR NORMAL HOURS	\$150.00	\$540.00
3	LABOUR NORMAL HOURS - AUTO ELECTRICIAN	\$140.00	\$420.00
	PARTS		
1	Hub Seal - High Temp	\$90.12	\$90.12
0.25	Litre 85W140 diff oil	\$9.95	\$2.49
1	5/8 axle gasket	\$4.50	\$4.50
1	Washer motor	\$43.50	\$43.50
1	Grommet	\$1.95	\$1.95
1	Operating supplies	\$20.00	\$20.00
1	Waste Disposal	\$40.00	\$40.00
1	Receiver drier	\$110.00	\$110.00
1	Liquid hose	\$70.00	\$70.00
1	Consumables	\$25.00	\$25.00
1.4	Refrigerant	\$130.00	\$182.00

EFT PAYMENTS	SALE AMOUNT	\$1,744.56
BSB [REDACTED]	FREIGHT	\$0.00
ACCOUNT [REDACTED]	GST	\$174.46

ORDER NUMBER	Shane XS58HE	TOTAL INCLUDING GST	\$1,919.02
---------------------	--------------	----------------------------	------------

**Your prompt payment is greatly appreciated. Please note all overdue invoices will incur a fee of 5%
We thank you for your business.**