



Fired-Up Automotive Performance and Service
 Box 691, 191 - 3rd Street NE
 Black Diamond, AB T0L0H0
 (403) 933-4701

Invoice

Plate AB 2006 F350
 Description White 2006 Ford F-350 Super Duty XLT V8 6.0L
 VIN P
 VIN 1FTWX33P86EC43969
 Odometer 221,866

Email

Inspection

Brake System Inspection

Labor	0 Hour		\$0.00 *G
		Sub	\$0.00

MECHANIC COMMENTS:

Steering & Suspension Pinpoint Inspection

Labor	0 Hour		\$0.00 *G
		Sub	\$0.00

Service

Cylinder Head Gasket - Ford 6.0L

Labor	22 Hour		\$2,750.00 *G
54450A - Mahle - Cylinder Head Gasket 18mm Dowel	2 Unit	\$99.80 / Unit	\$199.60 G
HSK-60 - Gator - Cylinder Head Bolt Kit	1 Unit	\$637.97 / Unit	\$637.97 G
FRT - Freight/Shipping	1 Unit	\$26.44 / Unit	\$26.44 G
W302193 - Ford - Rocker Arm Retaining Clip	2 Unit	\$10.32 / Unit	\$20.64 G
FRT - Freight/Shipping	1 Unit	\$20.00 / Unit	\$20.00 G
		Sub	\$3,654.65

Serpentine Belt(s)

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Retest and verify repair as required. Perform final road test where applicable.

Labor - Combined with labour for Head Gaskets	0.5 Hour		\$62.50 *G
4081265F - Goodyear - Serpentine Belt	1 Unit	\$104.65 / Unit	\$104.65 G
		Sub	\$167.15

Shock Absorber, Front

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Labor - Combined with Cab removal for Head Gaskets	0.5 Hour		\$62.50 *G
RS55042 - Rancho - Shock Absorber	2 Unit	\$142.22 / Unit	\$284.44 G
		Sub	\$346.94

MECHANIC COMMENTS:

IF TIRES HAVE BEEN REMOVED PLS RE-TORQUE WITHIN 100 KMS

Air Filter

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

2731 - Engine Air Filter	1 Unit	\$159.47 / Unit	\$159.47 G
		Sub	\$159.47

Rear Brake Pads & Rear Left Caliper

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Re-test and verify repair as required. Perform final road test where applicable.

Labor	1.5 Hour		\$187.50 *G
2624XB - Rear Left Coated Brake Caliper Dual Piston	1 Unit	\$228.07 / Unit	\$228.07 G
17D1067MH - AC Delco - Rear Premium Brake Pad Set	1 Unit	\$174.47 / Unit	\$174.47 G
		Sub	\$590.04

Brake Info:

Try to avoid hard braking for approx 300 kms to achieve optimum performance & life of your pads.

Total Parts		\$1,855.75
Total Labor		\$3,062.50
Total Before Taxes & Miscellaneous Charges		\$4,918.25
(*) Shop supplies include material and service items too small to itemize individually for service or repairs performed on vehicle.	7 %	\$25.00 G
(G) Canadian Goods and Services Tax (GST)	5 %	\$247.16
Grand Total		\$5,190.41

████████████████████
GST # 839102167RT0001

LIMITED GUARANTEE: Our work is performed in a careful workmanlike manner.
ANY WARRANTY WORK MUST BE PRE-APPROVED THROUGH FIRED-UP AUTOMOTIVE.

WE DO NOT assume any responsibility for vehicles, or any contents or articles left in vehicles delivered to our service centre for service, storage, or otherwise. please remove all personal contents from the vehicle.

I AGREE TO PAY 3% INTEREST PER MONTH(26.82% PER ANNUM) ON ALL UNPAID ACCOUNTS OVER 30 DAYS FROM DATE OF INVOICE.

WE DO NOT assume any responsibility for lost or misplaced hubcaps after vehicle has left the parking lot.

IF TIRES HAVE BEEN REMOVED PLS RE-TORQUE WITHIN 100 KMS