



9 HIGHLAND RD
MOOSE JAW SK S6J 1M5

INVOICE



[Redacted] t: [Redacted]

Phone: 306.692.2389
Fax
F212@fountaintire.com
802466086RT0001
2492171

[Redacted] 2 [Redacted]
[Redacted] 2 [Redacted]
PO#:
AirMiles # :

[Redacted] [Redacted] [Redacted]

Year: 2006 Unit:
Make: FORD TRUCK
Model: F350 SUPER DUTY P/U
Design:
Engine: V8-363 6.0L Dsl
License: Colour:
Vin: 1FTWX33P86EC43969
Mileage: 257804 Hours: 0

Item number	Item description	Qty	Unit price	Discount	Total
Wheel Alignments					
AL0202	4 Wheel Alignment - 3/4 and 1 Ton Pickup - Improves Tire Wear	1.00	\$159.00		\$159.00
Chassis and Steering Parts and Service					
DS80749-MOO	DRAG LINK	1.00	\$245.00		\$245.00
SC2965-482	Steering Damper	1.00	\$125.00		\$125.00
CHL	Remove & Replace Steering Damper	0.50	\$139.00		\$69.50
CHL	Remove & Replace Drag Link	1.30	\$139.00		\$180.70
Vision and Miscellaneous Parts and Service					
IN014	Out of Province Inspection	2.00	\$139.00	(\$139.00)	\$139.00
Other Miscellaneous Items					
M	Thank you for choosing Fountain Tire, we appreciate your business	1.00	\$0.00		\$0.00
SHOP	Shop Supplies	1.00	\$54.82		\$54.82

These parts and services were recommended for replacement or repair

Item Description	Qty	Unit price	Net amount
Repair both rear seatbelts-fail to	1.00	\$139.00	\$139.00
		Sub Total:	\$139.00

This estimate is valid for 30 days and excludes sales taxes

Air Miles: 0

[Redacted]
[Redacted]

I acknowledge: (1) receipt of goods and services; and (2) Fountain Tire may conduct a registry search to verify the VIN on my vehicle if required for collection purposes on unpaid invoices related to my vehicle.

The customer is to ensure all wheel lugs are re torqued by a qualified technician before the vehicle has travelled 100 kilometers.

Parts:	\$370.00
Services:	\$603.02
Sub Total:	\$973.02
GST:	\$48.65
PST:	\$58.38
Total: (CAD)	\$1,080.05

Pay type: VisaCard \$1,080.05

X _____