



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
Prv Phone:

[REDACTED]

Bus Phone:
Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 8/14/2024
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 1 of 7

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MISCELLANEOUS 2009 J&M 1150-22S GRAIN CA		2082	2082	

Gen1- Internal

COMPLAINT:
01 SAFETY INSPECTION

CORRECTION:

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N
Labor: \$265.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$15.93	Sub-Total: \$281.43		

Gen2- Internal

COMPLAINT:
02 WASH & CLEAN

CORRECTION:

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	21.60	21.60	\$21.60	N
Labor: \$360.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$21.60	Sub-Total: \$381.60		

Gen4- Internal

COMPLAINT:
04 DIAGNOSE & REPAIR REAR INSIDE SLIDING DOOR NOT WORKING

CORRECTION:

FIRST, TESTED THE DOOR AND IT DID NOT MOVE. FOUND THAT THE HOSES WERE PRESSURING UP, SO THEY WERE GOOD. DECIDED TO REMOVE THE BOTTOM CYLINDER PIN AND CRACK THE TOP HOSE TO SEE IF WE COULD MOVE IT BY HAND, WHICH DIDN'T WORK. TRIED THE HYDRAULICS WITHOUT THE DOOR CONNECTED AND THEY WORKED AS SHOULD. CONNECTED THE DOOR AND IT NOW WORKED GOOD. THERE MUST HAVE BEEN AN AIR BUBBLE INSIDE THE CYLINDER THAT CAUSED THE DOOR NOT TO MOVE. TIGHTENED UP THE HOSE.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
---------------	-------------	----------	------------	-----------	----------------	-----------



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
Prv Phone:

[REDACTED]

Bus Phone:
Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 8/14/2024
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 2 of 7

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MISCELLANEOUS 2009 J&M 1150-22S GRAIN CA		2082	2082	

Gen4- Internal								
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N		
Labor: \$354.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$21.24	Sub-Total: \$375.24				

Gen6- Internal
 COMPLAINT:
 06 REPLACE ALL REAR LIGHTS - BROKEN/MISSING

CORRECTION:
 AFTER ALL LIGHTS WERE INSTALLED NONE WERE WORKING. FOUND THAT NONE OF THE LIGHTS WERE PLUGGED IN CORRECTLY. REWIRED ALL THE LIGHTS AND MADE SURE ALL WORKED NOW USING A BATTERY AND TEST LEADS. TESTED FOR POWER AT THE CONTROLLER AND USING THE BATTERY AS GROUND AND FOUND THAT THERE WAS POWER AT THREE POINTS ON THE 4 POINT CONNECTOR. AFTER FINDING OUT WHAT WIRE WAS GROUND IT WAS USING FOR ALL OTHER TESTS. POWER WAS THEN TESTED LEAVING THE LIGHT ENHANCER AND FOUND THAT THERE WAS POWER AT ALL POINTS AND NO GROUNDS. AFTER FINDING THIS THE LIGHT ENHANCER WAS FOUND TO BE THE ISSUE AND WAS REMOVED. THE LIGHTS WERE THEN WIRED STRAIGHT FROM THE TRAILER PLUG BACK TO THE CONNECTOR FROM THE ENHANCER AND THE REST OF THE WIRING WAS WIRED INTO THE FOUR POINT CONNECTOR. TESTED THE LIGHTS USING AN ADAPTER FROM STANDARD 7 POINT TO HEAVY DUTY 7 POINT. TESTED THE SIGNAL LIGHTS AND THERE WAS NO LIGHT THE TESTED THE BRAKE LIGHTS AND NOTHING CAME ON. REMOVED THE SCREWS HOLDING THE CONNECTOR SLEEVE ON AND REMOVED THE CONNECTOR SLEEVE. FOUND THAT WIRING ON THE CONNECTOR DID NOT MATCH THE FUNCTIONS. REWIRED THE 7 PIN CONNECTOR AND TESTED AGAIN. THIS FIXED THE ISSUE. BOTH TURN LIGHTS WORK NOW BUT THE BRAKES STILL WOULD NOT COME ON. DROVE THE YARD TRACTOR OVER AND USED IT TO TEST THE LIGHTS. ALL THE LIGHTS WORKED WHEN IT WAS HOOKED UP TO THE TRACTOR. CLEANED UP THE WIRING AND PARKED THE TRACTOR.

EQUIPMENT

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14H778	Hex Nut #10	2.00	0.32	0.32	\$0.64	N
14M7027	Hex Nut M6	4.00	0.34	0.34	\$1.36	N
24H1371	Washer	2.00	3.53	3.53	\$7.06	N
R78061	Electrical Connector Terminal	4.00	1.46	1.46	\$5.84	N
R78062	Electrical Connector Seal Blue	4.00	0.56	0.56	\$2.24	N
R78063	Electrical Connector Seal Gray	8.00	0.75	0.75	\$6.00	N



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: [REDACTED]

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 8/14/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 3 of 7
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MISCELLANEOUS 2009 J&M 1150-22S GRAIN CA		2082	2082	

Gen6- Internal

JM0018819	LED AMBER RD LIGHT	2.00	129.60	129.60	\$259.20	N
JM0034389	LED RED OVAL TAIL LIGHT	2.00	61.28	61.28	\$122.56	N

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	71.69	71.69	\$71.69	N

Labor: \$1,194.75 Parts: \$404.90 OL&M: \$0.00 Misc: \$71.69 Sub-Total: \$1,671.34

GEN7- Internal

COMPLAINT:
 07 RESEAL UNLOADING AUGER LIFT CYLINDER

CORRECTION:
 REMOVED AND CAPPED THE HYDRAULIC LINES FOR THE CYLINDER. REMOVED PINS, REMOVED CYLINDER AND RESEALED THE CYLINDER. INSTALLED THE CYLINDER AND TESTED, IT ALL WORKED GOOD AND THERE WAS NO LEAKS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
JM0026544	SEAL KIT FOR LIFT CYLINDER	1.00	105.08	105.08	\$105.08	N

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	26.55	26.55	\$26.55	N

Labor: \$442.50 Parts: \$105.08 OL&M: \$0.00 Misc: \$26.55 Sub-Total: \$574.13

GEN8- Internal

COMPLAINT:
 08 STRAIGHTEN OR REPLACE UNLOADING AUGER DOWNSPOUT - BENT

CORRECTION:
 REMOVED THE DOWNSPOUT AND BROUGHT INSIDE. USED A HAMMER AND MANY WOODEN BLOCKS TO GET THE DOWNSPOUT AS STRAIGHT AS POSSIBLE. INSTALLED THE DOWNSPOUT.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
Prv Phone:

[REDACTED]

Bus Phone:
Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 8/14/2024
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 4 of 7

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MISCELLANEOUS 2009 J&M 1150-22S GRAIN CA		2082	2082	

GEN8- Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N	
Labor: \$354.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$21.24	Sub-Total: \$375.24			

GEN10- Internal
 COMPLAINT:
 10 STRAIGHTEN TARP ROLLER- BENT

CORRECTION:
 FOUND WHERE THE ROLLER WAS BENT, PUT A BLOCK UNDER THE BENT PART, STRAPPED THE COME ALONG TO THE END AND HOOKED THE OTHER END TO SOMETHING STRONG. PULLED DOWN ON THE END OF THE ROLLER TO BENT IT BACK UNTIL IT WAS AS STRAIGHT AS WE COULD GET IT.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$187.62		

GEN11- Internal
 COMPLAINT:
 11 STRAIGHTEN REAR TARP HOOD AND INSTALL MISSING HARDWARE

CORRECTION:
 OPENED THE TARP THEN CLIMBED INSIDE THE CART TO GO SEE HOW BAD IT WAS BENT. SAW IT WAS GOING TO NEED TO BE REMOVED, BEGAN REMOVING HARDWARE THEN LOWERED THE HOOD TO THE GROUND WITH THE FORK LIFT. BROUGHT THE HOOD INTO THE SHOP AND STRAIGHTENED THE HOOD USING PRY BARS AND HAMMERS. AFTER STRAIGHTENING THE HOOD IT WAS THEN TAKEN BACK OUT TO THE CART. THE HOOD WAS THEN LIFTED UP TO THE MOUNTING POINT THE HOOD WAS THEN MOUNTED TO THE CART USING NEW HARDWARE WHERE THE OLD HARDWARE COULDN'T BE USED. MADE SURE THAT THE TARP WOULD RIDE ON THE HOOD.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14H1040	Hex Nut 1/2" NC	2.00	1.65	1.65	\$3.30	N
14H786	Hex Nut 1/4" NC	16.00	0.34	0.34	\$5.44	N



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
 Prv Phone:

[REDACTED]

Bus Phone:
 Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 8/14/2024
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 5 of 7

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MISCELLANEOUS 2009 J&M 1150-22S GRAIN CA		2082	2082	

GEN11- Internal

19H1781	Hex Bolt 1/2" X 3 1/2" GR5 NC	2.00	7.89	7.89	\$15.78	N
19H1948	Hex Bolt 1/4" X 3/4" GR5 NC	16.00	1.01	1.01	\$16.16	N
24H1287	WASHER	32.00	0.58	0.58	\$18.56	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	84.96	84.96	\$84.96	N

Labor: \$1,416.00 Parts: \$59.24 OL&M: \$0.00 Misc: \$84.96 Sub-Total: \$1,560.20

GEN13- Internal

COMPLAINT:
 13 REPAIR OR REPLACE JACK STAND - BENT

CORRECTION:
 INSPECTED JACK AND FOUND THAT IT WAS VERY HARD TO TURN AND WAS BENT SO WAS DECIDED TO ORDER A NEW ONE.

GOT MEASUREMENTS FOR THE TUBE AND THE HOLES IN THE JACK, GOT THE PROPER SIZED BOLTS AND NUTS THEN FOUND A PIECE AND STEEL THAT WOULD HOLD THE WEIGHT AND BEND. DRILLED OUT HOLES IN THE STEEL AND MADE SURE THE BOLTS WOULD FIT THROUGH THE PLATE ON JACK AND ON THE STEEL PLATE. ALL FIT GOOD. TOOK THE JACK OUT TO THE CART AND INSTALLED IT. LIFTED THE HITCH UNTIL THE OLD JACK COULD BE REMOVED AND THEN REMOVED THE OLD JACK.

LIFTED THE CART UP USING THE FORKLIFT AND REMOVED THE MOUNTING PLATE FOR THE JACK, BROUGHT IT IN TO MAKE A SECOND PLATE FOR THE OTHER SET OF HOLES, DRILLED THE HOLES OUT IN THE NEW PLATE. BROUGHT THE PLATES BACK OUT AND MOUNTED THE JACK AGAIN, PAINTED THE PLATES TO MATCH THE JACK.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
12H294	5/8" Lock Washer	4.00	1.57	1.57	\$6.28	N
14H1039	Hex Nut 5/8" NC	4.00	3.39	3.39	\$13.56	N
19H3416	Hex Bolt 5/8" X 6 1/2" GR8 NC	4.00	19.97	19.97	\$79.88	N
24H1371	Washer	2.00	3.53	3.53	\$7.06	N
24H1380	Washer	4.00	5.95	5.95	\$23.80	N



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
 Prv Phone:

[REDACTED]

Bus Phone:
 Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 8/14/2024
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 6 of 7

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MISCELLANEOUS 2009 J&M 1150-22S GRAIN CA		2082	2082	

GEN13- Internal

JM0020936	HITCH JACK	1.00	759.53	759.53	\$759.53	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
FREIGHT	FREIGHT	1.00	500.00	500.00	\$500.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N

Labor: \$354.00 Parts: \$890.11 OL&M: \$0.00 Misc: \$521.24 Sub-Total: \$1,765.35

GEN14- Internal

COMPLAINT:
 14 GREASE UNIT

CORRECTION:
 GREASED THE UNIT.



<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY6341	SD POLYUREA GREASE	1.00	10.31	10.31	\$10.31	N

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------





Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]
 [REDACTED]
 Bus Phone:
 Prv Phone:

[REDACTED]
 [REDACTED]
 Bus Phone:
 Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 8/14/2024
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 7 of 7

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MISCELLANEOUS 2009 J&M 1150-22S GRAIN CA		2082	2082	

GEN14- Internal	SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor:	\$177.00	Parts: \$10.31	OL&M: \$0.00	Misc: \$10.62	Sub-Total:	\$197.93	

Customer PO No:
 Tax Exempt No:
 Advisor: [REDACTED]

Labor:	\$5,094.75
Parts:	\$1,469.64
OL&M:	\$0.00
Misc:	\$805.69
Grand Total:	\$7,370.08

*** DOCUMENT COPY ***

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
00 00	160	1	146827			USED AG EQUIPMENT
05 40	382	1	768733			INTERNAL LABOR-AG
00 00	178	15	768733			WORK IN PROCESS PARTS -MJ
05 40	482	1	768733			COS INTERNAL LABOR-AG
05 40	544	1	768733			SUPPLIES EXPENSE
05 30	372	2	768733			OTHER MFR PARTS-CNTR
00 00	172	5	768733			OTHER PARTS-MOOSE JAW
05 30	366	2	768733			JD PARTS-COUNTER
00 00	166	5	768733			JD PARTS-MOOSE JAW
05 30	375	1	768733			PARTS SPECIAL HANDLING
05 30	472	2	768733			OTHER MFR PARTS-CNTR
05 30	466	2	768733			JD PARTS-COUNTER

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:Date: