



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 9/3/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 1 of 4
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2014 JD 615P PICKUP PLATFORM		1H00615PAE0765696	1H00615PAE0765696	

/HEADER615P F Internal

COMPLAINT:
 01 GREENLIGHT SERVICE INSPECTION HEADER

CORRECTION:

Labor: \$265.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$265.50
-----------------	---------------	--------------	--------------	---------------------

/GLOPCLEAN615P Internal

COMPLAINT:
 02 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST

CORRECTION:

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	14.40	14.40	\$14.40	N

Labor: \$180.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$14.40	Sub-Total: \$194.40
-----------------	---------------	--------------	---------------	---------------------

/170048615P F Internal

COMPLAINT:
 03 REPLACE PICKUP BELT TEETH - 3 BROKEN

CORRECTION:

REMOVED BELT TENSION, TRIED REMOVING NUTS, HAD TO CUT TWO OFF AND REMOVED BOLTS, REPLACED BOLTS AND TEETH AND TIGHTEN, HAD TO SPIN ROLLERS OVER FOR LAST ONE, REMOVED AND INSTALLED NEW AND TIGHTEN, SET CORRECT TENSION

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14H786	Hex Nut 1/4" NC	3.00	0.34	0.34	\$1.02	N
A-1000378	Bolt W/Nut	3.00	0.63	0.63	\$1.89	N





Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 9/3/2024 Location: Work Order Number: Payment Type: Page: 2 of 4
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2014 JD 615P PICKUP PLATFORM		1H00615PAE0765696	1H00615PAE0765696	

/170048615P F Internal								
H86248	FINGER	3.00	4.01	4.01	\$12.03	N		
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>		
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N		
Labor: \$132.75	Parts: \$14.94	OL&M: \$0.00	Misc: \$7.97	Sub-Total: \$155.66				

Gen5- Internal

COMPLAINT:

05 REPLACE TINE LIFTING CYLINDER LOWER BRACKETS - BENT AND CRACKED. PAINT RIGHT HAND WELDED BRACKET

CORRECTION:

LH SIDE - FIRST, REMOVED AND CAPPED THE TWO HYDRAULIC LINES GOING TO THE MOTOR. REMOVED THE PINS ON EITHER SIDE OF THE LIFT CYLINDER AND PUT A PRY-BAR IN THE WAY SO THAT THE ARM WOULD NOT FALL. REMOVED BRACKET, CLEANED THE SHAFT, INSTALLED A NEW WASHER AND THE NEW BRACKET WITH SOME ANTI-SEIZE. INSTALLED THE PINS AND THE LIFT CYLINDER. CONNECTED THE HYDRAULIC LINES AND TIGHTENED.

RH SIDE - REMOVED THE PINS FOR THE LIFT CYLINDER. REMOVED THE ROLL PIN IN THE BRACKET. CUT THE BRACKET OFF CLEANED UP THE SHAFT AND INSTALLED A NEW BRACKET AND WASHER WITH SOME ANTI-SEIZE. INSTALLED PINS AND THE LIFT CYLINDER. RAN HEADER, RUNS GOOD AND PARKED THE COMBINE.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
11M7015	Cotter Pin M3.2 X 25	1.00	0.41	0.41	\$0.41	N
14M7140	Hex Nut M10	1.00	1.11	1.11	\$1.11	N
24H1471	WASHER	2.00	3.12	3.12	\$6.24	N
24H1864	WASHER	1.00	0.95	0.95	\$0.95	N
34M7049	Spring Pin M8 X 50	1.00	2.62	2.62	\$2.62	N
AH214009	Structural Tube Left Side	1.00	192.10	192.10	\$192.10	N
AH214010	Structural Tube Right Side	1.00	171.24	171.24	\$171.24	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 9/3/2024 Location: Work Order Number: Payment Type: Page: 3 of 4
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2014 JD 615P PICKUP PLATFORM		1H00615PAE0765696	1H00615PAE0765696	

Gen5- Internal								
SERVACCESS	SERVICE ACCESSORIES	1.00	18.59	18.59	\$18.59	N		
Labor: \$309.75		Parts: \$374.67		OL&M: \$0.00		Misc: \$18.59		Sub-Total: \$703.01

/170051615P F Internal
 COMPLAINT:
 06 REPLACE TABLE AUGER DRIVE CHAIN

CORRECTION:
 REMOVED OLD CHAIN AND REPLACED. TENSIONED CHAIN TO SPEC.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>		
AH215201	Roller Chain #80H (78 Links)	1.00	492.60	492.60	\$492.60	N		
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>		
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N		
Labor: \$44.25		Parts: \$492.60		OL&M: \$0.00		Misc: \$2.66		Sub-Total: \$539.51

/140621615P F Internal
 COMPLAINT:
 07 GREASE HEADER

CORRECTION:
 GREASED HEADER

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY6341	SD POLYUREA GREASE	1.00	10.31	10.31	\$10.31	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>





Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:
 Invoice Date: 9/3/2024
 Location:
 Work Order Number:
 Payment Type:
 Page: 4 of 4

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2014 JD 615P PICKUP PLATFORM		1H00615PAE0765696	1H00615PAE0765696	

/140621615P F Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	3.51	3.51	\$3.51		N
Labor: \$58.41	Parts: \$10.31	OL&M: \$0.00	Misc: \$3.51	Sub-Total: \$72.23			

Customer PO No:
 Tax Exempt No:
 Advisor:

Labor:	\$990.66
Parts:	\$892.52
OL&M:	\$0.00
Misc:	\$47.13
Grand Total:	\$1,930.31

*** DOCUMENT COPY ***

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
00 00	160	1	147693			USED AG EQUIPMENT
05 40	382	1	18540			INTERNAL LABOR-AG
00 00	178	15	18540			WORK IN PROCESS PARTS -MJ
05 40	482	1	18540			COS INTERNAL LABOR-AG
05 40	544	1	18540			SUPPLIES EXPENSE
05 30	366	2	18540			JD PARTS-COUNTER
00 00	166	5	18540			JD PARTS-MOOSE JAW
05 30	466	2	18540			JD PARTS-COUNTER

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:Date: