



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 1 of 34
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

/SPX9 1000 Internal
 COMPLAINT:
 01 GREENLIGHT SERVICE INSPECTION COMBINE

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY27786	WINTER FUEL CONDITIONER 946ML	2.00	32.00	32.00	\$64.00	N
Labor: \$2,599.00		Parts: \$64.00		OL&M: \$0.00		Misc: \$0.00
Sub-Total: \$2,663.00						

Gen2- Internal
 COMPLAINT:
 02 LUBE GULLWING LATCHES - STIFF

CORRECTION:
 lubed all gullwing latches, easier to open

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	4.46	4.46	\$4.46	N
Labor: \$74.40		Parts: \$0.00		OL&M: \$0.00		Misc: \$4.46
Sub-Total: \$78.86						

Gen3- Internal
 COMPLAINT:
 03 REPLACE LH FEEDERHOUSE SHIELD CLIP TIE - BROKEN

CORRECTION:
 removed damaged shield clip tie and installed new clip tie

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 7/31/2025 Location: Work Order Number: Payment Type: Page: 2 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	

Gen3- Internal

H167815	Lynch Strap Pin	1.00	7.76	7.76	\$7.76	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	1.12	1.12	\$1.12	N

Labor: \$18.60 Parts: \$7.76 OL&M: \$0.00 Misc: \$1.12 Sub-Total: \$27.48

Gen4- Internal

COMPLAINT:
 04 REPAIR OR REPLACE LH SAFETY SHIELD - BENT BAD

CORRECTION:
 replaced 2 x bent plates

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE90356	Shield	1.00	385.76	385.76	\$385.76	N
HXE19597	Deflector	1.00	218.64	218.64	\$218.64	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
FREIGHT	FREIGHT	1.00	20.00	20.00	\$20.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N

Labor: \$93.00 Parts: \$604.40 OL&M: \$0.00 Misc: \$25.58 Sub-Total: \$722.98

/150428X9 1000 Internal

COMPLAINT:
 05 INSTALL WATER FIRE EXTINGUISHER - MISSING

CORRECTION:
 found fire extinguisher on combine, empty out water to prevent freezing during winter if not sold

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 7/31/2025 Location: Work Order Number: Payment Type: Page: 3 of 34
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	

/150428X9 1000 Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	1.12	1.12	\$1.12	N	
Labor: \$18.60	Parts: \$0.00	OL&M: \$0.00	Misc: \$1.12	Sub-Total: \$19.72			

Gen6- Internal
 COMPLAINT:
 06 REMOVE NUMBER DECALS

CORRECTION:
 removed [redacted] decals on left, right and rear

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
Labor: \$93.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$5.58	Sub-Total: \$98.58		

/120014X9 1000 Internal
 COMPLAINT:
 07 GREASE COMBINE

CORRECTION:
 greased combine



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
T460	POLYUREA GREASE	1.00	10.89	10.89	\$10.89	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
Labor: \$186.00	Parts: \$10.89	OL&M: \$0.00	Misc: \$11.16	Sub-Total: \$208.05		

/120471X9 1000 Internal
 COMPLAINT:



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 4 of 34
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

/120471X9 1000 Internal
 08 ADJUST ALL BELTS

CORRECTION:
 adjusted belt tensions

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
Labor: \$186.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$11.16	Sub-Total: \$197.16		

GEN9- Internal
 COMPLAINT:
 09 REPAIR BOTTOM CAB LADDER STEP - BENT

CORRECTION:
 removed bent step and brackets, bent straight and installed

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
Labor: \$186.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$11.16	Sub-Total: \$197.16		

/170222X9 1000 Internal
 COMPLAINT:
 10 TOP UP WASHER FLUID

CORRECTION:
 topped up washer fluid

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
WASHER	W/W Fluid 4 lt Jug	1.00	6.99	6.99	\$6.99	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 5 of 34
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

/170222X9 1000 Internal						
SERVACCESS	DESCRIPTION	QTY	LIST PRICE	NET PRICE	EXTENDED PRICE	TAXED IND
	SERVICE ACCESSORIES	1.00	2.79	2.79	\$2.79	N
Labor: \$46.50		Parts: \$6.99		OL&M: \$0.00		Misc: \$2.79
Sub-Total: \$56.28						

/110302X9 1000 Internal
 COMPLAINT:
 11 REMOVE 2 WAY RADIO AND ANTENNA

CORRECTION:
 removed antenna, installed cap, removed 2 way radio, removed interior cab panel and removed 2 way wiring, installed can panel

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	13.95	13.95	\$13.95	N
Labor: \$232.50		Parts: \$0.00		OL&M: \$0.00		Misc: \$13.95
Sub-Total: \$246.45						

GEN12- Internal
 COMPLAINT:
 12 REMOVE ALL PERSONAL ITEMS FROM CAB AND TOOLBOX

CORRECTION:
 removed personal items from cab and toolbox

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	3.91	3.91	\$3.91	N
Labor: \$65.10		Parts: \$0.00		OL&M: \$0.00		Misc: \$3.91
Sub-Total: \$69.01						

/110176X9 1000 Internal
 COMPLAINT:



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 7/31/2025 Location: Work Order Number: Payment Type: Page: 6 of 34
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	

/110176X9 1000 Internal
 13 CHECK OUT ALL CODES FOUND ON GREENLIGHT
 VTI 524055.16

CORRECTION:
 VTI 524055.16, less than 5% capacity left - exported all data to usb, deleted all data off of monitor, code cleared and not appearing anymore.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
Labor: \$186.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$11.16	Sub-Total: \$197.16	

/140968AX9 1000 Internal
 COMPLAINT:
 14 UPDATE ALL MACHINE CONTROLLERS SOFTWARE

CORRECTION:
 updated all required software updates

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	27.90	27.90	\$27.90	N
Labor: \$465.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$27.90	Sub-Total: \$492.90	

GEN15- Internal
 COMPLAINT:
 15 RE-INSTALL RH SUN VISOR - INSTALLED BACKWARDS

CORRECTION:
 removed and reinstalled visor the correct way

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 7 of 34
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

GEN15- Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	3.35	3.35	\$3.35		N
Labor: \$55.80	Parts: \$0.00	OL&M: \$0.00	Misc: \$3.35	Sub-Total: \$59.15			

GEN16- Internal
 COMPLAINT:
 16 CLEAN OUT FEED ACCELERATOR

CORRECTION:
 removed top feederhouse cover, removed feed accelerator hardware and plate, cleaned debris out, installed in reverse order

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	33.48	33.48	\$33.48	N
Labor: \$558.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$33.48	Sub-Total: \$591.48		

/110014X9 1000 Internal
 COMPLAINT:
 17 ADJUST FEEDERHOUSE DRIVE CHAIN & LUBE

CORRECTION:
 adjusted feederhouse drive chain and lubed with chain lube

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26350	CHAIN LUBE	1.00	14.71	14.71	\$14.71	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	2.23	2.23	\$2.23	N
Labor: \$37.20	Parts: \$14.71	OL&M: \$0.00	Misc: \$2.23	Sub-Total: \$54.14		

GEN18- Internal
 COMPLAINT:



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 7/31/2025 Location: Work Order Number: Payment Type: Page: 8 of 34
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	

GEN18- Internal

18 REMOVE FEEDERHOUSE SLIP CLUTCH AND CHECK SPLINES

CORRECTION:

removed feederhouse drive chain, removed slip clutch inspected splines, added anti seize to splines, installed slip clutch torqued bolt to spec, installed drive chain

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
19M7804	Flange Head Cap Screw M10 X 40 GR10.9	1.00	3.55	3.55	\$3.55	N
Miscellaneous	DESCRIPTION	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
Labor: \$93.00		Parts: \$3.55	OL&M: \$0.00	Misc: \$5.58	Sub-Total: \$102.13	

/11550X9 1000 Internal

COMPLAINT:

19 ADJUST FEEDERHOUSE CONVEYOR CHAIN TENSION

CORRECTION:

adjusted feederhouse chain tension

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
Labor: \$93.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$5.58	Sub-Total: \$98.58	

GEN20- Internal

COMPLAINT:

20 WELD TABS BACK ON DRIVESHAFT SHIELDS - BOTH SIDES BROKEN

CAUSE:

removed feederhouse driveshaft shields, 4 tabs broken off completely the bolts were holding them in place. cleaned off paint, welded tabs back to shields, primed and painted shields, installed shields



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 7/31/2025 Location: Work Order Number: Payment Type: Page: 9 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	

GEN20- Internal

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
Labor: \$186.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$11.16	Sub-Total: \$197.16	

GEN21- Internal

COMPLAINT:

21 REPLACE ALL 8 UPPER AND LOWER FEEDERHOUSE CONVEYOR LITTLE STRIPS - WORN PAST SLANT

CORRECTION:

loosened off feederhouse conveyor chain tension, removed 8 x wear strips, installed 8 new wear strips, one rivnut spinning in hole had to cut bolt and rivnut out and install new rivnut, adjusted conveyor chain tension, installed top door on feederhouse

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
H154370	NUT	1.00	3.35	3.35	\$3.35	N
HXE144929	Strip	8.00	74.22	74.22	\$593.76	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	35.71	35.71	\$35.71	N
Labor: \$595.20		Parts: \$597.11	OL&M: \$0.00	Misc: \$35.71	Sub-Total: \$1,228.02	

GEN23- Internal

COMPLAINT:

23 REPLACE SHEAR BOLT AT HEADER LOCKING PINS - BROKEN

CORRECTION:

removed damaged shear bolt and installed new shear bolt and nut

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 7/31/2025 Location: Work Order Number: Payment Type: Page: 10 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	

GEN23- Internal

14M7264	Hex Lock Nut M4	1.00	0.49	0.49	\$0.49	N
19M9326	Socket Head Screw M4 X 30 GR12.9	1.00	2.12	2.12	\$2.12	N

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	1.12	1.12	\$1.12	N

Labor: \$18.60 Parts: \$2.61 OL&M: \$0.00 Misc: \$1.12 Sub-Total: \$22.33

/150290X9 1000 Internal

COMPLAINT:
24 CLEAN UNLOADING AUGER SUMP OF DEBRIS

CORRECTION:
cleaned all debris from unloading auger sump

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N

Labor: \$93.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$5.58 Sub-Total: \$98.58

GEN25- Internal

COMPLAINT:
25 CLEAN OUT FRONT SHAKER FAN

CORRECTION:
cleaned out debris from front shaker pan

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	8.37	8.37	\$8.37	N

Labor: \$139.50 Parts: \$0.00 OL&M: \$0.00 Misc: \$8.37 Sub-Total: \$147.87



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 11 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

GEN26- Internal

COMPLAINT:

26 SET MECHANICAL ADJUST OF LOUVERS TO 1" AND INSTALL HOLDER PART # X9BOLT

CORRECTION:

adjusted element louvers to 1" and installed x9 bolt

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
X9BOLT	X9 FRONT CHAFFER BOLT RETAINER.	1.00	69.95	69.95	\$69.95	N
Miscellaneous	DESCRIPTION	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	2.79	2.79	\$2.79	N
Labor: \$46.50		Parts: \$69.95	OL&M: \$0.00	Misc: \$2.79	Sub-Total: \$119.24	

/10180250AX9 1000 Internal

COMPLAINT:

27 CONCAVE LEVEL, ADJUST, AND CALIBRATE (WITH ACI), REPEAT PROCEDURE ON OPPOSITE SIDE

CORRECTION:

did concave leveling and calibration with ACI procedure

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	50.22	50.22	\$50.22	N
Labor: \$837.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$50.22	Sub-Total: \$887.22	

/101802500X9 1000 Internal

COMPLAINT:

28 CONCAVE, R&R - LH SIDE #6 HAS BENT BARS & RH SIDE #6 HAS BENT BARS

CORRECTION:

Remove side covers.Lower concave.Remove retainers, hardware and concaves.Reassemble.



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 12 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

/101802500X9 1000 Internal

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	41.96	41.96	\$41.96	N
Labor: \$699.36		Parts: \$0.00	OL&M: \$0.00	Misc: \$41.96	Sub-Total: \$741.32	

/110259X9 1000 Internal

COMPLAINT:

29 WELD AND REPAIR CONCAVE AS NEEDED (WHEN OUT) - LH SIDE #6 HAS BENT BARS & RH SIDE #6 HAS BENT BARS

CORRECTION:

left hand number 3,5,6 and right hand number 1,2,5,6 all had bent bars. heated bars and bent straight, welded cracks

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	33.48	33.48	\$33.48	N
Labor: \$558.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$33.48	Sub-Total: \$591.48	

GEN30- Internal

COMPLAINT:

30 REALIGN FRONT END DRIVE BELT & PULLEY

CORRECTION:

removed belt, shimmed pulley out, adjusted idler alignment, installed and tension belt, hardware torqued

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
Labor: \$186.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$11.16	Sub-Total: \$197.16	

GEN31- Internal

COMPLAINT:



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 7/31/2025 Location: Work Order Number: Payment Type: Page: 13 of 34
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	

GEN31- Internal

31 REPLACE 2 SEPARATOR FINGER GRATE - INNER FRONT ONE BROKEN

CORRECTION:

removed separator covers, removed outer middle and inner grates at 1st and 3rd row, installed new inner grates, installed old middle and outer grates.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE108431	Separator Grate	2.00	379.09	379.09	\$758.18	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
Labor: \$186.00		Parts: \$758.18		OL&M: \$0.00		Misc: \$11.16
						Sub-Total: \$955.34

/10180120X91000 Internal

COMPLAINT:

32 REPLACE 3 BROKEN SEPARATOR TINES - 1 ON LH SIDE AND 2 ON RH SIDE

CORRECTION:

Remove separator grate covers as necessary to access tines. Remove worn tines and discard hardware. Important: Always install three tines to maintain proper rotor balance. Install new tines to specification using new hardware. Check balance and test run.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
KXE10959	TINE KIT.	3.00	322.15	322.15	\$966.45	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	27.90	27.90	\$27.90	N
Labor: \$465.00		Parts: \$966.45		OL&M: \$0.00		Misc: \$27.90
						Sub-Total: \$1,459.35

GEN33- Internal

COMPLAINT:

33 CLEAN OUT TAILINGS AUGER TROUGH UNDERNEATH



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 14 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

GEN33- Internal

CORRECTION:

cleaned out tailings auger underneath

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.35	3.35	\$3.35	N
Labor: \$55.80		Parts: \$0.00		OL&M: \$0.00		Misc: \$3.35
						Sub-Total: \$59.15

/110016X9 1000 Internal

COMPLAINT:

34 ADJUST TAILINGS PADDLE CHAIN

CORRECTION:

adjusted chain tension to correct tension

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.23	2.23	\$2.23	N
Labor: \$37.20		Parts: \$0.00		OL&M: \$0.00		Misc: \$2.23
						Sub-Total: \$39.43

/170531X9 1000 Internal

COMPLAINT:

35 CLEAN ACTIVE VISION CAMERA LENSES

CORRECTION:

cleaned debris off of camera lenses

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	8.37	8.37	\$8.37	N
Labor: \$139.50		Parts: \$0.00		OL&M: \$0.00		Misc: \$8.37
						Sub-Total: \$147.87



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 7/31/2025 Location: Work Order Number: Payment Type: Page: 15 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	

GEN36- Internal

COMPLAINT:

36 CLEAN OFF ACTIVE TAILINGS WEAR STRIPS - CAKED ON DEBRIS

CORRECTION:

loosened off belt tensioner so can spin freely, cleaned debris off of wear strips, installed belt

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.35	3.35	\$3.35	N
Labor: \$55.80		Parts: \$0.00	OL&M: \$0.00	Misc: \$3.35	Sub-Total: \$59.15	

GEN37- Internal

COMPLAINT:

37 REPAIR LH SIDE BLACK CANISTER - LEAKING, HOSE CLAMP

CORRECTION:

tightened up loose hose clamp

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.79	2.79	\$2.79	N
Labor: \$46.50		Parts: \$0.00	OL&M: \$0.00	Misc: \$2.79	Sub-Total: \$49.29	

GEN38- Internal

COMPLAINT:

38 REPLACE SOLID SINGULAR BOLT ON CHOPPER COUNTERKNIFE

CORRECTION:

replaced counterknife and bolt

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 16 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

GEN38- Internal

HXE21494	Extra Fine Cut Stationary Blade	1.00	126.33	126.33	\$126.33	N
<u>Miscellaneous</u> SERVACCESS	<u>Description</u> SERVICE ACCESSORIES	<u>Quantity</u> 1.00	<u>List Price</u> 2.23	<u>Net Price</u> 2.23	<u>Extended Price</u> \$2.23	<u>Taxed Ind</u> N

Labor: \$37.20 Parts: \$126.33 OL&M: \$0.00 Misc: \$2.23 Sub-Total: \$165.76

/10172010X9 1000 Internal

COMPLAINT:
 39 R&R STRAW CHOPPER HAMMERS - SOME HAVE BEEN FLIPPED & ALL WORN

CORRECTION:
 removed all chopper knives and hardware, installed new knives and hardware, torqued to spec

HXE118760	Lock Nut M10	34.00	2.63	2.63	\$89.42	N
KXE10255	Knife Kit	-8.00	414.00	414.00	(\$3,312.00)	N
KXE11195	Knife Kit - 8 Blades per Kit	8.00	429.92	429.92	\$3,439.36	N
<u>Miscellaneous</u> SERVACCESS	<u>Description</u> SERVICE ACCESSORIES	<u>Quantity</u> 1.00	<u>List Price</u> 33.48	<u>Net Price</u> 33.48	<u>Extended Price</u> \$33.48	<u>Taxed Ind</u> N

Labor: \$558.00 Parts: \$216.78 OL&M: \$0.00 Misc: \$33.48 Sub-Total: \$808.26

GEN40- Internal

COMPLAINT:
 40 REPLACE SNAP PINS ON WIND ROW CURTAIN - MISSING

CORRECTION:
 installed snap pin on curtain and hang curtain at the top like it should be

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 17 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

GEN40- Internal

M72598	Quick Lock Pin	1.00	4.59	4.59	\$4.59	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	1.12	1.12	\$1.12	N

Labor: \$18.60 Parts: \$4.59 OL&M: \$0.00 Misc: \$1.12 Sub-Total: \$24.31

/110305X9 1000 Internal

COMPLAINT:
 41 CLEAN OUT SIEVE & CHAFFER SO CAN ADJUST

CORRECTION:
 cleaned out sieve and chaffer elements

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N

Labor: \$93.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$5.58 Sub-Total: \$98.58

/110081X9 1000 Internal

COMPLAINT:
 42 R&R SIEVE & CHAFFER TO CHECK FOR CRACKS

CORRECTION:
 removed chaffer tailboard, removed chaffer element, removed sieve element, fixed bent louvers on chaffer and sieve, installed sieve, chaffer and tailboard, hardware torqued

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	33.48	33.48	\$33.48	N

Labor: \$558.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$33.48 Sub-Total: \$591.48



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 18 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

/180015X9 1000 Internal

COMPLAINT:
 43 PREFORM INSTALL CALIBRATION OF SIEVE & CHAFFER

CORRECTION:
 calibrated sieve and chaffer element

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
Labor: \$186.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$11.16	Sub-Total: \$197.16	

GEN44- Internal

COMPLAINT:
 44 CLEAN OUT TAILBOARD & INSTALL CORRECTLY

CORRECTION:
 cleaned out tailboard and installed tailboard correctly

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	8.37	8.37	\$8.37	N
Labor: \$139.50		Parts: \$0.00	OL&M: \$0.00	Misc: \$8.37	Sub-Total: \$147.87	

GEN45- Internal

COMPLAINT:
 45 CLEAN OUT RETURN PAN

CORRECTION:
 cleaned out return pan

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
---------------	-------------	----------	------------	-----------	----------------	-----------



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 7/31/2025 Location: Work Order Number: Payment Type: Page: 19 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	

GEN45- Internal	SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
Labor: \$93.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$5.58	Sub-Total: \$98.58		

/1200250X9 1000 Internal
 COMPLAINT:
 46 CLEAN OUT PRECLEANER ELEMENT

CORRECTION:
 cleaned out pre cleaner element

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
Labor: \$93.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$5.58	Sub-Total: \$98.58	

GEN47- Internal
 COMPLAINT:
 47 REPAIR PRECLEANER ELEMENT - VERY LOOSE

CORRECTION:
 torqued pre cleaner element hold down cap screws - none were loose.
 removed fuel precleaner, cleaned out and reinstall

greenlight inspection sheet was for "fuel precleaner filter clean out and very loose" not pre cleaner element

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
Labor: \$186.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$11.16	Sub-Total: \$197.16	



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 20 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

/160023X9 1000 Internal
 COMPLAINT:
 48 REPLACE VACUUM FAN ROUND SEAL

CORRECTION:
 removed damaged seal, installed new seal

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE38720	Weatherstrip	1.00	93.32	93.32	\$93.32	N
Miscellaneous	SERVICE ACCESSORIES	1.00	2.79	2.79	\$2.79	N
Labor: \$46.50		Parts: \$93.32		OL&M: \$0.00		Misc: \$2.79
Sub-Total: \$142.61						

GEN49- Internal
 COMPLAINT:
 49 REPAIR POSITIVE CABLE ON BATTERY DISCONNECT - LOOSE ON SHUT OFF SWITCH

CORRECTION:
 removed battery box cover, tightened up positive cable on disconnect

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
Labor: \$93.00		Parts: \$0.00		OL&M: \$0.00		Misc: \$5.58
Sub-Total: \$98.58						

GEN50- Internal
 COMPLAINT:
 50 CLEAN OUT CLEAN GRAIN AUGER TROUGH UNDERNEATH COMBINE

CORRECTION:
 cleaned debris from clean grain auger underneath



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 21 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

GEN50- Internal

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.35	3.35	\$3.35	N
Labor: \$55.80		Parts: \$0.00		OL&M: \$0.00		Misc: \$3.35
Sub-Total: \$59.15						

/110015X9 1000 Internal
 COMPLAINT:
 51 ADJUST CLEAN GRAIN PADDLE CHAIN

CORRECTION:
 adjusted chain tension to correct tension

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.23	2.23	\$2.23	N
Labor: \$37.20		Parts: \$0.00		OL&M: \$0.00		Misc: \$2.23
Sub-Total: \$39.43						

GEN52- Internal
 COMPLAINT:
 52 CLEAN CLEAN GRAIN CAMERA LENSE

CORRECTION:
 cleaned debris off of camera lense

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.35	3.35	\$3.35	N
Labor: \$55.80		Parts: \$0.00		OL&M: \$0.00		Misc: \$3.35
Sub-Total: \$59.15						

GEN53- Internal
 COMPLAINT:



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 22 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

GEN53- Internal

53 REPLACE KNOB AND LITTLE PLATE MISSING AT SEPARATING COVERS (done on segment 54)

CORRECTION:

installed new nob and plate that was missing

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE157294	Plate	1.00	30.82	30.82	\$30.82	N
HXE167838	Knob	1.00	15.57	15.57	\$15.57	N
Labor: \$0.00		Parts: \$46.39	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$46.39	

GEN54- Internal

COMPLAINT:

54 REPAIR OR REPLACE 1 SEIZED KNOB AND 1 KNOB WON'T TIGHTEN AT SEPARATING COVERS

CORRECTION:

two knobs were seized, cut off knobs extracted remaining bolt, cleaned hole and installed new knobs, one wont tightened - removed cleaned and lubed hole and tightened like it should

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
14M7296	Flange Nut M10	3.00	2.06	2.06	\$6.18	N
HXE167838	Knob	2.00	15.57	15.57	\$31.14	N
R44302	TIE BAND 7"	1.00	0.45	0.45	\$0.45	N
Miscellaneous	DESCRIPTION	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	8.37	8.37	\$8.37	N
Labor: \$139.50		Parts: \$37.77	OL&M: \$0.00	Misc: \$8.37	Sub-Total: \$185.64	

GEN55- Internal

COMPLAINT:

55 REMOVE FEED ACCELERATOR PULLEY BUFF AND PAINT - BLACK



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 7/31/2025 Location: Work Order Number: Payment Type: Page: 23 of 34
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	

GEN55- Internal

CORRECTION:

removed belt off of driven pulley, removed pulley and hardware, buffed and painted pulley with JD primer and then paint, installed pulley - hardware torqued, installed belt

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY25624	Paint Ag/CCE Green Spray Bomb	1.00	20.07	20.07	\$20.07	N
TY26268	BUFF PRIMER SPRAY	1.00	15.84	15.84	\$15.84	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF25	ENVIRO FEE	2.00	0.25	0.23	\$0.46	N
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
Labor: \$186.00		Parts: \$35.91		OL&M: \$0.00		Misc: \$11.62
						Sub-Total: \$233.53

GEN56- Internal

COMPLAINT:

56 REPAIR ENGINE DECK LADDER LATCH AND CABLE - VERY STIFF

CORRECTION:

cable very stiff, removed cable - had a kink not moving freely, replaced cable and adjusted

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE82464	Push Pull Cable	2.00	243.87	243.87	\$487.74	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	3.35	3.35	\$3.35	N
Labor: \$55.80		Parts: \$487.74		OL&M: \$0.00		Misc: \$3.35
						Sub-Total: \$546.89

/10030020X9 1000 Internal

COMPLAINT:

57 ROTARY SCREEN SMALL DRIVE BELT, REMOVE AND REPLACE - CRACKING OUT



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 24 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

/10030020X9 1000 Internal

CORRECTION:
 removed damaged rotary screen small drive belt, installed new belt

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE184110	Rotary Screen Drive Belt (Eng Side)	1.00	113.09	113.09	\$113.09	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	8.37	8.37	\$8.37	N
Labor: \$139.50		Parts: \$113.09	OL&M: \$0.00	Misc: \$8.37	Sub-Total: \$260.96	

/170208X9 1000 Internal

COMPLAINT:
 58 TOP UP COOLANT - VERY LOW

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY26576	9.46L COOL-GARD PREMIX	1.00	61.58	61.58	\$61.58	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF240	ENVIRO FEE	1.00	2.40	2.16	\$2.16	N
SERVACCESS	SERVICE ACCESSORIES	1.00	1.12	1.12	\$1.12	N
Labor: \$18.60		Parts: \$61.58	OL&M: \$0.00	Misc: \$3.28	Sub-Total: \$83.46	

GEN59- Internal

COMPLAINT:
 59 TIGHTEN ALL HOSE CLAMPS

CORRECTION:
 tightened up hose clamps



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 25 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

GEN59- Internal

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
Labor: \$186.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$11.16	Sub-Total: \$197.16	

GEN60- Internal

COMPLAINT:
 60 REPLACE FUEL TANK FILL SCREEN - MISSING

CORRECTION:
 fuel tank fill screen installed

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
R183142	SCREEN	1.00	201.41	201.41	\$201.41	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	1.12	1.12	\$1.12	N
Labor: \$18.60		Parts: \$201.41	OL&M: \$0.00	Misc: \$1.12	Sub-Total: \$221.13	

/110040X9 1000 Internal

COMPLAINT:
 61 TOP UP OIL IN ENGINE/ SEPARATOR GEARCASE

CORRECTION:
 topped up oil in separator/engine gearcase

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY6354	3.78L HYGARD HYD/TRANS OIL J20C	1.00	35.61	35.61	\$35.61	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF50	ENVIRO FEE	1.00	0.50	0.45	\$0.45	N



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 7/31/2025 Location: Work Order Number: Payment Type: Page: 26 of 34
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	

/110040X9 1000 Internal						
SERVACCESS	SERVICE ACCESSORIES	1.00	3.35	3.35	\$3.35	N
Labor: \$55.80		Parts: \$35.61	OL&M: \$0.00	Misc: \$3.80	Sub-Total: \$95.21	

GEN62- Internal
 COMPLAINT:
 62 REPLACE HYDRAULIC RESERVOIR BREATHER

CORRECTION:
 removed and replaced hydraulic reservoir

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE82230	Hydraulic Reservoir Breather	1.00	135.61	135.61	\$135.61	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.23	2.23	\$2.23	N
Labor: \$37.20		Parts: \$135.61	OL&M: \$0.00	Misc: \$2.23	Sub-Total: \$175.04	

GEN63- Internal
 COMPLAINT:
 63 REPLACE ENGINE COMPARTMENT DOOR TOP SHOCKS - GETTING WEAK

CORRECTION:
 support door up and removed 2 weak shocks and installed new shocks

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH232248	Gas Operated Cylinder	2.00	193.12	193.12	\$386.24	N
H236461	Ball Stud	2.00	24.29	24.29	\$48.58	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 27 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	# 6

GEN63- Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N	
Labor: \$93.00	Parts: \$434.82	OL&M: \$0.00	Misc: \$5.58	Sub-Total: \$533.40			

/10230100AX9 1000 Internal
 COMPLAINT:
 64 R&R CLEAN GRAIN LOADING AUGER - GETTING SHARP SHOULD LAST ANOTHER YEAR

CORRECTION:
 inspected clean grain auger in hopper, not needed to replace at this time

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	8.37	8.37	\$8.37	N
Labor: \$139.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$8.37	Sub-Total: \$147.87		

/170169S780 Internal
 COMPLAINT:
 66 REPLACE UNLOADING AUGER PLASTIC DOWNSPOUT - NOT FOLDING PROPERLY

CORRECTION:
 removed spout, spout holding and pivot brackets are bent, removed damaged brackets and installed new brackets and spout

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE103448	Hinge	1.00	254.72	254.72	\$254.72	N
AXE103449	Bracket	1.00	660.77	660.77	\$660.77	N
HXE170706	Boot	1.00	897.35	897.35	\$897.35	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 28 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

/170169S780 Internal					
SERVACCESS	SERVICE ACCESSORIES	1.00	24.55	24.55	\$24.55 N
Labor: \$409.20		Parts: \$1,812.84	OL&M: \$0.00	Misc: \$24.55	Sub-Total: \$2,246.59

/GLOPCLEANX9 1000 Internal
 COMPLAINT:
 67 GREENLIGHT CLEANING CHECKLIST

 MOVED TO SEPARATE WORK ORDER

 CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
----------------------	----------------------	-------------------------	---------------------	--------------------------

EMD414566 Internal
 COMPLAINT:





1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 29 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

EMD414566 Internal

68 1 Expert Alerts on this ticket
 EA1- StarFire GNSS Navigation Models Unusable - Universal Receiver
 What is the problem or opportunity?

The receiver is no longer accounting for tidal and seismic ground movement, which can lead to tracking errors. This can have a negative impact on corrections in areas where seismic or tidal activity causes ground movement in the short or long term. If you are in a region without such influences, this will not affect performance.

This alert is specific to the PIN of the receiver with the issue. This machine may have multiple receivers installed and the customer may swap out receivers. Please get the PIN from the plot in the Alert Trigger section of the Expert Alert page.

If no action is taken, what will be the impact to the machine?

Loss of repeatability for all signal levels used by the receiver. Data may be recorded in an incorrect location. The DTC 517027.02 will remain active until the interactive solution is followed.

Any errors from this alert may take time to show up as it takes time for the ground to move under the machine. It is recommended to fix this even if there is nothing observed as by the time the ground has shifted it is too late to fix the issue, and data will need re-recorded as the receiver will be unable to compensate for the movement of the ground.

What might the operator be experiencing?

Line shift or movement. Inability to go over the same pass after some time passes. Boundaries or maps shifted. Loss of repeatability from one machine to another or one season to another. The receiver that is sending this alert may not be used for the customers current operation; we are only able to tell that the receiver is installed and sending the alert, not that it is in use.

What is triggering this Expert Alert?

DTC 517027.02 from the universal receiver on the setup. Loss of navigation models on the receiver. Ensure that you are addressing the correct receiver that triggered the alert. Use the receiver PIN in the alert picture to confirm. This could be on the machine or the implement. The receiver at fault may not be on the setup anymore.

WHAT WAS THIS FOR ?

This popped up before the repairs happened we had to do firmware on the receiver in order to rectify the code

CORRECTION:



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 30 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

EMD414566 Internal

EA1- StarFire GNSS Navigation Models Unusable - Universal Receiver

What is the recommended action?

Inform the customer about the issue identified. Complete the Interactive Solution at the next service opportunity.

What parts should I take with me?

Software for the receiver.

What service tools will I need?

None.

<https://interactivesolutions.deere.com/prweb/PRAuth/ISR?pziuaionzzz=CXtpbn1ZZTNFNFRsNEtpWVBlcUJFVURLa25wNHVoQVVEN2>

followed expert elert solution, Ocean Tide Model was invalid, updated starfire 6000 reciever, updated navigation models on reciever, after all updates on reciever were done according to procedure Ocean Tide Model status changed to 1.01, code not appearing anymore.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	21.32	21.32	\$21.32	N
Labor: \$355.26		Parts: \$0.00		OL&M: \$0.00		Misc: \$21.32
						Sub-Total: \$376.58

GEN69- Internal

COMPLAINT:

69 DIAGNOSE HIGH PITCH NOISE

CORRECTION:

noise came from cracked out small rotary drive belt

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	9.82	9.82	\$9.82	N
Labor: \$163.68		Parts: \$0.00		OL&M: \$0.00		Misc: \$9.82
						Sub-Total: \$173.50

/110103X9 1000 Internal

COMPLAINT:

70 STRAIGHTEN OR REPLACE FEEDER CHAIN SLAT - ONE



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 7/31/2025 Location: Work Order Number: Payment Type: Page: 31 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	

/110103X9 1000 Internal

CORRECTION:

3 bent feederhouse slats, removed slats and straightened out bent parts

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
Labor: \$93.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$5.58	Sub-Total: \$98.58	

/170353X9 1000 Internal

COMPLAINT:

71 BLOWOUT BATTERY BOX

CORRECTION:

cleaned out battery box

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.79	2.79	\$2.79	N
Labor: \$46.50		Parts: \$0.00	OL&M: \$0.00	Misc: \$2.79	Sub-Total: \$49.29	

GEN72- Internal

COMPLAINT:

72 DIAGNOSE WATER LEAK INTO CAB

CORRECTION:

removed front and rear roof panels to inspect for water leak, no water signs found at speaker or close to that. little water marks found in both front left and right corners. one hold down bolt bushing missing on right and one bolt seal washer ripped on left, replaced washer and bushing, installed roof panels

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
L200226	Washer	1.00	4.35	4.35	\$4.35	N



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 32 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

GEN72- Internal

L203073	Bushing	1.00	24.47	24.47	\$24.47	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	28.01	28.01	\$28.01	N

Labor: \$466.86 Parts: \$28.82 OL&M: \$0.00 Misc: \$28.01 Sub-Total: \$523.69

GEN73- Internal

COMPLAINT:
73 CALIBRATE TCM

CORRECTION:
calibrated TCM according to procedure

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.02	5.02	\$5.02	N

Labor: \$83.70 Parts: \$0.00 OL&M: \$0.00 Misc: \$5.02 Sub-Total: \$88.72

GEN74- Internal

COMPLAINT:
74 REPLACE PLASTIC COVERS ON GRAIN BIN DOORS

CORRECTION:
removed broken plastic covers and installed new plastic covers

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
H240320	Shield	1.00	297.37	297.37	\$297.37	N
HXE166125	SHIELD	1.00	312.79	312.79	\$312.79	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/31/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 33 of 34
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	[REDACTED]

GEN74- Internal								
SERVACCESS	SERVICE ACCESSORIES	1.00	4.24	4.24	\$4.24	N		
Labor: \$70.68		Parts: \$610.16		OL&M: \$0.00		Misc: \$4.24		Sub-Total: \$685.08

/110377X9 1000 Internal
 COMPLAINT:
 75 RERUN AFTER REPAIRS

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
Labor: \$186.00		Parts: \$0.00		OL&M: \$0.00		Misc: \$11.16
Sub-Total: \$197.16						

GEN76- Internal
 COMPLAINT:
 76 REPAIR CODE ECU 97.03

CORRECTION:

ECU 97.03 - water in fuel circuit fault - after following diagnostic procedure I found that water in fuel sensor is faulty. sensor replaced, code not appearing anymore

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE542107	SENSOR	1.00	175.04	175.04	\$175.04	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



1731 Main Street N.
 Moose Jaw, SK S6J 1L6
 Phone: 306-692-2371
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:
 Invoice Date: 7/31/2025
 Location:
 Work Order Number:
 Payment Type:
 Page: 34 of 34

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1103	1H0X910XAN0820029	1H0X910XAN0820029	

GEN76- Internal	SERVACCESS	SERVICE ACCESSORIES	1.00	12.16	12.16	\$12.16	N
Labor: \$202.74		Parts: \$175.04	OL&M: \$0.00	Misc: \$12.16	Sub-Total: \$389.94		

INVOICE CONTAINS \$0.33 DISCOUNT

Customer PO No:
 Tax Exempt No:
 Advisor:

Labor:	\$15,029.38
Parts:	\$7,764.41
OL&M:	\$0.00
Misc:	\$768.91
Grand Total:	\$23,562.70

*** DOCUMENT COPY ***

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
00	00	160	1		149384	USED AG EQUIPMENT
01	40	382	1		7194	INTERNAL LABOR-AG
00	00	178	11		7194	WORK IN PROCESS PARTS -MJ
01	40	482	1		7194	COS INTERNAL LABOR-AG
01	30	366	2		7194	JD PARTS-COUNTER
00	00	166	1		7194	JD PARTS-MOOSE JAW
01	40	544	1		7194	SUPPLIES EXPENSE
01	30	375	1		7194	PARTS SPECIAL HANDLING
01	30	372	2		7194	OTHER MFR PARTS-CNTR
00	00	172	1		7194	OTHER PARTS-MOOSE JAW
01	30	375	3		7194	PARTS SPECIAL HANDLING
01	30	466	2		7194	JD PARTS-COUNTER
01	30	472	2		7194	OTHER MFR PARTS-CNTR

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.
 I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:Date: