



Phone:
 • Fax
 www.youngs.ca



Regina 306-565-2405
Chamberlain 306-638-4516
Davidson 306-567-3074
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: .

A01-53

Invoice To:

Branch		
REPRINT		
Date 04/28/23	Time 22:02:24 (B)	Page 01
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#	HC Sprayer	HRS	PIN/EIN	WARRANTY DATE	HRS
UP0858	4420	3595	Y8T022720		
SEGMENT# 1 C 34032 SPRAYER INSP 04/06/23 04/06/23					
SPRAYER INSPECTION					
EHC1QT		EHC CHARGE	5	.22	1.10
76935DX6US		85W140 .95L	5	9.95	49.75
		PARTS			50.85
11030099		SEGMENT TOTAL==>			50.85
SEGMENT# 2 C 34032 NA 04/06/23					
SPRAYER INSPECTION WASH					
W10492					
SEGMENT# 3 C 34032 NA 04/06/23					
INSPECTION TRUCKING					
CUSTOMER BROUGHT UNIT IN					
SEGMENT# 4 C 34032 NA 04/17/23 04/17/23					
ENGINE					
+REMOVED STARTER TERMINALS					
+CLEANED UP TERMINALS					
+REMOVED AIR INTAKE HOUSING					
+REMOVED VALVE COVER					
+PERFORMED VALVE SET					
+INSTALLED VALVE COVER WITH NEW GASKET					
+INSTALLED AIR INTAKE HOUSING					
87345861		GASKET	1 N	151.83	151.83
		PARTS			151.83
		LABOR			1427.82
11030099		SEGMENT TOTAL==>			1579.65

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and its other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Phone: • Fax:
www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 04/28/23	Time 22:02:24 (B)	Page 02
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
UP0858 HC Sprayer 4420	3595	Y8T022720		
SEGMENT# 5 C 34032 NA	04/17/23	04/17/23		

BOOM

+REPLACED ALL 4 BOOM FOLD CYLINDERS AND HARDWARE
+REMOVED LEFT BOOM
+REMOVED LEFT BOOM PIVOT PIN
+LEFT BOOM PIVOT WAS CRACKED AND REQUIRED REPLACEMENT
+INSTALLED NEW BUSHING IN PIVOT
+INSTALLED PIVOT WITH NEW PINS AND SHIMS
+REPEATED PROCEDURE ON RIGHT SIDE
+RIGHT SIDE PIVOT WAS ALSO CRACKED
+RIGHT SIDE CYLINDER BRACKET WAS BENT AND COULD NOT BE USED
+INSTALLED NEW CYLINDER SWING BRACKET
+TESTED AUTO BOOM
+AUTO BEEN CONSTANTLY FLUCTUATING FORM MAX HEIGHT TO MIN
+TESTED ALL AUTO BOOM SENSORS
+CALIBRATED AUTO BOOM NO AFFECT
+SENSOR HEIGHT SETTINGS WHERE OFF
+CHANGED SENSOR HEIGHT SETTING
+TESTED AUTO BOOM
+WASHED AND CLEANED OFF BOOM BLOCK
+FOUND O-RING TO BE FAULTY AND CAUSING BLOCK TO LEAK
+REMOVED PLUG AND REPLACED O-RING
+CONFIRMED THAT BLOCK WAS NO LONGER LEAKING

BN302048	SHIM	4	30.14	120.56
BN306646	TUBE	2	275.80	551.60
BN310279	BOLT	4	26.42	105.68
BN326079	PIN	2	284.64	569.28
47622412	PIVOT	1	1548.04	1548.04
47622414	PIVOT	1	1548.04	1548.04
47669408	ARM	1	376.09	376.09

CONTINUED ON PAGE 03

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Phone: • Fax.
www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 04/28/23	Time 22:02:24 (B)	Page 03
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UP0858	HC Sprayer 4420	3595	Y8T022720		
84532296	BOLT	4	O	14.37	57.48
86980518	NUT	8		12.50	100.00
87272004	HYDRAULIC CYLIN	4	O	1157.48	4629.92
87310319	NUT, JAM	2		8.56	17.12
87341999	BOLT	1		51.35	51.35
87644287	BOLT	2		42.79	85.58
87675983	BUSHING, GROOVE	2		103.08	206.16
	PARTS				9966.90
	LABOR				3178.41
11030099	SEGMENT TOTAL==>				13145.31

SEGMENT# 6 C 34032 NA 04/17/23 04/17/23
HYDRAULIC & HYDROSTATIC SYSTEM
+REPLACED LEFT BOOM LIFT CYLINDER WITH UPDATED CYLINDER
+UPDATED CYLINDER REQUIRED UPDATED PIN
+INSTALLED UPDATED BOOM LIFT PIN
+REPLACED RIGHT HAND OUTER FOLD CYLINDER
+REPLACED O-RINGS IN FITTING FOR FOLD CYLINDER
+REPLACED BOTH REAR SHOCKS AND BUSHINGS
+REPLACED FRONT RIGHT ACTIVE SUSPENSION CYLINDER AND BUSHINGS
+CLEANED OFF TOP OF HYDRAULIC TANK
+REMOVED FITTING AND REPLACED O-RINGS
+CONFIRMED THAT FITTING WAS NOT LEAKING
+REMOVED FRONT LEFT WHEEL
+DISASSEMBLED PLANETARY
+INSPECTED PLANETARY
+BEARINGS IN PLANETARY ARE SHOWING SIGHS OF WEAR
+CONSULTED WITH CUSTOMER ABOUT BEARINGS
+DECIDED TO REUSE BEARINGS

CONTINUED ON PAGE 04

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Phone:

Fax:
www.youngs.ca

Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 04/28/23	Time 22:02:24 (B)	Page 04
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UP0858	HC Sprayer 4420	3595	Y8T022720		
+INSTALLED NEW SEAL IN PLANETARY					
+SET PRE LOAD FOR PLANETARY BEARINGS AND ASSEMBLED PLANETARY					
+FILLED PLANETARY WITH OIL					
+INSTALLED WHEEL AND TORQUED TO 450 FT/LB					
BN320608C	CORE-HYD CYLIND	1-	144.90		144.90-
BN320608R	REMAN-HYDR CYLI	1	889.78		889.78
BN320608C	CORE-HYD CYLIND		144.90		144.90
BN321661	BUSHING	2 O	47.63		95.26
FRTCP	FREIGHT-CASE	1	35.00		35.00
167268	O-RING	1	2.31		2.31
47582359	HYDRAULIC CYLIN	1 N	483.75		483.75
48142448	SHOCK ABSORBER	2	535.37		1070.74
48145864	BUSHING RUBBER	4 M	5.58		22.32
51557833	PIN	1 M	77.04		77.04
76935DX6US	85W140 .95L	1	9.95		9.95
87267726	CYLINDER	1	1967.01		1967.01
87270213	SHIM	1	72.93		72.93
87686094	RETAINER	1	1129.08		1129.08
90466671	HYDRAULIC CYLIN	1	796.08		796.08
90479158	BUSHING	4 M	7.13		28.52
91726945	BUSHING	2	4.63		9.26
9824050	O-RING	1	.89		.89
				PARTS	6689.92
				LABOR	1774.44
11030099	SEGMENT TOTAL==>				8464.36

SEGMENT# 7 C 34032 NA

04/17/23 04/17/23

CHASSIS

+REMOVED LEFT FRONT WHEEL

CONTINUED ON PAGE 05

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



Phone:
 • Fax:
 www.youngs.ca



Regina 306-565-2405
Chamberlain 306-638-4516
Davidson 306-567-3074
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: .

Invoice To:

Branch		
Date 04/28/23	Time 22:02:24 (B)	Page 05
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UP0858	HC Sprayer	3595	Y8T022720		
	4420				
	+REMOVED KNEE PIN				
	+REMOVED KNEE BUSHINGS AND SEALS				
	+INSTALLED NEW SEALS AND BUSHINGS				
	+INSTALLED NEW PIN				
	+INSTALLED WHEEL				
	+GREASED KNEE PINS				
	+REPEATED PROCEDURE ON LEFT REAR RIGHT FRONT AND RIGHT REAR				
	+PARALLEL LINK GREASE TUBE WAS PLUGGED AND NEEDED TO BE				
	+REPLACED				
	+REPLACED GREASE ZERK ON RIGHT INSIDE BOOM LIFT				
	+REPLACED GREASE ZERK FOR LEFT STEERING CYLINDER				
	+REPLACED BOTH GREASE ZERKS ON RIGHT STEERING CYLINDER				
BN302044	SEAL	8		32.37	258.96
BN302046	SHAFT	4		183.09	732.36
BN35810	HOSE	1 N		100.48	100.48
FRTCP	FREIGHT-CASE	1		30.00	30.00
1316827C1	BUSHNG-SPH	4		87.45	349.80
495-81278	WASHER	5 N		6.92	34.60
84600698	BOLT	4		48.74	194.96
87343900	NUT, SLOTTED	4 N		12.06	48.24
87400	PIN, SPLIT (COT	4		.83	3.32
87552137	COVER, BEARING	8		98.24	785.92
				PARTS	2538.64
				LABOR	5326.50
11030099				SEGMENT TOTAL==>	7865.14

SEGMENT# 8 C 34032 NA 04/17/23 04/17/23
SPRAY SYSTEM
+REPLACED PRODUCT PUMP
+REPLACED LEFT INSIDE BENT BOOM

CONTINUED ON PAGE 06

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
• It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
• Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
• An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
• Estimates are for the items specifically identified in the estimate only, and are non-binding.
• Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Phone

www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch		
Date 04/28/23	Time 22:02:24 (B)	Page 06
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UP0858	HC Sprayer 4420	3595	Y8T022720		
	+REPLACED LEFT OUTSIDE BENT BOOM +REPLACED PRODUCT PUMP +NEW PRODUCT PUMP HAD DIFFERENT FITTINGS HAD TO USE ADAPTER +FOR MANUAL PRESSURE GAUGE AND PRESSURE SENSOR				
1404-02-04	MP X FPS SWV	1		2.75	2.75
41200	SADDLE- WET 1"	1		6.35	6.35
5502-02-04-FG	02MP-04FP-90	1		4.29	4.29
87268178	PUMP	1		2023.82	2023.82
87671762	BOOM	1		389.36	389.36
87671763	BOOM	1		337.74	337.74
9992069	O-RING	1		1.13	1.13
				PARTS	2765.44
				LABOR	796.59
11030099				SEGMENT TOTAL==>	3562.03

SEGMENT# 9 C 34032 NA	04/17/23 04/17/23				
MAINTENANCE					
+TOPPED OFF ENGINE OIL (7L 15-40)					
+TOPPED OFF COOLANT					
+TOPPED OFF HYD OIL (40L HY-TRAN)					
+REPLACED GEAR INCREASER OIL					
+REPLACED CRANK CASE BREATHER					
CC2825	ANTIFREEZE	1		21.65	21.65
EHCOIL	EHC CHARGE	12		.05	.60
74645001US	15W40 BULK	RETAIL		4.84	
		7		4.74	33.18
76921DX6US	75W90 1QT	3		13.25	39.75
77400001US	ULTRACTION BULK	RETAIL		5.27	
		40		5.17	206.80
87338649	BREATHER	1		233.02	233.02

CONTINUED ON PAGE 07

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



Phone:

• Fax

www.youngs.ca



Regina	306-565-2405
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To: .

Invoice To:

Branch		
Date 04/28/23	Time 22:02:24 (B)	Page 07
Account #	Phone #	Inv #
Ship Via	Purchase Order # 22-23 INSPECTION	
Tax ID #		
		Salesperson

SERVICE INVOICE

STK#/FLEET#

UP0858

HC Sprayer
4420

HRS

3595

PIN/EIN

Y8T022720

WARRANTY DATE

HRS

11030099

PARTS

535.00

LABOR

346.50

SEGMENT TOTAL==>

881.50

***** WORK ORDER TOTALS *****

PARTS

22698.58

LABOR

12850.26

shop supplies

300.00

SPRAYER INSPECT

1899.00

SUB TOTAL==>

37747.84

GST 5%

1887.43

TOTAL ON ACCOUNT

39635.27

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Received By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!