

STOP

REQUIRED INSTALLATION PROCEDURES

Please read BEFORE installation Failure to complete will void warranty

BREAK-IN OIL CHANGE IS REQUIRED BEFORE 1 MONTH OR 1,000 KILOMETERS ON NEW ENGINE

Regular oil changes must occur every 5,000 kilometers Or 125 hours of idle.

Prior to the installation and operation of this remanufactured product it is necessary to perform several inspections, change over accessories and routine maintenance to insure uninterrupted service.

Overlooked maintenance items to consider

Original engine

Why did the original engine fail? There is usually an external item or issue that caused the engine to fail. This is important to know so it can be resolved before installing the new engine.

Lubrication

Ensuring quality oil with an additive are used. 5W30 min is required

Making sure there is proper oil level. Low oil will damage engine.

Parts that are re-used MUST be properly cleaned or replaced so as there is no chance of oil contamination. (Valve covers, Oil pan, ext.)

Refer to all OEM torque specs.

Replacing the oil cooler and lines are required.

Crankshaft bolt holes that are drilled straight through must have sealant applied to avoid leaks.

Cooling

It is strongly recommend that a new radiator cap and radiator are installed.

Ensure the cooling system can pressurize and maintains pressure.

(Pressure Tester)

Making sure hoses are acceptable.

Determine you have proper coolant levels.

Emission

Spark plugs MUST be replaced.

Air filters MUST be replaced.

Oxygen sensors MUST be replaced.

PCV valves MUST be replaced and ensure engine runs with negative pressure

Make sure all sensors and catalytic converters are in good working condition. (Scan vehicle)

Proper Air/Fuel trims must be maintained

Contamination

Making sure there is no contamination within the intake, air system.

Replace air filter.

66150287

Men

WINNIPEG ENGINE AND TRANSMISSION 545 Ferry Road

Winnipeg, Manitoba R3H 0T5 GST Number: R101397693

Phone: (204) 783-4878 Fax: (204) 774-4732

Email: info@winnipegengine.com





SALES ORDER #:







INVOICE	DATE YOUR OR	DER # PAYMENT TERMS	ENTERED	BY C	RDER SOURCE SI	IIPPED VIA
5/3/202	23	Due on receipt	Jae Auger N	1EW		
Qty Ord Q	ty Ship Item #	Description	Tax	Retail	Disc Net	Ext. Amour
1.00	1.00 300-164-02	6.4 LT CHRYSLER HEMI ENGINE - REMANUFACTURED	~	\$8,500.00	\$8,500.000	\$8,500.0
1.00	1.00 CORE	CORE VALUE SUBJECT TO QUALIFICAT	ION 🗸	\$3,000.00	\$3,000.000	\$3,000.0
1.00	1.00 WAR	WARRANTY CARD MUST BE RETURNED WITHIN 15 DAYS. FAILURE TO RETURN VOID WARRANTY - STRICTLY ENFORCE No. W0002498	WILL	\$0.00	\$0.000	\$0.0
1.00	1.00 OIL	5W40 NON SYNTHETIC OIL FOR THE 1S 6000KMS, 1ST CHANGE AT 1000KMS OR HRS. 2ND AT 6000KMS OR 80 HOURS. F PROPER BREAK IN. PREMATURE DARK OF OIL COULD INDICATE IMPROPER RUNNING CONDITION.	R 10 OR	\$0.00	\$0.000	\$0.0
1.00	1.00 O2	FRONT O2 SENSORS MUST BE REPLACE FAILURE TO DUE SO WILL VOID WARRA		\$0.00	\$0.000	\$0.0
1.00	1.00 INTAKE	IN THE CASE OF CATASTROPHIC FAILU AND CONTAMINATION OF PREVIOUS ENGINE DEBRIS, PLEASE REPLACE ENGINE OIL COOLER AND INSPECT INTAKE FOR DEBRIS. Https://www.youtube.com/watch?v=VZnEe0k (USUALLY ASSOCIATED WITH A DROPP VALVE SEAT)	RS Dei8Z	\$0.00	\$0.000	\$0.0
1.00	1.00 COOL	ENGINES HAVE TENDENCIES TO OVERHEAT, PLEASE PRESSURE TEST COOLING SYSTEM, ENSURE PROPER COOLANT LEVELS AND INSPECT RADIA	✓ STOR,	\$0.00	\$0.000	\$0.0
OMMENTS:	2015 RAM 2500				SUBTOTAL:	\$11,600.00
	-				FREIGHT:	\$0.00
					5.00% TAX:	\$580.00
					7.00% TAX:	\$812.00
IOIT alliance	(ada a.a. a.u.uii	annuine com for wormants information	ALL DET	TIDNIC MILE	OTHER:	\$0.00
Si i airect		gengine.com for warranty information				A40.000.00

BE RECEIVED WITHIN 30 DAYS *ALL ACCTS SUBJECT TO A 2% CREDIT CARD PROCESS FEE NO CHARGE FOR E-TRANSFERS OR COMPANY CHEQUES

5.00 % TAX.	\$500.00
7.00% TAX:	\$812.00
OTHER:	\$0.00
TOTAL	\$12,992.00

PAYMENTS:	PALID				AMOUNT	DUE	\$0.00
HOW PAID	DATE PAID	CHECK/CARD NUM	EXP DATE	AMT PAID	AMT RECVD	AUTHOR	IZATION
Visa	5/3/2023			\$12,992.00	\$12,992.00		
			Total:	\$12,992.00	Discount:		\$0.00

Printed: 5/3/2023 10:59:34 AM



WINNIPEG ENGINE AND TRANSMISSION

545 Ferry Road Winnipeg, Manitoba R3H 0T5 GST Number: R101397693 Phone: (204) 783-4878

Fax: (204) 774-4732 Email: info@winnipegengine.com



SALES ORDER #:







NVOICE D	ATE YOUR	ORDER#	PAYMENT TERMS	ENTERED B	Y OI	RDER SOURCE	SHIPPED VIA	
5/3/202	3		Due on receipt	Jae Auger NE	EW			
		AND WATE	PLACE THERMOSTAT, R PUMP	RAD CAP,				
1.00	1.00 ENGINE	RETURN FO	OR REFUND	V	\$100.00	\$100.	000 \$100.	

COMMENTS: 2015 RAM 2500

VISIT directauto.ca or winnipegengine.com for warranty information ALL RETURNS MUST BE RECEIVED WITHIN 30 DAYS *ALL ACCTS SUBJECT TO A 2% CREDIT CARD PROCESS FEE NO CHARGE FOR E-TRANSFERS OR COMPANY CHEQUES

SUBTOTAL: \$11,600.00 FREIGHT: \$0.00 \$580.00 5.00% TAX: 7.00% TAX: \$812.00 OTHER: \$0.00

\$12,992.00 TOTAL

PAYMENTS:

Visa

\$0.00 AMOUNT DUE AUTHORIZATION AMT RECVD AMT PAID **EXP DATE** DATE PAID CHECK/CARD NUM HOW PAID \$12,992.00 \$12,992.00 5/3/2023 \$0.00 Discount:

Total:

\$12,992.00

Printed: 5/3/2023 10:59:34 AM



* IMPORTANT *

Warranty Information & Warranty Card

This is a limited warranty covering defective materials or workmanship on only those items originally supplied by Winnipeg Engine & Transmission for a period of 1 year or 20,000 kilometers, or 500 hours, whichever occurs first. This warranty is not an unconditional guarantee against all hazards, failures, damage or improper installation procedures. If after installation any Winnipeg Engine & Transmission remanufactured engine or transmission that is deemed defective*(see Limitations, Defects and Service Restrictions) then an allowance* (see Installation Allowance) covering a portion of the cost of installation (when installed by a professional certified repair facility) is provided.

Basic Limited Warranty

The Basic Limited Warranty covers Passenger Cars, Light Duty Trucks, Commercial, Industrial, Marine, Fleet and Recreational Vehicles for a period of 1 Year or 20,000 Kilometers or 500 hours (whichever occurs first).

Installation Allowance

In the event a Winnipeg Engine & Transmission remanufactured engine or transmission is deemed defective* (see Limitations, Defects and Service Restrictions), after installation, then an Installation Allowance, for passenger cars and non-commercial light duty trucks, covering the original installers shop rate up to a maximum hourly rate of \$55.00 CDN multiplied by 80% of the retail time listed in the current release of the Mitchell Time Guide will be provided under this warranty. For commercial, marine, industrial, fleet and recreational vehicles (under 11,000 GVW) the Installation Allowance will be the same as above except \$650.00 CDN labour cap will be applied.

Limitations, Defects and Service Restrictions

If our product requires any service other then regularly scheduled maintenance within the warranty period you must notify Winnipeg Engine & Transmission of the intended service prior to the start of any work. Failure to provide prior notification could result in warranty being voided. Any parts suspected of being defective by the approved repair facility must then be returned to Winnipeg Engine for inspection. The inspection must be performed by Winnipeg Engine & Transmission, and must determine conclusively that the failure was due to defective materials or workmanship. If the repair requires replacement parts covered by this warranty, Winnipeg Engine & Transmission will supply the parts to the approved repair facility at jobber cost. Water pumps, timing belts, and any other routine maintenance items supplied with the engine are covered under the basic warranty.

This warranty does not cover failures caused by improper installation or installation of defective parts not originally supplied with the engine. This warranty does not cover engines that have been abused, neglected, overheated or operated under harsh or severe conditions that typically cause failure. Under no circumstances will Winnipeg Engine be liable for oil, oil filter, antifreeze, towing, car rental, or any other incidentals. Replacement or repairs to the original product do not extend this warranty.

Warranty Is Void If

The attached warranty card is not submitted to Winnipeg Engine & Transmission with the specified time or does not contain all of the requested information. If the new engine cooler and oil cooler lines are not installed at the time of engine installation. The re-installation of parts for the original engine or transmission which may have been damaged or contain debris as a result of the original failure such as; valve covers, oil pans, timing covers, intakes, fuel delivery systems, air delivery systems, etc. or have insufficient cooling systems, and or ignition systems which are not properly cleaned and or inspected prior to re-installation onto any of our products.

Winnipeg Engine & Transmission • 545 Ferry Road • Winnipeg • Manitoba • R3H 0T5

Phone: (204) 783-4878 • Toll Free: (888) 407-5349 • Fax: (204) 774-4732 • Email: info@winnipegengine.com • Website: www.winnipegengine.com

Retain the above portion for your records; you may be required to provide the warranty number located at the top of this form.





W0002498

This portion must be filled in completely and returned to Winnipeg Engine & Transmission • 545 Ferry Road • Winnipeg • Manitoba • R3H 0T5

	15 DAVE FROM THE ORIGINAL INVOICE	DATE
Customer Nam		Phone:
Installation Co		Phone:
Vehicle Year: 2016	Make: Declar Rom Model: 3500	Engine Size: 6.4 L
Date of Installation:	Vehicle Mileage:	Vehicle Hours:
Installed Item Number:		Invoice Number:

WINNIPEG ENGINE AND TRANSMISSION 545 FERRY ROAD WINNIPEG, MB R3H 0T5 204-786-2000

WINNIPEG ENGINE AND TRANSMISSI

Date: 05/03/2023

10:58:04 AM

CREDIT CARD SALE

VISA

CARD NUMBER:

********3759 K

TOTAL AMOUNT:

\$12,992.00

APPROVAL CD: RECORD #: CLERK ID:

INVOICE #:

Customer Copy

Engin Simulation Results



Winnipeg Engine & Transmission 545 Ferry Road Winnipeg, Manitoba R3H 0T5 Phone: 204-783-4878

Email: info@winnipegengine.com

Year	2016	Make	RAM	Model	2500
Engine	6.4	Vin (8th)		Cylinder	8
Part Number		300-264-02		Invoice	
Customer Name	-			Warranty	
Oil Pre	essure	30	At	30	00 RPM
Compression			Front		Compression
225/175 VVT	C		Front		225/175
225/175				0	225/175
225/175	C			0	225/175
225/175					225/175
	C			\bigcirc	
C. Harden De			100		