

Date: 08/12/20

Time: 09:52

BRANDT TRACTOR LTD.
Service History Summary
SRT: SERNO,WO,CUSTPage: 1
(SHHIST-1)

SERIAL NUMBER: 1T0318GBVJJ335953

MAKE: JD

MODEL: 318G

WORKORDER-SEG	E/Q	TYPE	METER	SPG CODE	SPG DESCRIPTION	INV DT
CUSTOMER:	10477	PDI PROGRAM				
3619926-01		CGD				26JAN19
				BST080-0	PREDELIVER	
3619926-02		CGD				26JAN19
					FUEL	
2469593-01		CHG	144.0			26JUN19
					TRAVEL TO 1080 BRADNER	
2469593-02		CHG	144.0			26JUN19
					DIAGNOSE QUICK COUPLER FAILS FUSE EVERY TIME IT'S ACTIVATED	
2469593-04		CHG	144.0			26JUN19
					SUPPLY 10 CAB AIR FILTERS	
2469762-01		CHG	175.0			23JUL19
					TRAVEL TO 1080 BRADNER	
2469762-02	E	WTY	175.0			23JUL19
					DIAGNOSE QUICK COUPLER NOT WORKING - ELECTRICAL	
2469762-03	E	WTY	175.0			23JUL19
					REPLACE SHORTED HARNESS	
2470166-01		CHG	250.0			17AUG19
					TRAVEL TO 1080 BRADNER	
2470166-02	E	WTY	250.0			17AUG19
					REPAIR FOR PIN CAME LOOSE FROM BOOM NOISE TO BUCKET COUPLER	
2470831-01		CHG	397.0			17OCT19
					TRAVEL TO 1080 BRADNER	
2470831-02		CHG	397.0			17OCT19
					SWAP COUPLER TO MANUAL VERSION	
2470831-03		CHG	397.0			17OCT19
					INSTALL BOLT FOR ENGINE COVER	
2471419-01	E	CHG				14NOV19
					TRAVEL TO 1080 BRADNER	
2471419-02	E	CHG				14NOV19
					REPLACE MISSING BUCKET LOCKING PIN	
2471767-01		CHG	580.0			20DEC19
					TRAVEL TO 1080 BRADNER	
2471767-02	E	WTY	580.0			20DEC19
					REPAIR LEFT SIDE REAR TIRE NOT TURNING	
2471767-03	E	WTY	580.0			20DEC19
					REPAIR RIGHT SIDE REAR TIRE NOT TURNING	
2473005-04		CHG	767.0			08APR20
					CHARGES NOT COVERED BY WARRANTY	
2473005-01		CHG	767.0			08APR20
					TRAVEL TO 1080 BRADNER	
2473005-02		CHG	767.0			08APR20
					REPLACE DAMAGED BUCKET CYLINDER RODS	
2473005-03		CHG	767.0			08APR20
					REPAIR BUCKET DUMP STOPS	
2472711-02	E	WTY	767.0			08APR20
					DIAGNOSE NO HEAT IN CAB - NO BLOWER FUNCTION	
2472711-03	E	WTY	767.0			08APR20
					REPAIR AS REQUIRED	

SERIAL NUMBER: 1T0318GBVJJ335953 MAKE: JD MODEL: 318G

WORKORDER-SEG	E/Q	TYPE	METER	SPG CODE	SPG DESCRIPTION	INV DT
CUSTOMER:	14000780		AMRIZE CANADA INC.			
2472711-04	E	WTY	767.0			08APR20
					DIAGNOSE AND REPAIR FOR NO DRIVE ON RIGHT SIDE	
2472711-05	E	WTY	767.0			08APR20
					DIAGNOSE AND REPAIR FOR DOOR NOT LATCHING CLOSED	
2472711-08	E	WTY	767.0			08APR20
					DIAGNOSE FOR EXCESS PLAY IN BUCKET CYL TO QT PIVOT	
2472711-10	E	WTY	767.0			08APR20
					REPAIR FOR EXCESSIVE PLAY IN BUCKET CYL TO QT PIVOT	
2472711-12	E	WTY	767.0			08APR20
					DIAGNOSE AND REPAIR FOR LEAK AT LEFT BUCKET CYLINDER	
2472711-13	E	WTY	767.0			08APR20
					DIAGNOSE AND REPAIR FOR LEAK AT RIGHT BUCKET CYLINDER	
2472711-01	INT		767.0			08APR20
					TRAVEL TO 1080 BRADNER	
2473652-01	CHG		904.0			10JUN20
					TRAVEL TO 1080 BRADNER ROAD, ABBOTSFORD	
2473652-02	CHG		904.0			10JUN20
					DIAGNOSE LOW VOLTAGE CODES & STALLS OUT	
2473652-03	CHG		904.0			10JUN20
					PARTS REQUIRED	
2473740-01	CHG		935.0			19JUN20
					TRAVEL TO 1080 BRADNER ROAD, ABBOTSFORD	
2473740-02	CHG		935.0			19JUN20
					REPLACE GASKETS FOR FUEL TANK LEVEL SENSOR, FILL NECK &	
2475681-01	CHG		1293.0			03DEC20
					TRAVEL TO 1080 BRADNER RD, ABBOTSFORD	
2475681-02	E	WTY	1293.0			16DEC20
					REPLACE FAILED HOSE - AT443740	
2475761-01	CHG		1322.0			24DEC20
					TRAVEL TO 1080 BRADNER RD, ABBOTSFORD	
2475761-04	INT		1322.0			24DEC20
					CORE RETURN	
2475761-02	E	WTY	1322.0			31DEC20
					DIAGNOSE NO START	
2475761-03	E	WTY	1322.0			31DEC20
					REPLACE STARTER	
2475858-02	E	WTY	1344.0			27JAN21
					ASSESS AND REPAIR FOR CAB BLOWER NOT WORKING	
2475858-01	E	WTY	1344.0			27JAN21
					ASSESS & REPAIR FOR EXCESS PLAY IN BOOM TO QUICK TATCH	
2475858-03	E	WTY	1344.0			27JAN21
					ASSESS AND REPAIR FOR CRACK IN QUICK TATCH FRAME	
2476178-01	CHG		1352.0			30JAN21
					TRAVEL TO 1080 BRADNER	
2476178-02	E	WTY	1352.0			31JAN21
					DIAGNOSE & REPAIR LEAKING WHEEL HUB	
2476178-03	E	WTY	1352.0			31JAN21
					DIAGNOSE & REPAIR ONE WHEEL NOT TURNING	

SERIAL NUMBER: 1T0318GBVJJ335953 MAKE: JD MODEL: 318G

WORKORDER-SEG	E/Q	TYPE	METER	SPG CODE	SPG DESCRIPTION	INV DT
CUSTOMER:	14000780		AMRIZE CANADA INC.			
2476625-01	CHG		1414.0		TRAVEL TO 1080 BRADNER	26FEB21
2476625-06	INT		1414.0		CORE RETURN	26FEB21
2476625-02	E	WTY	1414.0		DIAGNOSE LOW VOLTAGE CODE & ENGINE STOPPED	27FEB21
2476625-03	E	WTY	1414.0		REPLACE FAILED ALTERNATOR & DEAD BATTERY	27FEB21
2476866-01	CHG		1465.0		TRAVEL TO 1080 BRADNER	26MAR21
2476866-02	CHG		1465.0		REPLACE LEAKING BUCKET CYLINDER - REPLACE CYLINDER	26MAR21
2476866-03	CHG		1465.0		PERFORM 1000 HOUR SERVICE	26MAR21
2476866-04	INT		1465.0		REPAIR REAR WORK LIGHTS NOT WORKING	10APR21
2477016-01	CHG		1492.0		PERFORM END OF WARRANTY INSPECTION	10APR21
2477016-03	CHG		1492.0		CUT OPEN OIL FILTER & SUBMIT OIL SAMPLE - 1000 HOUR SERVICE	10APR21
2477016-04	CHG		1492.0		ASSESS AND REPAIR FOR TAIL LIGHTS NOT WORKING	10APR21
2477016-05	CHG		1492.0		WARRANTY REPAIR PERFORMED:	20APR21
2477016-02	E	WTY	1492.0		ASSESS & REPAIR FOR NO DRIVE ON LEFT SIDE	30APR21
2477356-01	CHG		1534.0		TRAVEL TO 1080 BRADNER	30APR21
2477356-02	E	WTY	1534.0		DIAGNOSE & REPAIR OIL LEAK FROM UNDER CAB	12MAY21
2477499-01	CHG		1557.0		TRAVEL TO 1080 BRADNER	12MAY21
2477499-02	CHG		1557.0		REPLACE BROKEN FRONT WINDOW	12MAY21
2477499-03	CHG		1557.0		REPLACE ENGINE BELTS	21JUN22
2481628-01	CHG		1219.0		TRAVEL TO CLEARBROOK PIT	21JUN22
2481628-02	CHG		1219.0		DIAGNOSE & REPAIR A/C NOT WORKING	30JUL22
2482136-01	E	CHG	2258.0		TRAVEL TO 1080 BRADNER - CENTRAL AGG.	30JUL22
2482136-02	CHG		2258.0		DIAGNOSE & REPAIR LACK OF POWER	30JUL22
2482136-03	CHG		2258.0		DIAGNOSE & REPAIR ENGINE NOISE ON START UP - TICKING NOISE	30JUL22
2482136-04	CHG		2258.0		PULL ENGINE OIL SAMPLE & REPLACE ENGINE AIR FILTERS	

Date: 4/7/25
Time: 11:51

BRANDT TRACTOR LTD.
Service History Summary
SRT: SERNO,WO,CUST

Page: 4
(SHHIST-1)

SERIAL NUMBER: 1T0318GBVJJ335953 MAKE: JD MODEL: 318G

WORKORDER-SEG	E/Q	TYPE	METER	SPG CODE	SPG DESCRIPTION	INV DT
CUSTOMER:	14000780		AMRIZE CANADA INC.			
2482136-05		CHG	2258.0			30JUL22
2482252-01	E	CHG	2279.0			31AUG22
2482252-02	E	CHG	2279.0		TRAVEL TO 1080 BRADNER - CENTRAL AGG	31AUG22
2482720-01	E	CHG	2279.0		DIAGNOSE & REPAIR ENGINE NOT TURNING OVER	31OCT22
2482720-02	E	CHG	2279.0		REMOVE ENGINE FROM MACHINE	31OCT22
2483405-01	CSH		2279.0		DISASSEMBLE AND ASSESS FOR ENGINE SEIZED	30NOV22
2483593-01	INT		2279.0		SUPPLY & INSTALL NEW ENGINE	16DEC22
2467871-01	E	WTY	4.0		REPLACE BROKE FAN	20FEB19
2467871-02	E	WTY	4.0		DIAGNOSE FOR HYDRAULIC OIL LEAK	20FEB19
					REPAIR AS REQUIRED	