

JobNumber	WorkOrderNumber	EquipmentName	MaintenanceGroup	Division	Rego	Supplier	EquipmentType	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DateDue	DistanceDone	DistanceToGo	HourDut	Worktype	WorktypeString
4873	3434	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Lights/HLight	Lights/HLight		REPLACED RUSTED P CLAMPS ON WIRING TO SPOTLIGHTS.	28/02/2025 10:10:00	13/03/2025 10:03:38	578967			Repair	Repair
4872	3434	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Cab/Seat	Cab/Seat Air Leak		REPAIRED AIR LEAK IN DRIVERS SEAT. TEST AND CHECK OK.	28/02/2025 10:08:00	13/03/2025 10:03:38	578967			Recair	Recair
4791	3434	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Glass/Windscreen Wash	drivers side beacon not working Truck		DIAGNOSE FAILED WINDSCREEN WIPER PIVOT AS REQUIRED. DISASSEMBLED AND FOUND WIPER PIVOT MOUNT BRACKET INSIDE DASH HAS RUSTED AND COLLAPSED. CUT RIVETS AND REPLACED MOUNT REFIT ALL NEW PARTS AND ASSEMBLED. TEST AND CHECK OK. TOUCH UP RIVETS WITH PAINT. REPLACED WINDSCREEN WASHER NOZZLE FITTING.	28/02/2025 10:03:00	19/02/2025 00:00:00	578967			Fault	Fault
4786	3433	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Lights/Beacon Lamp	drivers side beacon not working Truck		FOUND BROKEN WIRE FOR RIGHT SIDE ROTATING LIGHT. REPAIR AND TEST- FOUND BLOWN BULB IN LEFT LIGHT. REPLACE AND TEST- ALL TESTED OK	17/02/2025 09:53:00	17/03/2025 00:00:00	578965			Fault	Fault
4780	3198	PM701	25 PMS	Transport	342VQO	Law Transport	PM	MTDATA/Test	MTDATA/Test	MTData Guardian	closing job	10/12/2024 08:25:04	23/06/2022 05:56:46	574528			PreventativeMaintenance	PreventativeMaintenance
4335	3044	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/BS	Service/BS	B Service		20/11/2024 10:32:00	01/02/2025 13:41:00	574292	570950		Service	Service
4420	3149	PM701	25 PMS	Transport	342VQO	Landtree Machinery Service	PM	Service/AS	Service/AS	A Service	Service completed at JAC	09/11/2024 08:33:00	13/11/2024 13:48:00	574297	578630		Service	Service
4172	2936	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Brakes/Air Leak	brake low air light on when air is full. air gauges are at 700kpa. truck relay cluster needs rescuing as it fell on my foot/ leg whilst driving. totally unsafe and will be leaving out do not use until repaired. w/ Truck needs oil of Truck		fault repaired, closing fault	09/11/2024 08:32:00	09/11/2024 00:00:00	574528			Fault	Fault
4171	2935	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Electrical/ElecOth	oil level topped up and will monitor oil use, closing fault		relocated into correct position and secured, closing fault	09/11/2024 08:31:00	09/11/2024 00:00:00	574528			Fault	Fault
4173	2937	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Engine/OLevel	passengers side mirror broken needs replacing Truck		oil level topped up and will monitor oil use, closing fault	02/11/2024 05:33:00	04/11/2024 00:00:00	574297			Fault	Fault
4174	2934	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Body/Mirror Door	Service/AS	A Service	mirror replaced, closing fault	21/10/2024 08:10:00	18/11/2024 00:00:00	574528			Fault	Fault
4209	2909	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/AS	Service/AS			14/10/2024 13:48:00	04/09/2024 13:41:00	566300	560950		Service	Service
3910	2703	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Glass/Window	window driver side tint peeling causing slow to put up Truck		tint out and removed, now window operation smooth, closing Fault	14/10/2024 08:38:00	16/10/2024 00:00:00	574297			Fault	Fault
3992	2772	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Electrical/ElecOth	lights brackets tightened and earth to chassis checked, repaired, closing fault		lights brackets tightened and earth to chassis checked, repaired, closing fault	14/10/2024 08:37:00	16/10/2024 00:00:00	574297			Fault	Fault
3993	2772	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Cooling/Engine Fan	Truck engine fan wont cut out. Truck		Horton fan sensor faulty, changed and repaired, closing fault	14/10/2024 08:36:00	16/10/2024 00:00:00	574297			Fault	Fault
4028	2884	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Cab/Upholstery	switch panel is tak screwed in full down when doing 100kmph very dangerous needs original screws out, back in, also takes short cut before someone sets hurt Truck		replaced with correct screws had some adjustments to make due to movement, now repaired, closing fault	11/10/2024 08:39:00	13/10/2024 00:00:00	574297			Fault	Fault
4044	2883	PM701	25 PMS	Transport	342VQO	Law Transport	PM	ST/Replace	front right hand side steer Truck		Had Bridgestone repair tyre, closing fault	09/10/2024 10:45:00	23/10/2024 00:00:00	574297			Fault	Fault
4027	2883	PM701	25 PMS	Transport	342VQO	Law Transport	PM	DT/Replace	flat tyre right hand side front drive Truck		horn on steering wheel found to be a blown fuse. air horn requires new air line, cracked and brittle. Closing fault	07/10/2024 08:42:00	09/10/2024 00:00:00	574297			Fault	Fault
3994	2772	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Electrical/ElecOth	horn not working and one on steering wheel Truck		repaired at JAC on the day before leaving site, lines were clogged, closing fault	01/10/2024 06:00:00	16/10/2024 00:00:00	574297			Fault	Fault
3986	2772	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Glass/Windscreen Wash	window spray not working Truck		found to be a blown fuse, repaired, closing Fault	30/09/2024 08:34:00	16/10/2024 00:00:00	574297			Fault	Fault
3995	2772	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Glass/Window	driver side window don't wind up Truck		found to be a blown fuse, repaired, closing Fault	30/09/2024 06:35:00	16/10/2024 00:00:00	574297			Fault	Fault
3675	2461	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Brakes/Air Leak	auxiliary air tank strapped to mudguard needs to be replaced, it should of only been a temporary repair and needs the original main tank reinstated.		tank replace in correct position at JAC, repaired, closing Fault	12/08/2024 08:40:00	12/08/2024 00:00:00	574297			Fault	Fault
3676	2461	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Cooling/Engine Fan	Horton fan sticking on.		the fan sensor was replaced, now operating properly, closing fault	09/08/2024 08:39:00	12/08/2024 00:00:00	574297			Fault	Fault
3732	2593	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/C2S	Service/C2S	C2 Service	Stood Down since January - reps, paint	05/08/2024 13:41:00	15/01/2025 12:00:00	550650			Service	Service
3728	2593	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/AS	Service/AS	A Service	Stood Down since January - reps, paint	05/08/2024 13:41:00	08/12/2023 09:12:00	550650	556733		Service	Service
3731	2593	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/BS	Service/BS	B Service	Stood Down since January - reps, paint	05/08/2024 13:41:00	01/02/2025 13:41:00	550650	570950		Service	Service
3729	2593	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Compliance/Anninrp	Compliance/Anninrp	Annual Inspection (COI or NHV)	Stood Down since January - reps, paint	05/08/2024 13:40:00	05/08/2025 13:40:00	550650			Service	Service
3730	2593	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/CS	Service/CS	C Service	Stood Down since January - reps, paint	05/08/2024 13:40:00	15/01/2024 12:00:00	550650			Service	Service
2425	1675	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Body/Paint	JAC arranged for Truck to be washed and cleaned prior to painting.			23/01/2024 14:50:00	28/02/2024 14:48:37	550650			Fault	Fault
2334	1612	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Cab/ice Pack Service	On 0296 Fit new ice pack. JAC arranged.		Estimate \$16,500	23/01/2024 08:54:00	20/02/2024 08:53:09	550650			Fault	Fault
2265	1554	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Brakes/Air Leak	Order No.0298 Air valve fault.Dumping air		Purchase on 0196	08/01/2024 11:42:00	16/01/2024 11:41:05	550650			Fault	Fault
2152	1498	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Unknown/Fault not defin	Ignition Key Lost. Replace Ignition Barrel and door lock			20/12/2023 12:00:00	25/12/2023 11:59:15	545697			Fault	Fault
2216	1531	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Service/BS	Unknown/Fault not defin	B Service		08/12/2023 10:22:00	07/03/2024 10:22:00	545692	569522		Service	Service
1937	1399	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Body/MGuard	mud flap arm hitting tyre Truck			01/12/2023 10:56:00	10/12/2023 10:55:07	545697			Fault	Fault
1200	871	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Lights/HLight	spot lights not working Truck			30/11/2023 15:35:00	16/09/2023 15:34:54	545697			Fault	Fault
2116	1468	PM701	25 PMS	Transport	342VQO	Law Transport	PM	Lights/Hnd	FOLLOW UP REPAIRS HWS ELECTRICAL ISSUE AND PARK LIGHT REQUIRES REWIRING AIR GLIDE AND TORQUE ROD BUSHES N/S			30/11/2023 14:39:00	08/11/2023 13:21:38	545697			Fault	Fault
1806	1310	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/AS	Service/AS A service completed 342VQO 08.11.2023	A Service	FOLLOWUP REPAIRS RH ROOF LAMP N/S 4X DRIVE SHOCKS EXCHANGE P/S BOX LEAKING ELECTRICAL WIRING REPAIRS REQUIRED LH COIL SHOCK N/S Order number 0034 22/11/23 \$4850	08/11/2023 09:12:00	09/11/2023 13:20:00	546733	548702		Service	Service
1550	2567	PM701	25 PMS	Transport	342VQO	Law Transport	PM	MTDATA/Charger	Replaced all arglide bushes	A Service	had tablet and cradle connectors cleaned with steel wool, closing fault	13/10/2023 08:41:00	30/10/2023 12:05:46	574297			Fault	Fault
1492	1091	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/AS	Replaced air leaks		A service completed 342VQO 10.10.2023	10/10/2023 13:20:00	09/11/2023 13:20:00	538702	548702		Service	Service
1537	1132	PM701	25 PMS	Transport	342VQO	Brown & Hurley	PM	Equipment/Straps	Tie Down straps		5386526m	22/09/2023 16:45:00	09/11/2023 16:45:23	538655			Fault	Fault
1258	922	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Suspension/SAbsorb	FOLLOW UP REPAIRS REQUIRED AIRGLIDE BUSHES ALL ORDERED	A Service		14/09/2023 12:30:00	12/10/2023 12:30:39	545697			Fault	Fault
1532	1126	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/AS	Service/AS	A Service		12/09/2023 16:06:00	09/11/2023 13:20:00	538655	548702		Service	Service
1257	921	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/AS	Service/AS	A Service	A SERVICE COMPLETED 342VQO 12.09.2023	12/09/2023 12:22:00	12/10/2023 12:20:00	531895	541895		Service	Service
1178	858	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Lights/SLight	rh front clearance light out Truck			07/09/2023 08:18:00	08/09/2023 08:18:09	531895			Fault	Fault
1177	858	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Brakes/Brake switches	engine brake switch has been damaged now all floppy and not working correctly Truck			07/09/2023 08:18:00	12/09/2023 08:17:42	531895			Fault	Fault
1039	743	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Brakes/Air Leak	loss of air whenbrakes are applied Truck		Air Supply Button not Pushed in.	29/08/2023 09:05:00	30/08/2023 09:04:15	527555			Fault	Fault
820	689	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/BS	Service/BS	B Service		16/08/2023 11:15:00	14/11/2023 11:15:00	525534	545534		Service	Service
757	644	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Cab/Gauge	no dash lights Truck			13/07/2023 12:22:00	19/08/2023 11:20:14	520700			Fault	Fault
659	562	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/AS	Service/AS	A Service		26/05/2023 14:52:00	26/05/2023 13:59:00	515818	520287		Service	Service
635	538	PM701	25 PMS	Transport	342VQO	Bridgestone	PM	TY/SafeCheck	tread coming away from side wall Truck			16/05/2023 11:25:00	23/05/2023 11:22:05	513124			Fault	Fault
576	480	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/AS	Service/AS	A Service		28/04/2023 13:59:00	01/04/2023 01:08:00	510287	508913		Service	Service
476	442	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/BS	Service/BS	B Service		03/04/2023 14:39:00	16/04/2023 11:07:00	506622	500556		Service	Service
382	379	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/AS	Service/AS	A Service		01/03/2023 14:38:00	15/03/2023 11:07:00	498913	490556		Service	Service
262	268	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/BS	Service/BS	B Service	4 DRIVE TYRES 25% LHS	16/01/2023 11:07:00	22/01/2023 14:13:00	485556	474633		Service	Service
296	300	PM701	25 PMS	Transport	342VQO	Transport Main Roads	PM	Compliance/Anninrp	Compliance/Anninrp	COI Annual Inspection	Maintenance Management	01/01/2023 12:01:00	30/12/2008 23:30:00	473620			Service	Service
221	227	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/AS	Service/AS	A Service		13/12/2022 13:49:00	23/11/2022 14:13:00	470430	464633		Service	Service
95	102	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/AS	Service/AS	A Service		15/11/2022 15:54:00	23/11/2022 14:13:00	460697	464633		Service	Service
68	74	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/BS	Service/BS	B Service	Replaced 1st drive lh front airbag. Electronic horn n/s.	24/10/2022 14:13:00	10/07/2022 15:23:00	454633	457431		Service	Service
33	40	PM701	25 PMS	Transport	342VQO	JAC Diesel Repairs	PM	Service/BS	Service/BS	B Service		11/04/2022 15:23:00	30/03/2008 23:30:00	437431	20000		Service	Service