

Experian AutoCheck Report

Report run: 02/11/2026 12:11:44 EST

2016 Ram 3500 SLT / Tradesman

Regular Cab 2D (6.4L V8 SMPI Gasoline)

VIN:	3C7WRSAJ9GG157716
Class:	Pickup - Fullsize
Country of Assembly:	Mexico
Vehicle Age:	10 year(s)
Last Reported Odometer:	237,637 (05/05/2025)

Owners - 2



Vehicle Usage
Fleet, Lease



AutoCheck Score

Similar vehicles usually range between **83** and **91**

Vehicle History at a Glance

 State Title Brand CLEAN	 Auction Brand / Issues NO ISSUE	 Accident / Damage DAMAGE REPORTED
 Open Recall Check NO OPEN RECALLS	 Insurance Loss / Transfer NO ISSUE	 Odometer Check Last reported odometer: 237,637 (05/05/2025) NO ISSUE
 Certified Pre-Owned NO CPO INFO AVAILABLE	 Service / Repair 3 Service Record(s) Reported NO ISSUE	 Additional History NO ISSUES REPORTED



This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)




Accident & Damage



Overturned

Unknown

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.



Vehicle: 2016 Ram 3500 SLT / Tradesman (3C7WRS AJ9GG157716) Report Run Date: 02/11/2026 12:11:44 EST

Owner 1

Registration Event/Renewal(Leased Vehicle)

Owner 2

Location: FLOwned From: 10/2021Usage: Fleet, Lease				
Event Date	Location	Odometer	Data Source	Details
10/28/2021	TAMPA, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
12/16/2021	BARTOW, FL	169,701	Service Record	Heat or Air Conditioning Serviced Safety Inspection Performed Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Recommended Maintenance Performed Brakes Serviced Electrical System Serviced Lube, Oil And/Or Filter Changed
12/21/2021	BARTOW, FL	169,703	Service Record	Heat or Air Conditioning Serviced
01/03/2022	BARTOW, FL	169,976	Service Record	Air Filter Changed Safety Inspection Performed Engine Serviced Brakes Serviced Electrical System Serviced Lights or Signals Serviced Tires or Wheels Service Performed
10/27/2022	TAMPA, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
10/26/2023	TAMPA, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
10/28/2023	FL		Police Report	Accident Reported(Report #:2023-044211)
11/04/2024	TAMPA, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
05/04/2025	FL	237,637	Auto Auction	Reported at Auto Auction
05/05/2025	FL	237,637	Auto Auction	Auction Announced as Fleet/Lease(COLOR REPORTED AS RED)

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at [www.autocheck.com/terms](#) or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (3C7WRS AJ9GG157716) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at [www.autocheck.com/bbp/terms](#) or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.