

# Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
T-480	Steer	20/02/2026	20/02/2026	406,600		0		Internal Workshop Removed and replaced LHS + RHS steer tyres, torqued wheels to 450ft pound and set tyre pressure to 110psi.	\$0.00
R-3230	welding	13/02/2026	13/02/2026			0	2792		\$0.00
R-3205	lights	09/02/2026	09/02/2026			0	2748		\$0.00
R-3204	windscreen washers	09/02/2026	09/02/2026			0	2747		\$0.00
R-3203	windscreen	09/02/2026	09/02/2026			0	2746		\$0.00
R-3148	lights	04/02/2026	04/02/2026			0	2717		\$0.00
R-3126	batteries	04/02/2026	04/02/2026	402,236		0		Removed and replaced all 4 batteries Parts used: batteries Parts from: Hitech	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3119	Brakes, hubseal, mudflap	12/01/2026	29/01/2026	400,694		0		Removed and replaced all brake shoes and drums on truck, replaced 2nd axle lhs + rhs hub seals and axle gaskets, removed and placed rear lhs mudflap. Torqued all wheel nuts. Parts used: Hub seals and axle gaskets Brake shoes Brake drums Ashton's mudflap Parts from: NJ Ashton's stock Gilbert & Roach Truckline	\$0.00
S-1743	C - 100k	12/01/2026	29/01/2026	400,694 80,698		0		Carried out C service, replacing all filters and oil. Greased truck, brake adjusted torqued all wheel nuts, clutch adjusted.	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3110	tarp cable	05/01/2026	05/01/2026	400,537		0		Replaced Tarp cable with new tab cable stock NJ Ashton Parts used: 15 m cable Cable clamps Time taken 1 hour	\$0.00
R-2790	Brakes	04/08/2025	04/08/2025	370,073	0	0		Internal Workshop brake adjust	\$0.00
R-2800	Bushes, TYRES	03/07/2025	03/07/2025	365,364	0	0		Internal Workshop replaced all drive tyres as were low replaced front shackle pins & bushes as were worn 8 x drive tyres 6 x shackle pins 6 x bushes 6 x retainers	\$0.00
R-2779	TYRE	20/06/2025	20/06/2025	364,341	0	0		Internal Workshop Replaced R/H/F steer tyre	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-2036	aircon, engine light	02/04/2025	30/04/2025	351,797	0	0	1104, 1113	Heater tap turned on... heater works check engine light off after oil and coolant topped up	\$0.00
R-2145	Chassis	28/04/2025	28/04/2025	353,483		0		Orkhan Combe Remove+ replace 2x hydraulic tank straps with new	\$0.00
R-2040	Lights	03/04/2025	28/04/2025	358,072	0	0	1115	Diagnose entire LH headlight to be faulty... Remove + replace headlight with spare from workshop	\$0.00
R-1635	windscreen wipers	23/01/2025	09/04/2025	352,872	0	0	1069, 844, 949, 964	Rewire OEM harness in wiper circuit ALL OKAY	\$0.00
R-1586	body	17/01/2025	09/04/2025	352,872	0	0	793	Removed damaged side step Straighten step from damage refit sidestep securely ALL OKAY	\$0.00

<b>Number</b>	<b>Type</b>	<b>Date Open</b>	<b>Date Closed</b>	<b>Kilometres Closed</b>	<b>HoursClosed</b>	<b>Fuel Usage Closed</b>	<b>Fault</b>	<b>Repairer / Notes</b>	<b>Cost / Invoice</b>
R-2168	Cab	03/04/2025	03/04/2025	352,072	0	0	1118	Ely Cameron Locate triangles + first aid kit under passenger seat Inform driver of location	\$0.00
R-2039	Brakes	03/04/2025	03/04/2025	352,072	0	0	1114	Internal Workshop found broken airline at trailer.	\$0.00

Generated at: 29/05/2026, 2:47:11 pm