



## Vehicle History Summary

Fleet #	XB85UM
Registration	XB85UM
Make	Kenworth
Model	T409
VIN / Chassis #	6F5000000DA449789
Build Date	2013

Date	Reading / Units	Type / Repairer Notes	Repairer
<b>Air leaks, Clutch, Engine mount, Horn, King Pin, Lights, Seat cushion R-1807</b>			
12/06/2025	399,174 kms	<b>C S-891</b>  Repairs Required: Coolant to be replaced. Front parkers, RHF indicator, number plate light not working. Engine mounts to be replaced. King pins to be replaced. Front hub oils to be replaced. LHS tie rod to be replaced. Seat cushion to be replaced. Clutch rubber to be replaced. Bar behind engine to be repaired/replaced. Checker plate behind cab requires 2 bolts. Horn to be repaired/replaced. Radiator support rubbers to be replaced RHS. Turntable top and bushes to be replaced. LHF fuel strap rubber to be replaced. Air leaks to be investigated. Transmission oil and filter to be replaced (air tank to be removed for access). To be Monitored: Front and rear diff seals weeping.	Gippsland Truck Mechanics -GTM (P)
22/05/2025		<b>Grease lines R-1768</b>  Model: Kenworth T409 Reg No: XB85UM Body Type: Conventional 29/4/2025 *Grease steering shaft. *Fit joiners to leaking grease lines for LHS king pin, insulate hoses and secure.	AJT Truck Repairs (P)
01/05/2025	368,962 kms	<b>Coolant Leak R-1725</b>  XB85UM Find coolant leak, drain coolant remove worn coolant header tank hose, fit new hose and clamps,fill coolant up, test Jack up and remove lh rear wheel because tyres of the bead, get tyre fitters to fix it, put wheel on, tension wheel. Drain 15l off able out of tank because adblue not connected	Bennys Diesel services & repairs
30/04/2025		<b>New T-512</b>  Rego:XB85UM Odometer:387,124 11R22.5 148/145L FS FD664 Positions: 9,10,11,12	Bridgestone Albury
04/04/2025		<b>Road Worthy Inspection R-1642</b>  complete COI on Kenworth T409 P Mover Complete a registration assessment HVRAS on above Travel 2 visits one for re check screen	Transport Auditing and Compliance Services
01/04/2025	367,310 kms	<b>B S-787</b>  7/3/2025 *Pick up from SRV yard. 12/3/2025 *Carry out B service following customer supplied sheet, replace worn wiper heads, replace melted adblue injector line, pick up parts as required. Note: King pins worn *Fuel priming pump not picking up fuel *Clutch pedal rubber worn *Thru-shaft seal leaking *Steering shaft slip joint worn and wear in uni's *Plastic bonnet pivot bushes worn *RHS top mirror light n/w *RHR parker light faulty *Air compressor not cutting out, air drier constantly blowing off *RHS fuel tank J-bracket cracked. *RHS gusset behind gearbox cracked *Heater tap leaking	AJT Truck Repairs (P)
26/03/2025		<b>Puncture T-471</b>  PUNCTURE TRUCK - FITTED XB85UM	Goodyear Autocare Leongatha
17/03/2025		<b>compressor, Turntable R-1666</b>  XB85UM 19/3/2025 *Strip adjuster bolt assy, fit new adjuster shaft assy as required, pick up parts. *Remove and replace faulty air compressor, re-fill cooling system and test, all ok, return old compressor for core deposit.	AJT Truck Repairs (P)
03/03/2025		<b>Chassis R-1644</b>  Job date 28/2/2025 Rego# XB85UM 2013 KENWORTH T409 TRUCK 365400kms PO# R1644 Remove number plates and fit new ones as requested. Labour	On Point Mechanical
28/02/2025		<b>Windscreen R-1643</b>  PO/RO/Stock Number - Email Address - acc.payable@defgroup.com.au Supply & Fit - V57SJ - KENWORTH T400-SERIES T409 2014 - TRUCK N/C Part Used - KW1644 Guarantee - 12 month warranty on workmanship Time to Drive - Friday, February 28, 2025 2:27 PM Drying Time - 4 Window Down 48hrs - Yes ADAS Required - No	Economy Windscreens

Date	Reading / Units	Type / Repairer Notes	Repairer
18/02/2025		<b>Internal Tanker wash</b> O-180 Washout YB53BA/YB54BA Product - Black Oil Rego# XV57SJ Docket# 42100	Acacia Ridge Container Park
12/02/2025		<b>Internal Tanker wash</b> O-167 Washout YB53BA/YB54BA Product - Waste/Black Oil Rego# XV57SJ Docket# 41899	Acacia Ridge Container Park
14/01/2025		<b>New</b> T-400 11R22.5 148/145L FS FD664 Positions: 5,6,7,8	Bridgestone Albury
13/01/2025		<b>Internal Tanker wash</b> O-99 Washout YB53BA/YB54BA Product - Black Oil Rego# XV57SJ Docket# 41688	Acacia Ridge Container Park
08/01/2025		<b>External Vehicle wash</b> O-147	Singh Truck Wash
31/12/2024		<b>Internal Tanker wash</b> O-93	Acacia Ridge Container Park
20/12/2024		<b>Under run protection</b> R-1547	On Point Mechanical
20/12/2024		<b>indicator stalk</b> R-1546	On Point Mechanical
10/12/2024		<b>Internal Tanker wash</b> O-65	Acacia Ridge Container Park
27/11/2024		<b>Internal Tanker wash</b> O-62	Acacia Ridge Container Park
22/11/2024	360,592 kms	<b>Airbrake</b> R-1486 Rego# XV57SJ 360592Kms 2013 KENWORTH PRIME MOVER PO# R1486 Carry out repairs as per service sheet Faults identified: - Faulty and leaking brake hose Faults repaired: - Remove split hose and replaced with new hose - Fitted spiral flex over hose and secured all grease lines to the brake hose - Tested - OK	On Point Mechanical
14/11/2024		<b>Internal Tanker wash</b> O-58	Acacia Ridge Container Park
13/11/2024		<b>Adblue, Clutch</b> R-1474 Inspected and removed adblue injector and found that it has been blocked and cracked - Removed and replaced the adblue injector - Tested operations - OK - Attached and secured bonnet strap - Dropped the bonnet mount to reset the axle bolts on 1st drive left hand side to new hub cap - Test drove - OK	On Point Mechanical
12/11/2024		<b>Internal Tanker wash</b> O-50	Acacia Ridge Container Park
12/11/2024		<b>Internal Tanker wash</b> O-59 Washout YQ93RL/YQ94RL Product - Crude Oil Rego# XV57SS Docket# 41054 Note: Product still remains in compartment 4. Phone call was made to advise	Acacia Ridge Container Park
07/11/2024		<b>Tint</b> R-1465 Supply tint kit for Kenworth truck 2 doors and kick panel on passenger side Rego: xv57sj	Michael Melksham Tinting
30/10/2024		<b>Adblue, Air Conditioner, Air dryer assembly</b> R-1453 Carry out repairs as per service sheet Faults identified: - AC not working - Air dryer constantly exhausting - Ad blue light on dash - Engine belts need replacing Faults repaired: - Removed and replaced the A/C and Alternator belts due to be excessively cracked. - Removed and replaced air dryer breather - Found that the air exhaust silencer has been blocked - replaced with a new silencer - Inspected and repaired AC - Ran diagnostic on truck to inspect fault light on dash - Found multiple inactive adblue fault codes. Saved adblue fault codes to file. Erase fault codes and carry out test drive. Full adblue cycle carried out and no active fault codes are present. Vehicle tested OK. AC Inoperative Install test equipment, found refrigerant level ok, no internal cabin air flow, dismantle panels and locate blower motor, test operation, found blower motor failed and evaporator block, supply and fit new blower fan, fan resistor, clean evaporator, chemically flush test - OK	On Point Mechanical
28/10/2024		<b>Trailer plug</b> R-1449	On Point Mechanical
22/10/2024		<b>External Vehicle wash</b> O-131	Singh Truck Wash
22/10/2024		<b>Air Lines</b> R-1373	Bennys Diesel services & repairs

Date	Reading / Units	Type / Repairer Notes	Repairer
15/10/2024		AIR LEAK R-1367	Bennys Diesel services & repairs
30/09/2024	350,472 kms	Starter Motor R-1362	Bennys Diesel services & repairs
09/09/2024	349,885 kms	A S-546	Bennys Diesel services & repairs

Signed: \_\_\_\_\_  
Name: \_\_\_\_\_  
Date: \_\_\_\_\_