

## Vehicle History Summary

Fleet #	XW02IA
Registration	XW02IA
Make	Kenworth
Model	K200
VIN / Chassis #	6F500000DA450512
Build Date	2013

Build Bate 2015				
Date	Reading / Units	Type / Repairer Notes	Repairer	
11/04/2025		Electrical R-1604	Bennys Diesel services & repairs	
14/02/2025		Battery R-1822	Lunds Auto Electrical	
		Check fault in Adblue, repair power wir	ing to nox sensor and clear fault codes	
14/02/2025		Road Worthy Certificate Repairs R-1	509 Bennys Diesel services & repairs	
		steering, suspension, brakes, cab char shackle pins, drive line and all moving i and drums All wheel bearings King pins at gearbox Front crosmember loose Ne brake and reverse lights Cab Jack leak lights Need radios around Washer jets leaking Lh top shocker bolt lose Adblue	orth Model:k200 check over vehicle, Check all diff oils and gear box oil. Check all sis and drive line components and adjust when requited. check king pins, including auxiliary body parts. Test drive and clean up Roadworthy list All brakes as Suzy coil trailer plug Needs all airbags Gearbox oil cooler lines/ sensor leaking seds middle axle tyres Needs turntable Needs rh reverse light, needs Lh indicator, ing Teflon pads between rh spring worn Needs mirrors Need both high beam not working / broken Power steering hose leaking at resivor Cab Jack hose aline broken Gear stick bushes worn Steering shaft slip yolk worn Air intake from Steering wheel out off alignment Teflon cab mounts worn Needs steering	
05/12/2024		Coolant Leak R-1452	AJT Truck Repairs (P)	
		turn off heater taps 09/10/2024 *Close	heater taps, top up cooling system with water. (Requires new heater core)	
08/11/2024	334,224 kms	<b>A</b> S-630	AJT Truck Repairs (P)	
		globes and broken globe holders, adjust assembly, flush cooling system and reptemp and check heater operation, replayarts, adjust clutch as required, adjust washer jets as required, replace wiper at clamp for heater control valve, cut be (continental and bridgestone) - RHS Cato clutch not connected - L and R King Adblue Injector line u/s, melted connected	ver truck 29/10/2024 - 01/11/2024 *Carry out A service, replace blown dash at turntable jaw kit. *Pressure test cooling system and replace leaking heater core place coolant filter, fill system with new coolant and road test to get to running ace both leaking heater taps and re-check for leaks, refit dash covers, pick up all brakes. *Replace broken RHS windscreen washer nozzle, unblock and adjust heads, pick up parts. *Travel to Geelong and check coolant leak, found hose split ack hose and re-fit, top up cooling system Drive Tyres low, odd steer Tyres ab Ram weeping from cylinder Weep from bottom P/S reservoir - Grease lines pin has movement - Steer springs worn - L and R shackle pins and bushes u/s - tor - Bottom Grill loose RHS - Various air leaks - Torque rod bush's peeling - ation possible spigot bearing collapsed - Cab pump leaking - Cab mounts u/s -	
07/11/2024		<b>New</b> T-355	Bridgestone Albury	
28/10/2024	335,432 kms	Alternator R-1447	Amos Auto Electrical (P)	
		Traveled to Hallam truck centre, picked	Rego No - XW-02IA Kms - 3354327.1 Serial No - 6F5000000DA450512 - I up new alternator then traveled out to site SRV roadfrieght Diagnosed alternator, ran truck up and found to be charging well. All tested fine	
10/10/2024		Ten stud rim, Tyre R-1414	Bridgestone Albury	
		Replace rim and tyre Callout Info: Time	: 22:00:00 Location: MONASH FREEWAY CHADSTONE Ref: 160259	
01/10/2024		Air leaks, Brakes R-1364	Bennys Diesel services & repairs	
26/09/2024		MUDGUARD R-1347	Bennys Diesel services & repairs	
26/09/2024	313,467 kms	Steering R-1347	Bennys Diesel services & repairs	

Date	Reading / Units	Type / Repairer Notes	Repairer
		fit new bolt to pitman arm and replace drag link	
25/09/2024	325,177 kms	Wheel studs R-1391	Bennys Diesel services & repairs
		Replaced	
20/09/2024	320,841 kms	<b>B</b> S-561	Bennys Diesel services & repairs
Signed:			
Name:			
Date:			