

Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
T-509	Puncture	11/03/2026						Found puncture 3rd axle LHS inner, repaired with plug and set air pressure to 100psi.	\$0.00
S-1726	C - 100k	17/12/2025	17/12/2025	893,874 48,764		0			\$0.00
T-438	Drive	02/10/2025	02/10/2025	885,530	0	0		Patch repair RHR outer drive	\$0.00
R-2797	gear splitter	30/07/2025	30/07/2025	874,085	0	0		Internal Workshop checked range change/splitter not working. Found air leak at splitter hose replaced hose and joiner. Test ok	\$0.00
R-2987	tarp cable	21/07/2025	21/07/2025	0	0	0		Internal Workshop checked tarp cable, found clamps to be broken, re-joined cable fitted new clamps. test all ok	\$0.00
R-2589	TYRE	30/06/2025	30/06/2025			0	1634		\$0.00
S-1525	A - 10k	28/05/2025	28/05/2025	865,000 19,890	0	0		Internal Workshop A SERVICE	\$0.00
R-1351	windscreen	14/12/2024	14/12/2024	860,848	0	0	640		\$0.00
R-1252	Lights	04/12/2024	04/12/2024			0	593, 594		\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-1236	OIL LEAKS	03/12/2024	03/12/2024			0	587		\$0.00
R-1194	engine fan	28/11/2024	28/11/2024			0	550		\$0.00
R-1175	Air Conditioner	25/11/2024	25/11/2024	856,986		0	517	Archer Heavy Equipment Repairs Job completed by External workshop please refer to PO4007	\$0.00
R-1054	Tarp	14/11/2024	14/11/2024	854,348	0	0	435		\$0.00
R-1053	Lights	06/11/2024	06/11/2024	851,998	0	0	305,366	External workshop Job completed by external workshop please refer to PO3922	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-1331	air leak, CLUTCH	23/10/2024	23/10/2024	848,442	0	0		Archer Heavy Equipment Repairs Carried out repairs on clutch linkages. fitted new bearing and rose joints to clutch system. leak from disruption block. found the non-replaceable fitting leaking. Replaced hose and applied pipe sealant to fitting. No leak present. found air leaks on the treadle valve from multiple push lock fittings. remover treadle valve and installed new push lock fittings.	\$0.00
R-661	CLUTCH	27/09/2024	29/08/2024	845,110		0		Internal Workshop	\$0.00
S-602	C - 100k	29/08/2024	29/08/2024	845,110 845,110	0	0		Internal Workshop C SERVICE AND 2 STEER TYRES NEW REGO -- XP85BT	\$0.00
S-615	A - 5k	04/07/2024	04/07/2024	842,662 842,662	0	0		Internal Workshop A Service Tarp inop exhaust leaks	\$0.00
R-778	Steering, TYRE	02/10/2024	03/05/2024	830,550	0	0		Internal Workshop 4 drive tyres	\$0.00

