

# Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
T-510	Puncture	11/03/2026						Found puncture in 3rd axle RHS inner, repaired with plug and set air pressure to 100psi.	\$0.00
R-3313	Intercooler	20/02/2026	20/02/2026	826,172		0		Internal Workshop Attended breakdown, upon arrival inspected vehicle and found intercooler hose clamp to be loose, fit new intercooler hose and clamp. Checked all components for serviceability - all in working condition.	\$0.00
S-1725	C - 100k	12/12/2025	12/12/2025	814,909 77,491		0			\$0.00
R-3022	CLUTCH	07/11/2025	07/11/2025	807,541		0		Adjust clutch Adjust clutch brake ALL OKAY	\$0.00
R-3021	ELECTRICAL, lights	07/11/2025	07/11/2025	807,541		0		Found broken wire in circuit... Repair broken wire + test operation ALL OKAY	\$0.00
S-1650	A - 10k	07/11/2025	07/11/2025	807,541 2,133		0			\$0.00
S-1649	A - 10k	28/10/2025	28/10/2025	805,408 34,255		0			\$0.00
R-2804	TYRES	08/07/2025	08/07/2025	0	0	0		Internal Workshop replaced R/H 3rd axle drive tyres 2 x drive tyres	\$0.00
R-2802	TYRES	08/07/2025	08/07/2025	0	0	0		replaced R/H 3rd axle Tyres 2 x drive tyres	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-2737	tyres	20/06/2025	20/06/2025	785,645	0	0		Internal Workshop replaced 4 x low tread drive tyres tension wheel nuts 4 X 11R X 22.5 disposed 3 x tyres kept 1 x tyres for runout	\$0.00
R-2764	mudflap	16/06/2025	16/06/2025	785,214	0	0		Internal Workshop replaced missing mudflap	\$0.00
R-2557	airleak	14/06/2025	14/06/2025			0	1539		\$0.00
R-2556	Coolant Top Up	14/06/2025	14/06/2025			0	1538		\$0.00
R-2760	aircon	13/06/2025	13/06/2025	784,860	0	0		Internal Workshop refit A/C drain tube in floor of truck	\$0.00
R-2555	Brakes	13/06/2025	13/06/2025			0	1534		\$0.00
R-2535	tyres	13/06/2025	13/06/2025			0	1524	Ely Cameron	\$0.00
R-2253	Coolant Top Up	12/06/2025	12/06/2025	784,602	0	0	1510	found low coolant level. Topped up coolant to recommended level	\$0.00
R-2753	TYRE	08/06/2025	08/06/2025	784,183	0	0		Internal Workshop remove and replace.R/R/Inner drive Tyre with runout in shed. Tension wheel nuts Drive runout in shed x 1	\$0.00
R-2348	Lights	06/06/2025	06/06/2025			0	1494	replaced broken side light left hand rear side of truck	\$0.00
R-2445	fuel	03/06/2025	03/06/2025			0	1481	Ely Cameron	\$0.00