



Vehicle History Summary

Fleet #	XB23QG
Registration	XB23QG
Make	Kenworth
Model	K200
VIN / Chassis #	6F5000000MA475985
Build Date	2021

Date	Reading / Units	Type / Repairer Notes	Repairer
		Ice pack R-1835	
		Lights R-1833	
		Diff R-1864	
		Leak R-1834	
28/05/2025		External Vehicle wash O-307 No PO provided	Tranzwash
24/04/2025		New T-507	Bridgestone Albury
22/04/2025	374,078 kms	B S-834 2x left spot light flickering randomly when being used. Also day time running lights on spot lights are not working. Could be linked issue Both doors leaking lots of water thru top. Seats and driver get wet when raining Steer tyres starting to scallop Drive brakes really noisy	AJT Truck Repairs (P)
10/04/2025		External Vehicle wash O-258 Express PM + BD Trailers Wash Reg: XB23QG/ YQ60ZR/ YQ61ZR	Tranzwash
03/03/2025		Rotate Tyres T-453 Rego:XB23QG Odometer:353,217 BALANCE TBR	Bridgestone Albury
28/02/2025	348,188 kms	B S-760 XB23QG 19/2/2025 *Carry out B service following customer supplied sheet, rotate steers as required.	AJT Truck Repairs (P)
21/02/2025		Electrical, Fuel R-1578 XB23QG Odometer: 339,500 Kms 28/1/2025 *Pick up truck as required. *Check fault codes, found 1911 and 552 recent, remove and replace fuel/water seperator filter and fit new nut as driver complaint of leaking. *Check engine brakes only working on stage 1, monitor with laptop and found only to be activating stage 1 from steering wheel controls, possible jake switch. *Remove LHR wheel for puncture repair. 29/1/2025 *Get pucture repaired at tyreright, refit and tension wheel nuts. *Replace smart wheel switch for engine brakes, road test and check over still only working on stage 1 then stopped altogether, refit original switch, still n/w. Check all fuses and relays, all ok, check and test clock spring, all ok, check and test smart wheel module, all ok. Found all ignition switch wires loose and 1 nut missing and wire ready to fall off, fit new nut and tighten all others, road test and check operation, all ok and jakes working on all stages.	AJT Truck Repairs (P)
11/01/2025		External Vehicle wash O-104	Tranzwash
09/12/2024		Dovetail R-1526 10/12/2024 *Cut down exhaust and intake pipes. *Remove dove tail and seal up hoses. *Replace leaking oil pressure sensor for sleeper air.	AJT Truck Repairs (P)
03/12/2024		Battery R-1497 replace battery's Inspect and repair truck not starting. Install test equipment, found batteries failed. Supply and fit 4x new batteries, clean and tighten terminals, test charge rate. Test OK Labour	On Point Mechanical
22/11/2024		Horn, Lights R-1488	On Point Mechanical

Date	Reading / Units	Type / Repairer Notes	Repairer
		Test and repair driving lights and horn. Found corroded wires and relay Repair circuit, replace 2x relays. Test - OK	
28/10/2024	304,400 kms	B S-624 XB23QG 21/10/2024 *Carry out B service, tighten loose sleeper air mounts, check over unit and check oil level, requires new oil pressure switch as leaking. Clean out Fuel/ Water separator housing and replace worn nut as required. *Drive shock rubbers worn	AJT Truck Repairs (P)
24/10/2024	304,857 kms	call out T-341 Replace drive tyre	Bridgestone Albury
05/09/2024		Inverter R-1344	Pro Truck Electrical

Signed: _____

Name: _____

Date: _____