

Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3244	Drawbar	23/02/2026					2829	Ely Cameron	\$0.00
R-3449	air compressor, air dryer	24/02/2026	26/02/2026	513,517		0		Removed and replaced air compressor Removed and replaced air dryer filter Torqued all bolts to spec and tested everything for functionality	\$0.00
R-3243	welding	23/02/2026	23/02/2026			0	2828		\$0.00
R-3242	tyres	23/02/2026	23/02/2026			0	2827		\$0.00
R-3241	light	23/02/2026	23/02/2026			0	2826		\$0.00
R-3222	seatbelt	11/02/2026	11/02/2026			0	2779		\$0.00
R-3128	Brakes	03/02/2026	03/02/2026	509,635		0		Removed and replaced 2nd axle lhs brake booster, adjusted brakes. Parts used: 30/30 brake booster Parts from: NJ Ashton's stock	\$0.00
S-1747	C - 100k	03/02/2026	03/02/2026 423	509,635	0	0		Carried out C service adjusted brakes.	\$0.00
R-3142	Tarp	02/02/2026	02/02/2026			0	2706		\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3009	air leak, Brake Booster	29/09/2025	29/09/2025	489,126	0	0		Remove + replace RHF brake booster with new + adjust brakes Remove + replace 1/4" airline fitting on air dryer unit	\$0.00
R-2151	Hydraulics	29/04/2025	29/04/2025	465,843		0		Ely Cameron Remove + replace 3/4" hydraulic coupling with new + check for leaks under pressure	\$0.00
S-1526	A - 10k	29/04/2025	29/04/2025	465,843 13,078	0	0		Internal Workshop A Service	\$0.00
R-1900	Air valve, bra	07/03/2025	03/03/2025	461,389	0	0		Internal Workshop Diagnosed split airline at unloader valve fitting Replace air fitting and 1 meter 3/8 hose Replace front and rear brakes. adjust brakes, tension all wheel nuts	\$0.00
R-1751	TYRE	08/02/2025	08/02/2025	449,807	0	0		Internal Workshop Plug tyres Replaced mud flap	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-1473	bins	07/01/2025	06/01/2025	455,264	0	0		Internal Workshop Remove air lines from tipping valve under chassis + clean pistons with inox spray & refit airlines. test bins all okay.	\$0.00
R-1401	mudflap	17/12/2024	20/12/2024	454,460	0	0		Internal Workshop Put mudflap back on R/H/R Put mudflap back on R/H/R	\$0.00
R-1379	mudflap	16/12/2024	16/12/2024	494,146	0	0		Internal Workshop put mudflap back on L/H/R and R/H/R	\$0.00
R-1311	water washer	12/12/2024	11/12/2024	453,494	0	0		Internal Workshop - Remove + clean out RH washer jet parts - Test all okay	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
S-1265	C - Annual	07/12/2024	07/12/2024 332	452,765	0	0		Internal Workshop carry out C service on truck as outlined on service sheet Replace 2x wedge globe clearance lights on bonnet Replace 1x L/H bonnet mirror....	\$0.00
R-1278	TYRE	06/12/2024	06/12/2024	452,677	0	0		Internal Workshop Plug Tyres RHR	\$0.00

Generated at: 29/05/2026, 2:13:17 pm