

Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
S-1660	C - 100K Annual	16/10/2025	17/10/2025	507,664 55,160	0	0		Carried out C service	\$0.00
S-2019	C - 100K Annual	16/10/2025	16/10/2025	507,664 55,160	0	0		Internal Workshop Completed "C" service	\$0.00
S-1184	A - 10K	24/01/2025	24/01/2025	484,599 24,799	0	0		Internal Workshop A Service	\$0.00
R-1205	air leak	28/11/2024	28/11/2024	479,138	0	0		Internal Workshop Found 3/4 ABS hose to be leaking from vibrating against the chassis rail. Remove old hose and fit new hose, secure hose wraps around points of contact and ziptie all loose wiring and air hoses. check for leaks. all okay	\$0.00
S-1520	A - 10K	25/11/2024	25/11/2024	487,042 27,242		0		Ely Cameron	\$0.00
S-948	A - 10K	11/09/2024	11/09/2024	459,800 7,296		0		Ely Cameron	\$0.00
S-513	C - 100K Annual	14/08/2024	14/08/2024	452,504 452,504		0		Toby Simmonds	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-575	Brakes	30/07/2024	30/07/2024	448,284		0		Ely Cameron Brake adjust order park brake valve for slow releasing brakes	\$0.00
R-574	Air System, Brakes	30/07/2024	30/07/2024	448,284		0		Ely Cameron Found backing plate to be bent + rubbing on brake drum Bend backing plate out of the way test ALL OKAY	\$0.00
S-452	A - 10k	24/07/2024	24/07/2024	447,102 447,102		0		Ely Cameron	\$0.00
R-469	Tarp	06/03/2024	06/03/2024	409,438		0		Internal Workshop Rewire LH tarp cable + tension	\$160.00
R-204	Mudflaps	30/10/2023	30/10/2023	0	0	0		Internal Workshop Replaced missing mudflap	\$0.00
R-157	Mudflaps	30/10/2023	30/10/2023	0	0	0		Internal Workshop REPLACED MUDFLAP	\$0.00
R-150	TYRE	24/10/2023	24/10/2023	3,609	0	0		Internal Workshop REPLACED TYRE WITH RUNOUT TYRE	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
T-169	Fit Runout	24/10/2023	24/10/2023	389,609	0	0		adam travel to horsley park inspected flat tyre found blown replaced with runout	\$120.00

Generated at: 29/05/2026, 2:10:00 pm