

| Fleet # | YB58BA |
|-----------------|-------------------|
| Registration | YB58BA |
| Make | ATE |
| Model | |
| VIN / Chassis # | 6X9190731KM006252 |
| Build Date | |

| Balla Bate | | | |
|---------------------------------------|--------------------------------|--|--|
| Date | Reading / Units | Type / Repairer Notes | Repairer |
| | | Leg beam R-1913 | |
| 31/07/2025 | | Internal Tanker wash O-376 | Acacia Ridge Container Park |
| | | Tanker washout (internal) at Arc Park f | or YB58BA/ YB59BA This is prior to the equipment going to auction |
| 31/07/2025 | | External Vehicle wash O-378 | Singh Truck Wash |
| | | This is prior to the equipment going to | auction. |
| 18/07/2025 | | NHVAS and WAHVA Annual Inspect | on I-40 Murphys trailer repairs |
| 10/06/2025 | | External Vehicle wash O-314 | Singh Truck Wash |
| 09/05/2025 | C - C Service S-879 | Murphys trailer repairs | |
| | YB-58-BA 'C' S | YB-58-BA 'C' Service. Replace 1 brake | booster |
| 08/05/2025 | | Airbag, Electrical R-1720 | Murphys trailer repairs |
| | | YB59BA Replace 2 air bag assemblys | |
| 22/04/2025 | | Airbag R-1689 | Goldfields Fleet Management |
| 16/04/2025 | | Air bags R-1706 | Langtrees Machinery Service Townsville |
| | | Inspect to find POS 1,2, 4 and 6 air bag | A CARRY OUT REPAIRS TO TRAILERS. 09.04.2025 AIR BAG REPAIRS gs leaking, removed and installed new air bags and tested, test ok no leaks. 59BA KLMS - N/A CARRY OUT REPAIRS TO TRAILER. 09.04.2025 AIR BAG air bags leaking, removed and installed new air bags and tested, test ok no leaks, |
| | | packed up tooling and filled out paperw | rork, Job complete. LABOUR |
| 21/03/2025 B - B Service S-802 | | B - B Service S-802 | Murphys trailer repairs |
| | | YB-58-BA 'B' Service. Replace height of | control valve rod and linkages |
| 19/02/2025 | New T-440 | Bridgestone Albury | |
| | Rego:YB58BA 11R22.5 HAULMAX AT | T108 16PLY POS - 11,12,13,14,19,20 | |
| 23/01/2025 | | New T-408 | Bridgestone Albury |
| | | Rego:YB58BA 11R22.5 ATT202 HAUL | MAX |
| 06/01/2025 | | B - B Service S-714 | Murphys trailer repairs |
| | | 'B' Service. Replace 1 shock absorber. | |
| 12/12/2024 | | Brake Booster, Brakes R-1536 | Murphys trailer repairs |
| | | YB-58-BA Trailer Replace 2 brake book | sters and 1 slack adjuster. Replace brake shoes on left hand middle wheel. |
| 11/12/2024 | | New T-383 | Bridgestone Albury |
| 05/12/2024 | | Chassis R-1517 | EDGE DIESEL AUSTRALIA PTY LTD |
| | | | |

| Date | Reading / Units | Type / Repairer Notes | Repairer |
|------------|-----------------|---|--|
| | | BROUGHT TRAILER INTO SHED - BOOSTER BRACKET HAD BEEN SNAPPED OFF - JAREMOVED WHEELS ON LH SIDE - CLEANED UP THE SURFACE WITH A WIRE WHEEL FROM BROKEN OFF SECTION OF BRACKET - CLEANED UP ON THE WIRE WHEEL - SISOLATED THE TRUCK - TACKED BRACKET INTO PLACE - WELDED OUT BRACKET - IAND HEIGHT CONTROL VALVE - REFITTED WHEELS - TENSIONED WHEELS - CLEANIPACKED UP TOOLS - COMPLETED PAPERWORK | - REMOVED BOOSTER ET UP WELDER - REMOUNTED BOOSTER |
| 22/11/2024 | | B - B Service S-651 | Murphys trailer repairs |
| 07/11/2024 | | RUNOUT T-351 | Bridgestone Albury |
| 21/10/2024 | | B - B Service S-607 | Murphys trailer repairs |
| 05/08/2024 | | B - B Service S-498 | Brisbane Workshop |
| | | service tyres air leaks- booster fittings, air tank bungs, drain valves reseals hand rail ram lhs check fire extinguisher tighten shocks x 6 | ttable rebuild kingpin lights |
| 02/08/2024 | | New T-282 | Brisbane Workshop |
| 19/06/2024 | | B - B Service S-411 | Murphys trailer repairs |
| 09/05/2024 | | New T-181 | Brisbane Workshop |
| | | three tyres down to wire. replaced with new tyres and swapped runout for new tyre | |
| 24/04/2024 | | B - B Service S-340 | Murphys trailer repairs |
| 01/03/2024 | | A S-278 | Brisbane Workshop |
| | | carry out A service. replace rubber at front of trailer. replaced middle axle right hand side sho | ocker. |
| 10/01/2024 | | C - C Service S-230 | Brisbane Workshop |
| | | carried out C service cleaned and repacked all wheel bearings replaced front axle L/H secon R/H air bags | nd axle R/H and rear axle |
| 22/11/2023 | | A - A Service S-209 | Murphys trailer repairs |
| | | PRICE IS INCLUDED WITH S-206 | |
| 19/10/2023 | | MUDGUARD R-996 | Brisbane Workshop |
| | | Resecured RHF mudguard | |
| 04/09/2023 | | A - A Service S-175 | Murphys trailer repairs |
| | | 'A' Service. Replace 2 shock absorbers. COULD BE FOR REGO YN47HD?? COST INCLUE (XB83GS) | DED INTO SERVICE S-174 |
| 21/04/2023 | 2 kms | Trailer Tyre T-31 Go | oodyear Autocare Leongatha |
| | | 3553135 EFFIPLUS 11R22.5 R842E 18PR TL 2 EA 350.00 385.00 770.00 AS_6549997 FIT 12.98 25.96 XX_0083022 QLD CTRY1 TYRE RECYCLE/DISP - TRUCK 2 EA 33.36 36.70 7 Kilometers: 566989 Order Number: AB9840405 Fleet Number (Costar): YN46HD Vehicle ReSupplied by DSD CHILDS EMERALD TYRE SERVICE | 73.39 Odometer/Hubometer |
| 10/04/2023 | 2 hrs | B - B Service S-19 | Mechweld Services Pty Ltd |
| | | -trailer service -bearing movement check -lube air fittings -clean electrical plugs -general che hoses up | ck over -cable tied some |
| | | B - B Service S-28 | Mechweld Services Pty Ltd |
| 10/04/2023 | 2 hrs | | |
| 10/04/2023 | 2 hrs | -trailer service -bearing movement check -lube air fittings -clean electrical plugs -general che hoses up | ck over -cable tied some |
| 19/01/2023 | 2 hrs | -trailer service -bearing movement check -lube air fittings -clean electrical plugs -general che hoses up | eck over -cable tied some |

| Name: | | |
|-------|--|--|
| Date: | | |