



Vehicle History Summary

| | |
|-----------------|-------------------|
| Fleet # | YB59BA |
| Registration | YB59BA |
| Make | ATE |
| Model | |
| VIN / Chassis # | 6X9190732KM006253 |
| Build Date | 2019 |

| Date | Reading / Units | Type / Repairer Notes | Repairer |
|------------|-----------------|---|-----------------------------|
| 31/07/2025 | | External Vehicle wash O-379 This is prior to the equipment going to auction. | Singh Truck Wash |
| 31/07/2025 | | Internal Tanker wash O-377 Tanker washout (internal) at Arc Park for YB58BA/ YB59BA This is prior to the equipment going to auction. | Acacia Ridge Container Park |
| 10/06/2025 | | External Vehicle wash O-315 | Singh Truck Wash |
| 06/06/2025 | | Hose tray R-1818 Remove hose trays on LHS and RHS for inspection and re-fit. Provided quote for repairs to Dan | Fuel services Australia |
| 16/05/2025 | | Fault T-518 Replace | Bridgestone Albury |
| 08/05/2025 | | NHVAS and WAHVA Annual Inspection I-39 | Murphys trailer repairs |
| 08/05/2025 | | C - C Service S-850 YB-59-BA 'C' Service. Replace 2 air bag assemblys | Murphys trailer repairs |
| 17/04/2025 | | New T-505 YB59BA 11R22.5 148/145L FS FT469 | Bridgestone Albury |
| 07/04/2025 | | New T-494 YB59BA 11R22.5 148/145L FS FT469 | Bridgestone Albury |
| 04/04/2025 | | Accident Damage R-1587 YB59BA kms#n/a ***Accident damage repairs*** Carried out inspection to inside of compartment 4 valve to identify fault with internal valve not closing. Drained pipework & removed from tank. Washed out & cleaned pipes. Removed API valve, product indicators & cleaned. Cut off damaged sections of pipe & weld on new pipe & flanges. Replace pipe adaptors of compartment 2 & 3 pipes. Removed bent under run brackets & straightened . Straightened tool box mounts. Straightened front mudguards & brackets. Modified under run brackets to suit 100mm pipe under run. Supplied & fit under run protection & welded together. Fabricate new driveway bar. | Sustar Engineering |
| 13/12/2024 | | Accident Damage R-1538 remove damaged tyre rack and toolbox and dump | CDM Hydraulics |
| 22/11/2024 | | B - B Service S-653 | Murphys trailer repairs |
| 22/11/2024 | | B - B Service S-652 | Murphys trailer repairs |
| 07/11/2024 | | RUNOUT T-352 | Bridgestone Albury |
| 21/10/2024 | | B - B Service S-606 | Murphys trailer repairs |
| 05/08/2024 | | B - B Service S-499 service tyres air leaks kingpin lights 2 x airbags remove and straighten toolbox bracketery check fire extinguisher tighten x 2 shocks | Brisbane Workshop |

| Date | Reading / Units | Type / Repairer Notes | Repairer |
|------------|-----------------|---|---------------------------------------|
| 02/08/2024 | | New T-283 | Brisbane Workshop |
| 13/06/2024 | | B - B Service S-412 | Murphys trailer repairs |
| 09/05/2024 | | RUNOUT T-202 replaced with run out | Brisbane Workshop |
| 09/05/2024 | 624,627 kms | New T-182 swapped two tyres onto yn23io, stripped and put new tyres on | Brisbane Workshop |
| 24/04/2024 | | B - B Service S-341 | Murphys trailer repairs |
| 01/03/2024 | | A S-279 carry out A service. replaced right hand rear outer tyre used run out. freed up ring feeder and greased. | Brisbane Workshop |
| 10/01/2024 | | C - C Service S-231 carried out C service cleaned and repacked all wheel bearings replaced front L/H and rear R/H air bags | Brisbane Workshop |
| 22/11/2023 | | A - A Service S-210 PRICE IS INCLUDED IN S-206 | Murphys trailer repairs |
| 09/11/2023 | | Air bags R-1102 Replace air bag assembly. | Murphys trailer repairs |
| 17/10/2023 | 624,627 kms | Chassis R-992 Went to bolt shop and 3 new bolts on under run | Brisbane Workshop |
| 04/09/2023 | | A - A Service S-176 'A' Service. Replace 2 shock absorbers. COULD BE FOR REGO YN46HD?? COST IS INCLUDED WITH INVOICE FOR SERVICE S-174 (XB83GS) | Murphys trailer repairs |
| 08/06/2023 | 624,627 kms | Tyre R-212 replace tyre | Beaurepaires |
| 19/01/2023 | | SLP R-334 Carry out SLP inspection | Haulmark Trailers (Australia) Rocklea |

Signed: _____

Name: _____

Date: _____