



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3479310
Document Date:	2/08/2023
Repair Order No.:	383428
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	11623
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-0822
Page:	1 of 3

Check MFWD Pivot

- Checked reason for MFWD driveshaft disconnecting from drive clutch.
- Inspected MFWD axle pivot.
- Found pivot to be excessively worn causing shaft to be pulled out of clutch retain clip.
- Ordered parts required.
- Installed tractor support stand.
- Removed front wheels and steering hoses.
- Removed pivot bolts.
- Lowered axle to the ground.
- Replaced rear pivot bush, seal and pivot pin.
- Replaced front pivot pin housing and bush.
- Replace pivot pin sleeve thrust washers and oring.
- Replace input gear seal and oring.
- Replaced driveshaft due to spline wear.
- Installed axle.
- Tightened pivot housing bolts.
- Installed steering hoses and front wheels.
- Greased pivots.
- Removed stand.

LABOUR

\$1,121.74

<u>Part Number</u>	<u>Part Description</u>	<u>Serial No</u>	<u>Quantity</u>	<u>Nett Value</u>	<u>Total Cost</u>
R130895	Shaft		1.00	2,133.85	2,133.85
R125974	BUSHING		1.00	67.32	67.32
R124961	THRUST WAS		1.00	61.53	61.53
R124576	Snap Ring		1.00	10.84	10.84
R107719	BUSHING		1.00	313.67	313.67
R107718	SLEEVE		1.00	102.27	102.27



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3479310
Document Date:	2/08/2023
Repair Order No.:	383428
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	11623
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-0822
Page:	2 of 3

Check MFWD Pivot

LABOUR

Part Number	Part Description	Quantity	Unit Price	Total Price
R107466	SEAL	1.00	55.25	55.25
R124958	THRUST WAS	1.00	33.65	33.65
FREIGHT	FREIGHT & HANDLING	2.00	25.00	50.00
U10289	O-RING	1.00	7.37	7.37
T12529	Plug	1.00	38.12	38.12
R134224	O-RING	2.00	26.89	53.78
R83474	Ring	1.00	29.25	29.25
RE62204	Support	1.00	909.85	909.85
RE49315	SEAL	1.00	60.68	60.68
R285344	O-RING	1.00	18.84	18.84
Parts Totals:		18.00		\$3,946.27

ZONE 4 ONSITE CHARGE - 75-100km

LABOUR

ZONE 4 ONSITE CHARGE - 75-100km

Includes travel labour costs, vehicle km costs & fuel costs

<u>Part Number</u>	<u>Part Description</u>	<u>Serial No</u>	<u>Quantity</u>	<u>Nett Value</u>	<u>Total Cost</u>
--------------------	-------------------------	------------------	-----------------	-------------------	-------------------



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3479310
Document Date:	2/08/2023
Repair Order No.:	383428
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	11623
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-0822
Page:	3 of 3

ZONE 4 ONSITE CHARGE - 75-100km

Z4	ZONE 4 ONSITE CHARGE (KM & LAB)	1.00	450.00	450.00	<u>LABOUR</u>
Parts Totals:		1.00			\$450.00

Miscellaneous Charges

Environmental Levy	\$5.00
Consumables	\$50.00

Sub Total for All:	\$5,573.01
Rounding:	\$0.00
GST:	\$557.30
Total:	\$6,130.31

PAYMENT OPTIONS:
 PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3601929
Document Date:	18/04/2024
Repair Order No.:	412486
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	12324
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-2567
Page:	1 of 4

REPAIR OIL LEAKS, REPAIR SCV'S

- Remove side covers from engine.
- Wash engine and machine with pressure cleaner.
- Found oil leak at main pump.
- Move machine into workbay.
- Remove oil tube between main pump and cleaned tank.
- Fit new orings, refit tube.
- Found oil leak on engine timing cover.
- Drain coolant and remove fan shroud.
- Remove top radiator mounts and top radiator hoses.
- Found broken stud on right side mount.
- Drill and tap hole.
- Remove fan and fan belt.
- Remove bottom fan drive.
- Remove top fan drive.
- Remove coolant pump cover and gasket.
- Remove dampners from crankshaft.
- Undo sump bolts.
- Undo timing cover bolts.
- Remove timing cover from front of engine.
- Clean front of engine.
- Remove gasket.
- Fit timing cover and gasket.
- Fit new oil seal.
- Tighten all bolts.
- Fit new crankshaft damper, tighten bolt.
- Fit new coolant gasket and cover.
- Grease driven shaft and fit to coolant cover.

LABOUR
\$10,528.19



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3601929
Document Date:	18/04/2024
Repair Order No.:	412486
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	12324
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-2567
Page:	2 of 4

REPAIR OIL LEAKS, REPAIR SCV'S

LABOUR

- Fit new gasket and top fan drive to timing cover.
- Fit pads to bottom fan drive.
- Fit new fan belt.
- Fit fan to drive.
- Fit radiator cover and top mounts.
- Fit top radiator hose.
- Fit fuel hoses and fuel cooler to engine.
- Fit mounts to oil cooler and condensor on cooling package.
- Replace PDU panel and load new software.
- Dismantle armrest and repair gearshift linkage and mounts.
- Replaced coolant reservoir due to hole.
- Replace hydraulic oil filters.
- Replace coolant.
- Check transmission and engine oil.
- Test run machine.
- Replace SCV couplers.
- Clean machine.

<u>Part Number</u>	<u>Part Description</u>	<u>Serial No</u>	<u>Quantity</u>	<u>Nett Value</u>	<u>Total Cost</u>
R537359	Pad		3.00	48.59	145.77
R504885	GASKET		1.00	39.34	39.34
R502011	GASKET		1.00	18.74	18.74
R267645	Hose		1.00	47.96	47.96
R243288	Tank		1.00	400.74	400.74
R210589	Radiator Hose		1.00	100.95	100.95
R109982	O-RING		1.00	9.35	9.35

www.hutcheonandpearce.com.au



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3601929
Document Date:	18/04/2024
Repair Order No.:	412486
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	12324
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-2567
Page:	3 of 4

REPAIR OIL LEAKS, REPAIR SCV'S

LABOUR

M133730	Latch	2.00	20.29	40.58
H156922	Hose Clamp	1.00	6.93	6.93
FREIGHT	FREIGHT & HANDLING	4.00	25.00	100.00
21M7276	SCREW, PAN HEAD 4mm X 30mm	1.00	1.57	1.57
21M7216	SCREW, PAN HEAD 4mm X 20mm	1.00	1.71	1.71
19M8889	SCREW, HEX HEAD 16mm X 50mm	1.00	9.44	9.44
R311402	Misc	1.00	192.16	192.16
19M7796	SCREW, HFH 6mm X 30mm	1.00	3.01	3.01
CP8276	COOLANT 10L	3.00	78.01	234.03
A4540R	O-RING	1.00	10.72	10.72
R553043	Misc	1.00	0.00	0.00
0812	Misc	2.00	4.27	8.54
RE577560	BREAKAWAY	6.00	261.05	1,566.30
RE543639	SEAL KIT	1.00	70.79	70.79
RE523527	Pulley With Dampener	1.00	1,429.04	1,429.04
RE241176	Fuel Cooler	1.00	342.91	342.91
RE230665	Misc	2.00	158.48	316.96
RE210857	OIL FILTER	2.00	257.28	514.56
DZ116420	GASKET	1.00	107.50	107.50
TY22552	Bulk Hose	1.00	11.38	11.38
RM10017	Misc	1.00	2,501.06	2,501.06
RE57190	SEAL	2.00	14.24	28.48

www.hutcheonandpearce.com.au



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3601929
Document Date:	18/04/2024
Repair Order No.:	412486
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	12324
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-2567
Page:	4 of 4

REPAIR OIL LEAKS, REPAIR SCV'S

				<u>LABOUR</u>
TY26101AU	CLEANING S	2.00	11.21	22.42
R568198	V-BELT	1.00	158.50	158.50
Parts Totals:		49.00		\$8,441.44

Miscellaneous Charges

Environmental Levy	\$10.00
Consumables	\$100.00

Sub Total for All:	\$19,079.63
Rounding:	\$0.00
GST:	\$1,907.96
Total:	\$20,987.59

PAYMENT OPTIONS:
 PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3619300
Document Date:	21/05/2024
Repair Order No.:	417992
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	12431
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-2678
Page:	1 of 2

Remove and replace break line and test PTO

- Undo all clamps holding brake line
- Undo STC fitting under the cab
- Loosen fuel tank mounts
- Slide tank outward enough to remove old pipe
- Install new pipe, customer supplied
- Put clamps back onto the pipe to properly mount it
- Move fuel tank back into position
- Tighten up fuel tank mounts
- Check for leaks and operation of brakes
- Machine is good for work
- PTO clutches failed and will need to come to workshop at a later date to complete repairs

LABOUR

\$1,504.50

<u>Part Number</u>	<u>Part Description</u>	<u>Serial No</u>	<u>Quantity</u>	<u>Nett Value</u>	<u>Total Cost</u>
R132239	O-Ring		1.00	3.97	3.97
R132237	O-Ring		1.00	8.90	8.90
F3353R	O-Ring		1.00	4.19	4.19
Parts Totals:			3.00		\$17.06

ZONE 5 ONSITE CHARGE 100-125km

LABOUR

ZONE 5 ONSITE CHARGE 100-125km.

Includes travel labour costs, vehicle km costs & fuel costs.

<u>Part Number</u>	<u>Part Description</u>	<u>Serial No</u>	<u>Quantity</u>	<u>Nett Value</u>	<u>Total Cost</u>
--------------------	-------------------------	------------------	-----------------	-------------------	-------------------



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3619300
Document Date:	21/05/2024
Repair Order No.:	417992
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	12431
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-2678
Page:	2 of 2

<u>ZONE 5 ONSITE CHARGE 100-125km</u>				<u>LABOUR</u>
Z5	ZONE 5 ONSITE CHARGE (KM & LAB)	1.00	550.00	550.00
	Parts Totals:	1.00		\$550.00

Miscellaneous Charges
 Consumables

\$20.00

Sub Total for All:	\$2,091.56
Rounding:	\$0.00
GST:	\$209.16
Total:	\$2,300.72

PAYMENT OPTIONS:
 PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3676170
Document Date:	27/09/2024
Repair Order No.:	433983
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	12906
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-3606
Page:	1 of 2



Replace Rear Engine Dampener

LABOUR
\$675.00

Attend machine on farm
 Remove side panels and tilt bonnet forwards
 Remove transmission input shaft
 Remove transmission dampener off flywheel
 Clean up flywheel and remove dirt
 Fit new dampener and bolts
 Reassemble guards and input shaft
 Run machine and all was running well
 Remove broken bolts out of fuel tank strap
 Lift fuel tank back up
 Put new bolts in mounts
 Fuel tank has leak on back side near hydraulic filter where it had been patched before
 Informed customer
 Informed customer machine has 3 trouble codes, will be brought to workshop for further repairs sometime in the future
 Travelled back to town.

<u>Part Number</u>	<u>Part Description</u>	<u>Serial No</u>	<u>Quantity</u>	<u>Nett Value</u>	<u>Total Cost</u>
TA20453	VIBRATION		1.00	1,443.80	1,443.80
19M7789	SCREW, HFH 12mm X 30mm		8.00	3.58	28.64
19M7785	SCREW, HFH 10mm X 25mm		2.00	3.48	6.96
Parts Totals:			11.00		\$1,479.40

ZONE 4 ONSITE CHARGE 75-100km
 ZONE 4 ONSITE CHARGE 75-100km.

LABOUR



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3676170
Document Date:	27/09/2024
Repair Order No.:	433983
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	12906
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-3606
Page:	2 of 2

ZONE 4 ONSITE CHARGE 75-100km

LABOUR

Includes travel labour costs, vehicle km costs & fuel costs.

<u>Part Number</u>	<u>Part Description</u>	<u>Serial No</u>	<u>Quantity</u>	<u>Nett Value</u>	<u>Total Cost</u>
Z4	ZONE 4 ONSITE CHARGE (KM & LAB)		1.00	450.00	450.00
Parts Totals:			1.00		\$450.00

Miscellaneous Charges

Consumables **\$20.00**

Sub Total for All:	\$2,624.40
Rounding:	\$0.00
GST:	\$262.44
Total:	\$2,886.84

PAYMENT OPTIONS:

PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222

****PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE****

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3796922
Document Date:	20/05/2025
Repair Order No.:	445111
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	0
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-4560
Page:	1 of 7

Coolant In Engine Oil, resending invoice to include story

LABOUR
\$25,070.12

- Wash tractor
- Drive tractor into work bay
- Top up tractor with coolant
- Place pressure gauge on cooling system
- Drain engine oil out of engine
- Pressurize cooling system, coolant runs out of oil drain plug Need to find where coolant is leaking from
- Remove fan and fan drives from front of engine
- Found one coolant leak coming from water pump in timing cover housing
- Replace new timing cover and new water pump with new bolts Refit fan drive
- Refill coolant
- Pressurize system to 15 psi
- Water was still leaking from oil drain plug but was slower
- Place borescope inside sump
- Coolant was leaking from number 4 and 5 sleeves
- Drain coolant from engine. Remove driven fan drive
- Remove timing cover housing from block
- Undo all electrical connects and remove harness
- Remove transmission yoke
- Remove all air pipes and hoses from engine
- Remove exhaust guards and exhaust pipes from engine Remove heater hoses from engine
- Remove top and bottom radiator hoses
- Remove fan and shroud
- Remove top radiator mounts
- Undo all hose brackets
- Remove sump bolts
- Use John Deere lifting tools and shop crane to remove engine Place engine on stands
- Remove oil pump from engine

www.hutcheonandpearce.com.au



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3796922
Document Date:	20/05/2025
Repair Order No.:	445111
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	0
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-4560
Page:	2 of 7

Coolant In Engine Oil, resending invoice to include story

LABOUR

- Remove tappet cover
- Remove turbo and exhaust manifold from engine
- Undo injector wires
- Remove injector pipes from engine
- Undo injector clams
- Remove injectors from engine
- Remove rocker shaft and push rods from engine
- Remove intake manifold
- Remove head
- Remove rubber drive from rear of engine
- Remove flywheel from engine
- Lift engine up and place on turn over stand
- Remove fuel filter and housings
- Remove fuel manifold
- Tap out side bolt holes to fit stand
- Turn engine onto side
- Undo all connecting rod bolts
- Remove all 6 pistons from engine
- Use sleeve puller to pull all 6 sleeves out of block
- On examination, found block and sleeves both damaged, number 4 and 5 were the most damaged and sleeves were moving in block
- Write out parts list for owner for engine repair estimate
- Both parts to repair and long block were quoted
- Send estimate to owner
- Wait for response
- Owner decided not to repair engine
- Owner got second hand engine from Rural Wrecking
- Reassemble old engine to be sent back to Rural Wrecking

www.hutcheonandpearce.com.au



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3796922
Document Date:	20/05/2025
Repair Order No.:	445111
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	0
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-4560
Page:	3 of 7

Coolant In Engine Oil, resending invoice to include story

LABOUR

- Place sleeves back in engine
- Place pistions back in engine
- Tighten connecting rods
- Refit oil pump to engine
- Turn engine back upright
- Refit head to engine
- Refit rocker shaft, push rods and injectors
- Tighten bolts
- Refit injector harness
- Refit tappet cover
- Fit injector pipes to engine
- Fit fuel rail back to engine
- Refit fuel lines to engine
- Refit oil filter housing
- Refit fuel filter housing and fuel filter
- Fit exhaust manifold and turbo to engine
- Refit old timing cover and old water pump to engine
- Refit fan drive to engine
- Refit flywheel to engine
- Fit coolant overflow bottle to second hand engine
- Fit new timing cover and water pump off old engine to second hand engine using new bolts and gaskets, new seal and thrust washer
- Fit new thermostats to engine
- Fan drive and fan driven on second hand engine were broken Remove both fan drives off old engine and fit to second hand engine
- Use new gaskets on fans
- Fit torsional dampener onto crankshaft and tension bolt
- Fit transmission dampener and tension bolts

www.hutcheonandpearce.com.au



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3796922
Document Date:	20/05/2025
Repair Order No.:	445111
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	0
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-4560
Page:	4 of 7

Coolant In Engine Oil, resending invoice to include story

LABOUR

- Remove tappet cover
- Under injector wiring harness, remove old injectors and old injector lines
- Fit new injectors and line
- Replace new tappet cover gasket and tappet cover
- Undo bolts off mounting bracket
- Clean sump on tractor
- Fit new sump gasket with blue glue at front and rear
- Lift engine with shop crane and fit into tractor
- Fit sump bolts and tension
- Change engine oil filter and both fuel filters
- Refit engine wiring harness
- Refit exhaust pipe
- Refit air intake pipe
- Refit heater hoses
- Refit air hoses
- Refit coolant tan
- Refit fan shroud
- Refit top radiator mounts
- Refit fan to fan drive
- Refit engine breather
- Refit battery cables
- Charge batteries
- Fill tractor with engine oil and coolant
- Code injectors using injector calibration
- Start tractor
- Tractor had fan speed codes, crankshaft and camshaft position sensor codes
- Change sensors on both and fix broken wires to resolve codes

www.hutcheonandpearce.com.au



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3796922
Document Date:	20/05/2025
Repair Order No.:	445111
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	0
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-4560
Page:	5 of 7

Coolant In Engine Oil, resending invoice to include story

LABOUR

- Change fan speed solenoids to remove fan speed code
- Refit exhaust guards
- Refit side guards
- Refit bonnet
- Wash tractor
- Test drive tractor
- After test drive a park brake code appeared
- Test operation of park brake
- Found sump solenoid was faulty
- Replace park sump solenoid

<u>Part Number</u>	<u>Part Description</u>	<u>Serial No</u>	<u>Quantity</u>	<u>Nett Value</u>	<u>Total Cost</u>
40M7059	Snap Ring		2.00	3.81	7.62
19M8291	SCREW, HFH 8mm X 35mm		3.00	3.82	11.46
19M7786	SCREW, HFH 10mm X 30mm		1.00	3.94	3.94
F2674R	Washer		1.00	3.58	3.58
CP8276	COOLANT 10L		3.00	77.55	232.65
CP6658	PLUS 50 ENGINE OIL-20LITRES		1.00	169.11	169.11
CP6657	PLUS-50 TM ENGINE OIL-5LITRES		2.00	47.17	94.34
FUEL	FUEL Supply Charge		20.00	2.20	44.00
57M8924	ELEC. CONN		1.00	8.18	8.18
1016	HOSE CLAMP		5.00	2.91	14.55
SE501948-CR	CORE for: Injection Nozzle Reman		-1.00	155.00	-155.00
TY25879BAU	BATTERY, W		2.00	409.26	818.52
TY26632AU	Cleaning Solvent		1.00	16.94	16.94

www.hutcheonandpearce.com.au



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3796922
Document Date:	20/05/2025
Repair Order No.:	445111
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	0
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-4560
Page:	6 of 7

Coolant In Engine Oil, resending invoice to include story

				<u>LABOUR</u>
TY25624AU	GREEN SPRA	1.00	12.90	12.90
CPM555354	SEALANT	2.00	41.53	83.06
SE501948	Injection Nozzle Reman	6.00	931.39	5,588.34
RE543639	SEAL KIT	1.00	69.77	69.77
RE530194	Pump Kit	1.00	1,048.04	1,048.04
RE528096	SCREW WITH	6.00	6.03	36.18
RE525523	FILTER ELE	1.00	167.74	167.74
RE519144	SENSOR, WH	2.00	75.09	150.18
RE509672	FILTER ELE	1.00	48.54	48.54
RE242062	Solenoid Valve	1.00	874.27	874.27
RE211156	SOLENOID V	1.00	774.09	774.09
DZ120760	Cover	1.00	368.66	368.66
DZ115055	Gasket	1.00	29.88	29.88
DZ100553	THERMOSTAT	2.00	49.35	98.70
AT301456	CLAMP	1.00	47.37	47.37
TY25744	Grease	1.00	26.10	26.10
RE57190	SEAL	2.00	14.24	28.48
R536148	Screw	3.00	4.63	13.89
R527884	Gasket	1.00	96.90	96.90
TY26101AU	CLEANING S	3.00	11.21	33.63
R520844	GASKET	1.00	172.29	172.29
R504885	GASKET	1.00	38.78	38.78

www.hutcheonandpearce.com.au



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3796922
Document Date:	20/05/2025
Repair Order No.:	445111
Rego No.:	016956
Make/Model:	John Deere 8245R
Vehicle ID No.:	1RW8245RCBP016956
Fleet No.:	
Odometer:	0
Delivery Date:	11/06/2011
Invoice To:	2022132
Customer ABN:	56144208761
Tax Exempt No.:	
P/Order No.:	1-4560
Page:	7 of 7

Coolant In Engine Oil, resending invoice to include story

				<u>LABOUR</u>
R210589	Radiator Hose	1.00	100.95	100.95
R119384	Gasket	2.00	47.12	94.24
Parts Totals:		84.00		\$11,272.87

Miscellaneous Charges

Consumables **\$185.00**

Sub Total for All:	\$36,527.99
Rounding:	\$0.00
GST:	\$3,652.80
Total:	\$40,180.79

PAYMENT OPTIONS:
 PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.