

SERIAL NUMBER 12289

Work Order History Report

18-May-2026

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
TPH 962		Plant Hire 51 Volvo A40E ADT BMA Spec.						
	27284	Prepare unit to work status and fit all upgrades , fit new air filters , rust proof at 67 hrsPainted Bonnet	30/09/2010 1	67.00	Hours	.00	42.00	\$3995.91
	27316	1000 HR Service 67 hrs Labour charged on WO 27284Warranty Requested 150 hr Service	1/10/2010 12:	67.00	Hours	.00	.00	\$1462.22
	27426	October pre start checks , replace fuel filters and a/c button, paint bonnet 329 hrs	31/10/2010 1		Hours	.00	5.50	\$832.65
	27584	Glenden Repairs August - OctoberInspect A/C system 962 hrs 01/10	31/10/2010 1		Hours	.00	.00	\$245.00
	27544	Drain fuel tank, strain fuel & dose with fuel doctor	3/12/2010 12:		Hours	.00	1.60	\$183.95
	27944	500 HR Service at 647 hrs	9/02/2011 12:	647.00	Hours	.00	4.50	\$1164.69
	28617	March pre starts - Repair coolant leak on side cover and replace cover - gasket at 935 hrs	28/03/2011 1		Hours	.00	6.00	\$2526.05
	28595	1000 HR Service 966 hrs	2/04/2011 12:	966.00	Hours	.00	14.50	\$3044.95
	28957	Rectify oil leak from front axel Pos.1 brake hub & Inspection - clean to Weed and Seed standard	30/06/2011 1		Hours	.00	2.50	\$8041.50
	29480	500 HR Service 1521 hrs	29/07/2011 1	1521.00	Hours	.00	6.00	\$1285.69
	29518	August Pre-Start Checks at 1521 hrs	11/08/2011 1		Hours	.00	4.50	\$919.00
	29843	September inspections, remove diff lock switch, repair faulty wiring at compressor clutch, replace ignition barrel,	28/09/2011 1		Hours	.00	9.50	\$1078.38
	30098	2000 hr Service- 1965hrs	24/10/2011 1	1965.00	Hours	.00	10.00	\$5516.13
	30413	November pre-starts, fit rear number plate bracket	2/11/2011 12:		Hours	.00	.00	\$202.00
	30784	December Pre-Starts, replace slide rails for operators seat	13/12/2011 1		Hours	.00	5.00	\$544.00
	31051	January pre-starts,	31/01/2012 1		Hours	.00	8.50	\$580.00
	30089	Upgrade machine to BMA mine specification and fit VHF radio	30/04/2012 1		Hours	.00	.00	\$26555.00
	31736	Weed/Seed	1/05/2012 12:		Hours	.00	.00	\$1524.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	31737	Mechanical inspection, replace h/light bulbs	1/05/2012 12:		Hours	.00	.00	\$638.00
	32163	Replace belt idler pulley & belt	30/06/2012 1		Hours	.00	.00	\$292.00
	32354	Part meant for job 962/32163 (Engine Anchorage)	18/07/2012 1		Hours	.00	.00	\$1152.00
	32383	Carry out BMA inspection, check A/C wiring, replace microswitch on gear lever	27/07/2012 1		Hours	.00	.00	\$612.00
	31975	500 HR Service-2585hrs	1/08/2012 12:	2585.00	Hours	.00	.00	\$1009.74
	30821	Tyre repairs for Nebo	1/09/2012 12:		Hours	.00	.00	\$52.00
	32795	1000 HR Service- 2975hrs	24/09/2012 1	2975.00	Hours	.00	20.00	\$2659.24
	33579	Repair A/C system	26/02/2013 1		Hours	.00	.00	\$1346.00
	33912	Off Hire Inspection. 3338 hrs	27/02/2013 1		Hours	.00	.00	\$0.00
	35360	August Pre-starts. 3341 hrs	31/08/2013 1		Hours	.00	11.00	\$2216.00
	35526	Weed and seed. 3349 hrs	31/08/2013 1		Hours	.00	.00	\$2504.00
	35584	500 HR Service. 3424 hrs	2/09/2013 7:5	3424.00	Hours	.00	2.00	\$1332.74
	35693	September Pre-starts. Inspect mirror and frame damage/ replace. 3513 hrs	30/09/2013 1		Hours	.00	18.00	\$1654.28
	35958	October pre-starts. 3805 hrs	31/10/2013 1		Hours	.00	3.00	\$704.20
	36213	November pre-starts. Off hire inspection - Replace blown globes, Repair oil leak in ground dependant steering pump, replace o-rings in compensator - 3943 hrs.	31/12/2013 1		Hours	.00	19.25	\$1704.25
	36173	4000 hr Service - 3943 hrs	31/12/2013 1	3943.00	Hours	.00	24.00	\$5870.60
	37294	Pre- hire inspection. test and tag fire supression system, general clean.	30/06/2014 1		Hours	.00	.00	\$340.00
	38172	Pre hire inspection, bma compliance and cleaning, radios, and signage , fire suppression and extinguisher test and tag, remount number plate bracket and fit plates. - 4264 hrs	31/08/2014 1		Hours	.00	.00	\$1858.00
	38867	Puncture repair.	30/11/2014 1		Hours	.00	.00	\$146.00
	38661	500 HR Service - 4566 hrs	31/12/2014 1	4566.00	Hours	.00	.00	\$1884.20
	38963	Demobilize and clean, re-fitment of tailgate	31/12/2014 1		Hours	.00	.00	\$425.00
	39961	Pre-hire Inspection, Brake test, fire system check, replace LHS rear LED indicator, replace park/headlight globes. - 4567 hrs	31/08/2015 1		Hours	.00	5.00	\$1237.00
	40467	Off hire & Pre hire Inspection - 4667 hrs	30/11/2015 1		Hours	.00	.00	\$50.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	41205	Pre hire inspection. Modify BMA handrails, fit 2 x new batteries. - 4669 hrs	19/02/2016 1		Hours	.00	30.00	\$2300.13
	41276	Replace Pos.5 tyre, strip and fit new tyre - 4711 hrs	26/02/2016 1		Hours	.00	5.00	\$7385.00
	41297	March Pre-starts, replace muffler & clamps, - 4719 hrs	31/03/2016 1		Hours	.00	27.50	\$2380.00
	41572	May Pre-starts, fit new dowdy seals to engine oil filter. -	31/05/2016 1		Hours	.00	5.00	\$64.00
	41615	1000 hr Service - 4992 hrs	31/05/2016 1	4992.00	Hours	.00	9.50	\$2248.86
	41754	June Pre-starts - 4992 hrs	30/06/2016 1		Hours	.00	1.00	\$0.00
	41904	July Pre-starts. - 5004 hrs	31/07/2016 1		Hours	.00	.00	\$50.00
	42068	August Pre-starts. - 5021 hrs	31/08/2016 1		Hours	.00	.00	\$50.00
	42268	Off Dry Hire Inspection. - 5112 hrs	29/09/2016 1		Hours	.00	15.00	\$976.83
	42173	September Pre-starts, [replace middle diff input seal and nut. - 5080 hrs]	30/09/2016 1		Hours	.00	5.00	\$540.33
	42271	BMA Compliance checks, Inspection of unit, brake test & fire suppression system test, Pressure test & recertify cylinder. Repair handrails, mirror bracket, lower step at 5112 hrs	30/09/2016 1		Hours	.00	23.00	\$3508.68
	42280	Rotate tyres, fit Pos. 5 tyre from 0942, fit VLTZ in yard to Pos. 1 - 5112 hrs	7/10/2016 12:		Hours	.00	13.00	\$714.00
	42356	Prehire Inspection, fit tailgate from 981. - 5136 hrs	24/10/2016 1		Hours	.00	8.50	\$771.90
	42474	Replace AM/FM radio. - 5137 hrs	3/11/2016 12:		Hours	.00	1.25	\$295.50
	42789	500 hr Service, change out engine oil filter housing and steering damper from #981. - 5538 hrs	27/01/2017 1	5538.00	Hours	.00	20.00	\$1783.37
	42808	Replace steering damper and engine oil filter housing removed from #981.	3/03/2017 12:		Hours	.00	5.50	\$607.73
	43217	Replace broken bolt in intake manifold, remove broken stud, repair air leak on delivery pipe fitting, inspection at 5857 hrs	2/05/2017 12:		Hours	.00	2.00	\$451.16
	42886	6000 hr Service at 5857 hrs, Changed to Volvo AT102 Synthetic Transmission at 5857 hrs	9/05/2017 2:1	5857.00	Hours	.00	14.00	\$5983.35
	43625	Fire Suppression & extinguisher 6 Monthly Test & Certification - 6136 hrs	31/07/2017 1		Hours	.00	1.00	\$377.96
	43552	Pre - Hire Inspection- 6136 hrs, replace bulbs, clean, out body, weed & seed, 6136 hrs, replace reflective tape, clean cabin, windows, Brake test	1/08/2017 12:	6136.00	Hours	.00	13.50	\$1419.50
	43559	Rekit L/H Steering cylinder, strip down, replace seals,	1/08/2017 12:		Hours	.00	4.00	\$955.07

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		reassemble, replace middle diff input seals - 6136 hrs						
43859		Repair Tyre X 1 29.5R25 Bridgestone . F7S381254.	29/09/2017 1		Hours	.00	.00	\$600.00
43725		Replace Tyres - 6239 Hrs we supplied and were fitted by client	2/10/2017 12:		Hours	.00	12.00	\$21735.70
43847		500 hr Service - 6469 Hrs	31/10/2017 1	6469.00	Hours	.00	3.50	\$1430.86
43985		Replace muffler blanking cap for heated body option - 6469 hrs, light globes, repair leaking air line, fit new o-ring, check park brake operation, rear axel diff lock, exhaust leak - 6469 hrs	1/11/2017 12:		Hours	.00	4.00	\$409.97
44176		Replace Transmission installed Volvo Reman Volvo transmission - 6565 hrs, AT 102 Oil Installed [Note Serial No. 2010173002 has 3 year 6000 hour Warranty]	9/01/2018 12:	6565.00	Hours	.00	60.50	\$43819.16
44173		Off Dry Hire Inspection 6567 Hrs, replace all rear suspension blocks, belt tensioner, replace weeping hydraulic hose, fit new steering sensor, fitted rear main upgrade hose & filter, cleaned out a/c evaporator, fitted cab filters, replace exhaust manifold gaskets	15/01/2018 1		Hours	.00	.00	\$5667.11
44260		Rotate tyres. 6565 Hrs. Replace Pos.5 wheel - 6595 hrs Remove Tyre F8U184745 & Rim TN8 4359 / Replace with Tyre F0B438823 & Rim TN8 4395.	30/01/2018 1		Hours	.00	14.50	\$814.97
44369		Puncture Pos 6 Hrs Remove Tyre F7R282161 & Rim TN8 4411 / Replace with Tyre F8M282115 & Rim TN8 4359,	8/02/2018 12:		Hours	.00	8.50	\$496.90
44431		Replace hyd hose from L/S block to pump 3, inflated Pos.1 & 5 tyres - 6717 hrs	22/02/2018 1		Hours	.00	6.50	\$639.59
44207		Replace transmission oil cooler [no invoice for the recieved from CJD]	26/02/2018 1		Hours	.00	4.00	\$219.78
44472		Replace hyd hose from tredle valve to front diff brake line - 6719 hrs	2/03/2018 12:		Hours	.00	6.00	\$391.00
44515		March Pre starts, Change out hoses from pumps 1,2,3 to control valve - 6727 hrs	16/03/2018 1	6727.00	Hours	.00	12.00	\$1993.56
44603		April Pre Starts 6775 Hrs ,Looked at a/c fault + cleaned out evaporator and replaced outer a/c filter + checked thermostat cycles (ok),reset cushion sensor in seat,	9/04/2018 12:		Hours	.00	3.00	\$315.11
44753		1000 hr Service 6969 Hrs.	17/05/2018 1	6969.00	Hours	.00	6.50	\$1547.78
44980		C/o Pos 4 Tyre on site 7092 Hrs, Remove Tyre F1S384234 & Rim TN8 4409 / Replace with Tyre F7R282166 & Rim TN8	30/06/2018 1		Hours	.00	6.50	\$379.01

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		4533.						
45061		Replace all tyres -7140 Hrs. Remove pos 1 YVC6721M1A/Replace F8E484307-Pos 2 EVC0272A0A/F8E484252 - Pos 3 F0Y281338/F8E383386 - Pos 4 F7R282166/ F8Y284026 - Pos 5 F0B483823/F8E484308 - Pos 6 F8M282115/ F7A382080	10/07/2018 1		Hours	.00	.10	\$31111.00
45179		Late invoice for parts relating to work order 44207 & 44173 - replacement of oil cooler	19/07/2018 1		Hours	.00	.00	\$4501.65
45223		Replace Battery isolator switch -7204 Hrs	31/07/2018 1		Hours	.00	2.50	\$857.32
45233		August prestarts, Troubleshoot hyd leak + replaced orings on steering damper hose fitting 7012 Hrs Topped up Hyd Oil 20Ltrs, + replace muffler cap	31/07/2018 1		Hours	.00	3.00	\$462.19
45300		Replaced seat cushion sensor + fitted new muffler blanking cap + trouble shot park brake fault, 7265 Hrs,	7/08/2018 12:		Hours	.00	2.50	\$390.71
45319		Transmission Calibration - 7296 hrs	13/08/2018 1		Hours	.00	1.00	\$36.75
45455		Check park brake locking on fault, test brake system & trace to failed brake accumulators - 7404 hrs, reported fuel system	25/09/2018 1		Hours	.00	8.50	\$453.00
45424		500 hr Service 7478 Hrs	4/10/2018 12:	7478.00	Hours	.00	6.00	\$906.74
45628		October pre starts, 7492 Hrs, Check fuel issues, no faults found	8/10/2018 12:		Hours	.00	4.50	\$315.50
45757		Got RHS tailgate bearing to take grease + deflated tyres to 65 psi 7532 Hrs	15/11/2018 1		Hours	.00	5.00	\$279.35
45845		Replace all brake Accumulators -7622 Hrs	10/12/2018 1		Hours	.00	16.50	\$6652.36
45847		Off Dry Hire Inspection -7622 Hrs, Replace all Torque rod bushes, alt & belt, Pos.3 bellow, fire ext, repair & weld in new wear plate to rear dovetail section on body floor , clean battery terminals, grease all, top up oils coolant, get tailgate bearings to take grease, restamp all rims, replace o-rings pto's, replace hose pto pressure rail, fit safety stickers & non slip tape & reflective tape & aircon vent,	12/12/2018 1		Hours	.00	48.50	\$6768.46
45871		Repair damaged rear tailshaft due to broken rear suspension blocks	12/12/2018 1		Hours	.00	2.50	\$1385.61
45848		BMA Certification & Brake test - 7624 hrs, fit second hand radio, fit lower step rubbers	20/12/2018 1		Hours	.00	7.00	\$5159.17
45903		Check steering fault -7624 hrs, hard steering, remove front floor section, ball joints, slip joint, replace lower uni-joint on	20/12/2018 1		Hours	.00	12.50	\$1394.44

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
		rack, ball joint, fabricate tool to break ball joint taper, refit parts, floor, wirng , test OK						
	46044	Late Invoice relating to work order 45848 - fire suppression system service - certification	28/01/2019	1	Hours	.00	1.00	\$1302.50
	46640	Replace the exhaust brake actuator - 8021 hrs, repair minor hydraulic oil leak, replace bulbs	17/06/2019	1	8021.00 Hours	.00	1.00	\$308.47
	46503	4000 hr Service - 8021 hrs	18/06/2019	1	8012.00 Hours	.00	17.00	\$6857.04
	46667	Replace rear diff pinion seal - 8024 hrs	11/07/2019	1	Hours	.00	3.00	\$869.80
	46732	Fire Suppression foam change over, upgrade to F 3 foam	16/07/2019	1	Hours	.00	2.00	\$2500.00
	46735	Pre Hire Inspection - 8024 hrs, replace R/H steering cylinder seals, scavenge pump seals, N 200 Batteries from stock, R/H outer mirror brace, drop box level bung, reflective tape, blue beacon with amber one, bulbs as required, repair A/C wiring fault & thermostat switch, glue down rubber step tread on battery box lid with sikaflex, clean to weed & seed standard	16/07/2019	1	Hours	.00	19.75	\$3103.69
	46737	BMA Certification checks & Tests, certify air receiver & safety valve	24/07/2019	1	Hours	.00	4.00	\$440.00
	47370	500 hr Service 8513 Hrs , Serviced By Client. no data received from them - no oil cards	20/01/2020	1	8513.00 Hours	.00	.00	\$779.52
	47695	1000 hr Service 9126 Hrs . Please change AT102	10/06/2020	1	9126.00 Hours	.00	.00	\$1546.04
	47956	Pre Hire - 9128 Hrs, Fit 4.5kg fire Ext & Bracket to l/h mud guard, fit 4.5kg Ext bracket to r/h guard, Fit L E D indicators to both sides, Exhaust heat wrap, Change to Green flashing light, Clean cab & Windows, wash truck,	13/06/2020	1	9128.00 Hours	.00	13.50	\$2852.55
	47967	BMA Certification & Brake test - 9128 Hrs	16/06/2020	1	Hours	.00	.50	\$550.00
	48464	Replace Turbo - 9537 hrs, gaskets, studs, spacers, intercooler gaskets & connection pipe, sealing rings, Check exhaust gas leaks from Turbo	5/11/2020	12:	Hours	.00	6.25	\$3644.24
	48194	500 hr Service - 9537 Hrs	12/11/2020	1	9537.00 Hours	.00	4.00	\$966.39
	48460	Replace seals in R/H hoist cylinder due to leaks from the behind the gland section - 9539 hrs, remove cylinder, clean, strip, reseal, assemble, refit to unit,bleed cylinder, test, wash unit	25/11/2020	1	Hours	.00	18.50	\$2839.35
	48459	Off Hire Inspection - 9537 hrs, replace thermostat housing & seals, coolant expansion tank, wash unit /Caloundra yard 9540	26/11/2020	1	Hours	.00	9.00	\$2677.30

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		Hrs, Fit GPS Tracker 9920, Replace both a/c filters, LED beacon, Pos 4 bellow. grease,						
48629		Breakdown on Site Batteries - 9552 Hrs, CJD Fitter, Fuel Filters & housing replaced, electrical problems ECU Replaced, Late invoice relating to work order 48459 - replace A/C control panel	19/01/2021 1		Hours	.00	16.00	\$6004.11
48740		Off / Pre Hire 9581 Hrs, grease all, replace a/c cable, a/c cover & filters, a/c vent control panel, fire ext, lubricate park brake caliper, replace flashing light base, restamp pos 5 & 6 rims, check tyres, glue bonnet treads, replace tailgate side buffers, test all,	12/02/2021 1		Hours	.00	21.00	\$7112.72
48802		Replace UHF @ 9596 hrs (new S/N 98000082)	18/02/2021 1		Hours	.00	3.00	\$743.27
48901		Off / Pre Hire 9675 Hrs, clean brake cooling screen, test operations, modify coolant pipe brackets, check tyres, weld tailgate numbers, repaint front grill,	18/03/2021 1		Hours	.00	19.00	\$5087.94
49129		Top up hydraulic oil - 9831 hrs	20/05/2021 1		Hours	.00	1.50	\$127.25
49173		2000 hr Service - 9971 Hrs	29/06/2021 1	10013.00	Hours	.00	9.50	\$4694.69
49284		Off / Pre Hire - Hrs, repair cracks in body floor plates, replace Pos.6 suspension block, brake cooling hoses on both rear axles, W/P idler pulley bearing, R/H kerb Mirror, fuel tank screen screws, 9kg fire ext, repairs to mines triangle bracket & fit to machine	2/07/2021 12:		Hours	.00	13.50	\$4164.92
49659		Replace Grease line R/H tailgate & grease nipples X 3, 10206 Hrs, Check longitude switch,	24/09/2021 1		Hours	.00	2.00	\$272.50
49754		Replace broken spotter mirror & main mirror onsite 10270 hrs - [Invoice 1176 sent on 21/10/2021]	21/10/2021 1		Hours	.00	2.50	\$305.51
49995		500 hr Service 10447 Hrs	25/01/2022 1	10513.00	Hours	.00	4.50	\$785.38
50142		Replace blown hyd hoses - 10499 hrs, replace hose from P7 compensator to pilot filter, replaced hose from LH steer cyl to junction block.	21/02/2022 1		Hours	.00	7.00	\$1097.23
50180		Replace Rear tail shaft - 10527 hrs	22/02/2022 1		Hours	.00	6.50	\$686.42
50082		Repair head unit found out of hood - 10447 Hrs, top up oils, replace h4 bulb headlight, (Scott) replaced fuel filters and cleaned out contamination - 10465 hrs	1/03/2022 12:		Hours	.00	4.00	\$607.48
50329		Carry out decommission, remove the tracker from the Machine -10599 Hrs. Remove & Replace Pos.3 & 5 rubber suspension	14/04/2022 1		Hours	.00	20.00	\$3334.89

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		Remove tire, Remove & replace 1 core & 1 rubber suspension blocks, Reinstall original drive shaft from Centre diff to rear diff, Remove all Mine spec jewellery.						
	No of W/O for 962	:	<u>121</u>	Asset Total:	<u>962</u>	<u>0.0</u>	<u>923.2</u>	<u>\$329,647.67</u>
	No of W/O for TPH	:	<u>121</u>	Parent Total:	<u>TPH</u>	<u>0.0</u>	<u>923.2</u>	<u>\$329,647.67</u>
	Grand Total		<u><u>121</u></u>		<u><u>0.0</u></u>	<u><u>923.2</u></u>	<u><u>\$329,647.67</u></u>	