



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351
 Maple Creek, SK (306) 662-2233
 Kindersley, SK (306) 463-2683
 Kyle, SK (306) 375-2302
 Leader, SK (306) 628-3889
 Unity, SK (306) 228-2696
 North Battleford, SK (306) 445-4468
 Humboldt, SK (306) 682-2572
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639
 Yorkton, SK (306) 783-9459
 Balcarres, SK (306) 334-2492
 Moosomin, SK (306) 435-3301
 Preeceville, SK (306) 547-2007
 Russell, MB (204) 773-2149
 Wynyard, SK (306) 554-2536
 Kamsack, SK (306) 542-2814
 Swan River, MB (204) 734-3466



JOHN DEERE

Greenlite work done 2023

Invoice To Account No:

Deliver To:

SERVICE INVOICE

make/model: _____
 Meter _____
 Serial Number: _____
 EQ Id: _____
 Fleet No: _____

Invoice Number: _____
 Invoice Date: 09/11/2023
 Location: 11
 Work Order Number: _____
 Payment Type: _____
 Page: 1 of 20

JOHN DEERE 9750	2913	H09750S701320	10315WK	
-----------------	------	---------------	---------	--

Service Reminders:

JGLC JD STS ALL Retail

COMPLAINT:

STS SERIES COMBINE VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

20,693.76

CORRECTION:

VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST

 HEADER SERIAL # H00914W690557
 ENGINE HOURS 2913
 SEPERATOR HOURS 2009

DOES THIS UNIT GET A VALUEMAX STICKER * NO
 HAS THE STICKER BEEN INSTALLED * NO
 THIS UNIT HAS HAD THE CAB CLEANED JC (INITIAL)
 THIS UNIT HAS HAD A FINAL CHECKOVER RP (INITIAL)
 THIS UNIT HAS HAD A COMPLETE GREASE JOB RP (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:

 WARRANTY DATES ON REPAIRS COMPLETED
 STARTS: September 8, 2023
 ENDS: September 8, 2024

Job Total: \$2,500.00

JFCC JD ALL Retail

COMPLAINT:

FREE CLEANUP OF CAB

CORRECTION:

Cleaned cab and windows

Job Total: \$0.00

JGEN02- Retail



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708377

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



SERVICE INVOICE

Invoice To Account No: _____
 Deliver To: _____

Invoice Number:	
Invoice Date:	09/11/2023
Location:	11
Work Order Number:	
Payment Type:	
Page:	2 of 20

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:

COMPLAINT:

INSTALL MISSING BACKSHAFT SPEED SENSOR

CORRECTION:

Went to parts, ordered and grabbed the missing nuts for speed sensor
 Cleaned connections and wiring
 Installed and set gap on missing back shaft speed sensor
 Function checked
 Work complete

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH116104	SENSOR	1.00	58.52	\$58.52	Y
H104418	NUT	2.00	3.98	\$7.96	Y
Labor: \$90.00					
Parts: \$66.48					
OL&M: \$0.00					
Misc: \$0.00					
				Sub-Total: \$156.48	

9750STSF878505 Retail

COMPLAINT:

UPPER FEEDER HOUSE SHAFT AND SPROCKETS, REPLACE

CORRECTION:

Separated chain, removed slip clutch and removed wear plates.
 Loosened sprockets
 adjusted, set sprockets tight and hardware with loctite
 reassembled all parts
 work complete

Labor: \$1,260.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,260.00
--------------------------	----------------------	-------------------------	---------------------	------------------------------

9750STSF877541 Retail

COMPLAINT:

REPLACE FEEDERCHAIN OUTER CENTER RAILS

CORRECTION:

removed feederhouse turned 90 degrees
 removed feederchain, wear poly, strippers



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2896	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



SERVICE INVOICE

Invoice Number:	
Invoice Date:	09/11/2023
Location:	11
Work Order Number:	
Payment Type:	
Page:	3 of 20

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:

removed entire rails assembly from combine to gain access for outer center support removal and replacement, they were very jammed in place
 installed new center out rails, installed into feederhouse
 installed new wear poly strippers
 removed half link from feederchain
 installed feederchain and tensioned
 installed all removed components
 function checked
 work complete

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH155035	RUNNER	2.00	852.46	\$1,704.92	Y
H141123	NUT	7.00	2.16	\$15.12	Y
H171960	STRIP	3.00	34.91	\$104.73	Y
T13119	O-RING	1.00	3.26	\$3.26	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.00	\$1.00	Y
EF50	ENVIRO FEE	1.00	0.50	\$0.50	Y
Labor: \$1,077.25		Parts: \$1,828.03	OL&M: \$0.00	Misc: \$1.50	Sub-Total: \$2,906.78

JGEN01- Retail

COMPLAINT:

REPLACE LEAKING FEEDERHOUSE HOSE ON RHS

CORRECTION:

removed covers
 noted hose goes from RHS front of feederhouse to engine bay, 30+ clamps to remove and feed hose through and back
 function and leak checked
 work complete

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
X1JC43-6-4	-6fFF swiv	2.00	18.00	\$36.00	Y
X487-4-RL	-4 Hose 4000psi	372.00	0.65	\$241.80	Y
Labor: \$180.00		Parts: \$277.80	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$457.80

JGEN04- Retail

COMPLAINT:

REPLACE MISSING STONE TRAP RUBBER SEAL



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 81870837

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2914
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice Number:	
Invoice Date	09/11/2023
Location	11
Work Order Number:	
Payment Type:	
Page:	4 of 20

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:

CORRECTION:

REPLACED MISSING STONE TRAP RUBBER SEAL
 WORK COMPLETE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH80335	WEATHERSTR	5.00	11.62	\$58.10	Y
Labor: \$90.00	Parts: \$58.10	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$148.10	

JGEN05- Retail

COMPLAINT:

REPLACE TRANSMISSION OIL

CORRECTION:

REPLACED TRANSMISSION OIL 9L 80W90
 STRUGGLED TO REMOVE SUMP AND PIPE TO DRAIN OIL
 CLEANED AREA
 REINSTALLED SUMP AND PIPE
 FILLED WITH OIL
 FUNCTION CHECEKD
 WORK COMPLETE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY6296	80W90 946ml GL5	10.00	15.43	\$154.30	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF15	ENVIRO FEE	10.00	0.15	\$1.50	Y
Labor: \$100.00	Parts: \$154.30	OL&M: \$0.00	Misc: \$1.50	Sub-Total: \$255.80	

J06001370 JD 9750STS Retail

COMPLAINT:

09 REPLACE FEEDERHOUSE REVERSER GEARCASE OIL

CORRECTION:

DRAINED OIL. CLEANED DRAIN PLUG AND INSTALLED. REFILLED WITH NEW OIL. 2L 80W90 RAN GEARCASE AND ALLOWED OIL TO SETTLE. RECHECKED OIL LEVEL.



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



SERVICE INVOICE

Invoice Number:	
Invoice Date:	09/11/2023
Location:	11
Work Order Number:	
Payment Type:	
Page:	5 of 20

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:
WORK COMPLETE

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY6296	80W90 946ml GL5	1.00	15.43	\$15.43	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF15	ENVIRO FEE	1.00	0.15	\$0.15	Y

Labor: \$75.00 Parts: \$15.43 OL&M: \$0.00 Misc: \$0.15 Sub-Total: \$90.58

9750STSF972589 Retail

COMPLAINT:

SHOE AUGER KEYS, R&R

CORRECTION:

Open gull wing doors.
 Remove drive wheel shields and release tension on belt.
 Remove belt, pulley and keys.
 Install in reverse order to specification.
 Perform start-up procedure.
 Work complete

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
H167587	KEY	4.00	4.05	\$16.20	Y

Labor: \$360.00 Parts: \$16.20 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$376.20

J06180360 JD 9750STS Retail

COMPLAINT:

REPLACE PRIMARY COUNTERSHAFT GEARCASE INPUT SEAL AND OIL.

CORRECTION:

oil draining
 removed driveshaft set aside
 removed yoke with special tool, pulled off
 removed seal with remover
 cleaned area
 installed seal with seal installer
 installed yoke with special tool, set end play to 0.008", turned another 90 degrees
 set locking tab



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351
 Maple Creek, SK (306) 662-2233
 Kindersley, SK (306) 463-2683
 Kyle, SK (306) 375-2302
 Leader, SK (306) 628-3889
 Unity, SK (306) 228-2696
 North Battleford, SK (306) 445-4468
 Humboldt, SK (306) 682-2572
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639
 Yorkton, SK (306) 783-9459
 Balcarres, SK (306) 334-2492
 Moosomin, SK (306) 435-3301
 Preeceville, SK (306) 547-2007
 Russell, MB (204) 773-2149
 Wynyard, SK (306) 554-2536
 Kamsack, SK (306) 542-2814
 Swan River, MB (204) 734-3466



Invoice To Account No: _____ Deliver To: _____

SERVICE INVOICE

Invoice Number:	
Invoice Date	09/11/2023
Location:	11
Work Order Number:	
Payment Type:	
Page:	6 of 20

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:
 installed driveshaft
 installed 1.2L 80w90
 function checked
 work complete

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH137771	SEAL	1.00	76.32	\$76.32	Y
TY6296	80W90 946ml GL5	2.00	15.43	\$30.86	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF15	ENVIRO FEE	2.00	0.15	\$0.30	Y
Labor: \$450.00		Parts: \$107.18	OL&M: \$0.00	Misc: \$0.30	Sub-Total: \$557.48

JGEN06- Retail

COMPLAINT:

REPLACE LOWER FEEDERHOUSE DRIVE BELT

CORRECTION:

REPLACED LOWER FEEDERHOUSE DRIVE BELT
 REQUIRED FREEING UP OF SEIZED TENSIONER PULLEY ASSEMBLY
 WORK COMPLETE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H125565	BELT	1.00	197.98	\$197.98	Y
Labor: \$90.00		Parts: \$197.98	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$287.98

JGEN07- Retail

COMPLAINT:

REPLACE UPPER FEEDERHOUSE DRIVE BELT

CORRECTION:

REPLACED UPPER FEEDERHOUSE DRIVE BELT, REQUIRED REMOVAL OF SHIELDS, PUMP BRACKET, IDLER SUPPORT
 BRACKET R & R
 WORK COMPLETE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H156796	V-BELT	1.00	270.35	\$270.35	Y



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

[Empty box for account and delivery details]

Invoice Number:	
Invoice Date:	09/11/2023
Location:	11
Work Order Number:	
Payment Type:	
Page:	7 of 20

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:

Labor: \$90.00	Parts: \$270.35	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$360.35
----------------	-----------------	--------------	--------------	---------------------

9750STSF908937 Retail

COMPLAINT:

14 CONCAVE LEVEL, ADJUST

CORRECTION:

- Placed rotor gearcase in neutral.
- Removed rotor covers.
- Leveled concaves.
- Set zero, calibrated.
- Doubled checked, ok
- Reinstalled removed covers
- Placed rotor in gear 2
- Work complete

Labor: \$270.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$270.00
-----------------	---------------	--------------	--------------	---------------------

JGEN08- Retail

COMPLAINT:

REINSTALL CONCAVE POSITION SENSOR

CORRECTION:

- REINSTALLED CONCAVE POSITION SENSOR BY REMOVING MOUNTING PLATE, BENDING BACK INTO SHAPE AND REINSTALLING & CALIBRATING
- WORK COMPLETE

Labor: \$90.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$90.00
----------------	---------------	--------------	--------------	--------------------

JGEN09- Retail

COMPLAINT:

REPLACE MISSING REAR CONCAVE CENTER RETAINER

CORRECTION:

- installed all 3 concaves, z bar, installed and torqued



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

Invoice To Account No: 77-1000

Deliver To:

SERVICE INVOICE

Invoice Number:	
Invoice Date	09/11/2023
Location:	11
Work Order Number:	-----
Payment Type:	
Page:	8 of 20

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:
 work complete

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
A15147	SPRING LOC	1.00	2.72	\$2.72	Y
H170350	SUPPORT	1.00	77.56	\$77.56	Y
H170351	WEDGE	1.00	59.02	\$59.02	Y
Labor: \$18.00					
Parts: \$139.30					
OL&M: \$0.00					
Misc: \$0.00					
			Sub-Total:	\$157.30	

JELECDIAG4 JD ALL Retail

COMPLAINT:

RHS SHOE GRAIN LOSS DOES NOT REGISTER WIRING BROKE

CORRECTION:

RHS shoe loss sensor wiring broken - removed shields and harness clips
 Noted wiring to LHS shoe loss sensor was rubbed thru insulation as well, removed
 Repaired all questionable wiring
 Ideally entire harness needs to be changed if another problem arises, harness internally is not very good anymore
 Work complete

Labor: \$90.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$90.00
-----------------------	----------------------	-------------------------	---------------------	---------------------------

JGEN11- Retail

COMPLAINT:

FRONT GRAIN TANK CROSS AUGER BEARING NOISY

CORRECTION:

R & R left side front grain cross auger bearing
 work complete

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH133191	ECCENTRIC	1.00	22.23	\$22.23	Y
H161529	PRESSED FL	2.00	9.86	\$19.72	Y
JD39104	BALL BEARI	1.00	56.52	\$56.52	Y
Labor: \$450.00					
Parts: \$98.47					
OL&M: \$0.00					
Misc: \$0.00					
			Sub-Total:	\$548.47	

9750STSF877561 Retail



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

Invoice To Account No: _____ Deliver To: _____

SERVICE INVOICE

Invoice Number:	
Invoice Date:	09/11/2023
Location:	11
Work Order Number:	
Payment Type:	
Page:	9 of 20

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:

COMPLAINT:

VERTICAL UNLOADING AUGER, REBUILD

CORRECTION:

REBUILT UNLOADER GEARBOX AND VERTICAL AUGER
 TIMED
 REINSTALLED CHAIN AND COVERS
 INSTALLED REMOTE GREASE LINE AND P-CLAMPS
 FUNCTION CHECKED
 WORK COMPLETE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
24M7277	Washer M21x60	1.00	7.66	\$7.66	Y
AH136553	HOSE	1.00	166.13	\$166.13	Y
AH146840	AUGER	1.00	980.69	\$980.69	Y
AH90963	SEAL	1.00	50.33	\$50.33	Y
AH96585	BALL BEARI	2.00	44.92	\$89.84	Y
H149361	LOCK NUT	1.00	7.52	\$7.52	Y
H215085	SHAFT	1.00	224.21	\$224.21	Y
H64376	3/8x12" KeyStk	1.00	20.87	\$20.87	Y
JD8524	BALL BEARI	2.00	35.46	\$70.92	Y

Labor: \$1,175.40 Parts: \$1,618.17 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$2,793.57

JGEN12- Retail

COMPLAINT:

REPLACE MISSING LHS SHOE LIGHT BULB AND RETAINER

CORRECTION:

installed new left shoe light bulb and retainer.
 tested operation.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH162231	9006 Bulb 51W	1.00	13.23	\$13.23	Y
H132900	Retainer	1.00	3.11	\$3.11	Y

Labor: \$90.00 Parts: \$16.34 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$106.34



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



Invoice To Account No: _____ Deliver To: _____

SERVICE INVOICE

	Invoice Number: Invoice Date: 09/11/2023 Location: 11 Work Order Number: Payment Type: Page: 10 of 20
--	---

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:

JGEN13- Retail

COMPLAINT:

ADJUST ROTOR BELT (CANNOT ACHIEVE MAX RPM)1020RPM 8MM

CORRECTION:

ADJUST ROTOR BELT (CANNOT ACHIEVE MAX RPM)1020RPM 8MM
 ADJUSTED TO ACHIEVE MAX RPM
 VERIFIED
 WORK COMPLETE

Labor: \$180.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$180.00

JGEN14- Retail

COMPLAINT:

REPLACE CHOPPER TAILBOARD ARM

CORRECTION:

REPLACED CHOPPER TAIL BOARD ARM
 WORK COMPLETE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H204033	Support	1.00	274.79	\$274.79	Y

Labor: \$135.00 Parts: \$274.79 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$409.79

9750STSF908674 Retail

COMPLAINT:

PRIMARY COUNTERSHAFT BEARING AND SHAFT IF REQUIRED

CORRECTION:

removed belt on rh side
 1 hr removing very stubborn pulley, installed longer bolts on special tool, tapped with hammer, finally came cleaned area and shaft, checked with new bearing, new bearing too big so updated shaft needs to be installed
 removed LH feeder clutch belt and assembly from shaft
 1 hr stubborn shaft needed to be freed up from primary countershaft gearcase so that it could be slide all the way right



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

Invoice To Account No: _____

Deliver To: _____

SERVICE INVOICE

Blank area for notes or additional information.

Invoice Number:	
Invoice Date	09/11/2023
Location:	11
Work Order Number:	
Payment Type:	
Page:	11 of 20

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:

- installed new bracket on rh side for updated shaft
- installed new shaft into prim coun gearcase and installed assembly with new lock nut torqued to 242 ft lbs
- installed new bearing, locking collar and assembly on the rh side and torqued new nut to 242 ft lbs
- installed removed belt and pulley
- work complete

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
14M7291	FLANGE NUT	4.00	4.87	\$19.48	Y
19M7793	Screw M16x40 Flg 10.9	4.00	6.95	\$27.80	Y
AH213902	BEARING WI	1.00	487.15	\$487.15	Y
H165447	M30x2.0 NyLck Nut	2.00	18.65	\$37.30	Y
H214619	BRACKET	1.00	398.49	\$398.49	Y
HXE134521	SHAFT	1.00	1,666.30	\$1,666.30	Y

Labor: \$720.00 Parts: \$2,636.52 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$3,356.52

J06180150 JD 9750STS Retail

COMPLAINT:

REPLACE R.H. SIDE REAR COUNTERSHAFT JACKSHAFT BELT

CORRECTION:

REPLACED R.H. SIDE REAR COUNTERSHAFT JACKSHAFT BELT
 WORK COMPLETE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H154723	V-BELT	1.00	136.93	\$136.93	Y

Labor: \$351.00 Parts: \$136.93 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$487.93

JGEN17- Retail

COMPLAINT:

INSTALL SHOE DISCHARGE PADDLE UPDATE

CORRECTION:

Installed shoe discharge paddle update
 work complete

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
------------	-------------	----------	-----------	----------------	-----------



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: _____ Deliver To: _____

SERVICE INVOICE

Invoice Number:	
Invoice Date	09/11/2023
Location	11
Work Order Number:	441000
Payment Type:	
Page:	12 of 20

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:

AH218797	Steel		1.00	177.73	\$177.73	Y
Labor: \$360.00	Parts: \$177.73	OL&M: \$0.00	Misc: \$0.00	Sub-Total:	\$537.73	

9750STSF878495 Retail

COMPLAINT:

TAILINGS CONVEYOR CHAIN, REPLACE

CORRECTION:

Loosen tailings chain.
 Break master link.
 Remove chain and replace using new chain, master and off-set links.
 Adjust tension and test run.
 Work complete

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH148021	ROLLER CHA	1.00	449.42	\$449.42	Y
AZ10045	ECCENTRIC	1.00	13.17	\$13.17	Y
JD10384	BEARING	1.00	65.11	\$65.11	Y
Labor: \$540.00	Parts: \$527.70	OL&M: \$0.00	Misc: \$0.00	Sub-Total:	\$1,067.70

J06175008 JD 9750STS Retail

COMPLAINT:

REPLACE TAILINGS GRAIN ELEVATOR BOTTOM SPROCKET/ SHAFT KEY.

CORRECTION:

REMOVED TENSION FROM ELEVATOR CHAIN.
 DISCONNECTED ELEVATOR CHAIN.
 REMOVED HARDWARE AND BEARING.
 SLIDE OVER DRIVE SPROCKET, CUT AND INSTALL NEW KEY.
 INSTALLED SPROCKET, CONNECTED CHAIN.
 INSTALLED NEW BEARING ONTO SHAFT.
 SET ELEVATOR CHAIN TO PROPER TENSION.
 TIGHTEN ALL HARDWARE.
 INSTALLED AND TENSIONED OTHER BELTS LHS
 WORK COMPLETE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
------------	-------------	----------	-----------	----------------	-----------



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



Invoice To Account No: _____ Deliver To: _____

SERVICE INVOICE

Invoice Number:	
Invoice Date	09/11/2023
Location:	11
Work Order Number:	
Payment Type:	
Page:	13 of 20

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:					
H152916	PRESSED FL	2.00	17.78	\$35.56	Y

Labor: \$270.00	Parts: \$35.56	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$305.56
------------------------	-----------------------	-------------------------	---------------------	----------------------------

JGEN18- Retail

COMPLAINT:
 WELD/REPAIR SECTION OF CLEAN GRAIN ELEVATOR

CORRECTION:
 prepped welded and painted
 work complete

Labor: \$270.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$270.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

JGEN19- Retail

COMPLAINT:
 WELD/SUPPORT UPPER TAILINGS

CORRECTION:
 prepped welded and painted
 work complete

Labor: \$270.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$270.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

JGEN20- Retail

COMPLAINT:
 REPLACE MISSING UPPER TAILINGS INSPECTION DOOR

CORRECTION:
 Installed door

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
14M7020	M8x1.25 Wing Nut	2.00	5.67	\$11.34	Y

Labor: \$135.00	Parts: \$11.34	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$146.34
------------------------	-----------------------	-------------------------	---------------------	----------------------------



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

Invoice To Account No: _____ Deliver To: _____

SERVICE INVOICE

Make/Model: _____
 Meter _____ Serial Number: _____
 EQ Id: _____ Fleet No: _____

Invoice Number: _____
 Invoice Date: 09/11/2023
 Location: 11
 Work Order Number: _____
 Payment Type: _____
 Page: 14 of 20

JOHN DEERE 9750	2913	H09750S701320	10315WK	
-----------------	------	---------------	---------	--

Service Reminders:
9750STSF877554 Retail

COMPLAINT: **TAILINGS DRIVE BELT, REMOVE AND REPLACE**

CORRECTION:

Release belt tension.
 Replace belt.
 Installed other belts on the RH side
 Adjust tension.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH85276	Idler	1.00	86.06	\$86.06	Y
H154731	V-BELT	1.00	64.28	\$64.28	Y
Labor: \$90.00					
Parts: \$150.34					
OL&M: \$0.00					
Misc: \$0.00					
			Sub-Total:	\$240.34	

JELECDIAG6 JD ALL Retail

COMPLAINT: **REPAIR WIRING ON ALTERNATOR (DIODE)**

CORRECTION:

installed and tested operation, ok
 work complete

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE17012	Alternator Diode Harness	1.00	84.21	\$84.21	Y
Labor: \$180.00					
Parts: \$84.21					
OL&M: \$0.00					
Misc: \$0.00					
			Sub-Total:	\$264.21	

JGEN23- Retail

COMPLAINT: **REPAIR FUEL SENDER WIRING**

CORRECTION:

repaired wiring and verified operation
 work complete



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

Invoice To Account No: _____ Deliver To: _____

SERVICE INVOICE

Invoice Number: Invoice Date: 09/11/2023 Location: 11 Work Order Number: Payment Type: Page: 15 of 20	
--	--

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:

Labor: \$180.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$180.00

JGEN21- Retail

COMPLAINT:

REPLACE ENGINE OIL AND FILTERS

CORRECTION:

ENGINE OIL IS DROPPED INTO BUCKETS
 ENGINE OIL FILTER IS REPLACED
 ENGINE OIL INSTALLED
 FUNCTION AND LEAK CHECKED
 WORK COMPLETE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY26679	15W40 18.9L Plus-50 II	1.00	158.53	\$158.53	Y
Miscellaneous		Quantity	Net Price	Extended Price	Taxed Ind
EF150	ENVIRO FEE	1.00	1.50	\$1.50	Y
EF300	ENVIRO FEE	1.00	3.00	\$3.00	Y
EF50	ENVIRO FEE	1.00	0.50	\$0.50	Y

Labor: \$130.00 Parts: \$158.53 OL&M: \$0.00 Misc: \$5.00 Sub-Total: \$293.53

JGEN22- Retail

COMPLAINT:

REPLACE HYD OIL FILTERS

CORRECTION:

REPLACED AND LABELED ALL 3 HYD FILTERS
 WORK COMPLETE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH128449	Hydraulic Filter	3.00	132.02	\$396.06	Y
Miscellaneous		Quantity	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	3.00	1.00	\$3.00	Y

Labor: \$75.00 Parts: \$396.06 OL&M: \$0.00 Misc: \$3.00 Sub-Total: \$474.06



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



Invoice To Account No: _____ Deliver To: _____

SERVICE INVOICE

	Invoice Number: Invoice Date: 09/11/2023 Location: 11 Work Order Number: Payment Type: Page: 16 of 20
--	---

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:
JGEN24- Retail

COMPLAINT:

REPLACE FUEL FILTERS AND CLEAN WATER SEPERATOR

CORRECTION:

replaced strainer, water separator, filter, etc
 work complete

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
R502778	FILTER ELE	1.00	46.30	\$46.30	Y
RE509672	FILTER ELE	1.00	42.91	\$42.91	Y
RE522688	FUEL FILTE	1.00	76.79	\$76.79	Y
RE531703	FUEL FILTER	1.00	121.44	\$121.44	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.00	\$1.00	Y
EF50	ENVIRO FEE	1.00	0.50	\$0.50	Y
Labor: \$75.00		Parts: \$287.44	OL&M: \$0.00	Misc: \$1.50	Sub-Total: \$363.94

9750STSF1033413 Retail

COMPLAINT:

OIL PAN DRAIN PLUG

CORRECTION:

CLEANED AREA AROUND OIL PAN DRAIN PLUG FRONT AND BEHIND ENGINE BC IT HAS 3 DRAINS
 RAN ENGINE TO WARM UP
 DROPPED ENGINE OIL IN BUCKETS
 REMOVED TUBES FROM DRAINS, REMOVED FITTINGS X 4, INSTALLED ALL NEW O-RINGS AND PIPE THREAD SEALANT
 INSTALLED OIL
 FUNCTION AND LEAK CHECKED
 WORK COMPLETE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
R47151	O-RING	1.00	3.37	\$3.37	Y
Labor: \$458.10		Parts: \$3.37	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$461.47

JGEN25- Retail



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

Invoice To Account No: _____ Deliver To: _____

SERVICE INVOICE

Invoice Number:	
Invoice Date:	09/11/2023
Location:	11
Work Order Number:	
Payment Type:	
Page:	17 of 20

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:

COMPLAINT:

REPLACE LEVELING ROTOR SHIFT LEVER SEAL AND CHANGE OIL

CORRECTION:

REPLACED LEVELING ROTOR SHIFT LEVER SEAL AND CHANGE OIL
 FUNCTION LEAK CHECKED
 WORK COMPLETE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AT12820	SEAL	1.00	27.73	\$27.73	Y
TY6296	80W90 946ml GL5	5.00	15.43	\$77.15	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF15	ENVIRO FEE	5.00	0.15	\$0.75	Y

Labor: \$630.00 Parts: \$104.88 OL&M: \$0.00 Misc: \$0.75 Sub-Total: \$735.63

JGEN27- Retail

COMPLAINT:

REPLACE WORN OUT ELEVATOR/AUGER SEAL

CORRECTION:

REPLACED WORN OUT ELEVATOR/AUGER SEAL
 WORK COMPLETE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H167717	SHEET	1.00	178.83	\$178.83	Y

Labor: \$90.00 Parts: \$178.83 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$268.83

JGEN31- Retail

COMPLAINT:

REPAIR LIGHTS (RHS REAR RUNNING LIGHT AND LHS DISCHARGE LIGHT)

CORRECTION:

removed LH rear discharge light and found the wires were corroded.
 repaired wires and replaced bulb as it was bad too.



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

Invoice To Account No: _____ Deliver To: _____

SERVICE INVOICE

Invoice Number:	
Invoice Date:	09/11/2023
Location:	11
Work Order Number:	
Payment Type:	
Page:	18 of 20

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:
 replaced bulb for RH rear running light

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH165877	BULB	1.00	49.12	\$49.12	Y
AH165877	BULB	1.00	48.10	\$48.10	Y
H133384	3057 bulb	1.00	6.78	\$6.78	Y

Labor: \$90.00 Parts: \$104.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$194.00

JGEN33- Retail

COMPLAINT:

REPLACE FRONT ROLLER BEARINGS AND HOUSINGS

CORRECTION:

lubed front rollers
 attempted to remove locking collars, shaft damaged, tuned up shaft both sides
 removed locking collars, cleaned shafts
 removed bearings, cleaned shaft
 removed wrapped twine etc from shaft both sides
 installed new bearings into housings both sides
 installed bearings assemblies both sides and set tension
 centered and set locking collars
 installed grease zerks
 ran and function checked
 work complete

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H102699	BRG HOUSING	2.00	556.43	\$1,112.86	Y
JD8594	LOCK COLLAR	2.00	21.92	\$43.84	Y
JD9397	BALL BEARI	2.00	83.84	\$167.68	Y

Labor: \$360.00 Parts: \$1,324.38 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$1,684.38

JGEN36- Retail

COMPLAINT:

REPAIR ONE TABLE AUGER GUIDE AND GUIDE RETAINER

CORRECTION:

REPLACED ONE TABLE AUGER GUIDE AND GUIDE RETAINER AND FINGER



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



Invoice To Account No: _____ Deliver To: _____

SERVICE INVOICE

Invoice Number:	
Invoice Date	09/11/2023
Location:	11
Work Order Number:	
Payment Type:	
Page:	19 of 20

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:
 ALSO NEEDED TO USE SPECIAL TOOL TO STRAIGHTEN TUBE TO ACCEPT NEW GUIDE AND RETAINER
 WORK COMPLETE

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H162662	FINGER	1.00	11.19	\$11.19	Y
H87044	GUIDE	1.00	4.58	\$4.58	Y
H87192	CAP	1.00	4.33	\$4.33	Y

Labor: \$45.00 Parts: \$20.10 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$65.10

JGEN37- Retail

COMPLAINT:

REPAIR HEADER WARNING LIGHTS

CORRECTION:

Diagnosed a bad ground in the header wiring, cleaned connections, replaced both bulbs because they were not functioning
 While checking lights 2 combine warning lights quite working, cleaned their connections and changed one bulb
 work complete

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
19H2473	1/2 x 1.75 Cap Screw Gr8 FullThrd	2.00	4.63	\$9.26	Y
AD2062R	1156 Bulb	4.00	6.26	\$25.04	Y

Labor: \$90.00 Parts: \$34.30 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$124.30

JGEN38- Retail

COMPLAINT:

REPAIR CRACKED/BROKEN REAR SHEET

CORRECTION:

separated header from combine
 removed hardware, moved sheet away prepped welded painted, installed hardware
 prepped welded painted crack on RHR chopper pivot that was needed
 hooked header to combine
 work complete

Labor: \$180.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$180.00



P.O. Box 248
 Yorkton, SK S3N 2V7
 Phone: (306) 783-9459
 Fax: (306) 783-7177
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351
 Maple Creek, SK (306) 662-2233
 Kindersley, SK (306) 463-2683
 Kyle, SK (306) 375-2302
 Leader, SK (306) 628-3889
 Unity, SK (306) 228-2696
 North Battleford, SK (306) 445-4468
 Humboldt, SK (306) 682-2572
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639
 Yorkton, SK (306) 783-9459
 Balcarres, SK (306) 334-2492
 Moosomin, SK (306) 435-3301
 Preeceville, SK (306) 547-2007
 Russell, MB (204) 773-2149
 Wynyard, SK (306) 554-2536
 Kamsack, SK (306) 542-2814
 Swan River, MB (204) 734-3466



JOHN DEERE

Invoice To Account No: _____ Deliver To: _____

SERVICE INVOICE

Blank area for account information.

Invoice Number: _____
 Invoice Date: 09/11/2023
 Location: 11
 Work Order Number: _____
 Payment Type: _____
 Page: ZU OF ZU

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9750	2913	H09750S701320	10315WK	

Service Reminders:
JDISC JD ALL Retail

COMPLAINT:
 GREEN LIGHT INSPECTION DISCOUNTS

CORRECTION:
 20% off parts and labour as per Todd

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
DISC	Parts Discount	1.00	-3,274.80	-\$3,274.80	Y
LABDIS	LAB DISC CUST	1.00	-3,141.45	-\$3,141.45	Y

Miscellaneous Charges:
 SERVICE ACCESSORIES \$150.00

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: -\$6,266.25	Sub-Total: -\$6,266.25
---------------	---------------	--------------	-------------------	------------------------

Customer PO No:
 Tax Exempt No:
 Advisor: STEVE CURRIN

Labor:	\$15,707.25
Parts:	\$11,652.14
OL&M:	\$0.00
Misc:	-\$7,651.05
GST:	\$985.42
PST:	\$0.00
Grand Total:	\$20,693.76

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: Date: