

PATTISON AGRICULTURE LIMITED
 Hwy 7 East, Box 1180
 Kindersley, SK S0L 1S0
 Phone: (306) 463-2683
 Fax: (306) 463-6131
 Http://www.pattisonag.com
 GST Number 816708372

Swift Current, SK (306) 773-3351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2362	Preeseville, SK (306) 647-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2656	Wynyard, SK (306) 654-2636
North Battleford, SK (306) 448-4468	Kamsack, SK (306) 642-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4365	
Shaunavon, SK (306) 287-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 45342

Deliver To:

PHANTOM VALLEY FARMS LTD.
 SHAUNE SWITZER
 BOX 37
 ATTN: SHAUNE SWITZER
 SIBBALD AB T0J3E0

PHANTOM VALLEY FARMS LTD.
 BOX 37
 ATTN: SHAUNE SWITZER
 SIBBALD AB T0J3E0

Invoice Number:	3481277
Invoice Date:	08/28/2025
Location:	03
Work Order Number:	509423
Payment Type:	Credit Card
Authorization Number:	TDV020093
Page:	1 of 2

Bus Phone: (403)664-0378
 Prv Phone:

Bus Phone: (403)664-0378
 Prv Phone:

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2012 JOHN DEERE 9770STS	2766	1H09770SVA0738977	W175719	

Service Reminders:

JSC RADIUS C Retail

COMPLAINT:

01 SERVICE CALL TO AND FROM MACHINE LOCATED IN RADIUS C.

CORRECTION:

MADE 2 TRIPS.

1 - DIAGNOSE
 2 - REPAIR

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
ST MILE C	SERV TRK CHR G	1.00	252.00	\$252.00	Y
Labor: \$880.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$252.00	Sub-Total:	\$1,132.00

JELECDIAG1 JD ALL Retail

COMPLAINT:

02 PERFORM ELECTRICAL SYSTEM DIAGNOSTICS--- HMM 629.12 AND CDU 524189.09

CORRECTION:

GOT TO MACHINE AND VERIFIED CODES.
 FLASHED NEW HMM SOFTWARE.
 CALIBRATED MOISTURE AND YIELD SENSORS.
 CODE RETURNED.
 MADE DTAC CASE AND CHECKED MY WIRING TO THE MOISTURE SENSOR.
 EVERYTHING WAS GOOD AND MOISTURE SENSOR IS FAULTY.
 INSTALLED NEW MOISTURE SENSOR AND PROGRAMMED SOFTWARE.

Part Number	Description	Quantity	Net Price	Extended Price	Taxed Ind
SE502799	Moisture Sensor Reman	1.00	4,000.00	\$4,000.00	Y
SE502799-CR	CORE for Moisture Sensor Reman	-1.00	141.00	-\$141.00	Y

Miscellaneous Charges:

SERVICE ACCESSORIES

\$127.41

Labor: \$394.11	Parts: \$3,859.00	OL&M: \$0.00	Misc: \$127.41	Sub-Total:	\$4,380.52
-----------------	-------------------	--------------	----------------	------------	------------