

**PATTISON AGRICULTURE LIMITED**  
Hwy 7 East, Box 1180  
Kindersley, SK S0L 1S0  
Phone: (306) 463-2683  
Fax: (306) 463-6131  
Http://www.pattisonag.com  
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: 45342

Deliver To:

PHANTOM VALLEY FARMS LTD.  
SHAUNE SWITZER  
BOX 37  
ATTN: SHAUNE SWITZER  
SIBBALD AB T0J3E0

Bus Phone: (403)664-0376  
Prv Phone:

PHANTOM VALLEY FARMS LTD.  
BOX 37  
ATTN: SHAUNE SWITZER  
SIBBALD AB T0J3E0

Bus Phone: (403)664-0376  
Prv Phone:

<b>Invoice Number:</b>	<b>3399507</b>
Invoice Date	06/23/2025
Location:	03
Work Order Number:	489882
Payment Type:	Credit Card
Authorization Number:	TDV02997G
Page:	1 of 3

Make/Model:

Meter

Serial Number:

EQ Id:

Fleet No:

2016 JOHN DEERE 9630

4705

RW9630P010971

W175712

Service Reminders:

**JSC RADIUS C Retail**

COMPLAINT:

01 SERVICE CALL TO AND FROM MACHINE LOCATED IN RADIUS C.

SEB: DROVE OUT TO CUSTOMER ONCE.

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
ST MILE C	SERV TRK CHR G C	2.00	252.00	\$504.00	Y
Labor: \$880.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$504.00	Sub-Total: \$1,384.00	

**JHYDDIAG2 JD ALL Retail**

COMPLAINT:

02 PERFORM HYDRAULIC SYSTEM DIAGNOSTICS FAN SPEED DROPPING

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS: \_\_\_\_\_  
TALKED TO CUSTOMER ABOUT HIS HYDRAULIC PROBLEM  
WHEN HE LIFTED SHANKS THE FAN WOULD DROP  
PUT A GAUGE ON THE P PORT AND HAD HIM PUT ALL SCV IN DETENT  
THEN HAD HIM FLIP SCV TO NEUTRAL ONE BY ONE AND OBSERVED RESULTS  
GAUGE WOULD DROP 50 PSI EACH TIME  
DIAGNOSED IT TO A SHUTTLE VALVE  
WASHED OFF SCV BLOCK  
UNHOOKED FROM DRILL AND PULL IT INTO SHOP  
PULLED APART SCV STACK AND REALIZED I HAD THE WRONG PARTS  
REINSTALLED THE VALVE STACK  
WAITING FOR PARTS

JAREK .  
INSTALL ALL PARTS IN SCV .  
TOP UP OIL TEST WORK GOOD .

SEB: CUSTOMER COMPLAINT THAT HYDRAULICS NO LONGER WORKING. CANT STEER AND NO SCVS HAS PRESSURE.

GOT OUT TO UNIT AND SPOKE WITH CUSTOMER. LOOKED THREW PREVOUSE WORK DONE TO UNIT AND FOUND LOAD SENSE

**PATTISON AGRICULTURE LIMITED**  
Hwy 7 East, Box 1180  
Kindersley, SK S0L 1S0  
Phone: (306) 463-2683  
Fax: (306) 463-6131  
Http://www.pattisonag.com  
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: 45342

Deliver To:

PHANTOM VALLEY FARMS LTD. SHAUNE SWITZER BOX 37 ATTN: SHAUNE SWITZER SIBBALD AB T0J3E0  Bus Phone: (403)664-0376 Prv Phone:	PHANTOM VALLEY FARMS LTD. BOX 37 ATTN: SHAUNE SWITZER SIBBALD AB T0J3E0  Bus Phone: (403)664-0376 Prv Phone:	<b>Invoice Number: 3399507</b> <b>Invoice Date: 06/23/2025</b> <b>Location: 03</b> <b>Work Order Number: 489882</b> <b>Payment Type: Credit Card</b> <b>Authorization Number: TDV02997G</b> <b>Page: 2 of 3</b>
--	--	---

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 9630	4705	RW9630P010971	W175712	

### Service Reminders:

PRIORTY VALVE WAS WORKED ON.

CHECKED SYSTEM PRESSURE AT SCV AND FOUND ONLY 600 PSI COMING OF SCV. ON ALL SCVS. CHECKED WITH ALL SCVS DEAD HEAD AND RUNNING AND FOUND ALL ACTING THE SAME. STAYING AT 600 PSI.

THEN WITH SCVS ALL STILL ENGAGED. PRESSED ON BRAKES AND FOUND LOAD SENSE IS ACTING THE SAME. STAYING AT 600 PSI WITH BRAKES ON. ALSO STEERING BOTH WAYS AND FOUND PUMP PRESSURE STILL AT 600 PSI.

WENT TO PRIORITY LOAD SENSE VALVE BLOCK. HOOKED UP GUAGE ON LS PORT AND RETESTED THE SAME TESTS AND FOUND THE GUAGE READS THE SAME. PORT SITS HIGHER ON SHUTTEL VALVE. SUSPECT THAT SOMETHING IS JAMMED IN THE LS LINE TO THE PUMP COMPENSATOR VALVE.

TRIED TAKING OFF LINES AND FOUND NO ROOM AND TOO TIGHT FOR TOOLS AVAILABLE AT THE TIME. DECIDED TO TAKE OUT THE SHUTTLE VALVE INSTEAD. TOOK OUT THE SHUTTLE VALVE AND FOUND THAT A EXTRA PISONT ORFICE VALVE INSIDE VALVE BLOCK. TOOK OUT AND REINSTALLED EVERYTHING. TESTED AND FOUND THAT THE TRACTOR IS STILL DOING THE SAME.

CUSTOMER BROUGHT A CROWFOOT TO CRACK LINES. TOOK OFF LS LINE FROM THE SCVS TO HAV EBETTER ACCESS TO STEEL LINE TO COMPENSATOR VALVE. TOOK OFF STEEL LINE AND THEN TOOK OFF THE PORT IN PRIORITY VALVE BLOCK AND FOUND A BALL BLOCKING PORT.

INSTALLED ALL TAKE OFF. TESTED SYSTEM AND FOUND ALL NOW WORKING NORMALY. TESTED CUSTOMERS ORIGINAL COMPLAINT OF FAN SPEED DROPPING WHILE TURING AND PULLING SHANKS OUT OF GROUND AND FOUND ALL WORKING GOOD NOW. TOPPED UP HYDRAULIC OIL. ALL OK COMPLETED

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AR69444	HY-GARD 18.9L J20C PAIL	4.00	158.46	\$633.84	Y
R111292	DISK	12.00	4.45	\$53.40	Y
RE186600	1/2" SCV Socket Seal Kit	2.00	42.65	\$85.30	Y
RE220261	Fitting	4.00	40.07	\$160.28	Y
RE237001	O-RING KIT	4.00	79.89	\$319.56	Y
RE274550	Check Valve	1.00	309.83	\$309.83	Y
T78612	O-RING	1.00	4.70	\$4.70	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF300	ENVIRO FEE	4.00	3.00	\$12.00	Y
FRT	FREIGHT	1.00	35.00	\$35.00	Y

Labor: \$1,680.00    Parts: \$1,566.91    OL&M: \$0.00    Misc: \$47.00    Sub-Total: \$3,293.91

**JHYDDIAG1 JD ALL Retail**

COMPLAINT:

03 PERFORM HYDRAULIC SYSTEM DIAGNOSTICS - HYDRAULIC LEAK UNDER CAB



**PATTISON AGRICULTURE LIMITED**  
Hwy 7 East, Box 1180  
Kindersley, SK S0L 1S0  
Phone: (306) 463-2683  
Fax: (306) 463-6131  
Http://www.pattisonag.com  
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: 45342

Deliver To:

<b>PHANTOM VALLEY FARMS LTD.</b> SHAUNE SWITZER BOX 37 ATTN: SHAUNE SWITZER SIBBALD AB T0J3E0  Bus Phone: (403)664-0376 Prv Phone:	<b>PHANTOM VALLEY FARMS LTD.</b> BOX 37 ATTN: SHAUNE SWITZER SIBBALD AB T0J3E0  Bus Phone: (403)664-0376 Prv Phone:	<b>Invoice Number: 3399507</b> <b>Invoice Date:</b> 06/23/2025 <b>Location:</b> 03 <b>Work Order Number:</b> 489882 <b>Payment Type:</b> Credit Card <b>Authorization Number:</b> TDV02997G <b>Page:</b> 3 of 3
<b>Make/Model:</b> 2016 JOHN DEERE 9630	<b>Meter:</b> 4705 <b>Serial Number:</b> RW9630P010971	<b>EQ Id:</b> W175712 <b>Fleet No:</b>

Service Reminders:

### CORRECTION:

CARTER-- INSPECTED FOR A LEAK COMING FROM UNDER CAB. OIL WOULD SPRAY EVERYWHERE ONCE TRACTOR WAS STARTED. CLEANED AREA AND CHECKED FOR LEAKS. FOUND A HYDRAULIC LINE O RING TO BE LEAKING JAREK

CHECKED FOR LEAKS AND FOUND THE O RING WAS NOT LEAKING BUT A HOSE WAS RUBBED THROUGH CAUSING THE LEAK, REMOVED HOSE AND HAD A NEW HOSE MADE AND REINSTALLED.

CHECKED LEAK . HOSES LEAK . REMOVE AND REPLACE HOSES . TOP UP OIL TEST WORK GOOD .

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE219871	Pressure Relief Valve	1.00	434.39	\$434.39	Y
RE582808	Seal Kit	3.00	174.35	\$523.05	Y
X1J943-8-8	-8fFF 90short	1.00	41.92	\$41.92	Y
X1JC43-8-8	-8fFF swiv	1.00	26.33	\$26.33	Y
X487-8-RL	-8 HOSE(1/2") 4000 PSI	46.00	0.88	\$40.48	Y

### Miscellaneous Charges:

SERVICE ACCESSORIES

\$150.00

Labor: \$600.00	Parts: \$1,066.17	OL&M: \$0.00	Misc: \$150.00	Sub-Total: \$1,816.17
-----------------	-------------------	--------------	----------------	-----------------------

### Credit Card Information

<b>Customer PO No:</b> <b>Tax Exempt No:</b> <b>Advisor:</b> JP Strydom	<b>Type:</b> Credit Card <b>Auth No:</b> TDV02997G <b>Amount:</b> \$6,980.69	<b>Labor:</b> \$3,160.00 <b>Parts:</b> \$2,633.08 <b>OL&amp;M:</b> \$0.00 <b>Misc:</b> \$701.00 <b>GST:</b> \$324.73 <b>PST:</b> \$161.88 <b>Grand Total:</b> \$6,980.69
---	--	--

### TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: .....

Date: .....