

RITCHIE BROS. Diagnostic Report
 Auctioneers[®]
2009 International DuraStar 4300**Test Information**

Engine	International DT466/Maxxforce DT (7.6)
Engine Serial	INT *466224240711696M07*5005040563--
VIN	1HTMMAAN79H088391
Driveline	Class 7 4x2
Body	Truck
Test Time	Sept. 9, 2026, 3:59 p.m.
File Length	33.998 s

Usage

Label	Value	Units
Engine Odometer	240,396	mi
Engine Total Hours of Operation	12,115.2	h

Engine On/Off

Engine running

Check Engine Light

No check engine lights on

Emissions Deleted/Tampered

No

Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Active	Body Controller	Manufacturer Assignable SPN	Abnormal Update Rate	10
Previous	Body Controller	Manufacturer Assignable SPN	Erratic, Intermittent, or Incorrect	24
Previous	Body Controller	Source Address 0	Data Error	9
Previous	Body Controller	Manufacturer Assignable SPN	Out of Calibration	22
Previous	Body Controller	Cab HVAC Recirculation Door Control Actuator	Erratic, Intermittent, or Incorrect	3
Previous	Body Controller	Manufacturer Assignable SPN	Erratic, Intermittent, or Incorrect	11
Previous	Body Controller	Manufacturer Assignable SPN	Out of Calibration	24
Previous	Body Controller	Operator Input device for Cab Climate Control	Erratic, Intermittent, or Incorrect	2
Previous	Body Controller	Manufacturer Assignable SPN	Abnormal Update Rate	9