



**INLAND TRUCK
PARTS & SERVICE**

Employee Owned

inlandtruck.com

406 W Hwy 14
FORT PIERRE, SD 57532
(605) 223-2385

INVOICE

Invoice # [REDACTED]

SO # [REDACTED]

Date 08/09/2024

Writer [REDACTED]

Page 1 of 1

Inv: Cust [REDACTED] Cust acct# [REDACTED] Cust PO# [REDACTED]

Sold to: [REDACTED]
[REDACTED] 0

Ship to: [REDACTED]
[REDACTED]

Contact	Payment terms	COD Customer Choice	Ship via	None Specified			
Contact phone	Primary phone			Prepay and Add			
Repair Order no.	Operation #	1					
Condition	Fix ac						
Correction	Pulled truck into shop and inspected AC system. Found that the compressor would not turn on and did not have power going to it. Diagnosed no power to the compressor and found that the incorrect fuse was installed in the fuse panel for the AC compressor causing a bad connection. Checked AC performance and found that the system was over charged and the evaporator was severely plugged. Recovered the system and removed the evaporator. The low side line was seized to the evaporator so the evaporator and line were ruined upon removal. Cleaned out HVAC box and installed a new evaporator with new orifice tube with all new o-rings. Installed low side line with new o-rings and replaced accumulator. Installed a new cab air filter. Vacuumed the system and tested for leaks. Charged the system to spec. Ran the AC to confirm good performance.						
Part number	Description	Ord	Del	B/O	List Price	Unit price	Ext. price
507_800-2001	ACCUMULATOR - PACCAR	1	1	0	105.57	59.86	59.86
507_PART	MISC PART	1	1	0	0.00	627.63	627.63
400-5107 Evaporator							
460_F50-6332	HARDLINE ASSY.EVAP TO ACCUMALATOR	1	1	0	884.50	434.81	434.81
507_450-7004	ORIFICE TUBE - .062 RED	1	1	0	16.88	9.69	9.69
							1,118.70
Freight In	Freight In On Evaporator						98.65
Freight In	Freight In on Hardline						18.20
Shop supplies							78.31

#10917
Shop

Received by

See warranties on reverse side

Total merchandise	1,327.15
Total cores	0.00
	1,118.70
Tax amount	151.63
Invoice total	\$2,597.48