



Vehicle History Detail



Fleet #	PM394
Registration	XQ73QI
Make	Kenworth
Model	K200
VIN / Chassis #	6F5000000MA469819

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
		Heavy Vehicle Inspection Checklist - Truck I-886			\$0.00
		C S-16211 carry out c service	QLD WORKSHOP		\$1,194.75
26/02/2026	1,061,472 kms	NEW DRIVES T-4029	TREADCARE PTY LTD		\$1,650.00
03/02/2026		MUDFLAPS R-7033 BUMBER BAR SLIM MUDFLAPS	QLD WORKSHOP		\$220.00
27/01/2026		ACCIDENT REPAIR R-6998	RECAR BRISBANE		\$0.00
19/01/2026	1,061,517 kms	A S-15872 carry out a service carry out inspection after vehicle was involved in an accident check custom air wiring truck batteries keep going flat when custom air is running service custom air download ecm replace custom air relays	QLD WORKSHOP		\$76.97
19/01/2026		custom air service R-6979 1 X CUSTOM AIR SERVICE	QLD WORKSHOP		\$60.14
15/01/2026	1,061,381 kms	ROTATE DRIVES, ROTATE STEER T-3918 rotate drives diagonal rotate steers	DARREN BUDD'S TYRES PTY LTD		\$0.00
08/01/2026		ACCIDENT REPAIR R-6906	WARREGO TRANSPORT REPAIRS PTY LTD		\$770.00
08/01/2026		TOWING R-6919	QLD WORKSHOP		\$660.00
08/01/2026	1,059,477 kms	STEER BLOW OUT T-3886	TREADCARE PTY LTD		\$0.00
07/01/2026	1,059,591 kms	A S-15986 carry out a service inspect custom air blowing hot air send to qld workshop for repair	MAXIPARTS VIC		\$0.00
05/01/2026		BREAKDOWN R-7044 WARREGO TO ATTEND FLAT BATTERIES - SYDNEY	WARREGO TRANSPORT REPAIRS PTY LTD		\$550.00
29/12/2025	52,982 kms	CUSTOM AIR KIT R-6858	QLD WORKSHOP		\$22.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
25/11/2025	1,041,241 kms	B S-15532 CARRY OUT B SERVICE CUSTOM AIR WON'T STAY ON (stays on for 2sec)	QLD WORKSHOP		\$173.45
25/11/2025	28,928 kms	295/80R BRIDGESTONE T-3763 1 X 295/80R22.5 B/STONE R154 P1.	DARREN BUDD'S TYRES PTY LTD		\$0.00
20/11/2025	1,028,694 kms	A/C REPAIRS R-6690	QLD WORKSHOP		\$410.15
10/11/2025	23,776 kms	11R 22.5 ATT 101, 295/80R BRIDGESTONE, ROTATE TYRES T-3733	DARREN BUDD'S TYRES PTY LTD		\$0.00
24/10/2025		tv antenna R-6562	QLD WORKSHOP		\$82.24
21/10/2025	1,023,382 kms	custom air repair R-6545	QLD WORKSHOP		\$60.14
13/10/2025	1,021,477 kms	A S-15216 CARRIED OUT A SERVICE TIGHTEN UP BELLY BAR DOWN LOAD COMPLETED CUSTOM AIR UNIT @ 1039 DUE @ 1070	QLD WORKSHOP		\$0.00
08/10/2025		AIR CONDITIONER R-6495	PRECISION TRUCK AIR & STAINLESS		\$0.00
30/09/2025	1,009,981 kms	VIBRATION R-6467	QLD WORKSHOP		\$0.00
09/09/2025	1,002,890 kms	custom air repair R-6351 custom air alt belt	QLD WORKSHOP		\$110.00
09/09/2025	1,002,890 kms	custom air repair R-6350 TOP CUSTOM AIR BUSH	QLD WORKSHOP		\$60.50
04/09/2025	1,002,890 kms	A S-14910 CARRY OUT A SERVICE	QLD WORKSHOP		\$0.00
04/09/2025	1,002,890 kms	DRIVERS SEAT, IGNITION R-6333	QLD WORKSHOP		\$440.00
19/08/2025	987,312 kms	A S-14749 A SERVICE COMPLETED CUSTOM AIR SYSTEM @2940HRS NEXT DUE @3070HRS WORK LIGHT REPAIRED CLUTCH ADJUSTED PARK BRAKE ALARM REPAIRED FRONT HUB CAP COVERS REPLACED AS THEY WERE LEAKING OIL PRESSURE DASH LIGHT SENSOR REPLACED AS IT WAS LEAKING OIL FRONT END BANGS WERE THE SHACKLES NEEDING TIGHTENING.	QLD WORKSHOP		\$0.00
19/08/2025	987,312 kms	DRIVER SEAT, LIGHTS R-6215 ADJUSTED THE MECHANISUM OF THE SEAT WORK LIGHT REPAIRED CLUTCH ADJUSTED PARK BRAKE ALARM WAS FAULTY HORNS, RELAY FRIED. FRONT PLASTIC HUB CAPS REPLACED REPLACED OIL PRESSURE IDIOT LIGHT SENSOR, RESEALED OIL PRESSURE SENSOR BANK TIGHTENED SHACKLE HOLDERS AND U BOLTS AS THEY WERE ALL LOOSE.	QLD WORKSHOP		\$112.24
31/07/2025	968,669 kms	B S-14610 B SERVICE COMPLETED NEW DASH GLOBES NEW DASH MONKEY LIGHTS REPLACED STEP LIGHT REPLACED COOLANT FILTER NEW ESOC BUNG FITTING	QLD WORKSHOP		\$443.10

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
14/07/2025	950,240 kms	A S-14484	QLD WORKSHOP		\$0.00
14/07/2025	950,240 kms	POWER LOSS R-6073 NO FAULTS FOUND EXHAUST FELL OFF TURBO HOUSING, REFITTED	QLD WORKSHOP		\$0.00
30/06/2025		PUNCTURE REPAIR T-3419	QLD WORKSHOP		\$49.50
30/06/2025	934,911 kms	A S-14421 CARRY OUT A SERVICE LOW POWER CHECK WASTEGATE CHECKED ALL WORKING AS IT SHOULD ICEPACK HOURS 1940 ICEPACK DUE 3070	QLD WORKSHOP		\$0.00
11/06/2025	915,435 kms	A S-14265 CUSTOM AIR SYSTEM @2940HRS NEXT DUE @3070HRS DASH GLOBES REPLACED NEW AIR SEAT T PIECE NEW COMPRESSOR FEED LINE CLAMP NEW USB PORT FOR THE DASH NEW DASH MONKEY LIGHTS	QLD WORKSHOP		\$39.10
31/05/2025	904,767 kms	BATTERY S R-5888 REPLACED ALL 4 BATTERIES AND CHECKED ALT CHARGE RATE WAS 14.3 AND 14.1 AT BATTERIES	QLD WORKSHOP		\$698.15
28/05/2025	903,002 kms	ROTATE DRIVES, ROTATE STEER T-3349 ROTATED DRIVES SIDE/SIDE STEERS AS REQ	DARREN BUDD'S TYRES PTY LTD		\$165.00
28/05/2025	903,002 kms	B S-14057	QLD WORKSHOP		\$194.57
27/05/2025	973,245 kms	DRIVER SEAT, WASTEGATE ACTUATOR R-5819 NOTHING WRONG WITH DRIVERS SEAT NOTHING WRONG WITH WASTEGATE	QLD WORKSHOP		\$0.00
29/04/2025	881,768 kms	A S-13918 A SERVICE ADJUSTED CLUTCH AND REPAIR WIRING FOR REVERSE LIGHTS . CUSTOM AIR HRS 2908 , DUE AT 3070 HRS	QLD WORKSHOP		\$0.00
29/04/2025	881,768 kms	GEARBOX OILS R-5751 CHANGED OIL ONLY	QLD WORKSHOP		\$0.00
08/04/2025	862,249 kms	NEW STEERS T-3285 REPLACE STEER TYRES	QLD WORKSHOP		\$1,529.00
07/04/2025	862,249 kms	A S-13765 CUSTOM AIR SYSTEM@ 2906HRS NEXT DUE @3070 REPLACED REAR DIFF SENSOR.	QLD WORKSHOP		\$88.44
20/03/2025	846,537 kms	DRIVE BRAKES R-5621 REMOVE AND REPLACED WORN BRAKES SHOES, DRUMS AND HARDWARE, 1ST DRIVE AXLE, READJSUTED BRAKES SENT BACK INTO SERVICE	QLD WORKSHOP		\$632.13
19/03/2025	846,537 kms	ROTATE DRIVES, ROTATE STEER T-3227 QLD WORKSHOP ROTATED DRIVES DIAGONAL AND LEFT STEERS TO REPLACED NEXT SERVCIE	QLD WORKSHOP		\$0.00
19/03/2025	846,537 kms	B S-13652 CUSTOM AIR 2900HRS DUE 3070HRS REMOVE AND REPLACED IST DRIVE AXLE BRAKES	QLD WORKSHOP		\$173.80
17/03/2025	842,694 kms	PUNCTURE REPAIR T-3231 repair left hand inner on front drive puncture	DARREN BUDD'S TYRES PTY LTD		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
27/02/2025	812,618 kms	Heavy Vehicle Inspection Checklist - Truck I-671	QLD WORKSHOP		\$0.00
27/02/2025	812,618 kms	C S-13464	QLD WORKSHOP		\$1,094.81
27/02/2025	812,618 kms	A S-13602	QLD WORKSHOP		\$0.00
13/02/2025	812,618 kms	A S-13428	QLD WORKSHOP		\$0.00
05/02/2025	803,791 kms	AFTER TREATMENT , INTAKE BRACKET R-5473 REMOVED ALL LINES TO PUMP CHECKED ALL FITTINGS FOR CORROSION AND BLOCKAGES ALL GOOD REMOVED ADBLUE INJECTOR FOUND TIP BLOCKED SOAKED IN BOILING WATER TILL UNBLOCKED, FLUSHED SYSTEM WITH BOILING WATER WITHOUT INJECTOR NOZZLE ALL WORKING FINE INSTALLED INJECTOR ALL WORKING FINE, CARRIED OUT TEST CODE NO INACTIVE. FOUND P/S BOTTOM INTAKE BRACKET BROKEN REPLACED WITH BRAND NEW	QLD WORKSHOP		\$0.00
30/01/2025	989,134 kms	ADBLUE LEAK, HORTON FAN, MUDGUARDS R-5448 FIXED MUDGUARD BROKEN WIRE CAUSING FAN TO HAVE NO POWER FIXED ADBLUE CAP	QLD WORKSHOP		\$0.00
29/01/2025	796,258 kms	ROTATE DRIVES, ROTATE STEER T-3119 DRIVES ROTATED SIDE/SIDE STEER ROTATED SIDE/SIDE	DARREN BUDD'S TYRES PTY LTD		\$165.00
29/01/2025	797,123 kms	A S-13296	QLD WORKSHOP		\$0.00
15/01/2025	782,706 kms	B S-13106 B SERVICE	QLD WORKSHOP		\$191.45
07/01/2025	775,615 kms	TURN TABLE JAWS R-5328 REMOVED AND REPLACED JAW, SPRING, PIVOT TUBE, WEAR RING AND LOCKING BAR REGREASED WEAR RING AND JAW ADJUSTED TURNTABLE TESTED ON TRAILERS ALL GOOD SENT BACK TO SERVICE.	QLD WORKSHOP		\$214.07
03/01/2025	773,819 kms	AIR LINE FITTINGS, MUD GUARD R-5322	QLD WORKSHOP		\$258.83
19/12/2024	761,446 kms	A S-13000 2898 HOURS DUE AT 3070 HOURS TIGHTENED BELLY BAR ADJUSTED CLUTCH	QLD WORKSHOP		\$0.00
10/12/2024	750,990 kms	ADBLUE FAULT, AFTER TREATMENT , TRACKER R-5235 FOUND FITTING FOR DOSER PUMP FEED TO INJECTOR WORN HEAVILY AND CORROIDED FITTING, REPLACED FITTING AND CARRIED OUT DOSER PUMP OVERRIDE TEST AS NEEDED, CLEARED ALL ACTIVE ECM CODES AS REQUIRED, ALL OKAY REPAIRED WIRING TO DRIVERS SIDE LOAD LIGHT, CHECKED ALL OPERATIONS, ALL WORKING, ALL OKAY.	QLD WORKSHOP		\$104.59
03/12/2024	744,026 kms	AFTER TREATMENT , STARTER MOTOR R-5207 REPAIRED DEF SYSTEM AND ALL WORKING AS REQUIRED. REMOVED AND REPLACED STARTER MOTOR ON KILOMETERS AS REQUIRED, ALL OKAY.	QLD WORKSHOP		\$443.45
02/12/2024	744,026 kms	ROTATE DRIVES, ROTATE STEER T-3009 ROTATED DRIVES DIAGONAL AS REQUIRED. ROTATED STEERS SIDE TO SIDE AS NEEDED, TENSIONED WHEEL NUTS ALL OKAY. DONE BY QLD WORKSHOP	QLD WORKSHOP		\$0.00
02/12/2024	744,026 kms	A S-12885	QLD WORKSHOP		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
12/11/2024	732,972 kms	ALTERNATOR R-5146 REMOVED SQUEELING ALTERNATOR REPLACED FOR A BRAND NEW ALTERNATOR, CHECKED AND TESTED, CHARGING 13.5VLTs	QLD WORKSHOP	3376306	\$480.00
29/10/2024	733,891 kms	EXHAUST FLEXI, STEERING WHEEL R-5100 FOUND STEERING WHEEL U/S, REMOVED CENTRE COVER AND UNDONE 27MM NUT, REMOVED STEERING WHEEL FROM STEERING SHAFT, REFITTED NEW WHEEL INTO PLACE AND TIGHTENED NUT DOWN TO SECURE WHEEL, RECONNECTED ALL WIRES AND CHECKED ALL OPERATIONS, ALL OKAY. FOUND EXHAUST FLEX JOINT U/S REMOVED AND REPLACED FLEX JOINT AND BOTH AFM GASKETS AS NEEDED, SECURED INTO PLACE, ALL OKAY.	QLD WORKSHOP		\$1,044.14
29/10/2024	733,891 kms	A S-12571 CUSTOM AIR UNIT AT 2858 HOURS DUE AT 3070 HOURS STEERING WHEEL U/S EXHAUST FLEX JOINT U/S ADJUSTED CLUTCH AS REQUIRED	QLD WORKSHOP		\$0.00
09/10/2024	719,350 kms	B S-12378 B-SERVICE REPLACED AFM GASKET	QLD WORKSHOP		\$205.85
20/09/2024	708,247 kms	100,000KLM ENGINE TUNE], INVERTER R-4913 CARRIED OUT TOP TUNE 100,000KMS AFTER REBUILD FOUND LOOSE NUT ON INVERTER FUSE CONNECTION TIGHTENED RETESTED AND WORKING CORRECTLY	QLD WORKSHOP		\$0.00
16/09/2024	704,510 kms	A S-12190 CUSTOM AIR SERVICED AT 2770HRS REPLACED DASH BULBS AS NEEDED REPLACED MISSING HUB CAP	QLD WORKSHOP	3327071	\$77.83
16/09/2024	704,510 kms	NEW DRIVE TYRES T-2836 QLD WORKSHOP REMOVED AND REPLACED DRIVES TYRES WITH NEW	QLD WORKSHOP		\$5,984.00
27/08/2024	688,779 kms	A S-12014 ICEPACK 2737HRS Due @ 2780hrs MONITOR DIFF OUTPUT SEAL	QLD WORKSHOP		\$0.00
27/08/2024	688,779 kms	ROTATE DRIVES, ROTATE STEER T-2732 DRIVES NOT ROTATED STEERS AS REQUIRED FLIPPED POSITION 2 ON RIM TO GO ONTO POSITION 1	QLD WORKSHOP		\$0.00
02/08/2024	672,363 kms	A S-11789 Ice pack 2710hrs Due @ 2780hrs fitting 2 new toque rod bushes to rear axle repair seat tilt handle tyre rotate done	QLD WORKSHOP		\$0.00
02/08/2024	672,363 kms	DRIVERS SEAT, HUB CAP COVERS, TORQUE ROD BUSHES R-4814 Fitting 2 new toque rod bushes to rear axle fitting new steer hub cap repaired drivers seat adjustment arm	QLD WORKSHOP		\$242.06
18/07/2024	665,487 kms	LIGHT PLUG R-4748 REPLACED THE MALE LIGHT PLUG FOR NEW ONE AS IT HAD MELTED BECASUE A WIRE FELL OUT CHECKED ALL GOOD TRUCK SENT INTO SERVICE			\$19.16
09/07/2024	657,340 kms	B S-11561 LOOSE BOLTS FOUND ON P/S REAR ENGINE MOUNT, REMOVED AND REPAIRED THREAD ONE BOLT HOLE TO DAMAGED TO REPAIR (CHECK ON NEXT SERVICE) SLIGHT PLAY IN BOTH KING PINS CUSTOM AIR CURRENTLY 2710HRS DUE 2780HRS	QLD WORKSHOP		\$196.67

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
21/05/2024	639,102 kms	A S-11089 jacked up and inspected front wheel bearings all ok	MELBOURNE VIC WORKSHOP		\$0.00
29/04/2024	624,820 kms	ROTATE DRIVES, ROTATE STEER T-2519 ROTATE DRIVES SIDE/SIDE ROTATE STEERS SIDE/SIDE	DARREN BUDD'S TYRES PTY LTD		\$165.00
29/04/2024	624,820 kms	A S-10899 A-SERVICE 1ST DIFF OUT PUT SHAFT SEAL LEAKING	QLD WORKSHOP		\$0.00
10/04/2024	611,798 kms	HEATER CORE, OIL PRESSURE SWITCH, REKIT HORTON FAN HUB, REPLACE COMP ON KLMS, SUNVISOR CLIP, SUN VISOR R-4297 REPLACED HEATER CORE DUE TO LEAK REPLACED SUNVISOR DUE TO CRACKED MOUNT REPLACED INTERNAL SUNVISOR CLIP OIL LIGHT FLASHING DUE TO HEAVY RAIN WETTING WIRING REMOVE FAN FROM HUB AND REMOVE HUB FROM MOTOR PULL DOWN HORTEN HUB ON BENCH AND CLEAN ALL MAIN PARTS REKIT AND ASEMBLE AND REINSTALL INTO TRUCK, REFIT FAN START TRUCK UP AND TEST HORTEN FAN DRAIN COOLANT OUT OF TRUCK, REMOVE ALL AIR PIPING AND COOLANT LINES FROM COMPRESSOR, REMOVE POWER STEERING PUMP FROM COMPRESSOR, REMOVE COMPRESSOR, USE FITTINGS FROM OLD COMPRESSOR BUT REPLACED ALL O-RINGS, CLEANED ALL SURFACE AND REPALCED COMPRESSOR GASKET, INSTALLED COMPRESSOR AND FITTED ALL LINES BACK ON REMOVE AND REAPLCED GOVERNER VALVE, REPLACED GASKET BETWEEN COMPRESSOR AND POWER STEERING PUMP, PUT COOLANT BACK INTO TRUCK AND SENT FOR A TEST DRIVE, AFTER TEST DRIVE CHECKED ALL COMPONENTS FOR LEAKS, NO LEAKS FOUND. SENT TRUCK BACK INTO SERVICE	QLD WORKSHOP	3194506	\$5,367.28
10/04/2024	611,798 kms	A S-10752 A-SERVICE FAN HUB AND COMPRESSOR REPLACED HEATER CORE REPLACED SUNVISOR REPLACED INTERNAL SUNVISOR CLIP	QLD WORKSHOP		\$0.00
13/03/2024	594,592 kms	B S-10561 ICE-PACK HRS, CURRENTLY 2644 DUE 2780HRS REPLACED BOTTOM HEATER TAP REPLACED FUEL PRO COLLAR	QLD WORKSHOP		\$253.44
27/02/2024	585,101 kms	Heavy Vehicle Inspection Checklist - Truck I-434	QLD WORKSHOP		\$0.00
26/02/2024	585,101 kms	C S-10435	QLD WORKSHOP		\$1,036.65
26/02/2024	585,025 kms 7,379 hrs	ENGINE REBUILD R-4188 SENT TRUCK TO CUMMINS, FOUND DROPPED LINNER CYLINDERS 5 & 6 REMOVED AND REPLACED ALL LINNERS AND PISTON RINS. REPLACED ALL GASKETS AND SEALS AS NEEDED, TRUCK ALL OK DYNO RUN UP SENT BACK INTO SERVICE. NEW COOLANT FITTED TO COOLING SYSTEM	CUMMINS SOUTH PACIFIC PTY LTD	1170248	\$272.85
09/02/2024	579,451 kms	WATER LEAK R-4050 tightened sun visor an reaffix an filled bolt holes with silicone	MELBOURNE VIC WORKSHOP		\$0.00
07/02/2024	577,630 kms	A S-10244 GEAR STICK BOOT REPLACED RESEATED DOOR SEAL LOADING LIGHT NW TIGHETEND STEER U BOLTS AN PITMAN ARM	MELBOURNE VIC WORKSHOP		\$49.26
07/02/2024	577,630 kms	GEAR STICK BOOT R-4034 REMOVED OLD RUBBER BOOT AN FIT NEW RUBBER BOOT	MELBOURNE VIC WORKSHOP	1234204	\$89.21

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
07/02/2024	577,630 kms	ROTATE DRIVES, ROTATE STEER T-2314 ROTATE DRIVES DIAGONAL 2 X NEW STEERS BRIDGESTONES	TREADCARE PTY LTD		\$1,375.00
07/02/2024	577,630 kms	DRIVERS WINDOW R-4049 CALLED IN AUTO GLASS TO REMOVE AND REPLACE DAMAGED WINDSREEN ALL OK	AUTO GLASS SOLUTIONS PTY LTD		\$324.50
04/01/2024	564,844 kms	REVERSE SQUAWKER R-3880 REVERSE SQUAWKER FITTED AS REQUIRED AND SECURED INTO PLACE AND TESTED OPERATIONS, ALL OKAY.	QLD WORKSHOP		\$0.00
04/01/2024	564,844 kms	A S-9920 ICE PACK SERVICED 2484 HOURS NOW DUE 2784 HOURS	QLD WORKSHOP		\$41.66
13/11/2023	547,625 kms	A S-9454	MELBOURNE VIC WORKSHOP		\$0.00
12/09/2023	530,852 kms	B S-8896	QLD WORKSHOP	2989366	\$172.76
12/09/2023	530,852 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-1939 ROTATED STEERS SIDE TO SIDE AND FLIPPED ONE ON RIM ROTATED DRIVES DIAGONAL DONE BY QLD WORKSHOP	QLD WORKSHOP		\$0.00
22/08/2023	517,200 kms	AFTER TREATMENT R-3389 SCANNED TRUCK FOUND FAULT FOR FUEL PRESSURE METERING VALVE (DATA VAILD BUT ABOVE OPERATING PRESSURE) AIR IN FUEL SYSTEM CAUSES THIS FAULT, FOUND O-RING ON TOP NUT OF FUEL PRO HAD ASHFELT STONE STUCK IN IT CAUSING AIR TO GET INTO FUEL PRO AND CAUSING IT HARD TO START AND SLUGISH	MELBOURNE VIC WORKSHOP		\$0.00
17/08/2023	515,196 kms	A S-8720	MELBOURNE VIC WORKSHOP		\$0.00
29/06/2023	499,423 kms	A S-8347 ICE PACK SERVICED AT 2063 HOURS	QLD WORKSHOP	2926433	\$41.14
26/06/2023	499,423 kms	DRIVE BRAKES, TURBO ON KLMS R-3224 REMOVE TURBO AND EXHAUST MANIFOLD CLEAN ALL AREAS FOR NEW GASKETS, SPLIT TURBO FROM MANIFOLD AND CLEAN AREA INBETWEEN, REMOVE AND REPLACE ALL TURBO STUDS. MOUNT NEW TURBO TO MANIFOLD, REPALCED OLD NUTS WITH NEW AND TORQUE TO 60FT lbs, REPLACED ALL O-RINGS FOR OIL FEED LINES. REPALCED ALL MANIFOLD GASKETS, MOUNT TURBO AND MANIFOLD TO ENGINE TORQUE MANIFOLD BOLTS TO 44FT lbs. FINISHED INSTALLING ALL OTHER PIPEING FOR TUBRO, TEST RUN ALL WORKING CORRECTLY. REMOVED BRAKE SHOES AND DRUMS ON REAR DRIVE AXLE, KNOCKED OUT OLD ANCHOR PIN BUSHES AND INSTALLED NEW BUSHES. FIT UP NEW BRAKE SHOES AND DRUMS TOO 2ND DRIVE AXLE, ADJUSTED BREAKS, FIT UP TYRES SEND BACK INTO SERVICE	QLD WORKSHOP	2917018	\$8,426.22
30/05/2023	485,692 kms	A S-8142	MELBOURNE VIC WORKSHOP		\$0.00
30/05/2023	485,692 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-1759 ROTATED ALL DRIVES SIDE TO SIDE ROTATED STEERS AS NEEDED	TREADCARE PTY LTD		\$0.00
11/05/2023	470,000 kms	B S-7950	QLD WORKSHOP	2874360	\$169.05
20/04/2023	450,783 kms	WINDSCREEN R-3038 auto glass solutions came out and replaced drivers windscreen	AUTO GLASS SOLUTIONS PTY LTD	SI-00194136 PO7501	\$385.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
20/04/2023	450,783 kms	A S-7796	MELBOURNE VIC WORKSHOP		\$0.00
22/03/2023	439,193 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-1609 rotate and balanced steers rotate drives cross to cross	TREADCARE PTY LTD		\$0.00
22/03/2023	439,195 kms	A S-7560	MELBOURNE VIC WORKSHOP		\$0.00
22/03/2023	439,193 kms	DOOR LOCK R-2965 removed door skin and found central lock stripped the plastic gear inside replaced door popper and tested ok, refitted door skin	MELBOURNE VIC WORKSHOP	578975 PO-7466	\$127.96
22/03/2023	439,195 kms	C S-7638	MELBOURNE VIC WORKSHOP	578971	\$996.07
22/03/2023	432,738 kms	Heavy Vehicle Inspection Checklist - Truck I-237			\$0.00
08/03/2023	429,000 kms	A S-7399	MELBOURNE VIC WORKSHOP		\$0.00
07/02/2023	411,346 kms	B S-7180	QLD WORKSHOP	2760008 PO7027	\$169.05
01/02/2023	407,357 kms	ROTATE STEER T-1542 ROTATE STEERS SIDE TO SIDE	QLD WORKSHOP		\$0.00
01/02/2023	407,357 kms	CHECK ENGINE LIGHT R-2801 CHECK ENGINE LIGHT WAS WATER IN FLUE CLANED OUT WATER AND BOLW HORTON WAS PLUG WAS NO IN PROPERLY	QLD WORKSHOP		\$0.00
16/01/2023	396,354 kms	A S-6984 SERVICED ICE PACK AT 1397HRS	QLD WORKSHOP	2738099 PO6839	\$40.10
05/01/2023	388,755 kms	NEW DRIVE TYRES T-1520 ALL NEW BRIDGESTONE DRIVE TYRES FITTED UP ALL OK	DARREN BUDD'S TYRES PTY LTD	27946 PO6812	\$6,388.80
21/12/2022	380,955 kms	A S-6812	MELBOURNE VIC WORKSHOP		\$0.00
06/12/2022	371,256 kms	BATTERY S R-2636 Have removed the old batteries and fitted X4 brand new maintenance free batteries after fitment tested and works well	MELBOURNE VIC WORKSHOP	571535 PO6682	\$767.23
28/11/2022	367,480 kms	A S-6592	QLD WORKSHOP		\$0.00
11/11/2022	353,753 kms	FRIDGE R-2549 Have removed the old fridge and fitted a newly repaired working Engel fridge, have sent old fridge to get repaired, after fitment have tested and works well	MELBOURNE VIC WORKSHOP		\$0.00
07/11/2022	350,098 kms	B S-6461	QLD WORKSHOP	2678846 PO6333	\$159.66

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
27/10/2022	342,501 kms	DOSER PUMP R-2501 Have unplugged and removed doser off truck and fitted a brand new doser onto the doser frame then fitted the brand new doser pump to truck connected all lines and plugs then pulled out the doser injector from exhaust into a jar clear codes and connected to computed and started the doser pump over ride test, once the injector starts misting into a jar have fitted the injector back and and everything works well now	MELBOURNE VIC WORKSHOP	568352 PO6312	\$3,962.84
17/10/2022	334,814 kms	A S-6259	QLD WORKSHOP		\$0.00
17/10/2022	334,815 kms	NEW STEERS, R154 BRIDGESTONE, ROTATE DRIVES T-1267 2 X NEW BRIDGSTONE TYRES FITTED UP ALL OK ROTATED ALL DRIVES SIDE TO SIDE	DARREN BUDD'S TYRES PTY LTD	27338 PO6168	\$1,563.10
04/10/2022	328,960 kms	AFTER TREATMENT , AIR LEAK, WINDSCREEN R-2433 called auto glass solutions to come out and replaced drivers windscreen workshop removed stone guard and refitted once new screen was in Have removed the old leaking drain cock from the air tank and fitted a brand new drain cock tested and works well Have flushed the doser pump with hot water carried out with a click and override test and tested and work perfectly good cleared all inactive aftertreatment faults	AUTO GLASS SOLUTIONS PTY LTD, MELBOURNE VIC WORKSHOP	567217 PO6118	\$372.11
26/09/2022	320,920 kms	A S-6092	MELBOURNE VIC WORKSHOP		\$0.00
19/09/2022	317,248 kms	AFTER TREATMENT , AIR FITTINGS, tv antenna R-2384 Have flushed out whole ad blue system done the click test and primed the ad blue back cleared the air line tested and is ok now Have replaced the X1 damaged tv antenna also replaced X1 faulty female air fitting	MELBOURNE VIC WORKSHOP	565869 PO5989	\$103.95
09/09/2022	312,289 kms	AFTER TREATMENT , MUD GUARD R-2368 Have removed the rear r/H damaged drive guard and fitted a brand new black spraysafe guard flushed adblue system, unblocked tank breather, done a doser pump click test and doser pump over ride test all ok	MELBOURNE VIC WORKSHOP	564480 PO5985	\$65.99
01/09/2022	306,133 kms	A S-5933 Ice pack serviced @722hrs FITTED POWER SOCKET BEHIND DRIVERS SEAT FOR FRIDGE	MELBOURNE VIC WORKSHOP	565020 PO5970	\$73.06
04/08/2022	287,610 kms	B S-5761 ICE PACK DUE IN 50HRS	QLD WORKSHOP	2550108 PO5728	\$159.67
14/07/2022	273,683 kms	WEATHER SHIELD R-2211 REPLACE MISSING WEATHER SHIELD	QLD WORKSHOP	2527336 PO5569	\$155.29
27/06/2022	271,831 kms	A S-5477 REPLACED CAB FILTER	MELBOURNE VIC WORKSHOP	559770 PO5443	\$43.96
21/06/2022	268,213 kms	HUB CAP COVERS R-2104 Replaced with brand new centre hub cap	MELBOURNE VIC WORKSHOP	559755 PO5431	\$24.33
25/05/2022	254,945 kms	REVERSE LIGHT R-2011 Replaced fuzes	MELBOURNE VIC WORKSHOP		\$0.00
20/05/2022	254,940 kms	A S-5179	MELBOURNE VIC WORKSHOP		\$0.00
02/05/2022	242,123 kms	B S-5049 tyre rotation done	MELBOURNE VIC WORKSHOP	555736 PO4989	\$137.05

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
02/05/2022	242,123 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-1083 rotate drives cross to cross rotated and balanced steers	TREADCARE PTY LTD		\$0.00
29/04/2022	240,684 kms	POWER STEERING PUMP R-1920 gilbert and roach attended breakdown at rose hill and replaced pump and re-bleed system	GILBERT & ROACH		\$0.00
07/04/2022	228,121 kms	A S-4958	MELBOURNE VIC WORKSHOP		\$0.00
21/03/2022	216,949 kms	A S-4809	MELBOURNE VIC WORKSHOP		\$0.00
24/02/2022		Heavy Vehicle Inspection Checklist - Truck I-114			\$0.00
24/02/2022	199,564 kms	C S-4578	MELBOURNE VIC WORKSHOP	551165 PO4421	\$773.37
13/02/2022	190,644 kms	A S-4547 ICE PACK SERVICED AT 314hrs	MELBOURNE VIC WORKSHOP	550136 PO4309	\$33.78
13/02/2022	190,644 kms	NEW STEERS T-941 replaced steer tyres	TREADCARE PTY LTD	134666 PO4290	\$1,313.40
09/01/2022	174,485 kms	PASSENGER WINDOW R-1488 replaced windscreen	AUTO GLASS SOLUTIONS PTY LTD	SI-00189427 PO3988	\$324.50
09/01/2022	174,485 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-857 rotate and balance steers rotated drives front to back	TREADCARE PTY LTD		\$0.00
09/01/2022	174,485 kms	B S-4225	MELBOURNE VIC WORKSHOP	549053 PO4189	\$148.72
09/12/2021	157,618 kms	A S-4084	MELBOURNE VIC WORKSHOP		\$0.00
21/11/2021	143,580 kms	A S-3911	MELBOURNE VIC WORKSHOP		
04/11/2021	133,165 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-752 ROTATE AND BALANCED STEERS ROTATED DRIVES SIDE TO SIDE	TREADCARE PTY LTD		\$0.00
28/10/2021	129,642 kms	A S-3674	MELBOURNE VIC WORKSHOP		
07/10/2021	115,741 kms	B S-3557	MELBOURNE VIC WORKSHOP	541797 PO3438	\$133.75
20/09/2021	102,677 kms	A S-3421	MELBOURNE VIC WORKSHOP		
20/09/2021	102,677 kms	100,000KLM ENGINE TUNE] R-1111 carried out a 100,000km engine tune and cam inspection	MELBOURNE VIC WORKSHOP		
13/08/2021	85,699 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-591 rotated steers and balanced rotated drives front to back	TREADCARE PTY LTD	128552 PO2948	\$34.87
12/08/2021	85,699 kms	A S-3164	MELBOURNE VIC WORKSHOP		

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
02/07/2021	72,438 kms	A S-2784 have sent truck to kenworth laverton for warranty work - oil leaking from rear of fuel pump and air leaking from horton fan Assembly	MELBOURNE VIC WORKSHOP		
04/06/2021	55,665 kms	ESOC FITTINGS R-757 fitted esoc fittings to truck			
02/06/2021	55,665 kms	B S-2614 after treatment light on dash B&H have order the part to be fitted in Brisbane	MELBOURNE VIC WORKSHOP	533150 PO2397	\$133.75
27/05/2021	52,003 kms	AIR FITTINGS R-727 fitted 45 degree fittings to lines to give it a bit extra movement		532380 PO2199	\$6.23
13/05/2021	42,679 kms	A S-2326 INSTALLED GPS - RORY	MELBOURNE VIC WORKSHOP		
13/05/2021	48,419 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-404 rotated drives (cross to cross) Melbourne workshop completed DARREN BUDS ROTATED AND BALANCED ATEER TYRES	MELBOURNE VIC WORKSHOP	00023625 PO2232	\$44.00
19/04/2021	31,772 kms	COOLANT LEAK R-593 replace hose clamp on lower radiator hose due to not tightening up			
16/04/2021	29,941 kms	A S-2157	QLD WORKSHOP		
17/03/2021	9,950 kms	A S-1917 first service at brown and hurley		2142109 PO1544	\$22.03
17/03/2021	9,764 kms	DIFF OILS R-453 C/O diff oils on first service and filter			
165 Records				Total:	\$57,834.92