



# Vehicle History Summary



Fleet #	PM387
Registration	XQ83MI
Make	Kenworth
Model	K200
VIN / Chassis #	6F5000000LA467766
Build Date	2020

Date	Reading / Units	Type / Repairer Notes	Repairer
		A S-15914  CARRY OUT A SERVICE CHECK PASSENGERS SIDE WEATHER SHIELD	QLD WORKSHOP
		ROTATE DRIVES, ROTATE STEER T-3906  ROTATE STEERS AS REQUIRED ROTATE DRIVES -SIDE TO SIDE	QLD WORKSHOP
15/12/2025	967,526 kms	<b>RUNOUTS</b> T-3819  1 X RUNOUT.	DARREN BUDD'S TYRES PTY LTD
11/12/2025	967,526 kms	<b>A S-15735</b>  CARRY OUT A SERVICE DOWNLOAD COMPLETED	QLD WORKSHOP
11/12/2025	967,526 kms	<b>AIR LEAK, DRIVERS SEAT</b> R-6800  REPLACED SEAT CONTROL BUTTONS ON SIDE OF SEAT	QLD WORKSHOP
20/11/2025	951,507 kms 12,543 hrs	<b>B S-15511</b>  B SERVICE AND CUSTOM AIR UNIT SERVICED , NEXT DUE AT 4323 HRS	QLD WORKSHOP
10/11/2025	944,601 kms	<b>CHECKOVER, DRIVE BRAKES</b> R-6645	SRV ROAD FREIGHT
10/10/2025	941,066 kms	<b>MONKEY LIGHTS</b> R-6506	QLD WORKSHOP
02/10/2025	940,347 kms	<b>A S-15137</b>	QLD WORKSHOP
23/07/2025	928,519 kms	<b>ROTATE DRIVES, ROTATE STEER</b> T-3454  ROTATE DRIVES DIAGONAL STEERS AS REQ	DARREN BUDD'S TYRES PTY LTD
22/07/2025	928,519 kms	<b>C S-14562</b>  carried out c service as per checklist. carried out top tune on engine replaced all oil and filters required ICE PACK DUE 4000 DONE 3847 second axle brakes getting low	QLD WORKSHOP
22/07/2025	928,519 kms	<b>STEER BEARINGS, STUB AXLE</b> R-6126  removed front hubs to carry out repack, found LH outer wheel bearing worn out. removed hub seal and inspected inner bearing. Cleaned up stub axles and check condition, found LH stub axle had been worked on before and had dodgy repair. advised Corey. removed LH stub axle and cleaned up axle end. got new stub axle and assembled to axle using old kingpin new bushes. Removed old bearing cups and fitted new ones reassembled LH hub and repacked new wheel bearings. Fitted hub to stub axle and adjusted hub nut to spec. removed old bearing cups on RH side and fitted new ones. repacked new bearings and fitted hub to stub axle. tensioned to spec.	QLD WORKSHOP
22/07/2025	928,519 kms	<b>Heavy Vehicle Inspection Checklist - Truck</b> I-758	QLD WORKSHOP
03/06/2025	921,140 kms	<b>A S-14218</b>  A SERVICE	QLD WORKSHOP
11/03/2025	906,108 kms	<b>A S-13606</b>  LOWEST BRAKE 7MM CUSTOM AIR 3800HRS DUE 400HRS	QLD WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
17/02/2025	891,571 kms	<b>B</b> S-13450 B-SERVICE REPLACED FUEL PRO COLLAR NUT	QLD WORKSHOP
28/01/2025	880,490 kms	<b>ROTATE DRIVES, ROTATE STEER</b> T-3111 ROTATED DRIVES SIDE/SIDE STEERS SIDE/SIDE	DARREN BUDD'S TYRES PTY LTD
28/01/2025	880,490 kms	<b>A</b> S-13163 A SERVICE AND CUSTOM AIR SERVICE 3709 HOURS NEXT DUE AT 4009 HOURS	QLD WORKSHOP
17/01/2025		<b>adblue cap</b> R-5401	QLD WORKSHOP
20/12/2024	862,749 kms	<b>PITMAN ARM</b> R-5291 REMOVE AND REPLACED PITMAN ARM BOLT	QLD WORKSHOP
12/12/2024	858,572 kms	<b>A</b> S-12951	QLD WORKSHOP
08/11/2024	843,097 kms	<b>A</b> S-12653 CUSTOM AIR AT 3475 HOURS DUE AT 3700 HOURS FOUND 1ST DRIVE DIFF TEMP SENDER U/S CHECKED ALL WIRING AND CARRIED OUT CONTINUITY TEST ALL PASSED, REPLACED SENDER. LOWEST BRAKE 7MM	QLD WORKSHOP
22/10/2024	828,599 kms	<b>B</b> S-12426 B-SERVICE	QLD WORKSHOP
22/10/2024	828,599 kms	<b>NEW STEERS, ROTATE DRIVES</b> T-2895 2X NEW BRIDGESTONE R154 ROTATE CARRIED OUT BY QLD WORKSHOP	DARREN BUDD'S TYRES PTY LTD
04/10/2024	817,351 kms	<b>CALLOUT FEE, PUNCTURE REPAIR</b> T-2927 1 X PUNCTURE REPAIR AND STRIP/FIT	DARREN BUDD'S TYRES PTY LTD
20/09/2024	809,291 kms	<b>A</b> S-12249 ICE PACK 3408hrs Due @ 3700hrs 1st DRIVE AXLE BRAKES LOW ACCELERATOR FAULT FC1242 NEEDS HARNESS WHEN NEXT BACK AT WORKSHOP	QLD WORKSHOP
12/09/2024	803,773 kms	<b>DAMAGE REPAIR</b> R-4953 REPAIR ACCIDENT DAMAGE. REMOVING GRILL AND REPAIRING. FITTING NEW HUB CAP TO RH STEER REPAIR WIPER WASHERS REFITTING AIR HORN CORD REPAIRING TRAILER ELECTRICAL PLUG	QLD WORKSHOP
26/08/2024	794,112 kms	<b>A</b> S-12006 NEW UHF AERIAL AND BASE FITTED BY THE DON TIGHTENED BELLY BAR AS WAS LOOSE TIGHTENED PITMAN ARM PINCH BOLT AS WAS LOOSE MINOR LEAK FROM COOLANT EXCHANGE PIPE ON BLOCK.	QLD WORKSHOP
02/08/2024	779,512 kms	<b>NEW DRIVES</b> T-2726 8 X NEW M866 FITTED BY QLD WORKSHOP STEER AS REQUIRED	QLD WORKSHOP
02/08/2024	777,855 kms	<b>A</b> S-11757 Replacing dryve tyers	QLD WORKSHOP
10/07/2024	762,855 kms	<b>C</b> S-11572 REPLACED GEARBOX OIL ADJUSTED ALL DRIVE HUBS DONE BY MATT.C STEERS CHECKED BY MAT.A TOP TUNE TO BE COMPLATED AFTER 100,000KLM AFTER RE-BUILD	QLD WORKSHOP
09/07/2024	762,855 kms	<b>Heavy Vehicle Inspection Checklist - Truck</b> I-524	QLD WORKSHOP
09/07/2024	762,855 kms	<b>B</b> S-11441 ADDED 12L OF COOLANT ON 26.06.24	QLD WORKSHOP
08/07/2024	658,742 kms	<b>ENGINE REBUILD</b> R-4892 GOT TRUCK TO BRISBANE AND RUN TEST, FOUND TO BE PRESSURIZING COOLING SYSTEM SENT TRUCK TO CUMMINS. FOUND CYLINDER 5 TO BE BYPASSING. ENGINE REBUILT ALL OK. REPLACED ALL PISTON RINGS, GASKETS, SEALS AND PARTS NEEDED. RUN UP ON DYNOMETER ALL OK SENT BACK INTO SERVICE	CUMMINS SOUTH PACIFIC PTY LTD

Date	Reading / Units	Type / Repairer Notes	Repairer
05/07/2024	756,274 kms	<b>BREAK DOWN</b> R-4703  RV MECHANICAL SENT TO FREE UP ENGINE TOP UP COOLANT	RV MOBILE TRUCK & TRAILER REPAIRS PTY LTD
19/06/2024	751,618 kms	<b>BATTERYS</b> R-4636  LOAD TEST ALL BATTERIES X3 FAILED. REMOVE AND REPLACED ALL BATTERIES, TRUCK CHARGING AT 14.V, AT BATTERIES 13.8V TIGHTEN CUSTOM AIR BELTS, ALTERNATOR CHARING AT 13.8V SENT BACK INTO SERVICE	QLD WORKSHOP
28/05/2024	744,056 kms	<b>ALTERNATOR ON KLMS, Driveline, ICE PACK SERVICE, STARTER MOTOR</b> R-4532  REMOVED AND REPLACED ALTERNATOR AS REQUIRED ON KILOMETERS, SECURED INTO PLACE WITH ALL WIRING, STARTED UNIT AND CHECKED CHARGE RATE ALL OKAY. REMOVED AND REPLACED STARTER MOTOR AS REQUIRED ON KILOMETERS, SECURED INTO PLACE WITH ALL REQUIRED WIRING ALL OKAY SERVICE ICE PACK AS REQUIRED	QLD WORKSHOP
28/05/2024	742,257 kms	<b>A S-11156</b>  ICE PACK AT 3400, SERVICED NEXT DUE 3700	QLD WORKSHOP
20/05/2024	738,541 kms	<b>STEER WHEEL BEARINGS, TOWING</b> R-4515  TRUCK FAILED PASSENGER SIDE WHEEL BEARING AT WALLEN OUT SIDE OF MELBOURNE, GOT TRUCK AND TRAILERS TOWED BACK TO YARD TO BE REPAIRED. PULLED WHEEL OF FOUND WHEEL BEARING FAILED, USING OXY REMOVED HUB AND FAILED BEARING. CLEANED STUB AXLE AND HUB AND INSPECT ALL OK. REPLACED BEARINGS, GREASED UP AND REFITTED ALL PARTS. TORQUED TO SPEC AND DOUBLE CHECK ALL OK. REPLACED BEARING ON DRIVER SIDE AS PRECAUTION. ALL OK SENT TRUCK BACK INTO SERVICE	HEAVY HAULAGE TOWING , MELBOURNE VIC WORKSHOP
07/05/2024	733,511 kms	<b>BREAK DOWN, TOWING</b> R-4441  TRUCK PRESENTED WITH TRANSMISSION CODES AND BRAKES NOT RELEASEING. \$165.00 PLUGGED IN COMPUTER, CHECK CODES. FOUND BRAKE PRESSURE CODES. CHECK BRAKES FOUND PEDAL STIFF AND STICKING DOWN. LUBE PEDAL PIVOT POINTS AND FREE UP. WORKING , ALL GOOD	CANBERRA TRUCK REPAIRS PTY LIMITED
01/05/2024	729,053 kms	<b>ROTATE DRIVES, ROTATE STEER</b> T-2537  ROTATE DRIVES DIAGONAL STEERS T.O.R	QLD WORKSHOP
30/04/2024	729,053 kms	<b>FRIDGE</b> R-4396  FITTED BRAND NEW FRIDGE USING CRIMP AND HEAT SHRINK TERMINALS TESTED TURNS ON SENT TO SERVICE.	QLD WORKSHOP
30/04/2024	729,053 kms	<b>A S-10927</b>  A-SERVICE ICE PACK SERVICED AT 3359HRS FITTED DRAW FRIDGE NEW WIPER BLADES NEW LIGHT PLUG BETWEEN A AND B TRAILERS	QLD WORKSHOP
04/04/2024	714,037 kms	<b>A S-10732</b>  CUSTOM AIR HRS CURRENTLY 3334HRS DUE 3400HRS	QLD WORKSHOP
26/03/2024	710,037 kms	<b>AIR CONDITIONER</b> R-4258  FOUND AC LINE HAD BLOWN OFF CRIMP SECTION FOR HIGH PRESSURE SIDE AT PUMP. REMOVED A/C COMPRESSOR, RECIVER DRYER AND HIGH PRESSURE SIDE HOSE, REPLACED ALL WITH NEW, INSTALLED NEW A/C O-RINGS VAC DOWN SYSTEM AND MADE SURE HOLDING PRESSURE, GASSED UP SYSTEM, A/C IS COLD	QLD WORKSHOP
01/03/2024	699,066 kms	<b>TORQUE ROD BUSHES</b> R-4165  FOUND WORN TORQUE ROD BUSH REMOVED 1ST DRIVE AXLE D/S TORQUE ROD ARM, REMOVED AND REPLACED BOTH TORQUE ROD BUSHES RE-INSTALLED ARM AND TIGHTNED ALL BOLTS SEND BACK INTO SERVICE	QLD WORKSHOP
01/03/2024	699,066 kms	<b>B S-10424</b>  ICE-PACK HRS CURRENTLY 3233HRS DUE 3400HRS REPLACED 1ST DRIVE AXLE D/S TORQUE ROD BUSHES REPLACED AD-BLUE CAP RUBBER CLEANED OUT BRAKE PEDAL ROLLER PIN LOAD TEST ALL BATTERIES, ALL PASSED	QLD WORKSHOP
25/01/2024	685,185 kms	<b>A S-10117</b>  ADDED 3LTRS OF OIL TO THE ENGINE ICEPAK SERVICED NEXT DUE AT 3400HRS	QLD WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
25/01/2024	685,185 kms	<b>ROTATE DRIVES, ROTATE STEER T-2189</b> ROTATE DRIVES SIDE / SIDE ROTATE STEERS AS REQUIRED	DARREN BUDD'S TYRES PTY LTD
15/12/2023	667,162 kms	<b>A S-9797</b> 2968 HOURS DUE AT 3097 HOURS	QLD WORKSHOP
24/11/2023	655,380 kms	<b>clamp R-3763</b> REPLACED THE 4" INTAKE CLAMP FOR NEW TRUCK BACK IN SERVICE	QLD WORKSHOP
23/11/2023	654,759 kms	<b>A S-9541</b> REPLACED THE 4" INTAKE CLAMP	QLD WORKSHOP
20/10/2023	639,505 kms	<b>B S-9320</b> CARRIED OUT B-SERVICE CARRIED OUT ICE-PAK SERVICE AT 2797 HRS REPLACED 2ND FROM REAR D/S STEP MARKER LIGHT	QLD WORKSHOP
22/09/2023	626,125 kms	<b>A S-8986</b> 1ST DRIVE INPUT UNI U/S	QLD WORKSHOP
22/09/2023	626,125 kms	<b>UNI JOINT R-3527</b> REMOVED TAILSHAFT AND UNI JOINT AS REQUIRED, CLEANED DOWN ALL SURFACES, NEW UNI JOINT FITTED INTO PLACE AND SECURED AS REQUIRED, REFITTED TAILSHAFT TO 1ST DRIVE YOKE WITH NEW BOLTS, TORQUED ALL BOLTS TO SPEC OF 125 FTLB, ALL OKAY.	QLD WORKSHOP
22/09/2023	626,125 kms	<b>ROTATE DRIVES, ROTATE STEER T-1991</b> 8X ROTATE DIAGONALLY 2 STEER SIDE TO SIDE	DARREN BUDD'S TYRES PTY LTD
12/09/2023	610,639 kms	<b>HORN, REVERSE BUZZER, SUN VISER CLIP R-3471</b>	QLD WORKSHOP
25/08/2023	610,649 kms	<b>A S-8744</b> CARRIED OUT A-SERVICE AS PER CHECK LIST	QLD WORKSHOP
24/08/2023	610,649 kms	<b>EBS PLUG AND LEAD R-3400</b>	QLD WORKSHOP
21/07/2023	593,458 kms	<b>A S-8547</b>	QLD WORKSHOP
21/07/2023	593,458 kms	<b>REKIT HORTON FAN HUB, REPLACE COMP ON KLMS R-3293</b> REMOVED AND REKITTED HORTON HUB FAN, ALL SECURED INTO PLACED WITH ALL MOUNTING BOLTS AIR LINE REFITTED WITH FAN,STUDS AND MOUNTING HARDWARE. TESTED ALL OKAY. REMOVED CHARGE LINE, VACCUM HOSE AND COOLANT HOSES FROM COMPRESSOR, SPLIT POWER STEER PUMP OFF BACK OF COMPRESSOR AND MOVED OUT OF WAY TO GAIN FURTHER ACCESS, REMOVED REAR COMPRESSOR MOUNTING PLATE AS WELL AS FRONT MOUNTING BOLTS,REMOVED COMPRESSOR AND CHANGED OVER ALL NECESSARY FITTING WITH NEW O RINGS. CLEANED UP MOUNTING SURFACE AT REAR OF TIMING COVER AND CLEANED POWER STEER PUMP ON GASKET,NEW COMPRESSOR FITTED WITH NEW GASKET AND SECURED INTO PLACE, POWER STEER PUMP REFITTED WITH NEW GASKET AND SECURED, ALL COOLANT,VACCUM AND CHARGE LINES FITTED BACK INTO PLACE, NEW GOVENER FITTED TO COMPRESSOR ALL LINES SECURED,FILLED TRUCK BACK UP WITH COOLANT AND RAN COOLANT LEVEL GOOD.	QLD WORKSHOP
10/07/2023	587,812 kms	<b>DIFF RESEAL R-3264</b> DE-GREASED AND GURNIED DOWN DIFFS, REMOVED 1ST DIFF DRIVE AXLES. REMOVED FRONT SECTION OF DIFF. SCRAPED OFF OLD DIFF HOUSING GASKETS AND FINAL CLEAN WITH WIZZER WHEEL TO MAKE SURE ALL EXISTING GASKET WAS REMOVED. FIT NEW DIFF HOUSING GASKET AND INSTALL FRONT SETION OF DIFF MAKING SURE THE GASKET WASN'T TORN WHILE INSTALLING. CLEAN UP OLD DRIVE AXLE GASKETS AND REPLACED WITH NEW.	QLD WORKSHOP
07/07/2023	587,812 kms	<b>Heavy Vehicle Inspection Checklist - Truck I-300</b>	
07/07/2023	587,812 kms	<b>ROTATE DRIVES T-1817</b> ROTATED ALL DRIVES SIDE TO SIDE FLIPPED ALL OUTSIDE TYRES ON RIMS	DARREN BUDD'S TYRES PTY LTD
07/07/2023	587,812 kms	<b>C S-8331</b>	QLD WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
03/07/2023	584,098 kms	<b>FUEL PRO COLLAR</b> R-3242  FUEL PRO NUT REPLACED AND FITTED INTO PLACE, REPLUMBED FUEL LINE BACK INTO FUEL PRO HOUSING AND ALL FITTING SECURED, FILLED FUEL PRO HOUSING WITH FUEL AND LET TRUCK PRIME SYSTEM, STARTED AND TESTED NO LEAKS PRESENT, ROAD TEST CARRIED OUT AND CHECKED OVER AFTER ROAD TEST, NO LEAKS FOUND ALL OKAY.	QLD WORKSHOP
26/06/2023	581,144 kms	<b>BREAK DOWN</b> R-3885	EXPRESS TRUCK MAINTENANCE
23/06/2023	580,337 kms	<b>B</b> S-8296  ICE PACK SERVICED AT 2491hrs	QLD WORKSHOP
19/06/2023	575,625 kms	<b>WINDSCREEN</b> R-3207  CALLED IN THE FIXER GROUP TO REPLACE DRIVERS WINDSCREEN ALL OK	THE FIXER CORPORATION PTY LTD
26/05/2023	565,304 kms	<b>A</b> S-8024  MOVEMENT IN 1ST UNI 1ST DIFF LEAKING RESET DOG BOX DOOR BUTTON	QLD WORKSHOP
17/04/2023	549,147 kms	<b>BALANCE RINGS</b> R-3035  BALANCE RINGS FITTED UP ALL OK	QLD WORKSHOP
17/04/2023	549,147 kms	<b>DRIVE BRAKES</b> R-3036  REMOVED REAR DRIVE BREAKS AND DRUMS, KNOCK OUT ANCHOR PIN BUSHES AND INSTALLED NEW BUSHES, FIT UP NEW BREAKS AND DRUMS, RE-ADJUST BREAKS	QLD WORKSHOP
14/04/2023	549,148 kms	<b>NEW STEERS, ROTATE DRIVES</b> T-1532  ROTATED DRIVES SIDE TO SIDE 2 X NEW BRIDGESTONE R154 STEER TYRES FITTED UP	DARREN BUDD'S TYRES PTY LTD
06/04/2023	549,147 kms	<b>A</b> S-7736	QLD WORKSHOP
16/03/2023	533,944 kms	<b>A</b> S-7451  NEED TO REPLACE DOOR CLOSED SENDER AND DRIVERS SIDE SUNVISOR CLIP FRIDGE NEEDS TO BE REINSTALLED FIRST DRIVE CENTER LEAKING 3RD AXLE BRAKES AT 8MM	QLD WORKSHOP
17/02/2023	518,536 kms	<b>B</b> S-7226  DRIVERS SIDE SPOTTER MIRROR REPLACED EXHAUST ON AIR DRYER SILNCER REPLACED TRAILER BRAKE PENUT VALVE NEEDS REPLACEMENT	QLD WORKSHOP
20/01/2023	503,445 kms	<b>A</b> S-7019  ICE PACK SERVICED AT 2000HRS 1ST DIFF LEAKING	QLD WORKSHOP
12/01/2023	500,292 kms	<b>TURBO ON KLMS</b> R-2749  REMOVE TURBO AND EXHAUST MANIFOLD CLEAN ALL AREAS FOR NEW GASKETS, SPLIT TURBO FROM MANIFOLD AND CLEAN AREA INBETWEEN, REMOVE AND REPLACE ALL TURBO STUDS. MOUNT NEW TURBO TO MANIFOLD, REPALCED OLD NUTS WITH NEW AND TORQUE TO 60FT lbs, REPLACED ALL O-RINGS FOR OIL FEED LINES. REPALCED ALL MANIFOLD GASKETS, MOUNT TURBO AND MANIFOLD TO ENGINE TORQUE MANIFOLD BOLTS TO 44FT lbs. FINISHED INSTALLING ALL OTHER PIPEING FOR TUBRO, TEST RUN ALL WORKING CORRECTLY.	QLD WORKSHOP
16/12/2022	488,936 kms	<b>A</b> S-6756  1ST DIFF LEAKING 1ST UNI HAVES PLAY	QLD WORKSHOP
18/11/2022	473,572 kms	<b>NOx SENSOR</b> R-2578  PLUG COMPUTER IN AND SCAN FOR FAULTS FIND FAULT CODE FOR NOX SENDER TEST ALL WIRING AND FIND ALL AMPS AND VOLTS ARE CORRECT REPALCE NOX SENDER AND PROGRAM AND CLEAR FAULT CODES RECHECK AND CLEAR TO RETURN BACK TO FLEET	QLD WORKSHOP
18/11/2022	473,572 kms	<b>A</b> S-6521  FIRST DIFF STARTING TO WEEP	QLD WORKSHOP
21/10/2022	458,562 kms	<b>ROTATE/BALANCE STEER, ROTATE DRIVES</b> T-1358  ROTATED ALL DRIVES DIAGONAL ROTATED STEERS SIDE TO SIDE	DARREN BUDD'S TYRES PTY LTD
21/10/2022	458,562 kms	<b>B</b> S-6197	QLD WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
19/08/2022	424,882 kms	<b>BATTERYS</b> R-2313 LOAD TEST ALL BATTERIES ALL FAILED REPLACED ALL BATTERYS	QLD WORKSHOP
19/08/2022	424,882 kms	<b>A</b> S-5869 BATTERIES REPLACED	QLD WORKSHOP
22/07/2022	409,903 kms	<b>A</b> S-5664	QLD WORKSHOP
08/07/2022	402,401 kms	<b>C</b> S-5545	QLD WORKSHOP
08/07/2022		<b>Heavy Vehicle Inspection Checklist - Truck</b> I-122	
28/06/2022	396,893 kms	<b>BRAKE HOSE</b> R-2146 REPLACE REAR BREAK HOSE THAT WAS RUBBED THROUGH	QLD WORKSHOP
24/06/2022	395,041 kms	<b>B</b> S-5431	QLD WORKSHOP
24/06/2022	395,041 kms	<b>ROTATE/BALANCE STEER, ROTATE DRIVES</b> T-1202 QLD WORKSHOP ROTATED ALL DRIVES CROSS TO CROSS ROTATED AND BALANCED STEER TYRES AS NEED	DARREN BUDD'S TYRES PTY LTD, QLD WORKSHOP
27/05/2022	380,120 kms	<b>A</b> S-5241 ICE PACK SERVICED 1401HRS DASH LIGHTS FIXED CHANGED 10 GLOBES TRAILER LIGHT PIN RESET	QLD WORKSHOP
21/05/2022	376,488 kms	<b>cummins campaign</b> R-2000 re-torque backwound ide plant	CUMMINS SOUTH PACIFIC PTY LTD
06/04/2022	352,472 kms	<b>A</b> S-4950	QLD WORKSHOP
22/03/2022	344,093 kms	<b>NEW DRIVE TYRES</b> T-1042 ALL NEW TOYO DRIVE TYRES FITTED UP ALL OK	DARREN BUDD'S TYRES PTY LTD
01/03/2022	336,624 kms	<b>EXHAUST LEAK</b> R-1686 REMOVE TURBO AND MANIFOLD CLEAN ALL SURFACES REMOVE AND REPALCE ALL EXHAUST MANIFOLD GASKET MOUNT TURBO, RUN ENGINE AND CHECK FOR LEAKS NO LEAKS	QLD WORKSHOP
01/03/2022	336,624 kms	<b>B</b> S-4664	QLD WORKSHOP
16/02/2022	330,938 kms	<b>EXHAUST LEAK</b> R-1635 REPLACE MISSING AFM GASKET REPLACE 5INCH EXHAUST V-CLAMP	QLD WORKSHOP
08/02/2022	325,233 kms	<b>A</b> S-4506	QLD WORKSHOP
14/01/2022	310,147 kms	<b>A</b> S-4324	QLD WORKSHOP
22/12/2021	296,947 kms	<b>ROTATE DRIVES</b> T-730 ROTATED ALL DRIVES DIAGONAL 2 X NEW STEER TYRES BALANCED AND FITTED UP ALL OK	QLD WORKSHOP
22/12/2021	296,947 kms	<b>B</b> S-4168 1ST UNI JOINT OUT OF GEAR BOX HAS MOVEMENT	QLD WORKSHOP
02/12/2021	283,410 kms	<b>A</b> S-4032	QLD WORKSHOP
28/10/2021	268,223 kms	<b>A</b> S-3726	QLD WORKSHOP
10/09/2021	252,981 kms	<b>A</b> S-3374 Rory gilmore	QLD WORKSHOP
18/08/2021	238,072 kms	<b>B</b> S-3210	QLD WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
18/08/2021	238,072 kms	<b>ROTATE/BALANCE STEER</b> T-650 ROTATED FLIPPED AND BALANCED BOTH STEER TYRES	DARREN BUDD'S TYRES PTY LTD
27/07/2021	223,243 kms	<b>C</b> S-3012	QLD WORKSHOP
06/07/2021	208,355 kms	<b>ENGINE OIL LEAK</b> R-866 BROWN AND HURLEY REPAIRED ALL OIL LEAKS AROUND FUEL PUMP UNDER WARRENTY	BROWN & HURLEY GROUP
06/07/2021	208,305 kms	<b>A</b> S-2845	QLD WORKSHOP
05/07/2021	208,308 kms	<b>ROTATE/BALANCE STEER, ROTATE DRIVES</b> T-506 ROTATED ALL DRIVE TYRES SIDE TO SIDE ROTATED AND BALANCED STEER TYRES	DARREN BUDD'S TYRES PTY LTD
24/06/2021	208,826 kms	<b>HUB CAP COVERS</b> R-822 REPLACE MISSING HUBCAP COVERS STEERS	QLD WORKSHOP
07/06/2021	193,278 kms	<b>A</b> S-2644	QLD WORKSHOP
21/05/2021	178,575 kms	<b>B</b> S-2512 SLIGHT MOVEMENT IN D/S KING PIN	QLD WORKSHOP
28/04/2021	163,462 kms	<b>A</b> S-2184	QLD WORKSHOP
27/04/2021	163,463 kms	<b>ROTATE DRIVES</b> T-353 ROTATED DRIVES ONLY FRONT TO REAR	DARREN BUDD'S TYRES PTY LTD
07/04/2021		<b>GEAR BOX RECALIBRATION</b> R-540	BROWN & HURLEY GROUP
01/04/2021	148,511 kms	<b>A</b> S-2041	
01/04/2021	148,511 kms	<b>BALANCE STEERS, NEW STEERS</b> T-314 2 X NEW STEERS BALANCED AND FITTED UP ALL OK	DARREN BUDD'S TYRES PTY LTD
15/03/2021		<b>HUB CAP COVERS</b> R-449 REPLACE MISSING HUB CAP COVER	
15/03/2021	137,140 kms	<b>A</b> S-1819	QLD WORKSHOP
20/02/2021	118,986 kms	<b>B</b> S-1625	QLD WORKSHOP
10/02/2021	110,163 kms	<b>HUB LEAK</b> R-329 Removed and replaced front hub gasket on right steer side	QLD WORKSHOP
02/02/2021	104,679 kms	<b>A</b> S-1385	QLD WORKSHOP
02/02/2021	104,679 kms	<b>100,000KLM ENGINE TUNE]</b> R-280 CARRY OUT TOP TUNE UP ALL OK, NO FAULT FOUND	QLD WORKSHOP
11/01/2021	89,723 kms	<b>ROTATE/BALANCE STEER, ROTATE DRIVES</b> T-139 ROTATED ALL DRIVE TYRES ROTATED AND BALANCED STEER TYRES	DARREN BUDD'S TYRES PTY LTD
08/01/2021	89,723 kms	<b>A</b> S-1164	QLD WORKSHOP
15/12/2020	73,840 kms	<b>A</b> S-1000	
23/11/2020	58,962 kms	<b>ESOC FITTINGS</b> R-107 FIT UP ESOC FITTINGS TO TRUCK	
23/11/2020	58,962 kms	<b>B</b> S-738	

Date	Reading / Units	Type / Repairer Notes	Repairer
04/11/2020	45,955 kms	<b>ROTATE/BALANCE STEER, ROTATE DRIVES T-63</b> ROTATED ALL DRIVE TRYES REMOVED AND BALANCED STEER TYRES AND RITATED AS REQUIRED	DARREN BUDD'S TYRES PTY LTD
04/11/2020	45,955 kms	<b>A S-573</b>	
13/10/2020	29,565 kms	<b>A S-432</b>	
01/08/2020		<b>C S-1704</b>	

Signed: \_\_\_\_\_

Name: \_\_\_\_\_

Date: \_\_\_\_\_