



Vehicle History Summary



Fleet #	PM288
Registration	XQ18JT
Make	Kenworth
Model	K200
VIN / Chassis #	6F5000000LA466962
Build Date	2020

Date	Reading / Units	Type / Repairer Notes	Repairer
16/12/2025	1,159,496 kms	A S-15760 CARRY OUT A SERVICE DRIVE BRAKES NEXT SERVICE OUTPUT SHAFT SEAL NEEDS REPLACING NEXT SERVICE REPAIR DRIVERS DOOR CARD CHECK AND CLEAR ADBLUE FAULT WASH AND CLEAN INSIDE OF VEHICLE	QLD WORKSHOP
28/11/2025	1,140,855 kms	A S-15571 CARRY OUT A SERVICE CUSTOM AIR SERVICE KIT	QLD WORKSHOP
22/10/2025	1,125,292 kms	A S-15291 CARRIED OUT A SERVICE COMPLETED DOWNLOAD	QLD WORKSHOP
10/10/2025		SPOTTER MIRROR R-6510	QLD WORKSHOP
24/09/2025	1,109,959 kms	100,000KLM ENGINE TUNE], ENGINE BRAKE N/W, HOSE CLAMP, THROTTLE POSITION SENSOR R-6433	QLD WORKSHOP
23/09/2025	1,109,959 kms	B S-15065 carry out b service	QLD WORKSHOP
23/09/2025	1,109,959 kms	DIFF OIL LEAK R-6423	QLD WORKSHOP
17/09/2025	1,108,108 kms	ABS PLUG R-6386 REPLACED ABS PLUG	QLD WORKSHOP
12/09/2025	1,108,106 kms	295/80R BRIDGESTONE T-3599	DARREN BUDD'S TYRES PTY LTD
09/09/2025		BREAKDOWN R-6355	
11/07/2025	1,101,707 kms	A S-14599	SRV ROAD FREIGHT
07/07/2025	1,092,496 kms	SPOTTER MIRROR R-6050 REPLACED DRIVER SIDE SPOTTER MIRROR	QLD WORKSHOP
04/06/2025	1,074,697 kms	UNLOADER VALVE R-5921 MOVED TRUCK AROUND THE YARD AND NOTICED A SUFFICIENT AIR LEAK FROM THE AIR DRYER REKIT THE AIR DRYER WITH A NEW UNLOADER VALVE TESTED AND ALL GOOD	QLD WORKSHOP
22/05/2025	1,069,075 kms	ROTATE DRIVES, ROTATE STEER T-3145 ROTATED DRIVES DIAGONAL STEERS SIDE/SIDE	DARREN BUDD'S TYRES PTY LTD
22/05/2025	1,074,230 kms	C S-14091 C SERVICE	QLD WORKSHOP
22/05/2025	1,069,075 kms	Heavy Vehicle Inspection Checklist - Truck I-755	QLD WORKSHOP
22/05/2025	74,230 kms	A S-14123	QLD WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
A SERVICE			
21/05/2025		DASH GLOBES, DRIVERS DOOR, SPLITTER VALVE R-5836 LUBRICATE SPLITTER VALVE CHANGE DASH BULBS AND REP DOOR	QLD WORKSHOP
09/04/2025	1,111,205 kms	A S-13807 CHECKED BY COREY	QLD WORKSHOP
18/03/2025	1,042,021 kms	B S-13663 B SERVICE ,REPLACED CHROME GRILLE SURROUND 2ND HAND PART USED ,REPAIR R/H DOG BOX DOOR LOCK .	QLD WORKSHOP
11/02/2025	1,021,454 kms	A S-13379	QLD WORKSHOP
11/02/2025	1,021,454 kms	ABS PLUG, NOx SENSOR R-5494 FOUND FAULTY NOX SENSOR CAUSING CODE 1887, REPLACED NOX SENSOR AND TOOK TRUCK FOR HIGH NOX RESET, CLEARED ALL ACTIVE ECM CODES, ALL OKAY. WIRED UP NEW ABS PLUG AS REQUIRED, ALL OKAY.	QLD WORKSHOP
16/12/2024	1,010,335 kms	LIGHTS R-5272 MELBOURNE DIESEL MECHANICS MELBOURNE DIESEL MECHANICS SENT TO ASSES TRUCK INDICATORS NOT WORKING FOUND FAULTY RESETABLE FUSE REPLACED FOR NORMAL FUSE ALL OK REPLACED ABS PLUG AND REPLACED BLOWN FUSE FOR ABS REPLACED BROKEN LIGHT PLUG	MELBOURNE DIESEL MECHANICS
21/11/2024	1,003,300 kms	NEW STEERS T-2991 FIT 2 X NEW KUMHO STEERS OFF XB54EF BREAKDOWN	QLD WORKSHOP
21/11/2024	1,007,562 kms	A/C REPAIRS, KING PINS, TRUCK PROTECTION VALVE R-5179 -JACKED UP THE FROUNT AXEL, RIPPED WHEELS AND DRUMS OFF , PULLED HUBS OFF THE SPINDLE STRIPPED DOWN BREAK ASSEMBLY. - PULLED KING PIN CAPS OFF, PULLED WEDGES OUT AND DROPPED THE KINGPINS OUT, DEGREASED SPINDLE, BREAK ASSEMBLY AND HUB. - TOOK THE SPINDLE TO BROWN AND HURLEY TO PUT THE KINGPIN BUSHES AND SEAL IN THEY REAMED THE BUSH, CHECKED TO SEE HOW TIGHT THE KINGPIN WAS IN THE BUSHES ALL WAS GOOD. - PLACED THE SPINDLE ON PLACED THE CORRECT AMOUNT OF SHIMS BETWEEN FOR MINIMAL PLAY. - KINGPIN, CAPS, WEDGES, GREASE NIPPLES ALL ON - BREAK ASEMBLY RE ATACHED, TORQED TO SPEC, ADDED GREASE TO WHEEL BEARINGS AND HUBS, PLACED HUB AND WHEEL BEARINGS ON, TORQUED TO SPEC -WHEELS, DRUMS, BALANCE RINGS ATACHED TORQUED TO SPEC - CHECKED KINGPIN AND WHEEL BEARINGS NO PLAY -REPAIRED SUZIE COIL AIR LEAK -PULL DOWN P/S FRONT SECTION OF CAB TO ACCES A/C COMPONENTS REMOVED AND REPLACED TX-VALVE, PUT ALL COMPONENTS BACK TOGETHER, REMOVED AND REPLACED AIR COMPRESSOR AND REVICER DRYER, VACCUM DOWN SYSTEM HOLDS NEGATIVE PRESSURE. GAS UP SYSTEM TO 1.3L OF GAS, TESTED ALL WORKING CORRECTLY TRUCK ALL GOOD SENT BACK INTO SERVICE	QLD WORKSHOP
20/11/2024	1,007,562 kms	A S-12627 A-SERVICE REPLACED PRESSURE PROTECTION VALVE KING PINS OVERHAUL DUE TO EXCESSIVE MOVEMENT REPLACED A/C AND AIR DRIER, REGASSED TORQUED U-BOLTS P/S STEER TOP SHOCK BOLT LOOSE	QLD WORKSHOP
30/10/2024	990,504 kms	WIPER BLADE R-5104 REMOVED AND REPLACED WIPER BLADES	QLD WORKSHOP
02/10/2024	981,004 kms	SHOCK BUSHES, TORQUE ROD BUSHES R-5021 REMOVE AND REPLACED WORN TORQUE ROD BUSHES D/S 1ST AXLE REMOVE AND REPLACED ALL DRIVE LOWER SHOCK BUSHES REPLACED BOTH DOWETY WASHER ON FUEL RAIL CHECK VALVE	QLD WORKSHOP
01/10/2024	981,004 kms	B S-12345	QLD WORKSHOP
13/09/2024	967,572 kms	ICE PACK R-4956 FOUND CUSTOM AIR SHUT OFF SOLENOID HAD FAILED, REMOVED AND REPLACED SOLENOID AS REQUIRED AND ADJUSTED TO CORRECT STROKE, TESTED ALL OPERATIONS, ALL OKAY.	QLD WORKSHOP
13/09/2024	967,572 kms	NEW DRIVE TYRES T-2835 8XM866 DRIVES TYRES FITTED BY QLD WORKSHOP	QLD WORKSHOP
09/09/2024	963,714 kms	A S-12025	QLD WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
		A-SERVICE	
12/08/2024	949,663 kms	A S-11735 LHS DISC SPLIT ADDED 4 LITRES COOLANT RHS CAB TILT RAM WET TIGHTENED BELLY BAR AS WAS LOOSE REPLACED WIPER BLADES CUSTOM AIR UNIT SERVICED AT 5046 HOURS NOW DUE AT 5346 HOURS	QLD WORKSHOP
16/07/2024	934,273 kms	A/C REPAIRS R-4737 FOUND A/C BLOWER FAN U/S INTERNALLY FAILED, REMOVED DASH PANELS AND FUSE BLOCK TO GAIN ACCESS TO BLOWER FAN, REMOVED AND REPLACED BLOWER FAN TESTED FUNCTIONS, ONLY WORKING ON FAN SPEED 4, CHANGED FAN SPEED RESISTOR AND TESTED ALL OPERATIONS AGAIN, ALL WORKING AS REQUIRED, ALL OKAY.	QLD WORKSHOP
16/07/2024	934,273 kms	NEW STEERS T-2700 STRIPPED AND FITTED NEW STEER TYRES AS REQUIRED, INFLATED TO CORRECT PRESSURE, ALL OKAY, REFITTED TO TRUCK AND TORQUED WHEEL NUTS TO SPEC.	QLD WORKSHOP
15/07/2024	934,273 kms	A S-11583 RHS CAB RAM LEAKING/ WET LHS ENGINE MOUNT DISC SPLIT STEER TYRES LOW 2ND LAYER	QLD WORKSHOP
09/07/2024	930,509 kms	DRIVERS WINDOW R-4713 REMOVE AND REPLACED DRIVERS MODULE, ALL WORKING CORRECTLY SENT BACK INTO SERVICE	QLD WORKSHOP
24/06/2024	922,251 kms	ICE PACK BELTS R-4673 REMOVED BOTH ALTERNATOR AND PUMP BELTS OFF ICEPACK AND REPLACED AS REQUIRED, TENSIONED BOTH BELTS AS NEEDED, CHECKED ALL OPERATIONS AND CHECKED CHARGE RATE 13.6 VOLTS AT ALTERNATOR ALL OKAY.	QLD WORKSHOP
14/06/2024	918,406 kms	B S-11320 CUSTOM AIR HRS CURRENTLY 4871HRS DUE 5015 D/S 1ST TORQUE ROD BUSH SHOWING WEAR	QLD WORKSHOP
30/05/2024	908,969 kms	HOBBS SWITCH R-4571 REMOVED DASH FASCIA APPLIED BRAKES FOUND LEAKING HOBBS SWITCH REMOVED AND REPLACED TEXTED FOR LEAKS NONE PRESENT SENT BACK TO SERVICE.	QLD WORKSHOP
20/05/2024	903,201 kms	BRAKE RELINE R-4514 TOOK OFF OLD BRAKES AND PUSHED OUT OLD BUSHES AND PUSHED NEW ONES BACK IN AND PUT NEW BRAKE SHOES AND BRAKE DRUM ON LAST AXLE	QLD WORKSHOP
20/05/2024	903,201 kms	A S-11072 RELINE LAST AXLE AS DUE TO BRAKES BEING LOW ON WEAR MARKER	QLD WORKSHOP
26/04/2024	891,409 kms	ROTATE DRIVES, ROTATE STEER T-2505 ROTATE DRIVES DIAGONAL POS 1 T.O.R RUNOUT POS 2	DARREN BUDD'S TYRES PTY LTD
22/04/2024	889,559 kms	A S-10832 A-SERVICE ICE PACK SERVICED AT 4715HRS REPLACED AIR DRYER UNLOADER REPLACED TRAILER BRAKE RELEASE ASSEMBLY AS WAS LEAKING ADJUSTED CLUTCH	QLD WORKSHOP
22/04/2024	889,559 kms	AIR LEAKS, CLUTCH ADJUSTMENT R-4375 REMOVED AND REPLACED AIR DRYER DUMP VALVE ADJUSTED CLUTCH RED TRAILER BUTTON LEAKING AIR REMOVED AND REPLACED	QLD WORKSHOP
26/03/2024	880,124 kms	AIR BRAKE VALVE, AIR LEAK, CLUTCH ADJUSTMENT, DASH GLOBES, DOOR CARD R-4263 TOOK OUT GLOBES FOR VOLTAGE AND AXLE OIL RR RR AND REPLACED WITH NEW GLOBES TOOK APART SPITLER BUTTON OFF GEAR STICK CLEAN OUT ALL OF MOISTURE AROUND SEAL FOR BALL-BEARING THEN PUT BACK TOGETHER NO AIR LEAKS CLUTCH WAS ADJUSTED REPLACED PRIME MOVER YELLOW BUTTON AND TRAILER BUTTON TIGHTENED DOOR CARD, REPLACED MISSING SCREWS, REPLACED THE DOOR CARD TREES	QLD WORKSHOP
15/03/2024	876,619 kms	Heavy Vehicle Inspection Checklist - Truck I-445	QLD WORKSHOP
14/03/2024	876,619 kms	C S-10565	QLD WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
ICE PACK 4674 HOURS DUE AT 4714 HOURS TOP TUNE CARRIED OUT BY THE MC RESEALED FRONT OF 1ST DIFF HOUSING			
14/03/2024	876,619 kms	A S-10564	QLD WORKSHOP
05/03/2024	872,817 kms	FAN SPEED RESISTOR, SPOTTER MIRROR, STEERING WHEEL R-4179	QLD WORKSHOP
REMOVE AND REPLACED STEERING WHEEL REMOVE AND REPLACED FAN SPEED RESISTOR AND FAN SPEED FUSE REPLACED DAMAGED SPOTTER MIRROR			
12/02/2024	860,000 kms	ROTATE STEER T-2349	DARREN BUDD'S TYRES PTY LTD
		1 X T.O.R POS 1 1X ROTATE POS 2	
12/02/2024	859,426 kms	B S-10278	QLD WORKSHOP
		B-SERVICE P/S KING PIN HAS PLAY	
22/01/2024	845,922 kms	A S-10068	QLD WORKSHOP
03/01/2024	831,568 kms	A S-9901	QLD WORKSHOP
		SERVICED ICE PACK AT 4414HRS	
12/12/2023	824,914 kms	BATTERYS R-3819	QLD WORKSHOP
		LOAD TESTED ALL BATTERIES, 2X FAILED REMOVED AND REPLAVED ALL BATTERIES, CHECK CHARGE RATE, ALTERNATOR CHARGING AT 14V, AT BATTERIES 13.7V SENT BACK INTO SERVICE	
21/11/2023	812,516 kms	HORN, MUD GUARD R-3747	QLD WORKSHOP
		FITTED NEW GUARD AND SECURED INTO PLACE AS REQUIRED, ALL OKAY. REMOVED AND REPLACED ELECTRIC HORMS ON TRUCK. TESTED ALL OK	
21/11/2023	812,516 kms	A S-9615	QLD WORKSHOP
		ICE PACK SERVICED NOW DUE AT 4641 HOURS	
20/11/2023	812,604 kms 10,205 hrs	FUEL PUMP R-3780	CUMMINS SOUTH PACIFIC PTY LTD
		- Drive vehicle into workshop, quickserve vehicle - Active fault codes 559 & 1911 - Trouble shoot fault codes to find fuel pump pressure to be erratic, remove fuel pump head to find rear follower to be damage & stuck in body bore, fuel pump incorrectly assembled - Remove & replace fuel pump, plumb system, replace fuel filters - Remove oil filter, cut open filter & inspect to find no debris - Fit new oil filter, top up engine oil - Start engine, wash engine, road test vehicle - Clear inactive fault codes, check over - Return vehicle back to service	
08/11/2023	803,470 kms	ABS SENSOR, Turbo R-3719	QLD WORKSHOP
		REMOVE TURBO AND EXHAUST MANIFOLD CLEAN ALL AREAS FOR NEW GASKETS, SPLIT TURBO FROM MANIFOLD AND CLEAN AREA INBETWEEN, REMOVE AND REPLACE ALL TURBO STUDS. MOUNT NEW TURBO TO MANIFOLD, REPLACED OLD NUTS WITH NEW AND TORQUE TO 66FT lbs, REPLACED ALL O-RINGS FOR OIL FEED LINES. REPLACED ALL MANIFOLD GASKETS, MOUNT TURBO AND MANIFOLD TO ENGINE TORQUE MANIFOLD BOLTS TO 44FT lbs. FINISHED INSTALLING ALL OTHER PIPING FOR TURBO, TEST RUN ALL WORKING CORRECTLY. TEST DROVE UNIT AND CHECKED OVER AFTER RUN NO LEAKS PRESENT, ALL OKAY. REMOVED AND REPLACED LEFT HAND STEER ABS SENSOR. TEASTED ALL OK	
03/11/2023	801,517 kms	DRIVERS DOOR R-3706	QLD WORKSHOP
		FOUND DOOR HINGE HEAVILY DAMAGED AND BENT, TO GAIN ACCESS TO DOOR HINGE REMOVED ALL COMPONENTS OF DOOR, REMOVED DOOR AND CUT OFF ALL CONE RIVETS TO REMOVE DOOR HINGE, NEW DOOR HINGE FITTED INTO PLACE AND REFITTED DOOR TO TRUCK THEN REFITTED ALL PRIOR COMPONENTS THAT WERE REMOVED, NEW WINDOW FELTS FITTED TO WINDOW TRACK, NEW DOOR LOCK MECH FITTED INTO PLACE AND ALL LINKAGE CONNECTED AS REQUIRED, NEW MIRROR CONTROL SWITCH FITTED AS OLD ONE NON OPERATIONAL, TESTED ALL FUNCTION OF DOOR, OPERATION OF WINDOW, LOCK AND UNLOCK DOOR AND FUNCTION OF MIRROR SWITCH ALL WORKING AS SHOULD BE ALL OKAY.	
26/10/2023	801,517 kms 10,092 hrs	CLUTCH, DRIVERS DOOR, FUEL PUMP, GEAR BOX, GEAR BOX OIL ON KLMS R-3677	QLD WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
		DRAIN COOLANT INTO TUBS TO REUSE, REMOVE FUEL FILTER, POWER STEERING PUMP AND COMPRESSOR. REMOVE TOP SECTION OF FUEL PUMP, INSPECTED ALL COMPONENTS ALL WITHIN SPEC, CLEAN ALL COMPONENTS AND SURFACES REPLACE GASKET. MOUNT TOP SECTION AND TORQUE BOLTS TO 50FTLB, RE-FILL COOLANT. PLUGGED IN COMPUTER FOR IN SITE, RAN UP TRUCK TO TEST IF FUEL RAIL WAS HOLDING PRESSURE, FUEL RAIL HOLDING CORRECT PRESSURE. CHECK FOR LEAKS. NO LEAKS FOUND. REMOVED GEARBOX AND REMOVED TOP COVER INSPECTED ALL GEARS, FOUND MOST DOGGEAR TO BE WELL WORN. SENT AWAY TO GIBBS FOR REBUILD. INSPECT CLUTCH AND FOUND SMALL CHUNKS OF SPRING UP NEAR THE STARTER MOTOR, PULLED CLUTCH AND FLYWHEEL OFF, SENT FLYWHEEL TO BE MACHINED BY BROWN AND HURLEY. REAR MAIN SEAL IN GOOD CONDITION NO LEAKS FOUND. REPLACED SPIGOT BEARING AND RE-INSTALLED MACHINED FLYWHEEL AND TORQUED TO SPEC. INSTALLED CLUTCH AND TORQUED TO SPEC, INSTALLED GEARBOX WITH NEW CLUTCH BRAKE ON SHAFT, RE-FIT ALL COMPONENTS BACK ONTO GEARBOX, FILLED WITH FRESH OIL AND REPLACED GEARBOX FILTER. SENT TRUCK FOR TEST DRIVE, RE-INSPECTED ALL AREAS FOR LEAKS, NONE FOUND SENT TRUCK BACK INTO SERVICE	
13/10/2023	801,516 kms	FUEL PRO COLLAR R-3634 REPLACED THE FUEL PRO COLLAR ALL FIXED	QLD WORKSHOP
12/10/2023	801,341 kms	B S-9214 PLAY IN D/S KING PIN ICE PACK currently 4230hrs due 4340hrs	QLD WORKSHOP
12/09/2023	786,696 kms	A S-8994 CARRIED OUT A-SERVICE	QLD WORKSHOP
05/09/2023	779,338 kms	HUB CAP COVERS R-3438 PUT NEW HUB COVER ON AND MADE SURE IT WAS SECURED PROPERLY AND WOULDNT COME OFF	QLD WORKSHOP
30/08/2023	775,659 kms	A S-8842	QLD WORKSHOP
24/08/2023	772,405 kms	DRIVER SEAT, NO BOOST, WINDSCREEN R-3399 FOUND CHARGE LINE TO ACTUATOR TO BE PINCHED NOT ALLOWING BOOST PRESSURE TO REACH WASTEGATE TO ACTUATE, REPLACED HOSE AND TESTED ALL OKAY. REMOVED ALL GLUE OFF WINDSCREENS AS NEEDED, ALL OKAY. DRIVERS SEAT TRAVELS AS FAR BACK AS POSSIBLE ALL OKAY.	QLD WORKSHOP
04/08/2023	759,378 kms	A S-8644 FRONT ENGINE MOUNTS SMALL SPLIT ADJUSTED GEAR STICK CABLES 4167hrs currently due 4340hrs	QLD WORKSHOP
19/06/2023	741,333 kms	B S-8261	QLD WORKSHOP
25/05/2023	725,578 kms	A S-8090	QLD WORKSHOP
04/04/2023	710,849 kms	ROTATE DRIVES, ROTATE STEER T-1627 ROTATED ALL DRIVES SIDE TO SIDE QLD WORKSHOP ROTATED STEERS SIDE TO SIDE	DARREN BUDD'S TYRES PTY LTD
04/04/2023	710,849 kms	C S-7688	QLD WORKSHOP
04/04/2023	710,849 kms	Heavy Vehicle Inspection Checklist - Truck I-266	
03/04/2023	710,849 kms	DRIVERS DOOR SEAL, DRIVE SHOCK LOWER BUSHES, ENGINE MOUNTS R-2988 REMOVE LOWER SHOCK BOLT AND REMOVE OLD WORN BUSH INSTALL NEW BUSH AND INSTALL NEW LOWER SHOCK BOLT AND TIGHTEN TO SPEC REMOVED AND REPLACED DRIVER DOOR SEAL AS IT WAS BROKEN AND NO LONGER SEALING	QLD WORKSHOP
31/03/2023	710,848 kms	A S-7648 SMALL SPLIT IN FRONT ENGINE MOUNTS D/S REAR LOWER SHOCK BUSH WORN	QLD WORKSHOP
08/03/2023	694,185 kms	AD BLUE FAULT R-2912 FOUND AD-BLUE PUMP INTERNALS WORN, TRIED TO REPAIR BUT PUMPED STILL FAILED AFTER TEST RUN REMOVE AND REPLACED AD-BLUE PUMP	QLD WORKSHOP
06/03/2023	694,827 kms	A S-7405 ICE PACK SERVICED AT 4041 HOURS	QLD WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
25/02/2023	688,118 kms	AD BLUE FAULT, AD BLUE INJECTOR R-2873 TRUCK COME IN WHIT AD BLUE FAULT FOUND THE THE LINE WAS OF THE INJECTOR REPAIRED THE LINE AS NEED WHEN TO REMOVE THE INJECTOR TO DO A FLUSH AND FOUND THE INJECTOR WAS STUCK IN THW EXHAUST PIPE HAD TO REMOVE THE EXHAUST PIPE TO GET THE INJECTOR OUT DAMAGE INJECTCTOR TRYING TO GET IT OUT REPLECED INJECTOR AND HAD TO REPLECE THE EXHAUST PIPE GASKET WHEN PUTING EXHAUST PIPE BACK ON TRY DOING A FLUSH TO GET CLEAR CODE BUT DID NOT WORK TRY BLOWING OUT ALL THE LINE AND CHEAKING ALL LINES FOR O-RING RUN FLUSH AGIN STILL NO GOOD REMOVED AD-BLUE PUMP PULLED APART CLEANED AND PUT BACK TOGERTH AND ON THE TRUCK DONE A FLUSH AGIN AND TESTS AND STARTED WORKING AS SHOULD SENT TRUCK ON RUN. COME BACK AFTER A WEEK AND STILL HAD THE SAME FAULT, REMOVED AND REPLACED AD-BLUE PUMP ALL OK.	QLD WORKSHOP
13/02/2023	680,750 kms	ALTERNATOR R-2835 FOUND THE ALTERNTOR WAS NOT CHARGING REMOVED AND REPLACED ALTERNTOR	QLD WORKSHOP
13/02/2023	680,750 kms	NEW STEERS T-1550 2 X BRIDGSTONE STEER TYRES FITTED UP ALL OK	DARREN BUDD'S TYRES PTY LTD
13/02/2023	680,750 kms	B S-7218	QLD WORKSHOP
13/02/2023	680,750 kms	Heavy Vehicle Inspection Checklist - Truck I-239	
17/01/2023	662,153 kms	REKIT HORTON FAN HUB, REPLACE COMP ON KLMS R-2760 DRAIN ALL COOLENT AND REMOVE FUEL FILTER. REMOVE POWER STEER PUMP THEN UNBOLT ALL HOSES FROM AIR COMPRESSOR. REMOVE GOVENER FROM AIRCOMPRESSOR AND THEN REMOVE AIR COMPRESSOR CLEAN ALL FACES OF MOTOR AND POWER STEER PUMP PUT NEW SEALS ON THE MOTOR AND REINSTALL NEW AIR COMPRESSOR INSTALL NEW GOVERNER VALVE AND ALL HOSES ON AIR COMPRESSOR PLACE NEW POWER STEER PUMP SEAL ON AND REINSTALL POWER STEER PUMP PLACE FUEL FILTER BACK ON AND BLEED UN FUEL AND REFILL WITH GREEN COOLENT AND BLEED UP COOLING SYSTEM. START UO TRUCK AND CHECK FOR LEAKS NONE FOUND AND CHECK AIR BUILD RATE WITH NEW SYSTEM. REMOVE FAN FROM HUB AND REMOVE HUB FROM MOTOR PULL DOWN HORTEN HUB ON BENCH AND CLEAN ALL MAIN PARTS REKIT AND ASEMBLE AND REINSTALL INTO TRUCK, REFIT FAN START TRUCK UP AND TEST HORTEN FAN	QLD WORKSHOP
12/01/2023	660,296 kms	ROTATE DRIVES T-1516 ROTATED DRIVES DIAGONAL	QLD WORKSHOP
12/01/2023	660,296 kms	A S-6942	QLD WORKSHOP
05/12/2022	636,678 kms	A S-6657 ICE PACK SERVICED @3694HOURS	QLD WORKSHOP
16/11/2022	621,627 kms	ROTATE/BALANCE STEER T-1384 BALACED BOTH STEERS FLIPPED POS # 1 ON RIM	DARREN BUDD'S TYRES PTY LTD
16/11/2022	621,627 kms	B S-6520	QLD WORKSHOP
31/10/2022	609,046 kms	STARTER MOTOR, WIPER BLADE R-2509 Have checked for power going to starter motor and there was power so have disconnected the batteries and all the lines to the starter motor and started unbolting it removed the faulty starter and fitted a brand new paccar starter in connected all the wire and bolted the new starter in connected the batteries and the truck started on first go, also have zip tied all cables and lines up Have removed Old worn wiper blades and fitted brand new TRP wiper blades	MELBOURNE VIC WORKSHOP
28/10/2022	607,958 kms	ENGINE REBUILD R-2511 FOUND DROPPED CYLINDER 5, REMOVED AND REPLACED ALL LINNERS AND RINGS. FOUND FRONT GEAR BEARING HAD SPUN AND PUT METAL THROUGHOUT MOTOR. REPLACED ALL MAIN AND BIG END BEARINGS, REPLACED OIL COOLER AND OIL THERMOSTATE. REFITTED ALL COMPENTS AND DYNOMETER RUN UP ALL OK. TRUCK SENT BACK INTO SERVICE. ALL COVERED UNDER WARRANTY	CUMMINS SOUTH PACIFIC PTY LTD
24/10/2022	607,177 kms	NEW DRIVE TYRES T-1422 ALL NEW M766 BRIDGSTONE DRIVE TYRES FITTED UP ALL OK 2 X DUMPS	DARREN BUDD'S TYRES PTY LTD
24/10/2022	607,177 kms	A S-6306	QLD WORKSHOP
26/09/2022	590,832 kms	A S-6137	QLD WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
25/08/2022	574,545 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-1309 ROTATED ALL DRIVES DIAGONAL ROTATE AND BALANCED STEERS, FLIPPED POS 1 ON RIM	DARREN BUDD'S TYRES PTY LTD
25/08/2022	574,545 kms	A S-5922 SERVICE ICE PACK AT 3360	QLD WORKSHOP
24/08/2022	574,545 kms	ICE PACK ALTERNATOR R-2316 PARTS ON ORDER FOR ALTERNATOR REMOVE AND REPALCED ICEPACK ALTERNATOR CHECKED CHARGE RATE, CHARGING AT 13.2V	QLD WORKSHOP
17/08/2022	568,799 kms	ADBLUE TANK, NO BOOST R-2307 REPLACE C-CLIP FOR WASTEGATE FLUSH ADBLUE BREATHER WITH HOT WATER TO UNBLOCK	QLD WORKSHOP
03/08/2022	559,212 kms	B S-5726	QLD WORKSHOP
12/07/2022	543,605 kms	A S-5567	QLD WORKSHOP
30/06/2022	537,016 kms	SPEEDO HARNESS R-2148 TRUCK NOT REVING PAST 1500RPM CHECK ALL WIRING THAT MAY BE THE FAULT FIND THE GEARBOX WIRE LOOM HAS COROSON ON SPEED SENDER NO.2 REMOVE AND REPLACE LOOM TEST DRIVE TO MAKE SURE ALL IS WORKING FINE	QLD WORKSHOP
20/06/2022	529,731 kms	A S-5404 TOPPED UP OIL TOPPED UP COOLANT TIGHTEN HOSE CLAMP COOLANT HOSE D/S TOP RIGHT FROM RADIATOR	QLD WORKSHOP
20/06/2022	529,713 kms	ROTATE/BALANCE STEER T-1186 ROTATED AND BALANCED STEER TYRES ALL OK	DARREN BUDD'S TYRES PTY LTD
14/06/2022	526,196 kms	OIL LEAK R-2070 CHEAKED OVER ENG FIND OIL LEAKING FROM COMPRESSOR REMOVED AND REPLACED COMPRESSOR AND POWER STEERING PUMP GASKETS	QLD WORKSHOP
07/06/2022	522,650 kms	brake adjustment R-2049 put 45s on male and female air lines checked over all brakes on trailers	
26/05/2022	515,587 kms	A S-5243 OIL LAEK FROM AROUND FLUE PUMP AND FRONT OFF ENG	QLD WORKSHOP
26/05/2022	515,587 kms	ROTATE DRIVES T-1141 ROTATED ALL DRIVES CROSS TO CROSS ROTATED AND BALANCED STEER TYRES ALL OK	DARREN BUDD'S TYRES PTY LTD
20/05/2022	512,055 kms	CHECK ENGINE LIGHT, TURBO ON KLMS R-1998 REMOVED AND REPLACED TURBO, GASKET AND ORING ON KMS CHECK ENGING LIGHT C/O MAMOFLOND SENDER REMOVED AND REPLACED START SOLENOID TEST DROVE & CHECKED OVER ALL OK SENT BACK INTO SERVICE	QLD WORKSHOP
10/05/2022	499,769 kms	B S-5199	QLD WORKSHOP
30/04/2022	497,267 kms	BATTERYS, DASH GLOBES R-1922 REMOVED AND REPLACED ALL BATTERIES REPLACED 10 X DASH BULBS	QLD WORKSHOP
08/04/2022	484,943 kms	A S-4960 TRAILER ABS LIGHT ON, NO FAULT ON TRUCK	QLD WORKSHOP
22/03/2022		Heavy Vehicle Inspection Checklist - Truck I-92	
22/03/2022	473,538 kms	C S-4846	QLD WORKSHOP
14/03/2022	465,468 kms	A S-4741 REPLACE MISSING BOLT IN FAN BELT TENSIONER	QLD WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
27/02/2022	460,766 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-949 on inspection found steers tyres very low and replaced rotate and balance steers rotate drives front to back	TREADCARE PTY LTD
27/02/2022	460,766 kms	A S-4660	MELBOURNE VIC WORKSHOP
04/02/2022	442,472 kms	CHECK BATTERIES R-1582 LOAD TEST ALL BATTERIES 3 PASSED 1 FAILED REPLACE FAILED BATTERY WITH 2ND HAND BATTERY	QLD WORKSHOP
31/01/2022	440,564 kms	B S-4451 monitor battery's referee to job card	MELBOURNE VIC WORKSHOP
11/01/2022	426,250 kms	A S-4291	QLD WORKSHOP
15/12/2021	409,538 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-841 ROTATED ALL DRIVES DIAGONAL ONLY	DARREN BUDD'S TYRES PTY LTD, QLD WORKSHOP
15/12/2021	409,537 kms	A S-4138 TOPPED UP BATTERIES	QLD WORKSHOP
30/11/2021	395,041 kms	A S-3985	QLD WORKSHOP
30/11/2021	395,041 kms	ABS PLUG R-1380 REMOVE AND REPLACE BROKEN ABS PLUG WITH NEW TEST ALL OK	QLD WORKSHOP
25/11/2021	387,251 kms	ABS FAULT R-1589 FOUND REAR LEFT WHEEL SPEED SENSOR ISSUE, REMOVED AND REPLACE SENSOR WITH NO CHANGE. TRACED BACK WIRING, FOUND TO BE BROKEN. REMOVED AND REPLACED ALL WIRING AND PLUGS FRPOM CAB TO LEFH HAND REAR AXEL. TEST ALL OK	QLD WORKSHOP
01/11/2021	379,281 kms	B S-3780	QLD WORKSHOP
13/10/2021	364,004 kms	NEW DRIVE TYRES T-696 ALL NEW DRIVE TYRES FITTED UP ALL OK	DARREN BUDD'S TYRES PTY LTD
13/10/2021	364,005 kms	A S-3631 SERVICED ICE PACK	QLD WORKSHOP
13/10/2021	364,005 kms	BOOST CLAMP, ENGINE OIL LEAK R-1229 FOUND OIL TO BE LEAKING OUT FROM AROUND OIL FILLER ON ENGINE. REPLACED OIL FILL CAP AND MOUNTING O-RING REPLACED BOOST CLAMP ON TURBO SIDE	QLD WORKSHOP
22/09/2021	349,521 kms	A S-3482	QLD WORKSHOP
15/09/2021	343,900 kms	NEW STEERS T-685 FITTED AND BALANCED NEW STEER TYRES ALL OK	DARREN BUDD'S TYRES PTY LTD
01/09/2021	333,558 kms	A S-3310 Rory Gilmore	QLD WORKSHOP
16/08/2021	319,277 kms	WINDSCREEN R-1029	ADGLASS
12/08/2021	319,277 kms	B S-3177	QLD WORKSHOP
22/07/2021	299,831 kms	A S-2962	QLD WORKSHOP
08/07/2021	295,446 kms	ROCK GUARD, WINDSCREEN R-874 REMOVED AND REPLACED ROCK GUARD FROM ACCIDENT DRIVERS WINDSCREEN REPLACED IN PORT MAC	QLD WORKSHOP
29/06/2021	289,598 kms	A S-2791	QLD WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
28/06/2021	289,600 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-492 ROTATED ALL DRIVES SIDE TO SIDE 1 X FLIP ON RIM STEER 2 X BALANCE	DARREN BUDD'S TYRES PTY LTD
08/06/2021	275,716 kms	A S-2652	QLD WORKSHOP
17/05/2021	259,821 kms	B S-2455 ICE PAK SERVICED AT 1604HRS	QLD WORKSHOP
30/04/2021	246,385 kms	A S-2200	QLD WORKSHOP
30/04/2021	246,386 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-423	QLD WORKSHOP
30/03/2021	230,620 kms	A S-2053	QLD WORKSHOP
16/03/2021	215,093 kms	A S-1898	MELBOURNE VIC WORKSHOP
16/03/2021	215,093 kms	HEADLIGHT COVER R-450 replaced L/H headlight cover	
10/03/2021	211,382 kms	OIL LEAK R-438 replaced rocker cover gasket	
09/03/2021	209,503 kms	NEW STEERS T-302 2 NEW STEER TYRES BALANCED AND FITTED UP SRV WORKSHOP ROTATED DRIVE TYRES	DARREN BUDD'S TYRES PTY LTD
09/03/2021	209,593 kms	C S-1768	QLD WORKSHOP
24/02/2021	200,103 kms	B S-1678	MELBOURNE VIC WORKSHOP
03/02/2021	186,959 kms	A S-1492	
08/01/2021	169,593 kms	A S-1251	
03/12/2020	144,161 kms	BALANCE STEERS, FLIP ON RIM, ROTATE DRIVES T-92 ROTATED ALL DRIVE TYRES FLIPED BOTH STEER TYRES AND BALANCED	DARREN BUDD'S TYRES PTY LTD
26/11/2020	141,660 kms	B S-792	
18/11/2020	135,309 kms	A S-707	
01/03/2020		C S-1698	

Signed: _____

Name: _____

Date: _____