

Maintenance History (All work types) - BH 437

All History

Work Order ID	Description	yp	Hour Reading	meter Re	Status Date
151635	Remove decals . ----- Everest Naki added [09/26/2025 06:34 PM] -----Go through machine look for leaks found one major leak	Non PM			9/25/2025
148364	Complaint: Machine couldn't start Cause: Battery	N	3890 on 9/2/2024 3:1		9/16/2025
142286	Remove plexiglass frame	Non PM			5/23/2025
129972	- complete swivel install & top off hyd - travel still inop check codes, t/s & advised Doug ---08/12/2024---Mechanic Intern: Keola Ro	Non PM			3/8/2025
126898	Ordered parts after pm inspection.	Non PM			3/8/2025
137347	- assist replace travel motors	Non PM			12/19/2024
132130	PM2-----PM1	PI	3890 on 9/2/2024 3:1		9/9/2024
129472	T/s hyd system works and travel inop. Found swivel leaking. Tighten base cover, still leaking. Suspected swivel bypassing or broken	Non PM			8/12/2024
129409	Complaint: Hyd leak at cooling fan control valveCause: Worn o-ringsComplaint: Removed panels, disassembled and cleaned block.	N	3888 on 8/1/2024 9:1		8/12/2024
129085	- reinstall track guard & re-tighten all	Non PM			8/12/2024
129583	- hyd leak locate leak at cooling fan control valve remove panels to access valve clean , disassemble, & reseal valve ok	Non PM			8/5/2024
126041	- door latch inop from inside cab make temp repair will order parts Repairs completed per Doug 08/01/24	Non PM			8/1/2024
126788	PM1 ----- Douglas Nicolas added [07/01/2024 09:25 AM] -----Performed pm1	PI	3736 on 6/30/2024 1:		7/26/2024
127217	Air arc cracks on za507 and za793 and weld completed ----- Doni-Jay Pouuahi added [07/09/2024 10:08 PM] -----Assist with re	Non PM			7/24/2024
128765	- hyd leak locate leak at quick coupler & replace blown o-ring	Non PM			7/20/2024
126277	- weld crack track links	Non PM			6/29/2024
126120	Assess broken track links. Make parts list. ---06/18/2024---Mechanic Intern: Isaiah Acia = 6 hours- Press track links, load & transp	Non PM			6/26/2024
125777	- hyd leak right side aux line & left side stucci coupler replace right side hard line & left stucci	Non PM			6/13/2024
125578	- engine loss of power t/s found fuel issue advised Doug need fuel filters replace filters test ok ----- Everest Naki added [C	Non PM			6/8/2024
125017	- repair cracked link & adjust tracks	Non PM			6/8/2024
124945	- replace ripper teeth on ZA511	Non PM			6/8/2024
124567	Tighten track pad bolt and grease tracks ----- Douglas Nicolas added [05/18/2024 08:10 PM] -----Track carrier roller worn out. L	Non PM			6/8/2024
124869	Replaced missing hammer pin bolt. Complete	Non PM			5/24/2024
123385	Cut out track pads cut track link crawler frame spreading open u brace in crawler broken v out push in frame with 100 ton jack and	Non PM			5/13/2024
124044	Start going through machine ----- Marcus Calairo-Nakagawa added [05/09/2024 11:57 PM] -----Replaced stick cylinder grease li	Non PM			5/13/2024
122093	PM3Take oil samples for lab analysis - House swing motor Planetary/Final Drive oil Hydraulic and/or Hydrostatic oil	PI	3406 on 3/30/2024 1:		5/10/2024
120790	Look for track roller bolts and located. Head to kukuia to assist rance with roller install. Extracted broken bolts and inspected track f	Non PM			5/4/2024
118374	- hyd leak locate leak & repair loose fitting wash swing area & crawler frame ---01/05/2024---Mechanic Intern: Isaiah Acia = 2	Non PM			4/9/2024
120518	- secure quick coupler hoses on boom - install retainer bolt on quick coupler pin	Non PM			2/27/2024
117274	PM2Take oil samples for lab analysis - Engine oilChange engine oil and oil filter (including bypass filter)Replace fuel filter(s) and ble	PI	3074 on 12/29/2023		1/11/2024

117764	Complaint- machine not firing hammer.Cause- troubleshoot and found HKX box was disconnected prior to previous repair.Correctio	Non PM	12/29/2023
117486	Complaint- bucket curl slow.Cause- found main controller codes. Parts were ordered by Doug. ----- Darius Quedding added [12/16	Non PM	12/18/2023
117396	Complaint- hyd leak and machine not firing hammer as hard.Cause- cleaned swivel area and found no leaks possible residue. Correc	Non PM	12/13/2023
116760	Start cleaning swing area ----- Everest Naki added [11/29/2023 10:21 PM] ----- Assist with cleaning ----- Marcus Calairo-Nak	Non PM	12/12/2023
116488	Complaint- right side undercarriage roller bolts loose.Cause- wear and tear.Correctio- tighten bolts, tested ok. Done	Non PM	12/5/2023
115796	Top off hydraulic fluid.	Non PM	11/5/2023
115062	Top off hydraulic fluid and notify Doug about leaks. ----- Douglas Nicolas added [10/20/2023 07:42 PM] -----Ordered parts to re	Non PM	10/30/2023
114663	Complaint- hyd leak.Cause- found small house from 4&5 spool leaking.Correctio- replaced hose, tested ok.	Non PM	10/13/2023
114531	Ordered filters for pms	Non PM	10/8/2023
114451	Complaint- hyd leak.Cause-found multiple 4&5 spool hoses leaking.Correctio- remove hoses and install new hoses. Top off hyd lea	Non PM	10/6/2023
114133	Complaint- quick coupler hose leaking.Cause- found fitting on block cracked.Correctio- install new fitting and hose, tested ok. Done	Non PM	9/29/2023
112029	Line check machine, order parts	Non PM	9/26/2023
110953	- boom pin not taking grease grease hose leaking make temp repair install grease fitting, will make hoses---07/20/2023---Mec	Non PM	9/26/2023
113889	PM1Record hourmeter reading and service performedPerform visual inspectionDo operational checkout, including any attachmentsC	PI 2835 on 9/22/2023 1:	9/24/2023
113864	Complaint- no startCause- found batteries weak.Correctio- jumpstart batteries and will need to get new batteries. Not done ---09/2	Non PM	9/24/2023
113710	Complaint- hydraulic leak come from behind boom.Cause- found right side stick cylinder hose leaking.Correctio- remove hose and t	Non PM	9/21/2023
113017	Complaint- hydraulic leak.Cause- found boom hoses leaking.Correctio- top off hydraulic fluid to get machine off pile dirt, remove h	Non PM	9/7/2023
112964	Complaint- grease lines leaking.Cause- found grease block no good causing lines to rupture.Correctio- remove grease lines and ins	Non PM	9/5/2023
112835	Complaint- when hammering machine slows down and picks up.Cause- went in to monitor and operator used wrong breaker attach	Non PM	8/31/2023
112528	Complaint- Right side track pads loose.Cause- wear and tear.Correctio- install new bolts on track pads. Done ---08/23/2023---Mec	Non PM	8/26/2023
112422	Complaint- hyd leak behind boom.Cause- found stuck cylinder hose leaking.Correctio- remove hose take to D&M hydraulics to mak	Non PM	8/23/2023
110691	Air arc cracks on qc and weld	Non PM	7/24/2023
110893	- right side lower roller came off, bolts broke off slack tracks to remove roller & re-adjust tracks ---07/19/2023---Mechanic Intern:	Non PM	7/20/2023
110431	- a/c inop check system a/c blower motor inop t/s check fuses circuit keeps blowing fuse unable to t/s further machine load	Non PM	7/19/2023
110247	ADJUSTED AUX CIRCUIT FOR HAMMERPAPE MACHINERY SEE INVOICE# 341588 PO# 27376	N 2548 on 7/8/2023 2:2	7/12/2023
109854	Grease machine.	Non PM	7/11/2023
108835	Complaint- hyd leak underneath 4&5 spool.Cause- found T-fitting leaking.Correctio- tighten T-fitting and will monitor. ----- Everes	Non PM	7/11/2023
109640	Complaint- machine bogging out.Cause- troubleshoot found fuel filters clogged.Correctio- replaced fuel filters, blow back main hose	N 2548 on 7/8/2023 2:2	7/11/2023
108072	Set right side track tension per Doug. ----- Darius Quedding added [05/18/2023 11:48 PM] -----Top off coolant.	Non PM	6/1/2023
108690	Complaint- grease lines behind boom leaking.Cause- wear and tear.Correctio- repaired grease lines.	N 2453 on 5/31/2023 1:	6/1/2023
108629	Complaint- lift cylinder making loud noise.Cause- found grease line for pin leaking causing pin to squeak.Correctio- repaired grease	N 2453 on 5/31/2023 1:	6/1/2023
108593	Complaint- right side undercarriage roller bolts missing.Cause- wear and tearCorrection- install new bolts. Done	Non PM	6/1/2023
107942	Complaint- right side track split.Cause- found track links and pins broke off.Correctio- notified Doug and schedule for repair. -----	N 2433 on 5/24/2023 1:	5/25/2023
107328	Complaint- hyd leak on right side lift cylinder hose.Cause- wear and tear.Correctio- replaced hyd hose, top off hyd fluid, tested ok.	Non PM	5/8/2023

106413	Complaint- machine squeaky.Cause- found auto lube low on grease.Correction- grease machine. ----- Jack Guillermo added [04/14/2023 07:35 AM] -----	Non PM	5/8/2023
106321	Repair QC cracks---04/03/2023---GBI Crew: Kaena Pooouahi = 2 hours- Air arc crack in coupler, re-weld	N 2389 on 5/5/2023 1:00 PM	5/8/2023
106290	Complaint- left side undercarriage roller bolts loose.Cause- vibration.Correction- tighten all loose bolts. ----- Everest Naki added [04/03/2023 07:35 AM] -----	Non PM	5/8/2023
106085	Top off hyd fluid. ----- Everest Naki added [03/28/2023 11:16 PM] -----Assist with repairs ----- Darius Quedding added [03/30/2023 07:35 AM] -----	Non PM	5/8/2023
105777	Complaint- hyd leak in center swivel area.Cause- found fan reversing control valve leaking.Correction- tighten fitting on valve but still leaking	Non PM	5/8/2023
103941	PM4Drain & refill planeteriesCheck turbo for leaks and impeller for excessive playDrain & refill hydraulic reservoir fluid & clean strain	PM	5/8/2023
106637	Complaint- serpentine belt ripped and right side stuchi leaking.Cause- wear and tearCorrection- install new belt and replace leaking	N 2389 on 5/5/2023 1:00 PM	5/8/2023
105724	- hyd leak locate leak at hyd tank couplers replace coupler seals ok	N 2389 on 5/5/2023 1:00 PM	5/8/2023
106701	Complaint- hyd leak.Cause- found T-fitting for hyd hoses on 4&5 spools leaking.Correction- replaced fitting, tested ok.	N 2389 on 5/5/2023 1:00 PM	4/13/2023
105350	Line check machine identify p/o---03/11/2023---GBI Crew: Kaena Pooouahi = /1.5 hours- line check, order parts	N 2178 on 3/13/2023 1:00 PM	3/14/2023
104840	Complaint- machine making a lot of noise on boom pins.Cause- pins dry.Correction- grease entire machine. ----- Everest Naki added [03/13/2023 11:16 PM] -----	Non PM	3/14/2023
104731	Complaint- coolant leak.Cause- found reservoir hose from radiator to tank leaking.Correction- remove hose and go to Napa to get new	Non PM	3/14/2023
104466	Complaint- coolant level alarm on monitor.Cause- check coolant level ok. Correction- parts ordered on level sensor.	Non PM	3/14/2023
105341	Complaint- left side compartment door hyd leak.Cause- found hyd hose on pump drive leaking.Correction- replace hyd hose, test for	N 2178 on 3/13/2023 1:00 PM	3/14/2023
105154	Complaint- hyd on right side aux pipe.Cause- found O-ring on steel pipe no good.Correction- replaced O-ring, tested ok. ----- Everest Naki added [03/13/2023 11:16 PM] -----	N 2178 on 3/13/2023 1:00 PM	3/14/2023
104293	Complaint- quick coupler sticky.Cause- wedge is dry.Correction- grease quick coupler, tested ok.	N 2178 on 3/13/2023 1:00 PM	3/14/2023
103194	Put spare coupler on pallet, band coupler to pallet get ready for ship out	Non PM	2/21/2023
103946	Complaint- right side track guard bent.Cause- wear and tear.Correction- cut out old guard.	Non PM	2/8/2023
103750	Complaint- under carriage roller bolts loose and stuchi fitting.Cause- wear and tear.Correction- tighten under carriage roller bolts and	Non PM	2/8/2023
102554	Complaint- right stuchi fitting leaking.Cause- found O-ring for stuchi no good.Correction- replaced O-ring, tested ok. ----- Everest Naki added [02/08/2023 11:16 PM] -----	Non PM	2/8/2023
102893	Complaint- right side undercarriage roller loose and right side stuchi fitting leaking.Cause- wear and tear.Correction- install new bolt	N 2079 on 2/8/2023 2:00 PM	1/13/2023
102753	Complaint- right side aux pipe to valve leaking.Cause- wear and tear.Correction- remove pipe and take back to shop to weld. ----- Everest Naki added [02/08/2023 11:16 PM] -----	N 2079 on 2/8/2023 2:00 PM	1/6/2023
102522	- order PM service filters	Non PM	1/3/2023
102264	- secure broken track guards - repair hyd leak at stucci couplers ----- Jack Guillermo added [12/19/2022 07:35 AM] ----- - install	Non PM	1/3/2023
102403	Complaint- left side stuchi fitting leaking.Cause- found stuchi fitting no good.Correction- replaced stuchi fitting, tested ok. ----- Everest Naki added [12/19/2022 07:35 AM] -----	Non PM	1/3/2023
101565	Replaced left front step with new step. ----- Everest Naki added [12/01/2022 03:56 PM] -----Assist with repairs cut off blocks for	Non PM	1/3/2023
101446	Complaint- hyd leak in center swivel.Cause- found fitting loose on 4&5 spool hose.Correction- tighten fitting, tested ok. Also grease	Non PM	1/3/2023
101811	Assist Install hammer screen and tighten up all loose bolts on panels	Non PM	1/3/2023
101556	Assist with repairs cut off damaged blocks for steps grind and clean area Weldon new blocks on and install steps	Non PM	1/3/2023
100576	Wash machine and start line checking machine ----- Douglas Nicolas added [11/05/2022 07:04 PM] -----Replaced Qc hoses from	Non PM	12/19/2022
101387	Complaint- hyd leak in center swivel area.Cause- found 4&5 spool hose leaking.Correction- remove hose and had spare hose to repl	Non PM	12/19/2022
101032	Complaint- hyd leak on right side stick cylinder.Cause- found hose ruptured.Correction- remove hose and will take to D&M to be ma	Non PM	12/14/2022
100932	Complaint- both joysticks has too much play.Cause- wear and tear.Correction- adjust play on joysticks per operator.	Non PM	12/14/2022
100196	Chain down all attachments onto flat rack	Non PM	11/30/2022

99844	Pressure wash and clean for ship outNeedle gun dirt from tracksSuck out fuel to 1/4tank	Non PM	11/30/2022
99826	Get buckets Out and line up for wash	Non PM	11/30/2022
100161	Load attachments on flat rack	Non PM	11/14/2022
96427	Pressure Wash	Non PM	9/27/2022
96310	Pressure Wash	Non PM	9/27/2022
95417	Pressure Wash	Non PM	9/27/2022
98052	RESEALED BUBKET CYLINDERPAPE MACHINERY SEE INVOICE# 361425 PO# 26037	N 1677 on 8/8/2022 2:2	9/23/2022
95001	Get hose made	Non PM	9/13/2022
94509	Help with trouble shooting wiring to auxiliary s	Non PM	9/13/2022
94243	Help hyd leak	Non PM	9/13/2022
97028	Bucket cylinder leaking ----- Chazrick Pang added [08/19/2022 08:53 PM] -----Set up machine, block up stick. Remove cylinder	Non PM	8/31/2022
96496	Coupler hose pinched, ----- Chazrick Pang added [08/09/2022 09:42 PM] -----Replace hose	Non PM	8/31/2022
95597	Hyd leak under manifold dripping onto tracks ----- Chazrick Pang added [07/25/2022 09:23 PM] -----T/S where leak coming from	Non PM	8/22/2022
96300	Hkx clamp broken on stick ----- Chazrick Pang added [08/05/2022 09:46 PM] -----Pull threads on block, put threw nut and bolt	Non PM	8/9/2022
95168	PM1 Record hourmeter reading and service performed Perform visual inspection Do operational checkout, including any attachm	PI 1661 on 7/20/2022 1:	7/28/2022
94246	Hyd leak, Stu chi no good, replace Boom to stick hose keep coming loose, adapter strip, order new adapter	Non PM	7/26/2022
93834	hydraulic leaking from HKX ----- Dedrick Pang added [06/15/2022 10:44 AM] -----hardline cracked. Chaz temporary weld crack.	Non PM	7/26/2022
95269	Pressure side stuchi leaking ----- Bryan Ellis added [07/19/2022 10:33 AM] -----Replace stuchi	Non PM	7/26/2022
95209	Bucket cracked ----- Bryan Ellis added [07/18/2022 10:02 AM] -----Cut and weld bucket	Non PM	7/26/2022
95129	hydraulic leaking on stick ----- Dedrick Pang added [07/15/2022 11:05 AM] -----HKX hardline leaking. check if hardline is cracked	Non PM	7/26/2022
94949	Track pads bolts loose ----- Bryan Ellis added [07/12/2022 10:06 AM] -----Tighten bolts	Non PM	7/26/2022
94771	hydraulic leaking from behind boom ----- Dedrick Pang added [07/07/2022 10:14 AM] -----remove hose leaking for HKX and rep	Non PM	7/26/2022
94533	Hardline slipping ----- Bryan Ellis added [06/30/2022 10:20 AM] -----Clamps bad, bolt broken, replace clamps, tap new hole, inst	Non PM	7/26/2022
94437	Joystick spinning ----- Bryan Ellis added [06/28/2022 10:21 AM] -----Instal keeper pins	Non PM	7/26/2022
94416	Hyd leak, orfs fitting cracked. Fitting ordered, special order	Non PM	7/26/2022
94233	Track pads coming loose ----- Bryan Ellis added [06/23/2022 12:49 PM] -----Tighten cannot, cut off and instal new	Non PM	7/26/2022
94087	Hyd leak, replace o ringClamps for hkx loose, one fall off, tighten put new clamp an bolts	Non PM	7/26/2022
93793	Hyd leakss ----- Chazrick Pang added [06/14/2022 09:02 PM] -----Left side hardline cracked, remove clamp, clean up & weld cra	Non PM	7/26/2022
93889	REPLACED DPF FILTERPAPE MACHINERY SEE INVOICE# 361099 PO# 25421	N 1661 on 7/20/2022 1:	7/22/2022
93548	WELDED CRACK ON COUPERPAPE MACHINERY SEE INVOICE# 360887 PO# 25388	N 1661 on 7/20/2022 1:	7/22/2022
93169	REPAIRED BAD WIRE FOR HYD FUNCTIONS. PAPE MACHINERY SEE INVOICE# 361108 PO# 25323	N 1572 on 6/29/2022 2:	6/30/2022
92648	BLower motor in cab intermittently working ----- Bryan Ellis added [05/18/2022 10:09 AM] -----Check wires, check fan. Fan goin	Non PM	6/13/2022
92647	Ac belt loose ----- Bryan Ellis added [05/18/2022 10:08 AM] -----Tighten belt	Non PM	6/13/2022
93531	Stuchi bad, need replace ----- Bryan Ellis added [06/08/2022 10:00 AM] -----Replace stuchi	Non PM	6/13/2022

93386	control stick fell off ----- Dedrick Pang added [06/04/2022 10:55 AM] -----make pins to hold controller on. put on rubber lock ring	Non PM	6/13/2022
93120	Hyd Leak ----- Chazrick Pang added [05/27/2022 07:28 PM] -----Hose blown, change out	Non PM	6/13/2022
93090	Hyd leak ----- Chazrick Pang added [05/27/2022 12:45 PM] -----Fitting crack. R&R	Non PM	6/13/2022
93082	codes came on dash ----- Dedrick Pang added [05/27/2022 10:47 AM] -----connect computer to check codes. travel pilot pressure	Non PM	6/13/2022
92947	Final cover bolts coming loose ----- Bryan Ellis added [05/25/2022 10:02 AM] -----Instal new bolts	Non PM	6/13/2022
92834	oil leaking under swing frame ----- Dedrick Pang added [05/23/2022 10:05 AM] -----check under machine where oil coming from	Non PM	6/13/2022
92756	hydraulic leak on machine ----- Dedrick Pang added [05/20/2022 10:14 AM] -----fitting came loose and cut o-ring. remove all parts	Non PM	6/13/2022
92710	Hard line clamp fell off ----- Bryan Ellis added [05/19/2022 10:54 AM] -----Take off hardline drill bolt,tap replace	Non PM	6/13/2022
92589	Missing track pad bolt ----- Bryan Ellis added [05/17/2022 09:51 AM] -----Cut and replace	Non PM	6/13/2022
92156	Engine code popping up and engine limp mode ----- Dedrick Pang added [05/06/2022 10:29 AM] -----try removing engine code.	Non PM	5/13/2022
90608	Check on aux inop check wiring and solinoid ----- Bryan Ellis added [05/07/2022 04:27 PM] -----Take rail off, and hoses, bolts are	Non PM	5/13/2022
92467	Hose leaking on tank ----- Bryan Ellis added [05/13/2022 11:31 AM] -----Take off old hose instal new hose	Non PM	5/13/2022
92446	Hyd leak, t/s ----- Chazrick Pang added [05/12/2022 10:05 PM] -----Rub out, Change hose	Non PM	5/13/2022
91300	Track pin coming out check tracks Gonna get inspection done Pape	Non PM	5/5/2022
89819	Pape s window on boom cracked open Going over with Randy rework	Non PM	5/5/2022
89321	Loose track pad tighten up replacing one bolt	Non PM	5/5/2022
88255	Coupler cracked again Pape warranty	Non PM	5/5/2022
87693	Pape welding crack on boom All done they gotta touch up	Non PM	5/5/2022
92070	engine code came on ----- Dedrick Pang added [05/04/2022 10:13 AM] -----exhaust temperature sensor has high input. most likely	Non PM	5/5/2022
91989	Machine derating, fuse Hyd cut out blow. ----- Chazrick Pang added [05/02/2022 09:01 PM] -----Change fuse help t/s harness -	Non PM	5/5/2022
91988	Hammer hose fitting cracked ----- Chazrick Pang added [05/02/2022 08:59 PM] -----Put new hose	Non PM	5/5/2022
91678	Hammer hose blow ----- Chazrick Pang added [04/25/2022 09:54 AM] -----Bring Koa hamma hose at jobsite	Non PM	5/5/2022
91292	Hardline bent ----- Chazrick Pang added [04/14/2022 08:48 PM] -----Loosen all clamps. Turn hardline away from moving parts to	Non PM	5/5/2022
91247	Hkx clamps fall off ----- Chazrick Pang added [04/14/2022 12:38 AM] -----Look for clamps an bolts. Put um on	Non PM	5/5/2022
90970	Hardline bent/cracked. was temporary welded ----- Chazrick Pang added [04/07/2022 09:53 PM] -----Put on new hardline -----	Non PM	5/5/2022
90800	Machine hydraulics shut down, engine still running but no hydraulic functions, 9 different codes for the same harness controlling all	Non PM	5/5/2022
90693	Hydraulic leak ----- Chazrick Pang added [04/01/2022 08:31 PM] -----Troubleshoot wea leak coming from, was on return hose g	Non PM	5/5/2022
90606	Hardline crack ----- Chazrick Pang added [03/31/2022 09:45 AM] -----Weld hardline till new one come in	Non PM	5/5/2022
90283	Stu chi leaking ----- Chazrick Pang added [03/23/2022 10:02 PM] -----Replace wit new	Non PM	5/5/2022
90282	Hardline puka ----- Chazrick Pang added [03/23/2022 10:15 PM] -----Look in yard if we get spare, found one dat we can make v	Non PM	5/5/2022
89830	Hardline by ball valve missing bolt & clamps loose, put new bolt & tighten clamps. Top shape	Non PM	5/5/2022
89817	Missing bolts on ball valve ----- Chazrick Pang added [03/11/2022 09:06 PM] -----Find right bolts. Put in new bolts	Non PM	5/5/2022
89704	Hose for coupler cylinder blow, take off blown hose. Cap open lines.One more hose blow, take off dat one. Cap open lines. Hoses b	Non PM	5/5/2022
88546	Hydraulic hose loose, leaking. ----- Chazrick Pang added [02/10/2022 11:19 PM] -----Tighten hose fitting	Non PM	5/5/2022

88281	Ripper cracked ----- Bryan Ellis added [02/05/2022 10:49 AM] -----Weld ripper	Non PM	5/5/2022
88279	Coupler cracked ----- Bryan Ellis added [02/05/2022 10:47 AM] -----Found coupler cracks, cracked warranty weld	Non PM	5/5/2022
88148	Light on cab pointing down and inop ----- Bryan Ellis added [02/02/2022 09:08 AM] -----Wire cut splice wire, bolt rusted, instal r	Non PM	5/5/2022
91818	Hyd leak ----- Chazrick Pang added [04/27/2022 09:11 PM] -----Find um, change o ring	Non PM	5/5/2022
91747	Jumper hose on hammer blow ----- Chazrick Pang added [04/26/2022 09:53 PM] -----Put new one	Non PM	5/5/2022
91642	Hyd leak behind boom ----- Bryan Ellis added [04/24/2022 07:42 PM] -----Hose blew from boom to control manifold , take off h	Non PM	5/5/2022
91427	Broken glass ----- Bryan Ellis added [04/19/2022 10:07 AM] -----Replace bottom front glass	Non PM	5/5/2022
91390	Clamps on boom broken ----- Bryan Ellis added [04/18/2022 10:07 AM] -----Drill out bolts, weld broken clamp instal new clamps	Non PM	5/5/2022
91275	build up coupler ----- Dedrick Pang added [04/14/2022 05:12 PM] -----build up coupler	Non PM	5/5/2022
91266	Pressure side stuchi leaking frmale ----- Bryan Ellis added [04/14/2022 10:42 AM] -----Replace, and put hose back on	Non PM	5/5/2022
91217	Needs new step old steps high and cracked ----- Bryan Ellis added [04/13/2022 10:06 AM] -----Instal new step tested ok, weld	Non PM	5/5/2022
90866	Hardline clamp bolt broken ----- Chazrick Pang added [04/05/2022 10:09 PM] -----remove old, put new bolt	Non PM	5/5/2022
91686	PM2 Take oil samples for lab analysis - Engine oil Change engine oil and oil filter (including bypass filter) Replace fuel filter(s) and l	PI 1357 on 4/22/2022 5:	5/2/2022
90514	left control stick loose and bent ----- Dedrick Pang added [03/29/2022 10:18 AM] -----remove controller to adjust control rod. cl	Non PM	4/5/2022
90513	wedgelock coupler worn ----- Dedrick Pang added [03/29/2022 10:15 AM] -----build up ware on coupler	Non PM	4/5/2022
90200	final cover came loose ----- Dedrick Pang added [03/22/2022 11:01 AM] -----get new bolts to replace missing bolts. tighten up fi	Non PM	3/22/2022
90102	Bent step on track frame, missing 2 bolts ----- Chazrick Pang added [03/18/2022 07:58 PM] -----Bent frame back as straight as	Non PM	3/22/2022
90073	Trouble shoot hydraulic leak inside engine compartment, clean oil off all surrounding parts to see where oil coming from. Might hav	Non PM	3/22/2022
90035	regen light came on ----- Dedrick Pang added [03/17/2022 11:53 AM] -----hook up computer to force regen machine	Non PM	3/22/2022
89956	60 inch bucket wear plates peeling ----- Bryan Ellis added [03/16/2022 10:15 AM] -----Weld plates back, tested ok	Non PM	3/22/2022
89942	Hardline clamp looseHammer hose blow ----- Chazrick Pang added [03/16/2022 12:52 AM] -----Tighten clampReplace blown hos	Non PM	3/22/2022
89720	hose to bucket cylinders blown ----- Dedrick Pang added [03/10/2022 09:31 AM] -----cap back of machine from boom to move r	Non PM	3/22/2022
89703	Ripper boot worn ----- Chazrick Pang added [03/09/2022 09:36 PM] -----Take off old boot. Put new boot on	Non PM	3/22/2022
88608	Bucket tips worn, pins & retainers frozen ----- Chazrick Pang added [02/12/2022 05:01 PM] -----Cut off worn tips, burn out pins	Non PM	3/22/2022
88224	PM1 Record hourmeter reading and service performed Perform visual inspection Do operational checkout, including any attachmen	PI 1119 on 2/6/2022 6:C	2/28/2022
87467	Bucket pin keeper broken ----- Bryan Ellis added [01/15/2022 11:52 AM] -----Replace keeper pin	Non PM	1/24/2022
87394	Ripper boot worn ----- Bryan Ellis added [01/13/2022 09:36 PM] -----Replace ripper boot	Non PM	1/24/2022
87374	Belts loose ----- Bryan Ellis added [01/13/2022 09:31 AM] -----Adjust belts	Non PM	1/24/2022
87373	Swing brake hoses blew ----- Bryan Ellis added [01/13/2022 09:20 AM] -----Take hoses off, measure call in to d&m have picked	Non PM	1/24/2022
87213	clamp broken on stick cylinder ----- Dedrick Pang added [01/11/2022 09:14 AM] -----remove clamp to weld. put on new bolts a	Non PM	1/24/2022
87168	Stuchis leaking ----- Bryan Ellis added [01/10/2022 09:02 AM] -----Replace stitches	Non PM	1/24/2022
86868	Ball valve leaking ----- Bryan Ellis added [01/04/2022 09:17 AM] -----Take off hard lines, instal new ball valve, tested ok	Non PM	1/24/2022
86712	Wipers inop ----- Bryan Ellis added [12/22/2021 09:42 PM] -----Check switch, check contacts, need new contacts ----- Bryan E	Non PM	1/24/2022
87247	Step bent ----- Bryan Ellis added [01/11/2022 09:23 PM] -----Cut off step install new step	Non PM	1/24/2022

86600	WEDGE LOCK CRACKED. REPLACED PINS BUSHINGS AND WELDED CRACK. PAPE MACHINERY SEE INVOICE# 360741 PO# 24591	N 1059 on 1/11/2022 6:	1/12/2022
80561	DISPOSE OF DAMAGED ARM FROM REPAIRS ON WO#76597WORK PERFORMED BY PAPE MACHINERY KONA SEE INVOICE# 3604	N 1051 on 1/10/2022 6:	1/11/2022
86331	hammer/attachment issues. not firing continuous and stops. ----- Dedrick Pang added [12/14/2021 09:47 AM] -----3 way ball va	Non PM	1/3/2022
86015	Hoses and clamps loose ----- Bryan Ellis added [12/06/2021 09:15 AM] -----Tighten hoses and clamps on stick	Non PM	1/3/2022
85979	Coupler cracked Pape removing and take back to there shopPin is worn go look for pin ----- Derick Pang added [12/08/2021 09:29	Non PM	1/3/2022
85051	Hammer running fast then slows down have Pape check They said they never found anything checked all specs BUT they never ran	Non PM	1/3/2022
83452	Jd ink needs to be installed ----- Bryan Ellis added [10/06/2021 10:17 AM] -----Follow instructions, get serial numbers and ema	Non PM	1/3/2022
84807	Hydraulic leak ----- Rodney Sato added [11/02/2021 06:09 PM] -----Replace leaking stuchi coupler	Non PM	12/14/2021
85009	PM3 Take oil samples for lab analysis - House swing motor Planetary/Final Drive oil Hydraulic and/or Hydrostatic	PI 885 on 11/6/2021 2:2	11/15/2021
84826	DIAG SLOW HYDRAULICSPAPE SEE INVOICE# 360517 PO# 24324	N 899 on 11/12/2021 9:	11/15/2021
84602	Missing clamp for line ----- Rodney Sato added [10/28/2021 10:14 AM] -----Check missing clamp replace	Non PM	11/1/2021
84286	Replace ripper pin	Non PM	10/21/2021
83796	Missing track pad bolts ----- Rodney Sato added [10/12/2021 01:36 PM] -----Replace track pad bolts	Non PM	10/21/2021
83678	Go through plumbing clamps Go over machine	Non PM	10/21/2021
83409	Track roller worn , hydraulic leak ----- Rodney Sato added [10/05/2021 10:04 AM] -----Check rollers, check hydraulic leak replac	Non PM	10/21/2021
82087	Hydraucic leak ----- Rodney Sato added [09/07/2021 06:04 PM] ----- Checked leak found main suction hose leak reposition clarr	Non PM	10/21/2021
83460	REPLACE LEAKING HYDRAULIC HOSES 4/08/21 4872HRMAIN CONTROL VALVE TO JUMPER HOSES (2)CASE DRAIN HOSE ON P	N 798 on 10/20/2021 3:	10/21/2021
83454	LINE BORE AND REPLACE BOOM BASE MOUNTING BUSHINGS, PINS, REPAIR CRACK AT BOOM FOOT AREA 2/22/21 4872HRSLIN	N 798 on 10/20/2021 3:	10/21/2021
83411	Hyd leak by pump ----- Bryan Ellis added [10/05/2021 10:12 AM] -----Prong cut replace oring	Non PM	10/14/2021
81772	Keeper pin on bucket coming off ----- Bryan Ellis added [09/01/2021 10:30 AM] -----Replace keeper pin	Non PM	10/4/2021
79081	CLEAN DPF FILTER AND REPLACE DP SENSOR.QUOTEPAPE MACHINERY SEE INVOICE# 360353 PO#23644	N 741 on 9/27/2021 1:4	9/28/2021
82842	PM1 Record hourmeter reading and service performed Perform visual inspection Do operational checkout, including any at	PI 722 on 9/23/2021 2:C	9/27/2021
81615	Bucket tip fell off gonna get spare bucket	Non PM	9/7/2021
81530	Need panels put back on ----- Bryan Ellis added [08/27/2021 10:25 AM] -----Instal panels backmon	Non PM	9/7/2021
81215	Machine throwing codes ----- Bryan Ellis added [08/20/2021 10:43 PM] -----Trouble shoot overheat code, check wires check che	Non PM	9/7/2021
81004	Trouble shooting hyd leak on top control valve Found after market pressure sensor to turn on hammer lube blowing oil	Non PM	9/7/2021
81953	Hydraulic leak ----- Rodney Sato added [09/03/2021 09:49 AM] -----Replace stuchi coupler	Non PM	9/7/2021
81703	Missing bucket tips ----- Rodney Sato added [08/31/2021 01:28 PM] -----Clean off adapters and replace tips	Non PM	9/7/2021
80724	Leaking hyd ----- Bryan Ellis added [08/12/2021 10:16 AM] -----Hard line on boom leaking, tightened fitting	Non PM	8/23/2021
80949	Hydraulic leaks ----- Rodney Sato added [08/17/2021 07:24 AM] -----Check leak found auxiliary line leaking. Loosen line to rem	Non PM	8/23/2021
80667	Track pad bolts loose ----- Bryan Ellis added [08/11/2021 10:23 AM] -----Tighten track pads bolts	Non PM	8/23/2021
78702	Has 11989-4 code ----- Bryan Ellis added [07/07/2021 10:04 AM] -----T/s, check power good, check solenoid, check plug, take p	Non PM	8/10/2021
78232	Throwing codes ----- Bryan Ellis added [06/28/2021 01:25 AM] -----Check codes, plug computer, t/s codes, run regen, regen co	Non PM	8/10/2021
78110	DPF filter getting plugged ----- Bryan Ellis added [06/25/2021 10:27 AM] -----Hook up computer, run manual forced regen, need	Non PM	8/10/2021

79956	Coolant leak by turbo ----- Bryan Ellis added [07/29/2021 10:09 AM] -----Replace clamps, not leaking	Non PM	8/10/2021
79938	Loose bolts ----- Rodney Sato added [07/29/2021 07:07 AM] -----Replace missing clamps for auxiliary line	Non PM	8/10/2021
79910	Hydraulic leak ----- Rodney Sato added [07/28/2021 04:52 PM] -----Replace broken auxiliary line ----- Rodney Sato added [07/28/2021 04:52 PM] -----Replace broken auxiliary line	Non PM	8/10/2021
79888	Hkx pressure side hard line cracked ----- Bryan Ellis added [07/28/2021 12:18 PM] -----Take off hard line weld hard line, put back on	Non PM	8/10/2021
79761	Hkx clamps coming loose ----- Bryan Ellis added [07/26/2021 10:12 AM] -----Drill out broken bolts, replace clamps	Non PM	8/10/2021
79541	Belts loose ----- Bryan Ellis added [07/22/2021 10:28 AM] -----Adjust belts	Non PM	7/27/2021
79503	Hkx line cracked ----- Bryan Ellis added [07/21/2021 04:41 PM] -----Take off hardline, cut and weld hardline put back on, tested	Non PM	7/27/2021
79441	Fire extinguisher falling off ----- Bryan Ellis added [07/20/2021 11:30 AM] -----Remount bracket and fire extinguisher	Non PM	7/27/2021
79421	Hydraulic leak ----- Rodney Sato added [07/20/2021 07:17 AM] -----Replace leaking stuchi coupler, and seal on auxiliary line	Non PM	7/27/2021
78986	Multi clamp on back of boom loose ----- Bryan Ellis added [07/11/2021 11:52 PM] -----Bolt backed out, take off clamps above, reattach	Non PM	7/12/2021
78520	Hydraulic leaks ----- Rodney Sato added [07/01/2021 07:56 PM] -----Check hydraulic leak, replace cut seal on auxiliary line	Non PM	7/8/2021
78470	Hydraulic leak ----- Rodney Sato added [07/01/2021 10:12 AM] -----Check leak found leak on auxiliary return line replaced leaking	Non PM	7/8/2021
78064	Machine not regen ----- Bryan Ellis added [06/24/2021 10:17 AM] -----Hook up computer, enable forced regen, machine perform	Non PM	7/8/2021
77508	Acinop ----- Bryan Ellis added [06/11/2021 12:28 PM] -----Check charge, no charge, fill refrigerant, compressor not kicking on, c	Non PM	7/8/2021
77474	AC inop ----- Rodney Sato added [06/10/2021 05:35 PM] -----TS why not working found no charge. Evacuate system and charge	Non PM	7/8/2021
76597	REPLACE STICK CRACK DAMAGED BEYOND REPAIR 4872HRSPAPE MACHINERY KONA SOURCED USED STICK, REMOVED BROKEN MACHINERY	Non PM 366 on 2/8/2021 7:15	6/4/2021
76593	REPLACE LEFT IDLER 4872HRSWORK PERFORMED BY PAPE MACHINERY KONA, IDLER SUPPLIED BY GBI SEE INVOICE# 360124	Non PM 366 on 2/8/2021 7:15	6/4/2021
76580	REPLACE CAB WIRING HARNESS 4872HRSWORK PERFORMED BY PAPE MACHINERY KONA SEE INVOICE# 360084 PO#23103	Non PM 366 on 2/8/2021 7:15	5/28/2021
72423	Go over with Randy at Pape on back log 470 at shop	Non PM	2/17/2021
72379	AC hose worn for high pressure side ----- Dedrick Pang added [02/11/2021 09:35 AM] -----remove panels to get to compressor	Non PM	2/17/2021
72263	AC hose cracked by compressor ----- Dedrick Pang added [02/09/2021 08:56 AM] -----remove panels to get to hose. remove hose	Non PM	2/17/2021
72258	Needs low side hose installed ----- Bryan Ellis added [02/09/2021 08:36 AM] -----Take panels off, take all clamps off, route hose	Non PM	2/17/2021
72146	Can't regen, needs regen ----- Bryan Ellis added [02/05/2021 08:53 AM] -----Hook up computer, run forced regen	Non PM	2/17/2021
72086	throwing codes and derating ----- Dedrick Pang added [02/04/2021 09:24 AM] -----hook up computer. check codes. no active codes	Non PM	2/17/2021
71677	machine parked ----- Dedrick Pang added [01/26/2021 09:21 AM] -----look for hydraulic leaks. need to order a few hoses.check	Non PM	2/17/2021
72160	PM2 Take oil samples for lab analysis - Engine oil Change engine oil and oil filter (including bypass filter) Replace fuel filter(s) and	Non PM 366 on 2/8/2021 7:15	2/17/2021
71986	Ac needs hoses changed ----- Bryan Ellis added [02/02/2021 08:49 AM] -----Drop panels, take off hi side hose and drier off, ins	Non PM	2/3/2021
71820	Hyd leak ----- Bryan Ellis added [01/28/2021 09:01 AM] -----Change out orings on pump, tested ok	Non PM	2/1/2021
71614	Ac not blowing cold ----- Bryan Ellis added [01/25/2021 08:47 AM] -----Take off panels to see hoses, fill with nitrogen to look for	Non PM	1/25/2021
71307	Need new coupler pin ----- Bryan Ellis added [01/16/2021 01:35 PM] -----Take off old coupler pin, put new shims and rubber ori	Non PM	1/25/2021
71306	Radiator dirty ----- Bryan Ellis added [01/16/2021 01:34 PM] -----Blowout and clean radiator	Non PM	1/25/2021
71238	Batteries dead ----- Bryan Ellis added [01/15/2021 08:36 AM] -----Change batteries, tested ok	Non PM	1/25/2021
71188	Battery dead ----- Bryan Ellis added [01/14/2021 08:50 AM] -----Jump machine, orde new battery	Non PM	1/25/2021
71619	Broken glass ----- Bryan Ellis added [01/25/2021 08:57 AM] -----Replace front broken glass	Non PM	1/25/2021

71617	AC inop ----- Dedrick Pang added [01/25/2021 09:01 AM] -----troubleshoot unit. check refrigerant charge. check for leaks. charg	Non PM	1/25/2021
71194	machine won't start ----- Dedrick Pang added [01/14/2021 09:29 AM] -----check voltage. battery dead. let batteries charge and	Non PM	1/25/2021
70248	AC inop ----- Dedrick Pang added [12/16/2020 08:45 AM] -----troubleshoot AC not blowing. check fuses. check codes on monito	Non PM	1/25/2021
71071	hand rail broke off ----- Dedrick Pang added [01/12/2021 09:35 AM] -----bolts snapped. drill out broken bolts. put on rail with ne	Non PM	1/12/2021
71019	look for troubleshooting guide for AC and disassembly/assembly manual ----- Dedrick Pang added [01/11/2021 08:59 AM] -----	Non PM	1/12/2021
71017	Ac not blowing cold, has code 51 ----- Bryan Ellis added [01/11/2021 08:43 AM] -----Check fuse, check power, check connection	Non PM	1/12/2021
71016	Blower motor inop ----- Bryan Ellis added [01/11/2021 08:40 AM] -----Take seat out, take apart cab to get to blower, take out bl	Non PM	1/12/2021
70971	Cracked hxx line again ----- Bryan Ellis added [01/09/2021 09:23 AM] -----Weld crack on hardline, tested ok	Non PM	1/12/2021
70916	needs to regen ----- Dedrick Pang added [01/08/2021 09:27 AM] -----force regen	Non PM	1/12/2021
70915	hydraulic leaking on hardline ----- Dedrick Pang added [01/08/2021 09:25 AM] -----remove hardline for auxiliary hxx and weld h	Non PM	1/12/2021
70911	Hyd leak on stick ----- Bryan Ellis added [01/08/2021 08:47 AM] -----Found cracked hardline, take hammer off, take hxx hard lin	Non PM	1/12/2021
70855	hammer not firing ----- Dedrick Pang added [01/07/2021 09:11 AM] -----check ball valves if open on stick. check couplers if loos	Non PM	1/12/2021
70854	lift cylinder hardline clamps missing bolts and cracked ----- Dedrick Pang added [01/07/2021 09:05 AM] -----remove both clamps	Non PM	1/12/2021
70853	Windshield washer fluid reservoir fell off ----- Bryan Ellis added [01/07/2021 08:49 AM] -----Retrieve reservoir and clamp, install	Non PM	1/12/2021
70852	Boom clamps missing bolts and one broken clamp ----- Bryan Ellis added [01/07/2021 08:48 AM] -----Instal new bolts and order	Non PM	1/12/2021
70706	Coupler cracked ----- Bryan Ellis added [01/05/2021 09:02 AM] -----Weld coupler	Non PM	1/6/2021
70694	wedgelock coupler cracked open ----- Dedrick Pang added [01/05/2021 08:56 AM] -----air arc coupler crack open and weld. crack	Non PM	1/6/2021
70775	change coupler ----- Dedrick Pang added [01/06/2021 09:04 AM] -----change wedgelock	Non PM	1/6/2021
70768	Coupler cracked ----- Bryan Ellis added [01/06/2021 08:44 AM] -----Pull pins, take off old coupler, take off hyd hoses for couplin	Non PM	1/6/2021
70538	hydraulic leaking oil in coupler ----- Dedrick Pang added [12/23/2020 12:21 PM] -----remove fitting for wedgelock coupler and re	Non PM	1/6/2021
70472	wedge lock coupler hose leaking ----- Dedrick Pang added [12/22/2020 09:33 AM] -----remove safety latch hose and replace bos	Non PM	1/6/2021
70411	Bucket adapter cracked ----- Bryan Ellis added [12/21/2020 08:36 AM] -----Air ark crack to get ready for weld ----- Bryan Ellis a	Non PM	1/6/2021
70291	Light missing on boom ----- Bryan Ellis added [12/17/2020 08:47 AM] -----Replace light, connect wires, tested ok	Non PM	1/6/2021
70196	hydraulic leaking by ball valve ----- Dedrick Pang added [12/15/2020 09:13 AM] -----clean oil to see where oil dripping from. stu	Non PM	12/16/2020
69793	coupler cracked ----- Dedrick Pang added [12/05/2020 09:21 AM] -----start prepping machine to weld on saturday. take off hose	Non PM	12/16/2020
69789	Hxx line clamp came off ----- Bryan Ellis added [12/05/2020 09:14 AM] -----Drill out broken bolt, tap hole, install new fitting	Non PM	12/16/2020
69691	machine broke down. cant move ----- Dedrick Pang added [12/03/2020 09:05 AM] -----check fuses. fuse blown. put in resettabl	Non PM	12/16/2020
69684	Machine has no functions ----- Bryan Ellis added [12/03/2020 08:47 AM] -----Plug computer in, pull codes, troubleshoot codes, c	Non PM	12/16/2020
69644	hydraulic leaking on hardline right side ----- Dedrick Pang added [12/02/2020 09:18 AM] -----remove hardline and hose to weld	Non PM	12/2/2020
69632	Hxx hard line cracked, leaking hyd oil ----- Bryan Ellis added [12/02/2020 08:54 AM] -----Take hxx line off, weld crack, install hxx	Non PM	12/2/2020
69149	Hyd leak on control valve replace o ring	Non PM	11/25/2020
69147	force regen machine ----- Dedrick Pang added [11/17/2020 09:15 AM] -----force regen machine ----- Derick Pang added [11/1	Non PM	11/25/2020
69385	Cracked adapter,crack on inner bucket ----- Bryan Ellis added [11/23/2020 09:10 AM] -----Weld bucket	Non PM	11/25/2020
69142	Needs regen ----- Bryan Ellis added [11/17/2020 08:49 AM] -----Hook up computer, perform forced regen	Non PM	11/25/2020

68993	Hyd leak ----- Bryan Ellis added [11/13/2020 08:58 AM] -----Oring cut on stuchi from coming loose and tighten back up. Replace	Non PM	11/25/2020
67466	Fix grease lines	Non PM	11/5/2020
67323	Cracks on bucket ----- Bryan Ellis added [10/29/2020 10:00 AM] -----Air ark cracks out, weld bucket	Non PM	11/5/2020
67124	boom to stick pin walking ----- Dedrick Pang added [10/23/2020 10:18 AM] -----ear tab broke off and pin spinning. reposition pin	Non PM	11/5/2020
67123	Ac not blowing cold ----- Bryan Ellis added [10/23/2020 10:18 AM] -----Check fuse, check belt, found belt loose, idler frozen, repl	Non PM	11/5/2020
66984	Hyd leak ----- Bryan Ellis added [10/20/2020 10:19 AM] -----Hose leaking from boom, to control manifold, have hose in truck, re	Non PM	11/5/2020
67388	Bucket keeper pin fell out ----- Bryan Ellis added [10/30/2020 10:19 AM] -----Install new bucket keeper pin	Non PM	11/5/2020
67326	60" bucket cracked open at ears both sides ----- Dedrick Pang added [10/29/2020 10:16 AM] -----air arc out cracks and weld cra	Non PM	11/5/2020
67129	AC inop ----- Dedrick Pang added [10/23/2020 10:37 AM] -----help troubleshoot AC not working. check fuses. check belt. check	Non PM	11/5/2020
66532	seatbelt inop. twisted and jammed ----- Dedrick Pang added [10/09/2020 06:17 PM] -----remove seatbelt to try and fix. cannot f	Non PM	10/27/2020
66941	blow out radiator ----- Dedrick Pang added [10/19/2020 10:31 AM] -----blow out radiator. fix reverse fan switch. test switch and	Non PM	10/20/2020
66809	coolant leaking from reservoir ----- Dedrick Pang added [10/15/2020 10:30 AM] -----hose leaking under over flow reservoir. ren	Non PM	10/20/2020
66670	bolt broken off of bucket ----- Dedrick Pang added [10/13/2020 10:21 AM] -----replace bolt and weld nut on	Non PM	10/13/2020
66446	machine won't regen because of an engine code ----- Dedrick Pang added [10/08/2020 09:56 AM] -----hook up computer to che	Non PM	10/13/2020
64873	Pm 2 ** SEE WO 64890 - WAS COMPLETED ON THIS WOChange oil filter Drain/refill eng oil Change fuel filters Change hyd. Filter	PI 4507 on 8/31/2020 10	10/7/2020
66267	hydraulic leaking on wedge lock coupler ----- Dedrick Pang added [10/03/2020 04:08 PM] -----hose blown on coupler. grab hose	Non PM	10/7/2020
66160	Trouble with regen ----- Bryan Ellis added [10/01/2020 08:19 PM] -----Plug computer to force regen	Non PM	10/7/2020
65715	machine shut down, cannot move ----- Dedrick Pang added [09/21/2020 08:49 PM] -----plug in computer to machine to check c	Non PM	10/7/2020
64975	Chair broken and ripped ----- Bryan Ellis added [09/01/2020 06:44 PM] -----Replace chair	Non PM	10/7/2020
65644	Radiator dirty ----- Bryan Ellis added [09/18/2020 05:31 PM] -----Blow out radiator	Non PM	9/29/2020
65643	Clamp on back of boom broken ----- Bryan Ellis added [09/18/2020 05:30 PM] -----Stud broken inside, drill out and order new cl	Non PM	9/29/2020
65510	Machine keep trying to regen ----- Derick Pang added [09/16/2020 09:52 AM] -----Have AMI come out and trouble shoot Found	Non PM	9/29/2020
65572	REPAIR REGEN SYSTEM 4513HRSAMERICAN MACHINERY KONA REPLACED MAIN CONTROLLER SEE INVOICE# 308405 PO#2157	PI 4513 on 9/15/2020 10	9/29/2020
64890	PM2 Take oil samples for lab analysis - Engine oil Change engine oil and oil filter (including bypass filter) Replace fuel filter(s) ar	PI 4507 on 8/31/2020 10	9/23/2020
65148	Horn in op ----- Bryan Ellis added [09/04/2020 05:57 PM] -----Replace horn	Non PM	9/14/2020
64523	HKX clamp mount broke off boom on the back ----- Dedrick Pang added [08/21/2020 11:12 AM] -----remove hardline and weld l	Non PM	9/2/2020
64520	machine derating ----- Dedrick Pang added [08/21/2020 10:56 AM] -----hook up computer to check for codes. machine needs to	Non PM	9/2/2020
64981	change seat ----- Dedrick Pang added [09/01/2020 06:56 PM] -----change seat	Non PM	9/2/2020
64092	HKX hardline clamp fell off boom. tap threads and put clamp back on	Non PM	8/19/2020
63715	hydraulic leaking from stucchi. ----- Dedrick Pang added [08/04/2020 10:25 AM] -----swap stucchi's with new	Non PM	8/19/2020
63676	AC not blowing hard ----- Bryan Ellis added [08/04/2020 09:57 AM] -----Check filter,drop pans underneath cab, evap plugged ---	Non PM	8/19/2020
63585	wedge lock pin broken off for wedge ----- Dedrick Pang added [08/01/2020 10:29 AM] -----remove pin holding wedge. remove c	Non PM	8/19/2020
63462	no motion alarm ----- Dedrick Pang added [07/30/2020 10:47 AM] -----remove panels to look for motion alarm and connect new	Non PM	8/19/2020
63461	Loose ac belt ----- Bryan Ellis added [07/30/2020 10:47 AM] -----Adjust ac belt	Non PM	8/19/2020

63404	Hyd leak ----- Bryan Ellis added [07/29/2020 10:15 AM] -----Hydraulic hose blown on pilot control manifold, have hose made at	Non PM	8/19/2020
63121	machine shut down. hydraulics inop ----- Dedrick Pang added [07/22/2020 08:18 PM] -----troubleshoot machine codes. check fu	Non PM	8/19/2020
62907	cracks on coupler. major. ----- Dedrick Pang added [07/16/2020 08:59 PM] -----remove hammer from machine. prep coupler for	Non PM	8/19/2020
64253	coupler cracked again ----- Dedrick Pang added [08/15/2020 04:14 PM] -----cut out coupler and weld. than build up play in jaw	Non PM	8/19/2020
64152	machine overheating ----- Dedrick Pang added [08/13/2020 10:53 AM] -----remove cover to radiator and blow out radiator and i	Non PM	8/19/2020
64089	Clamp fell off on end of boom ----- Bryan Ellis added [08/12/2020 10:13 AM] -----Drill bolt out, tap and install New clamp and ha	Non PM	8/19/2020
64019	wedge lock coupler cracked again ----- Dedrick Pang added [08/11/2020 11:15 AM] -----cut and weld weld coupler	Non PM	8/19/2020
63970	Coupler crack ----- Bryan Ellis added [08/10/2020 11:09 AM] -----Air ark and weld crack	Non PM	8/19/2020
63893	Found clamps loose on hardline ----- Bryan Ellis added [08/07/2020 01:31 PM] -----Tightened clamps to spec	Non PM	8/19/2020
63810	build up weld wedge ----- Dedrick Pang added [08/06/2020 10:12 AM] -----build up wedge	Non PM	8/19/2020
63584	coupler has cracks on jaw again ----- Dedrick Pang added [08/01/2020 10:27 AM] -----cut cracks out and weld cracks	Non PM	8/3/2020
63089	Hydraulic leak ----- Rodney Sato added [07/22/2020 09:13 AM] -----Replace leaking stuchi coupler	Non PM	8/3/2020
62876	Horn inop ----- Bryan Ellis added [07/16/2020 08:58 PM] -----Found rubbed out wire, repair wire, horn good	Non PM	8/3/2020
62859	Tighten up clams	Non PM	8/3/2020
62702	Hydraulic leak ----- Bryan Ellis added [07/13/2020 09:58 AM] -----Stuchi couplers leaking replace left side and change oring on	Non PM	8/3/2020
62534	Final cover bolts fell off ----- Bryan Ellis added [07/09/2020 12:31 PM] -----Weld new mounting bracket for new bolts on final co	Non PM	8/3/2020
61337	PM1Record hourmeter reading and service performedPerform visual inspectionDo operational checkout, including any attachmentsC	PI 4252 on 6/12/2020 9:	6/17/2020
59596	Hydraulic leak ----- Rodney Sato added [04/23/2020 11:00 PM] -----Replace leaking quick coupler hose	Non PM	4/28/2020
58647	Clamps broke off ----- Derick Pang added [03/20/2020 09:15 AM] -----New bolt andclamp	Non PM	3/25/2020
56773	Loose track pad ----- Rodney Sato added [01/30/2020 09:44 PM] -----Replace worn track pad bolts	Non PM	2/5/2020
56234	Cracks on coupler ----- Rodney Sato added [01/18/2020 05:08 PM] -----Pressure wash coupler ----- Dedrick Pang added [01/	Non PM	1/29/2020
56138	Hydraulic leak ----- Rodney Sato added [01/17/2020 06:07 AM] -----TS hydraulic leaks found lines leaking parts to be ordered	Non PM	1/29/2020
55562	BOOM TO ARM PIN LOOSE - AMERICAN MACHINERY PERFORMED CORRECTION PER ATTACHED SEE INVOICE# 307721 PO# 196	N 4167 on 11/6/2019 3:	1/17/2020
54474	Hyd leak coupler to return came off	Non PM	12/17/2019
54248	hydraulic leak on coupler ----- Dedrick Pang added [12/01/2019 11:12 PM] -----remove blown hose from coupler for safety lever	Non PM	12/5/2019
54247	hardline clamp fell off boom ----- Dedrick Pang added [12/01/2019 11:09 PM] -----put hardline clamp back on hardline	Non PM	12/5/2019
53888	Hydraulic leak ----- Rodney Sato added [11/21/2019 05:49 AM] -----TS hydraulic leak under valve body, found leaks on auxiliary	Non PM	12/5/2019
53221	Hydraulic leak ----- Rodney Sato added [11/06/2019 09:05 AM] -----Replace leaking stuchi coupler	Non PM	11/20/2019
53053	AMI to check boom to stick pin ----- Rodney Sato added [11/04/2019 05:37 AM] -----Load up stand at Waikoloa yard for AMI.	Non PM	11/20/2019
52838	Pin arm to boom spun broke keeper ----- Derick Pang added [10/30/2019 09:53 AM] -----Had cleaned up mechanic put togethe	Non PM	11/20/2019
52826	Leaking hydraulic line ----- Rodney Sato added [10/30/2019 07:14 AM] -----Replace worn auxiliary hose, remove cracked line to	Non PM	11/20/2019
52761	Hydraulic leak ----- Rodney Sato added [10/29/2019 06:50 AM] -----Remove cracked hydraulic line , replace with temporary line	Non PM	11/20/2019
53526	Loose clamps ----- Rodney Sato added [11/13/2019 09:03 AM] -----Extract broken bolts for auxiliary lines . Install new clamps	Non PM	11/20/2019
53345	Ac pulley worn ----- Rodney Sato added [11/07/2019 09:22 PM] -----Replace worn pulley	Non PM	11/20/2019

52998	Missing bucket pin lock bolt ----- Rodney Sato added [11/01/2019 10:57 AM] -----Line up pin and install new bolt	Non PM		11/6/2019
52899	Hydraulic leak ----- Rodney Sato added [10/31/2019 07:49 AM] -----Pressure wash ,TS hydraulic leak on control valve.Repair le	Non PM		11/6/2019
52050	Cracks on wedge lock Help remove and clean so Dedrick can weld Help put on	Non PM		10/29/2019
51387	Hydraulic leak ----- Rodney Sato added [10/01/2019 06:56 AM] -----Hydraulic leak on auxiliary line on stick ,pick up temporary l	Non PM		10/29/2019
50135	AC inop ----- Rodney Sato added [09/08/2019 06:45 PM] -----TS why ac not working. Found belt broken and compressor frozen	Non PM		10/29/2019
52340	Hydraulic leak ----- Rodney Sato added [10/18/2019 05:57 PM] -----Replace leaking seal on control valve line	Non PM		10/29/2019
52288	Hydraulic leak ----- Rodney Sato added [10/18/2019 09:27 AM] -----TS hydraulic leak found quick coupler hose leaking.Parts to	Non PM		10/29/2019
52057	coupler has cracks ----- Dedrick Pang added [10/13/2019 01:49 AM] -----remove coupler from machine. cut out cracks and weld	Non PM		10/29/2019
52010	Hydraulic leak ----- Rodney Sato added [10/11/2019 05:50 PM] -----Replace leaking seal on auxiliary line on stick and boom	Non PM		10/29/2019
51984	Loose tip pin ----- Rodney Sato added [10/11/2019 09:41 AM] -----Replace loose bucket tip pins	Non PM		10/29/2019
51840	hydraulic leak on stick ----- Dedrick Pang added [10/09/2019 10:52 AM] -----help change hardline on boom to stick for auxiliary	Non PM		10/29/2019
51823	Hydraulic leak ----- Rodney Sato added [10/09/2019 06:50 AM] -----Replace blown seal on auxiliary line	Non PM		10/29/2019
51074	PM4PM1 Record hourmeter reading and service performed Perform visual inspection Do operational check PI 4026 on 9/30/2019 3:			10/14/2019
51101	Hydraulic leak in pump cabinets ----- Rodney Sato added [09/25/2019 07:07 AM] -----Replace seal on pressure hose to control	Non PM		10/2/2019
50926	Blown auxiliary system hose ----- Rodney Sato added [09/20/2019 02:43 PM] -----Remove blown hose have new hose made, an	Non PM		10/2/2019
50858	AC not cold ----- Rodney Sato added [09/20/2019 06:53 AM] -----Check for leaks found valve leaking parts ordered ----- Rodn	Non PM		10/2/2019
50797	Missing lock bolt ----- Rodney Sato added [09/19/2019 07:03 AM] -----Line up bucket pin and install new lock bolt	Non PM		10/2/2019
50480	----- Dedrick Pang added [09/13/2019 10:17 AM] -----change broken and bent track pad bolts	Non PM		9/13/2019
50434	Grease lines broken ----- Rodney Sato added [09/13/2019 07:17 AM] -----Repair and replace broken grease lines	Non PM		9/13/2019
50249	Loose bolts on auxiliary valve ----- Rodney Sato added [09/10/2019 09:58 AM] -----Replace missing clamps on auxiliary line nea	Non PM		9/12/2019
50059	Hammer slow ----- Rodney Sato added [09/06/2019 09:54 AM] -----Checked why slow	Non PM		9/12/2019
49431	----- Derick Pang added [08/25/2019 10:56 PM] -----Have hose mad3 a take to job and repair	Non PM		9/4/2019
49125	Auxiliary valve keeps closing ----- Rodney Sato added [08/20/2019 06:50 AM] -----Replace worn out snap ring with new ring	Non PM		9/4/2019
49694	Leaking hydraulic cylinder ----- Rodney Sato added [08/29/2019 09:06 PM] -----TS hydraulic leak on bucket cylinder ,replace lea	Non PM		9/4/2019
49553	----- Rodney Sato added [08/27/2019 10:45 PM] -----Replace temporary auxiliary line with new line and valves	Non PM		9/4/2019
49496	Leaking stuchi coupler ----- Rodney Sato added [08/27/2019 07:56 AM] -----Replace leaking stuchi coupler	Non PM		9/4/2019
49531	PERFORM PIP 18TX867 3136HRSAMERICAN MACHINERY UPDATED ECM SOFTWARE AND REPLACED COOLANT PLUG PER PIP WA N 3874 on 8/30/2019 5:			9/3/2019
48985	Hydraulic leak on quick coupler ----- Rodney Sato added [08/16/2019 10:49 AM] -----Replace broken hose for coupler	Non PM		8/21/2019
48917	Hydraulic leak ----- Rodney Sato added [08/16/2019 07:00 AM] -----TS hydraulic leak,found broken hose for quick coupler,rep	Non PM		8/21/2019
48754	Operator can not remove stuchi coupler ----- Rodney Sato added [08/13/2019 09:37 PM] -----Remove stuchi coupler and replac	Non PM		8/14/2019
48407	----- Derick Pang added [08/07/2019 11:47 AM] -----Aux tubes moving reset and tighten	Non PM		8/14/2019
47961	AC warm ----- Rodney Sato added [07/30/2019 07:46 PM] -----Check charge,recharge and test	Non PM		8/7/2019
47130	PM2PM1 Record hourmeter reading and service performed Perform visual inspection Do operational checkou PI 3654 on 7/20/2019 8:			7/31/2019
46788	----- Dedrick Pang added [07/10/2019 09:26 AM] -----remove cracked hardline from stick for auxiliary hose and replace tempor	Non PM		7/24/2019

46752	Check hydraulic leak on auxiliary line ----- Rodney Sato added [07/10/2019 06:54 AM] -----Replace cracked line with temporary	Non PM	7/24/2019
47215	Leaking stuchi ----- Rodney Sato added [07/18/2019 07:09 AM] -----Replace leaking stuchi coupler	Non PM	7/18/2019
46668	----- Dedrick Pang added [07/08/2019 12:29 PM] -----weld back hardline hose for auxiliary	Non PM	7/18/2019
46666	----- Dedrick Pang added [07/08/2019 12:18 PM] -----put on clamp on stick cylinder on boom. with new bolts	Non PM	7/18/2019
46574	reweld cracked hardline on auxiliary pressure side hose	Non PM	7/18/2019
46572	remove hardline for auxiliary on right side pressure hose. weld crack on hardline. put back on and test	Non PM	7/18/2019
46393	Repair broken grease fittings, straighten bent step	Non PM	7/18/2019
46222	install broken clamp on boom lift cylinder	Non PM	7/18/2019
46288	Extract broken bolts, and straighten bent step	Non PM	7/2/2019
46145	Repair broken grease lines and fittings	Non PM	7/2/2019
45962	Straighten bent steps remove lower steps and move top steps down Extract broken bolts	Non PM	7/2/2019
45970	Help remove coupler need to be welded	Non PM	7/2/2019
46007	remove wedge lock coupler to weld. pin bucket to machine. remove wedge and cylinder. air arc and weld cracks in coupler for jaw	Non PM	7/2/2019
45213	remove broken clamp on lift cylinder and order new clamp	Non PM	7/2/2019
46020	Remove cracked quick coupler and pin on bucket Install repaired coupler	Non PM	6/26/2019
45842	help fix grease lines on h-link	Non PM	6/26/2019
45841	fix rear step broken off	Non PM	6/26/2019
45785	Repair broken grease lines	Non PM	6/26/2019
44971	Replace worn out ripper tip	Non PM	6/26/2019
44695	Replace leaking stuchi coupler, and repair broken grease lines	Non PM	6/26/2019
42785	Repair hydraulic leak hose to wedge lock blown get made replaced	Non PM	5/15/2019
43014	troubleshoot AC. blower shuts off once in awhile. check if switch is good. switch works properly and doesn't cut out. have to put tog	Non PM	5/14/2019
43112	PM1 Record hourmeter reading and service performed Perform visual inspection Do operational checkout, including any	PI 3311 on 4/26/2019 3:	5/8/2019
43038	RESHIM WEDGLECK COUPLER TO ARM FOR SIDE TO SIDE MOVEMENT 3205HRSREPLACE LEAKING STUCHHI COUPLERSTIGHTEN	N 3311 on 4/26/2019 3:	5/2/2019
42683	keeper bolt missing for coupler pin. remove bar stuck in for temporary and put in new bolt	Non PM	4/22/2019
41812	Hyd leak Auxiliary tube at join to valve replace o ring	Non PM	4/3/2019
38790	REPLACE ENGINE 10/31/18 3204HRSAMERICAN MACHINERY REPLACED ENGINE WARRANTIED BY JOHN DEERE FOUND COMBU	N 3198 on 10/30/2018 1:	1/29/2019
38129	REPAIR REGEN 3204HRSREPLACE HYDRAULIC SHOCK HOSE RIGHT SIDEAMERICAN MACHINERY KONA REPLACED DIFFERENTIA	N 3198 on 10/30/2018 1:	1/18/2019
35107	T/S overheating ,check for leaks and possible comparison leak Continue to T/S	Non PM	11/14/2018
34693	Machine say over heat but didn't check physically hot talk to randy about It we gonna monitor Cool down pull both sensor wires	Non PM	11/14/2018
34342	Trouble shoot auto lube pump spin try pump lines to clean out	Non PM	11/14/2018
34870	Check quick coupler for wear ,found with in spec.	Non PM	10/30/2018
34772	Replace worn bucket tip pins	Non PM	10/30/2018
34622	Help get fitting for hyd repair	Non PM	10/30/2018

34579	Replace lock bolt on bucket pin	Non PM		10/30/2018
34268	Replace missing bolts for auxiliary line mounts,repair leak on boom cylinder line	Non PM		10/30/2018
35022	troubleshoot machine over heating. check physical temperatures and it's all good. remove each temperature sensor wires till the ga	Non PM		10/30/2018
35021	fix broken grease line on boom and on stick. try troubleshooting why grease isn't coming out of lift cylinder joints.	Non PM		10/30/2018
34873	Replace mirror	Non PM		10/30/2018
34818	code coming up for fuel level low but fuel is full. test sending unit and unit is working. check wires and found a wire under the fuel t	Non PM		10/30/2018
34773	Replace missing bucket tip pins	Non PM		10/30/2018
34399	auto lube not working. troubleshoot pump. plugged line somewhere. use my grease to manually grease stick pin and stick cylinder p	Non PM		10/19/2018
34391	Back log repair broken grease lines to dog link	Non PM		10/19/2018
34212	Walked marching out from back of site to frond for pick up. Got machine, bucket, and hammer ready for transport. Also checked for	Non PM		10/19/2018
34176	fix hydraulic leak on valve body. remove panels to get to hose leaking out. remove fitting for auxiliary hose and change o-ring. put f	Non PM		10/19/2018
33378	Weld cracks on quick coupler	Non PM		10/10/2018
33167	T/S hydraulic leak on auxiliary line, replace oring seal	Non PM		10/10/2018
33331	change hydraulic hose to wedge lock cylinder. hose pinched	Non PM		10/10/2018
33327	Reinstall stick cylinder pin and replace missing lock bolt	Non PM		10/10/2018
32887	PM3PM1 Record hourmeter reading and service performed Perform visual inspection Do operational checkout, including an	PI 3055 on 9/15/2018 1:		9/19/2018
33015	Check coolent leak found hose clamp loose tighten	Non PM		9/19/2018
32985	change all 4 stuchis on hammer and machine from leaking	Non PM		9/19/2018
32982	cut open and weld cracks on coupler. and build up play in coupler jaws	Non PM		9/19/2018
32981	troubleshoot machine over heating. take temperature with tempt gun. machine is physically hot.	Non PM		9/19/2018
32979	Trouble shoot temp running hot check system Take radiator screen apart and blow out gonna put back to work and see	Non PM		9/19/2018
32698	weld cracks on wedge lock coupler	Non PM		9/19/2018
32456	hydraulic leaking on hammer system. remove hose to see if hose leaking. o-ring for stuchi is cut. change o-ring and put hoses and s	Non PM		9/19/2018
32455	keeper pin fell out of hammer. put new keeper bolt in hammer	Non PM		9/19/2018
32453	remove broken hardline clamp on bucket cylinder and than drill out broken clamp bolt. get new bolt and hardline clamp. put clamp	Non PM		9/19/2018
32582	PERFORM PIP 17TX697A 2/19/18 2706HRSAMERICAN MACHINERY REPLACED DOC PER PIP WARRANTY NO CHARGE SEE INVC	N 3028 on 9/11/2018 5:		9/12/2018
32385	hardline clamp fell off of boom. climb up top to put clamp back on	Non PM		9/5/2018
32384	machine will not hammer. check ball valves on stick. return side is slightly closed. fix ball valve from turning so flow isn't restricted.	Non PM		9/5/2018
32381	change ripper boot for ripper	Non PM		9/5/2018
31810	T/S hydraulic leak found aux return leaking replaced seal	Non PM		8/29/2018
29547	jump start machine and let batteries charge for PTA job and grab attachments to mobe	Non PM		7/11/2018
29118	fix hydraulic leak under machine. slowly leaking oil out of valve body under machine. remove floor panels to get to leak. remove hos	Non PM		7/11/2018
27282	cut off smashed step with torch and cut off block for bolts. clean track frame. weld on block and line up step. weld on other block a	Non PM		5/23/2018
26559	drill out broken bolt in hose clamp on right side auxiliary hardline. replace with new bolt	Non PM		5/9/2018

26411	adjust mirror swinging loose on cab and blocking door. tighten mirror bracket	Non PM	5/2/2018
24700	REPAIR ENGINE OIL LEAK 2801HRSAMERICAN MACHINERY KONA TIGHTENED LOOSE BANJO BOLT FOR OIL FEED TUBE ON TUI	N 2901 on 4/18/2018 2:	5/1/2018
25932	Check hyd leak replace broken o ring on valve	Non PM	4/24/2018
24226	Replace missing lock bolt for bucket pin	Non PM	4/10/2018
23923	Alerts coming in temp over call in to see temp was cool	Non PM	4/10/2018
24902	windshield won't lock closed. remove latch inspection cover and see if parts missing. check latch adjustment. adjust latch out and cl	Non PM	4/10/2018
24465	Replace leaking seal on bucket cylinder line on boom	Non PM	3/26/2018
23152	PM1 Record hourmeter reading and service performed Perform visual inspection Do operational checkout, in	PI 2764 on 3/2/2018 1:C	3/20/2018
24270	troubleshoot ac. clean out air filters. ac blows better. charge system	Non PM	3/20/2018
24163	Go over machine with Forman claiming picked load and load dropped had AMI pull relief pressures and performer all checked out I	Non PM	3/20/2018
23942	Check over heating warning light, found coolant leak on bottom hose,tightened and repositioned clamp ,picked up coolant from AMI	Non PM	3/14/2018
22748	Build up worn area of coupler and weld crack on side plate	Non PM	3/7/2018
21947	Replace leaking oring on aux line at stuchi coupler	Non PM	3/7/2018
23317	Trouble shoot aux Check on hammer sensor	Non PM	3/7/2018
23080	remove broken battery cover and grind off paint. put cover on and weld back on. paint welds	Non PM	3/7/2018
22636	hardline leaking oil. loosen clamps to hardline. remove fitting leaking. remove ball valve for thumb and eliminate. cap 3 way fitting a	Non PM	3/7/2018
22634	change stucchi on right side. change o-rings on fittings to stucchi	Non PM	3/7/2018
22629	fix stuchi position. stuchi moved inwards and cannot fit hammer hose on. reposition and tighten	Non PM	3/7/2018
21756	Remove leaking auxiliary line to replace leaking seals and stuchi coupler,and turn up Relief valve for quick coupler	Non PM	1/23/2018
21335	T/S hydraulic leak found fan valve leaking and return line coupler, repaired leaks	Non PM	1/23/2018
21059	Trouble shoot hyd leak have to clean and let run	Non PM	1/23/2018
20995	REPAIR LOOSE COUNTERWEIGHT 2285HRSAMERICAN MACHINERY KONA RETORQUED COUNTERWEIGHT SEE INVOICE# 3057	N 2534 on 1/10/2018 7:	1/11/2018
20686	PM2PM1 Record hourmeter reading and service performed Perform visual inspection Do operational checkou	PI 2484 on 12/27/2017 :	1/3/2018
20500	Replace hard line clamp	Non PM	1/2/2018
20656	Replace missing bolts for bucket cylinder lines ,stick cylinder clamps, Extract broken autolube fitting for dog bone pin	Non PM	1/2/2018
20588	T/S Hyd leak found fan control valve ,Reseal leaking fan control valve	Non PM	1/2/2018
20544	Adjust track slack	Non PM	1/2/2018
20530	Tighten auxiliary line clamps bolts	Non PM	1/2/2018
20256	Bucket pin bolt replace	Non PM	12/19/2017
20019	Check out broken hard line cylinder clamps	Non PM	12/19/2017
19585	Replace leaking stuchi couplers and leaking ring on valve	Non PM	12/12/2017
19188	Weld cracks Prep cracks Air arc	Non PM	11/22/2017
18721	Tighten leaking stuchi coupler	Non PM	11/22/2017
18570	Front glass broken. Remove front door so that glass can be replaced. Remove floor mat and clean broken glass out of cab.	R N 2261 on 11/6/2017 9:	11/21/2017

18544	Go inspect counter weight may need to be reset gonnna give ami	Non PM		11/21/2017
18353	Check hydraulic leak, found bucket cylinder hose blown,removed hose and ordered new hose. Repair crack on 84" bucket moe	Non PM		11/21/2017
18828	T/S hydraulic leak no control valve, replace leaking hose o-ring	Non PM		11/14/2017
18566	PM1 Record hourmeter reading and service performed Perform visual inspection Do operational checkout, including any attac	PI 2261 on 11/6/2017 9:		11/7/2017
18218	Zonar	Non PM		11/7/2017
18088	Clean quick coupler , to look for cracks	Non PM		11/7/2017
17762	Trouble shoot hyd leak looks like fitting on bucket cylinder cracked I don't think this can be welded go AMI look for our cylinder take	Non PM		11/7/2017
18514	Broken front window locate parts oderd	Non PM		11/7/2017
17985	Pick bolts from broken quick coupler in Waikoloa yard,Lock down hammer shut off valve on aux line to stop valve from closing duri	Non PM		10/30/2017
17927	Missing bolts on coupler have to get rite bolts	Non PM		10/27/2017
17465	Replace leaking o-ring on bucket cylinder hose	Non PM		10/18/2017
16222	Auxiliary clamps needed locate	Non PM		10/13/2017
16612	Check battery's and jump start and check charging	Non PM		9/27/2017
15810	Pm 4	Non PM		9/25/2017
16429	Remove broken bolts on clamps on tube	Non PM		9/25/2017
15677	Remove auxiliary line to weld crack and reinstall Replace leaking tubing with new	Non PM		9/25/2017
15807	PM4 SERVICEPM1 Record hourmeter reading and service performed Perform visual inspection Do operational checko	PI 1984 on 9/11/2017 9:		9/13/2017
15617	Replace leaking pressure hose on pump and fill hydraulic oil	Non PM		9/12/2017
14706	Replace broken track pad bolts	Non PM		8/30/2017
14594	one blinker not working. change light bulb	Non PM		8/24/2017
14108	Replace worn bucket tips on 54" bucket	Non PM		8/15/2017
13304	REPLACE BOTH RADIATOR CORES, HYDRAULIC COOLER AND ENGINE FAN BLADES 1225HRS DAMAGED BY LOOSE BOLT	N 1815 on 8/8/2017 8:5		8/8/2017
13504	Repair hydraulic leak on auxiliary line on boom ,blow out radiator	Non PM		8/1/2017
13462	Repair hydraulic leak on auxiliary line on boom, and blow about radiator	Non PM		8/1/2017
12505	Replace leaking stuchi coupler	Non PM		7/17/2017
11885	Replace worn ripper tip	Non PM		7/5/2017
11785	Replace blown o-Ring on auxiliary line valve	Non PM		7/5/2017
11533	PM 2 service ** SEE WO 11056 FOR CHECKLIST AND CORRECTLY OPENED	N 1597 on 6/24/2017 1:		6/29/2017
11056	PM2 ** SEE ALSO WO 11533 OPENED IN THE FIELD FOR ADDITIONAL HOURSPM1 Record hourmeter reading and s	PI 1597 on 6/23/2017 8:		6/29/2017
11361	Replace blown hose on rental hammer	Non PM		6/28/2017
11441	Replace missing pin lock bolt	Non PM		6/28/2017
10502	Replace leaking stuchi couplers	Non PM		6/13/2017
10463	ENGINE VIBRATES SEVERLY 750HRS AMERICAN MACHINERY KONA REPLACED ENGINE WITH COMPLETE REMAN DUE TO NEW E	Non PM		6/13/2017
10759	Replace leaking o-ring on stick cyl line	Non PM		6/13/2017

10505	Start repairs to 60" bucket , air arc old weld to prep for new wear plates cut metal for wear plates in Waikoloa yard	Start to weld	Non PM	6/13/2017
10319	Replace missing lock bolt for bucket pin, grind off burns on pin		Non PM	6/13/2017
10280	Replace worn ripper tip		Non PM	6/13/2017
10279	Load AT74 84" bucket on to flat bed in Waikoloa yard and take to Uplands		Non PM	6/13/2017
10282	Hard face bucket		Non PM	6/5/2017
9416	Replace missing track bolts and bucket pin retainer bolt		Non PM	5/17/2017
8956	Replace missing bolts for fan motor support , remove rear engine covers , after cooler hose and pipe to access support		Non PM	5/10/2017
9263	Remove broken bolts for aux line clamps and install new clamps Replace missing bolts for thumb valve		Non PM	5/9/2017
7730	PM1 Record hourmeter reading and service performed Perform visual inspection Do operational checkout, including any	PI 1332 on 4/29/2017 1:		5/3/2017
8249	T/S Hyd leak on auxiliary line , replace o ring on shut off valve		Non PM	4/18/2017
7891	Change leaking stuchie hard line on left side		Non PM	4/18/2017
7719	Trouble shoot hyd and coolant leak. Found fan blew up and poked holes in hyd cooler and radiator		Non PM	4/18/2017
7710	Trouble shoot what caused fan stranode Notified AMI to replace hyd cooler ,fan and radiator		Non PM	4/18/2017
7718	T/s hydraulic leak, remove decking ,radiator covers, bottom plates, t/s coolant leak,Found cracked fan blades ,damaged radiator co		Non PM	4/13/2017
7605	T/S Hyd leak on auxiliary line on stick, found crack , weld crack modify mounting clamps and remount		Non PM	4/5/2017
6987	PROBLEM: Hammer firing/Hitting too slow. BUT hits hard. troubleshoot pump 2 flow on monitor settings. check pressures and re		Non PM	4/5/2017
7368	Replace 4 bottom steps on track frame, extract broken bolts		Non PM	4/4/2017
3866	AT74 Serial # 56384 bucket Hitachi 470 84 inch Cut off old pin bosses and prep for new ones Weld on new bosses a		Non PM	3/29/2017
5594	AT74 cut off boss from broken coupler to put on bucket		Non PM	3/22/2017
6048	Repair hydraulic leak at quick coupler, fittings loose and broken oring. Bolt for dog bone on stick.		Non PM	3/20/2017
6047	Weld pin boss on 84" bucket		Non PM	3/20/2017
5779	check battery voltage. monitor reading low voltage		Non PM	3/20/2017
6825	change glass on cab		Non PM	3/20/2017
6711	change stuchi coupler. damaged. change hydraulic hose blown. picked up hose from d&m		Non PM	3/20/2017
6710	install glass on machine		Non PM	3/20/2017
6648	weld ripper pin boss. cracked		Non PM	3/20/2017
6295	tighten track guide bolt loose		Non PM	3/14/2017
6162	weld bolt on h-link so it doesn't come off		Non PM	3/14/2017
6056	Order window and check hyd leak		Non PM	3/14/2017
5984	put new bolt in bucket pin		Non PM	3/14/2017
5923	change track pad bolts		Non PM	3/14/2017
5851	change ripper boot on ripper		Non PM	3/14/2017
5789	Trouble shoot jd link found arched wire at alternater notified Randy he located one and came down and put it on.		Non PM	3/14/2017
5595	h-link pin fell out of seat of coupler. put pin back and put new bolt in keeper		Non PM	3/14/2017

5523	at74 grind bucket ears to put pins in. line up pins. put on new teeth	Non PM	2/21/2017
4809	Repair autolube, not pumping grease	Non PM	2/15/2017
5119	Find tool for grind out pin boss	Non PM	2/13/2017
4341	Cut off bent step on track frame with torch. drill out bolts from frame and put new bolts and new steps.	Non PM	2/8/2017
3289	Weld on at 1077	Non PM	2/8/2017
3070	At1077 weld cracks on bucket Hard face	Non PM	2/8/2017
2957	Check on engine swap	Non PM	2/8/2017
2882	Set up AMI motor swap	Non PM	2/8/2017
2557	Wipes inop bad connection found and cleaned	Non PM	2/8/2017
6	PM1Record hourmeter reading and service performedPerform visual inspectionDo operational checkout, including any attachmentsC	PI 1004 on 1/20/2017 2:	1/24/2017
4050	PM3 SERVICEPM1 Record hourmeter reading and service performed Perform visual inspection Do operational checkout, includ	PI 1004 on 1/20/2017 2:	1/23/2017
1250	clean out broken glass. install new glass. windshield	Non PM	11/16/2016
1249	bucket pin bolt fell out. align pin and put new bolt in. weld bolt.	Non PM	11/16/2016
1007	T/S Hyd leak, repaired loose sending unit on pilot manifold	Non PM	11/16/2016
855	Repair bucket tips pins walking out	Non PM	11/16/2016
1706	Change bucket teeth	Non PM	11/16/2016
1538	Check crack on bucket set up to get another one to replace	Non PM	11/16/2016
1528	Take bucket AT1077 to West Hawaii landfill from waikoloa yard	Non PM	11/16/2016
1527	Repair cracks on top of bucket AT 1076	Non PM	11/16/2016
1183	Mount fire extinguisher mount	Non PM	11/16/2016
1055	Broken lower front window pane Hammering rock	Non PM	11/16/2016
841	Check warning light	Non PM	11/16/2016
725	Bucket tips fell off get parts and put on	Non PM	11/16/2016
645	Repair ripper weld boss in	Non PM	11/16/2016
374	PM1Record hourmeter reading and service performedPerform visual inspectionDo operational checkout, including any attachmentsC	PI 782 on 10/7/2016 7:1	10/14/2016
Totals:			

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

