



Box 9 • 105 Angus Street
 Windthorst, SK S0G 5G0
 Phone: 306-224-2110 • Fax: 306-224-4343
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Davidson 306-567-3074
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629

Ship To: .

Branch WINDTHORST		
Date 02/27/26	Time 09:21:50 (O)	Page 02

Invoice

Ship Via	Purchase Order #
Tax ID #	
	Salesperson S81

SERVICE INVOICE

STK#/FLEET#	TRACTOR	HRS	PIN/EIN	WARRANTY DATE	HRS
007368	TRACTOR ST470	2207	ZEF300453		
straightened it out					
ls- installed new light assembly					
47926473	LAMP			1 N 170.91	170.91
87309531	SCREW, SELF-TAP			2 M 4.99	9.98
				PARTS	180.89
				LABOR	149.25
11008004				SEGMENT TOTAL==>	330.14

SEGMENT#	DESCRIPTION	WARRANTY DATE	HRS
5 C 44006 NA	REPLACE FRONT WIPER BLADE	02/05/26 02/24/26	
CORRECTION: ls- replace front wiper blade			
84211825	WIPER BLADE	1 49.31	49.31
		PARTS	49.31
		LABOR	75.62
11008004		SEGMENT TOTAL==>	124.93

SEGMENT#	DESCRIPTION	WARRANTY DATE	HRS
6 C 44006 NA	REPLACE BLOCK HEATER CORD	02/05/26 02/24/26	
CORRECTION: ls- replaced block heater cord			
47920592	CABLE, ELE	1 N 112.76	112.76
		PARTS	112.76
		LABOR	39.80
11008004		SEGMENT TOTAL==>	152.56

SEGMENT#	DESCRIPTION	WARRANTY DATE
7 C 44006 NA	REPAIR STEADY BEARING LOOSE SET SCREW	02/05/26 02/24/26
CORRECTION: -am- 2/24/26 - tightend up set screw		

CONTINUED ON PAGE 03

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc. It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment. Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk. An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid. Estimates are for the items specifically identified in the estimate only, and are non-binding. Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Received By



Box 9 • 105 Angus Street
 Windthorst, SK S0G 5G0
 Phone: 306-224-2110 • Fax: 306-224-4343
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Davidson 306-567-3074
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629

Ship To: .

Branch WINDTHORST		
Date 02/27/26	Time 09:21:50 (O)	Page 03

Invoice To:

Ship Via	Purchase Order #
Tax ID #	
	Salesperson S81

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
007368	TRACTOR ST470	2207	ZEF300453		
11008004				LABOR	49.75
				SEGMENT TOTAL==>	49.75

SEGMENT# 8 C 44006 NA	02/05/26 02/25/26				
REPAIR HYDRAULIC HOSE LEAK					
CORRECTION:					
- am -2/25/26 - run unit on flowmeter, had trouble finding leak, found a loose fitting, tightened fitting up and ran unit no leaks					
11008004				LABOR	344.27
				SEGMENT TOTAL==>	344.27

SEGMENT# 9 C 44006 NA	02/05/26 02/24/26				
SERVICE AND GREASE					
CORRECTION:					
- am- 2/24/26 - replaced cab air filter, topped up coolant , (1 L oat) put 15-16 psi in all the tires					
ls - replaced both fuel filters, the 3 def filters, crankcase filter, both hydraulic and trans filters.					
-am- 2/25/26 - installed new eng air filter					
ADDITIONAL DESCRIPTION:					
Change fuel filters					
Change def filters					
Change crankcase filter					
Change hyd and trans filter					
Air filters if needed					
Cab filter if needed					
Top up antifreeze					
Adjust tire pressure					
EHCFIL1		EHC CHARGE		4 .55	2.20

CONTINUED ON PAGE 04

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 * It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
 * Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 * An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 * Estimates are for the items specifically identified in the estimate only, and are non-binding.
 * Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Received By

Thank You!
 We Appreciate Your Business

