

AA # 3

- 16 NEW LONG BLOCK WITH A NEW TURBO, FUEL PUMP, REPLACED, CALIBRATED ALL THE INJECTORS,
- + REPLACE LEFT SIDE DRIVE PUMP
- 16 REPLACE BOTH DRIVE MOTORS, WORN HOSES ETC,
- 16 INSTALL NEW HYD. VALVE, HOSES, GO THROUGH ROUTE, WRAP, REPLACE HOSES ETC. ROUTE / REPAIR ELECTRICAL,
- 16 INSTALL REQUIET LIFT CYLINDERS
- + RE/RE BOTH DUO-CONE SEALS,
- + REPAIR ALL CAB ELECTRICAL, REPLACE HIGH-LOW AND 2-SPEED SWITCHES, PERFORM COMPLETE CALIBRATION,
- + REPLACE LIGHTS, ROUTE / REPAIR ALL CAB WIRING.
- + GO THRU COMPLETE HEAD, REPLACE ALL HEAD BEARINGS, WEAR PLATES AND SCRIPS REPAIRED, REPLACE ALL CHAINS ON HEAD, REPAIR VALVES, ROUTE HOSES, REPLACE HOSES, INSTALL NEW ZURK HOSES, FITTINGS.
- + REPLACE SPROCKETS,
- 16 NEW RAILS AND PADS APP. 500 hrs ago.
- + REPLACE DRIVE COUPLER AND ALL APPLICABLES WITH NEW ENGINE.