

Report Name: **Maintenance History Report,**

Run on: **23/05/25 at 14:18**

Run By: **Administrator**

Notes:

Version: **V1.1**

From: **01/01/2023 00:00**

To: **23/05/2025 23:59**



Date	Fleet Number	Category	Supplier	Mechanic	Invoice Number	Current Km's	Maint Job
Fleet: XO58CO							
10/01/23	XO58CO	Internal Maintenance		Wayne Armour	0	927,573	35,962
	Notes:	Check diff oil leak, remove axle 3 diff centre- inspect, clean and reseal. Refit centre. Refill oil, refit axles, tighten loose through shaft nut, refit tailshaft. Test.					
19/01/23	XO58CO	A Service		Cohen Simpson	0	931,551	36,046
	Notes:	Carry out A service.					
19/01/23	XO58CO	Internal Maintenance		Cohen Simpson	0	931,551	36,071
	Notes:	Replace missing track rod bolt. Straightened tail light bar & weld into place.					
24/02/23	XO58CO	External Maintenance	RESOLUTION TYRES		51048	945,904	36,558
	Notes:	POS: 7,8,9,10 Fitted Haulmax tyres x 4 Scrap tyres x 4					
13/04/23	XO58CO	B Service		John Jacka	0	961,790	37,007
	Notes:	With Jay Carried out B service					
14/04/23	XO58CO	Internal Maintenance		John Jacka	0	961,790	37,066
	Notes:	With Joah & Riley R&R 1st drive suspension airbags due to air leaks Johnny RHS - Josh LHS- checked Resecure all hoses around tops of airbags Remove steer wheels & drums, measure drums R-423mm, L-424mm Strip worn linings, assemble new & fit new drums Fit wheels & tension to 450ftlb readjust steer axle brakes Fit hub cap to 2nd drive RHS					
18/04/23	XO58CO	Internal Maintenance		Cohen Simpson	0	963,345	37,099
	Notes:	R&R fan belt tensioner Replaced fan belt Ran truck all ok					

Date	Fleet Number	Category	Supplier	Mechanic	Invoice Number	Current Km's	Maint Job
Fleet: XO58CO							
20/04/23	XO58CO	Internal Maintenance		Cohen Simpson	0	964,161	37,122
	Notes:	R&R faulty body up sensor - alarm now works as should					
22/05/23	XO58CO	Internal Maintenance		Kenn Shaw	0	975,591	37,494
	Notes:	Find oil leak from compressor, no nuts on it Removed coolant lines air, removed compressor from engine check ok Oring snapped, filled grove with solastic & refitted compressor Found some nuts on brackets & used them Started & checked all ok cleaned up oil					
13/06/23	XO58CO	Internal Maintenance		Cohen Simpson	0	985,560	37,715
	Notes:	Jacked up & supported chassis & removed blown airbag Fit new airbag & airline Jacked up chassis & removed stand					
13/06/23	XO58CO	Internal Maintenance		Cohen Simpson	0	985,480	37,712
	Notes:	Found headlight plug to be dirty & have bad contacts Cleaned out & refit, R&R parker globe Lights working as should					
16/06/23	XO58CO	Internal Maintenance		Cohen Simpson	0	987,416	37,752
	Notes:	Topped up coolant until full Checked for leaks found no leaks anywhere					
16/06/23	XO58CO	External Maintenance	RESOLUTION TYRES		52958	0	37,808
	Notes:	POS: 3,4,5,6 Fit Haulmax tyres x 4 Scrap x 4					
29/06/23	XO58CO	Internal Maintenance		Kenn Shaw	0	992,700	37,992
	Notes:	Removed all parts to remove radaiator swapped housing & braces Refitted all parts filled with coolant, road test Z& cleaned area					
30/06/23	XO58CO	Internal Maintenance		Wayne Armour	0	992,722	37,923
	Notes:	Test drive aftr radiator replacement & check for leaks					
12/07/23	XO58CO	Internal Maintenance		Cohen Simpson	0	997,090	38,041
	Notes:	Tightened loose track rod bolt replaced RHS step light Roof lights are LEDS & none in stock R&R marker plates on rear of truck bin					
12/07/23	XO58CO	Internal Maintenance		Cohen Simpson	0	997,090	38,042
	Notes:	Carried out rego check					

Date	Fleet Number	Category	Supplier	Mechanic	Invoice Number	Current Km's	Maint Job
Fleet: XO58CO							
13/07/23	XO58CO	Internal Maintenance		Wayne Armour	0	997,090	38,081
	Notes:	Refit draw bar cover					
18/07/23	XO58CO	Internal Maintenance		Kenn Shaw	0	999,106	38,293
	Notes:	Checked engine oil was below add mark Topped up to full 15000 kms until service					
19/07/23	XO58CO	Internal Maintenance		Cohen Simpson	0	999,074	38,115
	Notes:	Found airleak to be 1/4 airline joiner in chassis leaking R&R joiner no more airleaks					
27/07/23	XO58CO	Internal Maintenance		Kenn Shaw	0	1,001,577	38,329
	Notes:	PTO disengaged. Check air system, blow out line to PTO, swap PTO air line to different solenoid. Remove directional valve, stripped replaced o-ring, reassemble					
28/07/23	XO58CO	Internal Maintenance		Kenn Shaw	0	1,001,593	38,331
	Notes:	Pto not staying engaged. Repair, fill with out					
01/08/23	XO58CO	External Maintenance	RESOLUTION TYRES		53774	1,001,927	38,368
	Notes:	POS:23,24 Fit Haulmax tyres steer x 2 Scrap x 2					
01/08/23	XO58CO	Internal Maintenance		Kenn Shaw	0	1,001,937	38,317
	Notes:	Drain transmission oil, remove pto, built new pto, assemble to transmission, refill and test. Hook up to trailer.					
10/08/23	XO58CO	Internal Maintenance		John Jacka	0	1,004,972	38,390
	Notes:	Replace wear plate on ringfeeder					
10/08/23	XO58CO	A Service		John Jacka	0	1,004,972	38,392
	Notes:	Carried out A service Josh filled auto greaser, checked operation of greaser, changed oil, oil filters & fuel filters					
06/09/23	XO58CO	Internal Maintenance		John Jacka	0	1,012,748	38,696
	Notes:	Breakdown- Fit runout to LHS 2nd drive & tension					
13/09/23	XO58CO	Internal Maintenance		Braith Winley	0	1,016,198	38,748
	Notes:	Replace spring brake valve as required. Need to also replace blower motor.					
19/09/23	XO58CO	External Maintenance	RESOLUTION TYRES		54645	1,021,623	38,819
	Notes:	Fit new tyre (MJR stock) pos 1					

Date	Fleet Number	Category	Supplier	Mechanic	Invoice Number	Current Km's	Maint Job
Fleet: XO58CO							
04/10/23	XO58CO	Internal Maintenance		Braith Winley	0	1,023,713	38,937
	Notes:	Upon inspection found pins in indicator plug to have been bent Fixed pins tested works as should Upon inspection found tank lights to have broken wire - fixed wire Readjusted dog body up alram sensor - tested all ok					
04/11/23	XO58CO	Internal Maintenance		Braith Winley	0	1,033,686	39,214
	Notes:	R&R blower meter & tested					
07/11/23	XO58CO	External Maintenance	RESOLUTION TYRES		55625	1,034,165	39,313
	Notes:	POS: 1,2 Fit Hankook tyres x 2 Scrap tyres x 2					
29/11/23	XO58CO	Internal Maintenance		Josh Murray	0	1,041,728	39,483
	Notes:	Topped up oil to full level					
02/12/23	XO58CO	Internal Maintenance		Kenn Shaw	0	1,042,879	39,612
	Notes:	R&R a/c compressor tx valve Replace drive belts pressure test & check Replaced a/c filters & shrouder valves					
04/12/23	XO58CO	External Maintenance	Alltech Automotive Elec		3818	0	39,601
	Notes:	Check a/c find new components fitted Vacuum system & gas as necessary Find poor air flow in cab Dismantle dash Remove cabin filter & clean Refit & reassemble					
20/12/23	XO58CO	C Service		Riley Timmins	0	1,049,729	39,688
	Notes:	With Josh & Jay Carried out C service					
20/12/23	XO58CO	Internal Maintenance		Riley Timmins	0	1,049,729	39,738
	Notes:	R&R oring on fill tube R&R spinner filter housing, fixed breather hose & washed down					
21/12/23	XO58CO	Internal Maintenance		Wayne Armour	0	1,049,946	39,747
	Notes:	Scan for eng fault find communication fault with after treatment bump Clear fault & test no longer active					

Date	Fleet Number	Category	Supplier	Mechanic	Invoice Number	Current Km's	Maint Job
Fleet: XO58CO							
14/02/24	XO58CO	External Maintenance	RESOLUTION TYRES		57325	0	40,254
	Notes:	POS: 7 Fit tyre x 1 Scrap x 1					
26/03/24	XO58CO	Internal Maintenance		Cohen Simpson	0	1,074,761	40,611
	Notes:	R&R LHS low beam headlight Replaced LHS & RHS front parkers Found fitting on bottom of p/steering reservoir to be finger tight Tightened fitting & cleaned off excess oil Topped up reservoir					
13/04/24	XO58CO	External Maintenance	RESOLUTION TYRES		58878	1,086,754	41,157
	Notes:	POS: 7,8,9,10 Fit Haulmax tyres x 4 Scrap x 4					
13/04/24	XO58CO	External Maintenance	RESOLUTION TYRES		58878	1,086,754	41,156
	Notes:	POS: 7,8,9,10 Fit Haulmax tyres x 4 Scrap x 4					
03/05/24	XO58CO	Internal Maintenance		Kenn Shaw	0	0	41,107
	Notes:	Checked over truck, found fitting from compressor head leaking Removed HP line & fitting replaced copper washer & tightened Replaced air lines on draw bar					
07/05/24	XO58CO	Internal Maintenance		Josh Murray	0	1,088,559	41,031
	Notes:	Replaced outter tyre on LHS on 1st axle of dog Wheel nuts torqued to 450ftlbs nut covers & indicators were fitted					
21/05/24	XO58CO	Internal Maintenance		Riley Timmins	0	1,088,975	41,159
	Notes:	R&R both torque rods R&R fill tube oring & fixed air leak in firewall by refitting 3/8 airline in joiner Cohen R&R booster on RHS 2nd drive R&R dump valve on steer axle R&R relay valve on 1st drive axle Removed jack shaft & tightened yoke nut, refit shaft & torqued to spec					
22/05/24	XO58CO	Internal Maintenance		Riley Timmins	0	0	41,165
	Notes:	Find blown 10amp fuse in firewall Replaced fuse & checked wiring ok					

Date	Fleet Number	Category	Supplier	Mechanic	Invoice Number	Current Km's	Maint Job
Fleet: XO58CO							
23/05/24	XO58CO	Internal Maintenance		Riley Timmins	0	1,088,975	41,183
	Notes:	With Cohen & Riley. D Carried out pre rego inspection					
27/05/24	XO58CO	Internal Maintenance		Cohen Simpson	0	1,089,803	41,230
	Notes:	Removed exhaust manifold ground out cracks, heated & welded cracks Cleaned up all gasket surfaces, buffed all botls Applied gasket sealant to both surfaces, fit manifold with gaskets Got new centre piece & fit new manifold to old side pieces with new gaskets - fit manifold Tentioned manifold to spec, fit turbo & tensioned Fit oil feed & return lies with new gaskets Refit all components, ran & checked for leaks Test drove - all ok					
07/06/24	XO58CO	A Service		John Jacka	0	1,093,535	41,366
	Notes:	With Jay & Preston Carried out service					
17/06/24	XO58CO	Internal Maintenance		Wayne Armour	0	1,094,865	41,469
	Notes:	Sort out air lines for tail gate etc Sort out wiring for bin alarm on all the time with spare trailer TE 13KV loaded up					
15/07/24	XO58CO	Internal Maintenance		Wayne Armour	0	1,103,485	41,833
	Notes:	Drivers window switch faulty - swap with LH side to get working **Need to order new switch**					
15/07/24	XO58CO	Internal Maintenance		Cohen Simpson	0	1,104,124	41,933
	Notes:	Turbo drain has been repaired on seperate job card Found RHS rear marker kight to have internal short & broken wire halfway up bin Replaced light & wire					
20/07/24	XO58CO	Internal Maintenance		Cohen Simpson	0	1,105,795	41,876
	Notes:	Found one turbo drain flange bolt loose - tightened bolt & cleaned with brake cleaner Ran truck at 1200 rpm & no leaks De-greased & pressure cleaned engine					
23/07/24	XO58CO	Internal Maintenance		John Jacka	0	1,105,906	41,902
	Notes:	Fuel up due to no power					
31/07/24	XO58CO	GR Service		Preston Wall	0	1,108,394	41,953
	Notes:	With Cooper & John Carried out GR service					

Date	Fleet Number	Category	Supplier	Mechanic	Invoice Number	Current Km's	Maint Job
Fleet: XO58CO							
14/08/24	XO58CO	Internal Maintenance		Riley Timmins	0	1,112,332	42,086
	Notes:	Found airline to be pinched on the RHS Replaced airline 3/8 hose & tested for airleaks - no leaks					
23/08/24	XO58CO	Internal Maintenance		John Jacka	0	0	42,177
	Notes:	Top up engine oil.					
27/08/24	XO58CO	Internal Maintenance		Kenn Shaw	0	1,116,544	42,226
	Notes:	Breakdown- Remove split hose and replace. Fill with coolant.					
11/09/24	XO58CO	Internal Maintenance		Wayne Armour	0	1,121,735	42,405
	Notes:	Breakdown- Check hoses, replace blown transmission cooling hose on drivers side under motor. Replace coolant, test.					
13/09/24	XO58CO	Internal Maintenance		Kenn Shaw	0	1,127,543	42,463
	Notes:	Breakdown- transmission cooler split. Bypass cooler, fill with coolant and get load off truck.					
16/09/24	XO58CO	Internal Maintenance		Cohen Simpson	0	1,127,928	42,508
	Notes:	Check coolant system pressurising. Replace blown oil cooler. Replace turbo drain gasket & o-rings.					
27/09/24	XO58CO	GR Service		Riley Timmins	0	1,128,329	42,598
	Notes:	Carried out GR service					
09/10/24	XO58CO	Internal Maintenance		Riley Duren	0	1,128,844	42,700
	Notes:	Topped up engine oil					
17/02/25	XO58CO	Internal Maintenance		Kenn Shaw	0	0	44,173
	Notes:	Removed batteries, cleaned down & charged					

Totals for Report: **64 Transactions**