



Vehicle History Summary

Fleet #	14023
Registration	
Make	Mercedes Benz
Model	Atego
VIN / Chassis #	WDB9702782L627863
Build Date	2012

Date	Reading / Units	Type / Repairer Notes	Repairer
13/02/2026		PREPARE FOR SALE R-33853 PREPARE FOR SALE REMOVE CAMERAS / CLEAN CAN INTERIOR TOP UP POWER STEER OIL PRESSURE CLEAN ENGINE AND REMOVE ALL STICKERS CLEAR ALL STORED CODES	HNL WORKSHOP
12/02/2026		DVR 208, Power Steering Faults R-33841 DVR 208 POWER STEERING MAKING NOISE - TOP UP OIL	HNL WORKSHOP
28/01/2026		DRIVE TYRES T-5382 REPLACE 4X DRIVE TYRES POS 3/4/5/6 FITTED 305/70R19.5 STOCK TYRES	ROSS TYRES
27/01/2026		CANCEL T-5196	
07/01/2026	695,318 kms	A - 10K S-14861 CARRY OUT 'A' SERVICE TOP UP ENGINE OIL	HNL WORKSHOP
22/12/2025	693,349 kms	DVR 07352, DVR 15, ENGINE OIL LEVEL SENSOR R-33334 DVR 07352 - DVR 15 ENGINE OIL LEVEL ISSUE WARNING LIGHT CAME ON BUT OIL LEVEL CORRECT MONITOR FOR SUSPECT SENSOR FAULT	HNL WORKSHOP
18/12/2025	692,742 kms	DVR 07692, DVR 07696, steering issue R-33242 DVR 07692 07696 STEERING ISSUES - REPLACED STEER TYRES TOP UP STEERING FLUID ENGINE LIGHT FOR ADBLUE	HNL WORKSHOP
17/12/2025	692,742 kms	steer tyres T-5296 replace steer tires found cracked rim	ROSS TYRES
13/11/2025		DRIVE TYRES, DVR 07658 T-5196 FIT RUN OUT TYRE TO DRIVE DRIVE TYRES TO BE CHANGED - 4 TYRES IN STOCK	HNL WORKSHOP, ROSS TYRES
11/11/2025	687,310 kms	ADBLUE ISSUE, DVR 07656 R-32710 DVR 07656 CHECK ADBLUE FAULT ON DASH REPLACED FILTER - RUN AND TEST OK CODE STILL ON DASH	HNL WORKSHOP
10/11/2025	686,978 kms	CABIN FILTER R-32672 REPLACE CABIN FILTER	HNL WORKSHOP
07/11/2025		DRIVE TYRES T-5199 SUPPLY ONLY 4x 305/70R19.5 ALL POSITION TYRES	SYDNEY TYRE SERVICE
06/11/2025	687,232 kms	DVR 10248, DVR 10250 R-32638 DVR 10248 10250 REPLACE L/H HEADLIGHT GLOBE CHECK REVERSE CAMERA - CAMERA OLD STYLE AND NEEDS UPDATING STEERING BOX LEAKS - NEEDS REBUILD	HNL WORKSHOP
04/11/2025	686,280 kms	A - 10K S-14543 CARRY OUT 'A' SERVICE	HNL WORKSHOP
23/10/2025	684,667 kms	Puncture Repair T-5164 PUNCTURE REPAIR POS L/H/R INNER	ROSS TYRES

Date	Reading / Units	Type / Repairer Notes	Repairer
16/10/2025	683,959 kms	DVR 10233, Steering Box Faulty R-32325 DVR 10233 STEERING FEELS STIFF CHECKED - TOP UP OIL - ROAD TEST OK STEERING BOX NEEDS OVERHAUL	HNL WORKSHOP
02/10/2025	683,315 kms	BRAKE ROTOR AND PADS, DVR 10222 R-32124 DVR 10222 L/H DRIVE DISC PADS WORN OUT - ROTOR TO BE REPLACED REPLACED BRAKE PADS ON 1ST DRIVE	HNL WORKSHOP
30/09/2025	681,631 kms	TOP UP ENGINE OIL R-32076 TOP UP ENGINE OIL - 3 LITRES	HNL WORKSHOP
18/09/2025	679,729 kms	Breakdown - Truck R-31989 TRAVEL TO COOKS HILL - TRUCK STUCK ON DRIVEWAY MANUALLY ADJUST DRIVE AIR BAGS TO GET TRUCK OFF DRIVEWAY	HNL WORKSHOP
04/09/2025	677,954 kms	TRANSMISSION AND DIFF OILS R-31560 TRANSMISSION AND DIFF OILS CHANGED	HNL WORKSHOP
04/09/2025	677,954 kms	C - 120K S-14173 carry out C service Replace engine oil and filter, replace fuel filters replace transmission filters and oil replace air dryer filter replace engine drive belt press in sway bar bushes replace diff oil remove rear shock and repair mount test drive truck, further inspection required possible boost leak. replace power steering fluid.	HNL Fleet Newcastle
03/09/2025	677,089 kms	A - 10K S-14159 DVR 10188 Carry out A service check engine light on dash found oil level low (topped up) engine light cleared wash, detail and paint rims DVR 10188	HNL Fleet Newcastle
11/08/2025	675,325 kms	PRE HVIS INSPECTION, Registration HVIS Inspection R-31368 HVIS INSPECTION - FAILED AHV1583481 FIT REFLECTORS REPAIR REAR TG FRAME FLUID LEAK AT TOP OF STEERING BOX - CLEAN AND ROAD TEST DEFECT CLEARED CA2853151	HNL WORKSHOP
29/07/2025	674,264 kms	brake wear sensor, DVR 10167 R-30842 DVR 10167 10163 BRAKE WEAR SENSORS REPLACED REPLACE STEER BRAKE PADS CHECK HARNESS FOR FAULTS AS BRAKE WARNING ON DASH REPAIR DAMAGED WIRING IN HARNESS	HNL WORKSHOP
24/07/2025	673,660 kms	24V SOCKETS, DVR 10161, WARNING LIGHT ON DASH R-31227 DVR 10161 WARNING LIGHT ON DASH 24V SOCKETS IN CAB DON'T WORK	HNL WORKSHOP
16/07/2025	673,119 kms	clearance lights , DVR 10153 R-31111 DVR 10153 CLEARANCE LIGHTS OUT REPAIR CLEARANCE LIGHT - REPLACE BLOWN GLOBES	HNL WORKSHOP
02/07/2025		Accident Damage R-30946 Incident No: NFS020725INC1 Date of incident: 02/07/2025 Report Description: At 10:55am this morning Aaron Thomas reported a minor incident directly to his Manager. Aaron was attempting to reverse into a loading zone at a delivery location and has shaved the side of a street sign with the side of 14023. There was a vehicle parked in part of the loading zone , heavy rain and the sign being higher than the mirrors of the truck contributed to Aaron hitting the sign. He stopped immediately upon hearing a noise and moved forward away from the sign . He then proceeded to do a drive around the block and upon his return the car had moved and loading spot was free for him to park safely. Scratches are minor and has not pierced the side wall. driver has been interviewed, tool boxed and will be given a verbal warning for his lack of attention when assessing his surroundings for a safe damage free delivery. Driver: Aaron Thomas Truck: 14023	HNL WORKSHOP
25/06/2025	670,998 kms	A - 10K S-13770 CARRY OUT 'A' SERVICE	HNL WORKSHOP
19/06/2025	670,565 kms	brakes locking on, DVR 10132 R-30828 DRIVE BRAKES LOCKING ON - DVR 10132 CHECK ALL BOOSTERS / CALIPERS / AIR VALVES FOUND R/H FRONT DRIVE BOOSTER LEAKING WITH MAXI BRAKES OFF REASSMBLE AND LOCK OUT TRUCK TILL PARTS ARRIVE	HNL WORKSHOP
18/06/2025	670,462 kms	A - 10K S-13680 CARRY OUT 'A' SERVICE DVR 10126 REPLACE LAZY BRAKE PADS DVR 10120 RESECURE MIRROR BRACKET COVER	HNL WORKSHOP
05/06/2025		STEER TYRES T-4845	ROSS TYRES

Date	Reading / Units	Type / Repairer Notes	Repairer
		DVR 10106 strip and fit stock steer tyre CLEAN AND PAINT ALL RIMS	
02/06/2025	668,522 kms	TOP UP COOLANT R-30636 TOP UP COOLANT .5 LITRE	HNL WORKSHOP
29/05/2025	668,521 kms	DRIVE HUB SEAL, drive wheel bearings R-30590 Leaking hub seal, - APPRENTICE TRAINING JACK - WORK EVIDENCE ATTACHED REPLACE WHEEL BEARINGS AND SEALS - REPLACE BOTH HUBS AND BRAKE PADS	HNL Fleet Newcastle
26/05/2025	668,095 kms	Accident Damage R-30558 ACCIDENT DAMAGE - TRUCK HAS HIT SOMETHING AND DAMAGED AIR SCOOP - NO INCIDENT REPORT SUPPLIED REMOVE AND REPAIR AIR SCOOP AND REFIT	HNL WORKSHOP
12/05/2025	666,589 kms	DVR 10091, DVR 10433, PAN SIDE WALL, Radio Replacement R-29973 REPLACE RADIO HEAD UNIT - DVR 10433 10091 - RUN NEW WIRES FOR REPLACEMENT HEAD UNIT CHECK R/H SIDE WALL STARTING TO BUBBLE OUTER SKIN - DVR 10440 MONITOR SIDE WALL	HNL WORKSHOP
22/04/2025	664,702 kms	headlight globe R-30090 replace passenger side headlight globe	HNL Fleet Newcastle
14/04/2025		TRUCK STUCK ON DRIVEWAY R-30000 DRIVER HAS TRUCK STUCK ON DRIVEWAY AT COOKS HILL CELLARS TOW TRUCK TO PULL TRUCK OFF DRIVEWAY	ONEILLS TOWING
13/03/2025	663,532 kms	A - 10K S-13102 Carry out A service APPRENTICE TRAINING - JACK	HNL Fleet Newcastle
11/03/2025	659,978 kms	A - 10K S-13117 CARRY OUT 'A' SERVICE CHECK FAULT CODES ON DASH WASH AND DETAIL	HNL WORKSHOP
04/03/2025	657,834 kms	steer tyres T-4598 fit new all position tire to spare rim	ROSS TYRES
18/02/2025		STEER AND DRIVE T-4551 4X 305/70R19.5 FOR STOCK	SYDNEY TYRE SERVICE
13/02/2025	655,963 kms	DVR REPAIRS R-29228 REVERSE BUZZER AND DOOR INDICATOR ISSUES REPAIRED - DVR 10437 FIT RUN OUT TYRE TO L/H STEER - DVR 10435	HNL WORKSHOP
30/01/2025	654,339 kms	TRANSMISSION FAULTS R-28939 * 6511089793 - REPAIR FRONT OIL LEAK AND PUT INTO SUB ASSEMBLES TO CHECK. Vehicle presented to workshop with complaints of front end oil leak. Inspected oil condition and found to appear burnt. Advised customer of findings and stripped transmission into sub-assemblies. inspected all components and chemically cleaned. Found wear to various bearings and bushes. Inspected for damage and repaired transmission replacing all damaged components. Flushed oil cooler on Hot Flush machine as required. Replaced all seals and gaskets and tested transmission on Dyno. Fit all accessories and carried out final check. No further faults found at time of testing.	HNL WORKSHOP
21/01/2025	654,339 kms	DRIVE BRAKE PADS, steer brakes R-28921 CHECK ALL BRAKE PADS FOR WEAR - REPLACE AXLE 2 BRAKE PADS PRESSURE CLEAN TRANS AND ENGINE AREA	HNL WORKSHOP
07/01/2025	652,691 kms	A - 10K S-12732 CARRY OUT 'A' SERVICE REPAIR LIGHTS AND REPLACE R/H/R LIGHT ASSEMBLY TOP UP HYDRAULIC OIL IN TG	HNL WORKSHOP
09/12/2024	649,172 kms	Electrical - Headlight Globe R-28491 REPLACE L/H HEADLIGHT GLOBE	HNL WORKSHOP
28/11/2024	647,182 kms	Front Axle & Suspension Fault R-28273 Replace front axle bushes	HNL WORKSHOP
28/11/2024	647,182 kms	OVERHAUL STEERING BOX R-28192	HT Newman Power Steering

Date	Reading / Units	Type / Repairer Notes	Repairer
		REMOVE STEERING BOX - DVR 13994 BOX SENT TO HT NEWMAN FOR OVERHAUL REFIT STEERING BOX - RUN AND TEST OK	
22/11/2024	647,182 kms	BUFF WALLS R-28326 BUFF BOTH SIDE WALLS AND CABIN	HNL WORKSHOP
21/11/2024		Accident Damage R-28226 DAMAGED FRONT TOP CORNER CAP AND TOP RAIL REPAIR DAMAGE TO TOP R/H/R	HNL WORKSHOP
30/10/2024	646,289 kms	A - 10K S-12393 CARRY OUT 'A' SERVICE REMOVE DRIVERS SEAT / REPAIR MOUNTS / REFIT SEAT REPAIR DAMAGED AIR LINE WASH AND DETAIL / PAINT RIMS SIDE WALL REPAIR	HNL WORKSHOP
28/10/2024		LOAD LOCKS R-28076 REFIT LOAD LOCK RAILS - DVR 13979	HNL WORKSHOP
24/10/2024	645,403 kms	drive tyres T-4298 replace 4x 1st drive tires	ROSS TYRES
03/10/2024	643,074 kms	REAR DOOR SEAL KIT R-27477 FIT NEW DOOR SEAL KIT - ROLLER DOOR REMOVED - APPROVED JK DVR 13958 13960	HNL WORKSHOP
09/09/2024	639,814 kms	DRIVERS SEAT R-27218 DRIVERS SEAT ASSEMBLY - APPROVED BY JK QUOTE 55322 REPLACED SEAT ASSEMBLY	HVSS
29/08/2024	638,546 kms	REAR ROLLER DOOR REPAIR R-27328 REPAIR REAR ROLLER DOOR TRACKS AND ROLLERS DVRs 13783 13784	HNL WORKSHOP
20/08/2024	637,523 kms	B - 30K S-11871 CARRY OUT 'B' SERVICE - OIL SAMPLE ATTENTION REPLACED DAMAGED TG REMOTE	HNL WORKSHOP
16/08/2024	9 kms	B - 30K S-11870 CANCEL	HNL WORKSHOP
12/08/2024	636,567 kms	DRIVE BRAKE PADS R-26992 REPLACE WORN OUT DRIVE BRAKE PADS AXLES 2 AND 3 - DVR 13770 13761 INSPECT BRAKE LIGHT ON DASH - NEED REPLACING CHECK ALL PADS - REPLACED 1ST DRIVE BRAKE PADS - ROTORS WORN - NEED TO BE REPLACED TOP UP COOLANT	HNL WORKSHOP
06/08/2024	635,711 kms	PRE RMS INSPECTION R-26943 PRE RMS INSPECTION RMS INSPECTION AT CARRINGTON - PASSED AZ2831137 SELF CLEARING DEFECT AHV1529551 - REPAIR DRIVERS SEAT BELT REPLACE R/H STEP BLINKER ASSY REPLACE L/H TOP LIGHT REPAIR WIRING TO REAR LIGHTS REPLACE L/H/R CLEARANCE LIGHT CHECK POWER STEER LEAK AT BOX REPLACE MARKER PLATES DRIVERS SEAT BELT REPLACED	HNL WORKSHOP
31/07/2024	635,778 kms	A - 10K S-11784 CARRY OUT 'A' SERVICE	HNL WORKSHOP
26/07/2024		DRIVE TYRES T-4090 DRIVE TYRES FOR STOCK 305/70R19.5	SYDNEY TYRE SERVICE
17/07/2024		Accident Damage R-26631	HNL WORKSHOP
17/07/2024	633,531 kms	Electrical - Headlight Globe , REAR ROLLER DOOR REPAIR R-26652 REPLACE R/H HEADLIGHT GLOBE - DVR 13285 REPAIR REAR ROLLER DOOR	HNL WORKSHOP
08/07/2024	632,181 kms	pogo rail repair R-26637 RE-SECURE LOAD LOCK RAIL - DVR 13278 REPAIR INTERNAL WALL AND RAIL REPAIR DOOR LOCK	HNL WORKSHOP
28/06/2024		Accident Damage R-26429	HNL WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
		Incident No: Allmen280624INC2 Date of incident: 28/06/2024 Report Description: Driver was leaving the dock at Rutherford Hotel and was boxed in tight by parked cars. He was watching front of the truck and rear end hit the car behind.	
24/06/2024	630,832 kms	engine exhaust leak R-26316 REPLACE RUSTED OUT ENGINE PIPE - DVR 10380 10351 REPAIR ENGINE WIRING HARNESS	HNL WORKSHOP
18/06/2024	630,170 kms	Puncture Repair T-4030 PUNCTURE REPAIR ON STEER FIT RUN OUT TO GET TRUCK MOBILE	ROSS TYRES
17/05/2024	628,562 kms	DRIVE TYRES T-3970 REPLACE DRIVE TYRES - USED COMPANY STOCK TYRES - DVR 10380	ROSS TYRES
07/05/2024	626,094 kms	STEER TYRE T-3932 REPLACE WORN STEER TYRE POS 2 FITTED STOCK 305/70.19.5 CLEAN AND PAINT RIMS	ROSS TYRES
22/04/2024	624,603 kms	CAB AIR BLOWER MOTOR R-25473 CABIN BLOWER MOTOR REPLACED - 10952 10954	HNL WORKSHOP
04/04/2024	623,025 kms	REPLACE LEAKING AIR BAG R-25343 REPLACE BLOWN AIR BAG L/H/R	HNL WORKSHOP
04/04/2024	622,900 kms	Breakdown - Truck R-25397 BREAKDOWN - BLOWN REAR AXLE AIR BAG REMOVE AND TRY AND SOURCE NEW ONE - HAD TO GET ONE OUT OF SYDNEY FITTED SIMILAR AIR BAG TO KEEP TRUCK WORKING CORRECT AIR BAG FITTED BY AFTERNOON SHIFT	HNL WORKSHOP
03/04/2024	622,897 kms	AIR CODE ON DASH R-25339 CHECK WATER IN AIR CODE ON DASH - FAULTY SENSOR - DVR 10938 SENSOR HAS BEEN ORDERED REPLACED SENSOR - FAULT STILL THERE REMOVE CLUSTER AND CHECK ALL WIRING REPAIRED FAULTY WIRING TEMP REPAIR TO CRACKED EXHAUST FLEX	HNL WORKSHOP
03/04/2024		STEER TYRE T-3869 SUPPLY ONLY 1X STEER TYRE	ROSS TYRES
03/04/2024	622,677 kms	Air Tank, engine exhaust leak R-25438 check exhaust leak - temp repair completed - DVR 10945 check air in compressor light on dash - checked and truck needs new sensor	HNL WORKSHOP
21/03/2024	621,443 kms	DRIVE HUB OIL LEAK R-25190 DRIVE HUB SEAL LEAKING - R/H/F REPLACE WHEEL BEARINGS R/H/F HUB	HNL WORKSHOP
18/03/2024	621,176 kms	Breakdown - Truck R-25158 BREAKDOWN AT WARATAH - BATTERY ISSUE - REPLACED BATTERIES TO GET TRUCK GOING TRUCK RETURNED FOR TEMP REPAIR TO REAR LIGHT ASSY - NEW ONE ORDERED REPAIR BATTERY TERMINAL AND HOLD DOWN CLAMP	HNL WORKSHOP
15/03/2024		DRIVE TYRES T-3842 SUPPLY 4 ONLY 305/70R19.5 DRIVE TYRES	SYDNEY TYRE SERVICE
13/03/2024	620,453 kms	DAMAGED AIR TANKS R-25165 BROKEN AIR TANK BRACKET - DVR 10923 REPAIR BRACKET AND REFIT TANK REPAIR AIR LINE TO TANK	HNL WORKSHOP
19/02/2024	617,999 kms	BRAKES R-24860 REPLACE BRAKE PADS TO 1ST DRIVE AXLE	HNL WORKSHOP
12/02/2024	617,301 kms	Puncture Repair T-3779 PUNCTURE REPAIR	Bridgestone Australia Ltd
22/01/2024	615,645 kms	POWER STEER NOISY R-24601 CHECK POWER STEER NOISE - DVR 09927 FOUND POWER STEER FLUID LOW TOP UP FLUID - ROAD TEST OK	HNL WORKSHOP
15/01/2024	615,517 kms	Accident Damage R-24533	HNL WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
		REPLACE DAMAGED L/H SPOTTER MIRROR REPAIR DAMAGED MIRROR BRACKETS	
15/01/2024	615,157 kms	CAMERA SYSTEM R-24637 FIT NEW CAMERA SYSTEM	HNL WORKSHOP
04/01/2024	614,269 kms	STRIP AND FIT T-3713 STRIP AND FIT STEER TYRE	ROSS TYRES
03/01/2024	614,394 kms	wheel speed sensor R-24424 WHEEL SPEED SENSOR ON R/H/R DRIVE REPLACED REPAIR DAMAGED WIRING HARNESS TEST DRIVE TRUCK - OK	HNL WORKSHOP
27/12/2023	613,733 kms	STEER TYRES T-3697 FIT 1X COMPANY STOCK STEER TYRE SWAP L/H STEER FOR 2ND HAND TYRE TO KEEP TRUCK WORKING	Bridgestone Australia Ltd
20/12/2023	613,023 kms	Breakdown - Truck R-24362 TRUCK HAS FLAT BATTERIES - JUMP START CHECK CHARGE RATE - CHARGE BATTERIES TEST OK	HNL WORKSHOP
18/12/2023		DRIVE TYRES T-3688 REPLACE DRIVE TYRES - USED TYRES SUPPLIED BY NWFS	ROSS TYRES
13/12/2023		DRIVE TYRES T-3680 SUPPLY 4X 305/70R19.5 DRIVE TYRES	NWFS
29/11/2023	610,868 kms	TOP UP ENGINE OIL R-24293 TOP UP ENGINE OIL 5 LITRES	HNL WORKSHOP
28/11/2023	610,861 kms	ENGINE OIL TOP UP R-24210 TOP UP ENGINE OIL - DVR 09869 ADD 3 LITRES OF OIL	HNL WORKSHOP
27/11/2023	610,699 kms	Body Rear Roller Door R-24204 REPLACE DOOR ROLLERS - DVR 09868	HNL WORKSHOP
30/10/2023	608,265 kms	Electrical - Headlight Globe R-23916 REPLACE L/H HEADLIGHT GLOBE - DVR 09821 TOP UP POWER STEER OIL INSPECT CAMERA FAULT	HNL WORKSHOP
24/10/2023	607,816 kms	A - 10K S-10234 CARRY OUT 'A' SERVICE CHECK TYRE TREAD DEPTHS	HNL WORKSHOP
16/10/2023	606,985 kms	coolant fault R-23649 TOP UP COOLANT - 1 LTR	HNL WORKSHOP
10/10/2023		Puncture Repair T-3541 PUNCTURE REPAIR	ROSS TYRES
09/10/2023	606,546 kms	A - 10K S-10184 CARRY OUT 'A' SERVICE REPAIR BLINKER FAULT	HNL WORKSHOP
13/09/2023		NHVAS HISTORY R-23295 2 YEARS TRUCK HISTORY FOR NHVAS	HNL WORKSHOP
21/08/2023	601,810 kms	SUSPENSION - V STAY R-23019 BREAKDOWN AT THORNTON - FOUND V STAY WAS BROKEN BRING TRUCK TO WORKSHOP TO INSPECT FOR OTHER DAMAGES NEED TO REPLACE V STAY AND BROKEN AIR FITTING UNLOAD PRODUCT INTO 14044 REPLACED V STAY AND FITTING - ROAD TEST OK	HNL WORKSHOP
10/08/2023		2024 REGO PAPERS, REGISTRATION RENEWAL R-22907 REGO RENEWAL ATTACHED	HNL WORKSHOP
03/08/2023	600,573 kms	B - 30K S-9786 CARRY OUT 'B' SERVICE - OIL SAMPLE REPLACE LEAKING HEADER TANK - DVR 09419	HNL Fleet Newcastle
01/08/2023	601,000 kms	Body Rear Door Repair R-22851	HNL Fleet Newcastle

Date	Reading / Units	Type / Repairer Notes	Repairer
		Check rear door operation, reinsert rollers and beat tracks back in place Door had to be lubricated to work, vehicle really needs rear door repaired/ tracks replaced. DVR 09455	
01/08/2023	599,000 kms	B - 30K S-9785 cancel	HNL Fleet Newcastle
01/08/2023		DRIVERS DOOR LOCK, steer brakes R-23008 DRIVER REPORTED DRIVERS DOOR WOULD NOT UNLOCK - DVR 09465 CHECKED LOCK AND KEY BOTH WORKED replaced steer brake pads - DVR 09460	HNL WORKSHOP
01/08/2023	601,000 kms	Power Steering Faults, Radiator Header Tank R-22838 Check vehicle coding system due to DVR pressure check and found leak around header tank - tank old and cracked. New tank ordered from Benz Check vehicle power steering issue, leak around power steering box, cleaned to be reinspected on B service top up fluid.	HNL Fleet Sydney
18/07/2023	598,774 kms	Body Rear Roller Door R-22724 REFIT ROLLERS IN ROLLER DOOR TRACK - DVR 09454 TOP UP COOLANT	HNL WORKSHOP
27/06/2023		PRE RMS INSPECTION, RMS Inspection R-22452 FRONT SHOCKS REPLACED GENERAL CHECK OVER REPAIR REAR SHOCK MOUNT REPLACE STEER SWAY BAR BUSHES WASH AND DETAIL RMS INSPECTION AT CARRINGTON - PASSED AZ2682703	HNL WORKSHOP
19/06/2023	596,128 kms	A - 10K S-9514 CARRY OUT 'A' SERVICE AND GENERAL INSPECTION	HNL WORKSHOP
31/05/2023		DRIVE TYRES T-3196 SUPPLY ONLY 4X 305/70R19.5 DRIVE TYRES	NWFS
25/05/2023	593,595 kms	BRAKES R-22136 REPLACE DRIVE BRAKE PADS - AXLES 2 AND 3 ADJUST BRAKES - ROAD TEST OK	HNL WORKSHOP
25/05/2023	593,595 kms	DRIVE TYRES T-3195 DRIVE TYRES POS 3/4/5/6 FITTED 305/70R19.5 STOCK TYRES	ROSS TYRES
27/04/2023		STEER TYRES T-3116 STEER TYRES	ROSS TYRES
16/04/2023	590,133 kms	NON-SLIP FLOOR R-21765 CLEAN / PREPARE AND PAINT NON-SLIP PRODUCT TO PAN FLOOR	HNL WORKSHOP
11/04/2023	589,613 kms	TRUCK STUCK ON D/WAY R-21772 TRUCK STUCK ON DRIVEWAY AT COOKS HILL REMOVE TRUCK REPLACE TG SWITCH - DVR 09358	HNL WORKSHOP
11/04/2023	589,613 kms	BODY REPAIR R-21725 REFIT COVER UNDER FRONT OF PAN	HNL WORKSHOP
27/03/2023	588,520 kms	A - 10K S-8915 CARRY OUT 'A' SERVICE REPAIR SIDE WALLS - USE PORTA POWER TO STRAIGHTEN INTERNAL WALL PLATES DRILL AND FIT NEW SIDE WALL BOLTS REPLACE RIVETS IN FRONT WALL WASH INSIDE AND OUTSIDE	HNL WORKSHOP
22/03/2023	588,072 kms	interior body damage R-21552 RE-SECURE INTERIOR POGO STICK RAILS - BOTH SIDES - DVR 09346	HNL WORKSHOP
06/02/2023	579,465 kms	STEER TYRE T-2979 run out tyre fitted to pos 1	ROSS TYRES
25/01/2023	581,465 kms	INTERNAL PAN REPAIR R-21229 REPAIR INTERNAL POGO RAIL BAR - DVR 09146	HNL WORKSHOP
12/12/2022	576,074 kms	BRAKES R-20540	HNL WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
		BRAKE FAULT ON DASH FOUND STEER BRAKE PADS WORN OUT REPLACED PADS CHECK REAR BRAKES AND SLIDES	
25/10/2022	571,299 kms	Electrical - Headlight Globe R-20081 REPLACE HEADLIGHT GLOBE	HNL WORKSHOP
25/10/2022	571,301 kms	B - 30K S-7987 CARRY OUT 'B' SERVICE REPLACE TOP CAB LIGHTS REMOVE DASH AND WIRE TIGHTEN BODY 'U' BOLTS WASH AND DETAIL	HNL WORKSHOP
25/10/2022	571,301 kms	B - 30K S-7961 CARRY OUT 'B' SERVICE REPLACE VISOR LIGHTS REPAIR DASH BLINKER LIGHTS TIGHTEN BODY MOUNT BOLTS WASH AND DETAIL	HNL WORKSHOP
14/09/2022	565,582 kms	ENGINE OIL TOP UP R-19700 TOP UP ENGINE OIL - 1 LTR	HNL WORKSHOP
18/08/2022	562,450 kms	PRE RMS INSPECTION, RMS Inspection R-19476 CARRY OUT PRE RMS INSPECTION WASH AND DETAIL RMS INSPECTION - PASSED AZ2587744	HNL WORKSHOP
09/08/2022		Registration O-2249	
09/08/2022		CTP O-2250	
02/08/2022		PINK SLIP INSPECTION R-19345 CARRY OUT PINK SLIP INSPECTION FOR REGO	HNL WORKSHOP
02/08/2022	560,567 kms	Power Steering Faults R-19339 TOP UP POWER STEER OIL	HNL WORKSHOP
26/07/2022	559,976 kms	ENGINE , Transmission Fault R-19324 CHECK REPORTED VIBRATION IN TRANSMISSION FOUND TO BE ENGINE IDLING ROUGH	HNL WORKSHOP
25/07/2022	559,976 kms	POLISH CAB AND BODY R-19236 POLISH CAB AND BODY FIT NEW COMPANY STICKERS	HNL WORKSHOP
25/07/2022	559,976 kms	Body Damage R-19223 COMPANY LOGO STICKERS	HNL WORKSHOP
22/07/2022	559,976 kms	Transmission Assembly R-19130 TRANSMISSION FAILED - NEW TRANSMISSION FROM DALTRANS SERVICE AND TEST DRIVE REPLACE TRANSMISSION OIL CHECK AND REPAIR DRIVE PLATE R/R TRANSMISSION - BALANCE TAILSHAFT CLEAN AND PAINT TAILGATE - FIT COMPANY SIGN TO TAILGATE REPAIR TOP FRONT R/H CORNER PANEL	HNL WORKSHOP
13/07/2022		Windscreen Replacement R-19146 SUPPLY AND FIT WINDSCREEN	coalfields glass and windscreens
29/06/2022		Breakdown - Tow R-19077 TRANSMISSION FAILED AT SOLDIERS POINT TOW BACK TO WORKSHOP	ONEILLS TOWING
15/06/2022	557,833 kms	BRAKES R-18911 check RH drive axle caliper as it seems to run hot. pull wheels off and check caliper slides, rotor and pads. All checked ok paint rear bar and fit reflective tape. wash and detail truck.	HNL Fleet Newcastle
05/05/2022	551,064 kms	STEER TYRE T-2484 FIT STEER TYRE AND BALANCE BOTH STEERS	Bridgestone Australia Ltd
02/05/2022	553,131 kms	Power Steering Faults R-18534 CHECK POWER STEER FAULTS - DVR 07748 REPLACE POWER STEER FLUID AND FILTER - RUN AND TEST OK REPLACE NON-SLIP TAPE IN REAR OF PAN REFIT NUMBER PLATE REPLACE STEER TYRES WASH AND DETAIL	HNL WORKSHOP
11/04/2022	551,064 kms	A - 10K S-7112	HNL WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
		CARRY OUT 'A' SERVICE TOP UP ENGINE OIL WASH AND DETAIL	
16/03/2022	548,522 kms	CABIN AIR CONDITIONER R-18118 TRUCK SENT TO DAIMLER FOR A/C REPAIR - DVR 08224	DAIMLER TRUCKS NEWCASTLE
17/02/2022	545,747 kms	Mirror - Spotter R-17942 REPLACE DAMAGED L/H SPOTTER MIRROR	HNL WORKSHOP
17/01/2022	541,193 kms	CABIN AIR CONDITIONER R-17685 REPAIR A/C WIRING FAULT	HNL WORKSHOP
12/01/2022	540,873 kms	Electrical - Headlight Globe R-17656 REPLACE HEADLIGHT AND PARKLIGHT GLOBES REPAIR HEADLIGHT MOUNT	HNL WORKSHOP
05/01/2022	539,157 kms	Batteries R-17586 Replace batterys	HNL FLEET SERVICES
23/12/2021	537,967 kms	Tailgate Remote Hand Control Damage/Repair R-17548 REPLACE HAND CONTROL WITH GOOD 2ND HAND UNIT. TESTED ALL OK	HNL Fleet Newcastle
24/11/2021	533,384 kms	CABIN AIR CONDITIONER R-17274 CHECK A/C WIRING FAULT - A/C DOES NOT WORK - DVR 07263 FOUND WIRING ISSUE IN HARNESS TEMP REPAIR - WIRE COMPRESSOR WIRING TO SWITCH WELD UP L/H/S RAIL WASH AND DETAIL	HNL WORKSHOP
22/11/2021	532,773 kms	DRIVE RECAPS T-2204 8X RECAPS FITTED TO DRIVE AND LAZY AXLES	ROSS TYRES
15/11/2021	531,680 kms	Body Rear Roller Door R-17127 REPAIR AND TIGHTEN REAR DOOR LATCH - DVR 07247 CHECK EXHAUST BRAKE OPERATION - TEST OK CAB NOISE ON L/H/S - NEEDS CAB MOUNT REPLACED WASH AND DETAIL TRUCK	HNL WORKSHOP
23/09/2021	526,565 kms	Exhaust Pipe R-16558 ENGINE LIGHT ON DASH - FOUND HOLE IN ENGINE PIPE FIT NEW FLEX PIPE TO ENGINE PIPE - REFIT RUN AND TEST OK	HNL WORKSHOP
22/09/2021	526,561 kms	Air leak R-16556 REPAIR AIR LEAK	HNL WORKSHOP
15/09/2021	526,021 kms	A - 10K S-6236 CARRY OUT 'A' SERVICE REWIRE TAILGATE PENDANT	HNL WORKSHOP
23/08/2021	522,710 kms	Tailgate Electrical Lead R-16209 CHECK WIRING FAULT FOR PENDANT FOUND WIRING HAD BEEN SQUASHED - REPLACE PENDANT WASH AND DETAIL REMOVE SPARE WHEEL	HNL WORKSHOP
21/08/2021		REGISTRATION PAPERS R-16159 COPY OF REGISTRATION PAPERS - EXPIRY 12/8/2022	HNL WORKSHOP
10/08/2021		CTP O-1761	
10/08/2021		Registration O-1760	
02/08/2021	519,720 kms	Tailgate Damage R-15842 CHECK TAILGATE WIRING ISSUE FOUND PENDANT DAMAGED REPLACED DAMAGED PENDANT	HNL WORKSHOP
30/07/2021	519,718 kms	Brake Disc Pads & Rotors R-15795 DRIVE ROTORS AND PADS REPLACED REPLACED DRIVE BRAKE WEAR SENSORS WASH AND DETAIL TRUCK	HNL WORKSHOP
27/07/2021		Body Damage R-15750 DAMAGED L/H MIRROR ASSY REPLACED - DVR 07180	HNL WORKSHOP
15/07/2021		Body Damage R-15629	HNL WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
		SECURE L/H SIDE PANEL ON TRUCK	
07/07/2021	516,735 kms	Air Leaks, Damage - Tailgate, Service - A Service R-15514	HNL WORKSHOP
		REPAIR AIR LEAK - DVR 07157 REPAIR TAILGATE PLATFORM AND FRAME CARRY OUT 'A' SERVICE WASH AND DETAIL	
06/07/2021	516,362 kms	RMS Inspection R-15513	RMS CARRINGTON
		RMS INSPECTION - CARRINGTON - PASSED AZ2468423	
24/06/2021	514,887 kms	Electrical - Fault R-15350	HNL WORKSHOP
		WIRE UP INTERIOR PAN LIGHTS - DVR 07114 CLEAN OUT PAN / REFIT POGO STICK RAIL CHECK AND CLEAR ENGINE CODES WASH AND DETAIL	
24/06/2021	514,596 kms	engine oil R-15367	HNL WORKSHOP
		TOP UP ENGINE OIL - 6LTRS	
22/06/2021	514,427 kms	Service - A Service R-15322	HNL WORKSHOP
		CARRY OUT 'A' SERVICE	
01/06/2021	511,392 kms	Service R-15106	HNL WORKSHOP
		CARRY OUT 'A' SERVICE REPAIR TAIL GATE WIRING REPLACE SIDE CLEARANCE LIGHT	
27/05/2021	511,192 kms	Engine Check Codes R-14982	HNL WORKSHOP
		ENGINE LIGHT ON DASH - EMISSIONS CONTROL - DVR 07104 WELD UP HOLE IN EXHAUST PIPE	
27/05/2021	511,192 kms	STEER TYRES T-1713	ROSS TYRES
		replace steer tyres - workshop stock	
04/05/2021	508,592 kms	Tailgate Remote Hand Control Damage/Repair R-14675	HNL WORKSHOP
		RE-WIRE TAILGATE PENDANT	
29/04/2021	508,272 kms	Service R-14646	HNL WORKSHOP
		CARRY OUT 'A' SERVICE CHECK ALL FLUIDS AND LIGHTS REPAIR LIGHTS AND WIRING TEMP REPAIR TO DAMAGED R/H/F OF ROOF OF PAN	
29/03/2021	504,282 kms	Service R-14269	HNL WORKSHOP
		CARRY OUT 'A' SERVICE CHECK ALL FLUIDS / TYRES / LIGHTS GENERAL CHECK OVER GREASE TURNTABLE	
23/03/2021	503,042 kms	Repairs R-14157	HNL WORKSHOP
		REPLACE ENGINE SUMP REPLACE FUEL FILTER COVER	
23/03/2021	503,042 kms	B - 30K S-5542	HNL WORKSHOP
		CARRY OUT 'B' SERVICE REPLACE ENGINE OIL AND FILTERS REPLACE FUEL AND AIR FILTERS CHECK AND ADJUST BRAKES REPAIR LIGHTS / FOUND LEAKING SUMP REPLACE FUEL FILTER HOUSING WASH AND DETAIL - POLISH SCUFF MARKS OFF CAB	
16/03/2021	502,130 kms	Electrical - Fault R-14048	HNL WORKSHOP
		BLINKER WIRING REPAIRED	
10/03/2021	501,908 kms	Repairs R-13956	HNL WORKSHOP
		DRIVERS WINDOW SWITCH AND REGULATOR NOT WORKING FOUND FAULTY SWITCH AND REGULATOR REPLACE SWITCH AND REGULATOR MAKE NEW L/H BAR FOR TAILGATE AND FIT WASH AND DETAIL	
04/03/2021	501,352 kms	Repairs R-13869	HNL WORKSHOP
		MIRROR COVER MOUNT KITS FITTED	
02/03/2021	500,795 kms	AdBlue Fault R-13886	HNL WORKSHOP
		ENGINE LIGHT ON DASH - AFTER TREATMENT FAULT FOUND HOLE IN EXHAUST NEAR INJECTOR WELD UP HOLE - RUN AND TEST OK	
22/02/2021	500,507 kms	Repairs R-13778	HNL WORKSHOP
		REAR FLOOR NON SLIP TAPE FITTED REPLACE FAULTY BLINKER SWITCH AT STEERING COLUMN REPLACE R/H MIRROR ASSY	

Date	Reading / Units	Type / Repairer Notes	Repairer
29/01/2021	496,173 kms	Body Rear Roller Door R-13456 REFIT REAR DOOR PANEL	HNL WORKSHOP
21/01/2021	495,119 kms	Service R-13379 CARRY OUT 'A' SERVICE CHECK ALL FLUIDS AND LIGHTS CHECK TYRES - GENERAL CHECK OVER	HNL WORKSHOP
15/01/2021	494,745 kms	Brake Fault, Trailer Axle Wheel Bearings R-13268 Service Repairs - Remove & replace axle 3 left & right brake disc rotors Remove & replace axle 3 left & right brake pads Remove & replace axle 3 wheel bearing kits & re pack with new bearing grease Adjust wheel bearings & all brakes Check air leak at relay valve in chassis, test & locate faulty brake booster axle 2 right backfeed to valve Remove & replace axle 2 right brake booster Remove & replace axle 2 left & right brake pads Tension all wheel nuts Note - Axle 2 right brake disc rotor to be replaced at next service	HNL Fleet Sydney
15/01/2021	494,745 kms	Fire Extinguisher, Service R-13291 Carried out vehicle A - Service & inspection Remove & replace inside cabin Fire Extinguisher & mounting bracket to floor Remove & replace several roller door rollers & hinges, re shape door track & tested operation of roller door	HNL Fleet Sydney
04/01/2021	493,061 kms	Batteries Replace R-13125 Check engine slow to crank Load test batteries & found faulty, remove & replace x 2 batteries Run engine & check alternator charge rate, all ok Grease tailgate All ok	HNL Fleet Sydney
24/11/2020	486,432 kms	Suspension Fault R-12503 Rectify bump stop missing Remove & replaced axle 2 left & right bump stop rubbers Remove & replaced axle 2 left & right bump stop spacer blocks All ok	HNL Fleet Sydney
13/11/2020	484,874 kms	Tailgate - Grease R-12516 Check engine oil level Check coolant level Grease tailgate Grease steer axle king pins	HNL Fleet Sydney
04/11/2020	483,895 kms	B - 30K S-4904 Carried out vehicle B service & inspection. as per HNL checklist Replace engine oil & filter Replace engine fuel filters Replace engine air filter Replace a/c cabin filter Grease tailgate & steer axle king pins Carry out all general service checks & adjustments Remove & replaced engine coolant Remove & replaced left & right rear updated marker plates	HNL Fleet Sydney
04/11/2020	483,895 kms	Air Leaks R-12355 Rectify air leak Check & find left & right axle 2 air bags leaking air Complaint of suspension dropping overnight Remove & replaced axle 2 left & right air bags Check for leaks, all ok	HNL Fleet Sydney
04/11/2020	483,895 kms	New Tyres T-1129 305/70r 19.5 Drive (x4) pos 3,4,5,6 as per Attachment	ADZ Tyre & Battery
15/10/2020	475,969 kms	Breakdown - After Hours R-12345 Check Air Conditioning System for cause of not Operating as per Attachment	Crowhurst Auto Electrical Pty Ltd
30/09/2020	477,133 kms	Trailer Axle Hub Seals R-11745 Rectify axle 2 hub seal leak - Left Inspect & found axle 2 left hub seal leaking oil onto rim & hub area Raise axle, remove left wheel & hub assembly. Inc removal of brake caliper (disc brake) Clean hub & wheel bearings, replace hub seal Refit & adjust wheel bearing, top up diff oil level Remove & replaced axle 2 left & right brake pads Adjust brakes & tension wheel nuts Wash rim & hub area Grease tailgate	HNL Fleet Sydney
26/09/2020	476,915 kms	Body Rear Roller Door, Tailgate - Grease R-11700 Rectify roller door panel has come adrift Confirm fault, found top panel has fallen out on left side. Remove & replaced x 4 hinges & rollers to suit Tested operation of roller door. All ok Grease tailgate	HNL Fleet Sydney
22/09/2020	475,974 kms	Wheel Alignment R-11628 Replace steer axle right side front of front spring eye bush Carry out wheel Alignment	Big Wheel Truck Alignment
21/09/2020	475,975 kms	New Tyres T-991 305/70r 19.5 Steer (x2) pos 1,2 as per Attachment	ADZ Tyre & Battery
18/09/2020	475,968 kms	Tailgate - Grease R-11580 Grease tailgate Grease steer axle king pins	HNL Fleet Sydney
18/09/2020	475,969 kms	Breakdown - After Hours R-12473	Crowhurst Auto Electrical Pty Ltd

Date	Reading / Units	Type / Repairer Notes	Repairer
		Service Call to Depot Check Air Conditioning System for cause of not Working as per Attachment	
12/09/2020		Tailgate Operating Fault R-11478 Rectify tilt not working at hand control Remove & replaced tailgate hand control & wiring into control box Tested operation All ok Greased tailgate	HNL Fleet Sydney
11/09/2020	1 kms	Pressure Check T-1027 Pressure Check as per Attachment	ADZ Tyre & Battery
08/09/2020	474,888 kms	Service R-11418 Carry out A - Service & inspection Check & top up engine oil level Check all fluid levels Check brake pads for wear Check tyres for wear Grease steer axle king pins, grease tailgate General visual inspection Replaced number plate globe All ok	HNL Fleet Sydney
06/08/2020		Registration O-1234 GSlip - \$2453.35	
22/07/2020		CTP O-1235	
14/07/2020		Pressure Check T-708 Pressures Only as per Attachment	ADZ Tyre & Battery
09/07/2020		Tailgate Operating Fault R-10543 Rectify tailgate hand control damaged Confirmed fault Remove & replaced tailgate hand control including wiring into control box Tested operation All ok	HNL Sydney Workshop
15/06/2020	462,090 kms	Alternator Warning Light R-10214 Check vehicle for alternator warning on dash Raise cabin & check alternator charge rate, no charge Remove air ducting pipe to gain access to wiring at alternator Found broken wire on lug terminal at back of alternator Cut damage section, solder & crimp new lug terminal to wiring Refit all air ducting & run engine Check alternator charge rate, all ok Grease tailgate Grease king pins Check oil & coolant level	HNL Sydney Workshop
21/05/2020	458,854 kms	Registration Inspection R-9785 RMS Inspection - PASSED	RMS Wetherill Park
21/05/2020	458,867 kms	Puncture Repair T-455 Puncture Repairs inc. S&F (x1) pos 10 as per Attachment	ADZ Tyre & Battery
21/05/2020	458,841 kms	Service R-9810 Carry out A - Service / Pre rego check over Topped up engine oil & check all fluid levels Grease tailgate & steer axle king pins Found n/s rear tail light damaged, cut & drill bracket to suit Wire in & mount tail light assembly, tested operation of lights	HNL Sydney Workshop
06/04/2020		Breakdown - After Hours R-9343 Report Taillift not Working as per Attachment	TRS
13/03/2020	451,966 kms	B - 30K S-3837 Carry out B service Replace air dryer filter Replace power steering filter Replace leaking O/S drive axle hub seals Replace blown interior light globes	TRS Onsite Mechanic
17/02/2020	448,262 kms	Service R-8161 Carry out A service Replaced steer axle rotors and brake pads Replaced drive axle rotors and brake pads. Cleaned bearings and hubs and packed with new oil. Fit new hub seals and adjust wheel bearings Replaced lazy axle brake pads and wear sensors Replaced door hinges and rollers Fit new reflectors Tightened loose body bolts Topped up engine oil and power steer oil Replaced top cab light globe	TRS
17/01/2020	9,645 kms	New Tyres T-151 305/70r19.5 Drive Pos 3-4 as per Attachment	ADZ Tyre & Battery
14/01/2020	8,807 kms	Fit COP T-144 Fit COP as per Attachment	ADZ Tyre & Battery
17/12/2019	437,784 kms	Service R-6996	HNL Sydney Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		topped up engine oil topped up coolant checked all other fluids all ok checked lights checked tires greased truck and tailgate damaged to front panel and bumper checked and reported brakes: steer: 8mm 80% drive: 8mm 80% lazy: 7mm 70%	
23/10/2019	429,317 kms	Electrical - Headlight Assembly R-5838 removed and replaced both head light globes tested system all ok	HNL Sydney Workshop
17/10/2019	428,048 kms	Brake - Warning R-5667 inspected bearing noise coming from engine found the idler tension-er bearing was warn replaced belt replaced tension er replaced idler bearing tested for noise no noise was found after repair removed and replaced drive axle brakes as they were warn and dash had warning on	HNL Sydney Workshop
09/10/2019	426,928 kms	Air Leaks R-5519 inspected air leak found air leak coming from t piece under drivers seat removed and replaced fitting checked for leaks none found	HNL Sydney Workshop
04/10/2019	426,450 kms	Tailgate - Grease R-5493 greased and inspected tailgate greased king pins	HNL Sydney Workshop
24/09/2019	424,480 kms	C - 120K S-2907 Daimler Huntingwood / Replace thermostats Carry out service Replace transmission oil & filters Replace diff oil Replace adBlue & power steering filter Replace engine air filter Replace air dryer filter removed and replaced engine oil and filter removed and replaced fuel filters checked all lights checked all tires checked and reported brakes: steer: 7mm 70% drive: 7mm 70% lazy: 7mm 70% greased truck and tailgate cleaned cab inspected coolant temp getting hot inspected for leaks and found coolant built up around air compressor head removed cylinder head and found coolant in the cylinder head and cylinder removed and replaced cylinder head topped up coolant started truck test drove truck upon test drive truck was still getting around 100 degrees topped up transmission level dropped truck at Daimler to have overheating fault looked at	HNL Sydney Workshop
17/09/2019	423,775 kms	Service R-5221 CHECKED ALL FLUIDS CHECKED ALL LIGHTS CHECKED ALL TIRES CLEANED CAB CHECKED AND REPORTED BRAKES: STEER: 7MM 70% DRIVE: 7MM 70% LAZY: 7MM 70% DAMAGE ON BONNET AND FRONT BUMPER	HNL Sydney Workshop
12/09/2019	422,743 kms	Breakdown - After Hours R-5131 Contact Darren Flemming - 8:40pm Travel to HNL yard Huntingwood, rectify air leak Inspect to find blown air bag axle 3 o/s Travel to Daimler Huntingwood & collect part Remove & replace axle 3 o/s air bag Test for leaks. No further fault found. All ok.	HNL Sydney Workshop
12/08/2019		CTP O-678	
12/08/2019		Registration O-677	
08/08/2019	416,397 kms	Defect Repairs R-4685 REMOVED AND REPLACED RHS BLOWN HEAD LIGHT GLOBE CHECKED ALL LIGHTS ALL OK	HNL Sydney Workshop
29/07/2019	414,470 kms	Breakdown - After Hours R-4604 loaded Ute with tools traveled to Daimler to get parts traveled to Cowles rd mosman inspected fault found blown air bag on lazy axle LHS removed damaged bag inspected new bag to old one they looked different traveled to Daimler and they showed me there was a bung covering the bolt traveled back to mosman replaced air bag tested system for leaks none found traveled back to workshop unloaded Ute	HNL Sydney Workshop
28/06/2019		Brake Fault R-4380 jacked up axle 2 removed wheels removed boosters removed brakes and calipers removed both axles removed both hubs removed brake rotors fitted new rotors fitted new hub seals refitted both hubs replaced ABS sensors both sides fitted calipers and new brakes fitted new boosters both sides fitted all wheels torqued wheels adjusted brakes put truck on ground took on test drive all ok	HNL Sydney Workshop
15/06/2019	406,704 kms	Registration Inspection, Service R-4282 CHECKED ALL FLUID LEVELS CHECKED ALL LIGHTS - Replaced left & right indicator lamp assemblies CHECKED ALL TIRES ONE NEEDS REPLACING DUE TO BUBBLE IN TIRE (Bridgestone replaced x 2 drive axle tyres) CHECKED ALL BRAKES GREASED TAILGATE AND KING PINS	HNL Sydney Workshop
07/06/2019	406,174 kms	Body Rear Roller Door R-4252	HNL Sydney Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		INSPECTED REAR ROLLER DOOR ROLLERS BROKEN FOUND ON BROKEN REMOVED AND REPLACED ROLLER AND HINGE CHECKED ALL OTHERS ALL OK	
13/05/2019	401,416 kms	B - 30K S-2500 carry out B service: drained and replaced engine oil and filter removed and replaced fuel filters cleaned out air filter checked all lights checked and reported brakes: steer: 7mm 70% 1st drive: 6mm 60% 2nd drive: 6mm 60% greased truck and tailgate checked all tyres all good coolant leak from air compressor head	HNL Sydney Workshop
13/05/2019	401,416 kms	Seat Belt R-4023 removed and replaced seat belt assembly	HNL Sydney Workshop
12/04/2019	395,811 kms	Tailgate Charging System R-3861 REMOVED AND REPLACED TAILGATE BATTERIES REMOVED AND REPLACED TAILGATE BUMPER STICKERS GREASED TAILGATE FITTED MAGNET TO TAILGATE REMOTE	HNL Sydney Workshop
21/03/2019		Tailgate Repairs R-3710	TRS
15/03/2019	391,791 kms	Electrical - Tail Light Assembly R-3624 removed and replaced rear tail lights to LED fitted reducers tested system all ok removed and replaced RHS side indicator due to damage	HNL Sydney Workshop
15/03/2019		Tailgate Repairs R-3647 Remove & replace tailgate bush & pins	TRS
15/03/2019		Body Repair R-3651 Replace all interior body kick plate	Thermal Mark Transport Refrigeration
10/03/2019	391,787 kms	Tailgate Remote Hand Control Replacement R-3612 REWired TAILGATE REMOTE CHANGED FUSE	HNL Sydney Workshop
02/02/2019	385,837 kms	B - 30K S-2289 carry out B service: drained and replaced engine oil and filter removed and replaced fuel filters cleaned out air filter checked all lights checked and reported brakes: steer: 8mm 80% 1st drive: 7mm 70% 2nd drive: 7mm 70% greased truck and tailgate checked all tyres all good removed and replaced rear bumper sticker	HNL Sydney Workshop
11/01/2019	383,104 kms	Brake - Warning R-3201 Check all brakes Replaced steer and drive axle brake pads Adjusted brakes and tensioned wheel nuts	HNL Sydney Workshop
11/01/2019	382,655 kms	Service R-3148 carried out A service: greased truck and tailgate check and inspected brakes steer:8mm 75% 1st drive:6mm 60% 2nd drive:6mm 60% checked all fluid levels topped up engine with 3ltrs checked tyres tyre tread is good repairs carried out: replace tail gate flags keep an eye on: oil weeping from sump seat belt damaged needs: new oil cap (cap is missing)	HNL Sydney Workshop
04/01/2019	264,408 kms	Rear Under-Run Bar Damaged R-3120 Cut off under run bar that was damaged Straightened and weld back on and paint	HNL Sydney Workshop
16/12/2018	378,561 kms	Body Rear Roller Door R-3006 Refit top panel with new rollers Replaced allworn rollers and hinges Straightened bent door tracks and checked operation of door Check door cable adjustment	HNL Sydney Workshop
07/12/2018	378,413 kms	Power Steering Faults R-2975 Remove and replace power steer hose Wash down engine and check for leaks Check power steer oil level	HNL Sydney Workshop
07/12/2018	377,298 kms	Service - Vehicle "C" Service R-2952 Flush power steer fluid and replace filter Top up with new power steer fluid Top up engine oil	HNL Sydney Workshop
17/11/2018	375,562 kms	Tailgate Operating Fault R-2819 Grease tailgate and refit LH main frame pin Not taking grease, recommend removing and replacing bushes and pin	HNL Sydney Workshop
26/10/2018	322,677 kms	Defect Repairs R-2605 Remove spring and sent to get spring eye bush replaced Removed spring housing and cut old spring plates off Refit spring housing and all components Torque u bolts and wheel nuts	HNL Sydney Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
19/10/2018		Electrical - Ignition Switch Key R-2525 Replace 2 x keys Program & test	Daimler Huntingwood
15/10/2018	367,876 kms	Repairs R-2562 Fit air blower in cab Grease tailgate	TRS
02/10/2018		Engine Valve Adjustment R-2344 Carry out valve adjustment Replace rocker cover gasket	Daimler Huntingwood
02/10/2018	366,811 kms	Belt Tensioner R-2373 Replaced belt and tensioner and checked for any noise	HNL Sydney Workshop
06/09/2018	363,591 kms	Bearing Noise R-2215 Remove and replace water pump Replaced all gaskets and o rings for water pump and thermostat housing Topped up coolant and check for leaks Greased tailgate	HNL Sydney Workshop
12/08/2018		CTP O-427	
12/08/2018		Registration O-426	
11/08/2018	358,904 kms	Repairs R-2064 Tested system and found 7 pin socket needed replacing, replaced 7 pin socket and plug Check operation	HNL Sydney Workshop
30/07/2018	357,814 kms	Engine Overheating R-1966 Found belt was worn and needed replacing Removed and replaced belt and tensioners Grease and check over tailgate Top up hydraulic oil Fit new marker stickers to under run bar Replace rear mudflaps Replace engine air compressor cylinder head Replace thermostat	HNL Sydney Workshop
16/07/2018		Tailgate Repairs R-1892	HNL Sydney Workshop
11/07/2018	355,259 kms	Rear Under-Run Bar Damaged R-1897 Weld new under run bar piece on, straightened bent under run bars Painted under run bar and fit marker stickers Weld new tailgate chain stay on and paint Remove and fit new fleet stickers	HNL Sydney Workshop
06/07/2018	354,168 kms	B - 30K S-1799 Carry out B service replace reflectors refit rollers that had come out of tracks and replace damaged hinges clean and paint rims	HNL Sydney Workshop
26/05/2018	348,358 kms	Mirror Assembly R-1637 Remove amd replace RH complete mirror and arm Plug on wiring was different Solder old plug onto new mirror Replace rear marker plates	HNL Sydney Workshop
30/04/2018		Accident Damage R-1520	HNL Sydney Workshop
27/04/2018		Accident Damage R-1479 Replaced right rear tail lamp	HNL Sydney Workshop
18/03/2018		Damage - Rear Lights R-1358 Remove and replace tail light	HNL Sydney Workshop
13/02/2018	333,213 kms	Brakes R-1209 Replace both drive axle brake pads	HNL Sydney Workshop
21/01/2018	330,568 kms	Wheel Bearings - Repack Grease & Adjust R-1123 Remove lazy axle hubs and clean all bearings and hubs and inspect Pack bearings and hubs with new grease and refit hubs Refit calipers and wheels Adjust wheel bearings, adjust brakes and tension wheel nuts	HNL Sydney Workshop
06/11/2017	321,021 kms	C - 120K S-1282 Carry out C service and check over Replaced engine oil and filters Replaced gearbox and diff oils and gearbox filters Replaced air dryer filter, ad blue filter, air filter and cabin filter Replaced coolant Refitted rollers back into door tracks that had come out, straightened bent door tracks and lubricated Hand control down not working, found broken wire inside hand control, repaired and refitted, checked tailgate and hand control operation	HNL Sydney Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
23/10/2017	319,339 kms	Body Rear Roller Door R-807 Removed broken hinges and replaced with new hinges and rollers Straightened door tracks and lubricated them Checked door operation and door cable tension all ok	HNL Sydney Workshop
12/10/2017	316,103 kms	Repairs R-743 Repaired damaged hand control lead and rewire hand control and test Replaced tilt button switch that was faulty	HNL Sydney Workshop
22/09/2017	314,910 kms	Electrical - Blinker Fault R-665 Replaced wiring for side indicator and fitting a new indicator assembly	HNL Sydney Workshop
15/09/2017	314,546 kms	Accident Damage R-629	HNL Sydney Workshop
04/09/2017	313,278 kms	Accident Damage R-548 Replace left & right side spotter mirror assemblies.	HNL Sydney Workshop
11/08/2017		CTP O-186	
11/08/2017		Registration O-185	
10/03/2017		Accident Damage, Repairs R-81 please repair and replace all that is needed	HNL WORKSHOP
13/02/2017	285,666 kms	B - 30K S-873	MHR
27/09/2016	266,956 kms	A - 10K S-147 Service Completed	
24/09/2016	266,956 kms	B - 30K S-688 AS PER SERVICE SHEET	Mal Hooley Truck Repairs
03/06/2016	242,318 kms	B - 30K S-689 AS PER SERVICE SHEET	Mal Hooley Truck Repairs
03/06/2016	242,318 kms	B - 30K S-58 Service Completed	
23/02/2016	215,408 kms	C - 120K S-36 Service Completed	

Signed: _____

Name: _____

Date: _____