



# Vehicle History Summary

Fleet #	14022
Registration	
Make	Mercedes Benz
Model	Atego
VIN / Chassis #	WDB9702782L630802
Build Date	2012

Date	Reading / Units	Type / Repairer Notes	Repairer
06/02/2026	741,801 kms	<b>PREPARE FOR SALE</b> R-33789 TRUCK TO GO TO RICHIE BROS AUCTIONS DEREGISTER TRUCK REMOVE COMPANY SIGNAGE	HNL WORKSHOP
02/02/2026		<b>RUNOUT TYRE</b> T-5398 RUNOUT TYRE FITTED POS 6	ROSS TYRES
15/01/2026	741,801 kms	<b>CABIN AIR CONDITIONER, DVR 04591, DVR 07699</b> R-33251 DVR 04591 07699 CABIN AIR CONDITIONER NOT WORKING Update DVR (DVR #: 11) Air con not working sent to a/c tech for repair workshop aware. waiting on new year for booking truck has been inspected - major repair needed. waiting on quote for repair A/C REPAIRED / REGASED - ROAD TESTED OK	HNL WORKSHOP
15/01/2026	741,103 kms	<b>CABIN AIR CONDITIONER</b> R-33505 remove dash and replace heater core and evaporator remove and replace engine AC compressor	HNL WORKSHOP
07/01/2026	741,069 kms	<b>A - 10K</b> S-14860 CARRY OUT 'A' SERVICE	HNL WORKSHOP
05/01/2026	741,068 kms	<b>DVR 07357, DVR 10, steering issue</b> R-33312 TRUCK CAME TO WORKSHOP WITH REPORTED STEERING ISSUE CHECKED ALL STEERING COMPONENTS BUT COULD NOT FAULT ONLY HAPPENS AT LOW SPEED - POSSIBLE STEERING BOX ISSUE MONITOR	HNL WORKSHOP
19/12/2025	739,531 kms	<b>Airbag - Replace</b> R-33144 replace airbag with one from stock	HNL Fleet Newcastle
15/12/2025	739,382 kms	<b>SUSPENSION - V STAY</b> R-33048 REPLACE WORN V-STAY	HNL WORKSHOP
15/12/2025	739,782 kms	<b>CABIN REPAIR</b> R-33101 REPLACE LOCKING RINGS FOR DASH PANEL fit RH bumper blinker, remove sticker glue from pan walls	HNL WORKSHOP
10/12/2025	739,380 kms	<b>B - 30K</b> S-14728 CARRY OUT 'B' SERVICE REPLACE ALL FILTERS - ADBLUE FILTERS REPLACED ENGINE SUMP - DRAIN PLUG STRIPPED - USE 2ND HAND SUMP	HNL WORKSHOP
10/12/2025	739,380 kms	<b>WALL AND FLOOR SEPARATION</b> R-32754 BOTH SIDE WALLS SEPERATED FROM FLOOR REMOVE KICK PLATES / CUT AND FIT ANGLE TO FLOOR ATTACHED ANGLE TO WALLS - REFIT KICK PLATE	HNL WORKSHOP
24/11/2025	739,468 kms	<b>spring bushes</b> R-32750 all front suspension bushes worn, RH spring walking across bush	HNL Fleet Newcastle
21/11/2025	739,468 kms	<b>Puncture Repair</b> T-5219 PUNCTURE REPAIR L/H/R OUTER	ROSS TYRES
21/11/2025	739,468 kms	<b>DAMAGED PANELS</b> R-32801 REPLACE DAMAGED PANELS	HNL WORKSHOP
13/11/2025	739,150 kms	<b>A - 10K</b> S-14556	KJS Fleet

Date	Reading / Units	Type / Repairer Notes	Repairer
		Carried out A service and inspection as per HNL checklist Grease all points and tailgate Replace power steering fluid and filter (Genuine fluid) Replace A3 brake pads and disc rotors Adjusted all brakes and road tested	
13/11/2025	739,150 kms	<b>DVR 04517, Power Steering Faults</b> R-32686	KJS Fleet
		DVR 04517 R/H DOWN STEERING FAULT - ALL STEERING FAULTS REPAIRED IN THORNTON WORKSHOP	
06/11/2025	738,317 kms	<b>FLAT TYRE</b> R-32652	KJS Fleet
		Fitted spare tyre to truck,tensioned wheel nuts and checked tyre pressure.All okay	
03/10/2025	733,758 kms	<b>Change Vehicle Number Plates</b> R-32149	KJS Fleet
		Replace number plates - New plate rego is - HNL022	
22/09/2025	733,297 kms	<b>Check Vehicle Lights</b> R-31972	KJS Fleet
		Replace number plate lamp assembly All ok	
13/09/2025	732,536 kms	<b>ABS Fault</b> R-31795	KJS Fleet
		Check ABS fault Replace axle 2 left & right side ABS wheel speed sensors Clear codes All ok	
12/09/2025	732,536 kms	<b>Suspension Fault</b> R-31804	KJS Fleet
		Replace damaged shock absorber A3 right - Repaired upper mount bracket to chassis	
12/09/2025	732,636 kms	<b>Brake - Park Brake Alarm</b> R-32096	Crowhurst Auto Electrical Pty Ltd
		Supply and fit park brake alarm Crowhurst	
11/09/2025	732,536 kms	<b>DRIVE TYRES</b> T-5085	SYDNEY TYRE SERVICE
		DRIVE TYRES POS 3/4/9/10 FITTED 305/70R19.5 LM216	
21/08/2025	729,950 kms	<b>ABS</b> R-31605	KJS Fleet
		scanned vehicle for codes or previous inactive codes. no codes present. inspected steer and drive wheel speed sensors plus pulse rings for build up of dirt and grime. all visually looks okay. inspect drive axle for hub seal leaks all ok. with computer measured sensors voltage and operation driving around yard. all ok. no message on dash currently. to be monitored.	
21/08/2025	729,577 kms	<b>ABS Fault, Air Pressure Issue, DVR 04400</b> R-31467	HNL Sydney Workshop
		DVR 04400 AIR PRESSURE ISSUE ABS ISSUE	
19/08/2025	729,577 kms	<b>ABS Fault, coolant fault, engine oil</b> R-31602	KJS Fleet
		topped up engine oil 4 litres. topped up coolant 1 litre. truck needs to return after being unloaded for abs issues. truck also felt like it was derating. so need to look into that.	
11/08/2025		<b>Accident Damage</b> R-31370	HNL WORKSHOP
		Incident No: Ram Tpt110825INC1 Date of incident: 11/08/2025 Report Description: At approximately 14:55, Shaneel Ram operating vehicle rego XO89XO was in the process of closing up the pan on Dock 43 at Metcash site. As he raised the dock leveller, the vehicle he had been operating began to roll off the dock. Initially, the movement was slow but it quickly gathered momentum. Shaneel observed the movement immediately and ran down the ramp. He opened the driver's door and applied the foot brake by hand, stopping the vehicle approximately one metre from another parked truck. This action prevented a potential collision that could have resulted in significant property damage. Prior to closing up the truck, Shaneel entered the vehicle and turned on the ignition. He believes that at this point he may have inadvertently disengaged the park brake without realising. Immediate actions taken: • Shaneel underwent a mandatory on-site drug and alcohol test, which returned a clear result. • CCTV footage of the incident was reviewed in consultation with Metcash representatives. • Following this review, it was determined that Shaneel would be stood down pending further investigation. • The load was unloaded and put on another truck for delivery Root cause .driver was careless and failed to follow procedure Driver: Shaneil Ram Truck: 14022	
06/08/2025	728,364 kms	<b>NHVR ROADWORTHY</b> R-31322	NHVR
		NHVR annual inspection - PASSED AZ2943107 Self clearing defect - AHV1582736 Replace number plate light Replace missing rear reflectors	
15/07/2025	726,067 kms	<b>headlight globe</b> R-31711	KJS Fleet
		Removed and replaced Right hand side low beam globe and tested lights all ok.	
07/07/2025		<b>Accident Damage</b> R-30994	HNL Sydney Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		Incident No: Total Personnel070725INC1 Date of incident: 07/07/2025 Report Description: Driver had completed delivery inside loading dock. When leaving the premises as he swung to exit ,the guard underneath the tail lift caught the side of a shopping trolley collection trailer and bent a metal guard on the RHS of the trailer. Driver: Creaster Athanasie Total Truck: 14022 Trailer: 14022	
01/07/2025	724,559 kms	<b>BRAKE PADS</b> R-30912 Replace axle 2 brake pads Replace axle 2 brake disc rotors Replace axle 2 wheel bearings All ok	KJS Fleet
27/06/2025	724,559 kms	<b>Body Rear Roller Door, DVR 04348</b> R-30894 DVR 04348 BROKEN DOOR CABLE Fleet: 14022 Rego: XP06CZ Repair date: 27/6/25 Call out to repair broken cable on Freezer Toddco door Replaced drivers side cable & replaced 2 x missing rollers. Replaced bottom roller holder. Lubricated door & spring	TDC TRUCK DOORS & CURTAINS
27/06/2025	724,425 kms	<b>BRAKES</b> R-31018 - Inspected all brakes - found A2o/s + n/s pads low - removed - found o/s rotor warping and glazing recommended replacing. Replaced pads. Returned as advised for rotor replacement tension wheels. All ok test around the yard. -A2 N/S tyres required replacing -Secured N/S mirror assy - test for tightness & security all ok. -Found truck not holding air, inspected underneath vehicle for leaks all ok. Checked under drivers seat found missing sound using soapy water found.	HNL FLEET SERVICES
17/06/2025	721,930 kms	<b>Tailgate Fault</b> R-30801 Check and found tailgate hand controller damaged Replace remote shell and re wired Tested all ok	KJS Fleet
30/05/2025	721,974 kms	<b>Transmission Fault</b> R-30539 Sublet Daimler / Daltrans for transmission fault	Daimler Huntingwood, DALTRANS
29/05/2025	720,792 kms	<b>DVR 04216, Power Steering Faults</b> R-30381 DVR 04216 Replace steering column Replace flexible power steer hose Replace fluid and bleed power steering system Wheel alignment Road tested ok	Big Wheel Truck Alignment
29/05/2025	721,675 kms	<b>Power Steering Faults</b> R-30354 Replace steering column Replace power steering fluid Replace draglink Replace tie rod ends	KJS Fleet
27/05/2025	721,974 kms	<b>Transmission Fault</b> R-30551 CHECK AND REPORT TRANSMISSION FAULT VEHICLE IM LIMP MODE - AGN WARNING ON DASH CAUSE ALLISON TRANS WILL NEED TO GO TO ALLISON FOR FURTHER DIAG CONNECTED XENTRY RAN QUICK TEST FOUND CODES IN AGN OIL LEVEL SESNOR OPEN CIRCUIT AND TURBINE SPEED SUPPLIES NO SIGNAL OR IMPLAUSIBLE SIGNAL CHECKED ACTUAL VALUES BUT UNABLE TO CHECKED TO SEE IF I CAN GO INTO CODES AND DO GUIDED TEST BUT ALSO UNABLE TO COMMUNICATE WILL NEED TO GO TO ALLISON PARKED UP TRUCK UPLOADED QUICKTEST TO ARCHIVE	Daimler Huntingwood
15/05/2025	720,929 kms	<b>Wheel Alignment - Chassis to Axles (Truck)</b> R-30540	Big Wheel Truck Alignment
14/05/2025	720,792 kms	<b>TYRE ROTATION</b> T-4783 ROTATE STEERS AND DRIVE POS 1/2/7/8	SYDNEY TYRE SERVICE
09/05/2025	720,792 kms	<b>Power Steering Faults</b> R-30307 Check over power steering fault Remove and replace power steering pump Bled system and road test Found steering seems harder to turn right than left (Further repairs required)	KJS Fleet
08/05/2025	720,792 kms	<b>DVR 00922, Steering Fault</b> R-30294 DVR 00922 - STEERING FAULT - DRIVER WAS TOLD TO LEAVE TRUCK AT WORKSHOP DRIVER HAS LEFT DEPOT WITHOUT TAKING TRUCK TO WORKSHOP CHECKED - MULTIPLE REPAIRS TO FIND AND REPAIR ISSUE COMPLETED ON R#30307	HNL Sydney Workshop
07/05/2025	720,792 kms	<b>DRIVE TYRES</b> T-4764 DRIVE TYRES POS 7/8 FITTED 305/70R19.5 DOUBLE COIN	SYDNEY TYRE SERVICE
15/04/2025	718,857 kms	<b>DVR 01485, DVR REPAIRS</b> R-29995 DVR 04185 - DAMAGED INDICATOR Replace indicator and left side step grate REPAIRED AS PER R#30032	KJS Fleet
15/04/2025	718,857 kms	<b>Electrical - Clearence Light Assembly</b> R-30032 Carried out removing damaged assembly.Fit new and test all okay secured to vehicle	KJS Fleet

Date	Reading / Units	Type / Repairer Notes	Repairer
01/04/2025	717,702 kms	<b>BRAKE PADS</b> R-29802 Replace steer axle brake pads and discs Replace diff drain plug	KJS Fleet
28/03/2025	717,507 kms	<b>C - 120K S-13195</b> Carried out vehicle C service and inspection as per HNL checklist (Parts from workshop supply) Replace engine oil & filters Replace cabin filter Replace air dryer filter Replace ad blue filter Replace engine air filter Replace Allison transmission oil and filters Replace diff oil Grease tailgate and steer king pins Carry out all general service checks	KJS Fleet
20/03/2025	716,694 kms	<b>alternator fault</b> R-29700 DVR 00916 no charge volts at alternator Remove & replace alternator and drive belt All ok Tested charge - All ok	KJS Fleet
03/03/2025	714,899 kms	<b>Puncture Repair</b> T-4602 DRIVE TYRES	SYDNEY TYRE SERVICE
25/02/2025	713,920 kms	<b>Body Side Door</b> R-29347 Driver side door handle faulty Replace driver door handle & cable All ok	KJS Fleet
21/02/2025	713,710 kms	<b>TOP UP COOLANT</b> R-29325 Inspected and topped up coolant.Door handle mechanism has snapped,requires new door handle assembly.	KJS Fleet
19/02/2025	711,985 kms	<b>DAMAGED MIRROR, Tailgate Fault</b> R-29251 Driver said he hit mirror with pallet jack while walking past with load	KJS Fleet
14/01/2025		<b>GPS TRACKER</b> R-28788 GPS TRACKER NUMBER 237812	HNL WORKSHOP
02/01/2025	706,300 kms	<b>DAMAGED MIRROR</b> R-28621 Replace damaged left side spotter mirror assembly All ok	KJS Fleet
24/12/2024	706,300 kms	<b>Accident Damage</b> R-28593 Incident No: AWX241224INC1 Date of incident: 24/12/2024 Report Description: A truck clipped the mirror as it turned left, away from my lane.Patrick was in lane 3, the other vehicle was in lane 2. Patrick stated that it happened so quickly that he didnt get a chance to grab the rego but observed that it was a white 3 tonne pantec. Driver: Patrick Hamilton Truck: 14022	HNL Sydney Workshop
19/12/2024	704,641 kms	<b>CAB TILT HOSE</b> R-28567 Replace cab jack hydraulic line & tested operation All ok	KJS Fleet
18/12/2024	705,863 kms	<b>Coolant Leak</b> R-28781 by passed heater core and top up coolant. removed o/s steer guard,removed cab jack line.install new line and ran through chassis. top up fluid.found exhaust brake acuator damaged.replaced all ok	KJS Fleet
18/12/2024	704,641 kms	<b>ENGINE EXHAUST BRAKE</b> R-28566 EXHAUST BRAKE CYLINDER REPLACED	HNL Sydney Workshop
17/12/2024	704,641 kms	<b>Coolant Leak</b> R-28683 coolant leak found leak inside of cab.suspect heater core leaking.unable to by pass as advised due to incorrect size barbs in stock.unable to lift cab due to cab jack leaking.need to book in for repairs.	KJS Fleet
11/12/2024	704,641 kms	<b>TOP UP COOLANT</b> R-28470 Inspect and topped up coolant level. Vehicle still needs to be booked in for cab jack repairs.	KJS Fleet
05/12/2024	702,260 kms	<b>STEER TYRES</b> T-4388 STEER TYRES POS 1/2 FITTED 305/70R19.5 LONGMARCH	SYDNEY TYRE SERVICE
05/12/2024	702,953 kms	<b>ENGINE OIL LEAKS</b> R-28415 Oil is leaking from oil filter housing,have fitted new oil filter o ring.Carried out A Service.Cab jack line has rubbed through,requires hydraulic joiner or new line installed unable to jack cab up and degrease engine bay.	KJS Fleet
04/12/2024	702,953 kms	<b>Engine Oil Leak</b> R-28406 Oil is leaking from oil filter housing,have fitted new oil filter o ring.Carried out A Service.Cab jack line has rubbed through,requires hydraulic joiner or new line installed unable to jack cab up and degrease engine bay.	KJS Fleet

Date	Reading / Units	Type / Repairer Notes	Repairer
03/12/2024	702,260 kms	<b>TOP UP COOLANT</b> R-28372 Check and top up coolant.Checked and topped up coolant as requested.	KJS Fleet
12/11/2024	698,436 kms	<b>Puncture Repair</b> T-4360 PUNCTURE REPAIR POS 7	SYDNEY TYRE SERVICE
26/10/2024	696,377 kms	<b>DRIVE TYRES</b> T-4292 DRIVE TYRES POS 3/4 FITTED 305/70R19.5 TRIANGLE	SYDNEY TYRES
23/10/2024	696,377 kms	<b>drive tyres</b> T-4288 Replace A2 right x 2 (workshop stock tyre)	Bridgestone Australia Ltd
23/10/2024	697,451 kms	<b>BRAKE PADS</b> R-27925 Replace axle 2 brake pads Replace axle 2 disc rotors Replace axle 3 brake pads Adjusted all and road tested all ok	KJS Fleet
18/10/2024	696,533 kms	<b>C - 120K</b> S-12288 Carried out vehicle C service and check over as per HNL checklist Replace engine oil & fuel filters Replace engine air filter Replace cabin filter Replace air dryer filter Replace diff oil (Mineral) Replace sun visor clip driver side Replace wiper blades	KJS Fleet
18/10/2024	696,532 kms	<b>self clearing defect</b> R-27870 A service and basic check over Replace damaged indicator lamp assembly Replaced missing reflectors Self clearing defect	KJS Fleet
10/10/2024		<b>Accident Damage</b> R-27785 Incident No: Metro021024INC1 Date of incident: 06/09/2024 Report Description: On 06.09.2024 Thanh arrived to find fresh damage in 14022 , Looks like the tynes from a loaders EPJ has gone through the front wall , There is no available camera footage to see into the back of the pan on the docks . Driver: Thanh Nam HO Metro Truck: 14022	Workhorse Collision Repair
20/09/2024	689,549 kms	<b>engine oil</b> R-27596 Check and top up engine oil level - 3 Ltrs All ok	KJS Fleet
16/09/2024	682,933 kms	<b>DAMAGED MIRROR</b> R-27510 Removed and replaced N/S mirror as requested.	KJS Fleet
12/09/2024		<b>Accident Damage</b> R-27476 Left side mirror damaged Remove and replaced left side mirror complete All ok	KJS Fleet
09/09/2024		<b>Body Rear Roller Door</b> R-27437 Check and repair rear roller door fault	TDC TRUCK DOORS & CURTAINS
06/09/2024		<b>Accident Damage</b> R-27709 Incident No: Metro021024INC1 Date of incident: 06/09/2024 Report Description: On 06.09.2024 Thanh arrived to find fresh damage in 14022 , Looks like the tynes from a loaders EPJ has gone through the front wall , There is no available camera footage to see into the back of the pan on the docks . Driver: Thanh Nam HO Metro Truck: 14022	HNL Sydney Workshop
06/09/2024	686,092 kms	<b>DAMAGE - MIRROR</b> R-27408 Driver complained of mirror unstable.Inspected and found back of mirror damaged and needs replacement.	KJS Fleet
23/08/2024	683,371 kms	<b>Tailgate Safety Chain</b> R-27191 repaired safety chain as requested,tested all okay.	KJS Fleet
21/08/2024		<b>Accident Damage</b> R-27181 Incident No: AWX220824INC1 Date of incident: 21/08/2024 Report Description: The driver whilst completing the delivery and unloading , someone parked a bicycle along the the side of the dock , chained up to a number of shopping trolleys. When the driver pulled out of the dock , the bicycle was hit by the rear of the truck as it was obscured due to the position of the sun coming through the drivers windscreen. The driver reported to the dock supervisor what had occurred.	HNL Sydney Workshop
16/08/2024		<b>Mirror Arms</b> R-26472 Left side mirror arm to cabin damaged / cracked Remove and replaced mirror arm assembly & checked over All ok	KJS Fleet
16/08/2024		<b>Belts</b> R-26972	KJS Fleet

Date	Reading / Units	Type / Repairer Notes	Repairer
		Belts worn - Reported at A Service interval - Remove & replaced all engine drive belts / tensioners & pulleys All ok	
14/08/2024	682,292 kms	<b>Body Nose Cone</b> R-27069 Removed damaged roof cone and all side skirts and mounts.	KJS Fleet
13/08/2024		<b>Accident Damage</b> R-27056 Incident No: Metro130824INC1 Date of incident: 13/08/2024 Report Description: Thanh was making a U turn in a side street in Burwood , while doing a U turn he heard a noise , Thanh reversed back and the Aero foil off the roof fell . Thanh has taken the Aero foil off and will bring it back to the Depot for repair . Thanh will complete an incident report when he returns .	HNL Sydney Workshop
08/08/2024	681,908 kms	<b>BLINKER LIGHT</b> R-26977 Picked up vehicle from Daimler,removed dash and front grille,run wiring from left and right door indicators,through body into the dash,mounted new indicator lights and wired into existing loom.Re assemble dash and front Grille.Return vehicle to Daimler.	KJS Fleet
08/08/2024	681,902 kms	<b>DEFECT, NHVR ROADWORTHY</b> R-26982 Defect attached - AHV1529436 Repaired and cleared 1.Install indicators on dash 2. Daimler Huntingwood repair demister / blower fan 3.Replaced number plates 4.Repair front left lights - Checked all 5.Repair / re tension left rear under run bar Clear Defect - S.Rice 8/8/24 - CA2639115	Daimler Huntingwood, KJS Fleet
07/08/2024		<b>new rego plates</b> R-26973 NEW REGO PLATES - NEW NUMBER XP06CZ OLD PLATE HNL022	HNL Sydney Workshop
06/08/2024	681,685 kms	<b>A - 10K</b> S-11821 Carried out vehicle A service and inspection as per HNL checklist Replace light left rear upper Replace left indicator globe Pre rego inspection	KJS Fleet
25/07/2024	679,927 kms	<b>Heater Fault</b> R-26669 Check and repair heater fault - Daimler Huntingwood	Daimler Huntingwood
04/07/2024	678,960 kms	<b>DAMAGE - MIRROR</b> R-26678 Remove mirrors from arm and removed and replaced arm.Refit mirror and spotter.Removed door trim to run wires and secure and refit door panel.	KJS Fleet
20/06/2024	677,186 kms	<b>B - 30K</b> S-11534 DUPLICATE ENTRY Carried Out B Service as per HNL Checklist.Grease steer axle king pins and tailgate.A1 40%,A2 70%,A3 50%.	KJS Fleet
19/06/2024	677,186 kms	<b>B - 30K</b> S-11514	KJS Fleet
13/06/2024	676,389 kms	<b>SPOTTER MIRROR</b> R-26200 Removed and replaced O/S Spotter Mirror.	KJS Fleet
12/06/2024	676,217 kms	<b>Breakdown - Truck</b> R-26229 BREAKDOWN AT HAMILTON - BRAKE ISSUE TOW BACK TO THORNTON WORKSHOP CHECK ALL BRAKES / CALIPERS / SENSORS REPLACE DISC PADS ON 1ST DRIVE ROAD TEST OK	ONEILLS TOWING
11/06/2024	675,808 kms	<b>Heater Fault</b> R-26159 Inspected mirror assembly,attempted to tighten top and bottom point,still loose,found mounts cracked at bottom of arm,recommended replacing entire assembly and arm.Blower motor faulty requires replacement. Inspected heater and tested only blows cold air,even at operating temp,further inspection carried out and found heater core has been by passed from possible leak previously,unable to by access gearbox to identify record of leakage/by passing	KJS Fleet
21/05/2024	673,680 kms	<b>PRESSURE CHECKS</b> T-3995 TYRE PRESSURE CHECKS	Bridgestone Australia Ltd
14/05/2024		<b>DAMAGE - MIRROR</b> R-25835 Spotter mirror broken,replaced spotter assembly	KJS Fleet
07/05/2024	671,745 kms	<b>CLEARANCE LIGHT FAULT</b> R-25770 Inspected and found short in wiring and tested all ok - DVR 01677	KJS Fleet
09/04/2024	667,613 kms	<b>Check Vehicle Lights</b> R-25422	KJS Fleet

Date	Reading / Units	Type / Repairer Notes	Repairer
		Check no clearance lights Found open circuit breaker Reset & tested operation All ok Repair rear roller door & tested OK	
03/04/2024	667,613 kms	<b>Body Rear Roller Door</b> R-25461  Inspected & found fuses popped. Reset & tested. Was OK. Inspected wiring & no visual issues found. Replaced missing roller door rollers & replaced broken bracket. Found N/S roller door track damaged - recommend replacing roller door tracks.	KJS Fleet
02/04/2024	667,503 kms	<b>Power Steering Faults</b> R-25236  Check power steering box oil leaks Remove power steering box and sent for reseal at Hydrosteer Refitted box, replaced pinch bolt on column and check over All ok Re filled power steering fluid & road tested vehicle All ok	KJS Fleet
27/03/2024	667,503 kms	<b>ad blue</b> R-25292  Replace missing ad blue cap	KJS Fleet
25/03/2024	667,397 kms	<b>Steering Box Faulty</b> R-25273  Remove Steering Box - DVR 01849	KJS Fleet
29/02/2024	664,742 kms	<b>REAR FRAME DAMAGES</b> R-24974  REALIGN REAR FRAME AND INSTALL 756MM X 5MM STAINLESS STEEL FLATBAR TO REINFORCE. SEAL AREAS NEEDED. REFIT DAMAGED ROLLER DOOR TRACKS AND PANELS.	TRS
28/02/2024	664,742 kms	<b>A - 10K</b> S-10914  Carried out vehicle A service as per HNL checklist Replace tailgate remote Check and repair wiring to vehicle lights All ok	KJS Fleet
15/02/2024	663,945 kms	<b>Accident Damage</b> R-24821  Fuel tank strap damaged Removed driver side fuel tank & replace rear J bracket due to damage Replaced strap & tension ALI ok	KJS Fleet
09/02/2024	663,039 kms	<b>Tailgate Fault</b> R-24770  Check and found tailgate remote damaged Replaced tailgate remote & tested operation Replace tailgate safety chain All ok Replaced missing ad blue cap	kjs
05/02/2024	663,039 kms	<b>Accident Damage</b> R-24698  REPLACED DAMAGED TOP CAP	HNL Sydney Workshop
11/01/2024	660,303 kms	<b>Damage - Tailgate</b> R-24518  Replace tailgate hand controller with 2nd hand unit Tested operation All ok	KJS Fleet
09/01/2024	660,257 kms	<b>Breakdown - Truck</b> R-24508  Refilled with 20 ltrs diesel Bled and started engine All ok	KJS Fleet
27/12/2023	658,157 kms	<b>Tailgate Fault</b> R-24382  Check and repair tailgate remote wiring harness Tested operation All ok	KJS Fleet
12/12/2023	656,709 kms	<b>Coolant Leak</b> R-24199  Check and found heater core leaking coolant onto cabin floor Bypassed heater core so truck can be used Check for other leaks All ok	KJS Fleet
12/12/2023	656,883 kms	<b>BRAKE WARNING</b> R-24218  Check brake warning on dash Inspect all brake pad linings for wear all ok Remove and found damaged wiring to axle 1 left brake pad wear sensor insecure Refitted and checked over All ok Repair rear roller door & tested all ok	KJS Fleet
10/11/2023	652,772 kms	<b>BRAKE PADS</b> R-23951  Replace A2 & A3 brake pads Replace brake pad wear sensors All ok	KJS Fleet
09/11/2023	651,433 kms	<b>DRIVE TYRES</b> T-3620  DRIVE TYRES 3/4/5/6 FITTED 1X AUSTONE 305/70R19.5 FITTED 3X 305/70R19.5 FROM STOCK	ROYALE TRUCK SERVICES
09/11/2023	652,772 kms	<b>A - 10K</b> S-10327  Carried out vehicle A service and inspection as per HNL checklist Grease tailgate Grease steer axle king pins Replace tailgate latch Topped up engine 4 ltrs 10/40w Replace damaged passenger side spotter mirror glass	KJS Fleet

Date	Reading / Units	Type / Repairer Notes	Repairer
01/11/2023		<b>Check Vehicle Lights</b> R-23858 Check indicator damaged - Check lights	KJS Fleet
23/10/2023	650,601 kms	<b>Tailgate Fault</b> R-23772 Travel to breakdown - Blackett Inspect and found tailgate wiring fault - Check and repair Tested operation All ok	KJS Fleet
20/09/2023	646,129 kms	<b>Tailgate Fault</b> R-23423 Remove and replace tailgate hand controller wiring loom Tested operation All ok	KJS Fleet
14/09/2023	645,573 kms	<b>coolant fault</b> R-23311 Check coolant low warning on dash Topped up system Check over for leaks All ok	KJS Fleet
19/08/2023	642,806 kms	<b>SPOTTER MIRROR</b> R-23039 Replaced passenger side spotter mirror	KJS Fleet
18/08/2023	643,104 kms	<b>BRAKES</b> R-23062 REPLACE PADS AND ROTORS ON STEER AXLE REPLACE PADS / ROTORS / HUB SEALS ON AXLE 3 REPLACE BRAKE SENSORS ON AXLE 3	HNL Sydney Workshop
16/08/2023	642,699 kms	<b>DAMAGED MIRROR, Tailgate Fault</b> R-22982 Check and repair wiring to tailgate hand controller Replace tailgate isolation switch and tested operation (Parts on order for spotter mirror) Remove and replace left side spotter mirror - All ok 16/8/23	KJS Fleet
10/08/2023		<b>2024 REGO PAPERS, REGISTRATION RENEWAL</b> R-22906 REGO RENEWAL ATTACHED	HNL WORKSHOP
08/08/2023	624,004 kms	<b>STEER TYRES</b> T-3368 11001529 305/70R19.5 148/145M BS R227 2 626.31 1,252.62 Positions: 1,2 33000084 FIT TBR TYRE 2 17.69 35.38 Positions: 1,2 33000517 REMOVAL:CUSTOMER PULL POINT 2 Positions: 1,2 33000115 SVC CALL OUT NORM HRS /15 MIN 6 20.81 124.86 LESS TRADEIN/ PURCHASE: 77000188 CASE STOCK 305/70-19.5	Bridgestone Australia Ltd
08/08/2023	642,004 kms	<b>B - 30K</b> S-9823 Carried out B service and inspection as per HNL checklist All ok Grease all chassis points Remove and replace batteries due to always having to jump start in the morning Check vehicle charge rate and tested all ok	KJS Fleet
01/08/2023	641,063 kms	<b>engine oil</b> R-22810 Check engine oil level Topped up 4Ltrs 15w40 engine oil	KJS Fleet
25/07/2023	640,160 kms	<b>No Start</b> R-22752 No start - Flat battery Jump started and check charge rate All ok	KJS Fleet
10/07/2023	638,965 kms	<b>Pre Rego Check over</b> R-22596 Pre rego check over Replace left front indicator globe due to faded white light flashing Replace worn out brake pedal rubber Replace damaged indicator lamp assembly right side door Repair front number plate letters - (Found A1 right forward spring eye bush worn - not enough time to repair)	HNL Fleet Sydney
10/07/2023		<b>NHVR ROADWORTHY</b> R-22618 NHVR annual inspection - Passed	NHVR
10/07/2023	638,994 kms	<b>Suspension Fault</b> R-22597 Check and repair Axle 1 left and right side spring eye bushes Remove and replace A1 left and right side forward spring eye bushes All ok	HNL Sydney Workshop
06/07/2023	638,653 kms	<b>A - 10K</b> S-9602 Carried out vehicle A service and inspection as per HNL checklist Grease tailgate and king pins Replaced left side headlight globe Replace missing reflectors Replace fire extinguisher inside cabin	KJS Fleet
30/06/2023	637,774 kms	<b>engine oil</b> R-22512 Check and top up engine oil level 1 ltr Check and top up coolant level 1 ltr	HNL Fleet Sydney
22/06/2023	636,427 kms	<b>Breakdown - Truck</b> R-22421	HNL Fleet Sydney

Date	Reading / Units	Type / Repairer Notes	Repairer
		Travel to Great Western Hightway Minchinbury - Truck run out of fuel Found stuck in left lane of highway Set up Traffic Control Plan - Filled 30L diesel Bled system & run engine All ok	
13/06/2023	635,157 kms	<b>engine oil</b> R-22322 Check engine oil low on dash Topped up engine oil 3 1/2 Ltrs All ok	HNL Fleet Sydney
30/05/2023	633,818 kms	<b>DRIVE TYRES</b> T-3221 DRIVE TYRES POS 5/6/7 FITTED 305/70R19.5 BRIDGESTONE M729	Bridgestone Australia Ltd
30/05/2023	633,725 kms	<b>Check Vehicle Lights</b> R-22171 Check all vehicle lights Found left indicator lamp at door damaged - not working Remove & replace lamp assembly All ok	HNL Sydney Workshop
09/05/2023	630,450 kms	<b>Tailgate Fault</b> R-21975 Check tailgate not working, battery flat Test & check vehicle charge to batteries. OK Remove & replace tailgate batteries Tested operation all ok Grease tailgate & check operation Repair electrical connection at PC board Replaced positive terminals on tailgate batteries	HNL Fleet Sydney
03/05/2023	629,428 kms	<b>Tailgate Fault</b> R-21937 Check tailgate fault Tailgate fluid low, top up 2L Tested operation Replace tailgate chain latch All ok	HNL Fleet Sydney
15/04/2023	627,503 kms	<b>Accident Damage</b> R-21754 Check right side fuel tank strap damaged REPLACE TANK BRACKET / STRAP / ISOLATORS	HNL Fleet Sydney
14/04/2023	627,018 kms	<b>DRIVE RECAPS</b> T-3128 FIT 2X DRIVE RECAPS FROM COMPANY STOCK POS 8/12	Bridgestone Australia Ltd
12/04/2023	627,109 kms	<b>ABS Fault</b> R-21731 Connect laptop & record fault codes related to axle 2 left wheel speed sensor Remove & replace abs wheel speed sensor axle 2 left Clear codes & road tested All ok	HNL Fleet Sydney
30/03/2023	625,855 kms	<b>Cab Window Faulty</b> R-21606 Remove & replace driver side window switch & tested operation All ok	HNL Fleet Sydney, KJS Fleet
10/03/2023	622,951 kms	<b>A - 10K</b> S-8801 Carried out vehicle A service & inspection as per HNL checklist All ok	HNL Fleet Sydney
10/03/2023	622,951 kms	<b>Brake Disc Pad - Replacement</b> R-21371 Replace axle 2 & 3 brake pads & wear sensors Replace axle 3 disc rotors & re pack wheel bearings with new grease Replace axle 3 hub seals Adjust all brakes Road Test	HNL Fleet Sydney
01/03/2023	621,519 kms	<b>Check Vehicle Lights</b> R-21285 Re position rear number plate light & tested operation All ok	KJS Fleet
03/02/2023	617,984 kms	<b>Coolant Leak</b> R-20923 Coolant leak at heater core Remove & replace heater core Invoice attached	Daimler Huntingwood
17/01/2023	615,702 kms	<b>Coolant Leak</b> R-20852 Check coolant leak - Leaking from heater core Operations desperate to use vehicle Remove hoses from heater core & bypassed Check for leaks All ok (Daimler Huntingwood booking 3/2/23)	HNL Fleet Sydney
11/01/2023	614,536 kms	<b>engine oil level low</b> R-20786 Check & report driver complaint of low on engine oil Top up engine oil 5L Check level & check for leaks All ok	HNL Fleet Sydney
11/01/2023		<b>ad blue</b> R-20796 Replace Ad Blue cap	HNL Fleet Sydney
16/12/2022	611,234 kms	<b>B - 30K</b> S-8217 Carried out B service & inspection as per HNL checklist All ok Replaced wiper blades Repaired clearance light at left rear	HNL Fleet Sydney
08/12/2022	609,983 kms	<b>TRANSMISSION AND DIFF OILS</b> R-20509 Remove & replace diff only only (Mineral Oil)	HNL Fleet Sydney
14/11/2022	605,542 kms	<b>Engine Light</b> R-20191	HNL Fleet Sydney

Date	Reading / Units	Type / Repairer Notes	Repairer
		Check engine light on dash Re fit left front upper cap to body Could not fault engine warning light on dash Repaired coolant leak to ad Blue pump Road tested for faults All ok	
11/11/2022	605,542 kms	<b>Coolant Leak</b> R-20223 Check and report coolant leak	HNL Fleet Sydney
31/10/2022	605,008 kms	<b>Transmission Fault</b> R-20102 CHECK TRANS LIGHT ON DASH - TRUCK HAS TRANSMISSION ISSUE - DVR 02618 WILL NOT DRIVE OR CHANGE GEARS - TRUCK TAKEN TO DALTRANS DALTRANS OVERHAUL TRANSMISSION REPAIR REAR LIGHTS - KJS FLEET	HNL Sydney Workshop
06/10/2022	601,267 kms	<b>Brake - Park Brake Fault</b> R-19822 RECTIFY PARK BRAKE HANDLE NOT WORKING CORRECTLY	HNL Fleet Sydney
27/09/2022	599,862 kms	<b>Trailer Side Wall Damage/Repairs</b> R-19788 RE-FIT L/H SIDE WALL TOP STRIP	HNL Sydney Workshop
23/09/2022		<b>ELECTRICAL LIGHT ISSUE</b> R-19756 repair interior pan light wiring	MJR Auto Electrical
09/09/2022	596,622 kms	<b>RMS Defect</b> R-19647 RMS DEFECT HVN0629272 REPAIRED BRAKE ISSUE DEFECT CLEARED VVG HUNTINGWOOD - CA2246006	Daimler Trucks Huntingwood
01/09/2022	595,915 kms	<b>AIR LEAK</b> R-19597 RECTIFY AIR LEAK REPLACE LEAKING CIRCUIT BRAKE VALVE RUN AND TEST OK	HNL Fleet Sydney
17/08/2022		<b>Tailgate Fault</b> R-19466 SELF LEVELING ISSUE REPAIRED MERCURY SWITCH REPAIRED	TRS
09/08/2022		<b>CTP</b> O-2247	
09/08/2022		<b>Registration</b> O-2248	
02/08/2022	592,110 kms	<b>RMS Defect</b> R-19396 CLEAR RMS DEFECT	Daimler Trucks Huntingwood
20/07/2022	590,631 kms	<b>new engine</b> R-18636 NEW ENGINE - APPROVED BY JEFF KETTLE	Daimler Trucks Huntingwood
18/07/2022	590,658 kms	<b>CLEARANCE LIGHT FAULT</b> R-19225 RECTIFY CLEARANCE LIGHTS INOP REPLACE LIGHT ASSEMBLIES FRONT OF BODY	HNL Sydney Workshop
10/05/2022		<b>Breakdown - Tow</b> R-18616 TOW FROM METCASH TO DAIMLER BLOWN ENGINE	ONEILLS TOWING
10/05/2022	590,599 kms	<b>Call out , Engine Oil Leak</b> R-18548 ATTEND CALL OUT AT GORDON , FOUND MAJOR OIL LEAK COMING FROM ENGINE ORGINSED TOW TRUCK .	HNL Sydney Workshop
06/05/2022	590,443 kms	<b>AdBlue Cap</b> R-18528 REPLACED MISSING ADBLUE CAP	HNL Sydney Workshop
13/04/2022		<b>Body Rear Door Repair</b> R-18384 REPAIR REAR ROLLER DOOR AS PER ATTACHED	TDC TRUCK DOORS & CURTAINS
05/04/2022	583,621 kms	<b>DAMAGE - MIRROR</b> R-18287 REMOVE AND REPLACED DAMAGED SPOTER MIRROR .	HNL Sydney Workshop
02/03/2022	580,146 kms	<b>Seat Belt</b> R-18030 REPOSITIONED MOUNT POINT FOR SEAT BELT AND CEHCKED OPERATION ALL OK .	HNL Sydney Workshop
01/03/2022	580,120 kms	<b>Air Compressor Fault</b> R-18016	HNL Sydney Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		INSPECTED AND FOUND DISCHARGE LINE CAME OUT OF HEAD AND DAMAGED THE THREAD . DRAINED COOLANT AND REMOVED COMPRESSOR HEAD , CLEANED SURFACES , FITTED NEW HEAD FILLED COOLANT	
26/02/2022		<b>Electrical - Ignition Switch Key</b> R-18296	HNL Sydney Workshop
23/02/2022	579,466 kms	<b>Body Rear Roller Door</b> R-17982 INSPECTED AND FOUND ROLLERS OUT OF THE TRACKS . REFITTED ROLLERS INTO TRACKS AND LUDED TRACKS AND REPLACED 1 HINGE DVR 03250	HNL Sydney Workshop
02/02/2022	576,840 kms	<b>left side clearance lights</b> R-17821 FITTED RED AND AMBER CLEARANCE LIGHT N/S REAR , CHECK OPERATION ALL OK .	HNL Sydney Workshop
27/01/2022	576,289 kms	<b>hand control</b> R-17771 REMOVE AND REPLACED HAND CONTROL AND TESTED OPERATION ALL OK .	HNL Sydney Workshop
31/12/2021	572,458 kms	<b>DRIVE RECAPS</b> T-2271 REPLACE POSITION 9,10,11,12 DRIVE TIRES	Bridgestone Australia Ltd
27/11/2021	568,442 kms	<b>STEER AND DRIVE</b> T-2216 REPLACE DRIVE TYRES POS 5/6/7/8 FITTED BANDAG RECAPS REPLACE STEER TYRES POS 1/2 FITTED 305/70R19.5 BRIDGESTONE R227	Bridgestone Australia Ltd
12/11/2021		<b>Check Engine Fluid Levels</b> R-17102 topped up coolant check warning on dash all okay 1L pre mix	HNL Sydney Workshop
07/10/2021	562,164 kms	<b>Body Rear Roller Door</b> R-16732 INSPECTED REAR DOOR FOUND 1 MOUNT AND ROLLER MISSING FITTING NEW ROLLER AND MOUNT X 1 ROLLER X 1 ROLLER MOUNT SPRAYED ROLLER SPRAY ON ALL ROLLERS DOOR WILL NEED TO BE SERVICED WITH NEW ROLLERS AND MOUNTS NEED TO WAIT TILL RESTOCK INSPECTED HAND CONTROL FOUND LOOSE LOCK NUT TOP OFF HAND CONTROL TIGHTEN NUT OPERATED CONTROL ALL WORKING CORRECTLY	HNL Sydney Workshop
27/09/2021	560,627 kms	<b>front brake pads</b> R-16595 REMOVED FRONT WHEELS AND INSPECTED FRONT BRAKES AND BRAKE PADS NEED REPLACING BUT ROTORS OK . REMOVE AND REPLACE FRONT PADS AND REFIT WHEELS AND TENSIONED AS NEEDED AND ROAD TEST ALL OK .	HNL Sydney Workshop
27/09/2021	560,627 kms	<b>Electrical Wiring - Faulty</b> R-17141 Travel to Beacon Hill. Test starting, jump start and locate faulty in wiring. Get vehicle back to yard and repair wiring.	MJR Auto Electrical
14/09/2021		<b>Electrical - Alternator Replacement</b> R-17135 Travel to yard. Check for V belt wearing, check wiring and report. Replace alternator and retest	MJR Auto Electrical
31/08/2021	557,057 kms	<b>Rego Inspection</b> R-16303 REPLACED AMBER REFLECTORS REPLACED R/H REAR MUD FLAP REPLACED R/H SIDE BLINKER GLOBE	HNL Sydney Workshop
27/08/2021	556,810 kms	<b>RUNOUT TYRE</b> T-1982 RUNOUT TYRE POS 2	Bridgestone Australia Ltd
26/08/2021	556,810 kms	<b>B - 30K</b> S-6135 CARRY OUT 'B' SERVICE	HNL Fleet Sydney
26/08/2021		<b>Breakdown - Tailgate</b> R-16249 ATTEND BREAK DOWN FOR TAILGATE NOT WORKING , FOUND NO POWER GETTING TO CONTROL BOX , TESTED MAIN FUSE , HAD POWER BOTH SIDES , GETTING NO POWER TO KILL SWITCH UNABLE TO LOCATE PROBLEM , CALL OUT MJR	HNL Sydney Workshop
23/08/2021	555,814 kms	<b>engine oil</b> R-16193	HNL Fleet Sydney
21/08/2021		<b>REGISTRATION PAPERS</b> R-16158 COPY OF REGISTRATION PAPERS - EXPIRY 12/8/2022	HNL WORKSHOP
12/08/2021		<b>Registration</b> O-1766	

Date	Reading / Units	Type / Repairer Notes	Repairer
10/08/2021		CTP O-1767	
16/07/2021	415,741 kms	<b>Tailgate Fault</b> R-15641 Removed and replaced 3 new cartridge valve on pump block and rewired hand control to suit tailgate Note After hours call out hunting wood HNL	Trs
15/07/2021	550,417 kms	<b>hand control</b> R-15679 REMOVE AND REPLACED HAND CONTROL AND CHECK OPERATION ALL OK . INSPECTED SOLENOID ON REAR MOTOR FOUND SOLENOIDS LOOSE TIGHTEN ALL	HNL Sydney Workshop
05/07/2021	550,401 kms	<b>Brake Disc Pads &amp; Rotors</b> R-15453 INSPECTED AND TESTED BRAKES TEST OPERATION OFF PARK BRAKE IN GEAR AND OUT OF GEAR ALL OK PARK BRAKE WORKING .	HNL Sydney Workshop
21/05/2021	543,806 kms	<b>brakes rotors and bearings</b> R-14866 removed and Replace axle 2 brake disc rotors & pads DVR 00451 replaced hubs seals and ABS Rings removed and replaced axle 3 brake pads and wear sensors	HNL Fleet Sydney
14/05/2021		<b>RUN OUT TYRE</b> T-1682 FIT RUN OUT TYRE POS 9	Bridgestone Australia Ltd
11/05/2021	542,765 kms	<b>hand control</b> R-14775 found wiring and buttons to be rusted on inside of control also found cut wiring inside replaced with 2nd hand working control with new buttons rewired wiring tested hand control all working	HNL Fleet Sydney
20/04/2021	538,742 kms	<b>A/C Fault, Air Horn</b> R-14343 Check horn not working Check a/c fan not working Remove & replace horn assembly, check operation. All ok Remove & replace A/C blower fan motor & fan speed resistor Tested operation All ok Grease tailgate	HNL Fleet Sydney
12/04/2021	537,868 kms	<b>repair tyre</b> T-1557 Repair tyre Position 9	Bridgestone Australia Ltd
01/04/2021	534,957 kms	<b>Repairs</b> R-14332 Check engine oil & coolant levels Top up washer bottle level Grease tailgate & steer axle king pins Check brake pads wear on all wheels Remove & replace red/amber clearance lamp, left side - Wire & test lights	HNL Fleet Sydney
11/03/2021	530,775 kms	<b>Check Vehicle Defects</b> R-13997 Replace right front indicator globe Replace left front upper clearance light globe Clean minor sharp edges left & right rear corners Re position reverse camera inside dash Remove & replace axle 1 right front spring eye bush	HNL Fleet Sydney
28/02/2021	528,344 kms	<b>Mirror Adjustment, Tailgate - Grease</b> R-13850 Rectify mirror not positioned correctly Driver complaint, re position left & right side spotter mirrors to suit driver Grease tailgate	HNL Fleet Sydney
15/01/2021	521,628 kms	<b>Fire Extinguisher, Service</b> R-13292 Carried out vehicle A - Service & inspection Remove & replace inside cabin Fire Extinguisher & mounting bracket to floor Replace missing screws from left side front step	HNL Fleet Sydney
03/12/2020	516,350 kms	<b>Puncture Repair</b> T-1461 Puncture - repairable as per Attachment	ADZ Tyre & Battery
02/12/2020	516,159 kms	<b>Tailgate - Grease</b> R-12807 Grease tailgate Check operation of hand control Replaced damaged isolation key & attached to control box All ok	HNL Fleet Sydney
07/11/2020	513,241 kms	<b>B - 30K</b> S-4915 Carried out vehicle B service & inspection, as per HNL checklist Replaced engine oil filter Replaced engine fuel filters Replaced engine air filters Replaced air drier filter Grease tailgate & steer axle king pins Carry out all general service checks Replaced axle 3 right shock absorber Tension several loose body mounting bolts Remove & replaced exhaust dump pipe clamp & mounting bolts Tension leaking AdBlue injector at dump pipe Repair tailgate hand control wiring, pulled from case Remove & replaced left & right rear marker plates with upgraded version Remove steer wheels, clean & paint rims silver. Re fit & tension wheels Clean & paint axle 2 & 3, left & right rims silver	HNL Fleet Sydney
23/10/2020		<b>Pressure Check</b> T-1159	ADZ Tyre & Battery

Date	Reading / Units	Type / Repairer Notes	Repairer
		Pressure Check as per Attachment	
20/10/2020	509,581 kms	<b>Air Leaks</b> R-11934  Air Leak at Foot Valve Inspect & found air leak at foot valve assembly Remove & replaced foot valve Remove & replaced brake pedal rubber Tested for air leaks All ok Vehicle sent to Gilbert & Roach Huntingwood for Brake Test - PASSED attached Check engine oil & coolant level Greased tailgate & steer axle king pins	HNL Fleet Sydney
12/10/2020	506,574 kms	<b>Check Brake Operation</b> R-11922  Inspect vehicle for brake wear Axle 2 brake pads low, raise axle on stands Remove & replaced axle 2 brake pads left & right Adjust brakes Re fit wheels & tension wheel nuts Check engine oil level Check coolant level Grease steer axle king pins Grease tailgate Replaced missing axle 2 rubber bump stop on axle housing, left side Replaced x 2 missing red reflectors to body Replaced x 2 missing amber reflectors to body	HNL Fleet Sydney
11/09/2020	1 kms	<b>Pressure Check</b> T-990  Pressure Check as per Attachment	ADZ Tyre & Battery
27/08/2020	9,990 kms	<b>Puncture Repair</b> T-917  Puncture - repairable as per Attachment	ADZ Tyre & Battery
14/08/2020	495,826 kms	<b>Body Rear Roller Door, Service</b> R-11059  Carry out A - Service & inspection Check engine oil & coolant levels Check all lights Grease tailgate Grease steer axle king pins Check brake pad wear Carry out visual inspection Replace x 5 rollers from rear door Replace centre hinge & mounting bolts Shape tracks in damaged areas Tested operation of rear door Replaced several sections of interior pogo rail Remove & replaced left & right axle 3 shock absorbers Replaced right side lower shock mounting bolt & nut	HNL Fleet Sydney
06/08/2020		<b>Registration</b> O-1232	
06/08/2020		<b>CTP</b> O-1233	
03/07/2020		<b>Tyres - Steer, Wheel Alignment</b> R-10459  Replace steer axle tyres Bridgestone	HNL Sydney Workshop
03/07/2020		<b>Pressure Check</b> T-734  Pressures Only as per Attachment	ADZ Tyre & Battery
05/06/2020		<b>Body Repair</b> R-10077  Repair front wall & interior panels	
05/06/2020	482,165 kms	<b>Puncture Repair</b> T-533  Puncture Repairs inc. S&F (x1) as per Attachment	ADZ Tyre & Battery
03/06/2020	482,060 kms	<b>Tailgate Operating Fault</b> R-10042  Check & found tailgate hand control damaged Remove old case & wiring Replace with new tailgate hand control & wiring to control box Fitted magnet to case Tested operation. All ok Greased tailgate	HNL Sydney Workshop
22/05/2020		<b>Pressure Check</b> T-444  Pressures Only (x10) as per Attachment	ADZ Tyre & Battery
19/05/2020	479,706 kms	<b>B - 30K</b> S-4170  Carry out B service & inspection as per HNL service sheet Grease tailgate & king pins Replaced x 1 grease nipple o/s upper tilt ram Road Test Remove & replaced damaged front sun visor assembly Fitted low clearance sticker to rear frame	HNL Sydney Workshop
21/04/2020		<b>New Tyres</b> T-339  305/70r 19.5 Drive pos 9,10 as per Attachment	ADZ Tyre & Battery
21/04/2020	473,806 kms	<b>Tailgate Operating Fault</b> R-9331  Test batteries and found they need replacing Test motor and found pump leaking between motor and pump Motor damaged causing flat batteries Replaced tailgate batteries Replaced Tailgate motor and pump Cleaned inside power pack Replaced hydraulic oil and filter Replaced all dowdy washers Check operation Greased tailgate	TRS Onsite Mechanic
21/03/2020	467,912 kms	<b>Tailgate Repairs</b> R-8895	HNL Sydney Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		Saturday 21/3/2020 Inspect & found damaged tailgate hand control Removed & replace tailgate hand control including new wiring to control box Wire up & tested operation. All ok Fitted magnet to hand control Grease tailgate All ok	
04/02/2020	460,832 kms	<b>Engine Overheating</b> R-7844 inspected engine and truck for coolant leaks none found found level low and the coolant watered down removed and replaced thermostat replaced coolant tested for leaks none found all ok test drove truck still no leaks found	HNL Sydney Workshop
24/01/2020	458,788 kms	<b>Brake Hand Control</b> R-7676 rewired hand control tested all ok	HNL Sydney Workshop
15/01/2020	457,283 kms	<b>Brake Fault</b> R-7488 jacked up steer axle removed wheels removed brake boosters and calipers removed and replaced both rotors refitted boosters and calipers fitted new brake pads adjusted brakes refitted wheels lowered axle removed and replaced axle 2 air bags removed and replaced wiper blades	HNL Sydney Workshop
13/01/2020	457,036 kms	<b>Damage - Rearview Mirrors</b> R-7417 Saturday - 11/1/2020 Inspect & find damage to driver side main & spotter mirror head Remove & replace both damaged mirrors complete Adjust & clean All ok.	HNL Sydney Workshop
07/01/2020		<b>Brake - Warning</b> R-7288 Found axle 3 brake wear sensor wiring damaged Remove & replace wiring to brake pad axle 3 Road Test Grease Tailgate Replace o/s spotter mirror Replace number plate lamp Replace o/s headlight globe Clean cabin Requires steer axle disc rotors Requires drive axle air bags	HNL Sydney Workshop
06/01/2020		<b>Body Rear Doors</b> R-7514 Repair Door as per Attachment	
22/12/2019	453,349 kms	<b>Breakdown - After Hours</b> R-7101 Contact - Darren Flemming / 7.20pm Travel to HNL yard Huntingwood Rectify air leak Inspect & find axle 3 right air bag damaged Remove & replace damaged part Tested operation of suspension from hand control Test for leaks All ok.	HNL Sydney Workshop
20/12/2019	453,090 kms	<b>Brake Hand Control</b> R-7092 rewired hand control tested all ok	HNL Sydney Workshop
17/12/2019	452,156 kms	<b>Service</b> R-6995 topped up engine oil topped up coolant checked all other fluids all ok checked lights checked tires greased truck and tailgate damage to panel on RHS in front of drive axle fitted new fleet stickers to body checked and reported brakes: steer: 6mm 60% drive: 8mm 80% lazy: 9mm 90%	HNL Sydney Workshop
06/12/2019	451,496 kms	<b>Tailgate - Grease</b> R-6707 greased and inspected tailgate greased king pins fitted x1 set of safety triangles to truck replaced x1 grease nipple	HNL Sydney Workshop
05/12/2019	451,472 kms	<b>AdBlue Fault</b> R-7077 Leaking from fittings and filter housing as per Attachment	Daimler Huntingwood
04/12/2019	451,121 kms	<b>Damage - Rearview Mirrors</b> R-6675 removed and replaced damaged LHS mirror removed and replaced spotter mirrors on LHS and RHS	HNL Sydney Workshop
08/11/2019	446,220 kms	<b>Tailgate Safety Chain</b> R-6213 contacted at 4:18 am on 7/11/2019 traveled to workshop inspected fault of tailgate inop found hand control inop removed and replaced hand control and harness tested system all ok	HNL Sydney Workshop
05/11/2019	445,515 kms	<b>Brake Fault</b> R-6134 inspected brake warning on dash jacked up and removed wheels off the drive and lazy axle upon inspection we found the brakes had been locking on on the drive axle and the pads were wearing uneven on the lazy axle removed and replaced brake pads on the lazy and drive axle tested drive axle booster and found a small amount of air leaking from the RHS drive axle booster removed and replaced drive axle boosters left & right refitted all wheels test drove vehicle all ok greased and inspected tailgate	HNL Sydney Workshop
30/10/2019	444,189 kms	<b>Engine Light</b> R-5946 Daimler Huntingwood Remove & replace AdBlue injector / difuser	Daimler Huntingwood
30/10/2019	444,189 kms	<b>Engine Valve Adjustment</b> R-5940	Daimler Huntingwood

Date	Reading / Units	Type / Repairer Notes	Repairer
		Carry out Valve Adjustment	
27/10/2019	444,189 kms	<b>C - 120K S-3044</b>  Carry out C service Replace all engine drive belts, tensioners & idler pullys Replace transmission oil & filters Replace diff oil Replace power steering filter Replace air dryer filter Replace AdBlue filter cleaned cab checked all lights removed and replaced LHS front indicator assembly checked all tires greased truck and tailgate sun viser broken brakes: steer: 7mm 70% drive: 8mm 80% lazy: 7mm 70% test drove truck all ok	HNL Sydney Workshop
10/10/2019	441,105 kms	<b>Repairs R-5558</b>  Contact - Scott Ford / 7pm - 11pm. Travel to Sandringham Rd, Dolls Point. Rectify vehicle run out of fuel. Found engine wont start & vehicle stuck parked across lane. Set up triangles & position ute with beacon lights to block off lane & create safe working area. Fill 40L Diesel into fuel tank, crank engine over but would not start. Raise cabin & remove fuel filter housing, fill with diesel. crank engine over but would not start. Crack fuel injector lines & bleed system. Crank & start engine. All ok. Lower cabin & direct driver to closest fuel station. All ok	HNL Sydney Workshop
04/10/2019	440,240 kms	<b>Tailgate - Grease R-5492</b>  greased and inspected tailgate greased king pins	HNL Sydney Workshop
11/09/2019	436,004 kms	<b>Service R-5148</b>  CHECKED ALL LIGHTS CHECKED ALL FLUIDS GREASED TRUCK AND TAILGATE CHECKED TIRES CHECKED AND REPORTED BRAKES: STEER: 7MM 70% DRIVE: 8MM 80% LAZY: 7MM 70%	HNL Sydney Workshop
21/08/2019	432,104 kms	<b>Service R-4824</b>  CHECKED ALL FLUIDS TOPPED UP ENGINE OIL 4 LTRS CHECKED ALL LIGHTS GREASED TRUCK AND TRAILER CHECKED ALL TIRES CLEANED CAB INSPECTED BRAKES FOUNT STEER LOW REPLACED PADS FOUND DRIVE LOW REMOVED WHEELS AND FOUND CRACKED ROTORS REMOVED AXLES REMOVED BOOSTERS AND CALIPERS REMOVED HUBS REMOVED ROTORS UPON REMOVING BEARINGS THEY CRACKED REMOVED AND REPLACED ALL DRIVE AXLE BEARINGS FITTED NEW ROTORS FITTED HUBS FITTED CALIPERS AND BOOSTERS FITTED NEW BRAKE PADS FITTED WHEELS ADJUSTED WHEEL BEARINGS FITTED AXLES ENGINE LIGHT IS ON - Daimler Huntingwood / Replaced Adblue pump	HNL Sydney Workshop
12/08/2019		<b>CTP O-676</b>	
12/08/2019		<b>Registration O-675</b>	
08/08/2019	429,554 kms	<b>Electrical Wiring - Faulty R-4699</b>  FIXED UP WIRING THAT WAS RIPPED OUT STRAIGHTENED BRACKET FOR MARKER LIGHT	HNL Sydney Workshop
11/07/2019		<b>Defect Repairs R-4466</b>  Replace indicator lamp assembly Replace dash indicator globe Replace right spotter mirror assembly	HNL Sydney Workshop
28/06/2019	426,108 kms	<b>Electrical - Headlight Globe R-4398</b>  removed and replaced LHS head light globe	HNL Sydney Workshop
27/06/2019	423,146 kms	<b>Body Damage R-4376</b>  REFITTED CORNER CAP	HNL Sydney Workshop
21/06/2019	422,380 kms	<b>Check Engine Fluid Levels R-4345</b>  TOPPED UP COOLANT WITH 1LTR	HNL Sydney Workshop
26/05/2019	419,007 kms	<b>Tailgate - Grease R-4167</b>  GREASED TAILGATE AND INSPECTED FITTED COVER TO HYDRAULIC BOX AND NEW STRAPS	HNL Sydney Workshop
20/05/2019	415,741 kms	<b>Tailgate Repairs R-4128</b>  Replace tailgate pins & bushes/ TRS invoice attached.	TRS
03/05/2019	415,736 kms	<b>B - 30K S-2469</b>  Carry out B service removed and replaced engine oil and filter removed and replaced fuel filters removed and replaced air filter greased truck and tailgate checked all lights checked all tires checked and reported brakes steer: 6mm 60% drive: 6mm 60% lazy: 6mm 60% pin fallen out of tailgate gone to TRS damage to top LHS of fridge body gone to TRS	HNL Sydney Workshop
31/03/2019	408,077 kms	<b>Service R-3728</b>	HNL Sydney Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		CARRY OUT A SERVICE CHECKED ALL FLUID LEVELS CHECKED ALL LIGHTS CHECKED ALL TIRES CHECKED AND REPORTED BRAKES STEER: 6MM 60% 1ST DRIVE: 6MM 60% 2ND DRIVE: 6MM 60% GREASED TAILGATE CLEANED CAB	
15/03/2019		<b>Cooling System - Leaks</b> R-3622	HNL Sydney Workshop
15/03/2019	408,559 kms	<b>Cooling System - Leaks</b> R-3665 drained coolant removed and replaced radiator header tank jacked up cab removed and replaced air compressor cylinder head bleed cooling system checked for leaks none found carried out tail light upgrade made new brackets wired in new LED tail lights tested system all ok	HNL Sydney Workshop
10/03/2019	407,220 kms	<b>Service</b> R-3611 CHECKED ALL FLUID LEVELS CHECKED ALL LIGHTS CHECKED AND REPORTED BRAKES: STEER: 6MM 60% 1ST DRIVE: 6MM 60% 2ND DRIVE: 6MM 60% CHECKED ALL TIRES NEEDS: COOLANT HEADER TANK AIR COMPRESSOR HEAD	HNL Sydney Workshop
08/03/2019	406,416 kms	<b>Electrical - Blinker Fault</b> R-3571 removed and replaced RHS front indicator assembly	HNL Sydney Workshop
16/02/2019	402,999 kms	<b>Tailgate Operating Fault</b> R-3520 Saturday - 16/2/2019 Inspect to find tailgate hand control has been crushed & damaged. Removed hand control & wiring, re wire in new hand control & lead to control box. Solder all wiring joints & insulate. Tested operation of tailgate. Grease all tailgate pivot points. All ok.	Lets Torque Mechanical
15/02/2019		<b>Tailgate Repairs</b> R-3433 Remove & replace left tilt ram lower pin & bushes.	Auslift Wetherill Park
19/01/2019	398,640 kms	<b>Electrical - Headlight Globe</b> R-3265	HNL Sydney Workshop
18/01/2019	397,802 kms	<b>Cooling System - Leaks</b> R-3212 diagnosed coolant leak: found coolant leak coming from water pump drained coolant removed belt and tensioner removed coolant lines and sensors removed water pump and thermostat housing cleaned surfaces fitted new water pump and thermostat fitted all coolant lines and sensors fitted belt and tensioner filled with coolant started truck bleed system washed engine test drove all good rechecked for leaks no leaks	HNL Sydney Workshop
11/01/2019	396,442 kms	<b>Tailgate Installation</b> R-3168 Check over tailgate Grease and check oil level Repairs required Platform doesn't close fully when all the way up Tailgate buffers missing LH frame and bottom tilt ram won't take grease Motor cover missing	HNL Sydney Workshop
11/01/2019	396,628 kms	<b>Electrical - Lense, Shock Absorbers - Replace</b> R-3170 removed and replaced lazy axle shock as old one had damaged bush removed and replaced both rear tail light lens covers as they were damaged	HNL Sydney Workshop
04/01/2019		<b>AdBlue Cap</b> R-3137	HNL Sydney Workshop
23/12/2018	574,927 kms	<b>Tailgate Installation</b> R-3070 Check over tailgate Grease and check oil level Straightened bent motor box and check for any damaged to motor or wiring Drill out snapped grease nipple, tap new thread and fit new grease nipple Repairs required Motor box damaged Frame bushes worn Scuff plate damaged	HNL Sydney Workshop
20/12/2018	394,481 kms	<b>Engine - Check Codes</b> R-3085 Travel to HNL yard Huntingwood to rectify engine no start. 7.50pm Found engine very slow to crank over. No start. Load tested vehicle batteries & found 1 battery faulty. Travel to Daimler Huntingwood & collect 2 new batteries. Remove & replace batteries, test alternator charge rate all ok. Test current draw front batteries with ignition off. All ok. No further faults found. All ok.	Lets Torque Mechanical
16/12/2018	393,048 kms	<b>Tailgate Installation</b> R-3005 Check ove tailgate Grease and check oil level Found oil leaking between pump Replaced o ring and checked for leaks Topped up hydraulic oil Repairs required Both tilt ram bushes worn LH main frame pin won't take grease	HNL Sydney Workshop
04/11/2018	386,972 kms	<b>Paint Repair</b> R-2705 Clean and paint tailgate Refit marker plates, fit new tailgate flags and rollers Paint under run bar and fit new stickers	HNL Sydney Workshop
26/10/2018	385,984 kms	<b>Accident Damage</b> R-2627	HNL Sydney Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		Fit new LH tail light assembly and new RH main mirror Check all lights	
26/10/2018	385,984 kms	<b>B - 30K S-2102</b>	HNL Sydney Workshop
		Carry out B service Replaced drive axle brake pads, tensioned all wheel nuts Welded LH tail light brackets back on Replaced damaged roller door hinges	
15/10/2018	383,441 kms	<b>Repairs R-2561</b>	TRS
		X-Truck Repairs	
11/10/2018	383,963 kms	<b>Repairs, Service - Vehicle "C" Service R-2502</b>	HNL Sydney Workshop
		Replace hand control case and check operation Grease tailgate Replace power steer filter and flush fluid Refill fluid and check	
06/10/2018	383,443 kms	<b>Tailgate Operating Fault R-2419</b>	HNL Sydney Workshop
		Tested batteries and replaced with new set Replaced washers between pump and oil pickup Topped up hydraulic oil and checked for oil leaks Checked tailgate charging system and truck charging system	
02/10/2018	383,306 kms	<b>Damage - Rear Lights R-2380</b>	HNL Sydney Workshop
		Replaced LH tail light assembly Welded snapped tail light bracket back on	
21/09/2018		<b>Repairs R-2331</b>	HNL Sydney Workshop
		Rewired hand control and repaired damaged wiring Check operation	
31/08/2018	378,241 kms	<b>Breakdown - After Hours R-2181</b>	HNL Sydney Workshop
		Order and pick up parts from stillwell trucks in Milperra Travel to Turrumurra IGA and replace LH rear axle airbag Check operation of airbags	
24/08/2018		<b>Electrical - Ignition Switch Key R-2145</b>	HNL Sydney Workshop
		Replace x 2 keys Cut & program All ok	
12/08/2018		<b>CTP O-425</b>	
12/08/2018		<b>Registration O-424</b>	
11/08/2018		<b>CTP O-184</b>	
11/08/2018		<b>Electrical - Tail Light Assembly R-2024</b>	HNL Sydney Workshop
11/08/2018		<b>Registration O-183</b>	
18/07/2018	369,111 kms	<b>Repairs R-2836</b>	TRS
		Replaced hand control and lead Wire new hand control to suit Check operation	
12/07/2018	369,385 kms	<b>Change Vehicle Fleet Numbers R-1909</b>	HNL Sydney Workshop
		Check low coolant Found no signs of coolant leaking, topped up coolant Remove and fit new fleet stickers	
20/05/2018	361,626 kms	<b>Body Rear Doors R-1615</b>	HNL Sydney Workshop
		Secured loose door latch with new bolts and straightened Secured loose door handle Refit door rollers that had come out	
03/05/2018		<b>Transmission Fault R-1565</b>	Allison Auto Transmissions
01/05/2018	360,372 kms	<b>B - 30K S-1675</b>	HNL Sydney Workshop
		Carry out B service Replace engine oil Replace oil and fuel filters and air filter Paint rear under run bar and fit new marker stickers	
30/04/2018	360,371 kms	<b>Mirror Assembly R-1548</b>	
		Remove amd replace LH spotter mirror and RH main mirror	
18/03/2018	353,741 kms	<b>Electrical - Fault R-1373</b>	HNL Sydney Workshop
		Test and find fault with interior lights Traced wiring and found damaged wiring and no power Repaired wiring and fitted new globes All ok	

Date	Reading / Units	Type / Repairer Notes	Repairer
13/03/2018	353,266 kms	<b>Electrical - Fault</b> R-1337 Remove and replace side indicator assembly	HNL Sydney Workshop
08/01/2018	343,526 kms	<b>Electrical - Fault</b> R-1084 Check tail lights not working Found blown fuse, replaced Replace blown head light globe and globes	HNL Sydney Workshop
26/12/2017	341,346 kms	<b>Tyre - Repair</b> R-1043 Remove wheel and fit spare wheel to truck as tyre fitted not available to change tyre New tyre fitted later that afternoon	HNL Sydney Workshop
22/11/2017	335,031 kms	<b>Wheel Bearings - Repack Grease &amp; Adjust</b> R-904 Remove rear axle wheels, calipers and hubs Clean hubs and bearings Repack hubs and bearings with new grease and refit hubs (BPW Grease) Refit calipers and adjust brakes Refit wheels and adjust wheel bearings Tension wheel nuts	HNL Sydney Workshop
14/11/2017	334,470 kms	<b>Brakes</b> R-891 Check all brakes Replace steer axle brake pads	HNL Sydney Workshop
13/10/2017	331,037 kms	<b>C - 120K</b> S-1228 Carry out C service and check over Reline both rear axles Replaced diff, gearbox and engine oil Replaced fuel, oil and gearbox filters Replace fan belt, ilder and tensioner Replace air dryer and cabin filter	HNL Sydney Workshop
07/09/2017	324,984 kms	<b>Accident Damage</b> R-596 Remove and replaced tail light assembly	HNL Sydney Workshop
09/08/2017		<b>Accident Damage</b> R-512 repaired as per invoice	Workhorse Collision Repair
20/02/2017	297,613 kms	<b>B - 30K</b> S-916	MHR
31/01/2017		<b>Accident Damage, Repairs</b> R-155 trs to repair body approx cost is \$10000	TRS
21/12/2016	210,350 kms	<b>C - 120K</b> S-265 Service Completed	
08/10/2016	280,103 kms	<b>A - 10K</b> S-163 Service Completed	
08/10/2016	280,103 kms	<b>B - 30K</b> S-686 AS PER SERVICE SHEET	Mal Hooley Truck Repairs
18/06/2016	255,685 kms	<b>B - 30K</b> S-70 Service Completed	
18/06/2016	255,685 kms	<b>B - 30K</b> S-687 AS PER SERVICE SHEET	Mal Hooley Truck Repairs

Signed: \_\_\_\_\_  
Name: \_\_\_\_\_  
Date: \_\_\_\_\_