

Vehicle History Summary

Fleet #	RP2419
Registration	
Make	FTE
Model	24 Pallet - Tri Axle
VIN / Chassis #	6B9FTE3JR6MAA5182
Build Date	2006

Date	Reading / Units	Type / Repairer Notes	Repairer
09/02/2026	125,928 kms	PREPARE FOR SALE R-33857 REMOVE SCUFF MARKS OFF WALLS TAKE TRAILER TO AUCTIONS	HNL WORKSHOP
11/10/2025		registration cancelled R-32252 CANCEL REGO - TRAILER SOLD - RITCHIE BROS	HNL WORKSHOP
27/09/2025		PREPARE FOR SALE R-32002 PREPARE FOR SALE REMOVE ALL COMPANY SIGNAGE DEGREASE AND WASH TRAILER FIT 4x RUNOUT TYRES REPLACE MUDFLAPS TAKE TRAILER TO RITCHIE BROS AUCTIONS	HNL WORKSHOP
26/09/2025		STRIP AND FIT T-5077 strip and fit 8x tyres	ROSS TYRES
31/08/2025	113,309 kms 20,675 hrs	B - 20K S-14146 Carried out trailer B service and inspection as per HNL checklist Replace right side clearance light Adjusted wheel bearings	
27/08/2025	113,309 kms	TRAILER TYRES T-5022 TRAILER TYRES POS 25/26/27/28/29/30 FITTED 11R22.5 FIRESTONE FT469	Bridgestone Australia Ltd
10/07/2025	87,253 kms 20,369 hrs	B - 20K S-13860 Carried out trailer B service and inspection as per HNL checklist Repair roller door and tested Adjusted all trailer wheel bearings	KJS Fleet
08/07/2025	86,373 kms	ROLLER DOOR JAMMED R-31921 Removed jammed rollers and unjam door.Refit rollers and test all okay.	KJS Fleet
16/06/2025	74,839 kms 20,238 hrs	B - 20K S-13658 CARRY OUT 'B' SERVICE REPLACE CALIPER / ROTOR	HNL Sydney Workshop
10/06/2025	74,263 kms	L/H WALL / FLOOR SEPERATION R-30555 L/H WALL AND FLOOR SEPERATION - ESTIMATE 45223 APPROVED BY JK EMAI; 27.5	Workhorse Collision Repair
27/05/2025	73,929 kms	ROLLER DOOR JAMMED R-31889 Bottom roller out of track and middle hinge missing nuts causing door to split.Replaced missing nuts.Refit roller into track.Track is worn at top.	KJS Fleet
21/05/2025	71,717 kms	Electrical - USB Socket R-30481 Removing and replacing and testng 7pin socket	KJS Fleet
15/05/2025	69,269 kms	TRAILER TYRES T-4775 TRAILER TYRES AXLE 1	ROSS TYRES
15/05/2025	69,269 kms	C - 200K S-13459	HNL WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
		CARRY OUT 'C' SERVICE - APPRENTICE TRAINING JACK AND COOPER REPLACE ALL WHEEL BEARINGS AND HUB NUTS REPLACE 6x BRAKE DISC ROTORS REPLACE ALL BRAKE PADS REPLACE AIR BAGS - AXLE 1 R/H - AXLE 2 R/H - AXLE 3 L/H REPLACE HUB SPEED RINGS REPAIR LIGHTS AND WIRING AT REAR OF TRAILER INSPECT AND REPORT L/H WALL SEPERATION - NEEDS TO BE QUOTED	
15/05/2025	69,269 kms	WASH AND DETAIL R-30405 WASH AND DETAIL CLEAN INTERIOR OF TRUCK	HNL WORKSHOP
08/05/2025	69,269 kms	B - 20K S-13446 CARRY OUT 'B' SERVICE TIGHTEN ALL WHEEL BEARINGS TRAILER DUE FOR 'C' SERVICE	HNL WORKSHOP
24/03/2025	50,111 kms	B - 20K S-13161 CARRY OUT 'B' SERVICE REPLACE R/H/R TYRE WITH RUNOUT PAINT RIMS APPRENTICE TRAINING WITH JACK	HNL WORKSHOP
19/03/2025	48,264 kms	DEFECT R-29693 Check air suspension fault Replace A1 left side air bag & tested operation All ok Check and clear defect	KJS Fleet
11/03/2025		Body Rear Roller Door R-29555 Check roller door cable broken	TDC TRUCK DOORS & CURTAINS
24/02/2025	21,700 kms	B - 20K S-12981 CARRY OUT 'B' SERVICE ADJUST WHEEL BEARINGS AXLES 1 AND 2	HNL WORKSHOP
24/02/2025		PRE RMS INSPECTION, Registration HVIS Inspection R-29349 CARRY OUT PRE RMS INSPECTION TAKE TO CARRINGTON FOR INSPECTION - PASSED AZ2891371	HNL WORKSHOP
13/01/2025	16,159 kms 19,520 hrs	B - 20K S-12772 Carried out trailer B service and inspection as per HNL checklist Adjusted all trailer wheel bearings as required Check and repair rear roller door & tested operation Replace x 2 brand new chiller boards	KJS Fleet
04/12/2024	1,089 kms	Fuel Cap R-28391 Fuel cap is missing fitted spare cap from spare tank as required.	KJS Fleet
29/11/2024		Air leak R-28323 Travel to Aldi Minchinbury Replace leaking brake booster A2 left side - ALI ok Replace hub odometer	KJS Fleet
20/11/2024	1 kms	B - 20K S-12531 CARRY OUT 'B' SERVICE TIGHTEN AXLE 1 WHEEL BEARINGS NEEDS NEW HUB METER	HNL WORKSHOP
28/10/2024		Body Rear Roller Door R-27975 Check roller door fault Tested operation of roller door Could not fault All ok	KJS Fleet, Thermal Mark Transport Refrigeration
21/10/2024	1 kms	B - 20K S-12304 Carried out trailer B service and inspection as per HNL checklist All ok	KJS Fleet
22/08/2024	4,247 kms 18,873 hrs	B - 20K S-11915 Carried out trailer B service and inspection as per HNL checklist Adjusted all left wheel bearings Repair number plate wiring Repair reverse light All ok	KJS Fleet
08/08/2024	4,202 kms	Body Floor Repair R-26986 Straighten Floor Plate.prep plate bottom support plate,install brace plate and tighten.	KJS Fleet
25/07/2024	881,327 kms	TRAILER TYRES T-4093 6 TRAILER TYRES POS 13/14/19/20/21/22 - DVR 01535 FITTED 11R22.5 KUNLUN	SYDNEY TYRE SERVICE
18/07/2024	881,327 kms	B - 20K S-11706 Carried out trailer B service and inspection as per HNL checklist All ok Check and repair rear roller door & tested ok	KJS Fleet
10/07/2024	878,423 kms	BURNT WIRING R-26725	KJS Fleet

Date	Reading / Units	Type / Repairer Notes	Repairer
		Driver states smoke coming from wiring loom when parkers are activated.Attend ALDI and inspect main wiring loom,found 7 core pigtail spliced into loom going in to nothing.Wiring had not been isolated causing short.Cut out pigtail,isolate remaining wires,test all okay.	
10/07/2024	878,423 kms	REVERSE LIGHT R-26730 Found brittle wiring on back of light and break in loom going to plugs.Repair all reverse light wiring and test all okay.	KJS Fleet
22/06/2024		Accident Damage R-26839 ACCIDENT DAMAGE FOUND 22.6.24 - DVR 01518 TO BE INSPECTED AND QUOTED	HNL Sydney Workshop
18/06/2024	856,932 kms	TRAILER TYRES T-4023 TRAILER TYRES POS 11/12 FITTED 11R22.5 NF876	SYDNEY TYRE SERVICE
17/06/2024	868,246 kms	B - 20K S-11538 CARRY OUT 'B' SERVICE ADJUST WHEEL BEARINGS L/H/C AND L/H/R PAINT RIMS REPAIR SIDE SKIRT THAT HAD BEEN DAMAGED	HNL WORKSHOP
14/05/2024	857,926 kms	B - 20K S-11322 Carried out B Service as per HNL Check list.A1 70% A2 90% A3 85%.	KJS Fleet
04/04/2024	847,041 kms	B - 20K S-11087 CARRY OUT 'B' SERVICE	KJS Fleet
08/03/2024	835,668 kms	CLEARANCE LIGHT FAULT R-25092 CHECK CLEARANCE LIGHT ISSUE - DVR 10918 CHECK ALL PLUGS AND HARNESS - FOUND SHORT AT REAR WIRING HARNESS REPAIR SHORT AND RUN NEW WIRING TO REAR LIGHTS REPLACED 7 PIN BASE	HNL WORKSHOP
07/03/2024	835,209 kms	Breakdown - Trailer R-25217 BREAKDOWN AT SINGLETON - CLEARANCE LIGHTS TRAVEL TO AND FROM SINGLETON - CHECK LIGHT WIRING TRAILER HAS MAJOR SHORT IN HARNESS TEMP REPAIR DONE TO KEEP TRAILER WORKING TO BE REPAIRED 8.3.24	HNL WORKSHOP
06/03/2024	834,770 kms	body and floor damage R-25045 Interior kick plate repairs Invoice attached	Workhorse Collision Repair
05/03/2024		REVERSE LIGHT R-25046 CHECK REVERSE LIGHT NOT WORKING FOUND AND REPAIRED CUT WIRING CHECK POWER TO REAR OF TRAILER / CHECK POWER AT PRIME MOVER NEEDS MORE WORK	HNL WORKSHOP
04/03/2024	834,770 kms	B - 20K S-10932 CARRY OUT 'B' SERVICE CARRY OUT PRE RMS INSPECTION ADJUST WHEEL BEARINGS AXLE 3 REPLACE FRONT MARKERS WASH AND DETAIL RMS INSPECTION PASSED AZ2775591 SELF CLEARING DEFECT FOR WHEEL BEARINGS - AHV1497086 CHECK WHEEL BEARING ADJUSTMENT ON 3 AXLES	HNL WORKSHOP
22/02/2024	830,550 kms	B - 20K S-10866 Carried out B-Service as per HNL Checklist	KJS Fleet
13/02/2024		Accident Damage R-24205 REAR DOOR FRAME REPAIR AS PER ESTIMATE 42694 - WORKHORSE APPROVED BY JK 12.12.23 - DVR 09215 09221 09246 09232 TO BE COMPLETED 22.2.24	Workhorse Collision Repair
23/01/2024	829,984 kms	PAN INSPECTION R-24628 PAN INTERNAL INSPECTION - AS PER ATTACHED 3 GOOD PADS - 1 PAD NEEDS REPLACING REAR DOOR FRAME CRACKED - BOOKED AT WORKHORSE KICK PLATES NEED MAJOR REPAIR FLOOR SHEETS LIFTED BETWEEN THE 2 REAR STEEL FLOOR SHEETS	HNL WORKSHOP
16/12/2023		Breakdown - After Hours R-24278 Contact - Rob May / Saturday 11am Travel to Aldi Minchinbury and check damaged interior kick plate stopping pallets from being loaded Cut and removed damaged section to allow trailer to be used. (Trailer to have body repairs carried out at later date)	HNL Fleet Sydney
22/11/2023	800,114 kms	B - 20K S-10424	HNL WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
		CARRY OUT 'B' SERVICE ADJUST WHEEL BEARINGS CHECK INTERNAL WALL AND FLOOR DAMAGE - DVR 09856 TO BE QUOTED BY WORKHORSE	
26/10/2023	786,551 kms	after hours call out T-3600 AFTER HOURS SERVICE CALL TO ST MARYS PUNCTURE REPAIR POS 19	ROYALE TRUCK SERVICES
18/10/2023	782,591 kms 17,361 hrs	B - 20K S-10203 Carried out trailer B service and inspection as per HNL checklist All ok	KJS Fleet
16/10/2023	781,488 kms	Check Vehicle Lights R-23655 Aldi Minchinbury Replace trailer electrical plug Tested all lights All ok	KJS Fleet
13/09/2023	768,242 kms	TRAILER TYRES T-3480 TRAILER TYRES POS 29/30/31/32 FITTED 11R22.5 FIRESTONE FT469	Bridgestone Australia Ltd
04/09/2023	766,355 kms	TRAILER TYRES T-3468 TRAILER TYRES FITTED 11R22.5 FIRESTONE FT469	Bridgestone Australia Ltd
28/08/2023	763,711 kms 17,408 hrs	B - 20K S-9933 Carried out trailer B service and inspection as per HNL checklist All ok No fault reported	HNL Fleet Sydney
24/08/2023	762,970 kms	REAR BODY DAMAGE R-23072 GO TO MINCHINBURY TO CHECK DAMAGE TO REAR OF TRAILER REMOVED DAMAGED BUMP STOP RUBBERS KJS BOILERMAKER TO REPAIR CRACKS IN FRAME AND BUMP STOP MOUNT FIT NEW BUMP STOP RUBBERS	HNL Sydney Workshop
21/08/2023	761,810 kms	ELECTRICAL BLINKER R-23048 FIND AND REPAIR BLINKER WIRING FAULT REPAIRED WIRING AT 7 PIN BASE	HNL WORKSHOP
02/08/2023	750,399 kms	AIR LEAK R-22808 Remove and replace A2 left side air bag due to leaks All ok	HNL Sydney Workshop
19/07/2023	743,213 kms 17,214 hrs	B - 20K S-9701 Carried out trailer B service and inspection as per HNL checklist All ok Pre trip Onsite Aldi Service Adjusted all trailer wheel bearings	HNL Fleet Sydney
14/06/2023	735,736 kms	TRAILER TYRES T-3237 TRAILER TYRES L/H/F FITTED 11R22.5 HIFLY HH104	ROSS TYRES
14/06/2023	735,736 kms	B - 20K S-9429 CARRY OUT 'B' SERVICE REPLACED DAMAGED TYRES	HNL WORKSHOP
01/06/2023	730,176 kms	Trailer tyre T-3218 TRAILER TYRE POS 28 FITTED 11R22.5 FIRESTONE FT469	Bridgestone Australia Ltd
24/05/2023	730,149 kms	ABS Fault R-22091 Replace damaged ABS plug at front of trailer All ok	HNL Fleet Sydney
23/05/2023	730,149 kms	Welding Repairs R-22090 Check bracket to front air lines damaged Repair by welding All ok	KJS Fleet
02/05/2023	719,228 kms	B - 20K S-9172 CARRY OUT B SERVICE ADJUST WHEEL BEARINGS AXLES 2 AND 3 FIT RUN OUTS	HNL WORKSHOP
26/04/2023		Registration O-2551	
19/04/2023	711,862 kms	TRAILER TYRES T-3139 replace pos 1&2 trailer tires REPAIR INTERNAL WALL - DVR 09185	ROSS TYRES
29/03/2023	704,603 kms	DEFECT R-21616	HNL Sydney Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		Check trailer brake defect - AHV1426796 Replace axle 3 right side booster Tested all ok Gilbert & Roach passed brake test All ok DEFECT CLEARANCE CA2357136	
29/03/2023	704,575 kms	B - 20K S-8923	HNL Fleet Sydney
		Carried out trailer B service & inspection as per HNL checklist Adjusted all wheel bearings left & right sides Replace rear marker plates left & right Fitted rear reverse lamps All ok	
23/03/2023	702,834 kms	Body Interior Scuff Plate R-21537	HNL Sydney Workshop
		Check interior checker plate floor Bolt down panel that has lifted to prevent trip hazard All ok	
09/03/2023	698,507 kms 16,723 hrs	B - 20K S-8788	HNL Fleet Sydney
		Carried out trailer B service & inspection as per HNL checklist attached All ok Adjusted all 6 wheel bearings Noted axle 1 tyres low, axle 2 tyres scolloped	
30/01/2023	703,679 kms	C - 200K S-8509	HNL WORKSHOP
		CARRY OUT C SERVICE REPLACE ALL BRAKES REPLACE AXLE 1 SPRING EYE BUSHES CLEAN AND PAINT HUBS WASH AND DETAIL	
19/01/2023	682,052 kms	Body Rear Roller Door R-20880	HNL Fleet Sydney
		Check roller door Replace rollers / hinges as required Tested operation All ok	
04/01/2023	672,716 kms 20,366 hrs	B - 20K S-8368	HNL Fleet Sydney
		Carried out trailer B service & inspection as per HNL checklist All ok Adjusted axle 1 & 2 wheel bearings & axle 3 left side Carry out fridge engine pre trip check over (Requires C - Service / bearing grease)	
20/10/2022	641,131 kms	Electrical - Clearance Light Fault R-20064	HNL WORKSHOP
		Clearance Light not working found problem in plug	
19/10/2022	640,432 kms	B - 20K S-7941	HNL Sydney Workshop
		CARRY OUT 'B' SERVICE ADJUST AXLE 3 WHEEL BEARINGS	
10/10/2022	578,090 kms	CAB LOCK SENSOR R-19946	HNL Sydney Workshop
		REPLACED FAULTY CAB LOCK SENSOR	
24/09/2022	633,028 kms	RUN OUT TYRE T-2758	Bridgestone Australia Ltd
		FIT RUN OUT TYRE POS 30	
21/09/2022	631,175 kms	Brake Booster R-19735	HNL Sydney Workshop
		R/H AXLE 1 REPLACED LEAKING BRAKE BOOSTER	
20/09/2022	631,175 kms	TRAILER TYRES T-2752	Bridgestone Australia Ltd
		TRAILER TYRES POS 23/24 FITTED 11R22.5 BRIDGESTONE R168	
15/09/2022	628,201 kms	B - 20K S-7771	HNL Sydney Workshop
		CARRY OUT 'B' SERVICE ADJUST WHEEL BEARINGS AXLE 3	
30/08/2022	620,013 kms	RUN OUT TYRE T-2729	Bridgestone Australia Ltd
		RUN OUT TYRE FITTED POS 26	
05/08/2022	613,047 kms	B - 20K S-7605	HNL WORKSHOP
		Carry out B service adjust all wheel bearings replace LH rear tires with runouts replace RH front outer tire with runout replace RH side clearance light wash and detail paint rims replace LHS front airbag	
03/08/2022		cancelled R-19349	ROSS TYRES
		CANCEL	
03/08/2022		TRAILER TYRES T-2681	ROSS TYRES
		TRAILER TYRES FITTED 11R22.5 HIFLY HH104	
14/07/2022	604,198 kms	TRAILER TYRES T-2647	Bridgestone Australia Ltd
		TRAILER TYRES POS 31/32 FITTED 11R22.5 FIRESTONE FT469	

Date	Reading / Units	Type / Repairer Notes	Repairer
23/06/2022	594,083 kms	internal kick plates R-19009 straightened kick panel and riveted back onto wall	HNL Sydney Workshop
17/06/2022	592,103 kms	B - 20K S-7407 CARRY OUT 'B' SERVICE	HNL Sydney Workshop
31/05/2022	581,000 kms	Trailer Body Damage R-18883 TRAILER FLOOR PLATES REPAIRED	WORKHORSE
24/05/2022		2023 rego papers R-18686 2023 rego papers	HNL WORKSHOP
13/05/2022	581,000 kms	Body Floor Repair R-18572 FLOOR TO BE INSPECTED / REPAIRED AFTER RMS INSPECTION - DVR 01176 REPAIRED BY WORKHORSE ON P/O 21590	HNL Sydney Workshop
13/05/2022	581,000 kms	DEFECT CLEARANCE R-19084 RMS DEFECT CLEARED	Daimler Trucks Huntingwood
11/05/2022	581,000 kms	CLEARANCE LIGHT FAULT R-18892 REPAIR TRAILER LIGHTS WIRING FAULT	MJR Auto Electrical
29/04/2022	572,085 kms	B - 20K S-7184 CARRY OUT B SERVICE . ADJUSTED ALL WHEEL BEARINGS .	HNL Sydney Workshop
29/04/2022		Registration O-2132 FAILED RMS INSPECTION , HAS BEEN REPAIRED AND PASSED	
01/04/2022	553,612 kms	TRAILER TYRES T-2450 TRAILER TYRES POS 21/22 FITTED 11R22.5 BRIDGESTONE R168	Bridgestone Australia Ltd
07/02/2022	534,159 kms	B - 20K S-6847 CARRY OUT 'B' SERVICE REPAIR LIGHTS AND WIRING REPAIR DAMAGE TO R/H/R OF TRAILER REPLACE HUB NUT AND REPACK BEARINGS L/H/F HUB REPAIR AIR LEAKS	HNL WORKSHOP
31/01/2022	550,672 kms	ABS Fault R-17876 CHECK ABS FAULT ON DASH - DVR 00644 CHECK FOR FAULTS - TRAILER RUNNING OLD 24V SYSTEM NOT COMPATIBLE WITH PRIME MOVER	HNL WORKSHOP
18/01/2022	515,814 kms	Puncture Repair T-2305 PUNCTURE REPAIR POS 28	Bridgestone Australia Ltd
04/01/2022	512,321 kms	TRAILER TYRES T-2287 TRAILER TYRES POSITION 31 32 . 11R22.5 148/145L BS R168.	BRIDGESTONE
03/12/2021	497,607 kms 14,788 hrs	C - 200K S-6635 CARRY OUT C SERVICE . CARRY OUT BRAKE RELINE ON ALL AXLES REPLACE 3 AXLE ROTORS AS WELL . REPLACED L/H REAR ABS LEAD .	HNL Sydney Workshop
26/11/2021		TRAILER TYRES T-2212 TRAILER TYRES POS 29/30 FITTED 11R22.5 FIRESTONE FT469	Bridgestone Australia Ltd
21/10/2021	14,490 kms	Body Damage R-16862 REMOVE DAMAGED OS LOWER CORNER CAP CUT DAMAGED FIBREGLASS SECTION CLEAN AND PREPARE FOR FIBREGLASS REPAIRS FIBREGLASS REPAIR OS LOWER CORNER AND FLOW COAT WHITE WELD REPAIR OS LOWER CORNER CAP AND FRAME SUPPLY AND FIT HEAVY DUTY DOCK RUBBER OVER NS AND OS IMPACT POINTS. REMOVE AND REPLACE DETERIORATED DOOR SEAL	Thermal Mark Transport Refrigeration
26/08/2021	446,266 kms	Trailer Tyre T-1949 TRAILER TYRE POS 19 AFTER HOURS CALL OUT FEE	Bridgestone Australia Ltd
26/08/2021	447,946 kms	Pressure Check T-1968	Bridgestone Australia Ltd

Date	Reading / Units	Type / Repairer Notes	Repairer
		PRESSURE CHECKS X12	
28/07/2021		Fridge Pre-Trip Inspection R-15801 PERFORMED REFRIGERATION UNIT PRE TRIP INSPECTION, CHECK AND ADJUST BELTS AS REQUIRED, VISUAL INSPECTION TO FUEL SYSTEM, ELECTRICAL COMPONENTS, CONNECTORS, FLUID LEVELS, IDLER BEARINGS AND MOUNTING BOLTS, OPERATE AND TEST UNIT. REMOVE AND REPLACE DAMAGED AIR FILTER HOUSING, TOP UP ENGINE OIL.	Thermal Mark Transport Refrigeration
08/07/2021	414,486 kms	TRAILER TYRES T-1829 TRAILER TYRES RMS DEFECT HVN0593178 DEFECT CLEARANCE CA2012919	Bridgestone Australia Ltd
07/07/2021	416,098 kms	Electrical - Clearence Light Assembly, WASH AND DETAIL R-15521 REPAIR BLINKER WIRING R/H/R REPLACE R/H/F FRONT MARKER LIGHT WASH AND DETAIL	HNL WORKSHOP
30/06/2021	408,861 kms	Puncture Repair T-1805 PUNCTURE REPAIR POS 21	Bridgestone Australia Ltd
23/06/2021	404,839 kms	Electrical - Clearence Light Fault R-15334 REPAIR CLEARANCE LIGHT WIRING REPLACE SIDE LIGHT ASSY	HNL WORKSHOP
21/05/2021	14,124 hrs	Fridge Pre-Trip Inspection R-14991 FRIDGE PRE TRIP	FLETCHERS TRANSREFRIGERATION
29/04/2021		Registration O-1629	
27/04/2021	14,077 hrs	Fridge Pre-Trip Inspection R-14605 CARRY OUT FRIDGE PRE-TRIP INSPECTION TOP UP ENGINE OIL - 2 LITRES	FLETCHERS TRANSREFRIGERATION
19/04/2021	374,392 kms	Mudflaps - Damaged R-14516 REPLACE L/H MUDFLAP	HNL WORKSHOP
14/04/2021	370,744 kms	B - 20K S-5617 CARRY OUT 'B' SERVICE CHECK WHEEL BEARING ADJUSTMENT - ADJUST L/H/F INSPECT / ADJUST BRAKES CHECK LIGHTS AND GREASE GENERAL CHECK OVER REPAIR FLOOR AT REAR OF TRAILER WASH AND DETAIL	HNL WORKSHOP
01/04/2021		Puncture Repair T-1507 PUNCTURE REPAIR POS 34	ROSS TYRES
30/03/2021		Fridge Pre-Trip Inspection R-14277 PRETRIP INSPECTION	FLETCHERS TRANSREFRIGERATION
17/03/2021	353,745 kms	Trailer Tyre T-1439 Replace x 4 Position 21/22/23/24	Bridgestone Australia Ltd
12/03/2021	353,787 kms	Registration Inspection R-13990 Could not fault trailer brakes - Sent directly to Gilbert & Roach for brake test - PASSED attached. Visual inspection as part of previous service.	RMS Wetherill Park
12/03/2021	353,745 kms 13,895 hrs	B - 20K S-5495 Carried out trailer B service & inspection, per HNL checklist Adjusted excessive wheel bearing movement left & right Axle 1 - 2 - 3. Replace right rear marker plate due to damage Pre RMS inspection checks. All ok	HNL Fleet Sydney
08/03/2021	13,886 hrs	Body Panels & Covers R-14116 Remove and Replace Damaged Wine Rack Cover as per Attachment	Thermal Mark Transport Refrigeration
25/02/2021	13,797 hrs	Fridge - Engine Service R-13782 Carry out fridge engine B service. Diesel Hours 13797	Thermal Mark Transport Refrigeration
28/01/2021	323,592 kms	Shock Absorbers - Replace R-13434	HNL Fleet Sydney

Date	Reading / Units	Type / Repairer Notes	Repairer
		Check shock absorbers leaking Remove & replace axle 1 left & right shock absorbers Remove & replace axle 2 left & right shock absorbers Remove & replace axle 3 left & right shock absorbers All ok	
28/01/2021	323,592 kms 13,579 hrs	B - 20K S-5298	HNL Fleet Sydney
		Carried out trailer B service & inspection, per HNL checklist Top up fridge engine 1L engine oil Replace both male & female air line fittings Replace left front upper clearance light & test operation Adjusted excessive wheel bearing movement, axle 3 left Note - Teflon skid plate badly worn (Reported to G.G)	
03/12/2020	290,383 kms	Fridge Fault R-12829	HNL WORKSHOP
		CHECK FOR WATER LEAKING ONTO FREIGHT REMOVED COVERS / TIGHTEN LOOSE HOSE CLEAN OUT DRAINS REPLACED MUDFLAPS	
24/11/2020	282,698 kms	B - 20K S-4994	HNL WORKSHOP
		CARRY OUT 'B' SERVICE BRAKE INSPECTION AND ADJUST WHEEL BEARING ADJUSTMENT CHECK CHECK LIGHTS AND GENERAL CHECK OVER WASH TRAILER	
11/11/2020	13,037 hrs	Fridge Pre-Trip Inspection R-12528	Thermal Mark Transport Refrigeration
		Performed Refrigeration Unit Pre Trip Inspection as per Attachment	
03/11/2020	265,109 kms	Clean - Wash & Detail Vehicle (Inside & Out) R-12354	HNL WORKSHOP
		WASH AND DETAIL	
27/10/2020	260,278 kms	C - 200K S-4862	HNL WORKSHOP
		CARRY OUT 'C' SERVICE REPLACE 6X WHEEL BEARING KITS - ADJUST WHEEL BEARINGS CHECK AND ADJUST BRAKES - REPLACE ROTORS AND PADS REPLACE AXLE NUTS X6 GREASE AND GENERAL CHECK OVER	
21/10/2020	257,686 kms	Trailer tyre T-994	ROSS TYRES
		REPLACED 2X TYRES ON L/H/C HUB DAMAGED AFTER BRAKE CALIPER FAILED	
20/10/2020	257,686 kms	B - 20K S-4840	HNL WORKSHOP
		CARRY OUT 'B' SERVICE - APPRENTICE TRAINING CHECK AND ADJUST ALL BRAKES CHECK WHEEL BEARINGS - ADJUST R/H/C-L/H/F-L/H/R CHECK LIGHTS AND GENERAL CHECK OVER	
20/10/2020	257,686 kms	Brakes R-12110	HNL WORKSHOP
		BRAKES LOCK ON L/H/C AXLE FOUND CALIPER RUSTED AND SIEZED REPLACE CALIPER TEST OK TYRES HAD BEEN FLAT SPOTTED - BOTH TYRES REPLACED	
09/10/2020	253,324 kms	Clean - Wash & Detail Vehicle (Inside & Out) R-11890	HNL WORKSHOP
		WASH AND DETAIL INSIDE AND OUT	
08/10/2020	236,627 kms	New Tyres T-824	ADZ Tyre & Battery
		Trailer - 11r (x2) pos 11,12 as per Attachment	
22/09/2020	245,045 kms	B - 20K S-4724	HNL WORKSHOP
		CARRY OUT 'B' SERVICE CHECK BRAKES AND LIGHTS CHECK WHEEL BEARINGS - ADJUST L/H 1ST AXLE BEARING APPRENTICE TRAINING	
18/09/2020	243,239 kms	Puncture Repair T-982	ADZ Tyre & Battery
		Puncture - repairable as per Attachment	
17/08/2020		Body Floor Repair R-11020	National Truck Repairs
		FIT 2X NEW CHECKER PLATE FLOOR PANELS REPAIRED REAR FLOOR PANEL	
12/08/2020	12,539 hrs	Fridge Pre-Trip Inspection R-11101	TRS
		PRETRIP ON UNIT - CHECK ALL LEVELS CHECK ALL BELTS AND TENSIONERS / CHECK PULLEYS CHECK BATTERY / CHECK FOR LEAKS / CHECK WATER PUMP	
12/08/2020	228,217 kms	B - 20K S-4540	HNL WORKSHOP
		CARRY OUT 'B' SERVICE CHECK BRAKES AND ADJUST CHECK WHEEL BEARINGS AND ADJUST ALL REPLACE REAR MARKER PLATE REPLACE L/H/F CLEARANCE LIGHT REPLACE TYRES L/H/R WASH TRAILER	
08/08/2020	227,650 kms	Check Vehicle Defects R-10940	HNL WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
		RMS DEFECT AT MT WHITE - HVN0561049 INSPECT AND ADJUST BRAKES CLEARED CA 1840619	
03/07/2020	207,915 kms	B - 20K S-4378	HNL WORKSHOP
		CARRY OUT 'B' SERVICE CHECK WHEEL BEARINGS AND BRAKES ADJUST WHEEL BEARINGS AXLE 1 AND 3 GENERAL CHECK OVER	
03/07/2020	12,331 hrs	Fridge Service R-10452	HNL WORKSHOP
		CARRY OUT FRIDGE SERVICE CHANGE ENGINE OIL AND FILTER REPLACE FUEL AND AIR FILTER GENERAL CHECK OVER	
02/07/2020	12,326 hrs	Fridge Pre-Trip Inspection R-10473	TRS
		PRE TRIP INSPECTION - THORNTON TOP UP COOLANT CHECK BELTS / LEVELS / CHARGE RATE RUN AND TEST OK	
26/05/2020		Tyres - Trailer R-9866	ROSS TYRES
		TRAILER TYRES POS 21/22 SD 178251	
25/05/2020	186,949 kms	B - 20K S-4229	HNL WORKSHOP
		CARRY OUT 'B' SERVICE CHECK BRAKES AND WHEEL BEARINGS GENERAL CHECK OVER	
20/05/2020		Body Rear Doors R-9673	TDC TRUCK DOORS & CURTAINS
		REAR DOOR REPAIR REPLACE DAMAGED TRACK AND ROLLERS REPLACED DAMAGED BOTTOM PANEL REPLACE DAMAGE DOOR LOCK	
20/05/2020	184,369 kms	Warning Signs - Install /Replace R-9886	HNL WORKSHOP
		REPLACE REAR MARKER PLATES	
30/04/2020		Registration O-1028	
06/04/2020	163,995 kms	B - 20K S-3978	HNL WORKSHOP
		CARRY OUT 'B' SERVICE REPAIR CLEARANCE LIGHT WIRING	
24/03/2020	11,806 hrs	Repairs R-9000	TRS
		X-RELAY BOARD	
13/03/2020	11,725 hrs	Fridge Pre-Trip Inspection R-8818	Thermal Mark Transport Refrigeration
		Performed Refrigeration unit Pre Trip Inspection	
09/03/2020	512,801 kms	Electrical - Fault R-8836	HNL WORKSHOP
		REPAIR INTERIOR LIGHT WIRING DVR 08699	
05/03/2020	144,938 kms	Electrical - Fault R-8627	HNL WORKSHOP
		REPLACE R/H SIDE MARKER LAMP REPAIR CLEARANCE LIGHT WIRING DVR 08690	
03/03/2020	143,691 kms	B - 20K S-3790	HNL WORKSHOP
		CARRY OUT 'B' SERVICE CHECK WHEEL BEARINGS CHECK LIGHTS	
03/03/2020	143,858 kms	New Tyres T-210	ADZ Tyre & Battery
		Trailer - 11r (x2) pos13,14 as per Attachment	
21/02/2020	11,621 hrs	Fridge Pre-Trip Inspection R-8390	Thermal Mark Transport Refrigeration
		Performed Refrigeration unit Pre Trip inspection as per Attachment	
18/02/2020	136,709 kms	Tyres - Repair R-8203	
		REPLACE TYRE - DAMAGED SIDE WALL POS 1	
18/02/2020		Registration Inspection R-8213	HNL WORKSHOP
		CARRY OUT PRE RMS INSPECTION REPAIR CLEARANCE LIGHTS	
18/02/2020		Registration Inspection R-8217	RMS CARRINGTON
		RMS INSPECTION AT CARRINGTON FAILED - BREAKAWAY SYSTEM FAULT - AHV1272151 NO FAULT FOUND CLEARANCE NUMBER CA1751934	

Date	Reading / Units	Type / Repairer Notes	Repairer
17/02/2020	11,601 hrs	Fridge Pre-Trip Inspection R-8279 CARRY OUT PRE-TRIP CHECK OVER UNIT CHECK LEVELS CHECK BELTS AND PULLEYS	TRS
22/01/2020	125,258 kms	B - 20K S-3575 CARRY OUT 'B' SERVICE REMOVE WATER SPRAY SHEETS	HNL WORKSHOP
03/01/2020	111,453 kms	Repairs R-7276 REMOVE BROKEN STEPS ON REAR REPAIR DAMAGED PANEL AT REAR BOTH SIDES FIT NEW DOCK RUBBER TO L/H/R FIT NEW MARKER PLATES FIT ANTI-SLIP TAPE TO BACK OF STEPS	HNL WORKSHOP
17/12/2019	104,863 kms	B - 20K S-3388 CARRY OUT 'B' SERVICE FIT REAR DOCK RUBBER	HNL WORKSHOP
04/12/2019	100,708 kms	Clean - Wash & Detail Vehicle (Inside & Out) R-6728 CLEAN AND DETAIL TRAILER	HNL WORKSHOP
13/11/2019	87,589 kms	B - 20K S-3170 CARRY OUT 'B' SERVICE CHECK WHEEL BEARINGS AND BRAKES GENERAL CHECK OVER L/H AND R/H REAR BOTTOM CORNERS OF PAN DAMAGED	HNL WORKSHOP
13/11/2019	11,105 hrs	Fridge - Engine Service R-6288 CARRY OUT FRIDGE ENGINE SERVICE	HNL WORKSHOP
23/10/2019	77,657 kms	Tyres - Trailer R-5864 2X TRAILER TYRES POS 1/2	Beaurepaires
14/10/2019	74,394 kms	B - 20K S-3027 CARRY OUT 'B' SERVICE ADJUST WHEEL BEARINGS REPLACE HUB NUT AND LOCK CLIP	HNL WORKSHOP
03/10/2019	10,919 hrs	Repairs R-5549 Travel to Minchinbury Unit reported as not starting. Alarm 17. Power up the unit. Perform fault diagnosis. Found starter to be faulty. R&R starter. Clear Alarm code 17. Test run unit. Download & Check the Das -All OK .	TRS
03/10/2019	10,919 hrs	Fridge Repair R-6023 Travel to Minchinbury unit reported as not starting Alarm 17 Power up the unit Perform fault diagnosis Found starter to be faulty R&R starter Clear alarm code17 Test run unit Download & check the Das -All ok	TRS
03/10/2019	10,919 hrs	Fridge Repair R-5768 TRAVEL TO MINCHINBURY. UNIT REPORTED AS NOT STARTING ALARM 17. POWER UP THE UNIT. PERFORM FAULT DIAGNOSIS. FOUND STARTER TO BE FAULTY . R&R STARTER. CLEAR ALARM CODE 17. TEST RUN UNIT. DOWNLOAD AND CHECK THE DAS-ALL OK.	TRS
30/09/2019	62,504 kms	Tyres - Trailer R-5428 REPLACE TRAILER TYRE	Beaurepaires
26/09/2019	65,315 kms	B - 20K S-2945 CARRY OUT 'B' SERVICE CHECK ALL LIGHTS AND BRAKES ADJUST WHEEL BEARINGS GENERAL CHECK OVER	HNL WORKSHOP
26/09/2019	65,315 kms	B - 20K S-2927 CARRY OUT 'B' SERVICE ADJUST WHEEL BEARINGS	HNL WORKSHOP
10/09/2019	13,490 hrs	Breakdown - After Hours R-5143 Fridge Engine Cutting Out	TRS
09/09/2019	57,841 kms	Tyres - New R-5124 REPLACE 2X TRAILER TYRES - POS 7/8	HNL WORKSHOP
23/08/2019	10,086 hrs	Fridge - Engine Service R-4822 Carry out fridge engine B service. Diesel Hrs 10086 Replace dash display PC board controller	TRS
18/08/2019	13,467 hrs	Breakdown - Fridge R-4898	HNL WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
		BREAKDOWN - TRAVEL TO FREIGHT YARD CHECK FRIDGE FAULTS - TRAILER TO GO TO TRS FOR REPAIR	
06/08/2019	44,050 kms	Repairs R-4688 X-REAR BAR	HNL WORKSHOP
28/06/2019	23,485 kms	C - 200K S-2613 CARRY OUT 'C' SERVICE	HNL WORKSHOP
11/06/2019	16,353 kms	B - 20K S-2584 CARRY OUT 'B' SERVICE ON TRAILER ADJUST WHEEL BEARINGS AXLE 1 LHS AXLE 2 RHS AXLE 3 RHS REPAIR INTERIOR LIGHT WIRING	HNL WORKSHOP
11/06/2019	16,353 kms	Brake - Warning R-4260 CHECK ABS OPERATION ON TRAILER FOUND ABS UNIT IS 24V AND NEEDS 24V SIGNAL FROM PRIME MOVER NEEDS RECHECK WITH BENZ PRIME MOVER	HNL WORKSHOP
05/06/2019	521,987 kms	Alternator R-4244 TENSION ALTERNATOR BELT - CHECK CHARGE RATE	HNL WORKSHOP
14/05/2019	5,170 kms	Air Leaks R-4078 REPLACE LEAKING AIR FITTING AT FRONT OF TRAILER	HNL WORKSHOP
14/05/2019	5,169 kms	B - 20K S-2516 CARRY OUT 'B' SERVICE ON TRAILER	HNL WORKSHOP
02/05/2019		Registration Inspection R-3589 RMS INSPECTION TO CHANGE FROM VICROADS TO NSW REGO REGO PAID ON CREDIT CARD - \$1939.45	HNL WORKSHOP
30/04/2019	1 kms	Brakes R-3892 REPLACE DISC PADS ON AXLE 1 / 2 / 3 REPLACE HUB METER	HNL WORKSHOP
16/04/2019	1 kms	B - 20K S-2450 CARRY OUT 'B' SERVICE REPLACE 3X CLEARANCE LIGHTS AND REPAIR WIRING ADJUST WHEEL BEARINGS AXLES 1 / 2 / 3	HNL WORKSHOP
29/03/2019		B - 20K S-2408 carry out B service greased trailer & tailgate checked all lights all ok checked all tires all ok checked all wheel bearings all ok checked adjusted and reported: axle 1: 7mm 70% axle 2: 7mm 70% axle 3: 7mm 70% repaired damaged to floor in back trailer need new hub meter	HNL Sydney Workshop
25/03/2019	10,086 hrs	Fridge Fault - Engine R-3732 CLEAR CODES AND REPLACE FUEL STOP SOLENOID	TRS
25/02/2019	9,934 hrs	Fridge Fault - Engine R-3512 CHECK ISSUES WITH FRIDGE UNIT- REPLACE ENGINE HEAD GASKET- REPLACE OIL SWITCH- CARRY OUT ENGINE 'B' SERVICE	TRS
10/01/2019		B - 20K S-2254 CARRY OUT 'B' SERVICE NEW HUB METER NEEDED	HNL WORKSHOP
08/01/2019	230,000 kms	Service R-3158 CARRY OUT 'A' SERVICE NEEDS NEW HUB METER	HNL WORKSHOP
19/12/2018	230,000 kms	Service R-3051 CARRY OUT 'A' SERVICE	HNL WORKSHOP
20/11/2018		Fridge Fault R-2863 TEMP REPAIR TO FRIDGE SIDE LIGHT ON R/H/S OF PAN	HNL WORKSHOP
11/10/2018	229,858 kms	B - 20K S-2083 CARRY OUT 'B' SERVICE INTERIOR LIGHTS REPAIRED ADJUST ALL WHEEL BEARINGS	HNL WORKSHOP
02/10/2018	225,964 kms	Service R-2398	HNL WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
		CARRY OUT 'A' SERVICE	
05/09/2018	220,136 kms	Service R-2224 'A' SERVICE	HNL WORKSHOP
03/09/2018	218,853 kms	Mudflaps - Damaged R-2206 REPLACE hnl MUDFLAPS USED SECOND HAND NFS MUDFLAPS	HNL WORKSHOP
22/08/2018	214,980 kms	Service R-2141 'A' SERVICE	HNL WORKSHOP
03/08/2018	208,469 kms	B - 20K S-1944 "B" SERVICE repair lights and wiring replace number plate light	HNL WORKSHOP
27/07/2018	205,819 kms	Fridge Repair R-1982 REPLACE BROKEN BELT FOR FRIDGE UNIT	HNL WORKSHOP
22/06/2018	11,423 hrs	Fridge Service R-1799 Carry out fridge engine B service	HNL WORKSHOP
21/06/2018		Fridge - Freezer Boards R-1726 Paint fleet numbers on freezer boards and fit into back of trailer	HNL Sydney Workshop
21/06/2018	186,916 kms 11,395 hrs	Fridge - Compressor Belts R-1755	TRS
20/06/2018	188,813 kms	Service R-1781 "A" SERVICE	HNL WORKSHOP
06/06/2018	9,148 hrs	C - 200K S-1796 Carry out C service Replace grease and dust shields Clean and repack bearings Inspect discs and hubs	NFS Workshop
20/05/2018	176,644 kms	B - 20K S-1724 Carry out B service and check over Replace both trailer fittings Replace 7 pin socket Cut and fit new mudflaps Fit new marker sticker to rear under run bar	HNL Sydney Workshop

Signed: _____
Name: _____
Date: _____

Vehicle History Summary

Fleet #	RP2419-F
Registration	
Make	Thermo-King Fridge
Model	Spectrum SB MP4
VIN / Chassis #	
Build Date	

Date	Reading / Units	Type / Repairer Notes	Repairer
11/09/2025	20,570 hrs	A - PRE-CHECK S-14202 PERFORM PM-A REFRIGERATION SYSTEM PRE TRIP INSPECTION VISUAL INSPECTION OF FUEL SYSTEM, ELECTRICAL COMPONENTS, HOSES, CONNECTORS AND MOUNTING POINTS CHECK ENGINE OIL & COOLANT FLUID LEVELS AND ADD AS REQUIRED, CHECK THE CONDITION OF ALL BELTS AND ADJUST SENSORS AND CLEAR CODES, START UNIT AND INITIATE SYSTEM PRE TRIP TEST. OPERATE AND TEST UNIT THROUGH ALL MODES. REPORTED - NO START CARRY OUT INSPECTION AND DIAGNOSTICS, FOUND CODE 48 -CHECK BELTS/CLUTCH- ACTIVE, DOWNLOAD DATA AND ASSESS BELTS AND CLUTCH OPERATIONS - NO FAULT FOUND, SUSPECT BELT SLIP DUE TO RAIN ON START UP, ADD ENGINE OIL, START AND RUN UNIT, PRE TRIP - PASS, OPERATE AND TEST ((NOTE:)) DAS REQUIRES BATTERY REPLACEMENT	THERMALMARK
28/08/2025	20,675 hrs	A - PRE-CHECK S-14143 REPORTED - ALARMS ACTIVE UPON INSPECTION FOUND CODE 48 -CHECK BELTS AND CLUTCH- ACTIVE IN UNIT, CARRY OUT DIAGNOSTICS, ASSESS BELTS AND CLUTCH CONDITION - PASS, FOUND HARMONIC BALANCER DISPLACED AND MOUNTING BOLTS SHEARED, REMOVE OLD BALANCER, CHECK CRANKSHAFT FOR DAMAGE - PASS, REPLACE FRONT MAIN SEAL AND CLEAR THREADS ON CRANSHAFT ASSY, FIT NEW HARMONIC BALANCER AND BOLT, TORQUE DOWN TO REQUIRED SPECS, ADD ENGINE OIL, PRE TRIP - PASS, DEGREASE ENGINE AND CONDENSOR, PRESSURE WASH, OPERATE AND TEST	Thermal Mark Transport Refrigeration
20/06/2025	20,275 hrs	A - PRE-CHECK S-13756 PERFORM PM-A REFRIGERATION SYSTEM PRE TRIP INSPECTION VISUAL INSPECTION OF FUEL SYSTEM, ELECTRICAL COMPONENTS, HOSES, CONNECTORS AND MOUNTING POINTS CHECK ENGINE OIL & COOLANT FLUID LEVELS AND ADD AS REQUIRED, CHECK THE CONDITION OF ALL BELTS AND ADJUST SENSORS AND CLEAR CODES, START UNIT AND INITIATE SYSTEM PRE TRIP TEST. OPERATE AND TEST UNIT THROUGH ALL MODES. CARRY OUT PMA INSPECTION, FOUND UNIT SHUTDOWN AND CODE 18 + 41 ACTIVE, CARRY OUT DIAGNOSTICS, LOCATE AND REPLACE LEAKING JACKSHAFT ASSEMBLY, WORN PULLEYS, BELTS AND FAULTY WATER TEMP SENSOR, CARRY OUT NITROGEN CLEAR OF BLOCKED DRAIN TUBES, FLUSH WITH WATER AND CLEAR DRAIN TRAYS OF DEBRIS, ADD ENGINE OIL AND COOLANT, PRE TRIP - PASS, DEGREASE ENGINE AND CONDENSOR, PRESSURE WASH, OPERATE AND TEST	THERMALMARK
14/05/2025	20,187 hrs	JUMP STARTER PLUG R-30391 FIT NEW FRIDGE JUMP STARTER PLUG AND WIRE IN MAKE AND FIT BRACKET	HNL WORKSHOP
12/05/2025	24,163 hrs	CODE 18 R-30377 CHECK CODE 18 - CHECK COOLANT LEVEL AND CHECK FOR COOLANT LEAKS REAR DOOR SEALS NEED REPLACING	HNL WORKSHOP
23/04/2025	20,086 hrs	CALIBRATION CERTIFICATE R-30130 FRIDGE CALIBRATION CERTIFICATE	Thermal Mark Transport Refrigeration
23/04/2025	20,086 hrs	A - PRE-CHECK S-13355 PRE TRIP AND REPAIR	Thermal Mark Transport Refrigeration
24/03/2025	19,923 hrs	B - 1000 HOUR SERVICE S-13160 CARRY OUT FRIDGE 1000 HOUR SERVICE	HNL WORKSHOP
21/03/2025	19,919 hrs	A - PRE-CHECK S-13157 	Thermal Mark Transport Refrigeration

Date	Reading / Units	Type / Repairer Notes	Repairer
		PERFORM PM-A REFRIGERATION SYSTEM PRE TRIP INSPECTION VISUAL INSPECTION OF FUEL SYSTEM, ELECTRICAL COMPONENTS, HOSES, CONNECTORS AND MOUNTING POINTS CHECK ENGINE OIL & COOLANT FLUID LEVELS AND ADD AS REQUIRED, CHECK THE CONDITION OF ALL BELTS AND ADJUST SENSORS AND CLEAR CODES, START UNIT AND INITIATE SYSTEM PRE TRIP TEST. OPERATE AND TEST UNIT THROUGH ALL MODES. CARRY OUT PMA INSPECTION, FOUND UNIT NOT STARTING AND CODE 18 -HIGH ENGINE COOLANT TEMP- ACTIVE, CARRY OUT ASSESSMENT OF COOLING SYSTEM FOR LEAKS - NONE PRESENT AT TIME OF INSPECTION, ADD COOLANT AND CLEAR RADIATOR OF DEBRIS AND BLOCKAGES, START UNIT AND RUN TO OPERATING TEMP WITHOUT FAULT, LOCATE AND REPAIR DAMAGED HIGH SPEED SOLENOID WIRING, ADD ENGINE OIL, PRE TRIP - PASS, DEGREASE ENGINE AND CONDENSOR, PRESSURE WASH, OPERATE AND TEST	
25/02/2025	19,768 hrs	A - PRE-CHECK S-13024	Thermal Mark Transport Refrigeration
		PERFORM PM-A REFRIGERATION SYSTEM PRE TRIP INSPECTION VISUAL INSPECTION OF FUEL SYSTEM, ELECTRICAL COMPONENTS, HOSES, CONNECTORS AND MOUNTING POINTS CHECK ENGINE OIL & COOLANT FLUID LEVELS AND ADD AS REQUIRED, CHECK THE CONDITION OF ALL BELTS AND ADJUST SENSORS AND CLEAR CODES, START UNIT AND INITIATE SYSTEM PRE TRIP TEST. OPERATE AND TEST UNIT THROUGH ALL MODES. CARRY OUT PMA INSPECTION, FOUND TOP IDLER SHAFT BEARINGS NOISEY IN OPERATION, REMOVE IDLER SHAFT HOUSING FROM UNIT, UNBOLT AND REMOVE ALL REQUIRED COMPONENTS TO GAIN ACCESS, REMOVE AND REPLACE WORN BEARINGS AND HARDWARE, RE-FIT ALL REMOVED ITEMS, REPLACE WORN DISCHARGE PIPE U-BOLT, ADD ENGINE OIL, PRE TRIP - PASS, DEGREASE ENGINE AND CONDENSOR, PRESUSRE WASH, OPERATE AND TEST	
30/01/2025	23,583 hrs	DVR 10421, TOP UP ENGINE OIL R-29029	HNL WORKSHOP
		DVR 10421 TOP UP FRIDGE ENGINE OIL - 3 LITRES TOP UP COOLANT AND CHECK COOLANT LEAKS CLEAN OUT FUEL STRAINER	
14/01/2025	19,524 hrs	A - PRE-CHECK S-12791	Thermal Mark Transport Refrigeration
		PERFORM PM-A REFRIGERATION SYSTEM PRE TRIP INSPECTION VISUAL INSPECTION OF FUEL SYSTEM, ELECTRICAL COMPONENTS, HOSES, CONNECTORS AND MOUNTING POINTS CHECK ENGINE OIL & COOLANT FLUID LEVELS AND ADD AS REQUIRED, CHECK THE CONDITION OF ALL BELTS AND ADJUST SENSORS AND CLEAR CODES, START UNIT AND INITIATE SYSTEM PRE TRIP TEST. OPERATE AND TEST UNIT THROUGH ALL MODES. CARRY OUT PMA INSPECTION, INSTALL FRONT DOOR LATCH (CUSTOMER SUPPLIED) TO FRONT ENGINE DOORS, ADD ENGINE OIL, PRE TRIP - PASS, DEGREASE ENGINE AND CONDENSOR, PRESSURE WASH, OPERATE AND TEST	
26/10/2024	19,196 hrs	FRIDGE NOT STARTING R-27962	TRS
22/10/2024	19,189 hrs	A - PRE-CHECK S-12334	Thermal Mark Transport Refrigeration
		REPORTED - UNIT NOT STARTING INSPECT UNIT AND CARRY OUT DIAGNOSTICS, PREFORM LOAD TEST - PASS, JUMP START UNIT, CONFIRM CHARGE RATE AND VOLTAGE, INITIATE PRE-TRIP - PASS, OPERATE AND TEST	
19/09/2024	19,011 hrs	A - PRE-CHECK S-12156	Thermal Mark Transport Refrigeration
		PERFORM PM-A REFRIGERATION SYSTEM PRE TRIP INSPECTION VISUAL INSPECTION OF OF FUEL SYSTEM, ELECTRICAL COMPONENTS, HOSES, CONNECTORS AND MOUNTING POINTS CHECK ENGINE OIL & COOLANT FLUID LEVELS AND ADD AS REQUIRED, CHECK THE CONDITION OF ALL BELTS AND ADJUST SENSORS AND CLEAR CODES, START UNIT AND INITIATE SYSTEM PRE TRIP TEST. OPERATE AND TEST UNIT THROUGH ALL MODES. CARRY OUT PMA INSPECTION, FOUND FRONT ENGINE DOORS DAMAGED AND CENTRE FASTENER NOT LATCHING CLOSED, REMOVE AND RE-INSTALL FASTENER MOUNTING BRACKETS FURTHER UP AND AWAY FROM DOOR DAMAGE, CONFIRM FASTENER NOW LATCHING AND DOORS ARE SECURE, FOUND BOTTOM ROLLERS ON D/S AND P/S OF REAR TODDCO DOOR DISLODGED FROM TRACKS, REMOVE AND RE-FIT BOTH ROLLERS TO TRACKS AND LUBRICATE AS REQUIRED, OPERATE AND TEST	
03/09/2024	18,939 hrs	REAR ROLLER DOOR REPAIR R-27416	Thermal Mark Transport Refrigeration
		REPORTED - ZONE 2 COVER + TODDCO DOOR UPON INSPECTION FOUND ZONE 2 COVER DETACHED FROM TRAILER AND LOCKING TABS BENT, REMOVE LOCKING TABS AND STRAIGHTEN, RE-FIT TABS ONTO COVER AND SECURE BACK OVER ZONE 2, CARRY OUT DEGREASE AND WASH OF ALL ZONE 2 COVERS. INSPECT REAR TODDCO DOOR AND FOUND BOTTOM ROLLERS SLIPPED FROM TRACKS AND BOTTOM SLAT FLAPPING, REMOVE BOTTOM HINGES, RE-INSTALL ROLLERS AND LUBRICATE TRACKS, CONFIRM DOOR OPERATIONS	
23/08/2024	18,877 hrs	zone 2 evap cover missing R-27160	Thermal Mark Transport Refrigeration
		REPORTED - MISSING EVAP COVER UPON INSPECTION FOUND ZONE 2 EVAPORATOR COVER MISSING, REPLACE MISSING COVER AND ALL REQUIRED HARDWARE, OPERATE AND TEST	
07/08/2024	18,797 hrs	A - PRE-CHECK S-11913	Thermal Mark Transport Refrigeration

Date	Reading / Units	Type / Repairer Notes	Repairer
19/07/2024	18,721 hrs	<p>PERFORM PM-A REFRIGERATION SYSTEM PRE TRIP INSPECTION VISUAL INSPECTION OF OF FUEL SYSTEM, ELECTRICAL COMPONENTS, HOSES, CONNECTORS AND MOUNTING POINTS CHECK ENGINE OIL & COOLANT FLUID LEVELS AND ADD AS REQUIRED, CHECK THE CONDITION OF ALL BELTS AND ADJUST SENSORS AND CLEAR CODES, START UNIT AND INITIATE SYSTEM PRE TRIP TEST. OPERATE AND TEST UNIT THROUGH ALL MODES. CARRY OUT PMA INSPECTION, RE-TENSION BELTS TO REQUIRED SPECS, REMOVE REAR TODDCO BRACKET TO REFIT ROLLER ONTO TRACKS, LUBRICATE ALL TRACKS, ROLLERS AND HINGES AND CONFIRM DOOR OPERATIONS, PRE TRIP - PASS, DEGREASE ENGINE AND PRESSURE WASH, OPERATE AND TEST</p>	Thermal Mark Transport Refrigeration
24/06/2024	18,574 hrs	<p>A - PRE-CHECK S-11732</p> <p>PERFORM PM-A REFRIGERATION SYSTEM PRE TRIP INSPECTION VISUAL INSPECTION OF OF FUEL SYSTEM, ELECTRICAL COMPONENTS, HOSES, CONNECTORS AND MOUNTING POINTS CHECK ENGINE OIL & COOLANT FLUID LEVELS AND ADD AS REQUIRED, CHECK THE CONDITION OF ALL BELTS AND ADJUST SENSORS AND CLEAR CODES, START UNIT AND INITIATE SYSTEM PRE TRIP TEST. OPERATE AND TEST UNIT THROUGH ALL MODES. CARRY OUT PMA INSPECTION, FOUND INTERNAL LIGHT HARNESS DETACHED FROM ROOF, RE-SECURE WIRING HARNESS WITH NEW CLAMPS AND REQUIRED HARDWARE, PRE TRIP - PASS, DEGREASE ENGINE AND CONDENSOR, PRESSURE WASH, OPERATE AND TEST</p>	Thermal Mark Transport Refrigeration
20/06/2024	18,558 hrs	<p>B - 1000 HOUR SERVICE S-11545</p> <p>PERFORM PM-A REFRIGERATION SYSTEM PRE TRIP INSPECTION VISUAL INSPECTION OF OF FUEL SYSTEM, ELECTRICAL COMPONENTS, HOSES, CONNECTORS AND MOUNTING POINTS CHECK ENGINE OIL & COOLANT FLUID LEVELS AND ADD AS REQUIRED, CHECK THE CONDITION OF ALL BELTS AND ADJUST SENSORS AND CLEAR CODES, START UNIT AND INITIATE SYSTEM PRE TRIP TEST. OPERATE AND TEST UNIT THROUGH ALL MODES. CARRY OUT PMA INSPECTION, LOCATE AND REPLACE BROKEN SERVICE INDICATOR AND DAMAGED COOLANT HOSE, REMOVE AND REPLACE DAMAGED N/S TODDCO DOOR SEAL, RE-FIT X2 DISLOGED TODDCO ROLLERS AND REMOUNT DISLODGED ZONE 2 COVER, ADD COOLANT, PRE TRIP - PASS, DEGREASE ENGINE AND CONDENSOR, PRESSURE WASH, OPERATE AND TEST</p>	KJS Fleet
13/05/2024	18,447 hrs	<p>A - PRE-CHECK S-11351</p> <p>PERFORM PM-A REFRIGERATION SYSTEM PRE TRIP INSPECTION VISUAL INSPECTION OF OF FUEL SYSTEM, ELECTRICAL COMPONENTS, HOSES, CONNECTORS AND MOUNTING POINTS CHECK ENGINE OIL & COOLANT FLUID LEVELS AND ADD AS REQUIRED, CHECK THE CONDITION OF ALL BELTS AND ADJUST SENSORS AND CLEAR CODES, START UNIT AND INITIATE SYSTEM PRE TRIP TEST. OPERATE AND TEST UNIT THROUGH ALL MODES. CARRY OUT TODDCO INSPECTION AND FOUND X2 ROLLERS SLIPPED OFF TRACKS, RE-INSTALL AND CHECK ALL REMAINING ROLLERS, BEARINGS AND HINGES, LUBRICATE ALL MOVING PARTS, CHECK DOOR TENSION AND CONFIRM OPERATIONS - ALL WITHIN REQUIRED SPECIFICATIONS AT TIME OF INSPECTION</p>	Thermal Mark Transport Refrigeration
12/05/2024	18,447 hrs	<p>STARTING ISSUE R-25850</p> <p>AFTER HOURS ASSISTANCE REQUESTED REPORTED - NO START ARRIVE ONSITE AND LOCATE TRAILER: UPON INSPECTION CARRY OUT FULL ASSESSMENT OF UNIT, LOAD TEST BATTERY - PASS, CHECK CHARGE CIRCUIT VOLTAGE AND COMPONENTS, START AND RUN UNIT - COULD NOT FAULT AT TIME OF INSPECTION</p>	Thermal Mark Transport Refrigeration
04/04/2024	18,327 hrs	<p>A - PRE-CHECK S-11174</p> <p>PERFORM PM-A REFRIGERATION SYSTEM PRE TRIP INSPECTION VISUAL INSPECTION OF OF FUEL SYSTEM, ELECTRICAL COMPONENTS, HOSES, CONNECTORS AND MOUNTING POINTS CHECK ENGINE OIL & COOLANT FLUID LEVELS AND ADD AS REQUIRED, CHECK THE CONDITION OF ALL BELTS AND ADJUST SENSORS AND CLEAR CODES, START UNIT AND INITIATE SYSTEM PRE TRIP TEST. OPERATE AND TEST UNIT THROUGH ALL MODES. UPON INSPECTION REMOVE AND REPLACE LEAKING FUEL RETURN LINE SET AND INSTALL FUEL STOP SOLENOID GROUNDING WIRE, ADD ENGINE OIL AND COOLANT, PRE TRIP - PASS, DEGREASE ENGINE AND CONDENSOR, PRESSURE WASH, OPERATE AND TEST</p>	Thermal Mark Transport Refrigeration
28/02/2024	18,164 hrs	<p>A - PRE-CHECK S-10930</p> <p>PERFORM PM-A REFRIGERATION SYSTEM PRE TRIP INSPECTION VISUAL INSPECTION OF OF FUEL SYSTEM, ELECTRICAL COMPONENTS, HOSES, CONNECTORS AND MOUNTING POINTS CHECK ENGINE OIL & COOLANT FLUID LEVELS AND ADD AS REQUIRED, CHECK THE CONDITION OF ALL BELTS AND ADJUST SENSORS AND CLEAR CODES, START UNIT AND INITIATE SYSTEM PRE TRIP TEST. OPERATE AND TEST UNIT THROUGH ALL MODES. UPON INSPECTION REMOVE AND REPLACE WORN DISCHARGE AND HOT GAS CLAMPS, PERFORM EVAPORATOR AND DRAIN TUBE CLEAN, RE-ATTACH CORNER COVER STRIP WITH NEW HARDWARE. REAR TODDCO DOOR DIFFICULT TO LIFT, CARRY OUT INSPECTION AND FOUND N/S ROLLER DETACHED FROM TRACKS, REMOVE HINGE AND REFIT ROLLER INTO TRACKS, CARRY OUT LUBRICATION OF ALL REQUIRED TODDCO PARTS, PRE TRIP - PASS, DEGREASE ENGINE AND CONDENSOR, PRESSURE WASH, OPERATE AND TEST</p>	Thermal Mark Transport Refrigeration

Date	Reading / Units	Type / Repairer Notes	Repairer
23/02/2024	830,552 kms 18,133 hrs	B - 1000 HOUR SERVICE S-10883 Carried out trailer fridge B service Replace engine and oil fuel filters Pre trip	KJS Fleet
08/01/2024	18,049 hrs	A - PRE-CHECK S-10589 REPORTED - ALARM 66 ACTIVE - DVR 09238 UPON INSPECTION FOUND OIL LEVEL IN UNIT EXTREMELY LOW, CARRIED OUT VISUAL INSPECTION FOUND VALVE COVER GASKET LEAKING - REMOVE AND REPLACE AS REQUIRED, REPLACE DAMAGED/WORN CONTROLLER BEZEL AND CONTROLLER COVER, SYSTEM PRE-TRIP - PASS, DEGREASE CONDENSOR AND ENGINE, PRESSURE WASH, OPERATE AND TEST UNIT.	Thermal Mark Transport Refrigeration
22/09/2023	17,518 hrs	A - PRE-CHECK S-10064 PRE TRIP AND REPAIR	FLETCHERS TRANSREFRIGERATION
15/08/2023	17,345 hrs	A - PRE-CHECK S-9868 PRE TRIP AND REPAIR	FLETCHERS TRANSREFRIGERATION
20/07/2023	17,149 hrs	fuel injection pump R-22737 REPLACED FUEL PUMP ASSEMBLY	TRS
10/07/2023	17,174 hrs	Engine Injector Fault R-22610 ENGINE MISS AND FUEL LEAK - DVR 09441 FOUND HOLD DOWN PLATE FOR INJECTOR STRIPPED FIT HELICOIL AND REPLACE BOLT - RUN AND TEST OK	HNL WORKSHOP
01/07/2023	17,530 hrs	No Start R-22459 Check fridge - Fuel related fault REPAIRED ELECTRICAL ISSUE REPAIRED REPLACED DAMAGED SIDE GRILLE PANEL	Thermal Mark Transport Refrigeration
01/07/2023	17,149 hrs	FUEL AND ELECTRICAL ISSUE R-22518 FUEL AND ELECTRICAL ISSUE REPAIRED SEE ATTACHED REPORT	TRS
19/06/2023		A - PRE-CHECK S-9450 PRE TRIP AND REPAIR REPLACE DAMAGED SIDE PANEL	Thermal Mark Transport Refrigeration
15/06/2023		RECTIFY NO START R-22339	Thermal Mark Transport Refrigeration
13/06/2023	17,092 hrs	A - PRE-CHECK S-9620 CARRY OUT FRIDGE PRE TRIP AND REPAIR	FLETCHERS TRANSREFRIGERATION
25/05/2023	17,039 hrs	engine exhaust leak R-21488 ENGINE EXHAUST LEAK BLOWING BLACK SMOKE OVER FRIDGE AND TRAILER	TRS
12/04/2023	16,838 hrs	A - PRE-CHECK S-9035 PRE TRIP AND REPAIR REFRIGERANT SERVICE	Thermal Mark Transport Refrigeration
13/03/2023	16,712 hrs	FRIDGE PRE TRIP R-21546 Fridge unit pre trip & check over Replace battery Replace belt set Replace coolant Condensor wash	Thermal Mark Transport Refrigeration
13/03/2023	699,750 kms 16,736 hrs	B - 1000 HOUR SERVICE S-8818 Carried out fridge unit B service & inspection as per HNL checklist All ok Replace engine oil - air fuel filters Pre trip	HNL Fleet Sydney
25/01/2023	16,562 hrs	B - 1000 HOUR SERVICE S-8518 CARRY OUT FRIDGE 1000 HOUR SERVICE	HNL WORKSHOP
11/12/2022	16,348 hrs	COOLANT TEMP SENSOR R-20604 COOLANT TEMP SENSOR WIRING ADJUST WATER PUMP BELT	Thermal Mark Transport Refrigeration
05/12/2022	16,321 hrs	A - PRE-CHECK S-8198 PRE TRIP AND REPAIR	FLETCHERS TRANSREFRIGERATION
05/10/2022	19,994 hrs	FRIDGE RAN OUT OF FUEL R-19881 FRIDGE HAS BEEN RAN OUT OF FUEL FILL FUEL TANK - BLEED SYSTEM RUN AND TEST OK	HNL WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
26/09/2022	16,034 hrs	A - PRE-CHECK S-7833 PRE TRIP AND REPAIR REPLACE GAS STRUT ON COVER	Thermal Mark Transport Refrigeration
19/08/2022	15,901 hrs	A - PRE-CHECK S-7714 PRE TRIP AND REPAIR	Thermal Mark Transport Refrigeration
04/07/2022	15,648 hrs	A - PRE-CHECK S-7534 PRE TRIP AND REPAIR	FLETCHERS TRANSREFRIGERATION
30/06/2022	15,627 hrs	B - 1000 HOUR SERVICE S-7305 carry out fridge engine 1000 hour service	Thermal Mark Transport Refrigeration
24/06/2022	15,608 hrs	A - PRE-CHECK S-7452 PRE TRIP AND REPAIR	Thermal Mark Transport Refrigeration
30/04/2022	15,422 hrs	A - PRE-CHECK S-7195 PRE TRIP AND REPAIR - AS PER ATTACHED	FLETCHERS TRANSREFRIGERATION
31/03/2022	15,279 hrs	FRIDGE PRE TRIP R-18303 PERFORMED REFRIGERATION UNIT PRE TRIP INSPECTION	Thermal Mark Transport Refrigeration
17/02/2022	15,130 hrs	FRIDGE PRE TRIP R-18167 PERFORMED REFRIGERATION UNIT PRE TRIP INSPECTION	Thermal Mark Transport Refrigeration
14/02/2022	536,568 kms	Battery Fault R-17922 Check fridge starting, check and find faulty battery, remove and replace battery and repair terminals + connections.	MJR Auto Electrical
31/01/2022	18,666 hrs	A - PRE-CHECK S-6801 PRE TRIP AND REPAIR	Thermal Mark Transport Refrigeration
06/12/2021	14,788 hrs	FRIDGE PRE TRIP R-17459 PERFORMED REFRIGERATION UNIT PRE TRIP INSPECTION	Thermal Mark Transport Refrigeration
08/11/2021	18,219 hrs	Fridge - Engine Cooling System R-17068 CARRIED OUT DIAGNOSTIC INSPECTION AND FOUND UNIT NIL REFRIGERANT. PRESSURE TEST AND INSPECT FOR LEAKS; PINHOLE LEAK EVIDENT AT EVAPORATOR REFRIGERANT LINE. WELD REPAIR AS REQUIRED AND RE-PRESSURE TEST; PASS. NITROGEN PURGE SYSTEM, REPLACE DRIER AND CHARGE REFRIGERANT. OPERATE AND TEST; PASS. PERFORMED REFRIGERATION UNIT PRE TRIP INSPECTION, CHECK AND ADJUST BELTS AS REQUIRED, VISUAL INSPECTION TO FUEL SYSTEM, ELECTRICAL COMPONENTS, CONNECTORS, FLUID LEVELS, IDLER BEARINGS AND MOUNTING BOLTS, OPERATE AND TEST UNIT.	Thermal Mark Transport Refrigeration
05/11/2021	482,751 kms	Call out R-17039 attend saber refitted fridge cover all ok	HNL Sydney Workshop
14/10/2021	14,610 hrs	Engine Fan Belt Idler Pulley, FRIDGE PRE TRIP R-16987 CHECK AND ADJUST BELTS AS REQUIRED, VISUAL INSPECTION TO FUEL SYSTEM, ELECTRICAL COMPONENTS, CONNECTORS, FLUID LEVELS, IDLER BEARINGS AND MOUNTING BOLTS, OPERATE AND TEST UNIT. REMOVE AND REPLACE WORN JACKSHAFT PULLIES IDENTIFIED DURING PRETRIP INSPECTION.	Thermal Mark Transport Refrigeration
30/08/2021	14,447 hrs	FRIDGE PRE TRIP R-16470 PERFORMED REFRIGERATION UNIT PRE TRIP INSPECTION	Thermal Mark Transport Refrigeration
18/08/2021		Cooltrax - Installation R-16082 New Installation	Cooltrax Asia Pacific

Signed: _____

Name: _____

Date: _____