

Model Desc	Plant #	Make	Manufacturers Model	Serial No	Inspection Date	Metre Reading	Service Type	Comments
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	21/11/2024	2132	Quarterly	Baseplan Import Service No:709184
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	31/08/2024	2132	Quarterly	Baseplan Import Service No:689679
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	15/06/2024	2113	Quarterly	Baseplan Import Service No:667940
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	15/06/2024	2113	Annual	Baseplan Import Service No:667940
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	14/06/2024	2113	Quarterly	Baseplan Import Service No:667827
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	14/06/2024	2113	Annual	Baseplan Import Service No:667827
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	15/03/2024	2106	Quarterly	Baseplan Import Service No:641933
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	06/03/2024	2105	Quarterly	Baseplan Import Service No:637506
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	27/09/2023	2093	Quarterly	Baseplan Import Service No:595061 Carry Out Inspection Quarterly Inspection
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	02/08/2023	2090	Quarterly	Baseplan Import Service No:580376 Carry Out General Travel to site Carry Out Inspection Annual Inspection
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	02/08/2023	2090	Annual	Baseplan Import Service No:580376 Carry Out General Travel to site Carry Out Inspection Annual Inspection
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	11/07/2023	2067	Quarterly	Baseplan Import Service No:573429
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	19/06/2023	2072	Quarterly	Baseplan Import Service No:569391
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	10/05/2023	2067	Quarterly	Baseplan Import Service No:555295
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	29/03/2023	2066	Quarterly	Baseplan Import Service No:528266

Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	13/11/2022	2050	Quarterly	Baseplan Import Service No:513458 Repair Wiring Engine Carry Out General Travel to site Diagnose Auxillary Battery Battery/Charger Diagnose Rated Capacity Limiter Safety Syatems Travel to site. Operator was stuck in basket due to start fault and auxiliary batteries going flat. Replaced start relay and 30a maxi fuse. 1x auxiliary battery U/S. Machine requires platform overload calibration. Carry Out General Technical Support Carry Out Quarterly Inspection as per Checklist Calibrate Over Load Protection System Safety Syatems Travel to site. Replace 1 x Aux battery.
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	04/10/2022	2043	Quarterly	Baseplan Import Service No:502494 Diagnose Auxillary Battery Battery/Charger Carry Out General Travel to site Carry Out Quarterly Inspection as per Checklist Replace Auxillary Battery Battery/Charger Travel to site. Diagnose auxiliary power fault. Batteries U/S. Return to workshop

Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	17/08/2022	2038	Quarterly	Baseplan Import Service No:492148 Carry Out General Travel to site Carry Out Annual Inspection as per Checklist
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	17/08/2022	2038	Annual	Baseplan Import Service No:492148 Carry Out General Travel to site Carry Out Annual Inspection as per Checklist
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	12/05/2022	2005	Quarterly	Baseplan Import Service No:470697 Carry Out General Travel to site Carry Out Quarterly Inspection as per Checklist Repair Tank Hydraulics General

Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	26/02/2022	1982	Quarterly	Baseplan Import Service No:449261 Job Created by FSM technician Repair Covers & Panelling Chassis/Bodywork Repair Other Engine Carry Out General Equipment Cleaning Cleaning. Replace inline fuel filter. Replace cover bolt. Adjust Other Boom Repair Over Load Protection System Safety Syatems Calibrate Over Load Protection System Safety Syatems Repair Other Platform Replace Wear Pads Boom Carry Out Quarterly Inspection as per Checklist
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	29/11/2021	1966	Quarterly	Baseplan Import Service No:433008 Carry Out Quarterly Inspection as per Checklist LES @ 1890 hrs Safety check,LS/C,AS/C,

Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	26/08/2021	1891	Quarterly	Baseplan Import Service No:409812 Carry Out Annual Inspection as per Checklist Replace Accessories Flashing Beacons Check/Inspect Wheel Nuts Wheels/Tyres Replace Fan Belt Cooling System Carry Out 500hr Service - Oil & Filter Change - Complete Service Inspection Checklist. Safety check,LSC,AS/C, full function tested. Re torque turntable bolts, wheel nuts
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	26/08/2021	1891	Annual	Baseplan Import Service No:409812 Carry Out Annual Inspection as per Checklist Replace Accessories Flashing Beacons Check/Inspect Wheel Nuts Wheels/Tyres Replace Fan Belt Cooling System Carry Out 500hr Service - Oil & Filter Change - Complete Service Inspection Checklist. Safety check,LSC,AS/C, full function tested. Re torque turntable bolts, wheel nuts

Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	29/07/2021	1864	Quarterly	Baseplan Import Service No:404579 Calibrate Drive Control Module Control Modules Recalibrated drive valve-not calibrated Carry Out Quarterly Inspection as per Checklist Repair Other Boom Calibrate Joy Stick Controllers General LES @ 1541 hrs Safety check,LSC,AS/C, full function tested. Bleeding see boom
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	18/05/2021	1817	Quarterly	Baseplan Import Service No:387877 Carry Out Quarterly Inspection as per Checklist Replace Mounting Platform Carry Out General Equipment Cleaning LES @ 1541 hrs Safety check,LSC,AS/C,
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	15/04/2021	1806	Quarterly	Baseplan Import Service No:379846 Carry Out Quarterly Inspection as per Checklist Calibrate Presence Detection Platform Recalibrated platform level sensor-keeps out of level. LES @ 1541 hrs full function tested
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	05/03/2021	1769	Quarterly	Baseplan Import Service No:370911 Carry Out Quarterly Inspection as per Checklist

Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	10/02/2021	1755	Quarterly	Baseplan Import Service No:364452 Remove Slew Motor Platform Carry Out Quarterly Inspection as per Checklist Dis assembled platform rotator and clean out-leaking Replace Hose High Pressure Hoses Reseal Slew Motor Platform Resealed slew motor and replaced platform level hyd hoses-U/S Refit Slew Motor Platform
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	25/01/2021	1745	Quarterly	Baseplan Import Service No:360699 Carry Out Quarterly Inspection as per Checklist
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	04/01/2021	1728	Quarterly	Baseplan Import Service No:356593 Carry Out Quarterly Inspection as per Checklist Carry Out General Equipment Cleaning LES @ 1541 hrs Safety check, LSC, ASC,full function tested, Bleeding sec.
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	28/09/2020	1703	Quarterly	Baseplan Import Service No:336053 Job Created by FSM technician Carry Out Annual Inspection as per Checklist Carry Out General Travel to site

Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	28/09/2020	1703	Annual	Baseplan Import Service No:336053 Job Created by FSM technician Carry Out Annual Inspection as per Checklist Carry Out General Travel to site
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	14/07/2020	1681	Quarterly	Baseplan Import Service No:318822 Scheduled Service - Carry Out Quarterly Inspection as per Checklist Carry Out General Travel to site
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	02/05/2020	1664	Quarterly	Baseplan Import Service No:302936 Carry Out Quarterly Inspection as per Checklist Repair Other Electrical general Safety check and full function tested.
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	09/04/2020	1662	Quarterly	Baseplan Import Service No:298615 Carry Out Quarterly Inspection as per Checklist Install Navman Electrical general LES @1541 hrs Safety check and full
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	18/03/2020	1640	Quarterly	Baseplan Import Service No:293811 Repair Wiring Harness Electrical general Carry Out Quarterly Inspection as per Checklist Replace Hose High Pressure Hoses LES @ 1541 hrs Safety check and full function tested. Replaced TP hyd. hoses

Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	19/02/2020	1638	Quarterly	Baseplan Import Service No:287098 Replace Accessories Fire Extinguisher Carry Out Quarterly Inspection as per Checklist Repair Linkages Controllers General LES @ 1541 hrs Safety check and full function tested. repaired throttle solenoid
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	03/02/2020	1606	Quarterly	Baseplan Import Service No:283651 Carry Out Quarterly Inspection as per Checklist
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	17/12/2019	1587	Quarterly	Baseplan Import Service No:275183 Carry Out Quarterly Inspection as per Checklist
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	02/12/2019	1580	Quarterly	Baseplan Import Service No:271686 Carry Out Quarterly Inspection as per Checklist Refit Hose Clamps Hoses
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	28/11/2019	1575	Quarterly	Baseplan Import Service No:270580 Carry Out Quarterly Inspection as per Checklist Replace Other Hydraulics General LES @ 1541 hrs safety check and full

Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	15/11/2019	1572	Quarterly	Baseplan Import Service No:267167 Check/Inspect Other Hydraulics General Carry Out Quarterly Inspection as per Checklist Check/Inspect Drive Tyres Wheels/Tyres Safety check and full function tested. Tighten flow divider valves on drive manifold. Re torque wheel nut. Replace Control Valve Hydraulics General Flush Other Hydraulics General Adjust Other Hoses LES @ 1541 hrs Adjusted sec. boom hyd. hoses and wiring harness-too loose
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	26/09/2019	1541	Quarterly	Baseplan Import Service No:255200
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	26/09/2019	1541	Quarterly	Baseplan Import Service No:255198
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	26/09/2019	1541	Annual	Baseplan Import Service No:255198

Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	26/08/2019	1539	Quarterly	Baseplan Import Service No:239054 Diagnose Other Control Modules Carry Out General Other General Repair Proximity Switch Boom Carry Out General Travel to site Diagnosed all boom won't come down- check all wiring connector and clean and tested all limit switches found secondary extend/retract limit switch roller arm accuator dis-align- stowed all boom down using bypass control.-found ground control touch pad some switch not responding- (parts order) Carry Out Quarterly Inspection as per Checklist Remove Hose High Pressure Hoses Replace Hose Rollers Hoses removed primary hydraulic hose-U/S and replaced 5x cable track hose roller-damage Refit Hose High Pressure Hoses Re fitt new hydraulic hose and adjusted hose and wiring harness into position. Repair Other Boom
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	09/07/2019	1518	Quarterly	Baseplan Import Service No:235575 Refit Other Platform Carry Out Quarterly Inspection as per Checklist

Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	27/06/2019	1511	Quarterly	Baseplan Import Service No:232317 Carry Out Quarterly Inspection as per Checklist
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	11/06/2019	1507	Quarterly	Baseplan Import Service No:228012 Carry Out Quarterly Inspection as per Checklist Replace Other Hydraulics General Replaced bell crank cylinder and platform
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	08/05/2019	1500	Quarterly	Baseplan Import Service No:220277 Repair Other Hydraulics General Carry Out Quarterly Inspection as per Checklist Re-tightened hyd.hose fittings on secondary
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	16/04/2019	1495	Quarterly	Baseplan Import Service No:216196 Carry Out Quarterly Inspection as per Checklist Repair Other Hydraulics General
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	21/02/2019	1479	Quarterly	Baseplan Import Service No:204456 Replace Battery Battery/Charger Carry Out Quarterly Inspection as per Checklist
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	31/01/2019	1470	Quarterly	Baseplan Import Service No:199669 Carry Out Quarterly Inspection as per Checklist Carry Out General Equipment Cleaning
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	12/01/2019	1439	Quarterly	Baseplan Import Service No:195750

Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	07/01/2019	1439	Quarterly	Baseplan Import Service No:192609 Repair Electric Throttle Control Engine Adjust Electric Throttle Control Engine Carry Out Quarterly Inspection as per Checklist Installed lock nut on throttle solenoid linkage-missing adjusted engine RPM.
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	28/11/2018	1436	Quarterly	Baseplan Import Service No:187809 Carry Out General Equipment Cleaning Carry Out Quarterly Inspection as per Checklist Replace Horn Safety Syatems
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	02/11/2018	1430	Quarterly	Baseplan Import Service No:181639 Carry Out Quarterly Inspection as per Checklist Replace Other Engine
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	02/11/2018	1430	Quarterly	Baseplan Import Service No:181641 Carry Out Annual Inspection as per Checklist
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	02/11/2018	1430	Annual	Baseplan Import Service No:181641 Carry Out Annual Inspection as per Checklist
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	16/10/2018	1396	Quarterly	Baseplan Import Service No:177666

Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	18/09/2018	1387	Quarterly	Baseplan Import Service No:171368 Carry Out Quarterly Inspection as per Checklist Refit Hose Protection Hoses Carry Out General Equipment Cleaning Repair Other Hydraulics General LES @ 1283 hrs Check and test limit switch safety envelope and and circuit. Removed low level bottom track roller
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	03/09/2018	1384	Quarterly	Baseplan Import Service No:168199 Carry Out General Equipment Cleaning Carry Out Quarterly Inspection as per Checklist
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	23/08/2018	1376	Quarterly	Baseplan Import Service No:165437 Carry Out General Equipment Cleaning Carry Out Quarterly Inspection as per Checklist Refit Switch Controllers General Refit Switch Controllers General
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	13/08/2018	1369	Quarterly	Baseplan Import Service No:163764
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	17/07/2018	1366	Quarterly	Baseplan Import Service No:157526 QI QI done by Rheece from Genie
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	21/06/2018	1355	Quarterly	Baseplan Import Service No:151621
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	05/06/2018	1349	Quarterly	Baseplan Import Service No:148110 Carry Out Quarterly Inspection as per Checklist Carry Out General Equipment Cleaning

Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	03/05/2018	1321	Quarterly	Baseplan Import Service No:140566 Carry Out Quarterly Inspection as per Checklist Replace Drive Tyres Wheels/Tyres Replace Other Electrical general Replace Other Engine Replace Electric Throttle Control Engine Replaced engine oil pump, Replaced platform control Deutz plug, Replaced blue end yellow side wheel. LES=1296 Carry Out General Equipment Cleaning Check/Inspect Other Boom
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	12/04/2018	1302	Quarterly	Baseplan Import Service No:133439 Carry Out Quarterly Inspection as per Checklist Replace All Tyres Wheels/Tyres Repair Other Engine Swap front wheels to Rear wheels, clean engine oil pump, full function test(twice), Retorque wheel nuts. LES=1286 Carry Out General Equipment Cleaning Full calibration Replaced see boom

Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	17/03/2018	1296	Quarterly	Baseplan Import Service No:130155 Replace Other Hydraulics General Carry Out Quarterly Inspection as per Checklist Repair Other Hydraulics General Top-up hydraulic oil, Repaired hyd.hoses
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	10/01/2018	1292	Quarterly	Baseplan Import Service No:114534 Carry Out General Equipment Cleaning Carry Out Quarterly Inspection as per
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	21/12/2017	1271	Service In	Baseplan Import Service No:97905 Repair Other Chassis/Bodywork Calibrate Other Electrical general Carry Out 500hr Service - Oil & Filter Change - Complete Service Inspection Checklist. Carry Out Annual Inspection as per Checklist Replace Mounting Platform Carry Out Quarterly Inspection as per Checklist annual inspection 90 day inspection 500 hr
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	30/11/2017		Repair	
Knuckle Boom - 135ft (41.5m) - DieselOpen	H102036	Genie	ZX135/70	ZX13514-2375	29/09/2017	1215	Quarterly	Baseplan Import Service No:81012 Scheduled Service - Carry Out Quarterly Inspection as per Checklist Carry Out General Travel to site Calibrate Over Load Protection System Safety Syatems

Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	22/06/2017	1123	Quarterly	Baseplan Import Service No:58306 quarterly inspection Carry Out General Equipment Cleaning Carry Out Quarterly Inspection as per Checklist
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	09/06/2017	1118	Quarterly	Baseplan Import Service No:55219
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	08/06/2017	1118	Quarterly	90 day inspection
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	18/05/2017	1111	Quarterly	90 day inspection Replaced 2x fuel hoses
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	08/05/2017	1101	Quarterly	90 day passed
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	26/04/2017	1099	Quarterly	
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	13/04/2017	1048	Quarterly	90 day inspection
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	15/02/2017	1026	Quarterly	90 day inspection Repair hydraulic tank - split in rear of tank
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	10/11/2016	950	Quarterly	90 day inspection Replace " rings on plugs in rear of function manifold (leak). Too up
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	10/11/2016	950	Quarterly	Automatic reset from Annual Inspection
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	10/11/2016	950	Annual	Annual inspection
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	17/08/2016	823	Quarterly	90 day inspection Fix hydraulic leak in hydraulic pump hose
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	21/07/2016	813	Quarterly	90 day inspection and clean Replace basket
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	29/06/2016	812	Quarterly	
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	29/06/2016	812	Other	lubricate and recalibrate jib level sensor
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	03/06/2016	804	Pre Hire Inspection	
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	30/05/2016	803	Quarterly	
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	30/05/2016	803	Hydraulic	replace pressure hose from rear knuckle to
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	30/05/2016	803	Other	clean machine top up hyd oil 30 litres
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	01/05/2016	771	Quarterly	
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	01/05/2016	771	Other	retorque wheel nuts 320 ft pounds refit wheel nut indicators as per bulletin check software settings for axle motion only

Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	01/03/2016	702	Service Inspection	
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	13/02/2016	669	Quarterly	
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	15/11/2015	532	Quarterly	Automatic reset from Annual Inspection
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	15/11/2015	532	Annual	
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	28/10/2015	477	Quarterly	
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	19/10/2015	468	Repair	
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	29/09/2015	442	Hydraulic	replaced o-ring on function manifold
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	18/09/2015	427	Service Inspection	
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	06/08/2015	342	Quarterly	
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	06/08/2015	342	Other	topped up engine
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	18/06/2015	242	Hydraulic	Remove sencondary boom cat track, remove primary extend and retract hoses from the cat track. Fit new hoses and
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	20/05/2015	189	Quarterly	250hr service saftey limit switch check
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	20/05/2015	189	Other	fitted new door handles
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	09/03/2015	106	Quarterly	
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	09/03/2015	106	Hydraulic	pulled though primery ext hoses (already
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	29/12/2014	30	Quarterly	
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	11/12/2014	23.3	Pre Hire Inspection	
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	01/12/2014	11	Quarterly	Automatic reset from Annual Inspection
Knuckle Boom - 135ft (41.5m) - DieselOper	H102036	Genie	ZX135/70	ZX13514-2375	01/12/2014	11	Annual	fitted weight decals to basket fitted new beacon