



Haylock Truck and Trailer
157A Aulac Rd.
Aulac, NB E4L 2V9
Tel.(506) 536-1813
www.hcrs.ca

JOOS

INVOICE #
042634

Created : August 19 2024

ESTIMATE #	29886
P.O. #	
DATE	August 29 2024

CUSTOMER : 000000938

Work: () - -

Cell: () - -

Fax: () - -

VEHICLE :

MAKE : WESTERN STAR

MODEL : WB123064T

YEAR : 2020

VIN # : 5KJJAEEFG6LPKY4283

EXIT KM : 701951

LICENSE : PUK777

CYLINDERS :

COLOUR : RED

ENGINE :

USAGE TIME : 14060

PART NO	DESCRIPTION	QTY	UNIT \$	%	PARTS	LABOUR
000MVI.TK	MVI TRUCK	1	155		155.00	
00MVI.BUS	MVI CHECK {D3}	1				
MVI.STICKERS	MVI STICKER HV 023074	1				
00MVI.BM	MVI BRAKE MEASUREMENTS {D3}	0.5				
	SHOES					
	11/16 11/16					
	9/16 9/16					
	11/16 9/16					
	DRUMS					
	16.57 16.57					
	16.58 16.58					
	16.58 16.61					
	TIRES					
	9 9					
	NEW					
	16/16 16/16					
00OIL.OF	OIL & FILTER CHANGE {CS}	1.5	110.00			165.00
FF5825NN	FUEL FILTER	1	83.50		83.50	
LF14000NN	OIL FILTER ISX (LF 9080 / LF9001)	1	64.53		64.53	
0FS19551	FUEL/WATER SEPERATOR	1	45.21		45.21	
00015W40	IDO Duron Oil 15W40	42	5.11		214.62	
00ELE.EG	ELECTRICAL GENERAL {D3}	1	110.00			110.00
00ELE.EG	REVERSE LIGHT {N1}	2.5	110.00			275.00
	CHECK POWER PROBLEM FOR REVERSE LIGHTS. FOUND THERE WAS INSUFFICIENT AMPERAGE. FOUND REVESE SWITCH BAD. REPLACED SWITCH.					
465P / GRO82-0465	BACK UP SWITCH	1	25.26		25.26	
00ELE.EG	CARGO LIGHT {D3}	1				
	NOTE: JUST REMOVED LIGHT AS IT WAS NOT HOOKED UP OR WIRED IN, AND LIGHT WAS CRACKED.					
0BRK.ABS	ABS BRAKING SYSTEM GENERAL {CG}	0.5	110.00			55.00
	CHECK FOR CAUSE OF ABS LIGHT ON. REMOVED & REPLACED ABS SENSOR.					
S28090/4410309092	MERITOR ABS WHEEL SENSOR KIT	1	72.28		72.28	
0ACC.MSC	MISCELLANEOUS REPAIRS {D3}	1	110.00			110.00
0BRK.GEN	RIGHT REAR BRAKE POT {CG}	1	110.00			110.00
	REMOVED & REPLACED RIGHT REAR BRAKE POT. REMOVED HUB CAP AND ADJUSTED WHEEL BEARING.					
U34HAB632C	AIR HOSE	1	17.40		17.40	

*** Continued on next page ***



Haylock Truck and Trailer
157A Aulac Rd.
Aulac, NB E4L 2V9
Tel.(506) 536-1813
www.hcrs.ca

INVOICE #
042634

Created : August 19 2024

ESTIMATE #	29886
P.O. #	
DATE	August 29 2024

CUSTOMER : 0000000938

Doncaster Logging Inc.
723 Rte 935
Woodpoint,
New Brunswick E4L 2K9

Work: () - -
Res. : (506) 232-6635
Cel. : () - -
Fax. : () - -

VEHICLE :

MAKE : WESTERN STAR
MODEL : WB123064T
YEAR : 2020
VIN # : 5KJJAEEFG6LPKY4283
LICENSE : PUK777
COLOUR : RED
USAGE TIME : 14060
EXIT KM : 701951
CYLINDERS :
ENGINE :

PART NO	DESCRIPTION	QTY	UNIT \$	%	PARTS	LABOUR
SB3030PKLC	PIGGY BACK	1	76.36		76.36	
E343-4024/303-4024	HUB CAP	1	63.10		63.10	
0AIR.ASG	AIR SYSTEM GENERAL {CS}	0.75	110.00			82.50
	REMOVED & REPLACED LEFT REAR AIR BAG					
W01-377-8536	AIR BAG	1	174.06		174.06	
0ACC.MSC	SPRING PIN REPAIRS {CS}	4	110.00			440.00
	REMOVED & REPLACED ALL SPRING PIN BUSHINGS ON ALL DRIVE AXLES.					
AUTMR782	SILENT BLOCK	2	61.87		123.74	
AUTMR783	OVERSIZED BUSHING	2	91.25		182.50	
0BRK.GEN	BRAKE WORK FRONT DRIVE {CS}	2.25	110.00			247.50
	REMOVED AND REPLACED BOTH SETS OF SHOES AND DRUMS ON FRONT DRIVES.					
GUN 3922X	DRUM	2	138.53		277.06	
1707/TRB046E23-6R	ROCKWELL Q+ BRAKES	2	76.93		153.86	
TIRE.WTG	WHEELS, TIRES GENERAL {CG}	0.5	110.00			55.00
	TIGHTENED RIGHT FRONT STEER WHEEL BEARING.					
5TH.REPL	5TH WHEEL {CG}	1	110.00			110.00
	REMOVED & REPLACED 5TH WHEEL PLATE.					
HOL XA351ALP	LEFT HAND PLATE	1	1609.98		1609.98	
0BRK.GEN	RIGHT REAR BRAKE WORK GENERL {CS}	0.5	110.00			55.00
	REMOVED & REPLACED RIGHT REAR DRUM & SHOES.					
N42A1658625B	CON MAT MOUNTAIN BRAKE DRUM	1	274.93		274.93	
BRAKES4711QP	BRAKES	1	191.90		191.90	
0SUS.GEN	SUSPENSION GENERAL {CS}	0.5	110.00			55.00
	REMOVED & REPLACED REAR REAR AXLE DRIVE SHOCKS.					
GAB 85724	SHOCK	2	94.25		188.50	
00E11715	WHEEL STUD	1	18.36		18.36	

We value our customers and want you to be satisfied. If you have any problems with the repairs we performed or the service we provided, please speak to our Service Manager.

Taney

Haylock Truck and Trailer

157A Aulac Rd.

Aulac, NB E4L 2V9

Tel.(506) 536-1813

www.hcrs.ca

INVOICE #

042634

ESTIMATE #	29886
P.O. #	
DATE	August 29 2024

Created : August 19, 2024

CUSTOMER: 0000000938

Doncaster Logging Inc.

723 Rte 935

Woodpoint,

New Brunswick E4L 2K9

Work: () -

Res. : (506) 232-6635

Cel. : () -

Fax. : () -

VEHICLE :

MAKE : WESTERN STAR

MODEL: WB123064T

YEAR: 2020

VIN #: 5KJJAEEFG6LPKY4283

LICENSE : PUK777

COLOUR: RED

USAGE TIME: 14060

EXIT KM: 701951

CYLINDERS :

ENGINE :

PART NO	DESCRIPTION	QTY	UNIT \$	%	PARTS	LABOUR

Hourly rate : 110.00

SUB-TOTAL	\$3 867.15	\$2 015.00
-----------	------------	------------

SUB-TOTAL	\$5 882.15
-----------	------------

SHOP SUPPLIES	\$200.00
---------------	----------

HST	876734419RT0001	\$912.32
-----	-----------------	----------

\$0.00

\$0.00

TOTAL	\$6 994.47
-------	------------

Disclaimer of Warranties

All repairs and all new or reconditioned parts installed are guaranteed for a minimum of ninety days or 5,000 KM, whichever comes first. The warranty takes effect upon delivery of the automobile.

PAYMENTS

RECEIVABLES	6994.47
-------------	---------

SALES BY CREDIT: Payable upon receipt of the account statement. Administration fees will be charged on all outstanding balances at a rate of 2% per month (24% yearly). All merchandise sold remains the property of the seller until full payment has been received. The customer's signature below confirms he/she has taken knowledge of and accepts all terms and conditions. I hereby authorize the opening and keeping of a maintenance and repair file and I also hereby authorize the repair shop and their employees to collect, use and communicate to any third party any personal or other information which is necessary to the constitution of the file and for marketing use. I hereby grant you and your employees permission to operate the vehicle herein described on streets, highway or elsewhere for the purpose of testing on inspection.

Date: _____

Customer's signature :