



Mur-Cal Services Ltd.
15301 89 Street
Grande Prairie, AB T8V 0V7
780 539-0928

EQUIPMENT WORK ORDER 2578

Equipment: 2170 24 CHEVROLET SILVERADO Chev Silverado 3500 crewcab

Serial #: 1GC4YTEY6RF275540

Repair Status: WORKING

Order Date: 01/28/25

Current location:

Mechanic: FINN

Required Date:

W.O. Status: Closed

Problem Type:

Start Date:

Priority: 1

Problem Cause:

Finish Date: 03/15/25

Reported By:

Return to Service: 03/15/25

Contact Name:

Closed Date: 03/15/25

Authorized By: _____
Signature and Date

Mechanic: _____
Signature and Date

Additional Parts Required:

Mechanics Completion Notes:



Mur-Cal Services Ltd.
15301 89 Street
Grande Prairie, AB T8V 0V7
780 539-0928

EQUIPMENT WORK ORDER 4540

Equipment: 2170 24 CHEVROLET SILVERADO Chev Silverado 3500 crewcab

Serial #: 1GC4YTEY6RF275540

Repair Status: COMPLETE

Order Date: 12/16/25

Current location:

Mechanic: CALIEN

Required Date:

W.O. Status: Finished

Problem Type: INSIDE

Start Date: 12/16/25

Priority: 9

Problem Cause: WEAR

Finish Date: 12/16/25

Reported By:

Return to Service: 12/16/25

Contact Name:

Closed Date:

WORK ORDERED

<u>Component Group</u>	<u>Work Ordered Notes</u>	<u>Work Order Status</u>
OPEN STATUS:		

SERVICES All components

REPLACE TIDY TANK PUMP

Open

☐

Warranty Status: No, not applicable

PARTS USED

<u>Date</u>	<u>Item</u>	<u>Bin Location</u>	<u>U/M</u>	<u>Quantity</u>	<u>Part Note</u>
Inventory:					
12/16/25	FR-4204 12V By 20 GPM Fill-Rite Pump	SCF-A01		-1.00	

NOTES

TOPIC NOTES:

December 16/2025 - Calien

Pull unit into shop. Test tidy tank fuel pump - non receptive. Replace tidy tank pump and fuse. Verify repairs.
Ok.

December 16/2025 - Calien

2170 2 hr
re re tidy tank pump

Authorized By: _____
Signature and Date

Mechanic: _____
Signature and Date

Additional Parts Required:

Mechanics Completion Notes: