



# Vehicle History Summary



Fleet #	YN63TN
Registration	YN63TN
Make	SLOANE BUILT
Model	4ADT02A
VIN / Chassis #	6B9X4DAH2AE6838
Build Date	2017

Date	Reading / Units	Type / Repairer Notes	Repairer
15/04/2026	1,127,755 kms	<b>B - 20k</b> S-6884	Ivan Plevnarovski
16/02/2026	783,548 kms	<b>Air leak, Indicator light, tailgate booster</b> R-9073 1. tailgate booster leaking internally. removed and replaced booster. had to cut pushrod and weld extender in to make booster length correct	Ivan Plevnarovski
25/11/2025	1,115,654 kms	<b>A - 15k</b> S-6800	Ivan Plevnarovski
24/10/2025	783,548 kms	<b>Tyres</b> T-137	South West Sydney Tyres
24/10/2025	783,548 kms	<b>Tyres</b> T-129	South West Sydney Tyres
24/10/2025	783,548 kms	<b>Tyres</b> T-188	South West Sydney Tyres
13/08/2025	1,099,800 kms	<b>B - 30k</b> S-6705 replaced a3 brakes RHS low	Ivan Plevnarovski
10/07/2025	783,548 kms	<b>brake lights, Fault report</b> R-8793 replaced tail light as required	Ivan Plevnarovski
25/06/2025	1,083,880 kms	<b>A - 15k</b> S-6644 1. Refitted dolly mudflap	Outback Industries
11/04/2025	1,073,522 kms	<b>C - Annual</b> S-6526	Ivan Plevnarovski
11/04/2025	1,073,522 kms	<b>Drawbar Measurements</b> I-231	
07/03/2025	1,071,398 kms	<b>Mudflap</b> R-8529 Fit new mudflap.	Ben Potts
31/01/2025	1,069,028 kms	<b>B - 30k</b> S-6410 1. 3rd axle brakes replace 2. A1 o/s air bag worn 3. A1 o/s shock	Gavin Smith-Croucher, Ivan Plevnarovski
31/01/2025	1,069,028 kms 783,548 hrs	<b>AIR BAGS, Brakes, shock absorber</b> R-8396 1. Next service. 2. Gsc replaced air bag with a new one 3. Bp replaced a3 o/s shock	Gavin Smith-Croucher
21/01/2025	1,067,358 kms	<b>Drawbar Measurements</b> I-204	
05/12/2024	1,063,171 kms	<b>A - 15k</b> S-6317 1. A3 n/s brakes getting low (5mm). Will schedule for next service. 2. A3 n/s air spring fatiguing. Will schedule for next service. 3. Tarp torn off bow nearly at n/s 2nd from front. Still servieable. Will schedule at next service. 4. Tyre report done. 5. Marker stickers fading. Schedule for next service.	Ben Potts
24/10/2024	1,048,863 kms	<b>B - 30k</b> S-6222	Alex Martin, Gavin Smith-Croucher

Date	Reading / Units	Type / Repairer Notes	Repairer
		1. A3 o/s air bag needs replacing 2. A3 brakes next service. 3. A3 inner and outer tyres worn lumpy/large flat spots. Outer tyre is worse. Did a tyre report for TT Tyres. 4. Crakes in bin cross support and in host well : photo have been taken of effected areas and has been reported to management	
22/10/2024	1,048,863 kms	<b>Fault report, wiring harness</b> R-8076 Broken/ corded wires in draw bar wiring harness repaired and fixed broken wires	Alex Martin
23/08/2024	1,035,797 kms	<b>A - 15k</b> S-6090 1. Grain lock wear plate missing n/s 2. Tail gate has a split in it	Alex Martin, Ben Potts, Gavin Smith-Croucher
13/08/2024	1,032,691 kms 783,548 hrs	<b>B - 30k</b> S-6076	Alex Martin, Gavin Smith-Croucher
05/07/2024	783,548 kms	<b>Drawbar Measurements</b> I-85 Drawbar: Tow eye width: 42.60mm, Tow eye bush ID: Fit new bush.	
05/07/2024	1,020,253 kms 783,548 hrs	<b>B - 20k</b> S-5997 1. Tow eye bush worn close to max spec. GSC/AM	Tripodi
05/07/2024	803,801 kms	<b>Tow eye</b> R-7638 Fit new tow eye bush. GSC	Tripodi
16/05/2024	1,004,665 kms 783,548 hrs	<b>A - Monthly</b> S-5920 1. A2 air springs cracking/fatigued. Will schedule for next service. 2. A3 o/s air spring cracks/fatigued. Will schedule for next service. 3. A3 o/s shock misting. Will schedule for next service. Ben/AM	Tripodi
09/04/2024	995,748 kms	<b>wheel nut indicator, Wheel stud</b> R-7371 1. Replaced broken wheel stud and fit new wheel nut as required. Ben 2. Fit new wheel nut indicators as required. Ben	Tripodi
09/04/2024	995,748 kms	<b>C - Annual</b> S-5856 1. A3 o/s has a broken wheel stud. 2. Has x12 wheel nut indicators missing? GSC/AM/Ben	Tripodi
27/02/2024	982,065 kms	<b>Reflector</b> R-7191 Fit reflective tape as required. AM/AR	Tripodi
27/02/2024	982,065 kms	<b>A - Monthly</b> S-5778 1. Needs yellow reflective tape on sides. GSC/AM	Tripodi
02/02/2024	783,548 kms	<b>Accident, air leaks, Breakdown</b> R-7128 Went to truck. Removed broken thread section from air tank and fit new drain valve as required. Ben	Tripodi
31/01/2024	970,964 kms	<b>B - 20k</b> S-5725 1. A1 n/s air spring cracks/worn. 2. A4 both side air springs cracks/worn GSC/Ben	Tripodi
31/01/2024	970,964 kms	<b>Suspension</b> R-7105 1. Fit new air spring to A1 n/s. 2. Fit new air springs to A4 both sides. AM	Tripodi
16/01/2024		<b>DEFECT MINOR</b> R-6994	Sloanebuilt trailers
25/10/2023	941,907 kms	<b>B - 20k</b> S-5588 GSC/AM/Adam	Tripodi
23/09/2023		<b>Electrical, Reverse camera/screen</b> R-6785 Repaired wiring harness inside harness plug. Ben	Tripodi
12/09/2023	140,420 kms	<b>Accident, Hydraulic oil leak, Hydraulics, Lights</b> R-6924	Sloanebuilt trailers
11/09/2023	923,979 kms	<b>B - 20k</b> S-5473 1. Tarp cable needs adjusting. 2. Tarp chain needs adjusting. 3. A2 and A4 brakes low. 4. A4 o/s and A3 n/s shocks leaking oil. GSC/AM	Tripodi

Date	Reading / Units	Type / Repairer Notes	Repairer
11/09/2023	923,979 kms	<b>Brakes, Suspension, Tarp cable</b> R-6766 1 .Adjusted cable. GSC. 2. Adjusted tarp motor drive chain. GSC. 3. Removed brakes. Cleaned and inspect. Fit new brake shoe kits. GSC/AM 4. Fit new shocks to those positions. GSC	Tripodi
03/08/2023		<b>Air, Tailgate</b> R-6907	Sloanebuilt trailers
30/05/2023	873,915 kms	<b>B - 20k</b> S-5265 GSC/AM	Tripodi
20/04/2023	810,630 kms	<b>B - 20k</b> S-5189 1. Grain locks bent. 2. A2 brakes next service. GSC/AM	Tripodi
20/04/2023	810,630 kms	<b>Grain lock</b> R-6483 Fit new grain locks. GSC	Tripodi
31/03/2023	849,181 kms	<b>Brakes, Fault Codes, Mudflap, Trailer Body, Trailer Drawbar</b> R-6454 1. Schedule for next service. Still serviceable. Ben 2. Fit good used mudflap. AM 3. Fit new safety cables. Ben. 4. Scheduled for next service. Ben 5. Schedule for next service. Still serviceable. Ben.	Tripodi
31/03/2023	849,181 kms	<b>A - Monthly</b> S-5162 1. Cracks in body cross member. 2. O/S mudflap missing. 3. Drawbar spring safety cable half rubbed through at o/s.. 4. A2 brakes low. 5 .Driver fault report. 6. Tailgate and grain locks bent.	Tripodi
27/03/2023		<b>Brakes, Suspension, Wheel Bearing</b> R-6588 1. Fit new wheel bearing kits as required. Tripodi supplied wheel bearing kits and grease. 2. Fit new brakes as per attached document. 3. Fit new height control valve as per attached document.	Prancer truck repairs
27/03/2023		<b>D</b> S-5263 Service carried out at Prancer as per attached document. 1. Wheel bearings due. 2. A4 brakes low.	Prancer truck repairs
03/11/2022	799,196 kms	<b>A - Monthly</b> S-4778 1. Carried out B-service also. 2. Fault report FR01469 and FR01470	Tripodi
03/11/2022	799,196 kms	<b>Lights</b> R-6163 1.BP repaired wire to fix clearance light indicator 2.GSC replaced indicator 3. Removed brakes. Cleaned and inspect. Fit new brake shoe kits and brake drums. GSC/AM/Bailey 4. Fit new air spring to A4 n/s. GSC/AM 5 .Fit new air spring to A1 o/s. GSC/AM	Tripodi
03/11/2022	799,196 kms	<b>Fault report, Lights</b> R-6161 Both lights are the same light and it was the N/S middle indicator lamp with a broken wire. Repaired broken wire. Ben.	Tripodi
03/11/2022	799,196 kms	<b>B - 20k</b> S-4779 1.n/s indicator clearance light out 2.n/s outer rear indicator half working 3. a1 dolly brakes getting low 4.a4 L/H air bag has slight gash 5. A1 o/s air spring many cracks/leaking air.	Tripodi
07/09/2022	783,548 kms	<b>Fault report, Lights</b> R-6040 Repaired broken wire. Ben.	Tripodi
07/09/2022	783,548 kms	<b>B - 20k</b> S-4648 1. Fault report FR01468. 2. A1 brakes low. 3. A4 O/S and A3 n/s shock absorber leaking oil. 4. Hub-o-meter not working. 5 .Body pivot bushes close to max wear.	Tripodi
07/09/2022	783,548 kms	<b>Brakes, Suspension, Tarp cable , Tech repair, Trailer Body</b> R-6039 Georges Canvas, Sloanebuilt trailers, Tripodi 1. Removed brakes and clean/inspect. Ben/GSC 2. Replaced leaking shock absorbers. Ben/GSC 3. Fit new hub-o-meter. (Need to add 783548km to reading). Ben 4. Took to Sloanebuilt trailers and they replaced body pivot pin/bushes. Sloanebuilt 5. Truck and trailer taken to Georges Canvas as cable broke before we could inspect. They replaced cable and drive pulley. Georges Canvas. Invoice cost shared with truck TRI020	Georges Canvas, Sloanebuilt trailers, Tripodi
18/07/2022		<b>air leaks, Reverse camera/screen, Suspension</b> R-5906 1. Ordered part. 2. Pat organising replacement system. 3. Fit new air spring as required. BM	Tripodi
15/07/2022		<b>A - Monthly</b> S-4534	Tripodi

Date	Reading / Units	Type / Repairer Notes	Repairer
		1.hubometer does not work 2.camera does not work 3. Excess air leak at A3 n/s air spring	
15/06/2022		<b>air leaks, Brakes, Mudflap, Suspension, Trailer Drawbar</b> R-5826	Tripodi
		1. bm replaced spray suppressor	
15/06/2022	752,843 kms	<b>C - Annual</b> S-4458	Tripodi
		1. Drawbar bushes fatigued. 2. A3/A4 brakes low. 3. A1/A2 25% left. 4. Rear dolly mudflap bracket bent at o/s. 5. A3 o/s brake booster leaking air with park brake released. 6. Dolly n/s spray suppressor damaged/missing section. 7. Dolly air spring HCV leaking air. 8. O/S grain lock bent in/accident damage 9. Drawbar: Tow eye width: 42.88mm, Tow eye bush ID: 51.20mm	
07/04/2022	719,744 kms	<b>Fault report, Mudflap</b> R-5957	Tripodi
		Fit new length of spray suppressor. GSC	
07/04/2022	719,744 kms	<b>B - 20k</b> S-4288	
05/02/2022		<b>B - 20k</b> S-4154	Jackson plant and transport repairs
24/12/2021		<b>A - Monthly</b> S-4086	Jackson plant and transport repairs
		Repairer notes- Carried out A service to trailer. Valvoline Valpex EP Grease (450G Cartridge) Workshop Consumables	
02/11/2021		<b>B - 20k</b> S-3946	
		Service as per attached documents. (JPTR JACKSON)	
11/08/2021	604,246 kms	<b>air leaks</b> R-5138	Tripodi
		Fit new length of air hose as required.	
11/08/2021	604,246 kms	<b>B - 20k</b> S-3742	Tripodi
		1. Drawbar: Tow eye width: 43.77mm, Tow eye bush ID: 50.52mm. 2. A2 brakes low. 3. Drawbar spring safety cable damaged. 4. Wiring rubbed through at drawbar. John/Gavin	
11/08/2021	604,246 kms	<b>Brakes, Electrical, Trailer Drawbar</b> R-5140	Tripodi
		1. Removed brakes. Cleaned and inspected. Fit new brake shoe kits only. (John) 2. Fit new safety cable as required. (Gavin) 3. Repaired rubbed through wiring. (Gavin)	
01/07/2021		<b>air leaks</b> R-5049	NSW Truck repairs
		NSW truck repairs fixed as per attached document.	
24/06/2021	581,692 kms	<b>Trailer Tarp</b> R-4973	Tripodi
		Replaced tarp cable. Adjusted and lubricated motor drive chain. Gavin/Graham	
22/06/2021	581,692 kms	<b>C - Annual</b> S-3620	Tripodi
		1. Number plate faded. Reported to Louise. 2. A3 brakes next service. 3. Adjusted tarp cable. 4. Drawbar: Tow eye width: 44.11mm, Tow eye bush ID: 50.48. 5. Trailer tarp cable fraying and tarp motor drive chain very slack as per R-4973.	
26/05/2021		<b>B - 20k</b> S-3566	NSW Truck repairs
27/04/2021	511,700 kms	<b>B - 20k</b> S-3465	NSW Truck repairs
09/03/2021	511,700 kms	<b>B - 20k</b> S-3336	
		Service carried out NSW truck repairs as per attached service sheet.	
24/02/2021		<b>A - 10k</b> S-3302	
03/02/2021	511,700 kms	<b>B - 20k</b> S-3233	
		1. Drawbar: Tow eye width 43.53mm, Tow eye ID: 50.21mm.	
25/11/2020	485,490 kms	<b>B - 20k</b> S-3064	Tripodi
15/09/2020		<b>A - 10k</b> S-2880	
30/07/2020	424,169 kms	<b>Trailer Drawbar</b> R-3710	Tripodi

Date	Reading / Units	Type / Repairer Notes	Repairer
		Fit new tow eye bush as required. Tow eye getting close to minimum width. Reported to Pat Tripodi.	
27/07/2020	424,169 kms	<b>Brakes R-3709</b>	Tripodi
		Removed brake components. Clean and inspect. Fit new brake shoe kits and brake drums as follows. A1: Brake shoe kit only. Drums serviceable. A3: Brake shoe kits only. Drums serviceable. A4: Brake shoe kits and brake drums. Had a broken brake return spring at O/S.	
27/07/2020	424,169 kms	<b>C - Annual S-2764</b>	Tripodi
		1. A1, A3 and A4 brakes low as per R-3709. 2. Toweye bush close to max spec as per R-3710.	
12/06/2020		<b>A - 10k S-2643</b>	
03/02/2020	344,304 kms	<b>B - 20k S-2297</b>	Tripodi
		1. Tightened loose d-shackle bolts for drawbar spring. 2. Adjusted tarp cable.	
05/12/2019	324,115 kms	<b>B - 20k S-2144</b>	
		1. A2 o/s brake spring broken and brake shoes low as per R-2660. 2. Had bold tyre on A2 n/s inner. Fit good spare as required.	
05/12/2019	324,115 kms	<b>Brakes R-2660</b>	Tripodi
		Removed brake components. Clean and inspect as required. Fit new brake shoe kits and brake drums as required.	
20/08/2019	279,954 kms	<b>A - 10k S-1803</b>	Tripodi
31/07/2019	271,527 kms	<b>C - Annual S-1766</b>	Tripodi
30/07/2019	271,526 kms	<b>C - Annual S-1760</b>	Tripodi
22/07/2019	267,741 kms	<b>air leaks R-2166</b>	Tripodi
		Removed hose from booster connection. Cut of damaged portion and refitted (There was plenty of length in hose to cut out damaged portion). Check for leaks. Checks okay.	
08/07/2019	261,712 kms	<b>A - 10k S-1705</b>	Tripodi
		1. Fit new type HOLCIM mudflap to rear N/S.	
20/06/2019	255,268 kms	<b>A - 10k S-1647</b>	Tripodi
11/06/2019	251,121 kms	<b>Lights R-2028</b>	Tripodi
		Had to fit new marker lamp and re-weld mount bracket to body.	
23/05/2019	244,006 kms	<b>A - 10k S-1557</b>	Tripodi
26/02/2019	206,887 kms	<b>B - 20k S-1343</b>	Tripodi
09/02/2019	182,803 kms	<b>A - 10k S-1230</b>	Tripodi
13/12/2018	177,671 kms	<b>A - 10k S-1174</b>	Tripodi
12/09/2018		<b>Registration O-59</b>	RMS - Rego

Signed: \_\_\_\_\_  
Name: \_\_\_\_\_  
Date: \_\_\_\_\_