



# Vehicle History Summary



Fleet #	TR56KG
Registration	TR56KG
Make	SLOANE BUILT
Model	4ADT02A
VIN / Chassis #	6B9X4DAH2AE6834
Build Date	2017

Date	Reading / Units	Type / Repairer Notes	Repairer
12/05/2026	1,096,254 kms	<b>B - 20k</b> S-6906	Ivan Plevnarovski
29/04/2026	1,075,000 kms	<b>Tyres</b> T-313	South West Sydney Tyres
25/03/2026	1,075,000 kms	<b>Tyres</b> T-271	South West Sydney Tyres
05/03/2026	1,075,000 kms	<b>C - Annual</b> S-6853 adjusted all dolly wheel bearings as too much movement.	Ivan Plevnarovski
13/02/2026	851,334 kms	<b>Tarp cable</b> R-9063 adjusted tarp cable as required	Ivan Plevnarovski
09/02/2026	1,075,000 kms	<b>Brakes, Fault report, Hub-o-meter</b> R-9092 1. replaced as required 2. replaced as required	Ivan Plevnarovski
27/10/2025	1,060,334 kms	<b>A - 15k</b> S-6772	Ivan Plevnarovski
24/10/2025	851,334 kms	<b>Tyres</b> T-99	South West Sydney Tyres
29/07/2025	1,042,854 kms	<b>Drawbar Measurements</b> I-246	
29/07/2025	1,042,854 kms	<b>B - 30k</b> S-6691	Ivan Plevnarovski
04/06/2025	869,166 kms	<b>Tarps</b> R-8735 tarp cable removed and replaced. correctly positioned and tensioned tarp setup. raised AMP on tarp system to handle load as it was set too low. Tested tarps and works as required.	Ivan Plevnarovski
22/05/2025	1,028,081 kms	<b>A - 15k</b> S-6601	Ivan Plevnarovski
20/03/2025	1,015,576 kms	<b>B - 30k</b> S-6489	Ivan Plevnarovski
04/03/2025	851,334 kms	<b>Fault report, Indicator light</b> R-8514 Found contaminated terminal connectors inside light distribution box. Cleaned as required. Checks ok.	Ben Potts, Ivan Plevnarovski
04/03/2025	851,334 kms	<b>Fault report, Indicator light</b> R-8515 As per Repair # 8541	Ben Potts, Ivan Plevnarovski
10/12/2024	998,153 kms	<b>B - 30k</b> S-6329 1. Did tyre report for tandem tyres. 2. A3 spring hangers had mount plates have a small crack in them not severe enough to worry about yet ( just need to monitor) 3. A2 N/S and A4 air bags old and worn out 4. Drawbar hoses at O/S have had joiner put in but are leaking as they are damaged again.	Alex Martin, Ben Potts
10/12/2024	998,183 kms	<b>AIR BAGS, drawbar harness, Suspension</b> R-8255 1. Removed damaged joiner's. Fit new joiners/clamps/length of hose. BEn 2. Gsc replaced air bags with new ones	Ben Potts
29/10/2024	987,960 kms	<b>air leaks, Fault report</b> R-8108	Ben Potts

Date	Reading / Units	Type / Repairer Notes	Repairer
		Repaired as per Repair # 8106.	
29/10/2024	987,960 kms	<b>air leaks, Fault report</b> R-8109	Ben Potts
		Repaired as per Repair # 8106.	
29/10/2024	987,960 kms	<b>air leaks, Fault report</b> R-8106	Ben Potts
		Removed joiners and fit correct size ones with new hose clamps. Check for air leaks. Checks ok. Secured air hose harness. Adjusted jackknife buzzer switch actuator plates to prevent over jackknife of trailer (the buzzer will come on earlier).	
29/10/2024	987,960 kms	<b>air leaks, Fault report</b> R-8107	Ben Potts
		Repaired as per Repair # 8106.	
14/10/2024	851,334 kms	<b>New T-54</b>	Tyre Masters
		As attached document	
19/09/2024	977,683 kms	<b>Fault report, Tarp cable</b> R-7957	Ben Potts
		Adjusted cable as required.	
18/09/2024	851,334 kms	<b>NHVR Trailer Annual</b> I-46	
16/09/2024	1,827,944 kms	<b>Ballrace assembly</b> R-7947	Gavin Smith-Croucher
		GSC tightened bolt	
16/09/2024	976,610 kms	<b>C - Annual</b> S-6153	Alex Martin, Ben Potts, Gavin Smith-Croucher
		1. Trailer abs light on 2. Loose ball race bolt n/s front	
20/08/2024	862,462 kms 18,060 hrs	<b>Lights</b> R-7812	Gavin Smith-Croucher
		Gsc removed old light and refitted new light	
05/08/2024	971,967 kms	<b>A - 15k</b> S-6067	
15/07/2024	965,094 kms	<b>Fault report, tyres</b> R-7622	South West Sydney Tyres
		Checked as still just legal. Filled out tyre report sheet for tyre guys.	
11/07/2024	851,334 kms	<b>Drawbar Measurements</b> I-83	
		Drawbar: Tow eye width: 42.88mm, Tow eye bush ID: Fit new tow eye bush Sloanebuilt fit new drawbar bushes 11/07/2024	
11/07/2024	963,289 kms	<b>Trailer Drawbar</b> R-7844	Sloanebuilt trailers
16/06/2024	957,976 kms	<b>A - Monthly</b> S-5961	Tripodi
		GSC/AM	
27/05/2024	954,693 kms	<b>Brakes, Suspension</b> R-7524	Tripodi
		1. Removed brakes. Cleaned and inspect. Fit new brake shoe kits and brake drums to A1/A2. Fit new brake shoe kits to A3. GSC/AM 2. Fit new air springs to these positions. AM	
27/05/2024	954,693 kms	<b>B - 20k</b> S-5941	Tripodi
		1. A1/A2/A3 brakes low. 2. A1 o/s and A3 n/s air spring cracked/worn. GSC/AM	
22/05/2024	851,334 kms	<b>Fault report, Lights</b> R-7486	Tripodi
		Repaired corroded/broken wire behind lamp. AM	
12/03/2024	932,139 kms	<b>C - Annual</b> S-5810	Tripodi
24/02/2024	927,856 kms	<b>Tarp cable</b> R-7178	Tripodi
		removed damaged tarp cable and worn drive v-pulley. Fit new v-pulley and cable as required. GSC/Ben	
09/02/2024	911,470 kms	<b>B - 20k</b> S-5771	Tripodi
		GSC/AM	

Date	Reading / Units	Type / Repairer Notes	Repairer
19/12/2023	851,334 kms	<b>Brakes</b> R-7108	Sloanebuilt trailers
11/10/2023	897,141 kms	<b>A - Monthly</b> S-5532 1. N/S safety cable needs replacing. 2. A2 o/s air spring cracks/tear. GSC	Tripodi
11/10/2023	897,141 kms	<b>Suspension, Trailer Drawbar</b> R-6807 1. Fit new cable. 2. Fit new air spring. GSC	Tripodi
19/09/2023	890,697 kms	<b>Brakes</b> R-6775 Removed brakes. Cleaned and inspect. Fit new brake shoe kits. GSC/AM	Tripodi
19/09/2023	890,697 kms	<b>B - 20k</b> S-5492 1. A4 brakes low. GSC/AM	Tripodi
29/08/2023	883,202 kms	<b>A - Monthly</b> S-5440 AM/Ben	Tripodi
29/06/2023	862,015 kms	<b>A - Monthly</b> S-5322	Tripodi
30/05/2023	851,334 kms	<b>B - 20k</b> S-5267 1. N/S outer indicator not working. 2. Hub-o-meter not working 3. A1/A2 brakes soon. 4. Drawbar bushes soon.	Tripodi
30/05/2023	851,334 kms	<b>Lights, Tech repair</b> R-6591 1. Light faulty. Fit new lamp as required. AM. 2. Fit new hub-o-meter. Add 851334km to reading. GSC	Tripodi
03/04/2023		<b>D</b> S-5264 Service and repairs carried out as per attached document	Prancer truck repairs
03/04/2023		<b>Wheel Bearing</b> R-6589	Prancer truck repairs
29/03/2023	836,917 kms	<b>Trailer hub, Wheel, Wheel stud</b> R-6714 Travelled to breakdown location. Had to replace hub assembly as it had damage evident. Fit good used hub assembly. Fill hub with new grease etc. Fit two good spare tyres/rims as old rims also damaged. Ben	Tripodi
21/03/2023	834,931 kms	<b>B - 20k</b> S-5136 1. A3 and A4 brakes getting low. 2. Hub-o-meter not working 3. Number plate impaired.	Tripodi
21/03/2023	834,931 kms	<b>Brakes, Number plate, Tech repair</b> R-6443 1. Removed brakes. Cleaned and inspect. Fit new brake shoe kits. GSC/AM 2. Ordered new one. 3. removed cover. Clean cover and number plate. Refit as required. Ben.	Tripodi
11/01/2023	776,566 kms	<b>A - Monthly</b> S-4971 Datatrac inop unable to read milage	Tripodi
13/10/2022	776,566 kms	<b>B - 20k</b> S-4707	Tripodi
12/10/2022		<b>Fault report, Trailer Tarp</b> R-6106 Tarp is damaged. Reported to Pat and AJ. Repaired as good as could for now. Smoothed over top of gunnels.	Tripodi
11/08/2022	749,649 kms	<b>C - Annual</b> S-4591 1.n/s a1 missing backing plate 2.a2 brakes low	Tripodi
11/08/2022	749,649 kms	<b>C - Annual</b> S-4593	Tripodi
31/05/2022		<b>Lights</b> R-5831 JPTR diagnosed as needing two new lights. They supplied and fit.	JPTR JACKSON Beresfield
19/05/2022	722,352 kms	<b>Brakes, Suspension</b> R-5769 1 .Removed brakes. Cleaned and inspect. Fit new brake shoe ktis and brake drums. BM/AM. 2. Fit new backing plate assembly as required. 3. Tightened shock mount as required. AM.	Tripodi

Date	Reading / Units	Type / Repairer Notes	Repairer
19/05/2022	722,352 kms	<b>air leaks, Fault report, Suspension, Trailer Tarp</b> R-5770 1. Adjusted cable. check operation. Checks okay. GSC 2. Found air leak at dump signal hose near HCV. Fit joiner to hose. Found HCV leaking from exhaust port constantly too (minor leak). Fit new HCV as required. GSC.	Tripodi
19/05/2022	722,352 kms	<b>B - 20k</b> S-4400 1. A1 and A2 brakes low. 2. A1 n/s brake backing plate missing 3. A4 n/s upper shock mount loose. 4 .Fault report FR01080	Tripodi
01/04/2022		<b>Lights</b> R-5760	JPTR JACKSON Beresfield
02/02/2022	674,608 kms	<b>B - 20k</b> S-4147 1. Fault report as per R-5550	Tripodi
02/02/2022	674,608 kms	<b>Fault report, Tarp cable</b> R-5550 Adjusted as required.	Tripodi
21/01/2022		<b>brake drum</b> R-5560 2022/01/21 - Traveled down to the breakdown at MT white. Jacked up the truck. Placed onto stands. Removed the wheels. Removed the shattered brake drum removed the brake shoes knocked out the damaged anchor pin bushes I. Fitted the new ones. Fitted the brake shoes. Fitted the drum and wheels. Joined the airlines and inflated. Fitted the new airbag and lowered down. Tensioned the wheel nuts and fitted the wheel nut indicators. Fitted a bolt to the trucks exhaust clamp as it had come off. Packed away tools and equipment used. Left the breakdown.	
15/11/2021	643,383 kms	<b>B - 20k</b> S-3977 1. Tarp cable loose and noisy in operation. 2. Drawbar: Tow eye width: 42.73mm, Tow eye bush ID: Fit new bush.	Tripodi
15/11/2021	643,383 kms	<b>Tow eye, Trailer Tarp</b> R-5424 1. Found tensioner pulley bearing no good. Fit new pulleys as required. 2 .fit new tow eye bush Gavin	Tripodi
19/08/2021	602,319 kms	<b>C - Annual</b> S-3766 1. Trailer tarp motor running on. 2. A4 n/s shock weeping oil. 3. Dolly N/S guard spray suppressor is damaged. 4. Bin floor signs of wear. Will monitor. (Phil/Gavin)	Tripodi
19/08/2021	602,319 kms	<b>Fault report, Mudflap, Suspension</b> R-5136 1. Checked over tarp system. Removed double pulley drive system and fitted new single drive v-pulley. Check/adjust. Checks okay. (John) 2. Fit new shock absorber as required. (Gavin) 3. Fit new spray suppressor to N/S A1/A2. (Gavin)	Tripodi
23/06/2021	578,570 kms	<b>Trailer Tarp</b> R-4996 Fit new cable as required. gavin/Graham	Tripodi
19/06/2021		<b>Tow eye, Trailer Body, Trailer Drawbar</b> R-5063 Took to Sloanebuilt to be repaired. They fit new drawbar bushes and pins, tow eye bush.	Sloanebuilt trailers
10/06/2021	573,797 kms	<b>Fault report, Suspension, Trailer Body, Trailer Drawbar</b> R-4928 1. Hoist feet bushes replaced at Sloanebuilt. 2. Body pivot repairs carried out at Sloanebuilt. 3. Drawbar stand replaced at Sloanebuilt. 4. Sloanebuilt inspect/repaired drawbar as follows. Drawbar bushes and toweye bush replaced by Sloanebuilt. 5. Replaced A3 o/s air spring as required. Checker and adjust ride heights as required.	Tripodi
10/06/2021	573,797 kms	<b>B - 20k</b> S-3601 1. Hoist feet bushes worn as per R-4928 2. Body pivot bushes at max wear as per R-4928 3. A3 o/s air spring off centre/damaged as per R-4928 4. Drawbar stand badly damaged as per R-4928 Gavin/Ben	
14/05/2021		<b>A - 10k</b> S-3523	NSW Truck repairs
03/05/2021	553,413 kms	<b>Drive Hub</b> R-4777 Fit new wheel hub assembly as required Filled with new syn grease.	Tripodi
03/05/2021	553,413 kms	<b>A - 10k</b> S-3484 1. Replace A2 n/s wheel hub as per R-4777	Tripodi
06/04/2021	539,248 kms	<b>Brakes</b> R-4743 NSW truck repairs fitted new brake shoe kits and brakes drums to both A1 and A2.	NSW Truck repairs

Date	Reading / Units	Type / Repairer Notes	Repairer
01/04/2021		<b>B - 20k S-3389</b> 1. replaced brake shoes and drums on A1 and A2 as per R-4743	NSW Truck repairs
10/03/2021	487,625 kms	<b>B - 20k S-3338</b>	
01/02/2021		<b>B - 20k S-3218</b>	
02/12/2020	487,625 kms	<b>B - 20k S-3087</b> 1. N/S inner indicator lamp not working as per R-4240. 2. Drawbar bushes worn as per R-4241. 3. A1 and A2 brakes low as per R-4242. 4. Excess air leak at tandem HCV as per R-4243. 5. Toweye: Tow eye ID: 51.70mm, Width: 43.30mm. Tow eye worn as per R-4241.	Tripodi
02/12/2020	487,625 kms	<b>air leaks R-4243</b> Fit new HCV as required. Adjust ride height.	Tripodi
02/12/2020	487,625 kms	<b>Lights R-4240</b> Fit new indicator lamp as required.	Tripodi
02/12/2020	487,625 kms	<b>Trailer Drawbar R-4241</b> Fit new drawbar bush/pin kit. Fit new tow eye bush. Leigh/Graham	Tripodi
02/12/2020	487,625 kms	<b>Brakes R-4242</b> Removed brakes/cleaned/inspect. Fit new brake shoe kits and brake drums as required. Leigh/Graham	Tripodi
13/10/2020		<b>B - 20k S-2950</b>	TRUCK REPAIRS
18/09/2020		<b>A - 10k S-2887</b>	Tripodi
04/08/2020	426,572 kms	<b>C - Annual S-2780</b> 1. Tarp cable badly frayed as per R-3753. 2. A3 and A4 brakes low as per R-3754. 3. Drawbar spring safety cable broken as per R-3755. 4. Trailer indicator n/s not working as per R-3756.	Tripodi
04/08/2020	426,572 kms	<b>Trailer Tarp R-3753</b> Fit new cable as required.	Tripodi
04/08/2020	426,572 kms	<b>Brakes R-3754</b> Removed brakes. Clean and inspect. Fit new brake shoe kts and brake drums as required. leigh/Graham	Tripodi
04/08/2020	426,572 kms	<b>Trailer Drawbar R-3755</b> Fit new cable as required. Graham	Tripodi
04/08/2020	426,572 kms	<b>Lights R-3756</b> Fit two new inc=diacor lamps to N/S as required. Leigh	Tripodi
18/06/2020		<b>A - 10k S-2661</b>	
03/03/2020	351,359 kms	<b>Brakes R-3015</b> Removed brake components. Cleaned and inspected. Fit new brake shoe kits and brake drums.	Tripodi
03/03/2020	351,359 kms	<b>Tailgate R-3017</b> Fit new lower apron mudflap as required. Emily	Tripodi
03/03/2020	351,359 kms	<b>Tech repair, Truck tarp R-3016</b> Adjusted tarp cable as required. Adjusted load sense sensor in control box as required. Ben/emily	Tripodi
03/03/2020	351,359 kms	<b>B - 20k S-2377</b> 1. A2 brakes low as per R-3015. 2. Tarp cable loose as per R-3016. 3. Tailgate lower apron mudflap damaged as per R-3017. 4. Tensioned drawbar bush bolt. Bushes okay. 5. Toweye measures okay. 50.5mm and 43.2mm. 6. Bled air body hoist. 7. Adjusted body alarm.	Tripodi
10/09/2019	291,215 kms	<b>Tech repair R-2336</b>	Tripodi

Date	Reading / Units	Type / Repairer Notes	Repairer
		Fit new tow eye bush as required.	
10/09/2019		<b>Brakes</b> R-2335	Tripodi
		Removed A1 and A2 brake components. Clean and inspect. Fit new brake shoe kits as required.	
10/09/2019		<b>B - 20k</b> S-1879	Tripodi
		1. Toe-eye bush measures oversize as per repair R-2336. 2. A1 and A2 brakes low R-2335. 3. Re-tightened ball race bolts.	
15/08/2019	271,537 kms	<b>C - Annual</b> S-1792	Tripodi
26/07/2019	264,021 kms	<b>A - 10k</b> S-1747	Tripodi
26/06/2019	256,418 kms	<b>Hydraulics</b> R-2076	Tripodi
		Fit new female hydraulic coupling. Check oil level and hoist operation. Checks okay.	
26/06/2019	256,418 kms	<b>A - 10k</b> S-1669	Tripodi
		1. ABS wiring harness has been pinched at ringfeeder. Will need repairing soon. 2. Hydraulic coupling fitting very hard to remove as per repair R-2076. 3. Grain lock wear plate missing as per repair R-2076.	
26/06/2019	256,418 kms	<b>Tech repair</b> R-2077	Tripodi
		Fit new grain lock wear plate as required.	
03/06/2019	248,048 kms	<b>B - 20k</b> S-1583	Tripodi
27/05/2019	215,302 kms	<b>Fault report</b> R-1976	Tripodi
		Re-positioned mudflap as required.	
09/05/2019	23,821 kms	<b>Brakes</b> R-1890	Tripodi
		Fit new brake booster as required.	
09/05/2019	238,211 kms	<b>A - 10k</b> S-1481	Tripodi
		1. A2 N/S outer tyre tread damaged as per repair R-1891. 2. A4 N/S brake booster push rod bent as per repair R-1890.	
09/05/2019	238,211 kms	<b>TECH</b> R-1891	Tripodi
		Fit good spare tyre as required.	
12/03/2019	218,111 kms	<b>B - 20k</b> S-1407	Tripodi
08/02/2019	202,343 kms	<b>A - 10k</b> S-1309	Tripodi
08/01/2019	188,435 kms	<b>A - 10k</b> S-1219	Tripodi
14/12/2018	185,132 kms	<b>A - 10k</b> S-1179	Tripodi
10/08/2018		<b>Registration</b> O-60	RMS - Rego
29/05/2018		<b>A - 10k</b> S-995	
		Trailer A service replaced ball race bolts	

Signed: \_\_\_\_\_  
Name: \_\_\_\_\_  
Date: \_\_\_\_\_