

Asset	Registration	Work	Work Order	Service	RM	Task	Employee	Product	W/H	Supplier	Details
RP31A	345UGV	15151	06/14/2018 BEARPK	BEARING PACK							
RP31A	345UGV	15152	06/14/2018 BEARPK	BEARING PACK							
RP31A	345UGV	15151	06/14/2018 DEFECT		1	LABOUR	MECH	Labour			
RP31A	345UGV	15152	06/14/2018 DEFECT		1	LABOUR	MECH	Labour			
RP31A	345UGV	15151	06/14/2018 FRIVANA		1	LABCON		BRIVAL01	EX00010593		LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15151	06/14/2018 FRIVANA		1	LABCON		BRIVAL01	EX00010594		LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15151	06/14/2018 FRIVANA		1	LABCON		BRIVAL01	EX00010595		LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15151	06/14/2018 FRIVANA		1	LABCON		BRIVAL01	753		LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15151	06/14/2018 FRIVANA		1	LABCON		BRIVAL01	766		LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15151	06/14/2018 FRIVANA		1	LABCON		BRIVAL01	785		LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	10384	06/18/2018 TYRES		15	33000096		BRIAUS01	EX00005497		PUNCTURE REPAIR TBR,RP31A
RP31A	345UGV	10384	06/18/2018 TYRES		15	33000241		BRIAUS01	EX00005497		SCRAP TYRES TBR,RP31A
RP31A	345UGV	10384	06/18/2018 TYRES		15	33000084		YAT	FIT TBR TYRE		
RP31A	345UGV	10384	06/18/2018 TYRES		15	33000361		YAT	NWR N CASE - IRREGULAR WEAR		
RP31A	345UGV	10384	06/18/2018 TYRES		15	33000096		BRIAUS01	4.42E+09		PUNCTURE REPAIR TBR,RP31A
RP31A	345UGV	10384	06/18/2018 TYRES		15	33000241		BRIAUS01	4.42E+09		SCRAP TYRES TBR,RP31A
RP31A	345UGV	10471	06/21/2018 TRA		1	LABOUR	Labour				0
RP31A	345UGV	10471	06/21/2018 TRB		1	LABOUR	Labour				0
RP31A	345UGV	10471	06/21/2018 TRB		0	LABOUR	MECH1	Labour - Internal			
RP31A	345UGV	10471	06/21/2018 TRB		0	LABOUR	MECH1	Labour - Internal			
RP31A	345UGV	10471	06/21/2018 TRB		16	CON		YAT	Consumables		
						SERVICE COMPLET ED. NEEDS FRIDGE BEARING REPAIRS. NEEDS HOSES REPLACED . NEEDS 'C' & 'D' SERVICE.					
RP31A	345UGV	10471	06/21/2018 TRB								

RP31A	345UGV	10620	06/22/2018 FRIVANSE	1 15W40	JC&SL01	EX00005605	ENGINE OIL,RP31A
RP31A	345UGV	10620	06/22/2018 FRIVANSE	1 Nov-82	JC&SL01	EX00005605	OIL FILTER, FRIDGE MOTOR,RP31A
RP31A	345UGV	10620	06/22/2018 FRIVANSE	1 Nov-42	JC&SL01	EX00005605	FUEL FILTER, FRIDGE MOTOR,RP31A
RP31A	345UGV	10620	06/22/2018 FRIVANSE	1 119300	JC&SL01	EX00005605	QTK Fridge A/Filter EMI 3000,RP31A
RP31A	345UGV	10620	06/22/2018 FRIVANSE	1 COIL	JC&SL01	EX00005605	COIL CLEAN, EVAPORATOR/CONDENSOR,RP31A
RP31A	345UGV	10620	06/22/2018 FRIVANSE	1 SUND	JC&SL01	EX00005605	SUNDRIES,RP31A
RP31A	345UGV	10620	06/22/2018 FRIVANSE	1 LABEXT	JC&SL01	EX00005605	Labour External,RP31A
RP31A	345UGV	10620	06/22/2018 FRIVANSE	SERVICE COMPLETED BY JC & SL REFRIGERATION.			
RP31A	345UGV	10620	06/22/2018 FRIVANSE	1 LABEXT	JC&SL01	8679	Labour External,RP31A
RP31A	345UGV	10620	06/22/2018 FRIVANSE	1 SUND	JC&SL01	8679	SUNDRIES,RP31A
RP31A	345UGV	10620	06/22/2018 FRIVANSE	1 COIL	JC&SL01	8679	COIL CLEAN, EVAPORATOR/CONDENSOR,RP31A
RP31A	345UGV	10620	06/22/2018 FRIVANSE	1 119300	JC&SL01	8679	QTK Fridge A/Filter EMI 3000,RP31A
RP31A	345UGV	10620	06/22/2018 FRIVANSE	1 Nov-42	JC&SL01	8679	FUEL FILTER, FRIDGE MOTOR,RP31A
RP31A	345UGV	10620	06/22/2018 FRIVANSE	1 Nov-82	JC&SL01	8679	OIL FILTER, FRIDGE MOTOR,RP31A
RP31A	345UGV	10620	06/22/2018 FRIVANSE	1 15W40	JC&SL01	8679	ENGINE OIL,RP31A
RP31A	345UGV	10556	06/26/2018 TYRES				
RP31A	345UGV	10556	06/26/2018 TYRES	15 LABOUR	Labour		0
RP31A	345UGV	10556	06/26/2018 TYRES	15 33000188	YAT	B FLEET PRESSURE CHECK	
RP31A	345UGV	10921	07/19/2018 TRA	1 LABOUR	Labour		0
RP31A	345UGV	10921	07/19/2018 TRA	0 LABOUR	MECH	Labour - Internal	
RP31A	345UGV	10921	07/19/2018 TRA	0 LABOUR	MECH1	Labour - Internal	
RP31A	345UGV	10921	07/19/2018 TRA	16 CON	YAT	Consumables	

				COMPLET ED. FITTED REGO LABEL, MAINTEN ANCE LABEL, FLEET NUMBER LABEL. FITTED FRIDGE MOTOR FUEL DONGLE. FRONT CROSS BRACE NEEDS REPAIR URGENTL Y. SPARE WHEEL RACK AND SPARE					
RP31A	345UGV	10921	07/19/2018 TRA						
RP31A	345UGV	11010	07/20/2018 TYRES	15 33000241	BRIAUS01	EX00005830	SCRAP TYRES TBR,RP31A		
RP31A	345UGV	11010	07/20/2018 TYRES	15 77000180	BRIAUS01	EX00005830	CASE STOCK 11-22.5,RP31A		
RP31A	345UGV	11010	07/20/2018 TYRES	REMOVED REFIT TYRES					
RP31A	345UGV	11010	07/20/2018 TYRES	15 33000241	BRIAUS01	95926909	SCRAP TYRES TBR,RP31A		
RP31A	345UGV	11010	07/20/2018 TYRES	15 77000180	BRIAUS01	95926909	CASE STOCK 11-22.5,RP31A		
RP31A	345UGV	11115	07/25/2018 GEN	39 SUND	JC&SL01	EX00005910	SUNDRIES,RP31A		
RP31A	345UGV	11052	07/25/2018 GEN	39 LABOUR	Labour			0	
RP31A	345UGV	11115	07/25/2018 GEN	39 LABEXT	JC&SL01	EX00005910	Labour External,RP31A		
RP31A	345UGV	11052	07/25/2018 GEN	0 LABOUR	TRADEA	Labour - Internal			
RP31A	345UGV	11115	07/25/2018 GEN	CHECKED UNIT PRE RUN TRIP, ALARM 22 CAME UP, RECONFIGURED UNIT, ALARM 22 CAM UP AGAIN, RESET AND RE TEST OK, PRE TRIP PASSED OK					
RP31A	345UGV	11052	07/25/2018 GEN	0 LABOUR	MECH	Labour - Internal			
RP31A	345UGV	11115	07/25/2018 GEN	39 LABEXT	JC&SL01	8793	Labour External,RP31A		
RP31A	345UGV	11052	07/25/2018 GEN	14 S566TI	YAT	BATTERY, STOP/START AGM			
RP31A	345UGV	11115	07/25/2018 GEN	39 SUND	JC&SL01	8793	SUNDRIES,RP31A		
RP31A	345UGV	11052	07/25/2018 GEN	16 CON	YAT	Consumables			

RP31A	345UGV	11052	07/25/2018 GEN	REPLACED BATTERY MODIFIED BATTERY TRAY					
RP31A	345UGV	11101	07/26/2018 TYRES	15 CON	BRIAUS01	EX00005895	Consumables ,RP31A		
RP31A	345UGV	11101	07/26/2018 TYRES	15 CON	BRIAUS01	95943957	Consumables ,RP31A		
RP31A	345UGV	11231	08/06/2018 TYRES	39 77000180	BRIAUS01	EX00006002	CASE STOCK 11-22.5,RP31A		
RP31A	345UGV	11231	08/06/2018 TYRES	15 11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187			
RP31A	345UGV	11231	08/06/2018 TYRES	R&R TYRES BY BRIDGESTONE AT YATALA YARD					
RP31A	345UGV	11231	08/06/2018 TYRES	39 77000180	BRIAUS01	95975915	CASE STOCK 11-22.5,RP31A		
RP31A	345UGV	11424	08/17/2018 TRA	1 LABOUR	Labour				0
RP31A	345UGV	11424	08/17/2018 TRA	0 LABOUR	MECH1	Labour - Internal			
RP31A	345UGV	11424	08/17/2018 TRA	16 CON	YAT	Consumables			
				SERVICE COMPLET ED BRAKE HOSE NEAR BACK AXLE NEED REPLACIN G					
RP31A	345UGV	11424	08/17/2018 TRA						
RP31A	345UGV	11455	08/20/2018 TYRES	15 33000114	BRIAUS01	EX00006137	RE-TORQUE TRUCK WHEEL EA WHEEL,RP31A		
RP31A	345UGV	11455	08/20/2018 TYRES	RE-TORQUE TRUCK WHEEL - BRIDGESTONE					
RP31A	345UGV	11455	08/20/2018 TYRES	15 33000114	BRIAUS01	96029307	RE-TORQUE TRUCK WHEEL EA WHEEL,RP31A		
RP31A	345UGV	12045	09/27/2018 DEFECT	1 LABOUR	MECH	Labour			

RP31A	345UGV	12045	09/27/2018 DEFECT	Reported
				Defect :-
				Defect
				Code :
				00001442
				Defect
				Reference
				: W/O
				10471
				Date :
				21/06/20
				18
				Description of
				Defect :
				NEEDS
				FRIDGE
				BEARING
				REPAIRS.
				COULDN'T
				FAULT

RP31A	345UGV	12045	09/27/2018 DEFECT	Reported
				Defect :-
				Defect
				Code :
				00001441
				Defect
				Reference
				: W/O
				10471
				Date :
				21/06/20
				18
				Description of
				Defect :
				NEEDS
				HOSES
				REPLACED
				.
				.

RP31A	345UGV	12045	09/27/2018 TRA	1 LABOUR	Labour					0	
RP31A	345UGV	12045	09/27/2018 TRA	0 LABOUR	MECH1	Labour - Internal					
RP31A	345UGV	12045	09/27/2018 TRA	0 LABOUR	APPREN	Labour - Internal					
RP31A	345UGV	12045	09/27/2018 TRA	16 CON		YAT	Consumables				
RP31A	345UGV	12045	09/27/2018 TRA	SERVICE COMPLETED							
RP31A	345UGV	12520	10/24/2018 FRIVANA	1 COOLANT		RIXREF01	EX00006822	COOLANT,RP31A			
RP31A	345UGV	12520	10/24/2018 FRIVANA	1 LABEXT		RIXREF01	EX00006822	Labour External,RP31A			
RP31A	345UGV	12520	10/24/2018 FRIVANA	1 SUND		RIXREF01	EX00006822	SUNDRIES,RP31A			
				SERVICE COMPLET ED R&R WATER TEMP SENSOR TOPPED UP							
RP31A	345UGV	12520	10/24/2018 FRIVANA	COOLANT							
RP31A	345UGV	12520	10/24/2018 FRIVANA	1 SUND		RIXREF01	18335	SUNDRIES,RP31A			
RP31A	345UGV	12520	10/24/2018 FRIVANA	1 LABEXT		RIXREF01	18335	Labour External,RP31A			
RP31A	345UGV	12520	10/24/2018 FRIVANA	1 COOLANT		RIXREF01	18335	COOLANT,RP31A			
RP31A	345UGV	12653	10/24/2018 GEN	39 LABOUR	Labour					0	
RP31A	345UGV	12653	10/24/2018 GEN	3 41-6539		YAT	WATER TEMPERATURE SENSOR				
RP31A	345UGV	12653	10/24/2018 GEN	PARTS SUPPLIED BY EXODAS FOR SERVICING BY RIXON							
RP31A	345UGV	12660	11/06/2018 DEFECT	1 LABOUR	MECH	Labour					

RP31A	345UGV	12660	11/06/2018 DEFECT	Reported Defect :- Defect Code : 00001960 Defect Reference : 12815 Date : 24/10/20 18 Descriptio n of Defect : SUZI COIL ON BACK OF TRAILER NEEDS REPLACIN G REPLACED
-------	--------	-------	-------------------	--

				Reported Defect :- Defect Code : 00001979 Defect Reference : 12815 Date : 24/10/20 18 Description of Defect : SUZI COIL ON BACK OF TRAILER NEEDS REPLACING G REPLACED
RP31A	345UGV	12660	11/06/2018 DEFECT	

RP31A	345UGV	12838	11/06/2018 FRIVANA	1 LABEXT	RIXREF01	EX00006980	Labour External,RP31A
RP31A	345UGV	12838	11/06/2018 FRIVANA	1 SUND	RIXREF01	EX00006980	SUNDRIES,RP31A
RP31A	345UGV	12838	11/06/2018 FRIVANA	SERVICE COMPLETED			
RP31A	345UGV	12838	11/06/2018 FRIVANA	1 LABEXT	RIXREF01	18472	Labour External,RP31A
RP31A	345UGV	12838	11/06/2018 FRIVANA	1 SUND	RIXREF01	18472	SUNDRIES,RP31A
RP31A	345UGV	12660	11/06/2018 TRA	1 LABOUR Labour			
RP31A	345UGV	12660	11/06/2018 TRA	0 LABOUR MECH1	Labour - Internal		
RP31A	345UGV	12660	11/06/2018 TRA	0 LABOUR MECH1	Labour - Internal		
RP31A	345UGV	12660	11/06/2018 TRA	0 LABOUR APPREN	Labour - Internal		
RP31A	345UGV	12660	11/06/2018 TRA	13 61-SC3MTSTSET	YAT	Suzi Coil Short	
RP31A	345UGV	12660	11/06/2018 TRA	13 SK2006	YAT	Turntable Pads	
RP31A	345UGV	12660	11/06/2018 TRA	16 CON	YAT	Consumables	

0

				SERVICE COMPLET ED REPLACED SHORT TAIL SUZI COILS AS REQUIRED REPLACED TURNTAB LE WEAR PADS			
RP31A	345UGV	12660	11/06/2018 TRA				
RP31A	345UGV	12743	11/07/2018 TYRES	15 77000180	BRI AUS01	EX00006930	CASE STOCK 11-22.5,RP31A
RP31A	345UGV	12743	11/07/2018 TYRES	15 11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187	
RP31A	345UGV	12743	11/07/2018 TYRES	R&R TYRES			
RP31A	345UGV	12743	11/07/2018 TYRES	15 77000180	BRI AUS01	96275989	CASE STOCK 11-22.5,RP31A
RP31A	345UGV	13081	11/14/2018 FRIVANA	1 LABEXT	RIXREF01	EX00007114	Labour External,RP31
RP31A	345UGV	13081	11/14/2018 FRIVANA	1 SUND	RIXREF01	EX00007114	SUNDRIES,RP31A
RP31A	345UGV	13081	11/14/2018 FRIVANA	SERVICE COMPLETED			
RP31A	345UGV	13081	11/14/2018 FRIVANA	1 SUND	RIXREF01	18555	SUNDRIES,RP31A
RP31A	345UGV	13081	11/14/2018 FRIVANA	1 LABEXT	RIXREF01	18555	Labour External,RP31
RP31A	345UGV	13072	11/15/2018 FRIVANA	1 LABEXT	RIXREF01	EX00007113	Labour External,RP31A
RP31A	345UGV	13072	11/15/2018 FRIVANA	1 SUND	RIXREF01	EX00007113	SUNDRIES,RP31A
RP31A	345UGV	13072	11/15/2018 FRIVANA	SERVICE COMPLETED			
RP31A	345UGV	13072	11/15/2018 FRIVANA	1 SUND	RIXREF01	18556	SUNDRIES,RP31A
RP31A	345UGV	13072	11/15/2018 FRIVANA	1 LABEXT	RIXREF01	18556	Labour External,RP31A
RP31A	345UGV	13329	11/28/2018 FRIVANA	1 PART	RIXREF01	EX00007254	DISCHARGE AIR SENSOR,RP31A
RP31A	345UGV	13329	11/28/2018 FRIVANA	1 LABEXT	RIXREF01	EX00007254	Labour External,RP31A
RP31A	345UGV	13329	11/28/2018 FRIVANA	1 SUND	RIXREF01	EX00007254	SUNDRIES,RP31A
				SERVICE COMPLET ED R&R DISCHRG AIR SENSOR, CLEANED CONDENS OR COIL			
RP31A	345UGV	13329	11/28/2018 FRIVANA				
RP31A	345UGV	13329	11/28/2018 FRIVANA	1 SUND	RIXREF01	18631	SUNDRIES,RP31A
RP31A	345UGV	13329	11/28/2018 FRIVANA	1 LABEXT	RIXREF01	18631	Labour External,RP31A
RP31A	345UGV	13329	11/28/2018 FRIVANA	1 PART	RIXREF01	18631	DISCHARGE AIR SENSOR,RP31A

RP31A	345UGV	13648	12/14/2018 FRIVANA	1 LABEXT	RIXREF01	EX00007413	Labour External,RP31A
RP31A	345UGV	13648	12/14/2018 FRIVANA	1 SUND	RIXREF01	EX00007413	SUNDRIES,RP31A
RP31A	345UGV	13648	12/14/2018 FRIVANA	SERVICE COMPLETED			
RP31A	345UGV	13648	12/14/2018 FRIVANA	1 SUND	RIXREF01	18847	SUNDRIES,RP31A
RP31A	345UGV	13648	12/14/2018 FRIVANA	1 LABEXT	RIXREF01	18847	Labour External,RP31A
RP31A	345UGV	13513	12/18/2018 FRIVANSE	1 FILKIT	BRIVAL01	EX00007353	FILTER KIT FRIDGE,RP31A
RP31A	345UGV	13513	12/18/2018 FRIVANSE	1 CC	BRIVAL01	EX00007353	CALIBRATION CETIFICATE,RP31A
							Consumables
RP31A	345UGV	13513	12/18/2018 FRIVANSE	1 CON	BRIVAL01	EX00007353	,RP31A
RP31A	345UGV	13513	12/18/2018 FRIVANSE	1 LABEXT	BRIVAL01	EX00007353	Labour External,RP31A
				SERVICE			
				COMPLET			
				ED			
				CALIBRAT			
				ED UNIT			
				R&R			
				ENGINE			
				OIL,			
				FILTERS			
				TOPPED			
RP31A	345UGV	13513	12/18/2018 FRIVANSE	UP OIL			
RP31A	345UGV	13513	12/18/2018 FRIVANSE	40 3413005	YAT	OIL 15W-40, CK 4/E9	
RP31A	345UGV	13513	12/18/2018 FRIVANSE	1 LABEXT	BRIVAL01	20	Labour External,RP31A
							Consumables
RP31A	345UGV	13513	12/18/2018 FRIVANSE	1 CON	BRIVAL01	20	,RP31A
RP31A	345UGV	13513	12/18/2018 FRIVANSE	1 CC	BRIVAL01	20	CALIBRATION CETIFICATE,RP31A
RP31A	345UGV	13513	12/18/2018 FRIVANSE	1 FILKIT	BRIVAL01	20	FILTER KIT FRIDGE,RP31A
RP31A	345UGV	13686	12/19/2018 FRIVANA	1 LABEXT	RIXREF01	EX00007420	Labour External,RP31A
RP31A	345UGV	13686	12/19/2018 FRIVANA	1 SUND	RIXREF01	EX00007420	SUNDRIES,RP31A
RP31A	345UGV	13686	12/19/2018 FRIVANA	SERVICE COMPLETED			
RP31A	345UGV	13686	12/19/2018 FRIVANA	SERVICE COMPLETED			
RP31A	345UGV	13686	12/19/2018 FRIVANA	1 SUND	RIXREF01	18800	SUNDRIES,RP31A
RP31A	345UGV	13686	12/19/2018 FRIVANA	1 LABEXT	RIXREF01	18800	Labour External,RP31A
RP31A	345UGV	13530	12/19/2018 TRA	1 LABOUR	Labour		
RP31A	345UGV	13530	12/19/2018 TRA	0 LABOUR	MECH1	Labour - Internal	
RP31A	345UGV	13530	12/19/2018 TRA	0 LABOUR	APPREN	Labour - Internal	
RP31A	345UGV	13530	12/19/2018 TRA	16 CON	YAT	Consumables	

				SERVICE COMPLET ED REPLACED MALE LIGHT PLUG REPAIRED 1 X F TRACK CAP ADJUSTED TURN TAB LE REPAIRED LHS MARKER LIGHT			
RP31A	345UGV	13530	12/19/2018 TRA				
RP31A	345UGV	13944	12/24/2018 FRIVANA	1 LABEXT	RIXREF01	EX00007574	Labour External,RP31A
RP31A	345UGV	13944	12/24/2018 FRIVANA	1 SUND	RIXREF01	EX00007574	SUNDRIES,RP31A
RP31A	345UGV	13944	12/24/2018 FRIVANA	SERVICE COMPLETED			
RP31A	345UGV	13944	12/24/2018 FRIVANA	1 SUND	RIXREF01	18806	SUNDRIES,RP31A
RP31A	345UGV	13944	12/24/2018 FRIVANA	1 LABEXT	RIXREF01	18806	Labour External,RP31A
RP31A	345UGV	14025	12/28/2018 GEN	39 78-1340	BRIVAL01	EX00007629	Fan Belt W/PUMP-ALT QTK,RP31A
RP31A	345UGV	14025	12/28/2018 GEN	39 42-1309	BRIVAL01	EX00007629	TRANSDUCER PRESSURE SWITCH 500 PSI,RP31A
RP31A	345UGV	14025	12/28/2018 GEN	39 CON	BRIVAL01	EX00007629	Consumables ,RP31A
RP31A	345UGV	14025	12/28/2018 GEN	39 LABEXT	BRIVAL01	EX00007629	Labour External,RP31A
RP31A	345UGV	14025	12/28/2018 GEN	REPLACED U/S WATER PUMP BELT & U/S DISCHARGE PRESSURE SENSOR			
RP31A	345UGV	14025	12/28/2018 GEN	39 LABEXT	BRIVAL01	25	Labour External,RP31A
RP31A	345UGV	14025	12/28/2018 GEN	39 CON	BRIVAL01	25	Consumables ,RP31A
RP31A	345UGV	14025	12/28/2018 GEN	39 42-1309	BRIVAL01	25	TRANSDUCER PRESSURE SWITCH 500 PSI,RP31A
RP31A	345UGV	14025	12/28/2018 GEN	39 78-1340	BRIVAL01	25	Fan Belt W/PUMP-ALT QTK,RP31A
RP31A	345UGV	13753	01/08/2019 TRA	1 LABOUR	Labour		0
RP31A	345UGV	13753	01/08/2019 TRB	1 LABOUR	Labour		0
RP31A	345UGV	13753	01/08/2019 TRB	0 LABOUR	MECH1	Labour - Internal	
RP31A	345UGV	13753	01/08/2019 TRB	0 LABOUR	APPREN	Labour - Internal	
RP31A	345UGV	13753	01/08/2019 TRB	2 AIRBRAHOS	YAT	Air Brake Hose	

RP31A	345UGV	13753	01/08/2019 TRB	16 CON	YAT	Consumables
RP31A	345UGV	13753	01/08/2019 TRB	13 37FW1	YAT	HOOD HOOK LATCH, RUBBER,

				SERVICE COMPLET EDADJUST ED TURN TABLE FITETD DOOR LATCH TO FRIDGE ADJUSTED WHEEL BEAINGS RELACED BRAKE HOSE AS REQUIRED
RP31A	345UGV	13753	01/08/2019 TRB	

RP31A	345UGV	13994	01/11/2019 TYRES	15 33000096	BRIAUS01	EX00007593	PUNCTURE REPAIR TBR,RP31A
RP31A	345UGV	13994	01/11/2019 TYRES	PUNCTURE REPAIR			
RP31A	345UGV	13994	01/11/2019 TYRES	15 33000096	BRIAUS01	96479474	PUNCTURE REPAIR TBR,RP31A
RP31A	345UGV	14095	01/19/2019 GEN	39 LABOUR Labour			0
RP31A	345UGV	14095	01/19/2019 GEN	0 LABOUR APPREN	Labour - Internal		
RP31A	345UGV	14095	01/19/2019 GEN	14 61-SC3MTSTSET	YAT	Suzi Coil Short	
RP31A	345UGV	14095	01/19/2019 GEN	14 82506	YAT	Suzi Coil Long Tail	
RP31A	345UGV	14095	01/19/2019 GEN	16 CON	YAT	Consumables	
RP31A	345UGV	14095	01/19/2019 GEN	REPLACED SUZI COIL & ELECTRICAL LEAD			
RP31A	345UGV	14376	01/23/2019 FRIVANA	1 LABEXT	BRIVAL01	EX00007804	Labour External,RP31A
RP31A	345UGV	14535	01/23/2019 FRIVANA	1 LABEXT	BRIVAL01	EX00007904	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	14376	01/23/2019 FRIVANA	SERVICE COMPLETED			
RP31A	345UGV	14535	01/23/2019 FRIVANA	SERVICE COMPLETED			
RP31A	345UGV	14376	01/23/2019 FRIVANA	1 LABEXT	BRIVAL01	68	Labour External,RP31A
RP31A	345UGV	14535	01/23/2019 FRIVANA	1 LABEXT	BRIVAL01	62	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	14436	02/06/2019 DEFECT	1 LABOUR MECH	Labour		

RP31A	345UGV	14436	02/06/2019 DEFECT
-------	--------	-------	-------------------

RP31A	345UGV	14436	02/06/2019 DEFECT	Reported
				Defect :-
				Defect
				Code :
				00001527
				Defect
				Reference
				: W/O
				10921
				Date :
				19/07/20
				18
				Description of
				Defect :
				FRONT
				CROSS
				BRACE
				NEEDS
				REPAIR
				URGENTLY.
				REPAIRED
				AS
				REQUIRED

RP31A	345UGV	14436	02/06/2019 DEFECT
-------	--------	-------	-------------------

RP31A	345UGV	14728	02/08/2019 GEN
-------	--------	-------	----------------

PANELS

RP31A	345UGV	14728	02/08/2019 GEN	39 LABEXT	BRIVAL01	103	Labour External,RP31A
RP31A	345UGV	14728	02/08/2019 GEN	39 51-1746	BRIVAL01	103	SHOULDER BOLT,RP31A
RP31A	345UGV	14968	03/01/2019 TRA	1 LABOUR	Labour		0
RP31A	345UGV	14968	03/01/2019 TRA	0 LABOUR	MECH1	Labour - Internal	
RP31A	345UGV	14968	03/01/2019 TRA	0 LABOUR	MECH1	Labour - Internal	
RP31A	345UGV	14968	03/01/2019 TRA	16 CON	YAT	Consumables	
				SERVICE COMPLET ED AIRLINES OVER FRONT AXLE NEED REPLACIN G & REORGAN ISING NEEDS FRONT LHS SHOCK			
RP31A	345UGV	14968	03/01/2019 TRA				
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	EX00008384	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	169	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	EX00008689	LABOUR & CONSUMABLES,RP31A, HOURS 10359
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	257	LABOUR & CONSUMABLES,RP31A, HOURS 10359
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	EX00009084	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	EX00009097	LABOUR & CONSUMABLES,RP31A, 10764 Hours
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	370	LABOUR & CONSUMABLES,RP31A, 10764 Hours
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	367	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	EX00009477	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	464	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	EX00009559	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	EX00009583	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	331	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	478	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	EX00009719	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	EX00009722	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	EX00009723	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	EX00009720	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	EX00009749	LABOUR & CONSUMABLES,RP31A

RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	EX00009750	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	534	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	538	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	507	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	511	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	510	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15395	03/08/2019 FRIVANA	1 LABCON	BRIVAL01	508	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 FILKIT	BRIVAL01	EX00008457	FILTER KIT FRIDGE,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 773124	BRIVAL01	EX00008457	Bearing 6304DD,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 452589	BRIVAL01	EX00008457	Alternator, QTK Fridge,,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 781945	BRIVAL01	EX00008457	Belt, Engine, Fridge SLXE,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 78-1831	BRIVAL01	EX00008457	Belt,Fridge Motor,(10PK1980),RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 773119	BRIVAL01	EX00008457	BEARING 6207DDUC,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 773186	BRIVAL01	EX00008457	PULLEY SMOOTH WIH BOLT ASSY.,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 773187	BRIVAL01	EX00008457	PULLEY AND BOLT ASS, 10PK GROOVED,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 CON	BRIVAL01	EX00008457	Consumables ,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 LABEXT	BRIVAL01	EX00008457	Labour External,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	40 3413005	YAT	OIL 15W-40, CK 4/E9	
				SERVICE COMPLET ED R&R U/S ALL IDLER BEARINGS , ALTERNAT OR & DRIVE BELTS, CALIBRAT ED UNIT			
RP31A	345UGV	15502	03/12/2019 FRIVANSE				
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 LABEXT	BRIVAL01	180	Labour External,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 CON	BRIVAL01	180	Consumables ,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 773187	BRIVAL01	180	PULLEY AND BOLT ASS, 10PK GROOVED,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 773186	BRIVAL01	180	PULLEY SMOOTH WIH BOLT ASSY.,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 773119	BRIVAL01	180	BEARING 6207DDUC,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 78-1831	BRIVAL01	180	Belt,Fridge Motor,(10PK1980),RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1 781945	BRIVAL01	180	Belt, Engine, Fridge SLXE,RP31A

RP31A	345UGV	15502	03/12/2019 FRIVANSE	1	452589	BRIVAL01	180	Alternator, QTK Fridge,,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1	773124	BRIVAL01	180	Bearing 6304DD,RP31A
RP31A	345UGV	15502	03/12/2019 FRIVANSE	1	FILKIT	BRIVAL01	180	FILTER KIT FRIDGE,RP31A
RP31A	345UGV	16046	03/14/2019 FRIVANA	1	LABCON	BRIVAL01	EX00008692	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	16046	03/14/2019 FRIVANA	SERVICE COMPLETED - 10,320 HOURS				
RP31A	345UGV	16046	03/14/2019 FRIVANA	1	LABCON	BRIVAL01	251	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	15773	03/26/2019 FRIVANA	1	LABCON	BRIVAL01	EX00008581	LABOUR & CONSUMABLES,
RP31A	345UGV	15773	03/26/2019 FRIVANA	1	LABCON	BRIVAL01	221	LABOUR & CONSUMABLES,
RP31A	345UGV	16026	03/27/2019 FRIVANA	SERVICE COMPLETED				
RP31A	345UGV	16184	04/11/2019 DEFECT	1	LABOUR	MECH	Labour	

Reported
Defect :-
Defect
Code :
00002343
Defect
Reference
:
WO14968
Date :
01/03/20
19
Description of
Defect :
AIRLINES
OVER
FRONT
AXLE
NEED
REPLACING &
REORGANISING
COMPLETED

RP31A	345UGV	16184	04/11/2019 DEFECT
-------	--------	-------	-------------------

RP31A	345UGV	16184	04/11/2019 TRA
RP31A	345UGV	16184	04/11/2019 TRA
RP31A	345UGV	16184	04/11/2019 TRA
RP31A	345UGV	16184	04/11/2019 TRA

				SERVICE COMPLET ED REPLACED BOTH FRONT SHOCKS (BPW LONG SHOCKS) REPLACED & REORGAN ISED AIRLINES ABOVE FRONT AXLE			
RP31A	345UGV	16184	04/11/2019 TRA				
RP31A	345UGV	16268	04/15/2019 GEN	39 CALL OUT FEE	NIEMOB01	EX00008811	Call Out After Hours/Off Site,RP31A
RP31A	345UGV	16268	04/15/2019 GEN	39 LABEXT	NIEMOB01	EX00008811	Labour External,RP31A
RP31A	345UGV	16268	04/15/2019 GEN	39 LABEXT	NIEMOB01	EX00008811	Labour External,RP31A
				CALL OUT - NIESLER MBILE MECHANI CAL CHECK OUT SLIDING TROUBLE & RENEW SWITCH SEALED SWITCH			
RP31A	345UGV	16268	04/15/2019 GEN				
RP31A	345UGV	16268	04/15/2019 GEN	39 CALL OUT FEE	NIEMOB01	5720	Call Out After Hours/Off Site,RP31A
RP31A	345UGV	16268	04/15/2019 GEN	39 LABEXT	NIEMOB01	5720	Labour External,RP31A
RP31A	345UGV	16268	04/15/2019 GEN	39 LABEXT	NIEMOB01	5720	Labour External,RP31A
RP31A	345UGV	17641	04/23/2019 FRIVANA	SERVICE COMPLETED			
RP31A	345UGV	16426	04/30/2019 TYRES	15 77000180	BRIAUS01	EX00008919	CASE STOCK 11-22.5,RP31A
RP31A	345UGV	16426	04/30/2019 TYRES	15 11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187	
RP31A	345UGV	16426	04/30/2019 TYRES	R7R TYRES			
RP31A	345UGV	16426	04/30/2019 TYRES	15 77000180	BRIAUS01	96816713	CASE STOCK 11-22.5,RP31A

RP31A	345UGV	16775	05/13/2019 FRIVANA	Service Completed					
RP31A	345UGV	16742	05/15/2019 FRIVANA	Service Completed					
RP31A	345UGV	16799	05/17/2019 TRA	1 LABOUR	Labour				0
RP31A	345UGV	16799	05/17/2019 TRA	0 LABOUR	MECH1	Labour - Internal			
RP31A	345UGV	16799	05/17/2019 TRA	16 CON		YAT	Consumables		

				SERVICE COMPLET ED COULDN'T CHECK INSIDE AS IT WAS LOADED					
RP31A	345UGV	16799	05/17/2019 TRA						
RP31A	345UGV	16911	05/21/2019 TYRES	15 77000180	BRIAUS01	EX00009157	CASE STOCK 11-22.5,RP31A		
RP31A	345UGV	16911	05/21/2019 TYRES	15 11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187			
RP31A	345UGV	16911	05/21/2019 TYRES	R&R TYRES					
RP31A	345UGV	16911	05/21/2019 TYRES	15 77000180	BRIAUS01	96884147	CASE STOCK 11-22.5,RP31A		
RP31A	345UGV	17486	06/04/2019 FRIVANA	SERVICE COMPLETED					
RP31A	345UGV	17745	06/10/2019 FRIVANA	SERVICE COMPLETED					
RP31A	345UGV	17994	06/17/2019 FRIVANA	SERVICE COMPLETED					
RP31A	345UGV	18017	06/18/2019 FRIVANA	SERVICE COMPLETED					
RP31A	345UGV	18040	06/19/2019 FRIVANA	SERVICE COMPLETED					
RP31A	345UGV	18086	06/21/2019 FRIVANA	SERVICE COMPLETED					
RP31A	345UGV	18177	06/26/2019 FRIVANA	SERVICE COMPLETED					
RP31A	345UGV	18193	06/27/2019 FRIVANA	SERVICE COMPLETED					
RP31A	345UGV	18378	07/11/2019 DEFECT	1 LABOUR	MECH	Labour			

				Reported Defect :- Defect Code : 00001440 Defect Reference : W/O 10471 Date : 21/06/20 18 Description n of Defect : NEEDS 'C' & 'D' SERVICE.					
RP31A	345UGV	18378	07/11/2019 DEFECT						

RP31A	345UGV	18377	07/11/2019 EXOINS	1 LABOUR	Labour	0
			2ND			
			INSPECTIO			
			N - DIESEL			
			SERVICES			
			FAILED			
			1ST			
			INSPECTIO			
			N			
			* AIRBAG -			
			REPAIRED			
			X4			
			BRAKE			
			LINING			
			RIVETED -			
			REPLACED			
			X 6			
			BRAKE			
			DRUM -			
			REPLACED			
			X 6			
			*STOP			
			LIGHTS -			
			REPAIRED			
			SHOCK			
			ABSORBE			
			R -			
RP31A	345UGV	18377	07/11/2019 EXOINS	REPLACED		

RP31A	345UGV	18378	07/11/2019 FRIVANA	1 LABCON	BRIVAL01	EX00010048	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	18378	07/11/2019 FRIVANA	1 LABCON	BRIVAL01	615	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	18378	07/11/2019 TRA	1 LABOUR	Labour		0
RP31A	345UGV	18378	07/11/2019 TRB	1 LABOUR	Labour		0
RP31A	345UGV	18378	07/11/2019 TRC	1 LABOUR	Labour		0

				COMPLET ED BY DIESEL SERVICES REPLACED WHEEL BEARINGS & SEALS REPLACED BRAKE LININGS REPLACED BRAKE DRUMS REPLACED BOTH FRONT AXLE AIR BAGS REPLACED KING PIN & BOLTS REPLACED BOTH REAR AXLE AIR BAGS			
RP31A	345UGV	18378	07/11/2019 TRC				
RP31A	345UGV	18378	07/11/2019 TRC	1 LABEXT	DIESER01	EX00009895	Labour External (C&D),RP31A
RP31A	345UGV	18378	07/11/2019 TRC	1 LABEXT	DIESER01	EX00009895	Labour External (REPLACE BRAKE KIT),RP31A
RP31A	345UGV	18378	07/11/2019 TRC	1 LABEXT	DIESER01	EX00009895	Labour External (BRAKE DRUM),RP31A
RP31A	345UGV	18378	07/11/2019 TRC	1 LABEXT	DIESER01	EX00009895	Labour External (AIRBAG REPALCEMENT),RP31A
RP31A	345UGV	18378	07/11/2019 TRC	1 LABEXT	DIESER01	EX00009895	Labour External (SHOCK ASBSORBER),RP31A

RP31A	345UGV	18378	07/11/2019 TRC	1 LABEXT	DIESER01	EX00009895	Labour External (TURNABLE & BUSH REPLACEMENT),RP31A
RP31A	345UGV	18378	07/11/2019 TRC	1 LABEXT	DIESER01	EX00009895	Labour External (ROLLBACK BATTERY, ROLLBACK PIN, EBS, ELECTRICAL
RP31A	345UGV	18378	07/11/2019 TRC	1 CON	DIESER01	EX00009895	DEGREASER,RP31A
RP31A	345UGV	18378	07/11/2019 TRC	1 CON	DIESER01	EX00009895	Consumables ,RP31A
RP31A	345UGV	18378	07/11/2019 TRC	10 BP1802.METAL	YAT	AIRBAG D36 ASSY (INCL PISTON)	Consumables
RP31A	345UGV	18378	07/11/2019 TRC	1 CON	DIESER01	24397	,RP31A
RP31A	345UGV	18378	07/11/2019 TRC	1 CON	DIESER01	24397	DEGREASER,RP31A
RP31A	345UGV	18378	07/11/2019 TRC	1 LABEXT	DIESER01	24397	Labour External (ROLLBACK BATTERY, ROLLBACK PIN, EBS, ELECTRICAL
RP31A	345UGV	18378	07/11/2019 TRC	1 LABEXT	DIESER01	24397	Labour External (TURNABLE & BUSH REPLACEMENT),RP31A
RP31A	345UGV	18378	07/11/2019 TRC	1 LABEXT	DIESER01	24397	Labour External (SHOCK ASBSORBER),RP31A
RP31A	345UGV	18378	07/11/2019 TRC	1 LABEXT	DIESER01	24397	Labour External (AIRBAG REPALCEMENT),RP31A
RP31A	345UGV	18378	07/11/2019 TRC	1 LABEXT	DIESER01	24397	Labour External (BRAKE DRUM),RP31A
RP31A	345UGV	18378	07/11/2019 TRC	1 LABEXT	DIESER01	24397	Labour External (REPLACE BRAKE KIT),RP31A
RP31A	345UGV	18378	07/11/2019 TRC	1 LABEXT	DIESER01	24397	Labour External (C&D),RP31A
RP31A	345UGV	18378	07/11/2019 TRC	13 XA351A	YAT	GREASED TOP PLATE ASSEMBLY	
RP31A	345UGV	18378	07/11/2019 TRC	14 NX120-7	YAT	BATTERY	
RP31A	345UGV	18378	07/11/2019 TRC	8 FQ4020-S	YAT	Hub Cap Screw on (K-Hitch)	
RP31A	345UGV	18378	07/11/2019 TRC	8 E-1318AHD	YAT	CAM SHAFT BUSH ASSY	
RP31A	345UGV	18378	07/11/2019 TRC	8 453879	YAT	SEAL	
RP31A	345UGV	18378	07/11/2019 TRC	8 KZ1012.01	YAT	50MM BOLT IN KING PIN	
RP31A	345UGV	18378	07/11/2019 TRC	2 LH190.OE	YAT	BRAKE DRUM 285ISO	
RP31A	345UGV	18378	07/11/2019 TRC	2 MSKMG1A4515Q	YAT	BRAKE SHOES & HARDWARE KIT	
RP31A	345UGV	18378	07/11/2019 TRC	8 SET413	YAT	Bearing Set, Cup & Cone, HM212049/212011	
RP31A	345UGV	18378	07/11/2019 TRC	8 SET414TIMKEN	YAT	BEARING SET, CUP& CONE, HM218248/218210	
RP31A	345UGV	18378	07/11/2019 TRC	14 82062	YAT	7 Pin Female Trailer Plug	
RP31A	345UGV	18378	07/11/2019 TRC	13 SK2121/69Z	YAT	Turn Table Rubber Kit-Bush Repair (Suit 3)	
RP31A	345UGV	18378	07/11/2019 TRC	10 F5194	YAT	MONROE SHOCK ABSORBER TRAILER	
RP31A	345UGV	18473	07/18/2019 GEN	39 LABOUR	Labour		0
RP31A	345UGV	18473	07/18/2019 GEN	0 LABOUR	MECH1	Labour - Internal	
RP31A	345UGV	18473	07/18/2019 GEN	14 100-203	YAT	SUZI COIL ELCT DIN 7 CORE	
RP31A	345UGV	18473	07/18/2019 GEN	14 61-SC3MTSTSET	YAT	Suzi Coil Short	

RP31A	345UGV	18473	07/18/2019 GEN	16 CON	YAT	Consumables	
RP31A	345UGV	18473	07/18/2019 GEN	REPLACED SUZI COILS AS REQUIRED DUE TO BEING PINCHED IN DRIVEWAY			
RP31A	345UGV	18835	07/23/2019 FRIVANA	SERVICE COMPLETED			
RP31A	345UGV	20003	08/29/2019 FRIVANA	SERVICE COMPLETED			
RP31A	345UGV	19795	08/29/2019 TRA	1 LABOUR	Labour		0
RP31A	345UGV	19795	08/29/2019 TRA	0 LABOUR	MECH1	Labour - Internal	
RP31A	345UGV	19795	08/29/2019 TRA	16 CON	YAT	Consumables	
				SERVICE COMPLET ED NEEDS FIRE EXTINGUI SHER FITTED			
RP31A	345UGV	19795	08/29/2019 TRA				
RP31A	345UGV	20018	08/30/2019 FRIVANA	SERVICE COMPLETED			
RP31A	345UGV	19848	08/30/2019 TYRES	15 33000096	BRIAUS01	EX00010528	PUNCTURE REPAIR TBR,RP31A
RP31A	345UGV	19848	08/30/2019 TYRES	PUNCTURE REPAIR POS 25			
RP31A	345UGV	19848	08/30/2019 TYRES	15 33000096	BRIAUS01	97210158	PUNCTURE REPAIR TBR,RP31A
RP31A	345UGV	20038	09/02/2019 FRIVANA	SERVICE COMPLETED			
RP31A	345UGV	20220	09/09/2019 FRIVANA	1 LABCON	BRIVAL01	EX00010733	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	20220	09/09/2019 FRIVANA	Service Completed			
RP31A	345UGV	20220	09/09/2019 FRIVANA	1 LABCON	BRIVAL01	827	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	20238	09/10/2019 FRIVANA	1 LABCON	BRIVAL01	EX00010734	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	20238	09/10/2019 FRIVANA	Service Completed BVR			
RP31A	345UGV	20238	09/10/2019 FRIVANA	1 LABCON	BRIVAL01	834	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	20308	09/12/2019 FRIVANSE	1 LABEXT	BRIVAL01	EX00010746	Labour External,RP31A Consumables ,RRP31A
RP31A	345UGV	20308	09/12/2019 FRIVANSE	1 CON	BRIVAL01	EX00010746	
RP31A	345UGV	20308	09/12/2019 FRIVANSE	1 FILKIT	BRIVAL01	EX00010746	FILTER KIT FRIDGE,RP31A
RP31A	345UGV	20308	09/12/2019 FRIVANSE	1 41-7063	BRIVAL01	EX00010746	SWITCH PRESS OIL,RP31A
RP31A	345UGV	20308	09/12/2019 FRIVANSE	1 Nov-80	BRIVAL01	EX00010746	HAND PRIMER,RP31A
				BVR - SERVICE COMPLET ED CALIBRAT ED UNIT R&R U/S OIL PRESSURE SWITCH & HAND PRIMER			
RP31A	345UGV	20308	09/12/2019 FRIVANSE				

RP31A	345UGV	20308	09/12/2019 FRIVANSE	40 3413005	YAT	OIL 15W-40, CK 4/E9	
RP31A	345UGV	20308	09/12/2019 FRIVANSE	1 Nov-80	BRIVAL01	837	HAND PRIMER,RP31A
RP31A	345UGV	20308	09/12/2019 FRIVANSE	1 41-7063	BRIVAL01	837	SWITCH PRESS OIL,RP31A
RP31A	345UGV	20308	09/12/2019 FRIVANSE	1 FILKIT	BRIVAL01	837	FILTER KIT FRIDGE,RP31A
RP31A	345UGV	20308	09/12/2019 FRIVANSE	1 CON	BRIVAL01	837	Consumables ,RP31A
RP31A	345UGV	20308	09/12/2019 FRIVANSE	1 LABEXT	BRIVAL01	837	Labour External,RP31A
RP31A	345UGV	20309	09/12/2019 GEN	39 LABEXT	BRIVAL01	EX00010747	Labour External,RP31A
RP31A	345UGV	20309	09/12/2019 GEN	39 CON	BRIVAL01	EX00010747	Consumables ,RP31A
RP31A	345UGV	20309	09/12/2019 GEN	BVR - FITTED NEW DRIVERS SIDE TOP LEFT PANEL TO UNIT - QTK SUPPLIED			
RP31A	345UGV	20309	09/12/2019 GEN	39 CON	BRIVAL01	840	Consumables ,RP31A
RP31A	345UGV	20309	09/12/2019 GEN	39 LABEXT	BRIVAL01	840	Labour External,RP31A
RP31A	345UGV	20384	09/19/2019 FRIVANA	1 LABCON	BRIVAL01	EX00010774	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	20384	09/19/2019 FRIVANA	SERVICE COMPLETED BVR 16.09.2019			
RP31A	345UGV	20384	09/19/2019 FRIVANA	1 LABCON	BRIVAL01	867	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	20512	09/21/2019 TYRES	15 77000180	BRIAUS01	EX00010830	CASE STOCK 11-22.5,RP31A
RP31A	345UGV	20512	09/21/2019 TYRES	15 11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187	
RP31A	345UGV	20512	09/21/2019 TYRES	R&R TYRES PLUS ROTATION			
RP31A	345UGV	20512	09/21/2019 TYRES	15 77000180	BRIAUS01	97318434	CASE STOCK 11-22.5,RP31A
RP31A	345UGV	20458	09/24/2019 FRIVANA	1 LABCON	BRIVAL01	EX00010804	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	20490	09/24/2019 FRIVANA	1 LABCON	BRIVAL01	EX00010810	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	20458	09/24/2019 FRIVANA	SERVICE COMPLETED 20.09.2019			
RP31A	345UGV	20490	09/24/2019 FRIVANA	SERVICE COMPLETED 23.09.2019			
RP31A	345UGV	20458	09/24/2019 FRIVANA	1 LABCON	BRIVAL01	901	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	20490	09/24/2019 FRIVANA	1 LABCON	BRIVAL01	900	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	22276	09/27/2019 FRIVANA	1 LABCON	BRIVAL01	EX00011558	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	22276	09/27/2019 FRIVANA	SERVICE COMPLETED BVR 24.09.2019			
RP31A	345UGV	22276	09/27/2019 FRIVANA	1 LABCON	BRIVAL01	902	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	20823	10/03/2019 FRIVANA	1 LABCON	BRIVAL01	EX00011044	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	20823	10/03/2019 FRIVANA	SERVICE COMPLETED BVR 01.10.2019			
RP31A	345UGV	20823	10/03/2019 FRIVANA	1 LABCON	BRIVAL01	948	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	21287	10/21/2019 FRIVANA	1 LABCON	BRIVAL01	EX00011264	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	21287	10/21/2019 FRIVANA	SERVICE COMPLETED BVR 17.10.2019			
RP31A	345UGV	21287	10/21/2019 FRIVANA	1 LABCON	BRIVAL01	1042	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	21272	10/23/2019 GEN	39 LABOUR	Labour		0
RP31A	345UGV	21272	10/23/2019 GEN	0 LABOUR	MECH	Labour - Internal	
RP31A	345UGV	21272	10/23/2019 GEN	16 CON	YAT	Consumables	

				BROKEN ELECTRIC AL PLUG FROM TRCUK HITTING IT - REPLACED DEF - 05339 - COLLIN				
RP31A	345UGV	21272	10/23/2019 GEN					
RP31A	345UGV	22804	10/25/2019 FRIVANA	1 LABCON	BRIVAL01	EX00011828	LABOUR & CONSUMABLES,RP31A	
RP31A	345UGV	22804	10/25/2019 FRIVANA	SERVICE COMPLETED BVR 23.10.2019				
RP31A	345UGV	22804	10/25/2019 FRIVANA	1 LABCON	BRIVAL01	1057	LABOUR & CONSUMABLES,RP31A	
RP31A	345UGV	21630	10/25/2019 GEN	39 LABEXT	BRIVAL01	EX00011354	Labour External,RP31A	
RP31A	345UGV	21630	10/25/2019 GEN	39 CON	BRIVAL01	EX00011354	Consumables ,RP31A	
RP31A	345UGV	21630	10/25/2019 GEN	39 92-7797	BRIVAL01	EX00011354	SLX ENGINE MOUNT FRIDGE,RP31A	
RP31A	345UGV	21630	10/25/2019 GEN	39 773186	BRIVAL01	EX00011354	PULLEY SMOOTH WIH BOLT ASSY.,RP31A	
RP31A	345UGV	21630	10/25/2019 GEN	39 773187	BRIVAL01	EX00011354	PULLEY AND BOLT ASS, 10PK GROOVED,RP31A	
RP31A	345UGV	21630	10/25/2019 GEN	BVR - R&R COMPRESSOR IDLERS SMOOTH & GROOVED DUE TO BEING NOISY , R&R FRONT ENGINE MOUNT, PASSED PRE TRIP				
RP31A	345UGV	21630	10/25/2019 GEN	39 773187	BRIVAL01	1059	PULLEY AND BOLT ASS, 10PK GROOVED,RP31A	
RP31A	345UGV	21630	10/25/2019 GEN	39 773186	BRIVAL01	1059	PULLEY SMOOTH WIH BOLT ASSY.,RP31A	
RP31A	345UGV	21630	10/25/2019 GEN	39 92-7797	BRIVAL01	1059	SLX ENGINE MOUNT FRIDGE,RP31A	
RP31A	345UGV	21630	10/25/2019 GEN	39 CON	BRIVAL01	1059	Consumables ,RP31A	
RP31A	345UGV	21630	10/25/2019 GEN	39 LABEXT	BRIVAL01	1059	Labour External,RP31A	
RP31A	345UGV	21557	10/28/2019 DEFECT	1 LABOUR	MECH	Labour		

				Reported Defect :- Defect Code : 00001526 Defect Reference : W/O 10921 Date : 19/07/20 18 Description n of Defect : SPARE WHEEL RACK AND SPARE WHEEL NEEDED.
RP31A	345UGV	21557	10/28/2019 DEFECT	

RP31A	345UGV	21557	10/28/2019 TRA	1 LABOUR	Labour		0
RP31A	345UGV	21557	10/28/2019 TRB	1 LABOUR	Labour		0
RP31A	345UGV	21557	10/28/2019 TRB	0 LABOUR	MECH1	Labour - Internal	
RP31A	345UGV	21557	10/28/2019 TRB	0 LABOUR	APPREN	Labour - Internal	
RP31A	345UGV	21557	10/28/2019 TRB	14 61-SC3MTSTSET	YAT	Suzi Coil Short	
RP31A	345UGV	21557	10/28/2019 TRB	13 B310-30KG-PP	YAT	WEIGH GAUGE,TRI AXLE,W/LGE AIR BAG. PUSH/PULL SWITCH	
RP31A	345UGV	21557	10/28/2019 TRB	13 4051912R	YAT	RECESSED TIMER SWITCH	
RP31A	345UGV	21557	10/28/2019 TRB	16 CON	YAT	Consumables	

RP31A	345UGV	21557	10/28/2019 TRB	SERVICE COMPLET ED REPLACED SUZI COILD REPLACED SWITCH FOR INTERIOR LIGHTS FITTED WEIGHT GAUGE FITTED 2.5 KG FIRE EXTINGUI SHER & BRACKET				
RP31A	345UGV	22219	10/29/2019 FRIVANA	1 LABCON	BRIVAL01	EX00011551	LABOUR & CONSUMABLES,RP31A	
RP31A	345UGV	22219	10/29/2019 FRIVANA	SERVICE COMPLETED BVR 28.10.2019				
RP31A	345UGV	22219	10/29/2019 FRIVANA	1 LABCON	BRIVAL01	1083	LABOUR & CONSUMABLES,RP31A	
RP31A	345UGV	23083	11/07/2019 FVPRE	1 LABCON	BRIVAL01	EX00011987	LABOUR & CONSUMABLES,RP31A	
RP31A	345UGV	23083	11/07/2019 FVPRE	SERVICE COMPLETED BY BVR 05.11.2019				
RP31A	345UGV	23083	11/07/2019 FVPRE	1 LABCON	BRIVAL01	1144	LABOUR & CONSUMABLES,RP31A	
RP31A	345UGV	22617	11/25/2019 TRA	1 LABOUR	Labour		0	
RP31A	345UGV	22617	11/25/2019 TRA	0 LABOUR	MECH1	Labour - Internal		
RP31A	345UGV	22617	11/25/2019 TRA	16 CON	YAT	Consumables		
RP31A	345UGV	22617	11/25/2019 TRA	14 82161BL	YAT	7 PIN PLUG TRAILER		
				SERVICE COMPLET ED. CARRIED OUT "A" SERVICE. REPLACED 7-PIN LIGHT PLUG.				
RP31A	345UGV	22617	11/25/2019 TRA					

				FRIDGE VAN PRE- CHECK COMPLET ED				
				PRE- CHECK COMPLET ED BY BVR				
RP31A	345UGV	23326	11/26/2019 FVPRE	.				
RP31A	345UGV	23494	12/20/2019 WEICAL	0 LABOUR	Labour			0
				AIR GAUGE: 19.5 ADJUSTED : 20.5 WEIGHBRI DGE: 20.1				
				AIR GAUGE CALIBRATI ON COMPLET ED CORRECTL Y.				
RP31A	345UGV	23494	12/20/2019 WEICAL					
RP31A	345UGV	23733	01/09/2020 TRA	1 LABOUR	Labour			0

				SERVICE COMPLET ED BEN / BILLY 09.01.202 0							
				CARRIED OUT A SERVICE							
RP31A	345UGV	23733	01/09/2020 TRA								
RP31A	345UGV	23733	01/09/2020 TRA	0 LABOUR	MECH1	Labour - Internal					
RP31A	345UGV	23733	01/09/2020 TRA	0 LABOUR	MECH1	Labour - Internal					
RP31A	345UGV	23733	01/09/2020 TRA	16 CON		YAT Consumables					
RP31A	345UGV	24539	01/13/2020 FVPRE	1 LABCON		BRIVAL01	EX00012840		LABOUR & CONSUMABLES,RP31A		
RP31A	345UGV	24539	01/13/2020 FVPRE	SERVICE COMPLETED BY BVR 09.01.2020							
RP31A	345UGV	24539	01/13/2020 FVPRE	1 LABCON		BRIVAL01	1443		LABOUR & CONSUMABLES,RP31A		
RP31A	345UGV	23971	01/20/2020 GEN	39 LABOUR	Labour					0	
				REPAIR COMPLET ED BY SEAN 20.01.202 0							
				REMOVED OLD MUDGUA RD - STRAIGHT ENED BRACKETS AND FITTED NEW GUARD.							
RP31A	345UGV	23971	01/20/2020 GEN								
RP31A	345UGV	23971	01/20/2020 GEN	0 LABOUR	MECH1	Labour - Internal					
RP31A	345UGV	23971	01/20/2020 GEN	13 K127-1116-08A		YAT Mudguard Red					
RP31A	345UGV	23971	01/20/2020 GEN	16 CON		YAT Consumables					
RP31A	345UGV	25228	01/29/2020 FVPRE	1 LABCON		BRIVAL01	EX00013218		LABOUR & CONSUMABLES,RP31A		
RP31A	345UGV	25228	01/29/2020 FVPRE	SERVICE COMPLETED BY BVR 22.01.2020							
RP31A	345UGV	25228	01/29/2020 FVPRE	1 LABCON		BRIVAL01	1533		LABOUR & CONSUMABLES,RP31A		
RP31A	345UGV	25266	02/05/2020 FVPRE	1 LABCON		BRIVAL01	EX00013225		LABOUR & CONSUMABLES,RP31A		
RP31A	345UGV	25266	02/05/2020 FVPRE	SERVICE COMPLETED BY BVR 29.01.2020							
RP31A	345UGV	25266	02/05/2020 FVPRE	1 LABCON		BRIVAL01	1563		LABOUR & CONSUMABLES,RP31A		

RP31A	345UGV	24515	02/12/2020 FVGEN	16 CON	BRIVAL01	EX00012831	RP31A,
RP31A	345UGV	24515	02/12/2020 FVGEN	13 LABEXT	BRIVAL01	EX00012831	RP31A,
				COMPLET ED BY BVR 12.02.202 0 INVOICE # 00001605			
				UNIT RUN OUT OF FUEL REFUELLE D AND PRIMED UNIT CLEANED FUEL SCREEN UNIT RUN ON TEST PRETRIP PASSED			
RP31A	345UGV	24515	02/12/2020 FVGEN				
RP31A	345UGV	24515	02/12/2020 FVGEN	13 LABEXT	BRIVAL01	1605	RP31A,
RP31A	345UGV	24515	02/12/2020 FVGEN	16 CON	BRIVAL01	1605	RP31A,
RP31A	345UGV	25145	02/13/2020 FVPRE	1 LABCON	BRIVAL01	EX00013196	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	25536	02/13/2020 FVPRE	1 LABCON	BRIVAL01	EX00013331	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	25145	02/13/2020 FVPRE	SERVICE COMPLETED BY BVR 10.02.2020			
RP31A	345UGV	25536	02/13/2020 FVPRE	SERVICE COMPLETED BY BVR 10.02.2020			
RP31A	345UGV	25145	02/13/2020 FVPRE	1 LABCON	BRIVAL01	1624	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	24666	02/20/2020 TRA	1 LABOUR	Labour		0

				SERVICE COMPLET ED BY KEIRAN 20.02.202 0 (SIGNED OFF BY SEAN)				
				REPLACED FRIDGE DOOR LATCH REPLACED REAR TOP LEFT RED MARKER LIGHT				
RP31A	345UGV	24666	02/20/2020 TRA					
RP31A	345UGV	24666	02/20/2020 TRA	0 LABOUR	APPREN	Labour - Internal		
RP31A	345UGV	24666	02/20/2020 TRA	16 CON		YAT Consumables		
RP31A	345UGV	25874	03/31/2020 FRIVANB	1 10-417		BRIVAL01	EX00013475	Filter Service Kit, Fridge Motor, SLX-400,RP31A
RP31A	345UGV	25874	03/31/2020 FRIVANB	16 CON		BRIVAL01	EX00013475	Consumables ,RP31A
RP31A	345UGV	25874	03/31/2020 FRIVANB	1 LABEXT		BRIVAL01	EX00013475	Labour External,RP31A

				ED BY BVR			
				31.03.202			
				0			
				INVOICE #			
				00001913			
				B SERVICE			
				OIL 14L			
				(CUSTOM			
				ER			
				SUPPLIED)			
				CALIBRATI			
				ON			
				CERTIFICA			
				TE			
				R & R			
				ENGINE			
				OIL			
				R & R			
				FILTERS			
				CHECK			
				COOLANT			
				CHECK			
				AND			
				ADJUST			
				BELTS			
RP31A	345UGV	25874	03/31/2020 FRIVANB	CHECK			

RP31A	345UGV	25874	03/31/2020 FRIVANB	16 CON	BRIVAL01	1913	Consumables ,RP31A
RP31A	345UGV	25874	03/31/2020 FRIVANB	1 10-417	BRIVAL01	1913	Filter Service Kit, Fridge Motor, SLX-400,RP31A
RP31A	345UGV	25881	03/31/2020 FVPRE	1 LABCON	BRIVAL01	EX00013477	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	25881	03/31/2020 FVPRE	SERVICE COMPLETED BY BVR 27.03.2020			
RP31A	345UGV	25881	03/31/2020 FVPRE	1 LABCON	BRIVAL01	1928	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	25967	04/05/2020 GEN	15 33000517	BRI AUS01	EX00013525	REMOVAL: CUSTOMER PULL POINT,RP31A
RP31A	345UGV	25967	04/05/2020 GEN	15 77000180	BRI AUS01	EX00013525	CASE STOCK 11-22.5,RP31A
RP31A	345UGV	25967	04/05/2020 GEN	15 11001464	BRI AUS01	EX00013525	TYRE 11R22.5 148/145L 16 BS R187,RP31A
RP31A	345UGV	25967	04/05/2020 GEN	15 33000084	BRI AUS01	EX00013525	FIT TBR TYRE,RP31A
				COMPLET ED BY BRIDGEST ONE 05.04.202 0 INVOICE # 98332534			
RP31A	345UGV	25967	04/05/2020 GEN				
RP31A	345UGV	25967	04/05/2020 GEN	15 33000084	BRI AUS01	98332534	FIT TBR TYRE,RP31A
RP31A	345UGV	25967	04/05/2020 GEN	15 11001464	BRI AUS01	98332534	TYRE 11R22.5 148/145L 16 BS R187,RP31A
RP31A	345UGV	25967	04/05/2020 GEN	15 77000180	BRI AUS01	98332534	CASE STOCK 11-22.5,RP31A
RP31A	345UGV	25967	04/05/2020 GEN	15 33000517	BRI AUS01	98332534	REMOVAL: CUSTOMER PULL POINT,RP31A
RP31A	345UGV	26056	04/07/2020 FVPRE	1 LABCON	BRIVAL01	EX00013571	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	26056	04/07/2020 FVPRE	SERVICE COMPLETED BY BVR 03.04.2020			
RP31A	345UGV	26056	04/07/2020 FVPRE	1 LABCON	BRIVAL01	1975	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	26196	04/16/2020 TRA	1 LABOUR Labour			0
RP31A	345UGV	26196	04/16/2020 TRA	SERVICE COMPLETED BY MICK / SEAN 16.04.2020			
RP31A	345UGV	26196	04/16/2020 TRA	0 LABOUR MECH	Labour - Internal		
RP31A	345UGV	26196	04/16/2020 TRA	0 LABOUR MECH1	Labour - Internal		
RP31A	345UGV	26196	04/16/2020 TRA	16 CON	YAT Consumables		
RP31A	345UGV	26409	04/20/2020 FVGEN	13 77-3186	BRIVAL01	EX00013743	SMOOTH SLX TENSIONER IDLER,RP31A
RP31A	345UGV	26409	04/20/2020 FVGEN	13 77-3187	BRIVAL01	EX00013743	GROOVED SLX TENSIONER IDLER,RP31A
RP31A	345UGV	26409	04/20/2020 FVGEN	13 77-3124	BRIVAL01	EX00013743	IDLER BEARING,RP31A
RP31A	345UGV	26409	04/20/2020 FVGEN	16 CON	BRIVAL01	EX00013743	Consumables ,RP31A
RP31A	345UGV	26409	04/20/2020 FVGEN	13 LABEXT	BRIVAL01	EX00013743	Labour External,RP31A

				COMPLET ED BY BVR 20.04.202 0 INVOICE # 00002048			
				UNIT FOUND EXCESSIVE LY NOISY TRACED TO NOISY IDLERS REMOVED AND REPLACED ALL IDLER BEARINGS UNIT RUN ON TEST PRETRIP PASSED			
RP31A	345UGV	26409	04/20/2020 FVGEN				
RP31A	345UGV	26409	04/20/2020 FVGEN	13 LABEXT	BRIVAL01	2048	Labour External,RP31A
RP31A	345UGV	26409	04/20/2020 FVGEN	16 CON	BRIVAL01	2048	Consumables ,RP31A
RP31A	345UGV	26409	04/20/2020 FVGEN	13 77-3124	BRIVAL01	2048	IDLER BEARING,RP31A
RP31A	345UGV	26409	04/20/2020 FVGEN	13 77-3187	BRIVAL01	2048	GROOVED SLX TENSIONER IDLER,RP31A
RP31A	345UGV	26409	04/20/2020 FVGEN	13 77-3186	BRIVAL01	2048	SMOOTH SLX TENSIONER IDLER,RP31A
RP31A	345UGV	26446	04/20/2020 FVPRE	1 LABCON	BRIVAL01	EX00013780	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	26446	04/20/2020 FVPRE	SERVICE COMPLETED BY BVR 16.04.2020			
RP31A	345UGV	26446	04/20/2020 FVPRE	1 LABCON	BRIVAL01	2069	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	26718	04/24/2020 FVPRE	1 LABCON	BRIVAL01	EX00013902	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	26718	04/24/2020 FVPRE	SERVICE COMPLETED BY BVR 20.04.2020			

RP31A	345UGV	26718	04/24/2020 FVPRE	1 LABCON	BRIVAL01	2104	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	26632	04/30/2020 FVGEN	13 78-1340	BRIVAL01	EX00013845	Fan Belt W/PUMP-ALT QTK,RP31A
RP31A	345UGV	26632	04/30/2020 FVGEN	16 CON	BRIVAL01	EX00013845	Consumables
RP31A	345UGV	26632	04/30/2020 FVGEN	13 LABEXT	BRIVAL01	EX00013845	,RP31A
				ED BY BVR			
				30.04.202			
				0			
				INVOICE #			
				00002126			
				UNIT			
				FOUND			
				WITH A			
				CRACKED			
				WATER			
				PUMP			
				BELT			
				REMOVED			
				AND			
				REPLACED			
				UNSERVIC			
				EABLE			
				BELT			
				CARRY			
				OUT A			
				SERVICE			
				A SERVICE			
				CHECK			
				COOLANT			
RP31A	345UGV	26632	04/30/2020 FVGEN	CHECK			

RP31A	345UGV	26632	04/30/2020 FVGEN	13 LABEXT	BRIVAL01	2126	Labour External,RP31A
RP31A	345UGV	26632	04/30/2020 FVGEN	16 CON	BRIVAL01	2126	Consumables ,RP31A
RP31A	345UGV	26632	04/30/2020 FVGEN	13 78-1340	BRIVAL01	2126	Fan Belt W/PUMP-ALT QTK,RP31A
RP31A	345UGV	27094	05/13/2020 FVPRE	1 LABCON	BRIVAL01	EX00014059	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	27094	05/13/2020 FVPRE	SERVICE COMPLETED BY BVR 07.05.2020			
RP31A	345UGV	27094	05/13/2020 FVPRE	1 LABCON	BRIVAL01	2251	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	27930	06/15/2020 DEFECT	1 LABOUR MECH	Labour		
RP31A	345UGV	27930	06/15/2020 DEFECT	DEFECT CLEARED. sean 15-06-20 ----- sean 15- 06-20 Reported Defect :- Defect Code : 00004244 Defect Reference : 12710 Date : 29/04/20 20 Description n of Defect : AIR LINES ARE BUT LONGER THEN THEY SHOULD BE, STILL WORK. REPLACE IF YOU			
RP31A	345UGV	27930	06/15/2020 DEFECT				

RP31A	345UGV	27930	06/15/2020 TRA	1 LABOUR	Labour			0
RP31A	345UGV	27930	06/15/2020 TRA	SERVICE COMPLETED.				
				service				
				complete				
				d				
				15/06/20				
				by sean				
				replaced				
				female				
				supply				
				fitting at				
				rear				
				replaced 2				
				hoses +				
				fitted				
				45degree				
				adaptors				
				to 1st axel				
				boosters				
				as the				
				hoses				
				were				
				kinking				
				replaced				
				missing				
				bolt in rhs				
				rear guard				
RP31A	345UGV	27930	06/15/2020 TRA	mount				
RP31A	345UGV	27930	06/15/2020 TRA	0 LABOUR	mech1	Labour - Internal		
RP31A	345UGV	27930	06/15/2020 TRA	16 con		YAT Consumables		
RP31A	345UGV	27880	06/18/2020 FRIVANA	1 LABCON	BRIVAL01	EX00014427	LABOUR & CONSUMABLES,RP31A	
RP31A	345UGV	27900	06/18/2020 FRIVANA	1 LABCON	BRIVAL01	EX00014429	LABOUR & CONSUMABLES,RP31A	
RP31A	345UGV	27880	06/18/2020 FRIVANA	SERVICE COMPLETED BY BVR 21.05.2020				
RP31A	345UGV	27900	06/18/2020 FRIVANA	1 LABCON	BRIVAL01	2432	LABOUR & CONSUMABLES,RP31A	
RP31A	345UGV	27880	06/18/2020 FRIVANA	1 LABCON	BRIVAL01	2424	LABOUR & CONSUMABLES,RP31A	
RP31A	345UGV	28765	07/07/2020 FRIVANA	1 LABCON	BRIVAL01	EX00014799	LABOUR & CONSUMABLES,RP31A	
RP31A	345UGV	28765	07/07/2020 FRIVANA	39 ROUNDING	BRIVAL01	EX00014799	ROUNDING,	
RP31A	345UGV	28765	07/07/2020 FRIVANA	39 ROUNDING	BRIVAL01	2677	ROUNDING,	
RP31A	345UGV	28765	07/07/2020 FRIVANA	1 LABCON	BRIVAL01	2677	LABOUR & CONSUMABLES,RP31A	
RP31A	345UGV	28765	07/07/2020 FRIVANA	SERVICE COMPLETED BVR				
RP31A	345UGV	28866	07/16/2020 FRIVANA	1 LABCON	BRIVAL01	EX00014813	LABOUR & CONSUMABLES,RP31A	
RP31A	345UGV	28866	07/16/2020 FRIVANA	1 LABCON	BRIVAL01	2759	LABOUR & CONSUMABLES,RP31A	
RP31A	345UGV	28866	07/16/2020 FRIVANA	SERVICE COMPLETED BVR				

RP31A	345UGV	29088	07/21/2020 FRIVANA	1 LABCON	BRIVAL01	EX00014896	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	29088	07/21/2020 FRIVANA	1 LABCON	BRIVAL01	2782	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	29088	07/21/2020 FRIVANA	SERVICE COMPLETED BVR			
RP31A	345UGV	29522	07/30/2020 GEN	1 LABCON	BRIVAL01	EX00015173	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	29522	07/30/2020 GEN	FLEET CHECK COMPLETED BY BVR 30.07.2020			
RP31A	345UGV	29522	07/30/2020 GEN	1 LABCON	BRIVAL01	2958	LABOUR & CONSUMABLES,RP31A
				SERVICE COMPLET ED. BY KEIRAN MICK 19/08/20 20			
				REPAIRED WIRING TO RH REAR LIGHT ASSEMBLY			
RP31A	345UGV	29682	08/19/2020 TRA				
RP31A	345UGV	29682	08/19/2020 TRA	0 LABOUR APPREN	1	85	85
RP31A	345UGV	29682	08/19/2020 TRA	0 LABOUR MECH	0.5	85	42.5
RP31A	345UGV	29682	08/19/2020 TRA	16 CON	YAT	Consumables	
RP31A	345UGV	29791	08/24/2020 FRIVANA	SERVICE COMPLETED BVR			
RP31A	345UGV	29792	08/24/2020 FRIVANA	1 LABCON	BRIVAL01	EX00015310	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	29971	08/24/2020 FRIVANA	1 LABCON	BRIVAL01	EX00015309	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	29792	08/24/2020 FRIVANA	SERVICE COMPLETED BVR			
RP31A	345UGV	29971	08/24/2020 FRIVANA	1 LABCON	BRIVAL01	3095	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	29792	08/24/2020 FRIVANA	1 LABCON	BRIVAL01	3092	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	29747	08/24/2020 GEN	1 LABCON	BRIVAL01	EX00015249	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	29755	08/24/2020 GEN	1 78-1831	BRIVAL01	EX00015265	Belt,Fridge Motor,(10PK1980),
RP31A	345UGV	29747	08/24/2020 GEN	SERVICE COMPLETED BVR 13/07/2020			
RP31A	345UGV	29755	08/24/2020 GEN	SERVICE COMPLETED BVR 20/08/2020			
RP31A	345UGV	29747	08/24/2020 GEN	1 LABCON	BRIVAL01	2716	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	29755	08/24/2020 GEN	1 78-1831	BRIVAL01	3051	Belt,Fridge Motor,(10PK1980),
RP31A	345UGV	30192	09/02/2020 FVPRE	39 LABCON	BRIVAL01	EX00015432	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	30192	09/02/2020 FVPRE	39 LABCON	BRIVAL01	3185	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	30673	09/24/2020 EXOINS	1 LABOUR MECH1	Labour		

				VEHICLE PASSED ANNUAL ROADWO RTHY INSPECTIO N. ATTEMPT #1				
				INSPECTIO N COMPLET ED BY JESSE YOUNG 24.09.202				
RP31A	345UGV	30673	09/24/2020 EXOINS	0				
RP31A	345UGV	30672	09/25/2020 TRA	1 LABOUR	Labour			0
RP31A	345UGV	30672	09/25/2020 TRA	SERVICE COMPLETED.				
RP31A	345UGV	30672	09/25/2020 TRB	1 LABOUR	Labour			0
RP31A	345UGV	30672	09/25/2020 TRB	SERVICE COMPLETED.				
RP31A	345UGV	30672	09/25/2020 TRC	1 LABOUR	MECH1	Labour		

				COMPLET ED BY JESSE, MICK AND BEN 25.09.202 0
				FITTED NEW 2.5KG FIRE EXTINGUI SHER FITTED NEW HUB CAP TO LHS MIDDLE AXLE FITTED NEW LHS FRONT BOTTOM MARKER LIGHT FITTED
RP31A	345UGV	30672	09/25/2020 TRC	

RP31A	345UGV	30672	09/25/2020 TRC	0 LABOUR	MECH	Labour - Internal	
RP31A	345UGV	30672	09/25/2020 TRC	0 LABOUR	APPREN	Labour - Internal	
RP31A	345UGV	30672	09/25/2020 TRC	16 CON		YAT	Consumables
RP31A	345UGV	30672	09/25/2020 TRC	14 91622		YAT	LED Marker light. Amber. Narva
RP31A	345UGV	30672	09/25/2020 TRC	14 91700BL		YAT	Clearance Light, LED Amber, Narva
RP31A	345UGV	30672	09/25/2020 TRC	13 BPW0321225310		YAT	BPW ECO PLUS M136 x 2.5 HUB CAP
RP31A	345UGV	31073	09/28/2020 TYRES	15 33000517		BRIAUS01	EX00015883
RP31A	345UGV	31073	09/28/2020 TYRES	15 33000085		BRIAUS01	EX00015883
RP31A	345UGV	31073	09/28/2020 TYRES	15 77000180		BRIAUS01	EX00015883
RP31A	345UGV	31073	09/28/2020 TYRES	15 11001464		BRIAUS01	EX00015883
RP31A	345UGV	31073	09/28/2020 TYRES	15 33000084		BRIAUS01	EX00015883
RP31A	345UGV	31073	09/28/2020 TYRES	15 33000084		BRIAUS01	99212318
RP31A	345UGV	31073	09/28/2020 TYRES	15 11001464		BRIAUS01	99212318
RP31A	345UGV	31073	09/28/2020 TYRES	15 77000180		BRIAUS01	99212318

REMOVAL: CUSTOMER PULL POINT,
ROTATE TBR TYRE,
CASE STOCK 11-22.5,
TYRE 11R22.5 148/145L 16 BS R187,
FIT TBR TYRE,
FIT TBR TYRE,
TYRE 11R22.5 148/145L 16 BS R187,
CASE STOCK 11-22.5,

RP31A	345UGV	31073	09/28/2020 TYRES	15	33000085	BRIAUS01	99212318	ROTATE TBR TYRE,
RP31A	345UGV	31073	09/28/2020 TYRES	15	33000517	BRIAUS01	99212318	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	30991	09/30/2020 FRIVANA	1	LABCON	BRIVAL01	EX00015842	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	30999	09/30/2020 FRIVANA	1	LABCON	BRIVAL01	EX00015842	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	30991	09/30/2020 FRIVANA	1	LABCON	BRIVAL01	3472	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	30999	09/30/2020 FRIVANA	1	LABCON	BRIVAL01	3472	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	31121	10/08/2020 GEN	39	LABOUR APPREN	Labour		
								REPAIR COMPLET ED BY BEN 08.10.202 0
								REPLACED BOTH SUZI COIL LINES
RP31A	345UGV	31121	10/08/2020 GEN					
RP31A	345UGV	31121	10/08/2020 GEN	13	CA2567	YAT	SUZI AIR HOSE SET 1/2 x 10MT	
RP31A	345UGV	31498	10/16/2020 GEN	39	LABOUR MECH1	Labour		
								REPAIR COMPLET ED BY SEAN 16.10.202 0
								R+R SUZI COILS.
RP31A	345UGV	31498	10/16/2020 GEN					
RP31A	345UGV	31498	10/16/2020 GEN	13	61-SC3MTSTSET	YAT	Suzi Coil Short	
RP31A	345UGV	31591	10/20/2020 FRIVANA	1	LABCON	BRIVAL01	EX00016128	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	31591	10/20/2020 FRIVANA	1	LABCON	BRIVAL01	3665	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	31578	10/20/2020 FVGEN	1	LABCON	BRIVAL01	EX00016127	LABOUR & CONSUMABLES,
RP31A	345UGV	31578	10/20/2020 FVGEN	1	LABCON	BRIVAL01	3664	LABOUR & CONSUMABLES,
RP31A	345UGV	31891	10/28/2020 FRIVANA	1	LABCON	BRIVAL01	EX00016243	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	31891	10/28/2020 FRIVANA	1	LABCON	BRIVAL01	3740	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	32707	11/26/2020 TRA	0	LABOUR MECH1	Labour		
RP31A	345UGV	32707	11/26/2020 TRA	SERVICE COMPLETED BY SEAN AND MICK				
RP31A	345UGV	32707	11/26/2020 TRA	0	LABOUR MECH	Labour - Internal		
RP31A	345UGV	32707	11/26/2020 TRA	16	CON	YAT	Consumables	
RP31A	345UGV	33790	01/12/2021 FRIVANA	1	LABCON	BRIVAL01	EX00017309	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	33790	01/12/2021 FRIVANA	SERVICE COMPLETED BY BVR ON 07/01/2021.				
RP31A	345UGV	33790	01/12/2021 FRIVANA	1	LABCON	BRIVAL01	4493	LABOUR & CONSUMABLES,RP31A

RP31A	345UGV	33727	01/12/2021 FRIVANB	39 10-417	BRIVAL01	EX00017292	FILTER KIT (FRIDGE MOTOR),RP31A
RP31A	345UGV	33727	01/12/2021 FRIVANB	39 CON	BRIVAL01	EX00017292	Consumables ,RP31A
RP31A	345UGV	33727	01/12/2021 FRIVANB	39 LAB	BRIVAL01	EX00017292	Labour,RP31A
RP31A	345UGV	33727	01/12/2021 FRIVANB	SERVICED COMPLETED BY BVR 07/01/2021.			
RP31A	345UGV	33727	01/12/2021 FRIVANB	39 LAB	BRIVAL01	4453	Labour,RP31A Consumables
RP31A	345UGV	33727	01/12/2021 FRIVANB	39 CON	BRIVAL01	4453	,RP31A
RP31A	345UGV	33727	01/12/2021 FRIVANB	39 10-417	BRIVAL01	4453	FILTER KIT (FRIDGE MOTOR),RP31A
RP31A	345UGV	33727	01/12/2021 FVGEN	0 LABOUR MECH	Labour - Internal		
RP31A	345UGV	34316	01/13/2021 FRIVANA	1 LABCON	BRIVAL01	EX00017546	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	34316	01/13/2021 FRIVANA	SERVICE COMPLETED BY BVR 11/01/2021.			
RP31A	345UGV	34316	01/13/2021 FRIVANA	1 LABCON	BRIVAL01	4547	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	33752	01/13/2021 FVGEN	39 PART	BRIVAL01	EX00017304	100W 12V SOLAR PANEL,RP31A
RP31A	345UGV	33752	01/13/2021 FVGEN	39 LAB	BRIVAL01	EX00017304	Labour,RP31A
RP31A	345UGV	33752	01/13/2021 FVGEN	SERVICE COMPLETED BY BVR ON 11/01/2021.			
RP31A	345UGV	33752	01/13/2021 FVGEN	39 LAB	BRIVAL01	4545	Labour,RP31A
RP31A	345UGV	33752	01/13/2021 FVGEN	39 PART	BRIVAL01	4545	100W 12V SOLAR PANEL,RP31A
RP31A	345UGV	33948	01/21/2021 TRA	0 LABOUR MECH1	Labour		
				REPLACED RHS REAR COMBINA SION LIGHT			
				INTERIOR LIGHTS NOT WORKING DUE TO BEING WIRED TO PARK LIGHTS IN LHS FRONT CORNER\			
				SERVICE COMPLET ED BY SDEAN AND BEN			
RP31A	345UGV	33948	01/21/2021 TRA				

RP31A	345UGV	33948	01/21/2021 TRA	0 LABOUR	APPREN	Labour - Internal		
RP31A	345UGV	33948	01/21/2021 TRA	16 CON		YAT	Consumables	
RP31A	345UGV	33948	01/21/2021 TRA	14 2424LED		YAT	2424LED Combo T/light	
RP31A	345UGV	34234	01/25/2021 FRIVANA	1 LABCON		BRIVAL01	EX00017511	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	34234	01/25/2021 FRIVANA	SERVICED COMPLETED BY BVR 21/01/2021.				
RP31A	345UGV	34234	01/25/2021 FRIVANA	1 LABCON		BRIVAL01	4663	LABOUR & CONSUMABLES,RP31A
				AIR				
				GAUGE:				
				17000				
				ADJUSTED				
				: 17500				
				WEIGHBRI				
				DGE:				
				17300				
				AIR				
				GAUGE				
				CALIBRATION				
				COMPLETION				
				CORRECTLY.				
RP31A	345UGV	34748	02/15/2021 WEICAL					
RP31A	345UGV	35083	02/25/2021 TRA	0 LABOUR	APPREN	Labour		

				FITTED EBS LEAD
				REPLACED MALE LIGHT PLUG
				REPLACED BOTH REAR SHOCKS
				SERVICE COMPLET ED BY KEIRAN, BEN AND SEAN
RP31A	345UGV	35083	02/25/2021 TRA	25//2021.

RP31A	345UGV	35083	02/25/2021 TRA	0 LABOUR	APPREN	Labour - Internal		
RP31A	345UGV	35083	02/25/2021 TRA	0 LABOUR	MECH1	Labour - Internal		
RP31A	345UGV	35083	02/25/2021 TRA	16 CON		YAT	Consumables	
RP31A	345UGV	35083	02/25/2021 TRA	14	82560	YAT	ABS Lead	
RP31A	345UGV	35083	02/25/2021 TRA	10	F5002	YAT	SHOCK ABSORBER, BPW LONG	
RP31A	345UGV	35161	02/25/2021 TYRES	15	77000180	BRI AUS01	EX00017935	CASE STOCK 11-22.5,RP31A
RP31A	345UGV	35161	02/25/2021 TYRES	15	77000180	BRI AUS01	85456095	CASE STOCK 11-22.5,RP31A
RP31A	345UGV	35315	02/26/2021 TYRES	15	PART	BRI AUS01	EX00017997	GENERAL PART CODE,RP31A
RP31A	345UGV	35315	02/26/2021 TYRES	15	33000241	BRI AUS01	EX00017997	SCRAP TYRES TBR,RP31A
RP31A	345UGV	35315	02/26/2021 TYRES	15	33000125	BRI AUS01	EX00017997	ETA MIN FEE,RP31A
RP31A	345UGV	35315	02/26/2021 TYRES	15	PART	BRI AUS01	85463285	GENERAL PART CODE,RP31A
RP31A	345UGV	35315	02/26/2021 TYRES	15	33000241	BRI AUS01	85463285	SCRAP TYRES TBR,RP31A
RP31A	345UGV	35315	02/26/2021 TYRES	15	33000125	BRI AUS01	85463285	ETA MIN FEE,RP31A
RP31A	345UGV	35585	03/08/2021 FRIVANA	1	LABCON	BRIV AL01	EX00018048	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	35585	03/08/2021 FRIVANA	SERVICE COMPLETED BY BVR 03/03/2021.				
RP31A	345UGV	35585	03/08/2021 FRIVANA	1	LABCON	BRIV AL01	5178	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	35550	03/08/2021 FVGEN	39	CON	BRIV AL01	EX00018038	Consumables ,RP31A

RP31A	345UGV	35550	03/08/2021 FVGEN	39 LAB	BRIVAL01	EX00018038	Labour,RP31A
RP31A	345UGV	35550	03/08/2021 FVGEN	SERVICE COMPLETED BY BVR 03/03/2021.			
RP31A	345UGV	35550	03/08/2021 FVGEN	39 LAB	BRIVAL01	5167	Labour,RP31A
RP31A	345UGV	35550	03/08/2021 FVGEN	39 CON	BRIVAL01	5167	Consumables ,RP31A
RP31A	345UGV	36250	03/22/2021 FRIVANA	1 LABCON	BRIVAL01	EX00018303	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	36250	03/22/2021 FRIVANA	SERVICE COMPLETED BY BVR 19/03/2021			
RP31A	345UGV	36250	03/22/2021 FRIVANA	1 LABCON	BRIVAL01	5376	LABOUR & CONSUMABLES,RP31A
				AIR GAUGE: 19250 ADJUSTED : 1900 WEIGHBRI DGE: 18690			
				AIR GAUGE CALIBRATI ON COMPLET ED CORRECTL Y.			
RP31A	345UGV	37007	04/12/2021 WEICAL				
RP31A	345UGV	36848	04/14/2021 FRIVANA	1 LABCON	BRIVAL01	EX00018572	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	36848	04/14/2021 FRIVANA	SERVICE COMPLETED BY BVR 12/04/2021			
RP31A	345UGV	36848	04/14/2021 FRIVANA	1 LABCON	BRIVAL01	5621	LABOUR & CONSUMABLES,RP31A

				AIR GAUGE: 19600 ADJUSTED : 19750 WEIGHBRI DGE: 19450			
				AIR GAUGE CALIBRATI ON COMPLET ED CORRECTL Y.			
RP31A	345UGV	37231	04/19/2021 WEICAL				
RP31A	345UGV	38376	06/10/2021 TRA	1 LABOUR	Labour		0
RP31A	345UGV	38376	06/10/2021 TRA	SERVICE COMPLETED.			
RP31A	345UGV	38376	06/10/2021 TRB	0 LABOUR	MECH1	Labour	
				SERVICE COMPLET ED SEAN AND BEN			
				R&R LHS STOP/PAR K INDICATO R LIGHT REPLACED LHS REAR MARKER LIGHT ADJUSTED ALL BEARINGS AND TENSION CAPS			
RP31A	345UGV	38376	06/10/2021 TRB				

RP31A	345UGV	38376	06/10/2021 TRB	0 LABOUR	APPREN	Labour - Internal		
RP31A	345UGV	38376	06/10/2021 TRB	16 CON		YAT	Consumables	
RP31A	345UGV	38376	06/10/2021 TRB	14	2378HELLA	YAT	SIGNAL LAMP SBBL GMD MD12-2	
RP31A	345UGV	38573	06/16/2021 FRIVANA	1 LABCON		BRIVAL01	EX00019361	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	38573	06/16/2021 FRIVANA	SERVICE COMPLETED BY BVR 10/06/2021				
RP31A	345UGV	38573	06/16/2021 FRIVANA	1 LABCON		BRIVAL01	6311	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	38675	06/17/2021 TYRES	15	33000096	BRIAUS01	EX00019396	PUNCTURE REPAIR TBR,RP31A
RP31A	345UGV	38675	06/17/2021 TYRES	15	33000096	BRIAUS01	4.81E+09	PUNCTURE REPAIR TBR,RP31A
RP31A	345UGV	39005	06/24/2021 FRIVANA	1 LABCON		BRIVAL01	EX00019544	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	39005	06/24/2021 FRIVANA	SERVICE COMPLETED BY BVR 22/06/2021				
RP31A	345UGV	39005	06/24/2021 FRIVANA	1 LABCON		BRIVAL01	6420	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	39137	06/28/2021 FRIVANA	1 LABCON		BRIVAL01	EX00019580	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	39137	06/28/2021 FRIVANA	SERVICE COMPLETED BY BVR 23.06.2021				
RP31A	345UGV	39137	06/28/2021 FRIVANA	1 LABCON		BRIVAL01	6429	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	39364	07/06/2021 FRIVANA	1 LABCON		BRIVAL01	EX00019667	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	39364	07/06/2021 FRIVANA	SERVICE COMPLETED BY BVR 02/07/2021				
RP31A	345UGV	39364	07/06/2021 FRIVANA	1 LABCON		BRIVAL01	6558	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	39610	07/15/2021 TRA	0 LABOUR	MECH1	Labour		

SERVICE
COMPLET
ED SEAN
AND
KEIRAN

FITTED
TRACKER
TO ROOF -
86528404
1007000

RP31A 345UGV 39610

07/15/2021 TRA

RP31A	345UGV	39610	07/15/2021 TRA	0 LABOUR	APPREN	Labour - Internal		
RP31A	345UGV	39610	07/15/2021 TRA	16 CON		YAT	Consumables	
RP31A	345UGV	39785	07/19/2021 FRIVANA	1 LABCON		BRIVAL01	EX00019840	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	39785	07/19/2021 FRIVANA	SERVICE COMPLETED BVR 16/07/2021				
RP31A	345UGV	39785	07/19/2021 FRIVANA	1 LABCON		BRIVAL01	6727	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	40574	08/03/2021 FRIVANA	1 LABCON		BRIVAL01	EX00020146	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	40574	08/03/2021 FRIVANA	SERVICE COMPLETED BY BVR 03/08/2021				
RP31A	345UGV	40574	08/03/2021 FRIVANA	1 LABCON		BRIVAL01	6961	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	40787	08/09/2021 FRIVANA	1 LABCON		BRIVAL01	EX00020198	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	40787	08/09/2021 FRIVANA	SERVICE COMPLETED BY BVR 09/08/2021				
RP31A	345UGV	40787	08/09/2021 FRIVANA	1 LABCON		BRIVAL01	7052	LABOUR & CONSUMABLES,RP31A

RP31A	345UGV	40771	08/10/2021 FRIVANA	1 LABCON	BRIVAL01	EX00020197	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	40771	08/10/2021 FRIVANA	SERVICE COMPLETED BY BVR 10/08/2021			
RP31A	345UGV	40771	08/10/2021 FRIVANA	1 LABCON	BRIVAL01	7050	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	41669	09/02/2021 FRIVANA	1 LABCON	BRIVAL01	EX00020478	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	41669	09/02/2021 FRIVANA	SERVICE COMPLETED BY BVR 02/09/2021			
RP31A	345UGV	41669	09/02/2021 FRIVANA	1 LABCON	BRIVAL01	7339	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	41573	09/02/2021 GEN	0 LABOUR	MECH1 Labour		
				REPAIR COMPLETED BY SEAN			
				DIAGNOSIS WIRING ISSUE TO BE LIGHT PLUG WIRING, REPAIRED AND CHECKED			
RP31A	345UGV	41573	09/02/2021 GEN				
RP31A	345UGV	41573	09/02/2021 GEN	16 CON	YAT Consumables		
RP31A	345UGV	41790	09/13/2021 GEN	39 F5002	BROHUR01	EX00020536	SHOCK ABSORBER, BPW LONG,RP31A
RP31A	345UGV	41790	09/13/2021 GEN	39 2.57E+08	BROHUR01	EX00020536	Hub Seal Grease, BPW, Eco Plus,RP31A
RP31A	345UGV	41790	09/13/2021 GEN	39 0509146320BH95	BROHUR01	EX00020536	BPW BRAKE SHOE & HARDWARE,RP31A
RP31A	345UGV	41790	09/13/2021 GEN	39 3.11E+08	BROHUR01	EX00020536	BRAKE DRUM 10/285 TRAILER,RP31A
RP31A	345UGV	41790	09/13/2021 GEN	39 3.11E+08	BROHUR01	2283987	BRAKE DRUM 10/285 TRAILER,RP31A
RP31A	345UGV	41790	09/13/2021 GEN	39 0509146320BH95	BROHUR01	2283987	BPW BRAKE SHOE & HARDWARE,RP31A
RP31A	345UGV	41790	09/13/2021 GEN	39 2.57E+08	BROHUR01	2283987	Hub Seal Grease, BPW, Eco Plus,RP31A
RP31A	345UGV	41790	09/13/2021 GEN	39 F5002	BROHUR01	2283987	SHOCK ABSORBER, BPW LONG,RP31A
RP31A	345UGV	41750	09/14/2021 EXOINS	1 LABOUR	MECH Labour		

				VEHICLE PASSED ANNUAL ROADWO RTHY INSPECTIO N. ATTEMPT # 1			
				INSPECTIO N COMPLET ED BY DIESEL SERVICES			
RP31A	345UGV	41750	09/14/2021 EXOINS				
RP31A	345UGV	41750	09/14/2021 GEN	39 LAB	DIESER01	EX00020799	Labour,RP31A
RP31A	345UGV	41761	09/14/2021 GEN	39 SA93.87	GIBBS01	EX00020516	1/2" FEMALE COUPLING NON SEALING,RP31A
RP31A	345UGV	41750	09/14/2021 GEN	39 LAB	DIESER01	EX00020799	Labour,RP31A
RP31A	345UGV	41761	09/14/2021 GEN	39 SA93.23	GIBBS01	EX00020516	1/2 NON SEAL AD.FEM,RP61A
RP31A	345UGV	41750	09/14/2021 GEN	39 LAB	DIESER01	EX00020799	Labour,RP31A
RP31A	345UGV	41761	09/14/2021 GEN	39 SA93.23	GIBBS01	1575063	1/2 NON SEAL AD.FEM,RP61A
RP31A	345UGV	41750	09/14/2021 GEN	39 LAB	DIESER01	EX00020799	Labour,RP31A
RP31A	345UGV	41761	09/14/2021 GEN	39 SA93.87	GIBBS01	1575063	1/2" FEMALE COUPLING NON SEALING,RP31A
RP31A	345UGV	41750	09/14/2021 GEN	39 LAB	DIESER01	EX00020799	Labour,RP31A
RP31A	345UGV	41750	09/14/2021 GEN	39 LAB	DIESER01	EX00020799	Labour,RP31A
RP31A	345UGV	41750	09/14/2021 GEN	39 CON	DIESER01	EX00020799	Consumables ,RP31A
RP31A	345UGV	41750	09/14/2021 GEN	39 PART	DIESER01	EX00020799	GENERAL PART CODE,RP31A
RP31A	345UGV	41750	09/14/2021 GEN	39 PART	DIESER01	26813	GENERAL PART CODE,RP31A
RP31A	345UGV	41750	09/14/2021 GEN	39 CON	DIESER01	26813	Consumables ,RP31A
RP31A	345UGV	41750	09/14/2021 GEN	39 LAB	DIESER01	26813	Labour,RP31A
RP31A	345UGV	41750	09/14/2021 GEN	39 LAB	DIESER01	26813	Labour,RP31A
RP31A	345UGV	41750	09/14/2021 GEN	39 LAB	DIESER01	26813	Labour,RP31A
RP31A	345UGV	41750	09/14/2021 GEN	39 LAB	DIESER01	26813	Labour,RP31A
RP31A	345UGV	41750	09/14/2021 GEN	39 LAB	DIESER01	26813	Labour,RP31A
RP31A	345UGV	41750	09/14/2021 TRA	1 LABOUR	Labour		0
RP31A	345UGV	41750	09/14/2021 TRA	SERVICE COMPLETED.			
RP31A	345UGV	41750	09/14/2021 TRB	1 LABOUR	Labour		0

RP31A	345UGV	41750	09/14/2021 TRB	SERVICE COMPLETED.			
RP31A	345UGV	41750	09/14/2021 TRC	1 LABOUR	Labour		0
				COMPLET			
				ED BY			
				DIESEL			
				SERVICES			
				INV:			
				00026813			
				C&D			
				SERVICE			
				WITH			
				GREASE			
				REPLACE			
				ALL			
				BRAKE			
				LININGS			
				AND			
				DRUMS			
				REPLACE			
				FRONT			
				TRAILER			
				SOCKET			
				REPLACE			
				REAR			
				TRAILER			
				SOCKET			
				REPLACEFI			
RP31A	345UGV	41750	09/14/2021 TRC	RST AND			
RP31A	345UGV	42614	10/05/2021 FRIVANA	1 LABCON	BRIVAL01	EX00020803	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	42614	10/05/2021 FRIVANA	SERVICE COMPLETED BY BVR 05/10/2021			
RP31A	345UGV	42614	10/05/2021 FRIVANA	1 LABCON	BRIVAL01	7813	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	42833	10/12/2021 FRIVANA	1 LABCON	BRIVAL01	EX00020925	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	42833	10/12/2021 FRIVANA	SERVICE COMPLETED BY BVR 12/10/2021			
RP31A	345UGV	42833	10/12/2021 FRIVANA	1 LABCON	BRIVAL01	7914	LABOUR & CONSUMABLES,RP31A
RP31A	345UGV	43644	11/11/2021 FRIVANB	39 100417	BRIVAL01	EX00021290	Filter Service Kit, Fridge Motor, SLX-400,RP31A

RP31A	345UGV	43644	11/11/2021 FRIVANB	39 77-1836	BRIVAL01	EX00021290	PULLEY IDLER COMPL,RP39A
RP31A	345UGV	43644	11/11/2021 FRIVANB	39 CON	BRIVAL01	EX00021290	Consumables
RP31A	345UGV	43644	11/11/2021 FRIVANB	39 LAB	BRIVAL01	EX00021290	,RP31A
RP31A	345UGV	43644	11/11/2021 FRIVANB	SERVICE COMPLETED BY BVR 11/11/2021			Labour,RP31A
RP31A	345UGV	43644	11/11/2021 FRIVANB	39 LAB	BRIVAL01	8240	Labour,RP31A
RP31A	345UGV	43644	11/11/2021 FRIVANB	39 CON	BRIVAL01	8240	Consumables
RP31A	345UGV	43644	11/11/2021 FRIVANB	39 77-1836	BRIVAL01	8240	,RP31A
RP31A	345UGV	43644	11/11/2021 FRIVANB	39 100417	BRIVAL01	8240	PULLEY IDLER COMPL,RP39A
RP31A	345UGV	43595	11/11/2021 TRA	0 LABOUR APPREN	Labour		
RP31A	345UGV	43595	11/11/2021 TRA	SERVICE COMPLETED.			
RP31A	345UGV	43595	11/11/2021 TRA	16 CON	YAT	Consumables	
RP31A	345UGV	43974	11/30/2021 GEN	39 CON	BRIVAL01	EX00021495	Consumables
RP31A	345UGV	43974	11/30/2021 GEN	39 LAB	BRIVAL01	EX00021495	,RP31A
RP31A	345UGV	43974	11/30/2021 GEN	39 LAB	BRIVAL01	8446	Labour,RP31A
RP31A	345UGV	43974	11/30/2021 GEN	39 CON	BRIVAL01	8446	Labour,RP31A
RP31A	345UGV	44101	12/09/2021 TRA	0 LABOUR MECH1	Labour		Consumables
				SERVICE COMPLETED BY IAN AND BEN			,RP31A
				REPAIRED RHS BOTTOM F-TRACK MIDWAY			
RP31A	345UGV	44101	12/09/2021 TRA				
RP31A	345UGV	44101	12/09/2021 TRA	0 LABOUR APPREN	Labour - Internal		
RP31A	345UGV	44597	01/11/2022 TRA	16 CON	YAT	Consumables	
RP31A	345UGV	44597	01/11/2022 TRA	1 LABOUR Labour			0
RP31A	345UGV	44597	01/11/2022 TRA	SERVICE COMPLETED BY BEN			
RP31A	345UGV	44597	01/11/2022 TRA	0 LABOUR APPREN	Labour - Internal		
RP31A	345UGV	44597	01/11/2022 TRA	16 CON	YAT	Consumables	
RP31A	345UGV	45614	02/18/2022 GEN	39 CALL OUT FEE	NIEMOB01	EX00022588	Call Out After Hours/Off Site,RP31A
RP31A	345UGV	45614	02/18/2022 GEN	39 LAB	NIEMOB01	EX00022588	Labour,RP31A
RP31A	345UGV	45614	02/18/2022 GEN	39 PART	NIEMOB01	EX00022588	GENERAL PART CODE,RP31A

				COMPLET ED BY NIESLER MOBILE MECHANI CAL INV# 6148
				CALL DOWN TO CANNONV ALE AND CHECK OUT TROUBLE, PULLED BOOSTER APART ON SAFETY PIN AND FOUND A HOLE TRAVELLE D BACK TO WORKSH OP AND
RP31A	345UGV	45614	02/18/2022 GEN	

RP31A	345UGV	45614	02/18/2022 GEN	39 PART	NIEMOB01	6148	GENERAL PART CODE,RP31A
RP31A	345UGV	45614	02/18/2022 GEN	39 LAB	NIEMOB01	6148	Labour,RP31A
RP31A	345UGV	45614	02/18/2022 GEN	39 CALL OUT FEE	NIEMOB01	6148	Call Out After Hours/Off Site,RP31A
RP31A	345UGV	45701	02/21/2022 GEN	39 LABOUR	Labour		0
RP31A	345UGV	45701	02/21/2022 GEN	TRACKER INSTALLED - 860112047126174			
RP31A	345UGV	45617	02/21/2022 TRA	0 LABOUR	APPRENK	Labour	

				SERVICE COMPLET ED BY KEIRAN, BEN AND TYLER				
				JUMP STARTED FRIDGE REPLACED FEMALE LIGHT PLUG ON FRONT OF TRAILER REPLACED 2.5KG F/E				
RP31A	345UGV	45617	02/21/2022 TRA					
RP31A	345UGV	45617	02/21/2022 TRA		0 LABOUR	APPRENB	Labour - Internal	
RP31A	345UGV	45617	02/21/2022 TRA		0 LABOUR	TRADEA	Labour - Internal	
RP31A	345UGV	45617	02/21/2022 TRA		16 CON	YAT	Consumables	
				AIR GAUGE: 18.5 ADJUSTED : 17.75 WEIGHBRI DGE: 17.44				
				AIR GAUGE CALIBRATI ON COMPLET ED CORRECTL Y.				
RP31A	345UGV	45980	02/21/2022 WEICAL					

RP31A	345UGV	45686	02/22/2022 TYRES	15	77000180	BRIAUS01	EX00022614	CASE STOCK 11-22.5,RP31A
RP31A	345UGV	45686	02/22/2022 TYRES	15	77000180	BRIAUS01	87305609	CASE STOCK 11-22.5,RP31A
RP31A	345UGV	46031	03/09/2022 GEN	39	CON	BRIVAL01	EX00022884	Consumables ,RP31A
RP31A	345UGV	46031	03/09/2022 GEN	39	LAB	BRIVAL01	EX00022884	Labour,RP31A
RP31A	345UGV	46031	03/09/2022 GEN	SERVICE COMPLETED BY 09.03.2022				
RP31A	345UGV	46031	03/09/2022 GEN	39	LAB	BRIVAL01	9601	Labour,RP31A
RP31A	345UGV	46031	03/09/2022 GEN	39	CON	BRIVAL01	9601	Consumables ,RP31A
RP31A	345UGV	46122	03/14/2022 GEN	0	LABOUR	APPRENK	Labour	
				REPAIR COMPLET ED BY KEIRAN				
				FITTED WASHERS BEHIND FEMALE LIGHT PLUG CHECKED ALL				
RP31A	345UGV	46122	03/14/2022 GEN	LIGHTS				
RP31A	345UGV	46122	03/14/2022 GEN	16	CON	YAT	Consumables	
RP31A	345UGV	46287	03/23/2022 TRA	1	LABOUR	Labour		0
RP31A	345UGV	46287	03/23/2022 TRA	SERVICE COMPLETED.				
RP31A	345UGV	46287	03/23/2022 TRB	0	LABOUR	SUBMEC	Labour	
RP31A	345UGV	46287	03/23/2022 TRB	SERVICE COMPLETED BRENDAN BEN AND TYLER				
RP31A	345UGV	46287	03/23/2022 TRB	0	LABOUR	APPRENB	Labour - Internal	
RP31A	345UGV	46287	03/23/2022 TRB	0	LABOUR	APPREN	Labour - Internal	
RP31A	345UGV	46287	03/23/2022 TRB	16	CON	YAT	Consumables	

				AIR GAUGE: 14.25 ADJUSTED : 14.75 WEIGHBRI DGE: 14.34			
RP31A	345UGV	47018	03/30/2022 WEICAL	AIR GAUGE CALIBRATI ON COMPLET ED CORRECTL Y.			
RP31A	345UGV	47172	04/27/2022 TRA		0 LABOUR	SUBMEC	Labour
				SERVICE COMPLET ED BY BRENDAN, KEIRAN AND TYLER			
				R&R TOP RHS MARKER LAMP			
				REMOVE AND RESEAL ABS PLUG			
RP31A	345UGV	47172	04/27/2022 TRA	R&R ENTRY STEP LADDER			

RP31A	345UGV	47172	04/27/2022 TRA	0 LABOUR	APPRENK	Labour - Internal	
RP31A	345UGV	47172	04/27/2022 TRA	0 LABOUR	APPREN	Labour - Internal	
RP31A	345UGV	47172	04/27/2022 TRA	16 CON		YAT	Consumables
RP31A	345UGV	47172	04/27/2022 TRA	14	91622	YAT	LED Marker light. Amber. Narva
RP31A	345UGV	47172	04/27/2022 TRA	13 PART		YAT	GENERAL PART CODE - ENTRY LADDER
RP31A	345UGV	47265	04/30/2022 GEN	0 LABOUR	MECH1	Labour	

REPAIR
COMPLET
ED BY IAN

TEST AND
DIAGNOS
E FAULTY,
CHANGE
CIRCUIT
SOLENOID
R&R
SOLENOID
AND
CHECK
CHARGE
RATE
13.92 -
ALL OK
HOOK UP
TO TO
RP27 AS
REQUESTE
D WHEN
COMPLET
ED

RP31A	345UGV	47265	04/30/2022 GEN
-------	--------	-------	----------------

RP31A	345UGV	47265	04/30/2022 GEN	16 CON		YAT	Consumables
RP31A	345UGV	47265	04/30/2022 GEN	14	24059BX	YAT	SOLENOID
RP31A	345UGV	47978	05/31/2022 TRA	0 LABOUR	APPRENB	Labour	
RP31A	345UGV	47978	05/31/2022 TRA	SERVICE COMPLETED BY BEN AND KEIRAN			

RP31A	345UGV	47978	05/31/2022 TRA	0 LABOUR	APPRENK	0.5	85	42.5	
RP31A	345UGV	47978	05/31/2022 TRA	16 CON		YAT	Consumables		
RP31A	345UGV	48193	06/09/2022 TYRES	15 33000096		BRIAUS01	EX00023949		PUNCTURE REPAIR TBR,RP31A
RP31A	345UGV	48193	06/09/2022 TYRES	15 33000096		BRIAUS01	87864918		PUNCTURE REPAIR TBR,RP31A
RP31A	345UGV	48558	06/28/2022 TYRES	15 33000096		BRIAUS01	EX00024173		PUNCTURE REPAIR TBR,RP31A
RP31A	345UGV	48558	06/28/2022 TYRES	15 33000096		BRIAUS01	87959894		PUNCTURE REPAIR TBR,RP31A
RP31A	345UGV	48722	06/30/2022 TYRES	15 77000180		BRIAUS01	EX00024243		CASE STOCK 11-22.5,RP31A
RP31A	345UGV	48722	06/30/2022 TYRES	15 77000180		BRIAUS01	87978973		CASE STOCK 11-22.5,RP31A
RP31A	345UGV	50226	08/30/2022 TRA	0 LABOUR	APPREN	Labour			

SERVICE
COMPLET
ED BY
TYLER
ANFD
KEIRAN

REPLACED
TRAILER
ELECTRIC
AL LEAD
LIGHT
PLUG
REPLACED
MIDDLE
TOP LH
SIDE
MARKER
LIGHT

RP31A	345UGV	50226	08/30/2022 TRA
-------	--------	-------	----------------

RP31A	345UGV	50226	08/30/2022 TRA	0 LABOUR	MECH1	Labour - Internal	
RP31A	345UGV	50226	08/30/2022 TRA	16 CON		YAT	Consumables
RP31A	345UGV	50226	08/30/2022 TRA	14 91700BL		YAT	Clearance Light, LED Amber, Narva

AIR
GAUGE:
19000
ADJUSTED
: 19500
WEIGHBRI
DGE:
19100

AIR
GAUGE
CALIBRATI
ON
COMPLET
ED
CORRECTL
Y.

RP31A	345UGV	50626	09/05/2022 WEICAL					
RP31A	345UGV	50431	09/06/2022 GEN	39	773124	BRIVAL01	EX00025034	Bearing 6304DD,RP31A
RP31A	345UGV	50431	09/06/2022 GEN	39	781904	BRIVAL01	EX00025034	Tensioner, Fan Drv Assy, W/Out Pulley, QTK Fridge,RP31A
RP31A	345UGV	50431	09/06/2022 GEN	39	45-2258	BRIVAL01	EX00025034	120 AMP ALTERNATOR,RP31A
RP31A	345UGV	50431	09/06/2022 GEN	39	PART	BRIVAL01	EX00025034	GENERAL PART CODE,RP31A
RP31A	345UGV	50431	09/06/2022 GEN	39	781945	BRIVAL01	EX00025034	Belt, Engine, Fridge SLXE,RP31A
RP31A	345UGV	50431	09/06/2022 GEN	39	CON	BRIVAL01	EX00025034	Consumables ,RP31A
RP31A	345UGV	50431	09/06/2022 GEN	39	LAB	BRIVAL01	EX00025034	Labour,RP31A
RP31A	345UGV	50431	09/06/2022 GEN	SERVICE COMPLETED BY BVR		BRIVAL01	12042	Labour,RP31A
RP31A	345UGV	50431	09/06/2022 GEN	39	LAB	BRIVAL01	12042	Consumables ,RP31A
RP31A	345UGV	50431	09/06/2022 GEN	39	CON	BRIVAL01	12042	
RP31A	345UGV	50431	09/06/2022 GEN	39	781945	BRIVAL01	12042	Belt, Engine, Fridge SLXE,RP31A
RP31A	345UGV	50431	09/06/2022 GEN	39	PART	BRIVAL01	12042	GENERAL PART CODE,RP31A
RP31A	345UGV	50431	09/06/2022 GEN	39	45-2258	BRIVAL01	12042	120 AMP ALTERNATOR,RP31A
RP31A	345UGV	50431	09/06/2022 GEN	39	781904	BRIVAL01	12042	Tensioner, Fan Drv Assy, W/Out Pulley, QTK Fridge,RP31A
RP31A	345UGV	50431	09/06/2022 GEN	39	773124	BRIVAL01	12042	Bearing 6304DD,RP31A
RP31A	345UGV	50455	09/07/2022 GEN	39	LABOUR Labour			0

									REPAIR COMPLET ED KEIRAN										
									-										
									REPLACED BOTH PLUGS ON ELECTRIC AL LEAD. - FOUND SHORT IN WIRING BEHIND FRONT LH PARK LIGHT.										
RP31A	345UGV	50455	09/07/2022	GEN															
RP31A	345UGV	50455	09/07/2022	GEN	0	LABOUR	MECH1	Labour - Internal											
RP31A	345UGV	50455	09/07/2022	GEN	16	CON		YAT	Consumables										
RP31A	345UGV	50493	09/08/2022	FRIVANSE	39	100417		BRIVAL01		EX00025074									Filter Service Kit, Fridge Motor, SLX-400,RP31A
																			Consumables ,RP31A
RP31A	345UGV	50493	09/08/2022	FRIVANSE	39	CON		BRIVAL01		EX00025074									
RP31A	345UGV	50493	09/08/2022	FRIVANSE	39	LAB		BRIVAL01		EX00025074									Labour,RP31A
RP31A	345UGV	50493	09/08/2022	FRIVANSE	SERVICE COMPLETED BY BVR 8.9.2022														
RP31A	345UGV	50493	09/08/2022	FRIVANSE	40	3413005		YAT	OIL 15W-40, CK 4/E9										
RP31A	345UGV	50493	09/08/2022	FRIVANSE	39	LAB		BRIVAL01		12151									Labour,RP31A
																			Consumables ,RP31A
RP31A	345UGV	50493	09/08/2022	FRIVANSE	39	CON		BRIVAL01		12151									
RP31A	345UGV	50493	09/08/2022	FRIVANSE	39	100417		BRIVAL01		12151									Filter Service Kit, Fridge Motor, SLX-400,RP31A

AIR
GAUGE
CALIBRATI
ON
COMPLET
ED
CORRECTL
Y.

RP31A	345UGV	50894	09/28/2022 WEICAL	Y.			
RP31A	345UGV	51201	09/29/2022 FVGEN	39 PART	BRIVAL01	EX00025452	45-2372,RP31A
RP31A	345UGV	51201	09/29/2022 FVGEN	39 CON	BRIVAL01	EX00025452	Consumables ,RP31A
RP31A	345UGV	51201	09/29/2022 FVGEN	39 LAB	BRIVAL01	EX00025452	Labour,RP31A

				REPAIR COMPLET ED BY BVR 29.09.202 2			
				TRAVEL TO SITTE AND INSPECT UNIT, REMOVE AND REPLACE DAMAGE D AND NOT WORKING HMI UNIT AND DOWNLO AD FLASH DRIVE - UNIT RUN ON TEST - PRETRIP PASSED			
RP31A	345UGV	51201	09/29/2022 FVGEN				
RP31A	345UGV	51201	09/29/2022 FVGEN	39 LAB	BRIVAL01	12413	Labour,RP31A
RP31A	345UGV	51201	09/29/2022 FVGEN	39 CON	BRIVAL01	12413	Consumables ,RP31A
RP31A	345UGV	51201	09/29/2022 FVGEN	39 PART	BRIVAL01	12413	45-2372,RP31A

RP31A	345UGV	50962	09/29/2022 WEICAL	AIR GAUGE: 19250 ADJUSTED :19500 WEIGHBRI DGE: 19100
				AIR GAUGE CALIBRATI ON COMPLET ED CORRECTL Y.

RP31A	345UGV	51126	10/06/2022 DEFECT	Reported Defect :- Defect Code : 00007992 Defect Reference : 19512 Date : 05/09/20 22 Descriptio n of Defect : WEIGHT GAUGE DOES NOT WORK
-------	--------	-------	-------------------	--

RP31A	345UGV	51127	10/06/2022 EXOINS	1 LABOUR	MECH	Labour
			VEHICLE PASSED ANNUAL ROADWO RTHY INSPECTIO N. ATTEMPT # 1 INSPECTIO N COMPLET ED BY KEIRAN			
RP31A	345UGV	51127	10/06/2022 EXOINS			
RP31A	345UGV	51126	10/06/2022 TRA	1 LABOUR	MECH	Labour
RP31A	345UGV	51126	10/06/2022 TRA	SERVICE COMPLETED.		
RP31A	345UGV	51126	10/06/2022 TRB	1 LABOUR	MECH	Labour
RP31A	345UGV	51126	10/06/2022 TRB	SERVICE COMPLETED.		
RP31A	345UGV	51126	10/06/2022 TRC	0 LABOUR	MECH1	Labour
			SERVICE COMPLET ED BY KEIRAN AND TYLER TRAILER NEEDS TO GO TO VAWDREY AS REAR DOORS ARE DELAMIN ATING #7992 COULD NOT FAULT GAUGE			
RP31A	345UGV	51126	10/06/2022 TRC			

RP31A	345UGV	51126	10/06/2022 TRC	0 LABOUR	APPREN	1.5	105	157.5	
RP31A	345UGV	51126	10/06/2022 TRC	16 CON		YAT	Consumables		
RP31A	345UGV	51560	10/21/2022 GEN	39 PART		BRIVAL01	EX00025596		GENERAL PART CODE,RP31A
RP31A	345UGV	51560	10/21/2022 GEN	39 CON		BRIVAL01	EX00025596		Consumables ,RP31A
RP31A	345UGV	51560	10/21/2022 GEN	39 LAB		BRIVAL01	EX00025596		Labour,RP31A
				REPAIR COMPLET ED BY BVR 21.10.202 2					
				TRAVEL TO SITE AND INSPECT UNIT, REMOVE AND REPLACE U/S STARTER MOTOR					
RP31A	345UGV	51560	10/21/2022 GEN						
RP31A	345UGV	51560	10/21/2022 GEN	39 LAB		BRIVAL01	12667		Labour,RP31A
RP31A	345UGV	51560	10/21/2022 GEN	39 CON		BRIVAL01	12667		Consumables ,RP31A
RP31A	345UGV	51560	10/21/2022 GEN	39 PART		BRIVAL01	12667		GENERAL PART CODE,RP31A
RP31A	345UGV	51704	10/28/2022 TYRES	15 77000180		BRI AUS01	EX00025687		CASE STOCK 11-22.5,RP31A
RP31A	345UGV	51704	10/28/2022 TYRES	15 77000180		BRI AUS01	88601931		CASE STOCK 11-22.5,RP31A
RP31A	345UGV	52298	11/28/2022 FVGEN	39 CON		BRIVAL01	EX00026028		Consumables ,RP31A
RP31A	345UGV	52298	11/28/2022 FVGEN	39 LAB		BRIVAL01	EX00026028		Labour,RP31A
RP31A	345UGV	52298	11/28/2022 FVGEN	SERVICE COMPLETED BY BVR - 22.11.22					
RP31A	345UGV	52298	11/28/2022 FVGEN	39 LAB		BRIVAL01	13287		Labour,RP31A
RP31A	345UGV	52298	11/28/2022 FVGEN	39 CON		BRIVAL01	13287		Consumables ,RP31A
RP31A	345UGV	52376	11/28/2022 TRA	0 LABOUR	APPREN	Labour			

				CHECKED TURN TAB LE AS DEFECTED , ADJUSTM ENT AND OPERATIO N ALL OK			
				SERVICE COMPLET ED BY TYLER FYNN AND KEIRAN			
RP31A	345UGV	52376	11/28/2022 TRA				
RP31A	345UGV	52376	11/28/2022 TRA	0 LABOUR	APPRENF	Labour - Internal	
RP31A	345UGV	52376	11/28/2022 TRA	0 LABOUR	MECH1	Labour - Internal	
RP31A	345UGV	52376	11/28/2022 TRA	16 CON		YAT	Consumables
RP31A	345UGV	53460	01/19/2023 GEN	0 LABOUR	APPRENK	Labour	
RP31A	345UGV	53464	01/19/2023 GEN	0 LABOUR	APPRENB	Labour	
				REPAIR COMPLET ED. FITTED NEW MUD FLAPS and REPAIRED MUD GUARD BRACKET			
RP31A	345UGV	53460	01/19/2023 GEN				
				REPAIR COMPLET ED. REPLACED RHS REAR AIRBAG			
RP31A	345UGV	53464	01/19/2023 GEN				
RP31A	345UGV	53460	01/19/2023 GEN	0 LABOUR	APPRENF	Labour - Internal	

RP31A	345UGV	53464	01/19/2023 GEN	16 SP0022ASPM	YAT	AIRBAG ASSBLY D36 PLASTIC PISTON	
RP31A	345UGV	53460	01/19/2023 GEN	16 EXOMUD	YAT	MUDFLAP EXODAS	
RP31A	345UGV	53460	01/19/2023 GEN	16 CON	YAT	Consumables	
RP31A	345UGV	53553	01/23/2023 TYRES	15 11001573	BRI AUS01	EX00026785	TYRE 11R22.5 148/145L 16 FS T559,
RP31A	345UGV	53553	01/23/2023 TYRES	15 77000180	BRI AUS01	EX00026785	CASE STOCK 11-22.5,
RP31A	345UGV	53553	01/23/2023 TYRES	15 33000084	BRI AUS01	EX00026785	FIT TBR TYRE,
RP31A	345UGV	53553	01/23/2023 TYRES	39 33000517	BRI AUS01	EX00026785	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	53553	01/23/2023 TYRES	15 33000085	BRI AUS01	EX00026785	ROTATE TBR TYRE,
RP31A	345UGV	53553	01/23/2023 TYRES	15 33000085	BRI AUS01	88792738	ROTATE TBR TYRE,
RP31A	345UGV	53553	01/23/2023 TYRES	39 33000517	BRI AUS01	88792738	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	53553	01/23/2023 TYRES	15 33000084	BRI AUS01	88792738	FIT TBR TYRE,
RP31A	345UGV	53553	01/23/2023 TYRES	15 77000180	BRI AUS01	88792738	CASE STOCK 11-22.5,
RP31A	345UGV	53553	01/23/2023 TYRES	15 11001573	BRI AUS01	88792738	TYRE 11R22.5 148/145L 16 FS T559,
RP31A	345UGV	53760	01/31/2023 TYRES	15 33000237	BRI AUS01	EX00026926	JOB DONE BRUCE HWY BP BURPENGARY POS3 FS,
RP31A	345UGV	53760	01/31/2023 TYRES	15 33000237	BRI AUS01	EX00026926	JOB DONE BRUCE HWY BP BURPENGARY POS3 FS,
RP31A	345UGV	53760	01/31/2023 TYRES	15 33000096	BRI AUS01	EX00026926	PUNCTURE REPAIR TBR,
RP31A	345UGV	53760	01/31/2023 TYRES	15 33000237	BRI AUS01	EX00026926	JOB DONE BRUCE HWY BP BURPENGARY POS3 FS,
RP31A	345UGV	53760	01/31/2023 TYRES	15 33000237	BRI AUS01	89096452	JOB DONE BRUCE HWY BP BURPENGARY POS3 FS,
RP31A	345UGV	53760	01/31/2023 TYRES	15 33000096	BRI AUS01	89096452	PUNCTURE REPAIR TBR,
RP31A	345UGV	53760	01/31/2023 TYRES	15 33000237	BRI AUS01	89096452	JOB DONE BRUCE HWY BP BURPENGARY POS3 FS,
RP31A	345UGV	53760	01/31/2023 TYRES	15 33000237	BRI AUS01	89096452	JOB DONE BRUCE HWY BP BURPENGARY POS3 FS,
RP31A	345UGV	53864	02/03/2023 TRA	1 LABOUR APPRENT	Labour		

RP31A	345UGV	53864	02/03/2023 TRA	SERVICE COMPLET ED. REPLACED RH FRONT MARKER LIGHT REPLACED AIR NOSE ABOVE BOOSTER AND REJOINED TOGETHE R REPLACED RELECTOR RHS SIDE FRONT OF TRAILER
-------	--------	-------	----------------	--

RP31A	345UGV	53864	02/03/2023 TRA	0 LABOUR	APPRENF	Labour - Internal		
RP31A	345UGV	53864	02/03/2023 TRA	16 CON		YAT	Consumables	
RP31A	345UGV	53864	02/03/2023 TRA	16 91700BL		YAT	Clearance Light, LED Amber, Narva	
RP31A	345UGV	53943	02/07/2023 TYRES	15 11004117		BRIAUS01	EX00027029	11R22.5 148/145L FS FT469,
RP31A	345UGV	53943	02/07/2023 TYRES	15 77000180		BRIAUS01	EX00027029	CASE STOCK 11-22.5,
RP31A	345UGV	53943	02/07/2023 TYRES	15 33000084		BRIAUS01	EX00027029	FIT TBR TYRE,
RP31A	345UGV	53943	02/07/2023 TYRES	15 33000517		BRIAUS01	EX00027029	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	53943	02/07/2023 TYRES	15 33000085		BRIAUS01	EX00027029	ROTATE TBR TYRE,
RP31A	345UGV	53943	02/07/2023 TYRES	15 11004117		BRIAUS01	89129304	11R22.5 148/145L FS FT469,
RP31A	345UGV	53943	02/07/2023 TYRES	15 77000180		BRIAUS01	89129304	CASE STOCK 11-22.5,
RP31A	345UGV	53943	02/07/2023 TYRES	15 33000084		BRIAUS01	89129304	FIT TBR TYRE,
RP31A	345UGV	53943	02/07/2023 TYRES	15 33000517		BRIAUS01	89129304	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	53943	02/07/2023 TYRES	15 33000085		BRIAUS01	89129304	ROTATE TBR TYRE,

				Throrra Cleland Drive to inspect issue with fridge unit inop. Retrieve fault code on main screen - oil pressure fault. Complete tests on all electrical circuits - OK. Check start / stop coil - OK. Test solenoid - OK. Complete tests and			
RP31A	345UGV	54315	02/13/2023 GEN				
RP31A	345UGV	54315	02/13/2023 GEN	39 PART	AUTELE01	EX00027268	GENERAL PART CODE - GPGP1460-04, 1/4 OLIVE,
RP31A	345UGV	54315	02/13/2023 GEN	39 PART	AUTELE01	EX00027268	GENERAL PART CODE - GPGP1484-04 1/4 SPIGOT,
RP31A	345UGV	54315	02/13/2023 GEN	39 PART	AUTELE01	EX00027268	GENERAL PART CODE - NT10004BK NYLON TUBE BLACK 1/4,
RP31A	345UGV	54315	02/13/2023 GEN	39 SUND	AUTELE01	EX00027268	SUNDRIES - PARTS CLEANER,
RP31A	345UGV	54315	02/13/2023 GEN	39 CON	AUTELE01	EX00027268	Consumables
RP31A	345UGV	54315	02/13/2023 GEN	39 LABEXT	AUTELE01	EX00027268	,
RP31A	345UGV	54339	02/24/2023 FVGEN	39 CON	BRIVAL01	EX00027285	Labour External, Consumables ,RP31A
RP31A	345UGV	54339	02/24/2023 FVGEN	39 40-0974	BRIVAL01	EX00027285	GRADED SENSOR,RP31A
RP31A	345UGV	54339	02/24/2023 FVGEN	39 TWIN CORE CABLE	BRIVAL01	EX00027285	TWIN CORE CABLE,RP31A

RP31A	345UGV	54339	02/24/2023 FVGEN	39 LAB	BRIVAL01	EX00027285	Labour,RP31A
RP31A	345UGV	54339	02/24/2023 FVGEN	Service completed by BVR 15/02/2023 - Travel to site and inspect unit - Remove and replace faulty return air sensors - Re-run control and display harn			
RP31A	345UGV	54667	03/09/2023 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	54667	03/09/2023 DEFECT				
RP31A	345UGV	54667	03/09/2023 DEFECT	DEFECT CLEARED.			
				Reported			
				Defect :-			
				Defect			
				Code :			
				00008751			
				Defect			
				Reference			
				: 41015			
				Date :			
				14/02/20			
				23			
				Descriptio			
				n of			
				Defect :			
				CHECK			
				ALL FUEL			
				LINES			
				FRIDGE			
				MOTOR,			
				AS			
				BRITTLE			
				AND			
				WEARING			
				ON			
RP31A	345UGV	54667	03/09/2023 DEFECT	CONDUDE			
RP31A	345UGV	54667	03/09/2023 TRA	1 LABOUR	MECH	Labour	
RP31A	345UGV	54667	03/09/2023 TRA	SERVICE COMPLETED.			
RP31A	345UGV	54667	03/09/2023 TRB	0 LABOUR	APPRENB	Labour	

				SERVICE COMPLET ED. DEFECT # 41015 OK BY JOSH @BVR INTERIOR LIGHT SWITCH U/S, NONE IN STOCK HAVE PULLED FUSE				
RP31A	345UGV	54667	03/09/2023 TRB					
RP31A	345UGV	54667	03/09/2023 TRB	0 LABOUR	MECH1	Labour - Internal		
RP31A	345UGV	54667	03/09/2023 TRB	16 CON		YAT Consumables		
RP31A	345UGV	54814	03/13/2023 TYRES	15 11004117		BRIAUS01	EX00027585	11R22.5 148/145L FS FT469,RP31A
RP31A	345UGV	54814	03/13/2023 TYRES	15 33000084		BRIAUS01	EX00027585	FIT TBR TYRE,RP31A
RP31A	345UGV	54814	03/13/2023 TYRES	15 33000114		BRIAUS01	EX00027585	RE-TORQUE TRUCK WHEEL EA WHEEL,RP31A
RP31A	345UGV	54814	03/13/2023 TYRES	15 33000527		BRIAUS01	EX00027585	REMOVAL: SIDEWALL CUT OR STAKED,RP31A
RP31A	345UGV	54814	03/13/2023 TYRES	15 33000527		BRIAUS01	89317450	REMOVAL: SIDEWALL CUT OR STAKED,RP31A
RP31A	345UGV	54814	03/13/2023 TYRES	15 33000114		BRIAUS01	89317450	RE-TORQUE TRUCK WHEEL EA WHEEL,RP31A
RP31A	345UGV	54814	03/13/2023 TYRES	15 33000084		BRIAUS01	89317450	FIT TBR TYRE,RP31A
RP31A	345UGV	54814	03/13/2023 TYRES	15 11004117		BRIAUS01	89317450	11R22.5 148/145L FS FT469,RP31A
RP31A	345UGV	54763	03/14/2023 DEFECT	1 LABOUR	MECH	Labour		
RP31A	345UGV	54763	03/14/2023 DEFECT					
RP31A	345UGV	54763	03/14/2023 DEFECT	DEFECT CLEARED.				
RP31A	345UGV	54763	03/14/2023 DEFECT	40 3413005		YAT	OIL 15W-40, CK 4/E9	
RP31A	345UGV	54763	03/14/2023 DEFECT	Service completed by BVR 09/03/2023 - Carry out B Service as per BVR SPecifications - Unit coding on air sensors - Repair rub through harness as requi				
RP31A	345UGV	54763	03/14/2023 FRIVANB	0 LABOUR	MECH	Labour		

RP31A	345UGV	54763	03/14/2023 FRIVANB	VAN "B" SERVICE COMPLET ED.
				FRIDGE VAN UNIT CALIBRAT ED @ SERVICE.
				SERVICE COMPLET ED BY BVR.
				OIL 14L (Customer Supplied) CALIBRATI ON CERTIFICA TE R+R ENGINE OIL R+R

RP31A	345UGV	54763	03/14/2023 FRIVANB	39 CON	BRIVAL01	EX00027548	Consumables ,RP31A
RP31A	345UGV	54763	03/14/2023 FRIVANB	39 CC	BRIVAL01	EX00027548	CALIBRATION CETIFICATE,RP31A
RP31A	345UGV	54763	03/14/2023 FRIVANB	39 100417	BRIVAL01	EX00027548	Filter Service Kit, Fridge Motor, SLX-400,RP31A
RP31A	345UGV	54763	03/14/2023 FRIVANB	39 40-0974	BRIVAL01	EX00027548	GRADED SENSOR,RP31A
RP31A	345UGV	54763	03/14/2023 FRIVANB	39 LAB	BRIVAL01	EX00027548	Labour,RP31A
RP31A	345UGV	54763	03/14/2023 FRIVANB	39 LAB	BRIVAL01	15012	Labour,RP31A
RP31A	345UGV	54763	03/14/2023 FRIVANB	39 40-0974	BRIVAL01	15012	GRADED SENSOR,RP31A
RP31A	345UGV	54763	03/14/2023 FRIVANB	39 100417	BRIVAL01	15012	Filter Service Kit, Fridge Motor, SLX-400,RP31A
RP31A	345UGV	54763	03/14/2023 FRIVANB	39 CC	BRIVAL01	15012	CALIBRATION CETIFICATE,RP31A
RP31A	345UGV	54763	03/14/2023 FRIVANB	39 CON	BRIVAL01	15012	Consumables ,RP31A
RP31A	345UGV	54763	03/14/2023 FRIVCAL	1 LABOUR MECH	Labour		
				OUT BELOW WORK - MOVE TRAILER IN & OUT OF WORKSH OP (NIL CHARGE) REMOVE & REFIT LH REAR DOOR REMOVE & REFIT INNER LOCK ROD FROM LH REAR DOOR REPAIR DELAMIN ATION IN LH REAR DOOR REMOVE			
RP31A	345UGV	55062	03/23/2023 GEN				

RP31A	345UGV	55062	03/23/2023 GEN	39 LABEXT	VAWAUS01	EX00027705	Labour External,
RP31A	345UGV	55062	03/23/2023 GEN	39 LABEXT	VAWAUS01	Q25432	Labour External,
RP31A	345UGV	55084	03/24/2023 FVGEN	39 CON	BRIVAL01	EX00027723	Consumables
RP31A	345UGV	55084	03/24/2023 FVGEN	39 CALL OUT FEE	BRIVAL01	EX00027723	,RP31A
							Call Out After Hours/Off Site,RP31A

				Service complete d by BVR 18/03/2023 - CALLOUT Travel to site and inspect unit for faulting air sensor - Traced fault to broken harness - Replace broken harness and calibrated sensors - Unit run on test - Pretrip passed				
RP31A	345UGV	55084	03/24/2023 FVGEN					
RP31A	345UGV	55084	03/24/2023 FVGEN	39 CALL OUT FEE	BRIVAL01	15148	Call Out After Hours/Off Site,RP31A	
RP31A	345UGV	55084	03/24/2023 FVGEN	39 CON	BRIVAL01	15148	Consumables ,RP31A	
RP31A	345UGV	55899	04/27/2023 FVGEN	39 CON	BRIVAL01	EX00028310	Consumables ,RP31A	
RP31A	345UGV	55899	04/27/2023 FVGEN	39 LAB	BRIVAL01	EX00028310	Labour,RP31A	
RP31A	345UGV	55899	04/27/2023 FVGEN	Service completed by BVR 20/04/2023 - Travel to site and inspect unit - Relocate evap coil sensor to bottom of coil and insulate as required - Unit run c				
RP31A	345UGV	55899	04/27/2023 FVGEN	39 CON	BRIVAL01	15718	Consumables ,RP31A	
RP31A	345UGV	55899	04/27/2023 FVGEN	39 LAB	BRIVAL01	15718	Labour,RP31A	

				AIR GAUGE: 19.50 ADJUSTED : 18.75 WEIGHBRI DGE: 18.46			
				AIR GAUGE CALIBRATI ON COMPLET ED CORRECTL Y.			
RP31A	345UGV	57052	06/04/2023 WEICAL				
RP31A	345UGV	56991	06/07/2023 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	56991	06/07/2023 DEFECT				
RP31A	345UGV	56991	06/07/2023 DEFECT	DEFECT CLEARED.			
RP31A	345UGV	56991	06/07/2023 TRA	0 LABOUR	MECH 1	Labour	
				SERVICE COMPLET ED. FIXED BRAK IN WIRE ALONG THE LH SIDE FOR THE LIGHT AT THE TOP REAR INTERIOR LIGHT HAS BEEN FIXED ON PRIOR SERVICE			
RP31A	345UGV	56991	06/07/2023 TRA				

RP31A	345UGV	56991	06/07/2023 TRA	0 LABOUR	APPREN	Labour - Internal	
RP31A	345UGV	56991	06/07/2023 TRA	16 91700BL		YAT	Clearance Light, LED Amber, Narva
RP31A	345UGV	56991	06/07/2023 TRA	16 CON		YAT	Consumables
RP31A	345UGV	57109	06/08/2023 FVGEN	39 CON		BRIVAL01	Consumables ,RP31A
RP31A	345UGV	57109	06/08/2023 FVGEN	39 LAB		BRIVAL01	Labour,RP31A
RP31A	345UGV	57109	06/08/2023 FVGEN	39 45-2372		BRIVAL01	HMI III Controller,RP31A
RP31A	345UGV	57109	06/08/2023 FVGEN	Service completed by BVR 07/06/2023 - Travel to site and inspect unit - Remove all panels - Remove and replace broken top cap - Refit all panels - HMI			
RP31A	345UGV	57109	06/08/2023 FVGEN	39 CON		BRIVAL01	Consumables ,RP31A
RP31A	345UGV	57109	06/08/2023 FVGEN	39 LAB		BRIVAL01	Labour,RP31A
RP31A	345UGV	57109	06/08/2023 FVGEN	39 45-2372		BRIVAL01	HMI III Controller,RP31A
RP31A	345UGV	57386	06/15/2023 FVGEN	39 CON		BRIVAL01	Consumables ,RP31A
RP31A	345UGV	57386	06/15/2023 FVGEN	39 LAB		BRIVAL01	Labour,RP31A
RP31A	345UGV	57386	06/15/2023 FVGEN	Service completed by BVR 13/06/2023 - Travel to site and inspect unit for check refrig capacity alarm code - check for repairs and gas level - Run unit d			
RP31A	345UGV	57386	06/15/2023 FVGEN	39 CON		BRIVAL01	Consumables ,RP31A
RP31A	345UGV	57386	06/15/2023 FVGEN	39 LAB		BRIVAL01	Labour,RP31A
RP31A	345UGV	57751	07/05/2023 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	57751	07/05/2023 DEFECT	DEFECT CLEARED.			
RP31A	345UGV	57751	07/05/2023 DEFECT				

					Reported Defect :- Defect Code : 00009407 Defect Reference : 10858 Date : 27/06/2023 Description of Defect : DRIVERS SIDE REAR MUDGAU RD, BOLTS KEEP COMING LOOSE			
RP31A	345UGV	57751	07/05/2023	DEFECT				
RP31A	345UGV	57751	07/05/2023	TRA	1	LABOUR	APPREN	Labour
				SERVICE COMPLETED. TOOK THE BOLT PUT ON RH REAR GUARD BRACKET AND APPLIED LOCK TIGHT TO BOLTS				
RP31A	345UGV	57751	07/05/2023	TRA				
RP31A	345UGV	57751	07/05/2023	TRA	0	LABOUR	APPRENB	Labour - Internal

RP31A	345UGV	57751	07/05/2023 TRA	16 CON	YAT	Consumables	
RP31A	345UGV	58365	07/14/2023 FVGEN	39 CON	BRIVAL01	EX00029678	Consumables ,RP31A
RP31A	345UGV	58365	07/14/2023 FVGEN	39 78-1968	BRIVAL01	EX00029678	GEN Water Pump Belt,RP31A
RP31A	345UGV	58365	07/14/2023 FVGEN	39 42-0100	BRIVAL01	EX00029678	STOP FUEL SOLENOID, FRIDGE MOTORS,RP31A
RP31A	345UGV	58365	07/14/2023 FVGEN	39 33-2230	BRIVAL01	EX00029678	SOLENOID O-RING FRIDGE MOTORS,RP31A
RP31A	345UGV	58365	07/14/2023 FVGEN	39 44-9298	BRIVAL01	EX00029678	RPM SENSOR, FRIDGE MOTOR,RP31A
RP31A	345UGV	58365	07/14/2023 FVGEN	39 44-9181	BRIVAL01	EX00029678	SPEED SOLENOID,RP31A
RP31A	345UGV	58365	07/14/2023 FVGEN	39 LAB	BRIVAL01	EX00029678	Labour,RP31A
RP31A	345UGV	58365	07/14/2023 FVGEN	Service completed by BVR 14/07/2023 - Travel to site and inspect unit - Remove and replace u/s fuel solenoid and RPM sensor - Remove and replace w			
RP31A	345UGV	58365	07/14/2023 FVGEN	39 CON	BRIVAL01	17108	Consumables ,RP31A
RP31A	345UGV	58365	07/14/2023 FVGEN	39 78-1968	BRIVAL01	17108	GEN Water Pump Belt,RP31A
RP31A	345UGV	58365	07/14/2023 FVGEN	39 42-0100	BRIVAL01	17108	STOP FUEL SOLENOID, FRIDGE MOTORS,RP31A
RP31A	345UGV	58365	07/14/2023 FVGEN	39 33-2230	BRIVAL01	17108	SOLENOID O-RING FRIDGE MOTORS,RP31A
RP31A	345UGV	58365	07/14/2023 FVGEN	39 44-9298	BRIVAL01	17108	RPM SENSOR, FRIDGE MOTOR,RP31A
RP31A	345UGV	58365	07/14/2023 FVGEN	39 44-9181	BRIVAL01	17108	SPEED SOLENOID,RP31A
RP31A	345UGV	58365	07/14/2023 FVGEN	39 LAB	BRIVAL01	17108	Labour,RP31A

									BY ICEMAN GROUP ON 17/07/20 23 INV NO. 866837
									*UNIT SHUTTING DOWN...A /HOURS... CALLOUT.. .LOADED.. .@ MT. SAINT JOHN REQUESTE D BY ADAM THOMSO N - PH: 0430 902 334 @ 1:51AM AFTER
RP31A	345UGV	58236	07/17/2023 GEN						
RP31A	345UGV	58236	07/17/2023 GEN	39	133507	ICEGRO01	EX00029611	TK 486 WATER PUMP W/GASKET - LARGER,	
RP31A	345UGV	58236	07/17/2023 GEN	39	781968	ICEGRO01	EX00029611	BELT FRIDGE,	
RP31A	345UGV	58236	07/17/2023 GEN	39	CON	ICEGRO01	EX00029611	SUNDRIES INCL. EPA CHARGE (TVL),	
RP31A	345UGV	58236	07/17/2023 GEN	39	LABEXT	ICEGRO01	EX00029611	LABOUR,	
RP31A	345UGV	58236	07/17/2023 GEN	39	133507	ICEGRO01	866837	TK 486 WATER PUMP W/GASKET - LARGER,	

RP31A	345UGV	58236	07/17/2023 GEN	39 781968	ICEGRO01	866837	BELT FRIDGE,
RP31A	345UGV	58236	07/17/2023 GEN	39 CON	ICEGRO01	866837	SUNDRIES INCL. EPA CHARGE (TVL),
RP31A	345UGV	58236	07/17/2023 GEN	39 LABEXT	ICEGRO01	866837	LABOUR,
							Consumables
RP31A	345UGV	58395	07/20/2023 FVGEN	39 CON	BRIVAL01	EX00029703	,RP31A
RP31A	345UGV	58395	07/20/2023 FVGEN	39 LAB	BRIVAL01	EX00029703	Labour,RP31A
RP31A	345UGV	58395	07/20/2023 FVGEN	39 13-2929	BRIVAL01	EX00029703	Pulley Pump Set,RP31A
RP31A	345UGV	58395	07/20/2023 FVGEN	Service completed by BVR 20/07/2023 - Travel to site and inspect unit - Remove and replace damaged water pump - Unit run on test			
							Consumables
RP31A	345UGV	58395	07/20/2023 FVGEN	39 CON	BRIVAL01	17163	,RP31A
RP31A	345UGV	58395	07/20/2023 FVGEN	39 LAB	BRIVAL01	17163	Labour,RP31A
RP31A	345UGV	58395	07/20/2023 FVGEN	39 13-2929	BRIVAL01	17163	Pulley Pump Set,RP31A
RP31A	345UGV	59023	08/15/2023 GEN	15 99015526	BRI AUS01	EX00030013	RUNOUT TYRE,
RP31A	345UGV	59023	08/15/2023 GEN	15 33000084	BRI AUS01	EX00030013	FIT TBR TYRE,
RP31A	345UGV	59023	08/15/2023 GEN	15 33000517	BRI AUS01	EX00030013	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	59023	08/15/2023 GEN	15 33000118	BRI AUS01	EX00030013	SCHEDULED DEPOT SERVICE 15MIN,
RP31A	345UGV	59023	08/15/2023 GEN	15 99015526	BRI AUS01	1.87E+08	RUNOUT TYRE,
RP31A	345UGV	59023	08/15/2023 GEN	15 33000084	BRI AUS01	1.87E+08	FIT TBR TYRE,
RP31A	345UGV	59023	08/15/2023 GEN	15 33000517	BRI AUS01	1.87E+08	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	59023	08/15/2023 GEN	15 33000118	BRI AUS01	1.87E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP31A	345UGV	59375	08/30/2023 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	59375	08/30/2023 DEFECT	DEFECT CLEARED.			
RP31A	345UGV	59375	08/30/2023 DEFECT	Service completed by BVR 24/08/2023 - Carry out B Service as per BVR Specifications - Found noisy cross shaft bearing - Remove cross shaft and replac			
RP31A	345UGV	59375	08/30/2023 FRIVANB	0 LABOUR	MECH	Labour	

RP31A	345UGV	59375	08/30/2023 FRIVANB	VAN "B" SERVICE COMPLET ED.
				FRIDGE VAN UNIT CALIBRAT ED @ SERVICE.
				SERVICE COMPLET ED BY BVR.
				OIL 14L (Customer Supplied) CALIBRATI ON CERTIFICA TE R+R ENGINE OIL R+R

RP31A	345UGV	59375	08/30/2023 FRIVANB	39 CON	BRIVAL01	EX00030203	Consumables ,RP31A
RP31A	345UGV	59375	08/30/2023 FRIVANB	39 CC	BRIVAL01	EX00030203	CALIBRATION CETIFICATE,RP31A
RP31A	345UGV	59375	08/30/2023 FRIVANB	39 100417	BRIVAL01	EX00030203	Filter Service Kit, Fridge Motor, SLX-400,RP31A
RP31A	345UGV	59375	08/30/2023 FRIVANB	39 781847	BRIVAL01	EX00030203	Idler Assembly Clutch QTK Fridge,RP31A
RP31A	345UGV	59375	08/30/2023 FRIVANB	39 Nov-38	BRIVAL01	EX00030203	VALVE OIL DRAIN,RP31A
RP31A	345UGV	59375	08/30/2023 FRIVANB	39 70-9183	BRIVAL01	EX00030203	Idler Pulley Sm/Groove,RP31A
RP31A	345UGV	59375	08/30/2023 FRIVANB	39 773119	BRIVAL01	EX00030203	BEARING 6207DDUC,RP31A
RP31A	345UGV	59375	08/30/2023 FRIVANB	39 LAB	BRIVAL01	EX00030203	Labour,RP31A
RP31A	345UGV	59375	08/30/2023 FRIVANB	39 LAB	BRIVAL01	INV-00017400	Labour,RP31A
RP31A	345UGV	59375	08/30/2023 FRIVANB	39 773119	BRIVAL01	INV-00017400	BEARING 6207DDUC,RP31A
RP31A	345UGV	59375	08/30/2023 FRIVANB	39 70-9183	BRIVAL01	INV-00017400	Idler Pulley Sm/Groove,RP31A
RP31A	345UGV	59375	08/30/2023 FRIVANB	39 Nov-38	BRIVAL01	INV-00017400	VALVE OIL DRAIN,RP31A
RP31A	345UGV	59375	08/30/2023 FRIVANB	39 781847	BRIVAL01	INV-00017400	Idler Assembly Clutch QTK Fridge,RP31A
RP31A	345UGV	59375	08/30/2023 FRIVANB	39 100417	BRIVAL01	INV-00017400	Filter Service Kit, Fridge Motor, SLX-400,RP31A
RP31A	345UGV	59375	08/30/2023 FRIVANB	39 CC	BRIVAL01	INV-00017400	CALIBRATION CETIFICATE,RP31A
RP31A	345UGV	59375	08/30/2023 FRIVANB	39 CON	BRIVAL01	INV-00017400	Consumables ,RP31A
RP31A	345UGV	59375	08/30/2023 FRIVCAL	1 LABOUR MECH	Labour		
RP31A	345UGV	59633	08/31/2023 FVGEN	39 LABEXT	BRIVAL01	EX00030348	Labour External,RP31A
RP31A	345UGV	59633	08/31/2023 FVGEN	39 SUND	BRIVAL01	EX00030348	SUNDRIES,RP31A
RP31A	345UGV	59633	08/31/2023 FVGEN	39 133507	BRIVAL01	EX00030348	TK 486 WATER PUMP W/GASKET - LARGER,RP31A
RP31A	345UGV	59633	08/31/2023 FVGEN	39 78-1340	BRIVAL01	EX00030348	WATER PUMP BELT (FRIDGE MOTOR),RP31A

				complete d by BVR 17/07/20 23 - ICEMAN TRANSPO RT REFRIGER ATED			
				**Unit shutting down - A/hours - Callout - Loaded - @ Mt.Saint John After hours callout - - Travelled to site checked unit for reported			
RP31A	345UGV	59633	08/31/2023 FVGEN				
RP31A	345UGV	59633	08/31/2023 FVGEN	39 LABEXT	BRIVAL01	INV-00017504	Labour External,RP31A
RP31A	345UGV	59633	08/31/2023 FVGEN	39 SUND	BRIVAL01	INV-00017504	SUNDRIES,RP31A
RP31A	345UGV	59633	08/31/2023 FVGEN	39 133507	BRIVAL01	INV-00017504	TK 486 WATER PUMP W/GASKET - LARGER,RP31A
RP31A	345UGV	59633	08/31/2023 FVGEN	39 78-1340	BRIVAL01	INV-00017504	WATER PUMP BELT (FRIDGE MOTOR),RP31A
RP31A	345UGV	59636	08/31/2023 GEN	39 LABEXT	ICEGRO01	EX00030351	Labour External,
RP31A	345UGV	59636	08/31/2023 GEN	39 133507	ICEGRO01	EX00030351	TK 486 WATER PUMP W/GASKET - LARGER,
RP31A	345UGV	59636	08/31/2023 GEN	39 781968	ICEGRO01	EX00030351	BELT FRIDGE, Consumables
RP31A	345UGV	59636	08/31/2023 GEN	39 CON	ICEGRO01	EX00030351	,

RP31A	345UGV	59636	08/31/2023 GEN	39 LABEXT	ICEGRO01	868701	Labour External,
RP31A	345UGV	59636	08/31/2023 GEN	39 133507	ICEGRO01	868701	TK 486 WATER PUMP W/GASKET - LARGER,
RP31A	345UGV	59636	08/31/2023 GEN	39 781968	ICEGRO01	868701	BELT FRIDGE,
RP31A	345UGV	59636	08/31/2023 GEN	39 CON	ICEGRO01	868701	Consumables
RP31A	345UGV	59466	09/01/2023 DEFECT	1 LABOUR MECH	Labour		
RP31A	345UGV	59467	09/01/2023 DEFECT	1 LABOUR MECH	Labour		
RP31A	345UGV	59466	09/01/2023 DEFECT				
RP31A	345UGV	59467	09/01/2023 DEFECT				
RP31A	345UGV	59466	09/01/2023 DEFECT	DEFECT CLEARED.			
RP31A	345UGV	59467	09/01/2023 DEFECT	DEFECT CLEARED.			

				Defect :-			
				Defect			
				Code :			
				00008881			
				Defect			
				Reference			
				: RP31A			
				Date :			
				10/03/20			
				23			
				Description of			
				Defect :			
				INTERIOR			
				LIGHT			
				SWITCH			
				U/S,			
				NONE IN			
				STOCK			
				HAVE			
				PULLED			
				FUSE			
				DEFECT			
				CLEARED			
				31/08/20			
RP31A	345UGV	59466	09/01/2023 DEFECT	23			

RP31A	345UGV	59467	09/01/2023 EXOINS	1 LABOUR	APPRENF	Labour		
				VEHICLE PASSED ANNUAL ROADWO RTHY INSPECTIO N. ATTEMPT # 1 NO FAULTS APPAREN T INSPECTIO N COMPLET ED BY WORKSH OP - FLYNN ON 31/08/20				
RP31A	345UGV	59467	09/01/2023 EXOINS	23				
RP31A	345UGV	59937	09/01/2023 GEN	39 LABEXT	AUTELE01	EX00030455	REMOVE & REPLACE FAULTY AIRBAG,	
RP31A	345UGV	59937	09/01/2023 GEN	39 AIRBAG	AUTELE01	EX00030455	AIRBAG TYPE 36,	
RP31A	345UGV	59937	09/01/2023 GEN	16 CON	AUTELE01	EX00030455	Consumables	
RP31A	345UGV	59937	09/01/2023 GEN	16 CON	AUTELE01	10638	,	
RP31A	345UGV	59937	09/01/2023 GEN	39 AIRBAG	AUTELE01	10638	Consumables	
RP31A	345UGV	59937	09/01/2023 GEN	39 LABEXT	AUTELE01	10638	,	
RP31A	345UGV	59466	09/01/2023 TRA	1 LABOUR	MECH	Labour	AIRBAG TYPE 36,	
RP31A	345UGV	59466	09/01/2023 TRA	SERVICE COMPLETED.			REMOVE & REPLACE FAULTY AIRBAG,	
RP31A	345UGV	59466	09/01/2023 TRB	1 LABOUR	MECH	Labour		
RP31A	345UGV	59466	09/01/2023 TRB	SERVICE COMPLETED.				
RP31A	345UGV	59466	09/01/2023 TRC	1 LABOUR	APPRENF	Labour		
RP31A	345UGV	59466	09/01/2023 TRC	SERVICE COMPLETED BY FLYNN ON 31/08/2023				
RP31A	345UGV	59466	09/01/2023 TRC	16 CON	YAT	Consumables		

				AIR GAUGE: 13750 ADJUSTED : 19700 WEIGHBRI DGE: 19400			
RP31A	345UGV	59912	09/13/2023	WEICAL Y.			
RP31A	345UGV	60124	09/21/2023	DEFECT	1	LABOUR	
RP31A	345UGV	60124	09/21/2023	DEFECT		MECH	Labour
RP31A	345UGV	60124	09/21/2023	DEFECT	DEFECT CLEARED.		

Defect :-
Defect
Code :
00009986
Defect
Reference
: 52251
Date :
21/09/20
23
Description
of
Defect :
CENTRE
AXLE
PASSENGER
SIDE
BOOSTER
HOSE
LEAKING
(DID
BANDAID
IT UP TO
GET
HOME)

RP31A	345UGV	60124	09/21/2023 DEFECT	DEFECT
-------	--------	-------	-------------------	--------

RP31A	345UGV	60124	09/21/2023 GEN	39 LABOUR	APPREN	Labour
-------	--------	-------	----------------	-----------	--------	--------

REPAIR
COMPLET
ED BY
TYLER ON
21/09/20
23.
RAN A
NEW
HOSE
FROM
TANK TO
BOOSTER

RP31A	345UGV	60124	09/21/2023 GEN	BOOSTER
-------	--------	-------	----------------	---------

				SERVICE COMPLET ED BY MATT, NICK & JOSEPH ON 04/10/20 23.				
				REPLACED AMBER MARKER LIGHT REPLACED SPRING EYE BUSHES FRONT AND REAR AXLES. (PARTS USED ALREADY NOTED ON W/O 00060512				
RP31A	345UGV	60548	10/06/2023 TRA					
RP31A	345UGV	60548	10/06/2023 TRA	0 LABOUR	MECH 1	Labour - Internal		
RP31A	345UGV	60548	10/06/2023 TRA	0 LABOUR	APPRENJ	Labour - Internal		
RP31A	345UGV	60548	10/06/2023 TRA	16 CON		YAT Consumables		
RP31A	345UGV	60548	10/06/2023 TRA	14 91700BL		YAT Clearance Light, LED Amber, Narva		
RP31A	345UGV	60686	10/11/2023 GEN	15 11004117		BRIAUS01 EX00030852	11R22.5 148/145L FS FT469,POSITIONS: 29, 30, 31, 32 - FITTED FROM (	
RP31A	345UGV	60686	10/11/2023 GEN	15 77000180		BRIAUS01 EX00030852	CASE STOCK 11-22.5,POSITIONS: 29, 30, 32	
RP31A	345UGV	60686	10/11/2023 GEN	15 33000084		BRIAUS01 EX00030852	FIT TBR TYRE,POSITIONS: 29, 30, 31, 32	
RP31A	345UGV	60686	10/11/2023 GEN	15 33000517		BRIAUS01 EX00030852	REMOVAL: CUSTOMER PULL POINT,	
RP31A	345UGV	60686	10/11/2023 GEN	15 33000535		BRIAUS01 EX00030852	REMOVAL: WORN TOO FAR,	
RP31A	345UGV	60686	10/11/2023 GEN	15 33000118		BRIAUS01 EX00030852	SCHEDULED DEPOT SERVICE 15MIN,	
RP31A	345UGV	60686	10/11/2023 GEN	15 11004117		BRIAUS01 1.87E+08	11R22.5 148/145L FS FT469,POSITIONS: 29, 30, 31, 32 - FITTED FROM (	

RP31A	345UGV	60686	10/11/2023 GEN	15 77000180	BRIAUS01	1.87E+08	CASE STOCK 11-22.5,POSITIONS: 29, 30, 32
RP31A	345UGV	60686	10/11/2023 GEN	15 33000084	BRIAUS01	1.87E+08	FIT TBR TYRE,POSITIONS: 29, 30, 31, 32
RP31A	345UGV	60686	10/11/2023 GEN	15 33000517	BRIAUS01	1.87E+08	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	60686	10/11/2023 GEN	15 33000535	BRIAUS01	1.87E+08	REMOVAL: WORN TOO FAR,
RP31A	345UGV	60686	10/11/2023 GEN	15 33000118	BRIAUS01	1.87E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP31A	345UGV	61344	10/24/2023 FVGEN	39 CON	BRIVAL01	EX00031178	Consumables
RP31A	345UGV	61344	10/24/2023 FVGEN	39 40-0974	BRIVAL01	EX00031178	,RP31A
RP31A	345UGV	61344	10/24/2023 FVGEN	39 LAB	BRIVAL01	EX00031178	GRADED SENSOR,RP31A
				COMPLET			Labour,RP31A
				ED BY BVR			
				ON			
				24.10.202			
				3			
				TRAVEL			
				TO SITE			
				AND			
				INSPECT			
				UNIT FOR			
				CONTROL,			
				DISPLAY			
				AND			
				RETURN			
				SENSOR			
				FAULTS -			
				REMOVE			
				AND			
				REPLACE			
				U / S			
				TEMP			
				SENSOR			
				AS			
				REQUIRED			
				-			
RP31A	345UGV	61344	10/24/2023 FVGEN	CALIBRAT			
				ED AND			
RP31A	345UGV	61344	10/24/2023 FVGEN	39 CON	BRIVAL01	INV-00018333	Consumables
							,RP31A

RP31A	345UGV	61976	11/14/2023 TRA	39 LABEXT	RCCLOW01	EX00031434	INSPECT LIGHTS - LHS REAR MARKER PLATE AND NUMBER PLATE LHS,
RP31A	345UGV	61976	11/14/2023 TRA	10 AIRBAG	RCCLOW01	EX00031434	AIRBAG,
RP31A	345UGV	61976	11/14/2023 TRA	31 PART	RCCLOW01	EX00031434	LED SIDE MARKER,
RP31A	345UGV	61976	11/14/2023 TRA	31 PART	RCCLOW01	EX00031434	NUMBER PLATE LIGHT,
RP31A	345UGV	61976	11/14/2023 TRA	16 CON	RCCLOW01	EX00031434	GREASE,
RP31A	345UGV	61976	11/14/2023 TRA	16 CON	RCCLOW01	EX00031434	Consumables
RP31A	345UGV	61976	11/14/2023 TRA	16 CON	RCCLOW01	EX00031434	,
RP31A	345UGV	61976	11/14/2023 TRA	16 ENVLEV	RCCLOW01	EX00031434	ENVIRONMENTAL LEVY,
RP31A	345UGV	61976	11/14/2023 TRA	16 ENVLEV	RCCLOW01	36105	ENVIRONMENTAL LEVY,
RP31A	345UGV	61976	11/14/2023 TRA	16 CON	RCCLOW01	36105	Consumables
RP31A	345UGV	61976	11/14/2023 TRA	16 CON	RCCLOW01	36105	,
RP31A	345UGV	61976	11/14/2023 TRA	16 CON	RCCLOW01	36105	GREASE,
RP31A	345UGV	61976	11/14/2023 TRA	31 PART	RCCLOW01	36105	NUMBER PLATE LIGHT,
RP31A	345UGV	61976	11/14/2023 TRA	31 PART	RCCLOW01	36105	LED SIDE MARKER,
RP31A	345UGV	61976	11/14/2023 TRA	10 AIRBAG	RCCLOW01	36105	AIRBAG,
RP31A	345UGV	61976	11/14/2023 TRA	39 LABEXT	RCCLOW01	36105	INSPECT LIGHTS - LHS REAR MARKER PLATE AND NUMBER PLATE LHS,
RP31A	345UGV	61976	11/14/2023 TRA	39 LABEXT	RCCLOW01	36105	REMOVE & REPLACE LEAKING AIRBAGS ON MIDDLE AXLE AND FRONT I
RP31A	345UGV	61976	11/14/2023 TRA	1 LABEXT	RCCLOW01	36105	CARRY OUT 'A' SERVICE,TIGHTEN UP RIGHT HAND REAR MUDGUARD B
RP31A	345UGV	62703	12/11/2023 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	62703	12/11/2023 DEFECT				
RP31A	345UGV	62703	12/11/2023 DEFECT	DEFECT CLEARED.			

				Reported Defect :- Defect Code : 00010447 Defect Reference : 41455 Date : 11/12/20 23 Description n of Defect : ELECTRIC AL CONNECT OR ON TRAILER DAMAGE D NEEDS REPLACIN G. (TRUCK TO TRAILER)			
RP31A	345UGV	62703	12/11/2023 DEFECT				
RP31A	345UGV	62703	12/11/2023 TRA	1 LABOUR	MECH 1	Labour	

				"A: SERVICE COMPLET ED BY WORKSH OP 11/12/20 23			
				REPAIRED ELECTRIC AL PLUG AT FRONT OF TRAILER AND STRAIGHT END FRONT MOUNTIN G PLATE.			
RP31A	345UGV	62703	12/11/2023 TRA				
RP31A	345UGV	62703	12/11/2023 TRA	1 LABOUR	APPRENJ	Labour - Internal	
RP31A	345UGV	62703	12/11/2023 TRA	1 LABOUR	APPRENB	Labour - Internal	
RP31A	345UGV	62703	12/11/2023 TRA	16 CON		YAT	Consumables
RP31A	345UGV	62703	12/11/2023 TRA	16 82062/1		YAT	7 PIN LGE ROUND METAL SKT
RP31A	345UGV	63168	01/03/2024 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	63168	01/03/2024 DEFECT				
RP31A	345UGV	63168	01/03/2024 DEFECT	DEFECT CLEARED.			
RP31A	345UGV	63168	01/03/2024 TRA	1 LABOUR	APPREN	Labour	
				SERVICE COMPLET ED BY TYLER, JOE & BEN ON 03/01/20 24. REPLACED RHS PARKLIGH T AT TOP			
RP31A	345UGV	63168	01/03/2024 TRA				

RP31A	345UGV	63168	01/03/2024 TRA	0 LABOUR	APPRENJ	Labour - Internal		
RP31A	345UGV	63168	01/03/2024 TRA	0 LABOUR	APPRENB	Labour - Internal		
RP31A	345UGV	63168	01/03/2024 TRA	16 CON		YAT	Consumables	
RP31A	345UGV	63168	01/03/2024 TRA	14 91700BL		YAT	Clearance Light, LED Amber, Narva	
							Consumables	
RP31A	345UGV	64180	01/23/2024 FVGEN	39 CON		BRIVAL01	EX00032587	,RP31A
RP31A	345UGV	64180	01/23/2024 FVGEN	39 8452739		BRIVAL01	EX00032587	CONTROLLER SR3 NEWX SLXI,RP31A
RP31A	345UGV	64180	01/23/2024 FVGEN	39 LAB		BRIVAL01	EX00032587	Labour,RP31A
				complete				
				d by BVR				
				23/01/20				
				24 - Travel				
				to site and				
				inspect				
				unit for				
				reported				
				not going				
				into high				
				speed -				
				Located				
				broken				
				wire off				
				speed				
				solenoid -				
				Repair				
				wiring as				
				required -				
				Test				
				speed				
				solenoid,				
				non				
				operation -				
				Test for				
				power at				
RP31A	345UGV	64180	01/23/2024 FVGEN	solenoid,				

RP31A	345UGV	64180	01/23/2024 FVGEN	39 CON	BRIVAL01	INV-00019583	Consumables ,RP31A
RP31A	345UGV	64180	01/23/2024 FVGEN	39 8452739	BRIVAL01	INV-00019583	CONTROLLER SR3 NEWX SLXI,RP31A
RP31A	345UGV	64180	01/23/2024 FVGEN	39 LAB	BRIVAL01	INV-00019583	Labour,RP31A
RP31A	345UGV	64761	02/20/2024 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	64761	02/20/2024 DEFECT				
RP31A	345UGV	64761	02/20/2024 DEFECT	DEFECT CLEARED.			
RP31A	345UGV	64761	02/20/2024 TRA	1 LABOUR	MECH	Labour	
RP31A	345UGV	64761	02/20/2024 TRA	SERVICE COMPLETED.			
RP31A	345UGV	64761	02/20/2024 TRB	1 LABOUR	MECH 1	Labour	
				SERVICE COMPLET ED BY NICK & JOSEPH ON 20/02/20 24. REPLACED RHF BPW CAP REPAIRED WIRING TO LHS CLEARANC E LIGHT REPLACED RHS TAIL STOP INDICATO R LIGHT REPLACED FIRE EXTINGUI SHER			
RP31A	345UGV	64761	02/20/2024 TRB	2.5KG			
RP31A	345UGV	64761	02/20/2024 TRB	0 LABOUR	APPRENJ	Labour - Internal	
RP31A	345UGV	64761	02/20/2024 TRB	16 CON	YAT	Consumables	
RP31A	345UGV	64761	02/20/2024 TRB	14 2378BLHE	YAT	LAMP TAIL DURALED COMBI-S 12/24V	
RP31A	345UGV	64761	02/20/2024 TRB	19 FIREEXT2.5KG	YAT	2.5KG FIRE EXTINGUISHER	
							Consumables
RP31A	345UGV	65099	02/26/2024 FVGEN	39 CON	BRIVAL01	EX00033082	,RP31A

RP31A	345UGV	65099	02/26/2024 FVGEN	39 LAB	BRIVAL01	EX00033082	Labour,RP31A
RP31A	345UGV	65099	02/26/2024 FVGEN	Service completed by BVR 26/02/2024 - Travel to site and inspect unit for reported control air sensor alarm code *trailer loaded* - Check sensor readir			
RP31A	345UGV	65099	02/26/2024 FVGEN	39 CON	BRIVAL01	INV-00020050	Consumables ,RP31A
RP31A	345UGV	65099	02/26/2024 FVGEN	39 LAB	BRIVAL01	INV-00020050	Labour,RP31A
RP31A	345UGV	65579	03/20/2024 GEN	15 99015526	BRIAUS01	EX00033340	RUNOUT TYRE,
RP31A	345UGV	65579	03/20/2024 GEN	15 33000084	BRIAUS01	EX00033340	FIT TBR TYRE,
RP31A	345UGV	65579	03/20/2024 GEN	15 33000517	BRIAUS01	EX00033340	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	65579	03/20/2024 GEN	15 33000118	BRIAUS01	EX00033340	SCHEDULED DEPOT SERVICE 15MIN,
RP31A	345UGV	65579	03/20/2024 GEN	15 99015526	BRIAUS01	1.88E+08	RUNOUT TYRE,
RP31A	345UGV	65579	03/20/2024 GEN	15 33000084	BRIAUS01	1.88E+08	FIT TBR TYRE,
RP31A	345UGV	65579	03/20/2024 GEN	15 33000517	BRIAUS01	1.88E+08	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	65579	03/20/2024 GEN	15 33000118	BRIAUS01	1.88E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP31A	345UGV	65941	03/28/2024 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	65941	03/28/2024 DEFECT				
RP31A	345UGV	65941	03/28/2024 DEFECT	DEFECT CLEARED.			
RP31A	345UGV	65941	03/28/2024 TRA	1 LABOUR	APPRENT2	Labour	
				SERVICE COMPLET ED BY TYSON & BEN ON 28/03/20 24. REPLACED LIGHT PLUG HOUSING ON FRONT. REPLACED LHS REAR TAIL LIGHT ASSEMBLY			
RP31A	345UGV	65941	03/28/2024 TRA				
RP31A	345UGV	65941	03/28/2024 TRA	0 LABOUR	APPRENB	Labour - Internal	
RP31A	345UGV	65941	03/28/2024 TRA	16 CON	YAT	Consumables	
RP31A	345UGV	65941	03/28/2024 TRA	14 2332-H24	YAT	Hella Red Stop/Rear LED Tail Light	
RP31A	345UGV	66229	04/09/2024 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	66229	04/09/2024 DEFECT				

RP31A	345UGV	66229	04/09/2024 DEFECT	DEFECT CLEARED.				
RP31A	345UGV	66137	04/09/2024 GEN	15 99015526	BRIAUS01	EX00033715	RUNOUT TYRE,	
RP31A	345UGV	66137	04/09/2024 GEN	15 77000180	BRIAUS01	EX00033715	CASE STOCK 11-22.5,	
RP31A	345UGV	66229	04/09/2024 GEN	39 LABOUR MECH 4	Labour			
RP31A	345UGV	66137	04/09/2024 GEN	15 33000084	BRIAUS01	EX00033715	FIT TBR TYRE,	
				REPAIR COMPLET ED BY ETHAN ON 09/04/20 24. REPLACED EBS LEAD AS OLD ONE IS MISSING				
RP31A	345UGV	66229	04/09/2024 GEN					
RP31A	345UGV	66137	04/09/2024 GEN	15 33000517	BRIAUS01	EX00033715	REMOVAL: CUSTOMER PULL POINT,	
RP31A	345UGV	66229	04/09/2024 GEN	16 CON	YAT Consumables			
RP31A	345UGV	66137	04/09/2024 GEN	15 33000118	BRIAUS01	EX00033715	SCHEDULED DEPOT SERVICE 15MIN,	
RP31A	345UGV	66229	04/09/2024 GEN	31 82560	YAT	12/24V 7 CORE EBS SHORT TAIL SUZI		
RP31A	345UGV	66137	04/09/2024 GEN	15 99015526	BRIAUS01	1.88E+08	RUNOUT TYRE,	
RP31A	345UGV	66137	04/09/2024 GEN	15 77000180	BRIAUS01	1.88E+08	CASE STOCK 11-22.5,	
RP31A	345UGV	66137	04/09/2024 GEN	15 33000084	BRIAUS01	1.88E+08	FIT TBR TYRE,	
RP31A	345UGV	66137	04/09/2024 GEN	15 33000517	BRIAUS01	1.88E+08	REMOVAL: CUSTOMER PULL POINT,	
RP31A	345UGV	66137	04/09/2024 GEN	15 33000118	BRIAUS01	1.88E+08	SCHEDULED DEPOT SERVICE 15MIN,	
RP31A	345UGV	66807	05/01/2024 DEFECT	1 LABOUR MECH	Labour			
RP31A	345UGV	66807	05/01/2024 DEFECT					
RP31A	345UGV	66807	05/01/2024 DEFECT	DEFECT CLEARED.				
RP31A	345UGV	66807	05/01/2024 TRA	1 LABOUR APPRENJ	Labour			
RP31A	345UGV	66807	05/01/2024 TRA	'A' SERVICE COMPLETED BY JOSEPH ON 01/05/2024.				
RP31A	345UGV	66807	05/01/2024 TRA	16 CON	YAT Consumables			
RP31A	345UGV	66962	05/10/2024 FRIVANB	0 LABOUR MECH	Labour			

RP31A	345UGV	66962	05/10/2024 FRIVANB	VAN "B" SERVICE COMPLET ED. FRIDGE VAN UNIT CALIBRAT ED @ SERVICE. SERVICE COMPLET ED BY BVR. OIL 14L (Customer Supplied) CALIBRATI ON CERTIFICA TE R+R ENGINE OIL R+R
-------	--------	-------	--------------------	--

RP31A	345UGV	66962	05/10/2024 FRIVANB	39 CON	BRIVAL01	EX00034173	Consumables ,RP31A
RP31A	345UGV	66962	05/10/2024 FRIVANB	39 CC	BRIVAL01	EX00034173	CALIBRATION CETIFICATE,RP31A
RP31A	345UGV	66962	05/10/2024 FRIVANB	39 100417	BRIVAL01	EX00034173	Filter Service Kit, Fridge Motor, SLX-400,RP31A
RP31A	345UGV	66962	05/10/2024 FRIVANB	39 Nov-99	BRIVAL01	EX00034173	AIR FILTER HOUSING,RP31A
RP31A	345UGV	66962	05/10/2024 FRIVANB	39 78-1831	BRIVAL01	EX00034173	GEN SLX Compressor Belt,RP31A
RP31A	345UGV	66962	05/10/2024 FRIVANB	39 LAB	BRIVAL01	EX00034173	Labour,RP31A
RP31A	345UGV	66962	05/10/2024 FRIVANB	40 3413005	YAT	OIL 15W-40, CK 4/E9	
RP31A	345UGV	66962	05/10/2024 FRIVANB	Service completed by BVR 01/05/2024 - Carry out B Service as per BVR Specifications - Remove and replace damaged air filter housing as required - Spl			
RP31A	345UGV	66962	05/10/2024 FRIVANB	39 CON	BRIVAL01	INV-00020931	Consumables ,RP31A
RP31A	345UGV	66962	05/10/2024 FRIVANB	39 CC	BRIVAL01	INV-00020931	CALIBRATION CETIFICATE,RP31A
RP31A	345UGV	66962	05/10/2024 FRIVANB	39 100417	BRIVAL01	INV-00020931	Filter Service Kit, Fridge Motor, SLX-400,RP31A
RP31A	345UGV	66962	05/10/2024 FRIVANB	39 Nov-99	BRIVAL01	INV-00020931	AIR FILTER HOUSING,RP31A
RP31A	345UGV	66962	05/10/2024 FRIVANB	39 78-1831	BRIVAL01	INV-00020931	GEN SLX Compressor Belt,RP31A
RP31A	345UGV	66962	05/10/2024 FRIVANB	39 LAB	BRIVAL01	INV-00020931	Labour,RP31A
RP31A	345UGV	67729	06/03/2024 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	67729	06/03/2024 DEFECT	DEFECT CLEARED.			
RP31A	345UGV	67729	06/03/2024 DEFECT	DEFECT CLEARED.			
RP31A	345UGV	67729	06/03/2024 TRA	1 LABOUR	APPREN	Labour	
RP31A	345UGV	67729	06/03/2024 TRA	'A' SERVICE COMPLETED BY TYLER & NICK ON 03.06.2024.			
RP31A	345UGV	67729	06/03/2024 TRA	0 LABOUR	MECH 1	Labour - Internal	
RP31A	345UGV	67729	06/03/2024 TRA	16 CON	YAT	Consumables	
				FRIDGE MOTOR CONDENS OR CLEAN COMPLET ED ON			
				AT LOCATION			
RP31A	345UGV	70663	06/05/2024 CONCLE	:			
RP31A	345UGV	70663	06/05/2024 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	70663	06/05/2024 DEFECT				

RP31A 345UGV 70663 06/05/2024 DEFECT DEFECT CLEARED.

TRAILER
SANITISAT
ION
COMPLET
ED ON
05/06/20
24

RP31A 345UGV 70663 06/05/2024 SANI : YATALA

RP31A	345UGV	67899	06/06/2024 GEN	15 99015526	BRI AUS01	EX00034657	RUNOUT TYRE,
RP31A	345UGV	67899	06/06/2024 GEN	15 33000084	BRI AUS01	EX00034657	FIT TBR TYRE,
RP31A	345UGV	67899	06/06/2024 GEN	15 33000517	BRI AUS01	EX00034657	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	67899	06/06/2024 GEN	15 33000118	BRI AUS01	EX00034657	SCHEDULED DEPOT SERVICE 15MIN,
RP31A	345UGV	67899	06/06/2024 GEN	15 99015526	BRI AUS01	1.89E+08	RUNOUT TYRE,
RP31A	345UGV	67899	06/06/2024 GEN	15 33000084	BRI AUS01	1.89E+08	FIT TBR TYRE,
RP31A	345UGV	67899	06/06/2024 GEN	15 33000517	BRI AUS01	1.89E+08	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	67899	06/06/2024 GEN	15 33000118	BRI AUS01	1.89E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP31A	345UGV	67899	06/06/2024 GEN	15 33000118	BRI AUS01	1.89E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP31A	345UGV	68063	06/07/2024 GEN	15 99015526	BRI AUS01	EX00034703	RUNOUT TYRE,
RP31A	345UGV	68063	06/07/2024 GEN	15 33000084	BRI AUS01	EX00034703	FIT TBR TYRE,
RP31A	345UGV	68063	06/07/2024 GEN	15 33000517	BRI AUS01	EX00034703	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	68063	06/07/2024 GEN	15 33000118	BRI AUS01	EX00034703	SCHEDULED DEPOT SERVICE 15MIN,
RP31A	345UGV	68063	06/07/2024 GEN	15 99015526	BRI AUS01	1.89E+08	RUNOUT TYRE,
RP31A	345UGV	68063	06/07/2024 GEN	15 33000084	BRI AUS01	1.89E+08	FIT TBR TYRE,
RP31A	345UGV	68063	06/07/2024 GEN	15 33000517	BRI AUS01	1.89E+08	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	68063	06/07/2024 GEN	15 33000118	BRI AUS01	1.89E+08	SCHEDULED DEPOT SERVICE 15MIN,

				AIR GAUGE: 13750 ADJUSTED : 14250 WEIGHBRI DGE: 14520
RP31A	345UGV	68234	06/14/2024 WEICAL	AIR GAUGE CALIBRATI ON COMPLET ED CORRECTL Y.
				TRAILER SANITISAT ION COMPLET ED ON 22/07/20 24
RP31A	345UGV	71571	07/22/2024 SANI	AT LOCATION : TULLY
				TRAILER WASH COMPLET ED ON 22/07/20 24
RP31A	345UGV	71572	07/22/2024 WASH	AT LOCATION : TULLY

RP31A	345UGV	69607	07/30/2024 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	69607	07/30/2024 DEFECT				
RP31A	345UGV	69607	07/30/2024 DEFECT	DEFECT CLEARED.			
				SERVICE COMPLET ED BY NQFM ON 30/07/20 24. INVOICE NO. 38154			
				CARRY OUT 'A' SERVICE AS PER SHEET REPLACE FRONT LHS BOTTOM LIGHT			
				NOTE: * FRONT AXLE AIRBAGS SLIGHTLY LEAKING -			
RP31A	345UGV	69607	07/30/2024 TRA				
RP31A	345UGV	69607	07/30/2024 TRA	1 LABEXT	RCCLOW01	EX00035525	CARRY OUT 'A' SERVICE AS PER SERVICE SHEET. REPLACE FRONT LHS B
RP31A	345UGV	69607	07/30/2024 TRA	14 PART	RCCLOW01	EX00035525	LED SIDE MARKER LIGHT,
RP31A	345UGV	69607	07/30/2024 TRA	16 GREASE	RCCLOW01	EX00035525	GREASE, Consumables
RP31A	345UGV	69607	07/30/2024 TRA	16 CON	RCCLOW01	EX00035525	,
RP31A	345UGV	69607	07/30/2024 TRA	16 ENVLEV	RCCLOW01	EX00035525	ENVIRONMENTAL LEVY,
RP31A	345UGV	69607	07/30/2024 TRA	1 LABEXT	RCCLOW01	38154	CARRY OUT 'A' SERVICE AS PER SERVICE SHEET. REPLACE FRONT LHS B

RP31A	345UGV	69607	07/30/2024 TRA	14 PART	RCCLW01	38154	LED SIDE MARKER LIGHT,
RP31A	345UGV	69607	07/30/2024 TRA	16 GREASE	RCCLW01	38154	GREASE,
RP31A	345UGV	69607	07/30/2024 TRA	16 CON	RCCLW01	38154	Consumables
RP31A	345UGV	69607	07/30/2024 TRA	16 ENVLEV	RCCLW01	38154	,
RP31A	345UGV	69964	07/30/2024 TRA	15 11002821	BRI AUS01	EX00035714	ENVIRONMENTAL LEVY,
RP31A	345UGV	69964	08/13/2024 TYRES	15 33000084	BRI AUS01	EX00035714	11R22.5 148/145L BS R119 ECO,
RP31A	345UGV	69964	08/13/2024 TYRES	15 33000371	BRI AUS01	EX00035714	FIT TBR TYRE,
RP31A	345UGV	69964	08/13/2024 TYRES	15 33000517	BRI AUS01	EX00035714	TYRE SENT FIR CAPPING,
RP31A	345UGV	69964	08/13/2024 TYRES	15 33000118	BRI AUS01	EX00035714	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	69964	08/13/2024 TYRES	15 11002821	BRI AUS01	1.89E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP31A	345UGV	69964	08/13/2024 TYRES	15 11002821	BRI AUS01	1.89E+08	11R22.5 148/145L BS R119 ECO,
RP31A	345UGV	69964	08/13/2024 TYRES	15 33000084	BRI AUS01	1.89E+08	FIT TBR TYRE,
RP31A	345UGV	69964	08/13/2024 TYRES	15 33000371	BRI AUS01	1.89E+08	TYRE SENT FIR CAPPING,
RP31A	345UGV	69964	08/13/2024 TYRES	15 33000517	BRI AUS01	1.89E+08	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	69964	08/13/2024 TYRES	15 33000118	BRI AUS01	1.89E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP31A	345UGV	70500	08/30/2024 DEFECT	1 LABOUR	MECH Labour		
RP31A	345UGV	70500	08/30/2024 DEFECT				
RP31A	345UGV	70500	08/30/2024 DEFECT	DEFECT CLEARED.			
RP31A	345UGV	70595	08/30/2024 FVGEN	39 CON	BRIVAL01	EX00036030	Consumables
RP31A	345UGV	70595	08/30/2024 FVGEN	39 91-4159	BRIVAL01	EX00036030	,RP31A
RP31A	345UGV	70595	08/30/2024 FVGEN	39 LAB	BRIVAL01	EX00036030	VIBRATION MOUNT,RP31A
RP31A	345UGV	70595	08/30/2024 FVGEN	Service completed by BVR 30/08/2024 - Travel to site and inspect unit for reported engine has lots of movement - Found worn front mount - Remove t			
RP31A	345UGV	70595	08/30/2024 FVGEN	39 CON	BRIVAL01	INV-00022652	Consumables
RP31A	345UGV	70595	08/30/2024 FVGEN	39 91-4159	BRIVAL01	INV-00022652	,RP31A
RP31A	345UGV	70595	08/30/2024 FVGEN	39 LAB	BRIVAL01	INV-00022652	VIBRATION MOUNT,RP31A
RP31A	345UGV	70500	08/30/2024 TRA	1 LABOUR	APPREN Labour		Labour,RP31A
RP31A	345UGV	70500	08/30/2024 TRA	'A' SERVICE COMPLETED BY TYLER & BEN ON 30/08/2024. LUBED ROLL BACK			
RP31A	345UGV	70500	08/30/2024 TRA	0 LABOUR	MECH 5	Labour - Internal	
RP31A	345UGV	70500	08/30/2024 TRA	16 CON	YAT	Consumables	

RP31A	345UGV	71268	09/17/2024 FVGEN	39 CON	BRIVAL01	EX00036319	Consumables ,RP31A
RP31A	345UGV	71268	09/17/2024 FVGEN	39 40-0974	BRIVAL01	EX00036319	GRADED SENSOR,RP31A
RP31A	345UGV	71268	09/17/2024 FVGEN	39 LAB	BRIVAL01	EX00036319	Labour,RP31A
RP31A	345UGV	71268	09/17/2024 FVGEN	Service completed by BVR 17/09/2024 - Travel to site and inspect unit for reported return air sensor alarm codes - Remove rear cage and panel - Remo			
RP31A	345UGV	71268	09/17/2024 FVGEN	39 CON	BRIVAL01	INV-00022908	Consumables ,RP31A
RP31A	345UGV	71268	09/17/2024 FVGEN	39 40-0974	BRIVAL01	INV-00022908	GRADED SENSOR,RP31A
RP31A	345UGV	71268	09/17/2024 FVGEN	39 LAB	BRIVAL01	INV-00022908	Labour,RP31A
				TRAILER SANITISAT ION COMPLET ED ON 23.09.202 4			
				AT LOCATION : TULLY			
RP31A	345UGV	72586	09/23/2024 SANI				
				TRAILER SANITISAT ION COMPLET ED ON 30.09.202 4			
				AT LOCATION : YATALA			
RP31A	345UGV	72639	09/30/2024 SANI				
RP31A	345UGV	72232	10/03/2024 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	72244	10/03/2024 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	72232	10/03/2024 DEFECT				
RP31A	345UGV	72244	10/03/2024 DEFECT				
RP31A	345UGV	72232	10/03/2024 DEFECT	DEFECT CLEARED.			
RP31A	345UGV	72244	10/03/2024 DEFECT	DEFECT CLEARED.			

				VEHICLE PASSED ANNUAL ROADWO RTHY INSPECTIO N. ATTEMPT # 1			
				INSPECTIO N COMPLET ED BY DIESEL SERVICES QLD ON 03/10/20 24 INVOICE NO. 00029812			
RP31A	345UGV	72244	10/03/2024 EXOINS	NO FAULTS IDENTIFIE D			
RP31A	345UGV	72244	10/03/2024 EXOINS	11 0980107040TSSC	YAT	KIT W/BRG & SEAL 10T ECO	
RP31A	345UGV	72244	10/03/2024 EXOINS	11 2.57E+08	YAT	Hub Seal Grease, BPW, Eco Plus	
RP31A	345UGV	72244	10/03/2024 EXOINS	19 FIREEXT2.5KG	YAT	2.5KG FIRE EXTINGUISHER	
RP31A	345UGV	72244	10/03/2024 EXOINS	1 LABEXT	DIESER01	EX00036595	C & D SERVICE WITH BEARINGS AND GREASE,
RP31A	345UGV	72244	10/03/2024 EXOINS	16 DEGREASER	DIESER01	EX00036595	DEGREASER,
RP31A	345UGV	72244	10/03/2024 EXOINS	16 CON	DIESER01	EX00036595	Consumables
RP31A	345UGV	72244	10/03/2024 EXOINS	1 LABEXT	DIESER01	29812	,
RP31A	345UGV	72244	10/03/2024 EXOINS	16 DEGREASER	DIESER01	29812	C & D SERVICE WITH BEARINGS AND GREASE,
RP31A	345UGV	72244	10/03/2024 EXOINS	16 DEGREASER	DIESER01	29812	DEGREASER,
RP31A	345UGV	72244	10/03/2024 EXOINS	16 CON	DIESER01	29812	Consumables
							,

RP31A	345UGV	72232	10/03/2024 TRA	1 LABOUR	MECH	Labour
RP31A	345UGV	72232	10/03/2024 TRA	SERVICE COMPLETED.		
RP31A	345UGV	72232	10/03/2024 TRB	1 LABOUR	MECH	Labour
RP31A	345UGV	72232	10/03/2024 TRB	SERVICE COMPLETED.		
				SERVICE COMPLET ED BY DIESEL SERVICES QLD ON 03/10/20 24. INVOICE NO. 00029812		
				C and D service with bearings and grease. Remove, replace all bearings and seals, clean and repack all hubs.		
RP31A	345UGV	72232	10/03/2024 TRC	Retention		

RP31A	345UGV	73518	11/14/2024 TYRES	15 11004117	BRI AUS01	EX00037256	11R22.5 148/145L FS FT469,
RP31A	345UGV	73518	11/14/2024 TYRES	15 33000084	BRI AUS01	EX00037256	FIT TBR TYRE,
RP31A	345UGV	73518	11/14/2024 TYRES	15 33000370	BRI AUS01	EX00037256	TYRE HELD FOR RUNOUT,
RP31A	345UGV	73518	11/14/2024 TYRES	15 33001507	BRI AUS01	EX00037256	CUSTOMER SCRAPPED OWN TYRE,
RP31A	345UGV	73518	11/14/2024 TYRES	15 33000531	BRI AUS01	EX00037256	REMOVAL: FLAT OR UNDER INFLATED,
RP31A	345UGV	73518	11/14/2024 TYRES	15 33000536	BRI AUS01	EX00037256	REMOVAL: MATCH OTD OR PATTERN,
RP31A	345UGV	73518	11/14/2024 TYRES	15 33000536	BRI AUS01	1.9E+08	REMOVAL: MATCH OTD OR PATTERN,
RP31A	345UGV	73518	11/14/2024 TYRES	15 33000531	BRI AUS01	1.9E+08	REMOVAL: FLAT OR UNDER INFLATED,
RP31A	345UGV	73518	11/14/2024 TYRES	15 33001507	BRI AUS01	1.9E+08	CUSTOMER SCRAPPED OWN TYRE,
RP31A	345UGV	73518	11/14/2024 TYRES	15 33000370	BRI AUS01	1.9E+08	TYRE HELD FOR RUNOUT,
RP31A	345UGV	73518	11/14/2024 TYRES	15 33000084	BRI AUS01	1.9E+08	FIT TBR TYRE,
RP31A	345UGV	73518	11/14/2024 TYRES	15 11004117	BRI AUS01	1.9E+08	11R22.5 148/145L FS FT469,

RP31A	345UGV	73708	11/26/2024 DEFECT	1 LABOUR	MECH	Labour
RP31A	345UGV	73708	11/26/2024 DEFECT			
RP31A	345UGV	73708	11/26/2024 DEFECT	DEFECT CLEARED.		
RP31A	345UGV	73708	11/26/2024 TRA	1 LABOUR	MECH 1	Labour

'A'
SERVICE
COMPLET
ED BY
NICK &
JOSEPH
(WORKSH
OP) ON
26/11/20
24.
REPLACED
EBS LEAD
WITH
SECOND
HAND
LEAD.

Fire Ext
Exp: Apr
2025

RP31A	345UGV	73708	11/26/2024 TRA
-------	--------	-------	----------------

RP31A	345UGV	73708	11/26/2024 TRA	0 LABOUR	APPRENJ	Labour - Internal	
RP31A	345UGV	73708	11/26/2024 TRA	16 CON		YAT	Consumables
RP31A	345UGV	74016	12/03/2024 TYRES	15	11002821	BRIAUS01	EX00037585
RP31A	345UGV	74016	12/03/2024 TYRES	15	77000232	BRIAUS01	EX00037585
RP31A	345UGV	74016	12/03/2024 TYRES	15	33000084	BRIAUS01	EX00037585
RP31A	345UGV	74016	12/03/2024 TYRES	15	33000517	BRIAUS01	EX00037585
RP31A	345UGV	74016	12/03/2024 TYRES	15	33000118	BRIAUS01	EX00037585
RP31A	345UGV	74016	12/03/2024 TYRES	15	11002821	BRIAUS01	1.9E+08
RP31A	345UGV	74016	12/03/2024 TYRES	15	77000232	BRIAUS01	1.9E+08
RP31A	345UGV	74016	12/03/2024 TYRES	15	33000084	BRIAUS01	1.9E+08
RP31A	345UGV	74016	12/03/2024 TYRES	15	33000517	BRIAUS01	1.9E+08
RP31A	345UGV	74016	12/03/2024 TYRES	15	33000118	BRIAUS01	1.9E+08
RP31A	345UGV	74512	01/06/2025 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	74512	01/06/2025 DEFECT				
RP31A	345UGV	74512	01/06/2025 DEFECT	DEFECT CLEARED.			
RP31A	345UGV	74512	01/06/2025 TRA	1 LABOUR	MECH 5	Labour	

				'A' SERVICE COMPLET ED BY BEN & JOSEPH (WORKSH OP) ON 06/01/20 25. REPLACED RED MARKER LIGHT ON REAR AT TOP					
RP31A	345UGV	74512	01/06/2025 TRA	F/E EXP : APRIL 2025					
RP31A	345UGV	74512	01/06/2025 TRA		0 LABOUR	APPRENJ	Labour - Internal		
RP31A	345UGV	74512	01/06/2025 TRA		16 CON		YAT Consumables		
RP31A	345UGV	74512	01/06/2025 TRA		14	91632	YAT LED Marker Light, Red. Narva		
				AIR GAUGE: 18840 ADJUSTED : 18540 WEIGHBRI DGE: 19000					
				AIR GAUGE CALIBRATI ON COMPLET ED CORRECTL Y.					
RP31A	345UGV	74906	01/12/2025 WEICAL						

AIR
GAUGE:
16420
ADJUSTED
: 16100
WEIGHBRI
DGE:
16600

AIR
GAUGE
CALIBRATI
ON
COMPLET
ED
CORRECTL
Y.

RP31A 345UGV 74961 01/17/2025 WEICAL

RP31A	345UGV	76154	03/05/2025 DEFECT	1 LABOUR	MECH	Labour
RP31A	345UGV	76154	03/05/2025 DEFECT	DEFECT CLEARED.		
RP31A	345UGV	76154	03/05/2025 TRA	1 LABOUR	APPRENJ	Labour - Internal

				COMPLET ED BY JOSEPH, JOSH & BEN (WORKSH OP) ON 05/03/20 25.			
				FIRE EXT EXP: APRIL 2025			
				ADJUSTED RIDE HEIGHT TO 370MM REPLACED LIGHT PLUG AT FRONT OF TRAILER AIR BAGS ARE NOT			
RP31A	345UGV	76154	03/05/2025 TRA				
RP31A	345UGV	76154	03/05/2025 TRA	16 CON	YAT	Consumables	
RP31A	345UGV	76154	03/05/2025 TRA	0 LABOUR	APPRENC	Labour - Internal	
RP31A	345UGV	76154	03/05/2025 TRA	0 LABOUR	MECH 5	Labour - Internal	
RP31A	345UGV	76154	03/05/2025 TRA	31 82062/1	YAT	7 PIN LGE ROUND METAL SKT	
RP31A	345UGV	76363	03/17/2025 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	76363	03/17/2025 DEFECT	DEFECT CLEARED.			
RP31A	345UGV	76363	03/17/2025 GEN	39 LABOUR	APPRENC	Labour	

				REPAIR COMPLET ED.BY WORKSH OP 17/03/20 25			
				REPLACE FEMALE LIGHT PLUG FRONT OF TRAIL			
RP31A	345UGV	76363	03/17/2025 GEN				
RP31A	345UGV	76363	03/17/2025 GEN	16 CON		YAT	Consumables
RP31A	345UGV	76363	03/17/2025 GEN	16 CON		YAT	Consumables
RP31A	345UGV	76445	03/20/2025 FRIVANB	0 LABOUR	MECH	Labour	
				VAN "B" SERVICE COMPLET ED.			
				FRIDGE VAN UNIT CALIBRAT ED @ SERVICE.			
				SERVICE COMPLET ED BY BVR.			
				OIL 14L (Customer Supplied) CALIBRATI ON CERTIFICA TE R+R ENGINE OIL R+R			
RP31A	345UGV	76445	03/20/2025 FRIVANB				

RP31A	345UGV	76445	03/20/2025 FRIVANB	39 100417-A500	ICEGRO01	EX00038984	FILTER KIT A500,RP31A
RP31A	345UGV	76445	03/20/2025 FRIVANB	39 904466	ICEGRO01	EX00038984	EXPANSION TANK COVER - SLX,RP31A
RP31A	345UGV	76445	03/20/2025 FRIVANB	39 CC	ICEGRO01	EX00038984	CALIBRATION CETIFICATE,RP31A
RP31A	345UGV	76445	03/20/2025 FRIVANB	39 CON	ICEGRO01	EX00038984	Consumables ,RP31A
RP31A	345UGV	76445	03/20/2025 FRIVANB	39 LAB	ICEGRO01	EX00038984	Labour,RP31A
RP31A	345UGV	76445	03/20/2025 FRIVANB	40 3413005	YAT OIL 15W-40, CK 4/E9		
RP31A	345UGV	76445	03/20/2025 FRIVANB	Service completed by Iceman 17/03/2025 - Carried out B Service as per Iceman Specifications - Installed expansion tank cover - Ran unit and rechecked			
RP31A	345UGV	76445	03/20/2025 FRIVANB	39 100417-A500	ICEGRO01	899147	FILTER KIT A500,RP31A
RP31A	345UGV	76445	03/20/2025 FRIVANB	39 904466	ICEGRO01	899147	EXPANSION TANK COVER - SLX,RP31A
RP31A	345UGV	76445	03/20/2025 FRIVANB	39 CC	ICEGRO01	899147	CALIBRATION CETIFICATE,RP31A
RP31A	345UGV	76445	03/20/2025 FRIVANB	39 CON	ICEGRO01	899147	Consumables ,RP31A
RP31A	345UGV	76445	03/20/2025 FRIVANB	39 LAB	ICEGRO01	899147	Labour,RP31A
RP31A	345UGV	76445	03/20/2025 FRIVCAL	1 LABOUR MECH	Labour		
RP31A	345UGV	76445	03/20/2025 FRIVCAL	FRIDGE VAN CALIBRATION COMPLETED			
RP31A	345UGV	77027	04/03/2025 FVGEN	39 CON	ICEGRO01	EX00039394	Consumables ,RP31A
RP31A	345UGV	77027	04/03/2025 FVGEN	39 33-2314-10	ICEGRO01	EX00039394	EXHAUST FLANGE GASKET - SE,RP31A
RP31A	345UGV	77027	04/03/2025 FVGEN	39 LAB	ICEGRO01	EX00039394	Labour,RP31A
RP31A	345UGV	77027	04/03/2025 FVGEN	39 130939	ICEGRO01	EX00039394	FLEXIBLE EXHUAUST TUBE,RP31A
RP31A	345UGV	77027	04/03/2025 FVGEN	Service completed by Iceman 03/04/2025 - Inspected unit - Found exhaust flex leaking - Removed fan panel - Cut and removed exhaust flange bolts - R			

RP31A	345UGV	77027	04/03/2025 FVGEN	39	130939	ICEGRO01	900537	FLEXIBLE EXHUAUST TUBE,RP31A
RP31A	345UGV	77027	04/03/2025 FVGEN	39	LAB	ICEGRO01	900537	Labour,RP31A
RP31A	345UGV	77027	04/03/2025 FVGEN	39	33-2314-10	ICEGRO01	900537	EXHAUST FLANGE GASKET - SE,RP31A
RP31A	345UGV	77027	04/03/2025 FVGEN	39	CON	ICEGRO01	900537	Consumables ,RP31A
RP31A	345UGV	77016	04/11/2025 DEFECT	1	LABOUR	MECH	Labour	
RP31A	345UGV	77016	04/11/2025 DEFECT	DEFECT CLEARED.				
RP31A	345UGV	77016	04/11/2025 TRA	1	LABOUR	MECH	Labour - Internal	
				A SERVICE COMPLET ED.				
RP31A	345UGV	77016	04/11/2025 TRA	FIRE EXT EXP:				
RP31A	345UGV	77016	04/11/2025 TRA	16	CON	YAT	Consumables	
RP31A	345UGV	77016	04/11/2025 TRB	1	LABOUR	APPRENJC	Labour - Internal	

				COMPLET ED BY WORKSH OP 11/04/20 25
				FIRE EXT EXP: JUN 25
				REPLACE ECO PLUS HUB CAP AND POSITION N 6 HUB REPLACE BRAKE HOSE POSITION 4 REPLACE 3X MARKER LIGHTS REPLACE
RP31A	345UGV	77016	04/11/2025 TRB	

RP31A	345UGV	77016	04/11/2025 TRB	16 CON	YAT	Consumables	
RP31A	345UGV	77016	04/11/2025 TRB	0 LABOUR MECH 1	3	105 315	
RP31A	345UGV	77016	04/11/2025 TRB	16 0321225310C	YAT	HCAP CHROME 136x2.5 E/PLUS	
RP31A	345UGV	77016	04/11/2025 TRB	16 91700BL	YAT	Clearance Light, LED Amber, Narva	
RP31A	345UGV	77016	04/11/2025 TRB	16 91622	YAT	LED Marker light. Amber. Narva	
RP31A	345UGV	77016	04/11/2025 TRB	16 91632	YAT	LED Marker Light, Red. Narva	
RP31A	345UGV	77016	04/11/2025 TRB	16 82245BL	YAT	7 PIN FLT TO 7 PIN LRG RND	
RP31A	345UGV	77261	04/23/2025 TYRES	15 11002821	BRIAUS01	EX00039557	11R22.5 148/145L BS R119 ECO,
RP31A	345UGV	77261	04/23/2025 TYRES	15 99015526	BRIAUS01	EX00039557	RUNOUT TYRE,
RP31A	345UGV	77261	04/23/2025 TYRES	15 77000232	BRIAUS01	EX00039557	CASE STOCK 11R22.5 ECOPIA,
RP31A	345UGV	77261	04/23/2025 TYRES	15 33000084	BRIAUS01	EX00039557	FIT TBR TYRE,
RP31A	345UGV	77261	04/23/2025 TYRES	15 33000517	BRIAUS01	EX00039557	REMOVAL: CUSTOMER PULL POINT,
RP31A	345UGV	77261	04/23/2025 TYRES	15 33000118	BRIAUS01	EX00039557	SCHEDULED DEPOT SERVICE 15MIN,
RP31A	345UGV	77261	04/23/2025 TYRES	15 33000118	BRIAUS01	1.91E+08	SCHEDULED DEPOT SERVICE 15MIN,

RP31A	345UGV	77261	04/23/2025 TYRES	15	33000517	BRIAUS01	1.91E+08	REMOVAL: CUSTOMER PULL POINT, FIT TBR TYRE, CASE STOCK 11R22.5 ECOPIA, RUNOUT TYRE, 11R22.5 148/145L BS R119 ECO,
RP31A	345UGV	77261	04/23/2025 TYRES	15	33000084	BRIAUS01	1.91E+08	
RP31A	345UGV	77261	04/23/2025 TYRES	15	77000232	BRIAUS01	1.91E+08	
RP31A	345UGV	77261	04/23/2025 TYRES	15	99015526	BRIAUS01	1.91E+08	
RP31A	345UGV	77261	04/23/2025 TYRES	15	11002821	BRIAUS01	1.91E+08	
RP31A	345UGV	78266	06/02/2025 DEFECT	1	LABOUR	MECH	Labour	
RP31A	345UGV	78266	06/02/2025 DEFECT	DEFECT CLEARED.				
RP31A	345UGV	78266	06/02/2025 GEN	39	LABOUR	APPRENJ	Labour	
				REPAIR COMPLET ED BY WORKSH OP 02.06.202 5				
				REPLACED SHORT TAIL AIR LINES				
RP31A	345UGV	78266	06/02/2025 GEN					
RP31A	345UGV	78266	06/02/2025 GEN	16	CON	YAT	Consumables	
RP31A	345UGV	78266	06/02/2025 GEN	16	61-SC3MTSTSET	YAT	Suzi Coil Short	
RP31A	345UGV	78215	06/03/2025 DEFECT	1	LABOUR	MECH	Labour	
RP31A	345UGV	78215	06/03/2025 DEFECT	DEFECT CLEARED.				
RP31A	345UGV	78215	06/03/2025 TRA	1	LABOUR	MECH 5	Labour - Internal	
				A SERVICE COMPLET ED BY WORKSH OP 03/06/20 25				
				FIRE EXT EXP: DECEMBE R 2025				
				REPLACED 2.5KG FIRE EXT				
RP31A	345UGV	78215	06/03/2025 TRA					

RP31A	345UGV	78215	06/03/2025 TRA	16 CON	YAT	Consumables
RP31A	345UGV	78215	06/03/2025 TRA	19 FIREEXT2.5KG	YAT	2.5KG FIRE EXTINGUISHER
RP31A	345UGV	79186	07/10/2025 DEFECT	1 LABOUR MECH	Labour	
RP31A	345UGV	79186	07/10/2025 DEFECT	DEFECT CLEARED.		
				Defect :-		
				Defect		
				Code :		
				00014045		
				Defect		
				Reference		
				: RP31A		
				Date :		
				16/04/20		
				25		
				Description of		
				Defect :		
				DISPLAYING A		
				DIGITAL		
				READOUT		
				LINK		
				FAULT -		
				DOES NOT		
				SHOW		
				ANY		
				REEFER		
				TEMPS		
				WHEN		
				VIEWED		
RP31A	345UGV	79186	07/10/2025 DEFECT	REMOTEL		

RP31A	345UGV	79186	07/10/2025 TRA
-------	--------	-------	----------------

				COMPLET ED BY WORKSH OP 10.07.202 5			
				FIRE EXT EXP: DECEMBE R 2025			
				WONT BE ABLE TO SEE TEMPS REMOTEL Y DUE TO IT BEING A OLDER FRIDGE COULDNT FAULT DOOR BEEN FIXED IN PRIOR			
RP31A	345UGV	79186	07/10/2025 TRA				
RP31A	345UGV	79186	07/10/2025 TRA	16 CON		YAT	Consumables
RP31A	345UGV	80486	09/02/2025 DEFECT	1 LABOUR	MECH	Labour	
RP31A	345UGV	80486	09/02/2025 DEFECT	DEFECT CLEARED.			

RP31A	345UGV	80486	09/02/2025 DEFECT	Defect :- Defect Code : 00014873 Defect Reference : 11570 Date : 07/08/20 25 Descriptio n of Defect : PASSENGE R SIDE BARN DOOR LOCKING SHAFT IS BENT AND NEEDS TO BE STAIGHTE NED BEFORE THE TOP OF THE		
RP31A	345UGV	80486	09/02/2025 TRA	1 LABOUR	MECH 1	Labour - Internal

				COMPLET ED BY WORKSH OP 02/09/20 25			
				FIRE EXT EXP: DECEMBE R 2025			
				REPLACE 1 X AIR LINE TO BOOSTER AT POSITION 4			
				DEFECT - 11570/14 873 - STRAIGHT EN REAR DOOR LOCKING			
RP31A	345UGV	80486	09/02/2025 TRA				
RP31A	345UGV	80486	09/02/2025 TRA	16 CON	YAT	Consumables	
RP31A	345UGV	80486	09/02/2025 TRA	0 LABOUR	APPREND	Labour - Internal	
RP31A	345UGV	81242	10/02/2025 EXOINS	1 LABOUR	APPREN	Labour	

				VEHICLE PASSED ANNUAL ROADWO RTHY INSPECTIO N. ATTEMPT #1			
				INSPECTIO N COMPLET ED BY WORKSH OP 02/10/20 25			
				FIRE EXT EXP - DECEMBE R 2025			
RP31A	345UGV	81242	10/02/2025 EXOINS	DEFECTS IDENTIFIE D - NONE			
RP31A	345UGV	81242	10/02/2025 EXOINS	0 LABOUR	MECH 5	Labour - Internal	
RP31A	345UGV	81241	10/02/2025 TRA	1 LABOUR	MECH	Labour - Internal	
				A SERVICE COMPLET ED.			
RP31A	345UGV	81241	10/02/2025 TRA	FIRE EXT EXP:			
RP31A	345UGV	81241	10/02/2025 TRA	16 CON		YAT	Consumables
RP31A	345UGV	81241	10/02/2025 TRB	1 LABOUR	MECH	Labour - Internal	

				B SERVICE COMPLET ED.			
RP31A	345UGV	81241	10/02/2025 TRB	FIRE EXT EXP:			
RP31A	345UGV	81241	10/02/2025 TRB	16 CON		YAT	Consumables
RP31A	345UGV	81241	10/02/2025 TRC	1 LABOUR	MECH 5	Labour	
				C SERVICE COMPLET ED BY WORKSH OP 02/10/20 25			
				FIRE EXT EXP: DECEMBE R 2025			
				REPLACED LHR GUARD REPAIRED BRACKETS REPLACED REFLECTO R SIGN			
RP31A	345UGV	81241	10/02/2025 TRC				
RP31A	345UGV	81241	10/02/2025 TRC	16 CON		YAT	Consumables
RP31A	345UGV	81241	10/02/2025 TRC	0 LABOUR	APPREN	Labour - Internal	
RP31A	345UGV	81241	10/02/2025 TRC	0 LABOUR	APPRENJC	Labour - Internal	
RP31A	345UGV	81241	10/02/2025 TRC	0 LABOUR	APPREND	Labour - Internal	
RP31A	345UGV	82000	10/22/2025 FRIVANB	0 LABOUR	MECH	Labour	

RP31A	345UGV	82000	10/22/2025 FRIVANB	VAN "B" SERVICE COMPLET ED. FRIDGE VAN UNIT CALIBRAT ED @ SERVICE. SERVICE COMPLET ED BY ICEMAN OIL 14L (Customer Supplied) CALIBRATI ON CERTIFICA TE R+R ENGINE OIL R+R
-------	--------	-------	--------------------	---

RP31A	345UGV	82000	10/22/2025 FRIVANB	39 CON	ICEGRO01	EX00042765	Consumables ,RP31A
RP31A	345UGV	82000	10/22/2025 FRIVANB	39 CC	ICEGRO01	EX00042765	CALIBRATION CETIFICATE,RP31A
RP31A	345UGV	82000	10/22/2025 FRIVANB	39 100417	ICEGRO01	EX00042765	Filter Service Kit, Fridge Motor, SLX-400,RP31A
RP31A	345UGV	82000	10/22/2025 FRIVANB	39 41-1566-10	ICEGRO01	EX00042765	SOLENOID - COMPLETE,RP31A
RP31A	345UGV	82000	10/22/2025 FRIVANB	39 935846	ICEGRO01	EX00042765	SLX BELT GUARD - METAL,RP31A
RP31A	345UGV	82000	10/22/2025 FRIVANB	39 91-8972-10	ICEGRO01	EX00042765	SLX ISOLATOR SNUBBER,RP31A
RP31A	345UGV	82000	10/22/2025 FRIVANB	39 LAB	ICEGRO01	EX00042765	Labour,RP31A
RP31A	345UGV	82000	10/22/2025 FRIVANB	40 3413005	YAT OIL 15W-40, CK 4/E9		
RP31A	345UGV	82000	10/22/2025 FRIVANB	SERVICE COMPLETED BY ICEMAN 22/10/2025 - CARRIED OUT "B" SERVICE AS PER ICEMAN SPECIFICATIONS - REPLACED U/S HIGH SPEED SOLENOID - RE			
RP31A	345UGV	82000	10/22/2025 FRIVANB	39 CON	ICEGRO01	913172	Consumables ,RP31A
RP31A	345UGV	82000	10/22/2025 FRIVANB	39 CC	ICEGRO01	913172	CALIBRATION CETIFICATE,RP31A
RP31A	345UGV	82000	10/22/2025 FRIVANB	39 100417	ICEGRO01	913172	Filter Service Kit, Fridge Motor, SLX-400,RP31A
RP31A	345UGV	82000	10/22/2025 FRIVANB	39 41-1566-10	ICEGRO01	913172	SOLENOID - COMPLETE,RP31A
RP31A	345UGV	82000	10/22/2025 FRIVANB	39 935846	ICEGRO01	913172	SLX BELT GUARD - METAL,RP31A
RP31A	345UGV	82000	10/22/2025 FRIVANB	39 91-8972-10	ICEGRO01	913172	SLX ISOLATOR SNUBBER,RP31A
RP31A	345UGV	82000	10/22/2025 FRIVANB	39 LAB	ICEGRO01	913172	Labour,RP31A
RP31A	345UGV	82000	10/22/2025 FRIVCAL	1 LABOUR MECH	Labour		
RP31A	345UGV	82000	10/22/2025 FRIVCAL	FRIDGE VAN CALIBRATION COMPLETED			
Total for Asset				88,728.60			
Total for Report				88,728.60			

Options:
Sort By
-
AssetCode
Starting
Asset
Code -
RP31A
To
- RP31A
Starting
Registrati
on -
To
-
Starting
Operation
s No -
To
-
From:
Work
Order
Location -
To
-
From:

CAL PLUG),RP3

CAL PLUG),RP3

arness for return air sensor - Unit run on t

IMI not turning "configuring" - Grease all controller plugs and HMI plug - Test operation, still not operational - Source part and return to site to fit new HMI - Test operation - Unit run on ti

it down to 0o - Check gas level again, ok - Unit cooling well, clear code - Unit run on t

e worn water pump belt and speed solenoid - Unit run on t

Replace worn bearings - Refit cross shaft - Fit oil drain valve - Replace u/s idler pulleys - Unit run on t

IM CUSTOMER'S OWN STC

IM CUSTOMER'S OWN STC

D BRACI

VT RI

VT RI

D BRAC

adings - Found control return reading 1c lower then display return - Adjust sensor grading to suit - Unit run on t

Split comp from engine - Remove and replace worn compressor belt - Refit comp to engine - Top up 1L coolant - Unit run on t

S BOTTOM LIGI

S BOTTOM LIGI

ve belly pan - Remove and replace worn front mount as required - Refit belly pan - Unit run on t

move and replace u/s return air sensors - Calibrate sensors - Refit rear panel and cage - Unit run on t

ked operatic

- Removed exhaust clamp and exhaust - Cleaned flange surface - Installed new exhaust flex with new gasket as required - Replaced bolts - Refitted fan panel - Checked operation - Unit ran on ti

- REPLACED U/S SNUBBER MOUNT - REPLACED U/S BELT GUARD - REPLACED MISSING FAN PANEL RIVNUTS AND BOLTS - RAN UNIT AND RECHECKED OPERATIO