

W/O No	Asset No	Asset Description	Description	Job Type	Finished Date/Time	Downtime	Repair Time	Component Code	Department	Parent Asset	Labour Costs	Material Costs	Other Costs
544	C311	Mack Granite Day Cab - 6x4 - 4:	A Service SCR Prime Mover. A Service was completed. Breakdown @ Eagle Farm Cause; Noise in Brakes. W/Shop attended inspected brakes, removed	PM	12/04/2016		2		Hemmant	Brisbane Single & Loca	0	38.22	0
569	C311	Mack Granite Day Cab - 6x4 - 4:	backing co ...	Break	12/09/2016		2	2	Hemmant	Brisbane Single & Loca	0	0	0
672	C311	Mack Granite Day Cab - 6x4 - 4:	B Service - Mack Granites A Service - Trucks	PM	01/21/2017		4.5	4.5	Hemmant	Brisbane Single & Loca	0	648.79	0
1096	C311	Mack Granite Day Cab - 6x4 - 4:	A Service was completed.	PM	03/24/2017		2	2	Hemmant	Brisbane Single & Loca	0	166.41	0
1154	C311	Mack Granite Day Cab - 6x4 - 4:	A Service - Trucks & Inspect Water Pump Housing A service was completed.	PM	05/05/2017		8	7	Hemmant	Brisbane Single & Loca	0	526.41	0
1254	C311	Mack Granite Day Cab - 6x4 - 4:	A Service - Trucks A Service was completed.	PM	06/19/2017		2	2	Hemmant	Brisbane Single & Loca	0	349.6	0
1357	C311	Mack Granite Day Cab - 6x4 - 4:	A Service - Trucks A Service was completed. Replaced header tank cap, tensioned front diff pinion	PM	08/05/2017		2	2	Hemmant	Brisbane Single & Loca	0	304.6	0
1417	C311	Mack Granite Day Cab - 6x4 - 4:	B Service - Mack MP8 and MP10 A Service was completed.	PM	09/06/2017		3	3	Hemmant	Brisbane Single & Loca	0	939.55	0
1572	C311	Mack Granite Day Cab - 6x4 - 4:	A Service. Service Cancelled. Wrong Vehicle Entered in System C Service - Mack MP8 and MP10 C Service Completed	PM	03/01/2018		0	0	Hemmant	Brisbane Single & Loca	0	152.76	0
2008	C311	Mack Granite Day Cab - 6x4 - 4:	Actual KMS 481,035 TRUCK ADBLUE- A Service-10,000KMS A Service Completed	PM	02/12/2018		0	0 servicing	Hemmant	Brisbane Single & Loca	195	1801.35	0
2240	C311	Mack Granite Day Cab - 6x4 - 4:	Actual KMS 490,911 TRUCK ADBLUE- A Service-10,000KMS A Service Complete	PM	03/17/2018		0	0	Hemmant	Brisbane Single & Loca	97.5	87.1	0
2241	C311	Mack Granite Day Cab - 6x4 - 4:	Actual KMS 499,899 TRUCK ADBLUE- A Service-10,000KMS A Service completed	PM	04/16/2018		0	0	Hemmant	Brisbane Single & Loca	97.5	87.1	0
2342	C311	Mack Granite Day Cab - 6x4 - 4:	Actual 515357kms TRUCK ADBLUE- B Service- 40,000KMS B Service completed	PM	05/29/2018		0	0	Hemmant	Brisbane Single & Loca	97.5	87.1	0
2447	C311	Mack Granite Day Cab - 6x4 - 4:	Actual 524878kms TRUCK ADBLUE- B Service- 40,000KMS B Service completed	PM	06/30/2018		0	0	Hemmant	Brisbane Single & Loca	157.5	948.55	0
2469	C311	Mack Granite Day Cab - 6x4 - 4:	Actual 524878kms TRUCK ADBLUE- A Service-10,000KMS A Service completed	PM	06/30/2018		0	0	Hemmant	Brisbane Single & Loca	0	948.55	0
2574	C311	Mack Granite Day Cab - 6x4 - 4:	Actual 531165kms TRUCK ADBLUE- A Service-10,000KMS A Service completed	PM	07/27/2018		0	0	Hemmant	Brisbane Single & Loca	52.5	87.1	0
2671	C311	Mack Granite Day Cab - 6x4 - 4:	Actual 538254kms TRUCK ADBLUE- B Service- 40,000KMS B Service completed	PM	08/27/2018		0	0	Hemmant	Brisbane Single & Loca	52.5	87.1	0
3397	C311	Mack Granite Day Cab - 6x4 - 4:	Actual 540270kms TRUCK ADBLUE & EGR- D Service - 12 Monthly D Service completed	PM	09/07/2018		0	0	Hemmant	Brisbane Single & Loca	292.5	948.55	0
3398	C311	Mack Granite Day Cab - 6x4 - 4:	Actual 540270kms TRUCK ADBLUE- A Service-10,000KMS A Service completed	PM	09/07/2018		0	0	Hemmant	Brisbane Single & Loca	260	145.26	0
3528	C311	Mack Granite Day Cab - 6x4 - 4:	Actual 554066kms TRUCK ADBLUE- A Service-10,000KMS A Service Completed	PM	10/17/2018		0	0	Hemmant	Brisbane Single & Loca	52.5	87.1	0
3670	C311	Mack Granite Day Cab - 6x4 - 4:	Actual 565815kms Standard Order	PM	12/05/2018		0	0	Hemmant	Brisbane Single & Loca	52.5	108.3	0
3693	C311	Mack Granite Day Cab - 6x4 - 4:	Repair Steering adjuster Standard Order	R & M	11/27/2018		0	0	Hemmant	Brisbane Single & Loca	17.5	0	0
4005	C311	Mack Granite Day Cab - 6x4 - 4:	Gas Strut	R & M	12/15/2018		0	0	Hemmant	Brisbane Single & Loca	52.5	87.43	0
4026	C311	Mack Granite Day Cab - 6x4 - 4:	Standard Order	R & M	12/15/2018		0	0	Hemmant	Brisbane Single & Loca	162.5	46.99	0
4077	C311	Mack Granite Day Cab - 6x4 - 4:	Battery and Indicator Stalk	R & M	12/19/2018		0	0	Hemmant	Brisbane Single & Loca	65	298.62	0
4081	C311	Mack Granite Day Cab - 6x4 - 4:	Breakdown	R & M	01/19/2018		0	0	Hemmant	Brisbane Single & Loca	65	0	0

4100 C311	Mack Granite Day Cab - 6x4 - 4:Standard Order		01/02/2019	0	0	Hemmant	Brisbane Single & Loca	0	0	0
4115 C311	Mack Granite Day Cab - 6x4 - 4:Indicator Bulb, 2 way radio C Service -90,000KMS C Service Completed.	R & M	12/20/2018	0	0	Hemmant	Brisbane Single & Loca	48.75	5.32	0
4177 C311	Mack Granite Day Cab - 6x4 - 4:Actual KMS: 570823 New Steer Tyres Fitted to Vehicle Note - 2 Conti Steers worn. Replaced with to new,	PM	12/31/2018	0	0	Hemmant	Brisbane Single & Loca	437.5	2165.58	0
4214 C311	Mack Granite Day Cab - 6x4 - 4:Old steers to ...	PM	01/02/2019	0	0	Hemmant	Brisbane Single & Loca	35	0	0
4259 C311	Mack Granite Day Cab - 6x4 - 4:2 x new conti HSR 295/80 steer tyres fitted	R & M	01/02/2019	0	0	Hemmant	Brisbane Single & Loca	35	0	0
4328 C311	Mack Granite Day Cab - 6x4 - 4:Left side Indicator	R & M	01/10/2019	0	0	Hemmant	Brisbane Single & Loca	32.5	0	0
4555 C311	Mack Granite Day Cab - 6x4 - 4:Cabin Filter	R & M	01/23/2019	0	0	Hemmant	Brisbane Single & Loca	65	46.64	0
4589 C311	Mack Granite Day Cab - 6x4 - 4:Break Down	Break	01/30/2019	0	0	Hemmant	Brisbane Single & Loca	958.75	0	0
4660 C311	Mack Granite Day Cab - 6x4 - 4:Faulty valve and indicator	R & M	01/31/2019	0	0	Hemmant	Brisbane Single & Loca	32.5	0	0
4691 C311	Mack Granite Day Cab - 6x4 - 4:Twistlocks	R & M	02/01/2019	0	0	Hemmant	Brisbane Single & Loca	130	0	0
4729 C311	Mack Granite Day Cab - 6x4 - 4:Replace mudguard TRUCK ADBLUE- A Service-10,000KMS A Service Completed	R & M	02/05/2019	0	0	Hemmant	Brisbane Single & Loca	130	70.09	0
4747 C311	Mack Granite Day Cab - 6x4 - 4:Actual 580449 km	PM	01/24/2019	0	0	Hemmant	Brisbane Single & Loca	195	74	0
4837 C311	Mack Granite Day Cab - 6x4 - 4:Wiper blades, Parker bulb and high idle from lifter.	R & M	02/12/2019	0	0	Hemmant	Brisbane Single & Loca	65	0	0
4920 C311	Mack Granite Day Cab - 6x4 - 4:Swap trucks around and fit PTO lines & air lines. TRUCK ADBLUE- A Service-10,000KMS A Service Completed Actual 594345kms	R & M	02/16/2019	0	0	Hemmant	Brisbane Single & Loca	65	0	0
5104 C311	Mack Granite Day Cab - 6x4 - 4:Fix Air leak Inspect tail light assembly, found to be hanging off	PM	02/27/2019	0	0	Hemmant	Brisbane Single & Loca	130	74	0
5271 C311	Mack Granite Day Cab - 6x4 - 4:zip tie tied into place will need to order new ... Get jumper leads & robbie truck, jump start vehicle,	R & M	03/07/2019	0	0	Hemmant	Brisbane Single & Loca	32.5	0	0
5490 C311	Mack Granite Day Cab - 6x4 - 4:check charge rates TRUCK ADBLUE- B Service- 60,000KMS B Service Completed	R & M	03/22/2019	0	0	Hemmant	Brisbane Single & Loca	32.5	0	0
5546 C311	Mack Granite Day Cab - 6x4 - 4:Actual 604883kms Look over found "U" bolts ... Had a slow start occurrence. Found U/S battery	PM	03/26/2019	0	0	Hemmant	Brisbane Single & Loca	390	309.22	0
5632 C311	Mack Granite Day Cab - 6x4 - 4:terminal, remove all leads, load test batteries, batt ...	R & M	04/01/2019	0	0	Hemmant	Brisbane Single & Loca	81.25	31.44	0
5649 C311	Mack Granite Day Cab - 6x4 - 4:Replace RH/Front headlight Change Tyres - 2 Sempreit Trans steels POS 7-8 on	R & M	04/02/2019	0	0	Hemmant	Brisbane Single & Loca	32.5	0	0
5926 C311	Mack Granite Day Cab - 6x4 - 4:Drive. TRUCK ADBLUE- A Service-10,000KMS A Service Completed Actual 614954kms	Tyre - S/S	04/23/2019	0	0	Hemmant	Brisbane Single & Loca	105	840	0
5967 C311	Mack Granite Day Cab - 6x4 - 4:Remove and replace left room ... Damage to front DG Sign. Bend loops back in shape	PM	04/23/2019	0	0	Hemmant	Brisbane Single & Loca	260	125.07	0
5973 C311	Mack Granite Day Cab - 6x4 - 4:so signs will turn. Inspect hydraulic oil lerak found x2 hoses to be rubbed through spoke to Pirtek they come out and d	R & M	04/26/2019	0	0	Hemmant	Brisbane Single & Loca	16.25	0	0
6008 C311	Mack Granite Day Cab - 6x4 - 4:...	R & M	04/29/2019	0	0	Hemmant	Brisbane Single & Loca	32.5	0	0
6044 C311	Mack Granite Day Cab - 6x4 - 4:hydraulic hoses. Pickup fitting from Pirtek. Fit corr ... Locate oil leak from cuppling, unhook truck &	R & M	05/01/2019	0	0	Hemmant	Brisbane Single & Loca	97.5	0	0
6166 C311	Mack Granite Day Cab - 6x4 - 4:Laptop. Exhaust back pressure. May need burn ...	R & M	05/09/2019	0	0	Hemmant	Brisbane Single & Loca	17.5	25	0
6181 C311	Mack Granite Day Cab - 6x4 - 4:Top up coolant	R & M	05/09/2019	0	0	Hemmant	Brisbane Single & Loca	32.5	0	0
6186 C311	Mack Granite Day Cab - 6x4 - 4:Testy lifter park up	R & M	05/11/2019	0	0	Hemmant	Brisbane Single & Loca	17.5	0	0
6194 C311	Mack Granite Day Cab - 6x4 - 4:lifter, Found hose not connected properly toppe ...	R & M	05/10/2019	0	0	Hemmant	Brisbane Single & Loca	130	0	0
6226 C311	Mack Granite Day Cab - 6x4 - 4:Move truck up front out of the way	R & M	05/13/2019	0	0	Hemmant	Brisbane Single & Loca	17.5	0	0
6244 C311	Mack Granite Day Cab - 6x4 - 4:Repair hydraulic leak.	R & M	05/14/2019	0	0	Hemmant	Brisbane Single & Loca	65	0	0
6250 C311	Mack Granite Day Cab - 6x4 - 4:trailer separating from truck to gain hydraulic lin ... Indicators working intermittantly, Replace change	R & M	05/14/2019	0	0	Hemmant	Brisbane Single & Loca	65	0	0
6280 C311	Mack Granite Day Cab - 6x4 - 4:over relays & flasher relay.	R & M	05/16/2019	0	0	Hemmant	Brisbane Single & Loca	65	0	0

6342	C311	Mack Granite Day Cab - 6x4 - 4:Repair electrical fault with front head light globe.	R & M	05/21/2019	0	0	Hemmant	Brisbane Single & Loca	32.5	18.56	0
6382	C311	Mack Granite Day Cab - 6x4 - 4:Repair DG Sign	R & M	05/22/2019	0	0	Hemmant	Brisbane Single & Loca	32.5	0	0
TRUCK ADBLUE- A Service-10,000KMS A Service Completed											
6392	C311	Mack Granite Day Cab - 6x4 - 4:Actual 625272kms. Repair short on drivers sid ...	PM	05/22/2019	0	0	Hemmant	Brisbane Single & Loca	260	74	0
6443	C311	Mack Granite Day Cab - 6x4 - 4:Replace 2 x headlight globes	R & M	05/27/2019	0	0	Hemmant	Brisbane Single & Loca	32.5	23.77	0
Replaced lights. went to gibbs for lights and candy											
6470	C311	Mack Granite Day Cab - 6x4 - 4:strips.	R & M	05/27/2019	0	0	Hemmant	Brisbane Single & Loca	43.75	0	0
Drive out to Breakdown. Inspect driving issue with											
6532	C311	Mack Granite Day Cab - 6x4 - 4:selections on touch pad and gearbox.	R & M	05/29/2019	0	0	Hemmant	Brisbane Single & Loca	227.5	0	0
Truck would get struck in gear or not select neutral.											
6533	C311	Mack Granite Day Cab - 6x4 - 4:Visual check of transmission oil, connectors, ...	R & M	05/30/2019	0	0	Hemmant	Brisbane Single & Loca	16.25	0	0
Pull out trans/Control Box. Repair it put back in and											
6546	C311	Mack Granite Day Cab - 6x4 - 4:tested OK.	R & M	05/30/2019	0	0	Hemmant	Brisbane Single & Loca	65	0	0
6562	C311	Mack Granite Day Cab - 6x4 - 4:R/R starter motor.	R & M	05/31/2019	0	0	Hemmant	Brisbane Single & Loca	100	0	0
Transmission playing up, holding gerars, not selecting											
6569	C311	Mack Granite Day Cab - 6x4 - 4:neutral etc. Check over gearbox, test PWM & ...	R & M	05/31/2019	0	0	Hemmant	Brisbane Single & Loca	113.75	25	0
Plug laptop in, check fault codes. Look at wiring and											
6583	C311	Mack Granite Day Cab - 6x4 - 4:check plug. Run a scr burn.	R & M	06/03/2019	0	0	Hemmant	Brisbane Single & Loca	52.5	0	0
6609	C311	Mack Granite Day Cab - 6x4 - 4:2 x semipriet trans steels fitted to POS 9-10	Tyre - S/S	06/03/2019	0	0	Hemmant	Brisbane Single & Loca	35	840	0
Inspect electrical issue with truck not selecting gear											
6700	C311	Mack Granite Day Cab - 6x4 - 4:found to have loose connection at the back o ...	R & M	06/07/2019	0	0	Hemmant	Brisbane Single & Loca	130	0	0
6730	C311	Mack Granite Day Cab - 6x4 - 4:Fit 2 x new twist locks.	R & M	06/10/2019	0	0	Hemmant	Brisbane Single & Loca	32.5	0	0
6757	C311	Mack Granite Day Cab - 6x4 - 4:2 x sempreit trans steels fitted to POS 3-4	Tyre - S/S	06/11/2019	0	0	Hemmant	Brisbane Single & Loca	17.5	840	0
6816	C311	Mack Granite Day Cab - 6x4 - 4:Top up coolant	R & M	06/13/2019	0	0	Hemmant	Brisbane Single & Loca	17.5	0	0
TRUCK ADBLUE- C Service -90,000KMS C Service Completed											
6925	C311	Mack Granite Day Cab - 6x4 - 4:Actual 635163kms.	PM	06/19/2019	0	0	Hemmant	Brisbane Single & Loca	715	1158.85	0
Jump start truck checked charge rate all charging											
7109	C311	Mack Granite Day Cab - 6x4 - 4:fine.	R & M	07/02/2019	0	0	Hemmant	Brisbane Single & Loca	75	0	0
Flasher can faulty, Pull dash apart to get to flasher.											
7137	C311	Mack Granite Day Cab - 6x4 - 4:Replace flasher can, put dash back together	R & M	07/04/2019	0	0	Hemmant	Brisbane Single & Loca	40	24.24	0
7186	C311	Mack Granite Day Cab - 6x4 - 4:Remove seat & order seat. Repair roof light	R & M	07/09/2019	0	0	Hemmant	Brisbane Single & Loca	95	10.42	0
7195	C311	Mack Granite Day Cab - 6x4 - 4:Refit new seat into place.	R & M	07/09/2019	0	0	Hemmant	Brisbane Single & Loca	150	0	0
7208	C311	Mack Granite Day Cab - 6x4 - 4:Replace lamp cluster	R & M	07/10/2019	0	0	Hemmant	Brisbane Single & Loca	40	150	0
Take rear right side lights off, swap them over and											
7210	C311	Mack Granite Day Cab - 6x4 - 4:figure out which wire is what.	R & M	07/10/2019	0	0	Hemmant	Brisbane Single & Loca	140	0	0
7214	C311	Mack Granite Day Cab - 6x4 - 4:R/R suzie coils	R & M	07/10/2019	0	0	Hemmant	Brisbane Single & Loca	75	0	0
7256	C311	Mack Granite Day Cab - 6x4 - 4:Gave both truck and trailer a good quick wash down.	R & M	07/12/2019	0	0	Hemmant	Brisbane Single & Loca	40	0	0
7258	C311	Mack Granite Day Cab - 6x4 - 4:Check brake problem on trailer, all working on	R & M	07/12/2019	0	0	Hemmant	Brisbane Single & Loca	75	0	0
Repair lifter faults, fit sign, repair 20-40, fit QR valve,											
7267	C311	Mack Granite Day Cab - 6x4 - 4:Repair step matt, Fix air leaks.	R & M	07/11/2019	0	0	Hemmant	Brisbane Single & Loca	787.5	20.94	0
Inspect issue with trailer brakes not releasing											
7279	C311	Mack Granite Day Cab - 6x4 - 4:properly. Checked suzi coils found suzi coils to ha ...	R & M	07/15/2019	0	0	Hemmant	Brisbane Single & Loca	37.5	25	0
Inspect air leak issue from under truck found QR											
7301	C311	Mack Granite Day Cab - 6x4 - 4:valve to be exhausting, Part ordered will be picke ...	R & M	07/17/2019	0	0	Hemmant	Brisbane Single & Loca	75	0	0
7311	C311	Mack Granite Day Cab - 6x4 - 4:Check for air leak.	R & M	07/17/2019	0	0	Hemmant	Brisbane Single & Loca	37.5	0	0
Go to breakdown & push air valve for trailer to get											
7320	C311	Mack Granite Day Cab - 6x4 - 4:lifter working	R & M	07/18/2019	0	0	Hemmant	Brisbane Single & Loca	75	0	0
Drive to breakdown at Naragbah, inspected issue											
7358	C311	Mack Granite Day Cab - 6x4 - 4:with lift inspected fuses found to have blown fuses ...	R & M	07/22/2019	0	0	Hemmant	Brisbane Single & Loca	300	25	0
7369	C311	Mack Granite Day Cab - 6x4 - 4:Remove & fit air valve from 275 & 311	R & M	07/23/2019	0	0	Hemmant	Brisbane Single & Loca	187.5	0	0
TRUCK ADBLUE- A Service-10,000KMS A Service Completed											
7633	C311	Mack Granite Day Cab - 6x4 - 4:Actual 654834kms. Remove and replace broken o ...	PM	08/10/2019	0	0	Hemmant	Brisbane Single & Loca	75	96.6	0
7635	C311	Mack Granite Day Cab - 6x4 - 4:Gave a good wash	R & M	08/10/2019	0	0	Hemmant	Brisbane Single & Loca	60	0	0
7671	C311	Mack Granite Day Cab - 6x4 - 4:Jump Start	R & M	08/12/2019	0	0	Hemmant	Brisbane Single & Loca	37.5	0	0
7854	C311	Mack Granite Day Cab - 6x4 - 4:Jump Start	R & M	08/24/2019	0	0	Hemmant	Brisbane Single & Loca	37.5	0	0

7917	C311	Mack Granite Day Cab - 6x4 - 4: Move bracket, insulation tape up wiring and plug in.	R & M	08/29/2019	0	0	Hemmant	Brisbane Single & Loca	152.5	0	0
7932	C311	Mack Granite Day Cab - 6x4 - 4: Remove blown head light globe. Refitted new globe. TRUCK ADBLUE- A Service-10,000KMS A Service Completed.	R & M	08/28/2019	0	0	Hemmant	Brisbane Single & Loca	37.5	18.56	0
8126	C311	Mack Granite Day Cab - 6x4 - 4: Actual 664041kms. Repair air leak on fire ... TRUCK ADBLUE- B Service- 60,000KMS. B Service Completed.	PM	09/03/2019	0	0	Hemmant	Brisbane Single & Loca	150	7.58	0
8238	C311	Mack Granite Day Cab - 6x4 - 4: Actual 668376kms. Repaired oil leak from ...	PM	09/13/2019	0	0	Hemmant	Brisbane Single & Loca	300	0	0
8298	C311	Mack Granite Day Cab - 6x4 - 4: Take phone call from allocators, load up Jesse's ute with new batteries, drove to heathwood had to ...	R & M	09/16/2019	0	0	Hemmant	Brisbane Single & Loca	187.5	482.32	0
8334	C311	Mack Granite Day Cab - 6x4 - 4: Drive up to top yard attempt to jump start truck, truck would not start, removed batteries on left ... TRUCK ADBLUE- A Service-10,000KMS. A Service Completed.	R & M	09/19/2019	0	0	Hemmant	Brisbane Single & Loca	150	241.16	0
8577	C311	Mack Granite Day Cab - 6x4 - 4: Actual 673407kms. Repair and tighten up m ...	PM	09/26/2019	0	0	Hemmant	Brisbane Single & Loca	150	74	0
8753	C311	Mack Granite Day Cab - 6x4 - 4: Replace tail light globes on left rear and replace front head light globe. Breakdown	R & M	10/04/2019	0	0	Hemmant	Brisbane Single & Loca	57.5	23.77	0
8922	C311	Mack Granite Day Cab - 6x4 - 4: Look for fault get remove working on lift	R & M	10/14/2019	0	0	Hemmant	Brisbane Single & Loca	187.5	0	0
8954	C311	Mack Granite Day Cab - 6x4 - 4: Look for remote. Remove guard reweld broken mudguard poles back into place.	R & M	10/15/2019	0	0	Hemmant	Brisbane Single & Loca	75	0	0
9031	C311	Mack Granite Day Cab - 6x4 - 4: Clean down mudguard poles (grinded old ...	R & M	10/17/2019	0	0	Hemmant	Brisbane Single & Loca	190	0	0
9074	C311	Mack Granite Day Cab - 6x4 - 4: R/R drive tyre x 8 Strip & Fit 8 x new drive tyres	R & M	10/19/2019	0	0	Hemmant	Brisbane Single & Loca	75	0	0
9083	C311	Mack Granite Day Cab - 6x4 - 4: Test tyres from Freedom TRUCK ADBLUE- A Service-10,000KMS A Service Completed	Tyre - S/S	10/19/2019	0	0	Hemmant	Brisbane Single & Loca	130	0	0
9139	C311	Mack Granite Day Cab - 6x4 - 4: Actual 685159kms Disconnect 311 from swinglift.	PM	10/22/2019	0	0	Hemmant	Brisbane Single & Loca	140	74	0
9163	C311	Mack Granite Day Cab - 6x4 - 4: Wash Down 311 Remove & replace hydraulic fitting, Refit hyd hoses	R & M	10/22/2019	0	0	Hemmant	Brisbane Single & Loca	230	0	0
9196	C311	Mack Granite Day Cab - 6x4 - 4: test no leaks, refit walk plate.	R & M	10/23/2019	0	0	Hemmant	Brisbane Single & Loca	225	0	0
9314	C311	Mack Granite Day Cab - 6x4 - 4: Inspect hydraulic on back of truck to trailer found to have hydraulic hoses not connected properly. ... Inspect leak from PTO block found to have loose connection tight up connection tested operation che	R & M	10/29/2019	0	0	Hemmant	Brisbane Single & Loca	110	0	0
9408	C311	Mack Granite Day Cab - 6x4 - 4: ...	R & M	10/31/2019	0	0	Hemmant	Brisbane Single & Loca	75	0	0
9447	C311	Mack Granite Day Cab - 6x4 - 4: Change over hydraulic fittings and lines on truck to match up to trailer, hooked up trailer to truc ...	R & M	11/01/2019	0	0	Hemmant	Brisbane Single & Loca	115	0	0
9469	C311	Mack Granite Day Cab - 6x4 - 4: Wash & degrease trick Disconnected 311 from trailer T168 took Hydraulic	R & M	11/02/2019	0	0	Hemmant	Brisbane Single & Loca	130	0	0
9719	C311	Mack Granite Day Cab - 6x4 - 4: hoses off to be replaced. Coolant pipe and airbag Remove T piece and put joiner in, Lift airbags and	R & M	11/12/2019	0	0	Hemmant	Brisbane Single & Loca	40	0	0
9722	C311	Mack Granite Day Cab - 6x4 - 4: remove one bag. Replace ...	R & M	11/14/2019	0	0	Hemmant	Brisbane Single & Loca	200	154	0
9735	C311	Mack Granite Day Cab - 6x4 - 4: 2 x Ogreens stars fitted to 295/80/22.5	Tyre - S/S	11/12/2019	0	0	Hemmant	Brisbane Single & Loca	52.5	0	0
9754	C311	Mack Granite Day Cab - 6x4 - 4: Put new mudflaps on 311 along with candy signs R/R mudguards, Straigten mudguard pole, Fit	R & M	11/13/2019	0	0	Hemmant	Brisbane Single & Loca	20	45.11	0
9756	C311	Mack Granite Day Cab - 6x4 - 4: mudflaps & candy strips. Repair roof lights, Check for air leaks, Make up	R & M	11/13/2019	0	0	Hemmant	Brisbane Single & Loca	375	27.38	0
9758	C311	Mack Granite Day Cab - 6x4 - 4: battery holder	R & M	11/13/2019	0	0	Hemmant	Brisbane Single & Loca	150	0	0
9817	C311	Mack Granite Day Cab - 6x4 - 4: Get list of parts to pick up	R & M	11/14/2019	0	0	Hemmant	Brisbane Single & Loca	187.5	0	0
9835	C311	Mack Granite Day Cab - 6x4 - 4: Drive to Pirtek get hose made and pick up fittings, Swap fittings over. Wash Truck. Connect to T193 ...	R & M	11/15/2019	0	0	Hemmant	Brisbane Single & Loca	120	0	0
10023	C311	Mack Granite Day Cab - 6x4 - 4: Oil Leak & other problem TRUCK ADBLUE- B Service- 60,000KMS B Service Completed	R & M	12/06/2019	0	0	Hemmant	Brisbane Single & Loca	37.5	0	0
10299	C311	Mack Granite Day Cab - 6x4 - 4: Actual 700980kms. Replace door striker RHS, ...	PM	12/05/2019	0	0	Hemmant	Brisbane Single & Loca	240	708.0779	0
10495	C311	Mack Granite Day Cab - 6x4 - 4: Repair hyd leaks	R & M	12/07/2019	0	0	Hemmant	Brisbane Single & Loca	75	0	0

10576 C311	Mack Granite Day Cab - 6x4 - 4:Change Bulb Air Leak, Located air leak, Blue suzie cord fitting,	R & M	12/12/2019	0	0	Hemmant	Brisbane Single & Loca	10	18.56	0
10606 C311	Mack Granite Day Cab - 6x4 - 4:replace with new one Plug in computer, Forward drive axle abnormal temp	R & M	01/02/2020	0	0	Hemmant	Brisbane Single & Loca	20	25	0
10705 C311	Mack Granite Day Cab - 6x4 - 4:check diff oil/ clean sensor	R & M	12/17/2019	0	0	Hemmant	Brisbane Single & Loca	157.5	25	0
10915 C311	Mack Granite Day Cab - 6x4 - 4:Pick up parts from Gibbs, Replace head light globes.	R & M	01/09/2020	0	0	Hemmant	Brisbane Single & Loca	32.5	25	0
11041 C311	Mack Granite Day Cab - 6x4 - 4:Missing mudguard	R & M	01/15/2020	0	0	Hemmant	Brisbane Single & Loca	65	0	0
11094 C311	Attend breakdown Narangba, Truck not building air, Mack Granite Day Cab - 6x4 - 4:Check rear right air leak, Fill up air. Fix lift ...	R & M	01/15/2020	0	0	Hemmant	Brisbane Single & Loca	350	0	0
11110 C311	Ahead breakdown Narangba, Truck not building air, Mack Granite Day Cab - 6x4 - 4:check rear right air leak, Fill up air. Fix lifte ...	R & M	01/15/2020	0	0	Hemmant	Brisbane Single & Loca	350	0	0
11152 C311	Mack Granite Day Cab - 6x4 - 4:a/c Chamber booster, ensure lifter had air and would	R & M	01/20/2020	0	0	Hemmant	Brisbane Single & Loca	40	0	0
11493 C311	Mack Granite Day Cab - 6x4 - 4:operate.	R & M	12/24/2019	0	0	Hemmant	Brisbane Single & Loca	160	0	0
11833 C311	Mack Granite Day Cab - 6x4 - 4:Repair indicator, Replace fuse	R & M	01/24/2020	0	0	Hemmant	Brisbane Single & Loca	32.5	25	0
11840 C311	Mack Granite Day Cab - 6x4 - 4:1 Puncher repair	R & M	01/24/2020	0	0	Hemmant	Brisbane Single & Loca	195	0	0
11914 C311	Mack Granite Day Cab - 6x4 - 4:Indicator issues	R & M	02/11/2020	0	0	Hemmant	Brisbane Single & Loca	64.9097215	0	0
12096 C311	Mack Granite Day Cab - 6x4 - 4:plug in laptop TRUCK ADBLUE- C Service -90,000KMS C Service Completed.	R & M	02/28/2020	0	0	Hemmant	Brisbane Single & Loca	40	25	0
12137 C311	Mack Granite Day Cab - 6x4 - 4:Actual 722192kms. Needed more engine oil ...	PM	02/04/2020	0	0	Hemmant	Brisbane Single & Loca	280	876.405	0
12157 C311	Mack Granite Day Cab - 6x4 - 4:Check over service, Top up gearbox oil. 311 Test alternator charge 14.1 and batteries 13.7	R & M	02/04/2020	0	0	Hemmant	Brisbane Single & Loca	97.5	50	0
12452 C311	Mack Granite Day Cab - 6x4 - 4:Grease turntable then drop off truck to snake ...	R & M	02/25/2020	0	0	Hemmant	Brisbane Single & Loca	137.5	0	0
12480 C311	Mack Granite Day Cab - 6x4 - 4:lifter no revving up	R & M	02/26/2020	0	0	Hemmant	Brisbane Single & Loca	60	25	0
12578 C311	calibrate Gear Box - Clutch wear reading 24.6 mm Mack Granite Day Cab - 6x4 - 4:	R & M	02/18/2020	0	0	Hemmant	Brisbane Single & Loca	100	50	0
12673 C311	Mack Granite Day Cab - 6x4 - 4:1 P/R drive L/F/O	R & M	03/02/2020	0	0	Hemmant	Brisbane Single & Loca	97.5	0	0
12703 C311	Mack Granite Day Cab - 6x4 - 4:Rewire lifter plug	R & M	03/03/2020	0	0	Hemmant	Brisbane Single & Loca	75	0	0
12775 C311	Mack Granite Day Cab - 6x4 - 4:lifter operation	R & M	03/05/2020	0	0	Hemmant	Brisbane Single & Loca	80	0	0
12789 C311	Mack Granite Day Cab - 6x4 - 4:Look for short in wiring and repair.	R & M	03/05/2020	0	0	Hemmant	Brisbane Single & Loca	112.5	0	0
12867 C311	Mack Granite Day Cab - 6x4 - 4:Jump Start	R & M	02/25/2020	0	0	Hemmant	Brisbane Single & Loca	75	0	0
13016 C311	Mack Granite Day Cab - 6x4 - 4:Look for short in elec/lead, R/R trailer plug. Lifter not working Check wiring in plug tighten loose wire	R & M	02/17/2020	0	0	Hemmant	Brisbane Single & Loca	150	25	0
13187 C311	Mack Granite Day Cab - 6x4 - 4:Test unit	R & M	03/17/2020	0	0	Hemmant	Brisbane Single & Loca	53.143057	0	0
13252 C311	Mack Granite Day Cab - 6x4 - 4:Take to snake pit	R & M	02/17/2020	0	0	Hemmant	Brisbane Single & Loca	37.5	0	0
13303 C311	Mack Granite Day Cab - 6x4 - 4:Refit back window	R & M	02/19/2020	0	0	Hemmant	Brisbane Single & Loca	37.5	0	0
13343 C311	PTO issues, no power to remote, check all Mack Granite Day Cab - 6x4 - 4:fuses/relays.	R & M	02/20/2020	0	0	Hemmant	Brisbane Single & Loca	130	0	0
13399 C311	Mack Granite Day Cab - 6x4 - 4:R/R suzies leads short tail	R & M	03/23/2020	0	0	Hemmant	Brisbane Single & Loca	112.5	46.25	0
13461 C311	Mack Granite Day Cab - 6x4 - 4:breakdown TRUCK ADBLUE- B Service- 60,000KMS B Service Completed.	R & M	03/25/2020	0	0	Hemmant	Brisbane Single & Loca	60	0	0
13521 C311	Mack Granite Day Cab - 6x4 - 4:Actual 733072kms. Adjust turntable, Oil ... Engine light on dash Crankcase pressure. Data erratic or incorrect	PM	03/25/2020	0	0	Hemmant	Brisbane Single & Loca	255	212.94	0
13576 C311	Mack Granite Day Cab - 6x4 - 4:Crankcase preeasure. Current belo ...	R & M	03/31/2020	0	0	Hemmant	Brisbane Single & Loca	32.5541645	0	0
13645 C311	Mack Granite Day Cab - 6x4 - 4:pick up parts Replace powering steering dip stick	R & M	04/02/2020	0	0	Hemmant	Brisbane Single & Loca	20	0	0
13654 C311	Mack Granite Day Cab - 6x4 - 4:Test charing issu everything tested fine	R & M	04/02/2020	0	0	Hemmant	Brisbane Single & Loca	65	0	0
13686 C311	Mack Granite Day Cab - 6x4 - 4:Lube module sliders	R & M	04/03/2020	0	0	Hemmant	Brisbane Single & Loca	37.5	0	0
13690 C311	Mack Granite Day Cab - 6x4 - 4:fix remote charger Swop truck trailers around, had to swop around	R & M	04/03/2020	0	0	Hemmant	Brisbane Single & Loca	20	0	0
13775 C311	Mack Granite Day Cab - 6x4 - 4:hydraulic fittings as well	R & M	04/09/2020	0	0	Hemmant	Brisbane Single & Loca	172.5	0	0
14248 C311	Mack Granite Day Cab - 6x4 - 4:Pull down seat leaver, repair dont need to replace	R & M	04/27/2020	0	0	Hemmant	Brisbane Single & Loca	32.5541645	0	0
14341 C311	Remove replace oil spinner o ring remove radiator Mack Granite Day Cab - 6x4 - 4:and fit new one remove and replace crankcase pre ...	R & M	04/29/2020	0	0	Hemmant	Brisbane Single & Loca	1265	0	0
14352 C311	Re fit. Radiator pressure test change o rings on Mack Granite Day Cab - 6x4 - 4:header tant pipes. Hook up trailer and test take t ...	R & M	04/30/2020	0	0	Hemmant	Brisbane Single & Loca	262.5	0	0

Breakdown - Call out to Acacia Ridge, to truck not selecting gears, Doagnosed down the machine, gea											
14744	C311	Mack Granite Day Cab - 6x4 - 4:...	R & M	05/07/2020	0	0	Hemmant	Brisbane Single & Loca	162.5	25	0
14756	C311	Mack Granite Day Cab - 6x4 - 4: 1 puncher repair drive	R & M	05/07/2020	0	0	Hemmant	Brisbane Single & Loca	97.5	0	0
15107	C311	Mack Granite Day Cab - 6x4 - 4: R/R hydraulic hose	R & M	05/21/2020	0	0	Hemmant	Brisbane Single & Loca	75	0	0
15117	C311	Mack Granite Day Cab - 6x4 - 4: Repair twist locks on lifter	R & M	05/21/2020	0	0	Hemmant	Brisbane Single & Loca	65.61386	0	0
15127	C311	Mack Granite Day Cab - 6x4 - 4: Repair wist lock	R & M	05/22/2020	0	0	Hemmant	Brisbane Single & Loca	75	0	0
15418	C311	Mack Granite Day Cab - 6x4 - 4: cut tag and connect	R & M	06/10/2020	0	0	Hemmant	Brisbane Single & Loca	20	25	0
15475	C311	Mack Granite Day Cab - 6x4 - 4: bring into workshop	R & M	06/15/2020	0	0	Hemmant	Brisbane Single & Loca	160	50	0
15485	C311	Mack Granite Day Cab - 6x4 - 4: TRUCK ADBLUE & EGR- D Service - 12 Monthly Assist allen bending ram straight	PM	06/09/2020	0	0	Hemmant	Brisbane Single & Loca	260	87.76	0
15490	C311	Mack Granite Day Cab - 6x4 - 4:	DA	06/15/2020	0	0	Hemmant	Brisbane Single & Loca	226.65136	0	0
15498	C311	Mack Granite Day Cab - 6x4 - 4: TRUCK ADBLUE- A Service-10,000KMS	PM	06/09/2020	0	0	Hemmant	Brisbane Single & Loca	420	80.41	0
15609	C311	Mack Granite Day Cab - 6x4 - 4: Put truck to gether	R & M	06/24/2020	0	0	Hemmant	Brisbane Single & Loca	84.0319435	0	0
15654	C311	Mack Granite Day Cab - 6x4 - 4: fix 7 pin plug	R & M	06/30/2020	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
15684	C311	Mack Granite Day Cab - 6x4 - 4: Replace mud gurad bracket	R & M	07/01/2020	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
15746	C311	Mack Granite Day Cab - 6x4 - 4: scan dtc faults	R & M	07/08/2020	0	0	Hemmant	Brisbane Single & Loca	42.5	25	0
15747	C311	Mack Granite Day Cab - 6x4 - 4: A service done repair lights Defects Air leaks	R & M	07/08/2020	0	0	Hemmant	Brisbane Single & Loca	212.5	0	0
15755	C311	Mack Granite Day Cab - 6x4 - 4: Stuck in gear	R & M	07/08/2020	0	0	Hemmant	Brisbane Single & Loca	297.594435	25	0
16067	C311	Mack Granite Day Cab - 6x4 - 4: Supply air to tanks	R & M	08/05/2020	0	0	Hemmant	Brisbane Single & Loca	42.8069435	0	0
16128	C311	Mack Granite Day Cab - 6x4 - 4: mudguard pole	R & M	08/12/2020	0	0	Hemmant	Brisbane Single & Loca	85	25	0
16135	C311	Mack Granite Day Cab - 6x4 - 4: Fit new mudguard poles fit new mudguard and brackets grease king pin etc assist with front steers	R & M	08/12/2020	0	0	Hemmant	Brisbane Single & Loca	332.916695	0	0
16142	C311	Mack Granite Day Cab - 6x4 - 4: defects	R & M	08/13/2020	0	0	Hemmant	Brisbane Single & Loca	170	38.385	0
16227	C311	Mack Granite Day Cab - 6x4 - 4: braided airline	R & M	08/24/2020	0	0	Hemmant	Brisbane Single & Loca	170	100	0
16381	C311	Mack Granite Day Cab - 6x4 - 4: Diagnose pto not engaging found loose plug on trailer	R & M	09/03/2020	0	0	Hemmant	Brisbane Single & Loca	85	25	0
16458	C311	Mack Granite Day Cab - 6x4 - 4: A servie done repair lights fill hyd oil 774142klm2245hrs	PM	09/04/2020	0	0	Hemmant	Brisbane Single & Loca	170	183.28	0
16623	C311	Mack Granite Day Cab - 6x4 - 4: Remove and replace pwm valve replum for new valve test drive	R & M	09/14/2020	0	0	Hemmant	Brisbane Single & Loca	1190	0	0
16633	C311	Mack Granite Day Cab - 6x4 - 4: replace seat valve	R & M	09/15/2020	0	0	Hemmant	Brisbane Single & Loca	42.5	216.33	0
16930	C311	Mack Granite Day Cab - 6x4 - 4: Drop driver to snake pit	R & M	09/29/2020	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
17050	C311	Mack Granite Day Cab - 6x4 - 4: Move to infront of tyre bay	R & M	10/08/2020	0	0	Hemmant	Brisbane Single & Loca	42.5	25	0
17434	C311	Mack Granite Day Cab - 6x4 - 4: Make up new drive tyre for fit up to rims for saturday Please note used 4 new tyres	R & M	10/23/2020	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
17505	C311	Mack Granite Day Cab - 6x4 - 4: Repair cutting out dianoise order parts replace battery terminals. And jump cable for positive Remove and replace fan belt and ac belt and belt	Break	10/27/2020	0	0	Hemmant	Brisbane Single & Loca	127.5	56.44	0
17557	C311	Mack Granite Day Cab - 6x4 - 4: tensioners by two	R & M	10/31/2020	0	0	Hemmant	Brisbane Single & Loca	170	0	0
17678	C311	Mack Granite Day Cab - 6x4 - 4: Repair hyd leak	R & M	11/04/2020	0	0	Hemmant	Brisbane Single & Loca	85	50	0
17715	C311	Mack Granite Day Cab - 6x4 - 4: Hydraulic leaks	R & M	11/06/2020	0	0	Hemmant	Brisbane Single & Loca	382.5	100	0
17940	C311	Mack Granite Day Cab - 6x4 - 4: Rotate steer tyre	Tyre - S/S	11/13/2020	0	0	Hemmant	Brisbane Single & Loca	35	25	0
18023	C311	Mack Granite Day Cab - 6x4 - 4: Remove diff assembly. With vish	Break	11/12/2020	0	0	Hemmant	Brisbane Single & Loca	637.5	25	0
18031	C311	Mack Granite Day Cab - 6x4 - 4: Fit trailer hand piece. Strip front diff and power divider	R & M	11/16/2020	0	0	Hemmant	Brisbane Single & Loca	85	0	0
18059	C311	Mack Granite Day Cab - 6x4 - 4: Clean all parts and inspect	R & M	11/16/2020	0	0	Hemmant	Brisbane Single & Loca	892.5	25	0
18075	C311	Mack Granite Day Cab - 6x4 - 4: Assist with removal of front diff	R & M	11/13/2020	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
18244	C311	Mack Granite Day Cab - 6x4 - 4: Rebuild Diff and power divider	R & M	12/07/2020	0	0	Hemmant	Brisbane Single & Loca	850	0	0
18479	C311	Mack Granite Day Cab - 6x4 - 4: Assit allan spooner with finishing of diff assembly Take truck to tefco pick up trailer bring back to seqh	R & M	12/30/2020	0	0	Hemmant	Brisbane Single & Loca	255	25	0
18488	C311	Mack Granite Day Cab - 6x4 - 4: weight trailer	R & M	12/01/2020	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
18497	C311	Mack Granite Day Cab - 6x4 - 4: clean out and detail cab	R & M	12/01/2020	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
18538	C311	Mack Granite Day Cab - 6x4 - 4: Assist alan woth tighten up U-Bolts Hook up lifter to truck and check all working.	R & M	12/02/2020	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
18540	C311	Mack Granite Day Cab - 6x4 - 4:	R & M	12/02/2020	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
18704	C311	Mack Granite Day Cab - 6x4 - 4: order and P/V battery world travel to helidon and drop off battery travel back to the yard Replace key barrel Used origanl barrel and keys for c311	Driving	12/07/2020	0	0	Hemmant	Brisbane Single & Loca	212.5	0	0
18776	C311	Mack Granite Day Cab - 6x4 - 4:	R & M	12/10/2020	0	0	Hemmant	Brisbane Single & Loca	85	0	0

18819	C311	Mack Granite Day Cab - 6x4 - 4: Changed over ignition barrel	R & M	12/10/2020	0	0	Hemmant	Brisbane Single & Loca	85	0	0
18828	C311	Mack Granite Day Cab - 6x4 - 4: Remove rear diff centre clean up work area	R & M	12/11/2020	0	0	Hemmant	Brisbane Single & Loca	361.25	25	0
18855	C311	Mack Granite Day Cab - 6x4 - 4: Remove diff center	Break	12/11/2020	0	0	Hemmant	Brisbane Single & Loca	446.25	25	0
18938	C311	Mack Granite Day Cab - 6x4 - 4: Help wish with diff install, fit axles, fit sensors.	R & M	12/16/2020	0	0	Hemmant	Brisbane Single & Loca	510	25	0
Fit diff mud guards horse shoe check diff oils to up											
18950	C311	Mack Granite Day Cab - 6x4 - 4: test drve hook up to lifter check lifter operat ...	R & M	12/17/2020	0	0	Hemmant	Brisbane Single & Loca	382.5	133.25	0
18961	C311	Mack Granite Day Cab - 6x4 - 4: Pick up parts from mack	Driving	12/16/2020	0	0	Hemmant	Brisbane Single & Loca	106.25	0	0
Finish off diff install Road test connect to trailer											
18996	C311	Mack Granite Day Cab - 6x4 - 4: swap fitting clean workshop mess up orgains ... Complete B service. Klms 799162	R & M	12/17/2020	0	0	Hemmant	Brisbane Single & Loca	595	40.14	0
19495	C311	Mack Granite Day Cab - 6x4 - 4: Hours 23227	PM	01/12/2021	0	0	Hemmant	Brisbane Single & Loca	262.20137	25	0
20107	C311	Mack Granite Day Cab - 6x4 - 4: Hook up lifter	R & M	02/04/2021	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
Massive air leak, change air dryer filter, didnt work,											
20150	C311	Mack Granite Day Cab - 6x4 - 4: pulled off whole air dryer assemble and clea ... Remove and replace battery terminals check oil top up coolant.	R & M	02/08/2021	0	0	Hemmant	Brisbane Single & Loca	595	212.79	0
20391	C311	Mack Granite Day Cab - 6x4 - 4: check over	R & M	02/20/2021	0	0	Hemmant	Brisbane Single & Loca	85	38.64	0
20412	C311	Mack Granite Day Cab - 6x4 - 4: Defects/Test run Plug in laptop and check codes and also fit new	Defect	02/22/2021	0	0	Hemmant	Brisbane Single & Loca	340	0	0
20420	C311	Mack Granite Day Cab - 6x4 - 4: intake sensor Find problem with truck cutting out test drive go to mack pick up parts	Defect	02/22/2021	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
20425	C311	Mack Granite Day Cab - 6x4 - 4: Clean WS	R & M	02/22/2021	0	0	Hemmant	Brisbane Single & Loca	340	0	0
20445	C311	Mack Granite Day Cab - 6x4 - 4: 311~ swingarm trailer Loosen all u bolts and realign drive axles (Check and change rear centre bolts	R & M	02/24/2021	0	0	Hemmant	Brisbane Single & Loca	127.263887	25	0
20614	C311	Mack Granite Day Cab - 6x4 - 4: Carry out wheel alig ...	R & M	02/09/2021	0	0	Hemmant	Brisbane Single & Loca	1020	140.14	0
20659	C311	Mack Granite Day Cab - 6x4 - 4: Park brake issue	R & M	03/03/2021	0	0	Hemmant	Brisbane Single & Loca	297.5	0	0
FAULT REPORTS: 1. UHF NEEDS TO BE FIXED 2. STEERING LEAK. 3. SERVICE DUE @809100 NOW @809389											
20705	C311	Mack Granite Day Cab - 6x4 - 4: 4. ...	Defect	03/06/2021	0	0	Hemmant	Brisbane Single & Loca	85	0	0
21150	C311	Mack Granite Day Cab - 6x4 - 4: w/o raised by mistake	Scheduled	03/30/2021	0	0	Hemmant	Brisbane Single & Loca	0	0	0
21183	C311	Mack Granite Day Cab - 6x4 - 4: C311 TIGHTEN MUDGUARD Engine Over heating issue Test drive sign off. MECHANIC COMMENTS: PRESSURE TEST OK 25 MIN @13PSI	Wear/Tear	03/23/2021	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
21886	C311	Mack Granite Day Cab - 6x4 - 4: CO ... C311 Truck A Service notes:complete svc defect: front shocky, needs new	Wear/Tear	04/17/2021	0	0	Hemmant	Brisbane Single & Loca	212.5	0	0
21922	C311	Mack Granite Day Cab - 6x4 - 4: fuel filter bowl wires cut ... Repair roof lights refit rear tail lights remove and fit	PM	04/21/2021	0	0	Hemmant	Brisbane Single & Loca	170	0	0
21976	C311	Mack Granite Day Cab - 6x4 - 4: mud flap and candy stripes FIT BATTERY TERMINAL THAT WERE LEFT OFF JUMP START	Scheduled	04/20/2021	0	0	Hemmant	Brisbane Single & Loca	170	0	0
22091	C311	Mack Granite Day Cab - 6x4 - 4: STILL HAS BOLT ON DASH		04/27/2021	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
Picked up 311 from snake up, had issues starting											
22134	C311	Mack Granite Day Cab - 6x4 - 4: 1. Drain oil from sump, pulled off the sensor, oil ...		04/28/2021	0	0	Hemmant	Brisbane Single & Loca	552.5	125.07	0
22136	C311	Mack Granite Day Cab - 6x4 - 4: Go to mack pick up parts	Scheduled	04/28/2021	0	0	Hemmant	Brisbane Single & Loca	85	0	0
C311 Truck A Service + Changed diff oils because											
22147	C311	Mack Granite Day Cab - 6x4 - 4: both diff temp reading hot + Gear box oil	PM	05/05/2021	0	0	Hemmant	Brisbane Single & Loca	680	162.965852	0
replace batteries (4). fit earth strap back on starter											
22162	C311	Mack Granite Day Cab - 6x4 - 4: motor. fit 2 bonnet straps. replace melted e ...	Wear/Tear	04/29/2021	0	0	Hemmant	Brisbane Single & Loca	616.25	2879.81	0
22203	C311	Mack Granite Day Cab - 6x4 - 4: POLISH WHEELS	Wear/Tear	04/30/2021	0	0	Hemmant	Brisbane Single & Loca	35	0	0
FAULT REPORTS: RANDOM ENGINE SHUTDOWN / ENGINE LIGHT ON /											
22258	C311	Mack Granite Day Cab - 6x4 - 4:	Wear/Tear	08/06/2021	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0

ID	Code	Description	Category	Date	Hours	Cost	Technician	Location	Rate	Material	Other
GO FOR A TEST DRIVE AS TRUCK IS STILL STOPPING MID DRIVE HAS NO CODES, MAYBE ENGINE HARNESS											
22270	C311	Mack Granite Day Cab - 6x4 - 4: NOT SUR ...	Wear/Tear	05/05/2021	0	0	Hemmant	Brisbane Single & Loca	127.5	25	0
22352	C311	Mack Granite Day Cab - 6x4 - 4: Take truck to mack	Wear/Tear	05/08/2021	0	0	Hemmant	Brisbane Single & Loca	85	0	0
22364	C311	Mack Granite Day Cab - 6x4 - 4: TAKE TRUCK TO MACK FOR REPAIRS random engine shutdown again FR5106 - Overheating warning and alarm, advised	Scheduled	05/08/2021	0	0	Hemmant	Brisbane Single & Loca	85	0	0
22863	C311	Mack Granite Day Cab - 6x4 - 4: workshop 15-4-21 could ... Go to mack with shane to collect 311 and pick up	Wear/Tear	08/06/2021	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
23412	C311	Mack Granite Day Cab - 6x4 - 4: head and liners As instructed by ben pick up mack from mack and	Scheduled	06/18/2021	0	0	Hemmant	Brisbane Single & Loca	85	0	0
23417	C311	Mack Granite Day Cab - 6x4 - 4: bring back to seqh work shop	Scheduled	06/18/2021	0	0	Hemmant	Brisbane Single & Loca	106.25	0	0
23523	C311	Mack Granite Day Cab - 6x4 - 4: Engine harness + Top End Tune	Scheduled	06/22/2021	0	0	Hemmant	Brisbane Single & Loca	892.5	0	0
23548	C311	Mack Granite Day Cab - 6x4 - 4: Picked up parts from mack, heavy traffic	Scheduled	06/23/2021	0	0	Hemmant	Brisbane Single & Loca	85	0	0
23587	C311	Mack Granite Day Cab - 6x4 - 4: Help keenan remove broken studs from head	Scheduled	06/23/2021	0	0	Hemmant	Brisbane Single & Loca	170	0	0
23592	C311	Mack Granite Day Cab - 6x4 - 4: Assisst keenan with 311 and clean up	Scheduled	06/24/2021	0	0	Hemmant	Brisbane Single & Loca	212.5	0	0
23606	C311	Mack Granite Day Cab - 6x4 - 4: Removing exhaust and turbo manifold with keenan	Wear/Tear	06/24/2021	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
23607	C311	Mack Granite Day Cab - 6x4 - 4: Picked up parts from mack	Scheduled	06/24/2021	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
23616	C311	Mack Granite Day Cab - 6x4 - 4: Remove steering box Putting exhaust and turbo manifold back on with	Scheduled	06/24/2021	0	0	Hemmant	Brisbane Single & Loca	85	0	0
23621	C311	Mack Granite Day Cab - 6x4 - 4: keenan Putting exhaust and turbo manifold back on with	Wear/Tear	06/28/2021	0	0	Hemmant	Brisbane Single & Loca	255	0	0
23622	C311	Mack Granite Day Cab - 6x4 - 4: keenan	Wear/Tear	06/25/2021	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
23669	C311	Mack Granite Day Cab - 6x4 - 4: Picked up parts from mack	Scheduled	06/29/2021	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
23695	C311	Mack Granite Day Cab - 6x4 - 4: Drop off part to gateway hydraulics	Scheduled	06/29/2021	0	0	Hemmant	Brisbane Single & Loca	85	0	0
23772	C311	Mack Granite Day Cab - 6x4 - 4: Put new power steering box in Go to all power steering to pick up steering box and	Scheduled	07/02/2021	0	0	Hemmant	Brisbane Single & Loca	42.5	1650	0
23797	C311	Mack Granite Day Cab - 6x4 - 4: put on truck 311	Scheduled	07/02/2021	0	0	Hemmant	Brisbane Single & Loca	297.5	0	0
23814	C311	Mack Granite Day Cab - 6x4 - 4: Put hydraulic bank valve back on prime mover, re- aranged hydraulic lines around to fit nice and neat, ...	Scheduled	07/06/2021	0	0	Hemmant	Brisbane Single & Loca	425	0	0
23822	C311	Mack Granite Day Cab - 6x4 - 4: Asissting keenan with connecting hydraulic lines	Scheduled	07/05/2021	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
23824	C311	Mack Granite Day Cab - 6x4 - 4: Finish hydraulic lines with keenan	Scheduled	07/05/2021	0	0	Hemmant	Brisbane Single & Loca	85	0	0
23825	C311	Mack Granite Day Cab - 6x4 - 4: Degrease and wash 311	Scheduled	07/05/2021	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
Requested by michael hanson to connect up 311 to											
23932	C311	Mack Granite Day Cab - 6x4 - 4: trailer attempt to cuts out bring back to workshop ...	Wear/Tear	07/08/2021	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
23943	C311	Mack Granite Day Cab - 6x4 - 4: Assist tony and change mud flap on 311	Scheduled	07/09/2021	0	0	Hemmant	Brisbane Single & Loca	255	0	0
23944	C311	Mack Granite Day Cab - 6x4 - 4: Assist tony with 311	DA	07/08/2021	0	0	Hemmant	Brisbane Single & Loca	170	0	0
23946	C311	Mack Granite Day Cab - 6x4 - 4: Rekit pwm valves Chnage kalmar tire and fix 311 hydraulic leak and	Wear/Tear	07/08/2021	0	0	Hemmant	Brisbane Single & Loca	864.166695	1194.49	0
24420	C311	Mack Granite Day Cab - 6x4 - 4: start service for a and dolly and b double Clean out airdryer fit new air filter breakdown remove and replace purge valve in 70 bring back to	Scheduled	07/28/2021	0	0	Hemmant	Brisbane Single & Loca	382.5	0	0
24552	C311	Mack Granite Day Cab - 6x4 - 4: ...	Wear/Tear	08/02/2021	0	0	Hemmant	Brisbane Single & Loca	297.5	0	0
24563	C311	Mack Granite Day Cab - 6x4 - 4: Remove and replace air dryer fr5110: driver side window works some times FR 55109: no reverse beeping. electronic lights stays	Wear/Tear	08/03/2021	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
24693	C311	Mack Granite Day Cab - 6x4 - 4: on ... CHANGED THE PWM VALVE	Wear/Tear	08/26/2021	0	0	Hemmant	Brisbane Single & Loca	340	0	0
24704	C311	Mack Granite Day Cab - 6x4 - 4: MATT: PICK UP PARTS DROP GEAR BOX, REPLACE DONUT PUT BACK	Wear/Tear	08/08/2021	0	0	Hemmant	Brisbane Single & Loca	233.75	0	0
24707	C311	Mack Granite Day Cab - 6x4 - 4: TOGETHER	Wear/Tear	08/07/2021	0	0	Hemmant	Brisbane Single & Loca	1445	0	0
24709	C311	Mack Granite Day Cab - 6x4 - 4: REPLACE MUD GUARD	DA	08/06/2021	0	0	Hemmant	Brisbane Single & Loca	127.5	45.86	0
24713	C311	Mack Granite Day Cab - 6x4 - 4: replace rear mudgaurd remove pto. hoses attached sealed box line to pto	DA	08/07/2021	0	0	Hemmant	Brisbane Single & Loca	85	0	0
24732	C311	Mack Granite Day Cab - 6x4 - 4: bung fit rear plate to sea gearbox REMOVE TANK SEPS FOR 311. PARTS UNDER NEW	Scheduled	08/10/2021	0	0	Hemmant	Brisbane Single & Loca	148.75	0	0
24745	C311	Mack Granite Day Cab - 6x4 - 4: BENCH	Wear/Tear	08/10/2021	0	0	Hemmant	Brisbane Single & Loca	170	0	0
REMOVE PTO AND HOSES, SEALED BOX LINE TO PTO											
24767	C311	Mack Granite Day Cab - 6x4 - 4: BUNG. FIT REAR PLATE TO SEAL DE GEARBOX	Wear/Tear	08/11/2021	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
24769	C311	Mack Granite Day Cab - 6x4 - 4: ASSIST REPLACE PWM	Wear/Tear	08/09/2021	0	0	Hemmant	Brisbane Single & Loca	297.5	0	0
removed fuel tank hoses, connector, fuel tank / hyd											
24778	C311	Mack Granite Day Cab - 6x4 - 4: tank (drained hyd fluid). removed step ladder s ...	Wear/Tear	08/11/2021	0	0	Hemmant	Brisbane Single & Loca	666.4	0	0

24821	C311	Mack Granite Day Cab - 6x4 - 4:disconnect prime mover form trailer, clean and wash	Scheduled	08/12/2021	0	0	Hemmant	Brisbane Single & Loca	85	0	0
24850	C311	Mack Granite Day Cab - 6x4 - 4:Truck A Service Truck C Service.	PM	08/13/2021	0	0	Hemmant	Brisbane Single & Loca	170	0	0
25070	C311	Mack Granite Day Cab - 6x4 - 4: breakdown: compressor flogged out prime mover wasn't building up air. plum air from service truck c	PM	08/26/2021	0	0	Hemmant	Brisbane Single & Loca	340	793.38	0
25239	C311	Mack Granite Day Cab - 6x4 - 4:...	Wear/Tear	09/02/2021	0	0	Hemmant	Brisbane Single & Loca	255	0	0
25250	C311	Mack Granite Day Cab - 6x4 - 4:lines hoses from moisture stock in the lines ... tied compressor air hoses inlet. clean compressor air	Wear/Tear	09/02/2021	0	0	Hemmant	Brisbane Single & Loca	212.5	0	0
26420	C311	Mack Granite Day Cab - 6x4 - 4:neutral. Let truck slowly build up air and se ... Driver complaint about not building air or going into	Wear/Tear	10/18/2021	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
26440	C311	Mack Granite Day Cab - 6x4 - 4:Found switch sticking valves. Removed valve and cl ... Inspected and found seat stayed up all the time.		10/18/2021	0	0	Hemmant	Brisbane Single & Loca	63.75	216.33	0
26442	C311	Mack Granite Day Cab - 6x4 - 4:on front right hand side. Removed booster and ma ... Inspected and found air leaking from brake booster	Wear/Tear	10/18/2021	0	0	Hemmant	Brisbane Single & Loca	85	0	0
26479	C311	Mack Granite Day Cab - 6x4 - 4:gear and loosing air find air leak lh brak bo ... Do bin runs with loader assist 311 as it was stuck in Inspected and found turbo gasket breaking apart.	Scheduled	10/18/2021	0	0	Hemmant	Brisbane Single & Loca	255	0	0
26492	C311	Mack Granite Day Cab - 6x4 - 4:...	Wear/Tear	10/19/2021	0	0	Hemmant	Brisbane Single & Loca	935	0	0
26494	C311	Mack Granite Day Cab - 6x4 - 4:truck D Service Driver complained about his indicators at the trailer not working.	Scheduled	10/20/2021	0	0	Hemmant	Brisbane Single & Loca	425	37.85	0
26527	C311	Mack Granite Day Cab - 6x4 - 4:Inspected and found suzie coil l ... - Engine light was coming on, scan tool was connected to diagnosis. The issue was on the exhaust	Wear/Tear	10/20/2021	0	0	Hemmant	Brisbane Single & Loca	85	0	0
26665	C311	Mack Granite Day Cab - 6x4 - 4:ba ...	Wear/Tear	10/26/2021	0	0	Hemmant	Brisbane Single & Loca	255	0	0
26791	C311	Mack Granite Day Cab - 6x4 - 4:STRIP AND FIT PUNCTURED INNER DRIVE TYRE	Wear/Tear	11/01/2021	0	0	Hemmant	Brisbane Port Tyres Brisbane Single & Loca	85	0	0
26810	C311	Mack Granite Day Cab - 6x4 - 4:Assist john with air dryer and speing brake valve Parts for 311 arrived from gibbs, fit air dryer filter	Wear/Tear	11/02/2021	0	0	Hemmant	Brisbane Single & Loca	85	0	0
26813	C311	Mack Granite Day Cab - 6x4 - 4:and spring brake valve Engine shutting down	Wear/Tear	11/02/2021	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
26904	C311	Mack Granite Day Cab - 6x4 - 4:Che ... Check over all power and earth straps Check and clean ECU wiring harness	Scheduled	11/03/2021	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
27086	C311	Mack Granite Day Cab - 6x4 - 4:Wash truck Driver complained about check engine light.	Scheduled	11/11/2021	0	0	Hemmant	Brisbane Single & Loca	170	0	0
27140	C311	Mack Granite Day Cab - 6x4 - 4:bac ... Insoceted and plugged in Tech Tool. Found exhaust	Unsched.	11/09/2021	0	0	Hemmant	Brisbane Single & Loca	85	0	0
27193	C311	Mack Granite Day Cab - 6x4 - 4:ECU Swap Continued inspecting for faults since truck turned off again.		12/10/2021	0	0	Hemmant	Brisbane Single & Loca	0	0	0
27219	C311	Mack Granite Day Cab - 6x4 - 4:Called Sam from Mack help in order to ...	Scheduled	11/17/2021	0	0	Hemmant	Brisbane Single & Loca	425	0	0
27220	C311	Mack Granite Day Cab - 6x4 - 4:wiggling, that the multiwire plug were the exhaust ... Inspected again some wiring and found after much	Scheduled	11/18/2021	0	0	Hemmant	Brisbane Single & Loca	212.5	0	0
27245	C311	Mack Granite Day Cab - 6x4 - 4:truck to put back into neutral Truck stuck in gear, hook air line and fitting up to Driver complained about his truck loosing air.		11/19/2021	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
27494	C311	Mack Granite Day Cab - 6x4 - 4:...		11/29/2021	0	0	Hemmant	Brisbane Single & Loca	255	0	0
27495	C311	Mack Granite Day Cab - 6x4 - 4:the U pipe and found pipe end flange had broken ... Driver complained that gears weren't selecting and or moving.	Wear/Tear	11/29/2021	0	0	Hemmant	Brisbane Single & Loca	255	0	0
28153	C311	Mack Granite Day Cab - 6x4 - 4:inspected and found gears selected bu ...	Wear/Tear	12/29/2021	0	0	Hemmant	Brisbane Single & Loca	425	0	0
28522	C311	Mack Granite Day Cab - 6x4 - 4:Diff and turntable	Unsched.	01/19/2022	0	0	Hemmant	Brisbane Single & Loca	2295	0	0

28570	C311	Mack Granite Day Cab - 6x4 - 4:Steering column issue	Wear/Tear	01/22/2022	0	0	Hemmant	Brisbane Single & Loca	212.5	0	0
28572	C311	Mack Granite Day Cab - 6x4 - 4:Cradle install Truck A Service - Completed	Scheduled	01/24/2022	0	0	Hemmant	Brisbane Single & Loca	170	0	0
28976	C311	Mack Granite Day Cab - 6x4 - 4:spring - Part ordered ...	PM	02/10/2022	0	0	Hemmant	Brisbane Single & Loca	255	0	0
29146	C311	Mack Granite Day Cab - 6x4 - 4:Make lever to tighten ratchet straps Drivers side door needs new inner handle return	Unsched.	02/17/2022	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
29252	C311	Mack Granite Day Cab - 6x4 - 4:spring - Part ordered 11/02 - REPAIRED 21/2/22	Wear/Tear	02/21/2022	0	0	Hemmant	Brisbane Single & Loca	85	0	0
29263	C311	Mack Granite Day Cab - 6x4 - 4:camera installed Camera not attached to windscreen	Scheduled	02/21/2022	0	0	Hemmant	Brisbane Single & Loca	297.5	0	0
29439	C311	Mack Granite Day Cab - 6x4 - 4: replaced 3 container lockers	Unsched.	02/24/2022	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
31112	C311	Mack Granite Day Cab - 6x4 - 4:	Wear/Tear	05/09/2022	0	0	Hemmant	Brisbane Single & Loca	85	0	0
31117	C311	Mack Granite Day Cab - 6x4 - 4:Fixing mud guard and putting back on	Wear/Tear	05/09/2022	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
32027	C311	Mack Granite Day Cab - 6x4 - 4:Cab camera fallen off windscreen	Wear/Tear	06/06/2022	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
32357	C311	Mack Granite Day Cab - 6x4 - 4:TIGHT TURBO BOLTS TO MANIFOLD, MUDGUAR ... Truck B service MUG FLATS DONE, TIGHT JACK SHAFT YOKE NUT , Driver complained about trailer making weird	PM	06/22/2022	0	0	Hemmant	Brisbane Single & Loca	1105	329.78	0
32913	C311	Mack Granite Day Cab - 6x4 - 4:clanking noise at turntable.	Wear/Tear	07/11/2022	0	0	Hemmant	Brisbane Single & Loca	170	0	0
32971	C311	Mack Granite Day Cab - 6x4 - 4:Truck wont start.	Wear/Tear	07/13/2022	0	0	Hemmant	Brisbane Single & Loca	212.5	0	0
33024	C311	Mack Granite Day Cab - 6x4 - 4:Repairs to truck replace door strike , tight mud guard and fit candy	DA	07/22/2022	0	0	Hemmant	Brisbane Single & Loca	765	0	0
33027	C311	Mack Granite Day Cab - 6x4 - 4:stripes and wash truck. Replace driver door door lock.	Wear/Tear	07/15/2022	0	0	Hemmant	Brisbane Single & Loca	340	0	0
33039	C311	Mack Granite Day Cab - 6x4 - 4:Repair air leak under cab. FR 5118.	Wear/Tear	07/18/2022	0	0	Hemmant	Brisbane Single & Loca	765	0	0
33307	C311	Mack Granite Day Cab - 6x4 - 4:Seat base - no cushioning FR 5118.	Wear/Tear	09/20/2022	0	0	Hemmant	Brisbane Single & Loca	21.25	0	0
33309	C311	Mack Granite Day Cab - 6x4 - 4:UHF radio (80 channel) - not working Driver seat is stiff and no more cushion	Wear/Tear	09/20/2022	0	0	Hemmant	Brisbane Single & Loca	21.25	0	0
33321	C311	Mack Granite Day Cab - 6x4 - 4:Radio speaker is loosing volume.	Wear/Tear	07/26/2022	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
33483	C311	Mack Granite Day Cab - 6x4 - 4:Air leak	Wear/Tear	08/02/2022	0	0	Hemmant	Brisbane Single & Loca	255	0	0
33577	C311	Mack Granite Day Cab - 6x4 - 4:TRUCK WON'T START FR 5120. 1 - Engine brake - not releasing. Truck comes to a slow stop. Smoke coming out of	DA	08/06/2022	0	0	Hemmant	Brisbane Single & Loca	255	0	0
33854	C311	Mack Granite Day Cab - 6x4 - 4:exhaust ... FR 3827 + FR12404 + 12406 (6/9/22). 1 - Engine light on.	Wear/Tear	08/19/2022	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
34757	C311	Mack Granite Day Cab - 6x4 - 4:2 - Power steering - heavy & noisy FR 3828 + FR 12406 (6/9/22) + 12407 (6/9/22) + FR 12416 (16/9/22).	Wear/Tear	09/20/2022	0	0	Hemmant	Brisbane Single & Loca	255	0	0
34789	C311	Mack Granite Day Cab - 6x4 - 4:1 - Oil leaks - rear diff & engi ...	Unsched.	09/19/2022	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
34823	C311	Mack Granite Day Cab - 6x4 - 4:'Check transmission at next stop' Light coming on	Wear/Tear	08/31/2022	0	0	Hemmant	Brisbane Single & Loca	85	0	0
34916	C311	Mack Granite Day Cab - 6x4 - 4:Driver complaint: Noise coming from the engine bay	DA	09/05/2022	0	0	Hemmant	Brisbane Single & Loca	85	0	0
34944	C311	Mack Granite Day Cab - 6x4 - 4:derating FR 12405 (6/9/22) + FR 12406 (6/9/22). 1 - Engine light on - Noted WOH# 34757.	Wear/Tear	09/06/2022	0	0	Hemmant	Brisbane Single & Loca	595	0	0
35104	C311	Mack Granite Day Cab - 6x4 - 4:2 - Tensioner pulle ... FR 12407.	Wear/Tear	09/19/2022	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
35105	C311	Mack Granite Day Cab - 6x4 - 4:Shock absorbers leaking - position not specified	Wear/Tear	09/19/2022	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
35106	C311	Mack Granite Day Cab - 6x4 - 4:Tyre check req'd - R/H steer wearing on outer edge. FR 12413. 1 - Oil leak - front diff, appears major leak.	Wear/Tear	09/19/2022	0	0	Hemmant	Brisbane Port Tyres Brisbane Single & Loca	42.5	0	0
35107	C311	Mack Granite Day Cab - 6x4 - 4:2 - Rear diff - check stabiliser bushes. FR 12414 (15/9/22) + FR 12415 (15/9/22).	Wear/Tear	09/19/2022	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
35114	C311	Mack Granite Day Cab - 6x4 - 4:Fire extinguisher - no inspection tag OIL FILTER HOUSING PIPE NEED TO REPLACE 4	M/Request	10/27/2022	0	0	Hemmant	Brisbane Single & Loca	21.25	0	0
35185	C311	Mack Granite Day Cab - 6x4 - 4:ORINGS	Scheduled	09/20/2022	0	0	Hemmant	Brisbane Single & Loca	255	25	0

		Air conditioning - Fan only just working, not very cold.											
39891 C311	Mack Granite Day Cab - 6x4 - 4:	[FR 12371 - 24/3/23]	Wear/Tear	05/17/2023	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0		
40601 C311	Mack Granite Day Cab - 6x4 - 4:	driver complaint about engine light on dash	Unsched.	05/17/2023	0	0	Hemmant	Brisbane Single & Loca	4037.5	0	0		
		Steering - Pulling to the L/H. [FR 12374 - 11/4/23]											
40699 C311	Mack Granite Day Cab - 6x4 - 4:		Wear/Tear	05/15/2023	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0		
41022 C311	Mack Granite Day Cab - 6x4 - 4:	Air leak in air system	Scheduled	05/15/2023	0	0	Hemmant	Brisbane Single & Loca	680	0	0		
41116 C311	Mack Granite Day Cab - 6x4 - 4:	topped up oil ect	M/Request	05/17/2023	0	0	Hemmant	Brisbane Single & Loca	85	0	0		
		Warning light - Driver complained about check engine light.											
41212 C311	Mack Granite Day Cab - 6x4 - 4:	[FR 12375 - 23/5/23 + FR 12376 - 24/5/ ...	Unsched.	05/22/2023	0	0	Hemmant	Brisbane Single & Loca	85	0	0		
		Fluid leak - Engine light on. Heater hose is leaking on chassis rail under cab.											
41242 C311	Mack Granite Day Cab - 6x4 - 4:	[FR 12375 - 23/5/2 ...	Wear/Tear	06/12/2023	0	0	Hemmant	Brisbane Single & Loca	170	0	0		
		Engine warning light - Light is on.											
41339 C311	Mack Granite Day Cab - 6x4 - 4:	[FR 12379 - 27/5/23] See WO# 41212	Unsched.	08/24/2023	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0		
		1 - Warning light - "Check Engine" light on again.											
41405 C311	Mack Granite Day Cab - 6x4 - 4:	2 - Engine alarm - "Stop/Coolant Low" sounding. ...	Unsched.	08/15/2023	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0		
		1 - Vibration - Heavy vibration that intensifies when											
41554 C311	Mack Granite Day Cab - 6x4 - 4:	Foot is removed from accelerator especially a ...	Unsched.	06/13/2023	0	0	Hemmant	Brisbane Single & Loca	170	0	0		
		Tablet cradle - Installation req'd.											
41591 C311	Mack Granite Day Cab - 6x4 - 4:	NO FR.	Scheduled	06/12/2023	0	0	Hemmant	Brisbane Single & Loca	85	0	0		
		Headlight - R/H not working.											
41674 C311	Mack Granite Day Cab - 6x4 - 4:	[FR 12382 - 9/6/23]	Unsched.	06/08/2023	0	0	Hemmant	Brisbane Single & Loca	85	0	0		
		Bad vibration under load.											
41858 C311	Mack Granite Day Cab - 6x4 - 4:	[MFD - A.N - 14/6/23]	Unsched.	06/29/2023	0	0	Hemmant	Brisbane Single & Loca	85	0	0		
		Mudguard - Axle 3 R/H mudguard has been ripped off mounts & destroyed - needs replacing.											
42554 C311	Mack Granite Day Cab - 6x4 - 4:	NO FR.	DA	07/06/2023	0	0	Hemmant	Brisbane Single & Loca	170	0	0		
		Axle alignment - Drive axles out of alignment. + Steering is very heavy.											
42832 C311	Mack Granite Day Cab - 6x4 - 4:	[FR 12385 - 13/7/23 + FR 1 ...	Wear/Tear	09/08/2023	0	0	Hemmant	Brisbane Single & Loca	425	0	0		
		Brakes - Not working smoothly, applies instantly.											
42888 C311	Mack Granite Day Cab - 6x4 - 4:	[FR 12386 - 14/7/23]	Unsched.	08/16/2023	0	0	Hemmant	Brisbane Single & Loca	595	0	0		
		Indicator - L/H bonnet side indicator not working.											
43245 C311	Mack Granite Day Cab - 6x4 - 4:	[FR 12368 - 25/7/23]	Wear/Tear	08/15/2023	0	0	Hemmant	Brisbane Single & Loca	113.3333305	119.92	0		
		Driveline vibration - vibration appears to be in diff/axle area. [FR 12368 - 25/7/23]											
43246 C311	Mack Granite Day Cab - 6x4 - 4:		Wear/Tear	09/08/2023	0	0	Hemmant	Brisbane Single & Loca	765	0	0		
43669 C311	Mack Granite Day Cab - 6x4 - 4:	B Service - Truck Breakdown - Truck stalled in gear at Americold. Air dumped from transmission.	PM	08/15/2023	0	0	Hemmant	Brisbane Single & Loca	255	73.3	0		
		Breakdown - Truck stalled in gear at Americold. Air dumped from transmission.											
45170 C311	Mack Granite Day Cab - 6x4 - 4:	[FR 12389 - 5/10/23]	Unsched.	10/05/2023	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0		
		Coolant leak - Water pump leaking. [FR 6635 - 18/11/23]											
45495 C311	Mack Granite Day Cab - 6x4 - 4:	Coolant leak - Coolant level drops during ...	Wear/Tear	11/25/2023	0	0	Hemmant	Brisbane Single & Loca	765	0	0		
		Bonnet - Chrome trim around radiator intake fell off & was run over. Totally destroyed.											
45962 C311	Mack Granite Day Cab - 6x4 - 4:	[FR 12391 - ...	DA	04/16/2024	0	0	Hemmant	Brisbane Single & Loca	510	0	0		
		Shudder - Drive line shudder/vibration at 75-90 km/h.											
46414 C311	Mack Granite Day Cab - 6x4 - 4:	[FR 12393 - 22/11/23]	Unsched.	02/27/2024	0	0	Hemmant	Brisbane Single & Loca	1742.5	0	0		
47431 C311	Mack Granite Day Cab - 6x4 - 4:	Need a new battery cable.	Unsched.	01/10/2024	0	0	Hemmant	Brisbane Single & Loca	170	0	0		
47889 C311	Mack Granite Day Cab - 6x4 - 4:	D Service - Truck	PM	02/29/2024	0	0	Hemmant	Brisbane Single & Loca	170	0	0		
48169 C311	Mack Granite Day Cab - 6x4 - 4:	battery not charging.	M/Request	02/21/2024	0	0	Hemmant	Brisbane Single & Loca	85	0	0		
48187 C311	Mack Granite Day Cab - 6x4 - 4:	batteries loosed.	MFD	02/12/2024	0	0	Hemmant	Brisbane Single & Loca	170	0	0		
48434 C311	Mack Granite Day Cab - 6x4 - 4:	Air leaks	Workshop	02/23/2024	0	0	Hemmant	Brisbane Single & Loca	425	0	0		
48463 C311	Mack Granite Day Cab - 6x4 - 4:	get the truck ready for test drive. Trailer plug - Plug pins broken.	Scheduled	02/26/2024	0	0	Hemmant	Brisbane Single & Loca	1700	0	0		
48561 C311	Mack Granite Day Cab - 6x4 - 4:	[FR 17109 - 29/2/24]	DA	02/28/2024	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0		

48586	C311	Mack Granite Day Cab - 6x4 - 4:	Parts pick up (Mack)	Workshop	03/01/2024	0	0	Hemmant	Brisbane Single & Loca	85	0	0
49160	C311	Mack Granite Day Cab - 6x4 - 4:	Window - R/H window will not go up. [FR 12395 - 25/3/24]	R/Request	03/26/2024	0	0	Hemmant	Brisbane Single & Loca	85	0	0
49653	C311	Mack Granite Day Cab - 6x4 - 4:	Warning light - Check engine light displaying. + Light coming on at start up & during run. [FR 1239 ...	Wear/Tear	06/20/2024	0	0	Hemmant	Brisbane Single & Loca	21.25	0	0
49802	C311	Mack Granite Day Cab - 6x4 - 4:	Tyre check req'd - Drive 1 R/H Outer - Tyre described as flat. [FR 12398 - 24/4/24]	Unsched.	04/24/2024	0	0	Hemmant	Brisbane Single & Loca	255	0	0
50309	C311	Mack Granite Day Cab - 6x4 - 4:	steer Tyre flat Headlight - R/H light not working. [FR 17304 - 21/5/24] Waiting for request to be supplied.	Tyres - UN	05/16/2024	0	0	Hemmant	Brisbane Port Tyres Brisbane Single & Loca	85	0	0
50431	C311	Mack Granite Day Cab - 6x4 - 4:	Marker light - R/H inner cab roof marker light not working. [FR 17309 - 20/6/24]	Wear/Tear	06/20/2024	0	0	Hemmant	Brisbane Single & Loca	21.25	0	0
51200	C311	Mack Granite Day Cab - 6x4 - 4:	Radio - Hanging clip for hand piece is broken. [FR 17310 - 20/6/24]	Wear/Tear	06/24/2024	0	0	Hemmant	Brisbane Single & Loca	85	0	0
51203	C311	Mack Granite Day Cab - 6x4 - 4:	Air fitting - Hose connection piece needs to be replaced. [FR 17312 - 20/6/24]	Wear/Tear	06/24/2024	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
51204	C311	Mack Granite Day Cab - 6x4 - 4:	Horn - Horn doesn't work. Air or electric horn NOT specified. [FR 17313 - 20/6/24]	Wear/Tear	06/25/2024	0	0	Hemmant	Brisbane Single & Loca	85	0	0
51205	C311	Mack Granite Day Cab - 6x4 - 4:	Drain cable - Air tank drain cable broken. [FR 17314 - 20/6/24]	Wear/Tear	06/24/2024	0	0	Hemmant	Brisbane Single & Loca	170	0	0
51206	C311	Mack Granite Day Cab - 6x4 - 4:	C/D Service - Truck - Brisbane [FR 17316 - 21/6/24]	Wear/Tear	06/24/2024	0	0	Hemmant	Brisbane Single & Loca	85	0	0
51210	C311	Mack Granite Day Cab - 6x4 - 4:	Odometer Reading - 921827 km Steering - Power steering not working. [FR 17316 - 21/6/24]	PM	06/25/2024	0	0	Hemmant	Brisbane Single & Loca	1870	0	0
51227	C311	Mack Granite Day Cab - 6x4 - 4:	Air conditioning - Not working. [NO more details supplied. Check the cabin filter.]	R/Request	06/25/2024	0	0	Hemmant	Brisbane Single & Loca	170	0	0
51228	C311	Mack Granite Day Cab - 6x4 - 4:	[FR 17316 - 21 ...	R/Request	06/24/2024	0	0	Hemmant	Brisbane Single & Loca	1147.5	0	0
51355	C311	Mack Granite Day Cab - 6x4 - 4:	GREASE NIPPLE BROKEN ON JACK SHAFT	MFD	06/24/2024	0	0	Hemmant	Brisbane Single & Loca	340	0	0
51356	C311	Mack Granite Day Cab - 6x4 - 4:	SHOCKIE BROKEN	MFD	06/24/2024	0	0	Hemmant	Brisbane Single & Loca	170	0	0
51363	C311	Mack Granite Day Cab - 6x4 - 4:	coolant leak Air leak - Leak is under R/H side of cab. [NO Information as to severity supplied.]	Unsched.	06/24/2024	0	0	Hemmant	Brisbane Single & Loca	170	0	0
51693	C311	Mack Granite Day Cab - 6x4 - 4:	[FR 17317 - 8/7 ...	R/Request	07/10/2024	0	0	Hemmant	Brisbane Single & Loca	170	0	0
51719	C311	Mack Granite Day Cab - 6x4 - 4:	Derating - Breakdown on Bruce Hwy at Morayfield - Truck restarted twice, runs ok for a couple of km ...	Unsched.	07/09/2024	0	0	Hemmant	Brisbane Single & Loca	1331.666661	0	0
51760	C311	Mack Granite Day Cab - 6x4 - 4:	exhaust flex leaking.	MFD	07/10/2024	0	0	Hemmant	Brisbane Single & Loca	510	0	0
51780	C311	Mack Granite Day Cab - 6x4 - 4:	Truck derating - Breakdown at Belmont Pads - Engine over revving (2500rpm?) & derating. Same issues ... Steering - very heavy steering. Steering box? Locks up at low speeds.	Unsched.	07/11/2024	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
51849	C311	Mack Granite Day Cab - 6x4 - 4:	[FR 17318 - 15/7/24 + FR 1732 ... Turntable - No adjustment left in mechanism, needs a re-kit.	Wear/Tear	07/23/2024	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0
51988	C311	Mack Granite Day Cab - 6x4 - 4:	[MFD - A.N - 22/7/24 + FR 17321 - 23/ ...	Wear/Tear	07/23/2024	0	0	Hemmant	Brisbane Single & Loca	340	0	0
52049	C311	Mack Granite Day Cab - 6x4 - 4:	Header tank leaking. Gear selection - Selection not functioning properly, select 1st gear & reverse is engaged.	MFD	07/23/2024	0	0	Hemmant	Brisbane Single & Loca	255	0	0
52414	C311	Mack Granite Day Cab - 6x4 - 4:	[FR 148 ... Trailer plug - Brake lights working, indicators are not working.	Wear/Tear	08/09/2024	0	0	Hemmant	Brisbane Single & Loca	807.5	0	0
52541	C311	Mack Granite Day Cab - 6x4 - 4:	[FR 17322 - 13/8/24] + Scheduled ... Air leak - Possible air dryer issue.	Wear/Tear	09/25/2024	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
52604	C311	Mack Granite Day Cab - 6x4 - 4:	[FR17324 - 15/8/24] Roof top marker - Roof marker light is out/not working. NO Pos'n supplied.	Wear/Tear	08/22/2024	0	0	Hemmant	Brisbane Single & Loca	0	0	0
52606	C311	Mack Granite Day Cab - 6x4 - 4:	[FR 17323 - 15/8/24] + ... air leak.	Wear/Tear	09/26/2024	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0
52634	C311	Mack Granite Day Cab - 6x4 - 4:	See WO# 52604.	Unsched.	08/15/2024	0	0	Hemmant	Brisbane Single & Loca	170	0	0

		Coolant leak - Coolant level is below the minimum level. + Header tank appears to be cracked.										
52698	C311	Mack Granite Day Cab - 6x4 - 4:[FR 1 ...	Wear/Tear	08/27/2024	0	0	Hemmant	Brisbane Single & Loca	255	0	0	
52827	C311	Mack Granite Day Cab - 6x4 - 4:low coolant low	Unsched.	08/22/2024	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0	
		Steering - steering wheel heavy to turn, especially when reversing.										
52911	C311	Mack Granite Day Cab - 6x4 - 4:[FR 17332 - 27/8/24 + FR 17335 ...	R/Request	10/15/2024	0	0	Hemmant	Brisbane Single & Loca	85	0	0	
		Window - R/H door window not going all the down.										
52912	C311	Mack Granite Day Cab - 6x4 - 4:[FR 17331 - 26/8/24 + FR 17336 - 6/9/24] + Schedu ...	Wear/Tear	09/25/2024	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0	
53016	C311	Mack Granite Day Cab - 6x4 - 4:electrical issue on back rear bar	Unsched.	08/28/2024	0	0	Hemmant	Brisbane Single & Loca	425	0	0	
53426	C311	Mack Granite Day Cab - 6x4 - 4:right hand headlight blown	Unsched.	09/12/2024	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0	
		Headlight - NO Pos'n supplied. Light not working.										
53456	C311	Mack Granite Day Cab - 6x4 - 4:[FR 17339 - 13/9/24]	R/Request	10/12/2024	0	0	Hemmant	Brisbane Single & Loca	42.5	0	0	
53759	C311	Mack Granite Day Cab - 6x4 - 4:Engine brake not working	Scheduled	09/25/2024	0	0	Hemmant	Brisbane Single & Loca	425	0	0	
		Fuel cap thigten hard and also mirror drive side										
53773	C311	Mack Granite Day Cab - 6x4 - 4:loose	Scheduled	09/25/2024	0	0	Hemmant	Brisbane Single & Loca	127.5	0	0	
53962	C311	Mack Granite Day Cab - 6x4 - 4:air leak from back of cab	Unsched.	10/03/2024	0	0	Hemmant	Brisbane Single & Loca	170	0	0	
		Tyre check req'd - Drive axle 2 L/H Inner & Outer -										
54061	C311	Mack Granite Day Cab - 6x4 - 4:New tyres requested. NO Justification supplied. ...	Tyres - UN	10/14/2024	0	0	Brisbane Port Tyres	Brisbane Single & Loca	63.75	680	0	
		Windscreen - Preparations for R/H windscreen pane										
54115	C311	Mack Granite Day Cab - 6x4 - 4:replacement. Remove external sun visor & internal ...	R/Request	10/14/2024	0	0	Hemmant	Brisbane Single & Loca	85	0	0	
54125	C311	Mack Granite Day Cab - 6x4 - 4:broken and faulty brake booster.	Unsched.	10/09/2024	0	0	Hemmant	Brisbane Single & Loca	1105	0	0	
		right hand window not working correctly.										
54247	C311	Mack Granite Day Cab - 6x4 - 4:[MFD - A.N -14/10/24]	R/Request	10/15/2024	0	0	Hemmant	Brisbane Single & Loca	552.5	0	0	
		Air conditioning - Air con not working again.										
54311	C311	Mack Granite Day Cab - 6x4 - 4:[FR 17343 - 24/9/24]	Unsched.	10/15/2024	0	0	Hemmant	Brisbane Single & Loca	510	0	0	
		rear lights bracket damaged.										
54365	C311	Mack Granite Day Cab - 6x4 - 4:[MFD - D.C - 16/10/24]	DA	10/16/2024	0	0	Hemmant	Brisbane Single & Loca	340	0	0	
		Trailer lights - not working.										
54869	C311	Mack Granite Day Cab - 6x4 - 4:[FR 22853 - 4/11/24]	Wear/Tear	11/21/2024	0	0	Hemmant	Brisbane Single & Loca	85	0	0	
		Gearbox - gearbox is neutralizing while in motion.										
55375	C311	Mack Granite Day Cab - 6x4 - 4:[FR 22854 - 22/11/24]	Unsched.	11/21/2024	0	0	Hemmant	Brisbane Single & Loca	340	0	0	
		Gearbox - Box keeps selecting neutral when driving.										
55585	C311	Mack Granite Day Cab - 6x4 - 4:Truck neutralized while going up Gateway bridge ...	Wear/Tear	11/28/2024	0	0	Hemmant	Brisbane Single & Loca	170	0	0	
		Vibration - Extreme vibration through steering & whole truck at 80-95 km/h.										
55588	C311	Mack Granite Day Cab - 6x4 - 4:[FR 22857 - 27/11/24]	Wear/Tear	11/28/2024	0	0	Hemmant	Brisbane Single & Loca	1190	0	0	
		Steering - Steering is very heavy, particularly when loaded at low speeds & when reversing.										
55589	C311	Mack Granite Day Cab - 6x4 - 4:[FR 22 ...	Wear/Tear	11/28/2024	0	0	Hemmant	Brisbane Single & Loca	170	0	0	
		Power loss - Not specified if it is engine or electrical power loss.										
55774	C311	Mack Granite Day Cab - 6x4 - 4:[FR 22861 - 5/12/24]	R/Request	12/21/2024	0	0	Hemmant	Brisbane Single & Loca	340	0	0	
		Mudguard - Damage - rh rear mudguard hanging off.										
55880	C311	Mack Granite Day Cab - 6x4 - 4:NO FR Supplied.	DA	12/11/2024	0	0	Hemmant	Brisbane Single & Loca	85	0	0	
		Seat - Front of seat tilted upwards in a very uncomfortable position.										
56034	C311	Mack Granite Day Cab - 6x4 - 4:[FR 22866 - 18/12/24] + [FR ...	Wear/Tear	12/18/2024	0	0	Hemmant	Brisbane Single & Loca	212.5	0	0	
		Air leak - leaking from the trailer connection fitting.										
56037	C311	Mack Granite Day Cab - 6x4 - 4:[FR 22868 - 18/12/24]	DA	12/19/2024	0	0	Hemmant	Brisbane Single & Loca	170	0	0	
		Air leak - Leak is on L/H side under the cab. [Air Dryer issue?]										
56038	C311	Mack Granite Day Cab - 6x4 - 4:[FR 22869 - 18/12/24]	Wear/Tear	12/19/2024	0	0	Hemmant	Brisbane Single & Loca	425	0	0	
		Steering - No power steering/heavy when manoeuvring at slow speed with a load on. Steering										
56066	C311	Mack Granite Day Cab - 6x4 - 4:pump app ...	Wear/Tear	01/06/2025	0	0	Hemmant	Brisbane Single & Loca	1827.5	0	0	

56067	C311	Mack Granite Day Cab - 6x4 - 4: [FR 22863 ... Mudguard - Damage - Drive axle 2 R/H guard loose due to contacting a trailer goose neck.	DA	12/19/2024	0	0	Hemmant	Brisbane Single & Loca	170	0	0
56473	C311	Mack Granite Day Cab - 6x4 - 4: bar to chasis - air and hose line mounting bracket , needed locking isolator installation requires and trailers light bracket	M/Request	01/13/2025	0	0	Hemmant	Brisbane Single & Loca	651.666661	0	0
56515	C311	Mack Granite Day Cab - 6x4 - 4: installation	Unsched.	01/10/2025	0	0	Hemmant	Brisbane Single & Loca	595	0	0
56541	C311	Mack Granite Day Cab - 6x4 - 4: ****Tyre Check Req'd - steer tyres worn.	Unsched.	01/14/2025	0	0	Hemmant	Brisbane Single & Loca	425	0	0
56556	C311	Mack Granite Day Cab - 6x4 - 4: steering hard to turn Jesse.	Unsched.	01/14/2025	0	0	Hemmant	Brisbane Single & Loca	85	0	0
56610	C311	Mack Granite Day Cab - 6x4 - 4: [FR 22871 - 15/01/2025] Steering - Vibrations at High Speed - 85km +. Turbo - Driver States there is no Boost - Only got to 1/2.	R/Request	01/30/2025	0	0	Hemmant	Brisbane Single & Loca	1360	0	0
56614	C311	Mack Granite Day Cab - 6x4 - 4: [FR 22870 - 15/01/2025] Headlight - L/H light not working.	R/Request	01/30/2025	0	0	Hemmant	Brisbane Single & Loca	85	0	0
57478	C311	Mack Granite Day Cab - 6x4 - 4: [FR 22873 - 26/2/25]	Wear/Tear	03/14/2025	0	0	Hemmant	Brisbane Single & Loca	85	0	0
									Sum = \$113,999.	Sum = \$29,812.07	Sum = \$0.00