

W/O No	Asset No	Asset Description	Description	Job Type	Finished Date/Time	Downtime	Repair Time	Component Code	Department	Parent Asset	Labour Costs	Material Costs	Other Costs
			TRUCK ADBLUE- A Service-10,000KMS A Service completed										
	2498 1402	Mack Super-Liner Sleeper Cab	- Actual 23619kms	PM	07/13/2018	0	0		Toowoomba	General Freight	97.5	87.1	0
			TRUCK ADBLUE- A Service-10,000KMS A Service completed										
	2558 1402	Mack Super-Liner Sleeper Cab	- Actual 30678kms	PM	07/23/2018	0	0		Hemmant	General Freight	0	87.1	0
			TRUCK ADBLUE- B Service- 40,000KMS B Service Completed										
	2622 1402	Mack Super-Liner Sleeper Cab	- Actual 37960	PM	08/09/2018	0	0		Hemmant	General Freight	157.5	948.55	0
			TRUCK ADBLUE- A Service-10,000KMS A Service completed										
	3381 1402	Mack Super-Liner Sleeper Cab	- Actual 50827kms	PM	08/31/2018	0	0		Hemmant	General Freight	97.5	87.1	0
			TRUCK ADBLUE- B Service- 40,000KMS B Service completed										
	3451 1402	Mack Super-Liner Sleeper Cab	- Actual 59483kms	PM	09/24/2018	0	0		Hemmant	General Freight	157.5	0	0
			TRUCK ADBLUE- A Service-10,000KMS A Service completed										
	3482 1402	Mack Super-Liner Sleeper Cab	- Actual 72057kms	PM	10/06/2018	0	0		Hemmant	General Freight	97.5	87.1	0
			TRUCK ADBLUE- A Service-10,000KMS A Service completed										
	3543 1402	Mack Super-Liner Sleeper Cab	- Actual 82077kms	PM	10/19/2018	0	0		Hemmant	General Freight	97.5	87.1	0
	4032 1402	Mack Super-Liner Sleeper Cab	- TRUCK ADBLUE- B Service- 60,000KMS	PM	12/15/2018	0	0		Hemmant	General Freight	157.5	772.15	0
	4243 1402	Mack Super-Liner Sleeper Cab	- Replace broken shockey Bolts on RHC Drive	R & M	01/02/2019	0	0		Toowoomba	General Freight	52.5	0	0
	4568 1402	Mack Super-Liner Sleeper Cab	- Change Tyres	R & M	01/24/2019	0	0		Toowoomba	General Freight	35	0	0
	4576 1402	Mack Super-Liner Sleeper Cab	- TRUCK ADBLUE- A Service-10,000KMS	PM	01/24/2019	0	0		Hemmant	General Freight	200	83.1	0
			Hook up laptop and check Adblue fault, ad blue tank sender unit U/S. Truck to be booked in for warr ...	R & M	04/02/2019	0	0		Toowoomba	General Freight	32.5	25	0
			TRUCK ADBLUE- A Service-10,000KMS A Service Completed										
	5890 1402	Mack Super-Liner Sleeper Cab	- Actual 113143kms	PM	04/16/2019	0	0		Hemmant	General Freight	65	74	0
			TRUCK ADBLUE- A Service-10,000KMS A Service Completed										
	6294 1402	Mack Super-Liner Sleeper Cab	- Actual 120785kms	PM	05/16/2019	0	0		Hemmant	General Freight	700	561.395	0
			TRUCK ADBLUE- C Service -90,000KMS C Service Completed										
	6295 1402	Mack Super-Liner Sleeper Cab	- Actual 120785kms	PM	05/16/2019	0	0		Hemmant	General Freight	700	2014.8	0
			TRUCK ADBLUE- A Service-10,000KMS A Service Completed										
	6874 1402	Mack Super-Liner Sleeper Cab	- Actual 130936kms.	PM	06/17/2019	0	0		Hemmant	General Freight	97.5	74	0
	6919 1402	Mack Super-Liner Sleeper Cab	- Tried to adjust K factor from 95-100	R & M	06/19/2019	0	0		Toowoomba	General Freight	97.5	25	0
	6941 1402	Mack Super-Liner Sleeper Cab	- Set speed limiter.	R & M	06/20/2019	0	0		Toowoomba	General Freight	65	25	0
			TRUCK ADBLUE- A Service-10,000KMS A Service Completed										
	7162 1402	Mack Super-Liner Sleeper Cab	- Actual 142426kms.	PM	07/05/2019	0	0		Hemmant	General Freight	192.5	74	0
			Found exhaust pipe damaged from stack bracket impacting top of pipe, removed pipe A& mounting										
	7290 1402	Mack Super-Liner Sleeper Cab	- brack ...	R & M	07/16/2019	0	0		Toowoomba	General Freight	150	0	0
			TRUCK ADBLUE- B Service- 60,000KMS B Service Completed										
	7432 1402	Mack Super-Liner Sleeper Cab	- Actual 149123kms.	PM	07/29/2019	0	0		Hemmant	General Freight	337.5	869.87	0
			TRUCK ADBLUE- A Service-10,000KMS A Service Completed										
	7743 1402	Mack Super-Liner Sleeper Cab	- Actual 162662kms.	PM	08/19/2019	0	0		Hemmant	General Freight	75	74	0
			Check engine mounts, measure difference in height, try do wheel alignment.										
	7929 1402	Mack Super-Liner Sleeper Cab	- try do wheel alignment.	R & M	08/28/2019	0	0		Toowoomba	General Freight	130	0	0
			TRUCK ADBLUE- A Service-10,000KMS. A Service Completed.										
	8217 1402	Mack Super-Liner Sleeper Cab	- Actual 172332kms.	PM	09/12/2019	0	0		Hemmant	General Freight	130	95.23	0
			Hook up roadtrain, adjust dolly lines & fit rubber, check lights.										
	8546 1402	Mack Super-Liner Sleeper Cab	- check lights.	R & M	09/25/2019	0	0		Toowoomba	General Freight	75	0	0
	8846 1402	Mack Super-Liner Sleeper Cab	- Assist Auto Elec with A/C repairs.	R & M	10/11/2019	0	0		Toowoomba	General Freight	75	0	0
			TRUCK ADBLUE- B Service- 60,000KMS B Service Completed										
	8928 1402	Mack Super-Liner Sleeper Cab	- Actual 180024kms	PM	10/14/2019	0	0		Hemmant	General Freight	262.5	313.71	0
	9044 1402	Mack Super-Liner Sleeper Cab	- Assist auto electrical A/C repairs.	R & M	10/18/2019	0	0		Toowoomba	General Freight	75	0	0
			Report LHS door lock U/S check operation found LO/S order parts through Ben once arrive fit parts &										
	9407 1402	Mack Super-Liner Sleeper Cab	- ...	R & M	10/31/2019	0	0		Toowoomba	General Freight	32.5	0	0

9780	I402	Mack Super-Liner Sleeper Cab - Tap longer thread onto M12x60 bolt & cut down to size, fit bolt to RHS Lpipe mounting bracket on RH ...	R & M	11/13/2019	0	0	Toowoomba	General Freight	56.25	25	0
		TRUCK ADBLUE- A Service-10,000KMS A Service Completed Actual 193125km .									
10040	I402	Mack Super-Liner Sleeper Cab - Drill & Fit nut serts to w ...	PM	11/22/2019	0	0	Hemmant	General Freight	262.5	117.6	0
		TRUCK ADBLUE- A Service-10,000KMS A Service Completed									
10547	I402	Mack Super-Liner Sleeper Cab - Actual 200063kms	PM	12/11/2019	0	0	Hemmant	General Freight	75	74	0
		LHS exhaust stack mounting not secure at base, removed bolts, re-tapped threads into L-pipe & refit									
10694	I402	Mack Super-Liner Sleeper Cab - ...	R & M	12/17/2019	0	0	Toowoomba	General Freight	75	25	0
11118	I402	Mack Super-Liner Sleeper Cab - Puncher Repair on POS7 Drive 3 x little nails later	Tyre - S/S	01/15/2020	0	0	Hemmant	General Freight	52.5	0	0
		TRUCK ADBLUE- B Service- 60,000KMS B Service Completed									
12108	I402	Mack Super-Liner Sleeper Cab - Actual 209643kms.	PM	02/10/2020	0	0	Hemmant	General Freight	262.5	269.79	0
		TRUCK ADBLUE- A Service-10,000KMS A Service Completed									
12753	I402	Mack Super-Liner Sleeper Cab - Actual 220948kms.	PM	02/29/2020	0	0	Hemmant	General Freight	230	72.71	0
12870	I402	Mack Super-Liner Sleeper Cab - Strip & fit 8 x drive tyres.	R & M	02/25/2020	0	0	Hemmant	General Freight	230	0	0
13053	I402	Mack Super-Liner Sleeper Cab - Remove steer tyres, spin on rim & fit balancing bags, swap rims side to side & pump up to 110psi, t ...	R & M	03/12/2020	0	0	Hemmant	General Freight	115	0	0
		TRUCK ADBLUE- A Service-10,000KMS A Service Completed.									
13738	I402	Mack Super-Liner Sleeper Cab - Actual 230550kms. Hook up trailers and pre ...	PM	04/06/2020	0	0	Hemmant	General Freight	230	72.71	0
13945	I402	Mack Super-Liner Sleeper Cab - Pick up parts from Gibbs, repair broken sidelight LHR	R & M	04/14/2020	0	0	Hemmant	General Freight	80	0	0
14171	I402	Mack Super-Liner Sleeper Cab - Flipped the steer tyres.	R & M	04/21/2020	0	2.0	Hemmant	General Freight	52.5	0	0
14413	I402	Mack Super-Liner Sleeper Cab - Repair air leaks	R & M	05/01/2020	0	0	Hemmant	General Freight	75	0	0
14502	I402	Mack Super-Liner Sleeper Cab - Drill out & remove broken bolt in LHS exh. stack	R & M	05/05/2020	0	0	Hemmant	General Freight	187.5	25	0
15267	I402	Mack Super-Liner Sleeper Cab - mount, fit 2 x new bolts. Locate airleak behind tr ...	R & M	05/27/2020	0	0	Hemmant	General Freight	37.5	0	0
16284	I402	Mack Super-Liner Sleeper Cab - check KM's repair request	R & M	08/27/2020	0	0	Hemmant	General Freight	42.5	25	0
17164	I402	Mack Super-Liner Sleeper Cab - program	PM	10/14/2020	0	0	Toowoomba	General Freight	42.5	0	0
17890	I402	Mack Super-Liner Sleeper Cab - A service	PM	10/14/2020	0	0	Toowoomba	General Freight	42.5	0	0
18370	I402	Mack Super-Liner Sleeper Cab - 2 x runout tyres	Tyre - S/S	11/09/2020	0	0	Brisbane Port Tyres	General Freight	70	70	0
18370	I402	Mack Super-Liner Sleeper Cab - B service									
18370	I402	Mack Super-Liner Sleeper Cab - Klms - 289119	PM	11/24/2020	0	0	Toowoomba	General Freight	765	329.66	0
19734	I402	Mack Super-Liner Sleeper Cab - FIT 2X NEW STEER TYRES	Tyre - S/S	01/21/2021	0	0	Toowoomba	General Freight	127.5	50	0
		A-svc									
21256	I402	Mack Super-Liner Sleeper Cab - 309476.5Km 5280Hr	Scheduled	03/24/2021	0	0	Toowoomba	General Freight	127.5	7.57	0
23701	I402	Mack Super-Liner Sleeper Cab - B service done 335043klm	Scheduled	06/29/2021	0	0	Toowoomba	General Freight	382.5	691.62	0
		Truck B service see w/o 23701									
23703	I402	Mack Super-Liner Sleeper Cab - B service done 335043klm	PM	06/29/2021	0	0	Hemmant	General Freight	212.5	0	0
23720	I402	Mack Super-Liner Sleeper Cab - Assist tony with 402 b service.	Scheduled	06/30/2021	0	0	Toowoomba	General Freight	357	0	0
24052	I402	Mack Super-Liner Sleeper Cab - Truck B service	PM	06/29/2021	0	0	Hemmant	General Freight	255	329.78	0
25108	I402	Mack Super-Liner Sleeper Cab - Driver complained of coolant smell in cabin. Believed he had a heater core leak as "the smell stopp ...	Unsched.	08/30/2021	0	0	Toowoomba	General Freight	170	0	0
25116	I402	Mack Super-Liner Sleeper Cab - Unit came back in presenting with coolant leakage at trans cooler (machine had been checked 2 days ...	Unsched.	08/30/2021	0	0	Toowoomba	General Freight	340	0	0
25119	I402	Mack Super-Liner Sleeper Cab - Trans cooler arrived, fitted to truck and filled cooling system, pressure tested and checked for le ...	Unsched.	08/30/2021	0	0	Toowoomba	General Freight	170	0	0
25821	I402	Mack Super-Liner Sleeper Cab - Rectified air leak at transmission, hose supplying air to trans rubbed through. Removed and replace ...	Unsched.	09/23/2021	0	0	Toowoomba	General Freight	85	0	0
		Both exhaust elbows cracked through on bend. Removed elbows and fitted new elbows.									
26169	I402	Mack Super-Liner Sleeper Cab - fr 516: exhaust ...	Unsched.	10/07/2021	0	0	Toowoomba	General Freight	170	0	0
26506	I402	Mack Super-Liner Sleeper Cab - Inspect 402 bullbar lights cut wires on bullbar lights -rewire light and inspect non working spottie ...	DA	10/19/2021	0	0	Toowoomba	General Freight	170	0	0
		Fault code on dash. Back pressure sensor fault,									
26644	I402	Mack Super-Liner Sleeper Cab - replaced sensor.		10/25/2021	0	0	Toowoomba	General Freight	85	0	0
27081	I402	Mack Super-Liner Sleeper Cab - ROTATE STEERS	Wear/Tear	11/11/2021	0	0	Brisbane Port Tyres	General Freight	42.5	0	0

			Driver complained about check engine light on. Plugged in Tech Tool and found several Active fault									
31338	I402	Mack Super-Liner Sleeper Cab - ...	Wear/Tear	05/16/2022	0	0	Toowoomba	General Freight	170	0	0	
32177	I402	Mack Super-Liner Sleeper Cab - Truck B service	PM	06/11/2022	0	0	Toowoomba	General Freight	680	0	0	
32886	I402	Mack Super-Liner Sleeper Cab - KM Check	Scheduled	07/08/2022	0	0	Toowoomba	General Freight	0	0	0	
33385	I402	Mack Super-Liner Sleeper Cab - Truck A Service	PM	07/20/2022	0	0	Hemmant	General Freight	850	0	0	
35065	I402	Mack Super-Liner Sleeper Cab - km check	Scheduled	08/19/2022	0	0	Toowoomba	General Freight	0	0	0	
35307	I402	Mack Super-Liner Sleeper Cab - KM Check	Scheduled	09/19/2022	0	0	Toowoomba	General Freight	0	0	0	
35356	I402	Mack Super-Liner Sleeper Cab - KM Check	Scheduled	09/23/2022	0	0	Toowoomba	General Freight	0	0	0	
35608	I402	Mack Super-Liner Sleeper Cab - KM Check	Scheduled	10/05/2022	0	0	Toowoomba	General Freight	0	0	0	
35693	I402	Mack Super-Liner Sleeper Cab - KM Check	Scheduled	10/07/2022	0	0	Toowoomba	General Freight	0	0	0	
36221	I402	Mack Super-Liner Sleeper Cab - KM Check	Scheduled	10/28/2022	0	0	Toowoomba	General Freight	0	0	0	
36406	I402	Mack Super-Liner Sleeper Cab - KM Check	Scheduled	11/07/2022	0	0	Toowoomba	General Freight	21.25	0	0	
36755	I402	Mack Super-Liner Sleeper Cab - KM Check	Scheduled	11/11/2022	0	0	Toowoomba	General Freight	0	0	0	
			Wash trailers, fit 2 new tyres, repair guards, replace									
36856	I402	Mack Super-Liner Sleeper Cab - guard brackets, replace mud flaps	Wear/Tear	11/23/2022	0	0	Toowoomba	General Freight	765	0	0	
37150	I402	Mack Super-Liner Sleeper Cab - Truck - C Service	PM	12/08/2022	0	0	Hemmant	General Freight	2337.5	0	0	
			Truck - B service (Driver noted service due FR 8981 -									
37151	I402	Mack Super-Liner Sleeper Cab - 21/3/23)	PM	05/17/2023	0	0	Toowoomba	General Freight	510	0	0	
			Went to pick up 402 from wheel alignment and truck									
37459	I402	Mack Super-Liner Sleeper Cab - had flat batteries, tried to jump start, unsucce ...	PM	12/15/2022	0	0	Toowoomba	General Freight	467.5	0	0	
37760	I402	Mack Super-Liner Sleeper Cab - no start	DA	01/03/2023	0	0	Toowoomba	General Freight	255	0	0	
38210	I402	Mack Super-Liner Sleeper Cab - no engine break going down the range	Wear/Tear	01/18/2023	0	0	Toowoomba	General Freight	127.5	0	0	
			Breakdown/Callout - Toowoomba Yard.									
			Truck has trouble building up & maintaining air									
38343	I402	Mack Super-Liner Sleeper Cab - pressure when ...	DA	01/24/2023	0	0	Toowoomba	General Freight	170	0	0	
39827	I402	Mack Super-Liner Sleeper Cab - A Service - Truck	PM	03/22/2023	0	0	Hemmant	General Freight	0	7.7	0	
40007	I402	Mack Super-Liner Sleeper Cab - r/h exhaust pipe falling off	DA	03/29/2023	0	0	Toowoomba	General Freight	212.5	0	0	
			removed r/h exh stack ready for new pipe to be									
			fitted									
40123	I402	Mack Super-Liner Sleeper Cab - refit pipe and r/h headlight globe	DA	04/03/2023	0	0	Toowoomba	General Freight	297.5	0	0	
			1 - Spot lights - need repairing.									
40515	I402	Mack Super-Liner Sleeper Cab - 2 - Screw - Mis ...	Wear/Tear	05/15/2023	0	0	Toowoomba	General Freight	2210	0	0	
			Air conditioning - not working.									
40519	I402	Mack Super-Liner Sleeper Cab - [FR 8984 - 14/4/23]	Wear/Tear	05/18/2023	0	0	Toowoomba	General Freight	425	0	0	
			Windscreen check req'd - Chips & Bullseye/s									
			reported. [No details supplied.]									
40809	I402	Mack Super-Liner Sleeper Cab - [FR 8983 - 6/4/23]	DA	06/29/2023	0	0	Toowoomba	General Freight	0	0	0	
			Tablet cradle - Installation req'd.									
41608	I402	Mack Super-Liner Sleeper Cab - NO FR.	Scheduled	06/29/2023	0	0	Toowoomba	General Freight	0	0	0	
			start cleaning and fitting signs to go to bris ware									
41762	I402	Mack Super-Liner Sleeper Cab - house	M/Request	06/12/2023	0	0	Toowoomba	General Freight	170	0	0	
41807	I402	Mack Super-Liner Sleeper Cab - fit and mount beacon lights	M/Request	06/13/2023	0	0	Toowoomba	General Freight	467.5	0	0	
41854	I402	Mack Super-Liner Sleeper Cab - engine light on	MFD	06/14/2023	0	0	Toowoomba	General Freight	85	0	0	
42412	I402	Mack Super-Liner Sleeper Cab - no lights to trailer	M/Request	07/03/2023	0	0	Toowoomba	General Freight	170	0	0	
			Face Camera - No video.									
42428	I402	Mack Super-Liner Sleeper Cab - [FR 13997 - 4/7/23]	Unsched.	09/09/2023	0	0	Toowoomba	General Freight	42.5	0	0	
			Driver side Elbow pipe cracked and flex fallen off.									
42833	I402	Mack Super-Liner Sleeper Cab - NO FR.	MFD	08/19/2023	0	0	Toowoomba	General Freight	680	0	0	
			Tyre req'd - Axle 1 L/H steer - Flat/puncture.									
42975	I402	Mack Super-Liner Sleeper Cab - [MFD - R.C - 17/7/23 + FR 8987 - 18/7/23]	Tyres - UN	07/18/2023	0	0	Brisbane Port Tyres	General Freight	255	0	0	
43108	I402	Mack Super-Liner Sleeper Cab - reading		07/20/2023	0	0	Hemmant	General Freight	0	0	0	
43937	I402	Mack Super-Liner Sleeper Cab - A Service - Truck	PM	08/19/2023	0	0	Hemmant	General Freight	170	0	0	
44007	I402	Mack Super-Liner Sleeper Cab - Headlight and clearance light not working	MFD	08/19/2023	0	0	Hemmant	General Freight	170	0	0	
			Clearance light - R/H air cleaner intake stack. NO									
			detail, assume some not working.									
44067	I402	Mack Super-Liner Sleeper Cab - [FR 135819 - 2 ...	Wear/Tear	10/25/2023	0	0	Hemmant	General Freight	0	0	0	
			Windscreen - Check condition of both windscreen									
			panes - Both panes described as broken.									
44083	I402	Mack Super-Liner Sleeper Cab - [FR 13519 ...	DA	09/08/2023	0	0	Hemmant	General Freight	127.5	0	0	
			Air & electrical lines - need to relocate lines from									
44084	I402	Mack Super-Liner Sleeper Cab - Octose arm to back of cab. (Refer Lachlan Brow ...	M/Request	10/11/2023	0	0	Hemmant	General Freight	1615	0	0	
44595	I402	Mack Super-Liner Sleeper Cab - Electrical inspection	MFD	09/09/2023	0	0	Hemmant	General Freight	680	0	0	
			V-DAQ & Toll tag - Both tags need to be moved.									
44654	I402	Mack Super-Liner Sleeper Cab - Positions tags were reinstalled in after windscreen ...	Compliance	11/30/2023	0	0	Hemmant	General Freight	42.5	0	0	

		Turntable - request for turntable to be moved rearward by one bolt hole.										
44684 I402	Mack Super-Liner Sleeper Cab	-[FR 13529 - 13/9/23]	M/Request	10/25/2023	0	0	Hemmant	General Freight	340	0	0	
45126 I402	Mack Super-Liner Sleeper Cab	- wiper blade missing 1 - Wiper arm - L/H broken. 2 - Mudguard - Drive 2 L/H guard broken.	Scheduled	10/03/2023	0	0	Hemmant	General Freight	42.5	0	0	
45472 I402	Mack Super-Liner Sleeper Cab	-3 - Mudflap - Joining flap b ... Tablet - tablet is not fitted or missing.	DA	11/30/2023	0	0	Hemmant	General Freight	170	0	0	
46274 I402	Mack Super-Liner Sleeper Cab	-[FR 10361 - 17/11/23]	R/Request	11/30/2023	0	0	Hemmant	General Freight	42.5	0	0	
46468 I402	Mack Super-Liner Sleeper Cab	- Check over	MFD	11/24/2023	0	0	Hemmant	General Freight	340	0	0	
46575 I402	Mack Super-Liner Sleeper Cab	- B Service - Truck Coolant leak - Leaking from pipe coming off header	PM	11/30/2023	0	0	Hemmant	General Freight	595	0	0	
46673 I402	Mack Super-Liner Sleeper Cab	- tank.	Unsched.	12/05/2023	0	0	Hemmant	General Freight	85	0	0	
46726 I402	Mack Super-Liner Sleeper Cab	- mud guard request replace and header tank	MFD	12/07/2023	0	0	Hemmant	General Freight	595	0	0	
46768 I402	Mack Super-Liner Sleeper Cab	- Tyre request steer tyres worn out.	Tyres - UN	12/09/2023	0	0	Hemmant	General Freight	340	0	0	
47899 I402	Mack Super-Liner Sleeper Cab	- D Service - Truck	PM	02/19/2024	0	0	Hemmant	General Freight	297.5	0	0	
47908 I402	Mack Super-Liner Sleeper Cab	- A Service - Truck - Ignore - Out of sequence. Tyre Req'd - Drive 2 L/H Outer - Flat tyre.	PM	02/19/2024	0	0	Hemmant	General Freight	382.5	0	0	
48099 I402	Mack Super-Liner Sleeper Cab	-[FR 17806 - 09/02/2024]	Tyres - UN	02/19/2024	0	0	Brisbane Port Tyres	General Freight	0	0	0	
48115 I402	Mack Super-Liner Sleeper Cab	- Tyre req'd - L/H rear axle outer was puncture Oil leak - Engine sump is leaking.	Tyres - UN	02/09/2024	0	0	Hemmant	General Freight	170	0	0	
48461 I402	Mack Super-Liner Sleeper Cab	-[MFD - J.L - 19/2/24 + FR 10365 - 28/5/24] Windscreen - R/H pane, chip needs checking.	Tyres - UN	05/28/2024	0	0	Hemmant	General Freight	0	0	0	
48462 I402	Mack Super-Liner Sleeper Cab	-[MFD - J.L - 19/2/24] Turntable - Needs adjustment.	DA	06/18/2024	0	0	Hemmant	General Freight	0	0	0	
48464 I402	Mack Super-Liner Sleeper Cab	-[MFD - J.L - 19/2/24] Tyre req'd - Steer 1 R/H - Tyre described as flat.	Wear/Tear	05/07/2024	0	0	Hemmant	General Freight	42.5	0	0	
49264 I402	Mack Super-Liner Sleeper Cab	-[11596 - 2/4/24]	Tyres - UN	04/02/2024	0	0	Brisbane Port Tyres	General Freight	510	0	0	
50029 I402	Mack Super-Liner Sleeper Cab	- C/D Service - Truck - Brisbane General Fleet Repairs from C-D service. See WOH# 50029	PM	05/07/2024	0	0	Hemmant	General Freight	977.5	0	0	
50078 I402	Mack Super-Liner Sleeper Cab	-[MFD - E.M - 7/5/24]	PM	05/07/2024	0	0	Hemmant	General Freight	1530	0	0	
51642 I402	Mack Super-Liner Sleeper Cab	- head light and indicator lights problems' A/D Service - Truck - Brisbane General Fleet	Unsched.	07/05/2024	0	0	Hemmant	General Freight	127.5	0	0	
51920 I402	Mack Super-Liner Sleeper Cab	- - Scheduled 30/7/24 - NO SHOW NHVR Sticker - Sticker is faded, replacement requested.	PM	08/15/2024	0	0	Hemmant	General Freight	425	0	0	
52115 I402	Mack Super-Liner Sleeper Cab	-[ER 4138 - 25/7/24] Requested from Truck P ... Indicator - L/H Indicator repeater light in bullbar not working. Photo attached.	Compliance	02/18/2025	0	0	Hemmant	General Freight	42.5	0	0	
52175 I402	Mack Super-Liner Sleeper Cab	-[ER 4173 - 29/7/24 ...	Wear/Tear	09/02/2024	0	0	Hemmant	General Freight	42.5	0	0	
52866 I402	Mack Super-Liner Sleeper Cab	- brake down at nebo Seat - Leaking air fitting/line in seat.	Unsched.	08/23/2024	0	0	Toowoomba	General Freight	170	0	0	
53083 I402	Mack Super-Liner Sleeper Cab	-[FR 17882 - 2/9/24] Door - L/H door not opening or unlocking with or without the key.	Unsched.	09/02/2024	0	0	Hemmant	General Freight	85	0	0	
53125 I402	Mack Super-Liner Sleeper Cab	-[FR 17884 - 3/9/24] - Scheduled ... Tyre check req'd - Drive axle 2 R/H Inner - Tyre described as low pressure.	Wear/Tear	10/03/2024	0	0	Hemmant	General Freight	170	0	0	
53545 I402	Mack Super-Liner Sleeper Cab	-[FR ????? - 17/9/24] Tyre change requested - Steer axle 1 L/H & R/H - Change tyres from Techking to Michelin.	Tyres - UN	09/17/2024	0	0	Brisbane Port Tyres	General Freight	212.5	0	0	
53547 I402	Mack Super-Liner Sleeper Cab	-[FR 17894 ... UHF radio - radio has no range, driver suspects issue with the aerial.	Tyres - UN	10/03/2024	0	0	Brisbane Port Tyres	General Freight	255	1234	0	
53585 I402	Mack Super-Liner Sleeper Cab	-[FR 17893 - 18/9/24] - Sche ... B/D Service - Truck - Brisbane General Fleet [Updated 31/7/24]	R/Request	10/17/2024	0	0	Hemmant	General Freight	85	0	0	
54000 I402	Mack Super-Liner Sleeper Cab	-	PM	10/15/2024	0	0	Hemmant	General Freight	850	0	0	
54361 I402	Mack Super-Liner Sleeper Cab	- electrical issues	DA	10/17/2024	0	0	Hemmant	General Freight	1955	0	0	
54453 I402	Mack Super-Liner Sleeper Cab	- radio need to be replace.	Unsched.	10/25/2024	0	0	Hemmant	General Freight	297.5	0	0	
54928 I402	Mack Super-Liner Sleeper Cab	- NO FR Suppl ... Air leak - Breakdown on the way up the Toowoomba bypass - Appears to compressor issue. raise up to 100 kpm speed limit	Unsched.	11/06/2024	0	0	Hemmant	General Freight	743.75	0	0	
55755 I402	Mack Super-Liner Sleeper Cab	- calibrate gearbox Breakdown on Toowoomba By-pass.	MFD	12/04/2024	0	0	Hemmant	General Freight	127.5	0	0	
55979 I402	Mack Super-Liner Sleeper Cab	- NO FR Supplied.	Unsched.	12/16/2024	0	0	Hemmant	General Freight	680	0	0	
56130 I402	Mack Super-Liner Sleeper Cab	- Driver seat lifting all the way up Seat - R/H seat not maintaining ride height, goes all the way up or all the way down.	Unsched.	12/20/2024	0	0	Hemmant	General Freight	42.5	0	0	
56381 I402	Mack Super-Liner Sleeper Cab	-[FR 17930 - ...	Wear/Tear	01/08/2025	0	0	Hemmant	General Freight	85	0	0	

		Lights - Load lights not operational.										
56590	1402	Mack Super-Liner Sleeper Cab - [FR 17926 - 13/01/2025]	R/Request	03/15/2025	0	0	Hemmant	General Freight	127.5	0	0	
56696	1402	Mack Super-Liner Sleeper Cab - seat leaking air	Unsched.	01/21/2025	0	0	Hemmant	General Freight	170	0	0	
		Tyre check - Drive axel 1 L/H inner & outer - low										
56779	1402	Mack Super-Liner Sleeper Cab - pressure	Tyres - UN	02/18/2025	0	0	Hemmant	General Freight	85	0	0	
		Air hose - Hose between compressor & air dryer										
		blowing off fitting. Has occurred several times.										
56831	1402	Mack Super-Liner Sleeper Cab - [F ...	Wear/Tear	01/28/2025	0	0	Hemmant	General Freight	170	0	0	
		A/D Service - Truck - Brisbane General Fleet										
56853	1402	Mack Super-Liner Sleeper Cab - [Updated 31/7/24] - Scheduled 4/2/25 - NO SHOW	PM	02/21/2025	0	0	Hemmant	General Freight	170	0	0	
		Air leak - Air dryer bleeding air every 10 seconds.										
56873	1402	Mack Super-Liner Sleeper Cab - Sounds like an air line is loose or not connect ...	Wear/Tear	02/21/2025	0	0	Hemmant	General Freight	283.3333305	0	0	
57271	1402	Mack Super-Liner Sleeper Cab - Needs new bateries.	Unsched.	02/17/2025	0	0	Hemmant	General Freight	170	0	0	
									Sum = \$38,284.08	Sum = \$9,892.45	Sum = \$0.00	