

FROM DATE : 01/01/2017 TO DATE : 10/07/2025 FROM PROD# : HE1415 TO PROD# : HE1415

=====						
PRODUCT NUMBER :		HE1415	EXCAVATOR 336-07 CAT HYD			
DATE	SEQ CODE	WO #	REPAIRED BY	METER	TOTAL COST	DESCRIPTION
----	----	----	-----	-----	-----	-----
05/20/2023	001 4	E2C97060180	SHAWN KIM	5290.00	283.95	500 HR ENGINE SERVICE
						SOSOIL SOS BOTTLE OIL , AMT : 16.50
						434-3928 ELEMENT FUEL , AMT : 0.01
						500-0483 ELEMENT LUB , AMT : 0.01
						523-4987 ELEMENT SEP , AMT : 0.01
						4526001 EXT APLI GREASE , AMT : 6.15
						4969841 ELEMENT-PRIM , AMT : 0.01
						4969842 ELEMENT SEC , AMT : 0.01
						ENGINE SERVICE AT 5290HRS - E2 , AMT : 230.00
						ENGINE OIL , AMT : 0.00
						TRAVEL TIME , AMT : 0.00
						TRAVEL DISTANCE KM , AMT : 31.25
						ENGINE SERVICE 500HRS - E2
						REMOVE AND REPLACE FUEL FILTERS
						REMOVE AND REPLACE ENGINE OIL AND FILTER
07/29/2023	001 4	E2C97060500		5644.00	356.20	500 HR ENGINE SERVICE
						434-3928 ELEMENT FUEL , AMT : 59.11
						500-0483 ELEMENT LUB , AMT : 44.77
						523-4987 ELEMENT SEP , AMT : 55.07
						SOSOIL SOS BOTTLE OIL , AMT : 24.75
						500 HR SERVICE AT 5644 , AMT : 172.50
						ENGINE OIL , AMT : 0.00
						ENGINE SERVICE 500 HRS - E2
						CUSTOMER: QM Environmental
						JULY. 29. 2023
						500 HRS SERVICE AT 5644HR
						GREASING
						TO CHECK ALL FLUID LEVEL
08/28/2023	001 4	E2C97060658		5777.00	553.95	500 HR ENGINE SERVICE
						434-3928 ELEMENT FUEL , AMT : 59.11
						500-0483 ELEMENT LUB , AMT : 44.77
						523-4987 ELEMENT SEP , AMT : 55.07
						500 HOUR FIELD SERVICE , AMT : 345.00
						ENGINE OIL , AMT : 0.00
						TRAVEL TIME , AMT : 0.00
						TRAVEL DISTANCE KM , AMT : 50.00
						TRAVELLED TO PORTLANDS TO SERVICE MACHINE FOR 500 HOUR
						SERVICE
						PERFROMED SERVICE ON MACHINE AND GREASED BOOM THOROUGHLY
09/14/2023	001	C97060735		5832.00	310.00	SERVICE CALL , AMT : 157.50
						TRAVEL TIME , AMT : 90.00
						TRAVEL DISTANCE KM , AMT : 62.50
						NOT GETTING GREASE TO THE TRACKS
						ADDRESS: 4770 LAKESHORE

COOPER EQUIPMENT RENTALS
EQUIPMENT MAINTENANCE COST REPORT

FROM DATE : 01/01/2017 TO DATE : 10/07/2025 FROM PROD# : HE1415 TO PROD# : HE1415

=====						
PRODUCT NUMBER :	HE1415	EXCAVATOR 336-07	CAT HYD			
DATE	SEQ CODE	WO #	REPAIRED BY	METER	TOTAL COST	DESCRIPTION
----	---	----	-----	-----	-----	-----
						CONTACT: AREA FOREMAN - CHRIS 365 999 6416
						TRAVEL SHOP TO PORTLANDS
09/14/2023	002	C97060764		5832.00	571.50	
						51P-41501 SENSOR AS-LE , AMT : 260.25
						51P-41503 .VALVE-FILL , AMT : 53.75
						SERVICE CALL , AMT : 105.00
						TRAVEL TIME , AMT : 90.00
						TRAVEL DISTANCE KM , AMT : 62.50
09/29/2023	001	C97060830		5909.00	.01	
						AA7-C97 C97 ATTACHMENTS , AMT : 0.01
						TO CONSUME ATTACHMENT AGAINST UNIT
10/03/2023	001	C97060690		5777.00	765.07	
						51P-41011 LAMP GP - FLOOD , AMT : 555.07
						REMOVE AND REPLACE CAB , AMT : 210.00
10/03/2023	002	C97060691		5777.00	707.96	
						51P-41012 COVER AS , AMT : 284.10
						51P-41013 COVER AS , AMT : 318.86
						REMOVE AND REPLACE CAB , AMT : 105.00
04/02/2024	001	C97061680		6881.00	2142.26	
						51P-46223 WINDOW , AMT : 935.53
						51P-46224 WINDOW FRAME SEAL , AMT : 25.58
						51P-46225 CURVED SAFETY GLASS , AMT : 376.15
						REMOVED AND INSTALLED FRONT GL , AMT : 345.00
						TRAVEL DISTANCE KM , AMT : 45.00
						TRAVEL TIME , AMT : 120.00
						SUBLET REPAIR , AMT : 295.00
						CUSTOMER QM ENVIRONMENTAL
						CONTRACT: 002155
						CUSTOMER PO: P425212
						TRAVELLED TO PORTLANDS AND FOUND MACHINE
						CLEANED CAB AND PREPPED FOR WINDOW INSTALL, INSTALLED DOOR
						AND CHECKED OPERATION, INSTALLED GLASS AND CHECKED FOR
						FITMENT
						PERFORMED REMOTE FLASH ON UNIT
						TRAVELLED BACK TO SHOP
						SUBLET REPAIR INSTALL DOOR GLASS INTO DOOR FRAME
04/09/2024	001 4	E2C97061717		6881.00	1350.28	
						500 HR ENGINE SERVICE
						256-6453 TEMP SENSOR , AMT : 95.43
						238-5080 O-RING , AMT : 10.10
						496-9842 ELEMENT - SEC , AMT : 27.47
						434-3928 ELEMENT FUEL , AMT : 60.12
						523-4987 ELEMENT SEP , AMT : 56.00
						500-0483 ELEMENT LUB , AMT : 45.55
						496-9841 ELEMENT-PRIM , AMT : 218.11
						E2 SERVICE - 500 HR SERVICE , AMT : 172.50

COOPER EQUIPMENT RENTALS

EQUIPMENT MAINTENANCE COST REPORT

FROM DATE : 01/01/2017 TO DATE : 10/07/2025

FROM PROD# :

HE1415

TO PROD# :

HE1415

=====						
PRODUCT NUMBER :	HE1415	EXCAVATOR 336-07	CAT HYD			
DATE	SEQ CODE	WO #	REPAIRED BY	METER	TOTAL COST	DESCRIPTION
----	---	----	-----	-----	-----	-----
						EXCHANGE INTEL AIR TEMP SENSOR , AMT : 172.50
						TRAVEL DISTANCE KM , AMT : 312.50
						TRAVEL TIME , AMT : 180.00
						E2 500 HR SERVICE
						EXCHANGE INTEL AIR TEMP SENSOR
04/15/2024	001	C97061764		6881.00	482.50	
						2526-3 & 582-3 CODE ON , AMT : 287.50
						TRAVEL DISTANCE KM , AMT : 75.00
						TRAVEL TIME , AMT : 120.00
						TRAVEL FROM SHOP TO TORONTO AND RETURN
						TECH: SHAWN
05/15/2024	001	C97061904		6881.00	2089.13	
						51P-47569 SENSOR , AMT : 1646.63
						REPLACE NOX SENSOR , AMT : 230.00
						TRAVEL DISTANCE KM , AMT : 62.50
						TRAVEL TIME , AMT : 150.00
						TRAVEL TO PORTLANDS AND RETURN TO SHOP
06/28/2024	001	C97062023		7255.00	500.00	
						ADJUST LEFT TRACK TENSION , AMT : 287.50
						TRAVEL DISTANCE KM , AMT : 62.50
						TRAVEL TIME , AMT : 150.00
						ADJUST LEFT TRACK TENSION
						TRAVEL FROM SHOP TO PORTLAND AND RETURN
						TECH SHAWN
08/23/2024	001 4	E2C97062163		7255.00	611.67	
						500 HR ENGINE SERVICE
						434-3928 ELEMENT FUEL , AMT : 60.12
						523-4987 ELEMENT SEP , AMT : 56.00
						500-0483 ELEMENT LUB , AMT : 45.55
						E2 SERVICE 500 SERVICE , AMT : 157.50
						TRAVEL DISTANCE KM , AMT : 112.50
						TRAVEL TIME , AMT : 180.00
						E2 500
						QM ENVIROMENTAL
						15 WEST DRIVE TO TORONTO AND RETURN
						SHAWK K SERVICE CALL
11/06/2024	001	C97062565		7800.00	3102.72	
						251-2552 LINKAGE PIN , AMT : 2495.22
						REMOVE THUMB INSTALL NEW PIN & , AMT : 287.50
						TRAVEL DISTANCE KM , AMT : 200.00
						TRAVEL TIME , AMT : 120.00
						REMOVE THUMB AND INSTALL NEW PIN AND HARDWARE
						SHAWN AND LOU
						PORTLANDS
						QM ENVIRO
12/02/2024	001	C97062711		7896.00		

COOPER EQUIPMENT RENTALS

EQUIPMENT MAINTENANCE COST REPORT

FROM DATE : 01/01/2017 TO DATE : 10/07/2025

FROM PROD# :

HE1415

TO PROD# :

HE1415

=====						
PRODUCT NUMBER :	HE1415	EXCAVATOR 336-07	CAT HYD			
DATE	SEQ CODE	WO #	REPAIRED BY	METER	TOTAL COST	DESCRIPTION
----	---	----	-----	-----	-----	-----
						SUBLET REPAIR , AMT : 0.00
						SUBLET REPAIR - WARRANTY COVERAGE
						COMPALINT PERFORM PS47583 - TAKE PSR
						REMOVE ENGINE PANEL AND FLOOR PANEL
						SEE ATTACHED WO FOR DETAILS
12/02/2024	002	C97062684		7896.00		
						SUBLET REPAIR - PERFORM PS47583
						CORRECTION: TAKE PSR. REMOVE ENGINE PANEL AND FLOOR PANEL.
						SEE ATTACHED WO FOR ENTIRE DETAILS.
						COVERED UNDER WARRANTY
12/20/2024	002	C97062756		7896.00	528.50	
						641-5407 SENSOR , AMT : 266.00
						REMOVE AND REPLACE FUEL SENSOR , AMT : 262.50
						REMOVE AND REPLACE FUEL SENSOR
						QM ENVIROMENTAL
12/20/2024	001 4	E2C97062763		7896.00	819.98	
						500 HR ENGINE SERVICE
						434-3928 ELEMENT FUEL , AMT : 60.42
						523-4987 ELEMENT SEP , AMT : 56.29
						500-0483 ELEMENT LUB , AMT : 45.77
						E2 SERVICE 500 HR , AMT : 287.50
						TRAVEL DISTANCE KM , AMT : 250.00
						TRAVEL TIME , AMT : 120.00
						E2 500 -PORT HOPE
01/21/2025	001	C97062902		8069.00	2281.80	
						611-7548 JOY STICK GRIP , AMT : 2166.80
						REPLACE LEFT CONTROL LEVER , AMT : 115.00
						REMOVE AND REPLACE LEFT HAND JOYSTICK
						SAM R
02/12/2025	001	C97063027		7896.00	1647.78	
						SUBLET REPAIR , AMT : 1647.78
						PO # C97072393 - HE1415 - TOROMONT SUBLET - UNIT WILL NOT
						RUN THUMB
						SEE ATTACHED WO FROM TOROMONT
02/19/2025	001 4	E2C97063097		8151.80	597.86	
						500 HR ENGINE SERVICE
						590-9787 ELEMENT , AMT : 166.57
						523-4987 ELEMENT SEP , AMT : 56.29
						E2 SERVICE 500 HR , AMT : 375.00
						E2 500
						WEST DR
						PETER
02/19/2025	002 4	P1C97063098		8151.80	536.08	
						1000HR POWERTRAIN SERVICE
						434-3928 ELEMENT FUEL , AMT : 60.42
						571-5253 ELEMENT AS-X , AMT : 100.66

COOPER EQUIPMENT RENTALS

EQUIPMENT MAINTENANCE COST REPORT

FROM DATE : 01/01/2017 TO DATE : 10/07/2025

FROM PROD# :

HE1415

TO PROD# :

HE1415

```

=====
PRODUCT NUMBER :      HE1415    EXCAVATOR 336-07 CAT HYD
  DATE   SEQ CODE    WO #  REPAIRED BY      METER   TOTAL COST  DESCRIPTION
  ---   --  ---    -  -
02/19/2025 003 4 P2C97063099      8151.80    517.61  P1 1000 HOUR SERVICE , AMT : 375.00
                                           P1 1000 HOUR SERVICE
                                           WEST DR
                                           PETER
02/19/2025 003 4 P2C97063099      8151.80    517.61  2000HR POWERTRAIN SERVICE
                                           479-8989 ELEMENT-PRIM , AMT : 142.60
                                           479-8991 ELEMENT - SEC , AMT : 0.01
                                           P2 2000 HOUR SERVICE , AMT : 375.00
                                           P2 2000 HR SERVICE
                                           WEST DR
                                           PETER
02/25/2025 001      C97063100      8151.80    368.14  349-7059 CAP AS-FUEL , AMT : 218.14
                                           REPLACE FUEL CAP , AMT : 150.00
                                           PO C97072459
                                           REPLACE FUEL CAP
03/27/2025 001      C97063355      8151.80    750.00  THUUMB PIN WORKING OUT , AMT : 750.00
04/15/2025 001      C97063510      8151.80    750.00  REPLACE MISSING BOLTS CUTTING , AMT : 750.00
05/28/2025 001      C97063611      8151.80    1206.00  C7X2454 BOLT , AMT : 44.00
                                           C8T4167 WASHER , AMT : 12.00
                                           CR7876 EXC ROLLER , AMT : 700.00
                                           REMOVE & REPLACE 2 BOTTOM TRAC , AMT : 450.00
                                           4/29 C97072697 REMOVE AND REPLACE 2 BOTTOM TRACK ROLLERS
                                           ESS
                                           ON GOING UNIT MAY RETURN TO 15 WEST DR FOR SALE
05/28/2025 002      C97063663      8295.00    12366.66  491-3844 ROLLER , AMT : 4251.10
                                           451-2177 WASHER , AMT : 169.68
                                           447-1723 BOLT , AMT : 118.68
                                           453-2854 BOLT , AMT : 144.64
                                           451-2177 WASHER , AMT : 48.48
                                           447-1723 BOLT , AMT : 989.00
                                           528-8101 GUARD , AMT : 3408.81
                                           528-8101 GUARD , AMT : 1136.27
                                           UNDER CARRIAGE REPAIR , AMT : 2100.00
                                           5/7 C97072947 REPLACEMENT OF BOTTOM ROLLERS AND GUIDES
                                           TOROMONT - WEST DR
07/31/2025 001      C97064268      8151.80    331.86  2A55413420A AFTERMARKET KOMATS , AMT : 114.35
                                           498-9091 SWITCH , AMT : 67.51
                                           REPLACE MIRROR AND QUICK COUPL , AMT : 150.00
                                           7/28 PO TBD - REPLACE SIDE RIGHT MIRROR REPLACE QUICK
=====

```

COOPER EQUIPMENT RENTALS
EQUIPMENT MAINTENANCE COST REPORT

FROM DATE : 01/01/2017 TO DATE : 10/07/2025 FROM PROD# : HE1415 TO PROD# : HE1415

```
=====
PRODUCT NUMBER :      HE1415    EXCAVATOR 336-07 CAT HYD
  DATE   SEQ CODE    WO #  REPAIRED BY      METER   TOTAL COST  DESCRIPTION
  ---   - - - - -    - - -  - - - - -      - - -   - - - - -  - - - - -
                                           COUPLER SWITCH
                                           TOROMONT / INVENTORY - WEST DR
                                           EVAN PENDING SALE
                                           TO BE CLOSED TO C99
08/21/2025 001      C97064471              8300.00    225.00
                                           TRACK ADJUSTER NOT HOLDING GREASE , AMT :    225.00
                                           8/21 TRACK ADJUSTER NOT HOLDING GREASE
                                           TECH SAM
                                           SEE ATTACHED MECHANIC WORKSHEET FOR DETAILS

                                           -----
PRODUCT TOTAL :              36754.47
```