

Seymour Whyte Work Order History Report: CAT 825H Compactor VIN: CAT0825HAAZW00278

W/O No	Description	Reading	Date
908	Repair coolant leak in the heater box	9638.0	5/05/23
937	Heater core issues	9638.0	5/04/23
940	500hr CAT 825H Compactor Service	9511.0	2/04/23
1011	Replace cutting edges	9511.0	2/04/23
1037	250hr CAT 825H Compactor Service	9741.0	5/06/23
1074	Repair coolant leak bottom hose.	9705.0	25/05/23
1078	Welded snapped steering pin lug	9708.0	29/05/23
1102	Right hand steer pin mount cracked	9874.0	8/07/23
1103	Check steer system pressures and setting. Adjust as needed	10075.0	15/08/23
1214	5000hr CAT 825H Compactor Service	10049.0	8/08/23
1226	Repaired issue: Failing to start.	9975.0	26/07/23
1280	Replace broken blade control joystick mount	10140.0	3/10/23
1366	A/C not working, blowing warm air.	10138.0	20/09/23
1530	Repairs before leaving site M12	10157.0	13/11/23
1762	Blade tilt cylinder leaking and chrome damaged.	10175.0	16/01/24
1763	Exhaust muffler cracked	10175.0	16/01/24
1764	Charged air hoses cooked from crack in exhaust.	10175.0	16/01/24
1765	Coolant bleed lines perished from top of block.	10175.0	16/01/24
1770	Machine won't start - Batteries Replaced	10175.0	16/01/24
1828	250hr CAT 825H Compactor Service	10247.0	25/01/24
1881	Coolant sample bad last service.	10295.0	12/02/24
1900	Aircon keeps tripping curcuit breaker.	10520.0	25/05/24
2201	500hr CAT 825H Compactor Service	10520.0	25/05/24
2627	Investigate oil dilution in engine oil	10689.0	30/08/24
2635	Diagnose and repair: machine has lost all drive	10699.0	4/09/24
2655	250hr CAT 825H Compactor Service	10741.0	13/09/24
2948	1000hr CAT 825H Compactor Service	11044.0	20/12/24
2994	Unblock windscreen washer jets & check over machine	10896.0	22/11/24
3084	Replace cracked front windscreen		10/01/25
3142	250hr CAT 825H Compactor Service - Stood Down in QLD Plant Yard - To be completed before next hire	11250.0	21/10/25
3164	Defect repairs as per task list		29/10/25
4257	Off hire cleaning		28/07/25
4930	Repaired oil leak in steer hose due to rubbing on tail shaft.		23/10/25
5030	Rotate corner tips on blade for transport compliance and refit on arrival.		6/11/25
5229	Diagnose and repair operator reported "noise under engine load and lacking pushing power"		2/12/25
5471	Check over AC after reports of AC not working from operator		15/01/26
5516	250hr CAT 825H Compactor Service	11500.0	24/01/26
5568	Carry out visual inspection and pre start	11369.0	2/02/26
5638	Carry out visual inspection and pre start	11395.0	10/02/26
5639	Remove and replace mushroom handle, remove mushroom and screen.		
5861	Replace failed turbo		26/03/26
6077	Prepare for disposal		23/04/26