



Commercial Vehicle Inspection Report

Decal Number: GD35089
Decal Expiry Date: 2025-Aug-31
Inspection Number: 21046857

Inspection Result:
PASS

FACILITY: OK TRUCK CENTRE 2015 / S11720 INSP. TYPE: Complete INSP. START: 2024-Aug-22 01:00 PM PDT
INSPECTOR: ROSIN, JASON EDWIN / 112645 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2024-Aug-23 10:20 AM PDT
WORK ORDER #:
VEHICLE JUR: British Columbia REG: 12802820 VIN: 2M5130973K1182715
PLATE #: 78013K UNIT/FLEET#: SFB03 OWNER/LESSEE NAME: Sunfire Consulting Ltd, DIV Of Sunfire Transport
LICENCED GVW(kg): 0 BODY STYLE: Flat Deck Trailer ADDRESS: PO Box 932
VEHICLE YEAR: 2019 ODOMETER: Osoyoos, British Columbia
MAKE: MANAC HUB ODOMETER: V0H1V0, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) Change #3R brake shoes & drum.
Section 3A - Air Brakes	Repaired (same day) Change #1L, 3L&R brake pots. Change #1R & 2R S-cam & tubes.
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) Install missing amber reflector on right side.
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) Change loose bolt on left rear mud flap.
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Not Applicable	34	36
2	Clamp	30	Not Applicable	35	35
3	Clamp	30	Not Applicable	35	32

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
1	8.30	8.17	8.54	9.62	
2	11.82	11.88	5.53	7.93	
3	8.12	8.15	4.53	5.78	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	28	45
2	40	41
3	81	100

Comment:

Brake Lining/Pad (mm)

	Left	Right
Lining/Pad	20	17
Lining (Shoe)	18	18
Lining (Shoe)	12	10

Comment: New brake shoes #3R - 21mm

Rotor Thickness or Drum Inside Diameter (mm)

	Left	Right
Rotor/Drum	0.00	419.25
Drum	0.00	419.56
Drum	0.00	422.20

Comment: New drum installed on #3R - 419.10mm

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: ROSIN, JASON EDWIN

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2024-Aug-23 10:21 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the St. Manager, NSCVSP at the Commercial Vehicle Safety Enforcement.

CVSE014

8/23/2024 10:21:46 AM PDT