

Box 17 • Highway #11 Chamberlain, SK SOG 0R0

Phone: 306-638-4516 • Fax: 306-638-4633 www.youngs.ca

WARRANTY DATE

Assiniboia 306-642-5991 Davidson 306-567-3074 Moose Jaw 306-694-1800 Raymore 306-746-2288 Watrous 306-946-3387 Weyburn 306-842-2629 Windthorst

Ship To:

Invoice To: LYLE BENZ

BOX 15

AYLESBURY SK SOG 0B0

		Windt	horst	306-224-2110
Branch CHAMBERLAI	N	*REPRI	Nm*	
Date 08/19/20	Time 22:04:19 (B) Phone # In			Page 01
Account # BENZ0002			v # 02711	
Ship Via				
Tax ID #				
			Salesper 9 S	

HRS

SERVICE INVOICE

STK#/FLEET#

001214

Combine 2388

HRS PIN/EIN

3129 JJC0198555

2487

SEGMENT# 1 C 94009 NA Shaker

08/10/20 08/10/20

COMPLAINT:

Shaker system making loud banging sound.

CAUSE:

Slip clutch worn out.

CORRECTION:

- shaker arm bushings worn out or broken, nearly every one. Removed all shaker arms to extract their bushings, some bushings required extra time as they were damaged in the bores and difficult to remove or rusted in. Cleaned arm bores and prepped new bushings for installation. Installed new shaker arm bushings.
- removed sieves to remove all shaker arms, found breaks and cracks on upper and lower sieves.
- drive arm bearing is in good shape however secondary arm bearing is not. Removed hubs from bearings, to reuse secondary hub and save drive arm bearing. Performed bulletin on hub-slip welding. Installed new hub/slip to drive arm.
- removed auger driveshaft and extricated reusable components.
- replaced rocker arm shaft.

serial no- JJC0292255

B12170 RATCHET 2 B505500 34.26 CHAIN LUBE 68.52 RETAIL 7.12 B95352 3 5.95 KIT 17.85 1 M 176.81 COTTERPIN 176.81 COTTERPIN 2 1.00 2.00 CONTINUED ON PAGE 02

Received By

^{I hereby authorize the above repair work to be completed, including any necessary to operate said-vehicle, for the purposes of the testing, diagnosing, inspecting, reporting, reporting,}



Box 17 • Highway #11 Chamberlain, SK SOG ORO Phone: 306-638-4516 • Fax: 306-638-4633 www.youngs.ca

Nousilia Assiniboia 306-642-5991 Davidson 306-567-3074 Moose Jaw 306-694-1800 Raymore 306-746-2288 Watrous 306-946-3387 Weyburn 306-842-2629

Ship To:

Invoice To: LYLE BENZ BOX 15

AYLESBURY SK SOG OBO

		Windtho	rst	306-224-2110	
Branch CHAMBERLAI	N			Cashamar and	
Date 08/19/20	Time 22:04:19 (B))	Page 02	
Account # BENZ0002	000		1000000	Inv # W02711	
Ship Via		Purchase Orde			
Tax ID #					
		Sa	lesperso 9SM	n	

SERVICE INVOICE

STK#/FLEET	#	HRS DIN/BIN				
MWASHER ZK8 1303136C2 131198A1 1322616C2 1322623C1 1322624C1 1330336C1 193414C2 1979190C1 1979191C1	# Combine 2388	HRS PIN/EIN 3129 JJC0198555 2487 MACHINE WASHER GR8 BOLT 1/10LB HUB BAR SHAFT RETAINER RING WASHER BOARD RETAINER	3 1 1 M 1 M 1 4 1 ,1 M 5		HRS	5.52 1.28 265.21 50.10 776.48 64.84 23.57 11.12 198.90 23.57
388418C1 425-1212 47471 47509176 47900948 495-81057 84330069 86512371 86620026 86624125 86624166 87040910 87299946 87375654		WASHER WASHER NUT KEY, WOODRUFF BEARING, B CAM WASHER BEARING, B NUT, LOCK FLANGE SCREW WASHER RETAINER KIT	1 M 1 M 2 2 1 2 3 2 M 1 4 M 5	17.68 38.31 8.25 6.56 197.44 216.59 2.01 55.99 .90 6.85 1.92 1.84 3.90 691.02		17.68 38.31 8.25 13.12 394.88 216.59 4.02 167.97 1.80 13.70 1.92 7.36 19.50
87430518 11008009		GEAR FLANGE	5 2 M SEGMENT	53.04 14.51 PARTS LABOR TOTAL==>		691.02 265.20 29.02 3576.11 3979.79 7555.90

CONTINUED ON PAGE 03

Received By



^{*} I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at myrisk. Young's Equipment to roung's support inc. Is hereby released from any and all claims for loss and/or damage not caused, woorpt where such loss and/or delivering at myrisk. Young's Equipment inc. and/or in possession of the above noted equipment. In a level of insurance, including physical damage insurance, that is acceptable to that customer's responsibility or more that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment inc. is working on.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment to work in the control of the customer's reposition of the above noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment to the control of the control of the storage of the purpose in the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the lens specifically identified in the estimate only, and are not brinding.

Young's Equipment Inc. reserves the light, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs per formed on equipment that has been modified.



Box 17 • Highway #11 Chamberlain, SK SOG ORO Phone: 306-638-4516 • Fax: 306-638-4633 www.youngs.ca



Assiniboia 306-642-5991 Davidson 306-567-3074 Moose Jaw 306-694-1800 Raymore 306-746-2288 Watrous 306-946-3387 Weyburn 306-842-2629 Windthorst

Ship To:

Invoice To: LYLE BENZ

BOX 15

AYLESBURY SK SOG 0B0

		Windtho	rst	306-224-2110
Branch CHAMBERLAI	N			
Date 08/19/20	Time 22:04:19 (B) Phone # 3067342967		_	Page 03
Account # BENZ0002			Inv # W02711	
Ship Via		Purchase Order #		
Tax ID #				
		Sa	lesperso	on

HRS

SERVICE INVOICE

STK#/FLEET#

001214

Combine 2388

HRS PIN/EIN 3129 JJC0198555

2487

SEGMENT# 2 C 94009 QC

08/10/20

Young's Complimentary QuickCheck Inspection

SEGMENT# 3 C 94009 NA sieves

08/10/20 08/10/20

COMPLAINT:

breaks and cracks in sieves found during disassembly of other parts.

CORRECTION:

- make brackets to fix through-n-through break.
- weld upper sieve in 3 places including where break was with brackets, grind back down to proper size to fit guides.
- weld lower sieve in 1 place at mounting bracket where crack was forming.

sieves has been previously repaired, some previous repair welds had broken again, others had not. 169256C2

11008009

WASHER

5.37

WARRANTY DATE

32.22

PARTS

32.22

LABOR

SEGMENT TOTAL ==>

6

341.21

1.07

373.43

***** WORK ORDER TOTALS ***** PARTS 3608.33

LABOR 4321.00

SHOP SUPPLIES 200.00 SUB TOTAL ==> 8129.33

PST 6%

CONTINUED ON PAGE 04

employees at own risk.

An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% or annual to the principle of explanation of explanation or explicit as invoices have been paid.

Selamates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment his, and any other manufacturers do not provide variantly, neither expressed nor implied, on any repair sper formed on equipment that has been modified.

Leading The Way In A Thriving Agricultural Community!



I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment inc., its employees, and assigns may operate is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collisions, fig., the fit, or any other cause, except where such loss and/or damage is due to registere the contents of the customer's responsibility to ensure that a level of insurance, including physical damage not caused by the nepligence of Young's Equipment for any other cause, including physical damage is not caused by the nepligence of Young's Equipment for any other cause, including physical damage into caused by the nepligence of Young's Equipment for any other caused by the nepligence of Young's Equipment for any other caused by the nepligence of Young's Equipment for the part of the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is accordance of Young's Equipment for the part of the customer's responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.



Box 17 • Highway #11 Chamberlain, SK SOG 0R0 Phone: 306-638-4516 • Fax: 306-638-4633 www.youngs.ca



170AILIO Assiniboia 306-642-5991 Davidson 306-567-3074 Moose Jaw 306-694-1800 Raymore 306-746-2288 Watrous 306-946-3387 · Weyburn 306-842-2629

Ship To: .

Invoice To: LYLE BENZ

BOX 15

AYLESBURY SK SOG 0B0

		Windtho	rst	306-224-2110	
Branch CHAMBERLAI	N				
Date 08/19/20	Time 22	:04:19 (B))	Page 04	
Account # BENZ0002	S. Charles and S. Carles	Phone # 3067342967		Inv # W02711	
Ship Via	Purchase Order			2/11	
Tax ID #					
		Sa	lesperso	on	

HRS

SERVICE INVOICE

STK#/FLEET#

001214

Combine

2388

HRS PIN/EIN JJC0198555

3129

2487

08240J

XXXXXXXXXXXXXX

GST 5%

TOTAL CREDIT CARD

WARRANTY DATE

406.51

8536.91

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment thm, its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment inc. Young's Equip

Received By

